**This document was too large to scan
as a single document; therefore, it has
been divided into smaller sections.**

Section 1 of 2

Document Information			
Document #	HNF-2346	Revision	1
Title	PROJECT W-058 MONITOR & CONTROL SYS LOGIC		
Date	2/22/99		
Originator	ROBERTS JB	Originator Co.	LMSI
Recipient		Recipient Co.	
References	ECN-651363		
Keywords			
Projects			
Other Information			

ENGINEERING CHANGE NOTICE

H

Page 1 of 2

1. ECN 651363

Proj.
ECN

S

2. ECN Category (mark one) Supplemental ☐ Direct Revision ☒ Change ECN ☐ Temporary ☐ Standby ☐ Supersedure ☐ Cancel/Void ☐	3. Originator's Name, Organization, MSIN, and Telephone No. JB Roberts, SSTE 74800, T4-07, 373-7912 6. Project Title/No./Work Order No. Cross Site Transfer Monitor & Control System Logic Changes 9. Document Numbers Changed by this ECN (includes sheet no. and rev.) HNF-2346, Rev. 0	4. USQ Required? [X] Yes [ ] No USQ# TF-99-0148 7. Bldg./Sys./Fac. No. 242-S 10. Related ECN No(s). N/A	5. Date 02/18/99 8. Approval Designator N/A 11. Related PO No. N/A
12a. Modification Work [ ] Yes (fill out Blk. 12b) [X] No (NA Blks. 12b, 12c, 12d)	12b. Work Package No. N/A	12c. Modification Work Complete N/A Design Authority/Cog. Engineer Signature & Date	12d. Restored to Original Condition (Temp. or Standby ECN only) N/A Design Authority/Cog. Engineer Signature & Date
13a. Description of Change This ECN replaces Rev. 0 of HNF-2346 with Rev. 1 attached. 13b. Design Baseline Document? [ ] Yes [X] No			
14a. Justification (mark one) Criteria Change [ ] Design Improvement [ ] Environmental [ ] Facility Deactivation [ ] As-Found [X] Facilitate Const [ ] Const. Error/Omission [ ] Design Error/Omission [ ]			
14b. Justification Details HNF-2346 was prepared based on the W-058 Project original logic diagram. During construction and testing, changes had to be made to the logic and adjustments made to timing in order to get the system to work as designed. Some of the original values were based on best available information prior to construction. This ECN provides the "AS Built" configuration of the control logic.			
15. Distribution (include name, MSIN, and no. of copies) RE Larson T4-07 DP Mendoza T4-08 JB Roberts T4-07 MJ Sutey S5-07			

Page 2 of 2

651363

A-7900-013-3 (05/96) GEF096

DISTRIBUTION SHEET

[illegible]

S

Project W-058 Monitor and Control System Logic

J.B. Roberts

Lockheed Martin Hanford Co., Richland Wa 99352

Richland, WA 99352

U.S. Department of Energy Contract DE-AC06-96RL13200

EDT/ECN: 651363

UC: 2030

Org Code: 7800

Charge Code: 108460

B&R Code: 39EW31301

Total Pages: 5445

2/22/99

Key Words: W-058, Monitor and Control System, MCS, PCS, Ladder Logic, Software Printout, RCSTS

Abstract: This supporting document contains the printout of the control logic for the Project W-058 Monitor and Control System, as developed by Programmable Control Services, Inc. The logic is arranged in five appendices, one for each programmable logic controller console.

TRADEMARK DISCLAIMER. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

Printed in the United States of America. To obtain copies of this document, contact: Document Control Services, P.O. Box 950, Mailstop H6-08, Richland WA 99352, Phone (509) 372-2420; Fax (509) 376-4989.

Release Approval

2/22/99
Date

Release Stamp

Approved For Public Release

RECORD OF REVISION

(1) Document Number

HNF-2346

Page 1

(2) Title

Project W-058 Monitor and Control System Logic

Change Control Record

(3) Revision

(4) Description of Change - Replace, Add, and Delete Pages

Authorized for Release

(5) Cog. Engr.

(6) Cog. Mgr.

Date

RS 1

(7)

Replace Rev. 0 with Rev. 1 (all pages), Per ECN 165363

[Signature]

RE for 2/19/99

This supporting document consists of the following appendices:

Appendix A: PLC-1 Ladder Logistics . . . . . Pages i through 106

Appendix B: PLC-2 Ladder Logistics . . . . . Pages i through 186

Appendix C: PLC-3 Ladder Logistics . . . . . Pages i through 126

Appendix D: PLC-4 Ladder Logistics . . . . . Pages i through 78

Appendix E: PLC-5 Ladder Logistics . . . . . Pages i through 36

WINTelligent LOGIC 5 is a registered trademark of Rockwell Software Inc., of
717 West Smith Road, Medina, OH 44256

WIntelligent LOGIC 5 - Rockwell Software Inc.

Project Name : PLC1.X5

Time/Date : 08:15:24 02/19/99

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
WL5 - Table of Contents
Lockheed Martin Hanford Co.

HNF-2346, Rev. 1

08:16:12 02/19/99

Page Rung Description

1		Ladder Report
1	0	MAINLINE PROGRAM INITIALIZATION JUMP
2	2	GENERAL USE BITS AND TIMING FUNCTIONS
6	12	PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
8	0	PROCESSOR FAULT ROUTINE PROGRAM FILE
10	0	ANALOG INPUTS BLOCK TRANSFER & DH+ MESSAGES SEQUENCING
15	9	ANALOG INPUT OVER / UNDER RANGE ALARMS
22	0	COMMUNICATION HANDLING SUBROUTINE
41	0	GENERAL CONTROL SEQUENCING FOR PCU #1
42	2	TRANSFER PUMP INTERLOCK LOGIC, Y-75.1
46	13	SPEED REFERENCE RAMP CALL SEQUENCING
56	24	MASTER SHUTDOWN LOGIC, Y-77.1
57	27	FLUSH PUMP P-3100A CONTROL LOGIC, ES-058-Y90 SH.1
60	0	PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
71	0	COMMUNICATIONS SPEED CHECKING SUBROUTINE
72	0	PLC RAMP FUNCTION SUBROUTINE
77		DT Form Report
77		DB Form Report

Sorted By: Address

Hanford Cross Site Transfer System (PCU-1)
 MAINLINE PROGRAM INITIALIZATION JUMP
 Lockheed Martin Hanford Co.
 Page:00001

File #2 MAIN Proj:PLC1

08:15:24 02/19/99

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
 P.O. Box 28970
 Spokane, WA 99228-8970
 (509) 466-2656

*THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
 *THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS
 *BEEN UPDATED ON POWERUP OR
 *ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS
 *BEEN READ. TIMER T4:0 IS
 *USED TO SET THIS TIME DELAY.

First scan
 of ladder
 or SFC
 step

POWER-UP
 SEQUENCING
 DELAY

S:1/15

+--TOF--++
 Timer Off Delay |-(EN)-
 Timer: T4:0
 Base (SEC): 0.01 |-(DN)
 Preset: 20
 Accum: 20

T4:0.DN - TOF - File #2 MAIN - 0
 -| | - File #2 MAIN - 1,15

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

T4:0.DN

Q2:0

Q2:0 - JMP - File #2 MAIN - 1
 LBL - File #2 MAIN - 12

*****
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF
 *****

ALWAYS OFF OUTPUT ALWAYS OFF B3/0	ALWAYS OFF OUTPUT ALWAYS OFF B3/0	ALWAYS OFF OUTPUT ALWAYS OFF B3/0
2:0002	-	-

B3/0   - ( ) - File #2 MAIN - 2
           - ( ) - File #2 MAIN - 2
           - | | - File #2 MAIN - 2
           BSL - File #2 MAIN - 7
           - | | - File #2 MAIN - 17
                   File #4 REG 10 - 5,12
                   File #5 COMM_CHK - 3
                   File #6 GEN_CTRL - 2,23,28
                   File #9 DEMO - 12

*****
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON
 *****

	ALWAYS ON OUTPUT ALWAYS ON B3/1
2:0003	- ( )

B3/1   - ( ) - File #2 MAIN - 3

*****
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE
 *EXECUTED ONCE EVERY SECOND.
 *****

REAL TIME CLOCK SECOND ONE'S BIT	ONE SECOND RISING ONE SHOT	ONE SECOND SINGLE SCAN PULSE 1_SEC PULSE B3/2
S:23/0	B3/32	
2:0004	-	- [ONS]

REAL TIME
CLOCK
SECOND
ONE'S BIT

ONE SECOND
FALLING
ONE SHOT

S:23/0   B3/33

- | | - [ONS] -

B3/2   - ( ) - File #2 MAIN - 4
           - | | - File #2 MAIN - 8,17
                   File #5 COMM_CHK - 5

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 GENERAL USE BITS AND TIMING FUNCTIONS
 Lockheed Martin Hanford Co.
 Page:00003

HNF-2346, Rev. 1

File #2 MAIN Proj:PLC1

08:15:24 02/19/99

*****
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE
 *EXECUTED ONCE EVERY TWO
 *SECONDS.
 *****

	REAL TIME CLOCK SECOND TWO'S BIT	TWO SECOND RISING ONE SHOT		TWO SECOND SINGLE SCAN PULSE 2_SEC PULSE B3/3
2:0005	S:23/1	B3/34	----- -----	( )
		[ONS]		

REAL TIME CLOCK SECOND TWO'S BIT	TWO SECOND FALLING ONE SHOT
S:23/1	B3/35
----- -----	[ONS]-----

B3/3   - - ( ) - - File #2 MAIN - 5
           - - | - - File #2 MAIN - 7,7

	REAL TIME CLOCK MINUTE ONE'S BIT	ONE MINUTE RISING ONE SHOT		ONE MINUTE SINGLE SCAN PULSE 1_MIN PULSE B3/7
2:0006	S:22/0	B3/50	----- -----	( )
		[ONS]		

REAL TIME CLOCK MINUTE ONE'S BIT	ONE MINUTE FALLING ONE SHOT
S:22/0	B3/51
----- -----	[ONS]-----

B3/7   - - ( ) - - File #2 MAIN - 6
           - - | - - File #2 MAIN - 17
           - - / - - File #9 DEMO - 11
           - - | - - File #9 DEMO - 15

*****
 *THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS *
 *FROM B3/16 TO B3/31 WILL BE *
 *SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. *
 *IF A ONE IS LOADED INTO *
 *B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE *
 *BITS CAN BE USED TO DIVIDE *
 *PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMOUNG MULTIPLE *
 *SCANS. THE PLC PROGRAM SCAN *
 *TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED. *
 *****

FILE F:B003:001\X001 LEN 1 - BSL - File #2 MAIN - 7

R6:0.UL - BSL - File #2 MAIN - 7
 -|/| - File #2 MAIN - 7
 -(U) - File #2 MAIN - 7
 -|/| - File #2 MAIN - 7
 B3/0 - { } - File #2 MAIN - 2
 -|/| - File #2 MAIN - 2
 -|/| - File #2 MAIN - 2
 BSL - File #2 MAIN - 7
 -| - File #2 MAIN - 17
 File #4 REG 10 - 5,12
 File #5 COMM CHK - 3
 File #6 GEN CTRL - 2,23,28
 File #9 DEMO - 12
 R6:0.UL - BSL - File #2 MAIN - 7
 -|/| - File #2 MAIN - 7
 -(U) - File #2 MAIN - 7
 -|/| - File #2 MAIN - 7
 B3:1 - BSL - File #2 MAIN - 7
 MOV - File #2 MAIN - 7
 BSL - File #2 MAIN - 7

*****
 *THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.
 *****

ONE SECOND
 SINGLE SCAN
 PULSE
 1_SEC PULSE
 B3/2

HALF SECOND
 FLASHER TIMER

2:0008

+-TOF-----+
 Timer Off Delay -(EN)-
 Timer: T4:1
 Base (SEC): 0.01 -(DN)
 Preset: 900
 Accum: 21
 -----+

T4:1.DN - TOF - File #2 MAIN - 8
 -| |- File #2 MAIN - 9

*****
 *THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT *
 *DEVICES:
 *****

HALF SECOND
 FLASHER TIMER

HALF SECOND
 FLASHER
 HALF_SEC_FLASH
 B3/4
 ( )

2:0009

T4:1.DN

B3/4 - - ( ) - File #2 MAIN - 9

*****
 *THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT *
 *DEVICES:
 *****

REAL TIME
 CLOCK
 SECOND
 ONE'S BIT

ONE SECOND
 FLASHER
 1_SEC_FLASH
 B3/5
 ( )

2:0010

S:23/0

B3/5 - - ( ) - File #2 MAIN - 10

*****
 *THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT *
 *DEVICES:
 *****

REAL TIME
 CLOCK
 SECOND
 TWO'S BIT

TWO SECOND
 FLASHER
 2_SEC_FLASH
 B3/6
 ( )

2:0011

S:23/1

B3/6 - - ( ) - File #2 MAIN - 11

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
 Lockheed Martin Hanford Co.
 Page:00006

File #2 MAIN Proj:PLC1

08:15:25 02/19/99

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING
 *****

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

PROGRAM FILE
 JUMP-TO-SUBR.
 CONTROL RUNGS
 COMMENT COIL

2:0012 Q2:0 B3/36
 [LBL] - ( ) -

B3/36 - ( ) - File #2 MAIN - 12

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

2:0013 +--JSR--
 | Jump To Subroutine |
 | File #: U:4 |
 +-----+

U:4 - JSR - File #2 MAIN - 13
 SBR - File #4 REG_10 - 0

DATA HIGHWAY +
 COMMUNICATIONS
 CTRL & CHECK
 SUBROUTINE

2:0014 +--JSR--
 | Jump To Subroutine |
 | File #: U:5 |
 +-----+

U:5 - JSR - File #2 MAIN - 14
 SBR - File #5 COMM_CHK - 0

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING
 *****

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO END

2:0015 T4:0.DN Q2:1
 [ ] [JMP]

Q2:1 - JMP - File #2 MAIN - 15
 LBL - File #2 MAIN - 18

GENERAL CONTROL
 SEQUENCING
 SUBROUTINE

2:0016 +--JSR--
 | Jump To Subroutine |
 | File #: U:6 |
 +-----+

U:6 - JSR - File #2 MAIN - 16
 SBR - File #6 GEN_CTRL - 0

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
Lockheed Martin Hanford Co.
Page:00007

File #2 MAIN Proj:PLC1

08:15:25 02/19/99

```

      ONE SECOND
      SINGLE SCAN
      PULSE
      1_SEC_PULSE
      B372
      ALWAYS OFF
      OUTPUT
      ALWAYS_OFF
      B370
      PLC SEQUENCING
      DEMONSTRATION
      PROGRAM FILE
2:0017 +---JSR-----+
      | Jump To Subroutine |
      | File #:           U:9 |
      +---+
      ONE MINUTE
      SINGLE SCAN
      PULSE
      1_MIN_PULSE
      B377
      U:9      - JSR      - File #2 MAIN - 17
      *THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE
      MAIN PROGRAM
      FILE START-UP
      JUMP TO END
      MCP FILE #2
      END OF PROGRAM
      COMMENT COIL
2:0018 Q2:1      B3/37
      [LBL]      ( )
      B3/37      - - ( ) - - File #2 MAIN - 18
2:0019 [End]
```

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
PROCESSOR FAULT ROUTINE PROGRAM FILE.
Lockheed Martin Hanford Co.
Page:00008

HNF-2346, Rev. 1

File #3 PRO_FLT Proj:PLC1

08:15:25 02/19/99

*****
*THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL
*OCCURE
*ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN,
*A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE
*COPIED
*INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.
*****

First scan
of ladder
or SFC
step

PROCESSOR
FAULT ROUTINE
JUMP TO END

3:0000 S:1/15
-----|-----

Q3:0
-----[JMP]-----

Q3:0 - JMP - File #3 PRO_FLT - 0
LBL - File #3 PRO_FLT - 2

Logical Rack
Status Bits
For Racks 0-7

3:0001

+-BTD-----+
| Bit Field Distributor |
| Source: S:7 |
| Source Bit: 0 |
| Dest: N10:7 |
| Dest Bit: 0 |
| Length: 8 |
+-----+

Last
program
scan time
ladder &
SFC

+-COP-----+
| Copy File |
| Source: #S:8 |
| Dest: #N10:8 |
| Length: 16 |
+-----+

S:7 - BTD - File #3 PRO_FLT - 1
N10:7 - BTD - File #3 PRO_FLT - 1
FILE _F:S002:0081%016 LEN 16 - COP - File #3 PRO_FLT - 1
FILE _F:N010:0081%016 LEN 16 - COP - File #3 PRO_FLT - 1

PROCESSOR
FAULT ROUTINE
JUMP TO END

FAULT ROUTINE
FILE #3
END OF PROGRAM
COMMENT COIL

3:0002 Q3:0
-----[LBL]-----

B3/38
----- ( ) -----

B3/38 - ( ) - File #3 PRO_FLT - 2

REGISTER FOR
VERIFYING
FAULT ROUTINE
FILE OPERATION

3:0003

+-ADD-----+
| Add |
| Source A: N10:0 |
| Source B: 0 |
| Dest: N10:0 |
+-----+

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
PROCESSOR FAULT ROUTINE PROGRAM FILE.
Lockheed Martin Hanford Co.
Page:00009

File #3 PRO_FLT Proj:PLC1

08:15:26 02/19/99

N10:0 - ADD - File #3 PRO_FLT - 3,3
N10:0 - ADD - File #3 PRO_FLT - 3,3

3:0004

[End]

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 ANALOG INPUTS BLOCK TRANSFER & DH+ MESSAGES SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00010

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:26 02/19/99

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

PROGRAM
 FILE #4 START
 OF SUBROUTINE
 COMMENT COIL

4:0000 +--SBR-----+
 |Subroutine |
 +-----+-----+

B3/39
 ( )

B3/39 - ( ) - File #4 REG_10 - 0

ANALOG MODULE
 POWERED UP BUT
 NOT CONFIGURED

4:0001 N13:0/0 BT12:0.EN BT12:1.EN
 -----| |-----|/|-----|/|

+--BTW-----+
 |Block Transfer Write |-(EN)-
 |Mod Type: 1771-IFE |
 |12 Bit Analog Input |-(DN)-
 |Rack: 0 |
 |Group: 0 |-(ER)-
 |Module: 0 |
 |Control Block: BT12:1 |
 |Data File: N13:28 |
 |Length: 15 |
 |Continuous: N |
 +-----+

BT12:1.EN - BTW - File #4 REG_10 - 1
 -|/| - File #4 REG_10 - 1,2
 N13:28 - BTW - File #4 REG_10 - 1,1

4:0002 BT12:0.EN BT12:1.EN
 -----|/|-----|/|

+--BTR-----+
 |Block Transfer Read |-(EN)-
 |Mod Type: 1771-IFE |
 |12 Bit Analog Input |-(DN)-
 |Rack: 0 |
 |Group: 0 |-(ER)-
 |Module: 0 |
 |Control Block: BT12:0 |
 |Data File: N13:0 |
 |Length: 9 |
 |Continuous: N |
 +-----+

BT12:0.EN - -|/| - File #4 REG_10 - 1
 BTR - File #4 REG_10 - 2
 -|/| - File #4 REG_10 - 2
 -| - File #4 REG_10 - 3
 N13:0/1 - -| - File #4 REG_10 - 1
 BTR - File #4 REG_10 - 2,2
 -| - File #4 REG_10 - 10,11,12,13,14,15,16,17

FLUSH PUMP
 P-3100A
 OUTLET FLOW
 FT-302C-1

4:0003 BT12:0.DN
 -----|

+--COP-----+
 |Copy File |
 |Source: #N13:4 |
 |Dest: #N20:0 |
 |Length: 8 |
 +-----+

FILE _F:N013:0001%009 LEN 9 - BTR - File #4 REG_10 - 2
 FILE _F:N013:0001%009 LEN 9 - COP - File #4 REG_10 - 3
 FILE _F:N020:0001%008 LEN 8 - COP - File #4 REG_10 - 3
 File #5 COMM_CHK - 5
 FILE _F:N020:0001%008 LEN 8 - FAL - File #9 DEMO - 15

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 ANALOG INPUTS BLOCK TRANSFER & DH+ MESSAGES SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00011

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:26 02/19/99

4:0004 BT12:2.EN BT12:3.EN
 -|/|- -|/|-

FLOW CONTROL
 CHEN ADD
 PUMP P-3100B
 P-3100BR

+--COP--+
 Copy File
 Source: #N20:16
 Dest: #N13:62
 Length: 4

+--BTW--+
 Block Transfer Write (EN)
 Mod Type: 1771-0FE (DN)
 12 Bit Analog Output
 Rack: 0
 Group: 1 (ER)
 Module: 0
 Control Block: BT12:3
 Data File: N13:62
 Length: 13
 Continuous: N

FILE F:N020:0161X004 LEN 4 - COP - File #4 REG_10 - 4
 FILE F:N013:0621X004 LEN 4 - COP - File #4 REG_10 - 4
 FILE F:N013:0621X004 LEN 4 - BTW - File #4 REG_10 - 4
 FILE F:N013:0621X004 LEN 4 - COP - File #5 COMM_CHK - 5
 BT12:3.EN - BTW - File #4 REG_10 - 4
 -|/|- - File #4 REG_10 - 4,5
 N13:62 - COP - File #4 REG_10 - 4
 BTW - File #4 REG_10 - 4
 COP - File #4 REG_10 - 4
 BTW - File #4 REG_10 - 4
 COP - File #5 COMM_CHK - 5,5

ALWAYS OFF
 OUTPUT
 ALWAYS OFF

4:0005 B3/O BT12:2.EN BT12:3.EN
 -|/|- -|/|-

+--BTR--+
 Block Transfer Read (EN)
 Mod Type: 1771-0FE (DN)
 12 Bit Analog Output
 Rack: 0
 Group: 1 (ER)
 Module: 0
 Control Block: BT12:2
 Data File: N13:57
 Length: 5
 Continuous: N

BT12:2.EN -|/|- File #4 REG_10 - 4
 BTR - File #4 REG_10 - 5
 -|/|- File #4 REG_10 - 5
 N13:57 - BTR - File #4 REG_10 - 5,5

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 ANALOG INPUTS BLOCK TRANSFER & DH+ MESSAGES SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00012

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:27 02/19/99

```

4:0006  BT12:4.EN  BT12:5.EN  +--BTW-----+
-----|/|-----|/|-----+ Block Transfer Write +-(EN)-
                                         Mod Type:      1771-N
                                         High Resolution Analog I/O  -(DN)
                                         Rack:          0
                                         Group:         4
                                         Module:         0
                                         Control Block:   BT12:5
                                         Data File:       N13:103
                                         Length:          59
                                         Continuous:      N
                                         +-----+

BT12:5.EN  - BTW  - File #4 REG_10 - 6
            - |/| - File #4 REG_10 - 6,7
N13:103     - BTW  - File #4 REG_10 - 6,6

4:0007  BT12:4.EN  BT12:5.EN  +--BTR-----+
-----|/|-----|/|-----+ Block Transfer Read  +-(EN)-
                                         Mod Type:      1771-N
                                         High Resolution Analog I/O  -(DN)
                                         Rack:          0
                                         Group:         4
                                         Module:         0
                                         Control Block:   BT12:4
                                         Data File:       N13:75
                                         Length:          28
                                         Continuous:      N
                                         +-----+

BT12:4.EN  - |/| - File #4 REG_10 - 6
            - BTR - File #4 REG_10 - 7
            - |/| - File #4 REG_10 - 7
            - |/| - File #4 REG_10 - 8
N13:75     - BTR - File #4 REG_10 - 7,7
  
```

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
ANALOG INPUTS BLOCK TRANSFER & DH+ MESSAGES SEQUENCING
Lockheed Martin Hanford Co.
Page:00013

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:27 02/19/99

4:0008

BT12:4.DN

TANK
TK-302-C
TEMPERATURE
TE-302C-1

+---DIV-----+
Div
Source A: N13:80 432
Source B: 10
Dest: N20:8 43
+-----+

FLUSH PUMP
P-3100A
OUTLET TEMP
LINE 3
TE-302C-2

+---DIV-----+
Div
Source A: N13:82 536
Source B: 10
Dest: N20:9 54
+-----+

SPARE
THERMOCOUPLE
INPUT

+---DIV-----+
Div
Source A: N13:84 25016
Source B: 10
Dest: N20:10 2502
+-----+

SPARE
THERMOCOUPLE
INPUT

+---DIV-----+
Div
Source A: N13:86 25016
Source B: 10
Dest: N20:11 2502
+-----+

SPARE
THERMOCOUPLE
INPUT

+---DIV-----+
Div
Source A: N13:88 25016
Source B: 10
Dest: N20:12 2502
+-----+

SPARE
THERMOCOUPLE
INPUT

```
--DIV--
div
Source A: N13:90
          25016
Source B: 10
          10
Dest: N20:13
       2502
```

SPARE
THERMOCOUPLE
INPUT

```
--DIV--
div
Source A: N13:92
          25016
Source B: 10
          10
Dest: N20:14
       2502
```

SPARE
THERMOCOUPLE
INPUT

```
--DIV--
div
Source A: N13:94
          25016
Source B: 10
          10
Dest: N20:15
       2502
```

```
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:8 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15
        ADD - File #9 DEMO - 15
        FAL - File #9 DEMO - 15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:9 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15,15,15,15,15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:10 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15,15,15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:11 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15,15,15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:12 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15,15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:13 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15,15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:14 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
        FAL - File #9 DEMO - 15,15
FILE_F:N013:0751%028 LEN 28 - BTR - File #4 REG_10 - 7
FILE_F:N013:0751%028 LEN 28 - DIV - File #4 REG_10 - 8
N20:15 - DIV - File #4 REG_10 - 8
        COP - File #5 COMM_CHK - 5
```

	ANALOG MODULE UNDERRANGE BITS REGISTER	ANALOG MODULE OVERRANGE BITS REGISTER	ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE
4:0009	+-EQU-----+ Equal (A=B) Source A: N13:1 249 Source B: 0 0 +-+-----+	+-EQU-----+ Equal (A=B) Source A: N13:2 0 Source B: 0 0 +-+-----+	B3/48 ( )
	B3/48 - ( ) - File #4 REG_10 - 9 - - File #4 REG_10 - 10,11,12,13,14,15,16,17		
4:0010	ANALOG MODULE CHAN. 1 DATA UNDERRANGE N13:1/0 -----	FLUSH PUMP P-3100A OUTLET FLOW FT-302C-1R +-LIM-----+ Limit Test (Circular) Low Lim: 5 5 Test: N13:4 0 High Lim: -5 -5 +-+-----+	PCU-1 INPUT ANALOG OVER OR UNDER RANGE ALARM FI-302C-1_A N14:11/0 -----
	ANALOG MODULE CHAN. 1 DATA OVERRANGE N13:2/0 -----		
	ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE N13:0/1 -----	ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE B3/48 -----	
	N14:11/0 - ( ) - File #4 REG_10 - 10		

N14:11/1 - - ( ) - - File #4 REG_I0 - 11

N14:11/2 - - ( ) - - File #4 REG_I0 - 12

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00017

HNF-2346, Rev. 1

File #4 REG_I0 Proj:PLC1

08:15:28 02/19/99

N14:11/3 --( )-- File #4 REG_I0 - 13

N14:11/4 --( )-- File #4 REG_I0 - 14

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00018

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:28 02/19/99

N14:11/5 - - ( ) - - File #4 REG_10 - 15

N14:11/6 - - ( ) - - File #4 REG_10 - 16

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00019

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:28 02/19/99

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
ANALOG INPUT OVER / UNDER RANGE ALARMS
Lockheed Martin Hanford Co.
Page:00020

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC1

08:15:28 02/19/99

N14:12/13 - -( ) - - File #4 REG_I0 - 23

THERM. MODULE
CHAN. 7 DATA
UNDERRANGEPCU-1 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU1-SP-TI-7_A
N14:12/14
-( )-----4:0024 +-----+
| N13:91/0 |
+-----+
| THERM. MODULE |
| CHAN. 7 DATA |
| UNDERRANGE |
+-----+
| N13:91/1 |
+-----+
| |

N14:12/14 - -( ) - - File #4 REG_I0 - 24

THERM. MODULE
CHAN. 8 DATA
UNDERRANGEPCU-1 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU1-SP-TI-8_A
N14:12/15
-( )-----4:0025 +-----+
| N13:93/0 |
+-----+
| THERM. MODULE |
| CHAN. 8 DATA |
| UNDERRANGE |
+-----+
| N13:93/1 |
+-----+
| |

N14:12/15 - -( ) - - File #4 REG_I0 - 25

I/O HANDLING
FOR ANALOG OR
OTHER REG IN
SUBROUTINE4:0026 +---RET-----+
| Return () |
+-----+

4:0027 -----[End]-

File #5 COMM CHK Proj:PLC1

08:15:29 02/19/99

DATA HIGHWAY +
COMMUNICATIONS
CTRL & CHECK
SUBROUTINE

```
PROGRAM
FILE #5 START
OF SUBROUTINE
COMMENT COIL
```

```
5:0000 | +--SBR-----+
        | Subroutine  |
```

B3/40
-- ( ) --

83/40 - - ( ) - - File #5 COMM CHK - 0

HEARTBEAT
FROM OCS
TO PLC-1
HB OCS PLC1
NT4:120/0

HEARTBEAT
FROM PLC-1
TO OCS
HB PLC1 OCS
N14:070

5:0001 | ---- [/] ----

```

N14:0/0      - - ( ) - - File #5 COMM_CHK - 1
              - - / - - File #5 COMM_CHK - 2
              - - / - - File #5 COMM_CHK - 2

```

HEARTBEAT COMMUN. LOSS
FROM PLC-1 WITH OCS
TO OCS ONE-SHOT
HB_PLC1_OCS

COMM LOSS
TIMER
WITH OCS

5:0002 -+-----|-----[ONS]

```

+-----+
| Timer Off Delay |-(EN)
| Timer:          |T4:40
| Base (SEC):     |1.0  -(DN)
| Preset:         |30
| Accum:          |30
+-----+

```

HEARTBEAT COMMUN. LOSS
FROM PLC-1 WITH OCS
TO OCS ONE-SHOT
HB PLC1 OCS
N14:070 B3/201
-----[ONS]-----

```
T4:40.DN      - T0F      - File #5 COMM_CHK - 2
               - ||| - - File #5 COMM_CHK - 3
```

COMM LOSS	ALWAYS OFF
TIMER	OUTPUT
WITH OCS	ALWAYS OFF

COMMUN. WITH
OCS
IGNORED
COM-1_OCS
N14:0/1

5:0003 14:40 DN 8370
-----|/|-----|

N14:0/1 - -( )- - File #5 COMM_CHK - 3

Battery
is bad or
missing

PLC-1 BATTERY
IS BAD OR
MISSING
BATT BAD PLC1
NT4:076

5:0004 | S:10/0
-----| | -

N14:0/6 - -( )- - File #5 COMM CHK - 4

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00023

HNF-2346, Rev. 1

File #5 COMM_CHK Proj:PLC1

08:15:29 02/19/99

ONE SECOND
 SINGLE SCAN
 PULSE
 1_SEC PULSE
 B3/2

5:0005

DIGITAL INPUT
 REGISTER TO
 OIT TERMINALS

```

+--MOV-----+
| Move
| Source: 1:003
|           35
| Dest:  N14:26
|           35
+-----+

```

DIGITAL OUTPUT
 REGISTER TO
 OIT TERMINALS

```

+--MOV-----+
| Move
| Source: 0:007
|           25
| Dest:  N14:29
|           25
+-----+

```

FLUSH PUMP
 P-3100A
 OUTLET FLOW
 FI-302C-1

```

+--COP-----+
| Copy File
| Source:  #N20:0
| Dest:   #N14:30
| Length:    16
+-----+

```

FLOW CONTROL
 CHEM ADD
 PUMP P-3100B
 FI-302C-2A

```

+--COP-----+
| Copy File
| Source:  #N13:62
| Dest:   #N14:46
| Length:    4
+-----+

```

```

1:003/006 - MOV - File #5 COMM_CHK - 5
          - | | - File #6 GEN_CTRL - 24,25,36
N14:26 - MOV - File #5 COMM_CHK - 5
0:007/005 - MOV - File #5 COMM_CHK - 5
          - ( ) - File #6 GEN_CTRL - 1,9
          - ( ) - File #6 GEN_CTRL - 10
          - ( ) - File #6 GEN_CTRL - 12,12,32,33
          - ( ) - File #6 GEN_CTRL - 34
          - / - File #6 GEN_CTRL - 35
          - - - File #6 GEN_CTRL - 36
N14:29 - MOV - File #5 COMM_CHK - 5
FILE_F:N020:0001%008 LEN 8 - COP - File #4 REG_I0 - 3
          File #5 COMM_CHK - 5
FILE_F:N020:0001%008 LEN 8 - FAL - File #9 DEMO - 15
FILE_F:N014:0301%016 LEN 16 - COP - File #5 COMM_CHK - 5
FILE_F:N013:0621%004 LEN 4 - COP - File #4 REG_I0 - 4
FILE_F:N013:0621%004 LEN 4 - BTW - File #4 REG_I0 - 4
FILE_F:N013:0621%004 LEN 4 - COP - File #5 COMM_CHK - 5
FILE_F:N014:0461%004 LEN 4 - COP - File #5 COMM_CHK - 5

```

*****
 *COMMUNICATION BETWEEN PCU-1 AND PCU-2
 *****

HEARTBEAT
 FROM PCU-2
 TO PCU-1
 HB-21
 N19:2/1

HEARTBEAT
 FROM PCU-1
 TO PCU-2
 HB-12
 N19:1/2

5:0006

N19:1/2 - ( ) - File #5 COMM_CHK - 6
 - | - File #5 COMM_CHK - 7
 - | - File #5 COMM_CHK - 7

HEARTBEAT COMMUN. LOSS
 FROM PCU-1 WITH PCU-2
 TO PCU-2 ONE-SHOT

COMMUN. LOSS
 TIMER WITH
 PCU-2

5:0007

N19:1/2 B3/81
 - | - [ONS]
 HEARTBEAT COMMUN. LOSS
 FROM PCU-1 WITH PCU-2
 TO PCU-2 ONE-SHOT
 HB-12
 N19:1/2 B3/82
 - | - [ONS]

+---TOF---+
 Timer Off Delay +-(EN)-
 Timer: T4:4
 Base (SEC): 1.0 -(DN)
 Preset: 5
 Accum: 0

T4:4.DN - TOF - File #5 COMM_CHK - 7
 - | - File #5 COMM_CHK - 8

COMMUN. LOSS
 TIMER WITH
 PCU-2

COMMUN. WITH
 PCU-2
 IGNORED
 COM-12
 N14:0/2

5:0008

T4:4.DN
 - | -
 N14:0/2 - ( ) - File #5 COMM_CHK - 8
 - | - File #5 COMM_CHK - 9,26

COMMUN. WITH
 PCU-2
 IGNORED
 COM-12
 N14:0/2

5:0009

R6:10.IN
 (U)

COMPARE
 PCU-1 TO PCU-2
 MSG FILE
 WITH PREVIOUS

MG11:0.EN

+-FSC-
 File Search/Compare
 Control: R6:10
 Length: 20
 Position: 0
 Mode: ALL
 Expression:
 #N21:20 <> #N21:120

-(EN)

-(DN)

-(ER)

R6:10.FD

+-COP-
 Copy File
 Source: #N21:20
 Dest: #N21:220
 Length: 20

SEND MSG
 FROM PCU-1
 TO PCU-2

+-MSG-
 Send/Receive Message
 Control Block: MG11:0
 -(EN)
 -(DN)
 -(ER)

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:0.DN B3/160

+-COP-
 Copy File
 Source: #N21:220
 Dest: #N21:120
 Length: 20

R6:10.IN - FSC - File #5 COMM_CHK - 9
 -| - File #5 COMM_CHK - 9
 -(U) - File #5 COMM_CHK - 9,10
 RES - File #5 COMM_CHK - 10
 -| - File #5 COMM_CHK - 10,10
 R6:10.IN - FSC - File #5 COMM_CHK - 9
 -| - File #5 COMM_CHK - 9
 -(U) - File #5 COMM_CHK - 9,10
 RES - File #5 COMM_CHK - 10
 -| - File #5 COMM_CHK - 10,10
 FILE_F:N021:0201%020 LEN 20 - COP - File #5 COMM_CHK - 9
 FILE_F:N021:0201%020 LEN 20 - MSG - File #5 COMM_CHK - 9
 FILE_F:N021:0201%020 LEN 20 - COP - File #5 COMM_CHK - 9
 FILE_F:N021:0201%020 LEN 20 - MSG - File #5 COMM_CHK - 9
 FILE_F:N021:2201%020 LEN 20 - COP - File #5 COMM_CHK - 9,9
 MG11:0.EN - MSG - File #5 COMM_CHK - 9
 -| - File #5 COMM_CHK - 9
 -| - File #5 COMM_CHK - 9
 FILE_F:N021:2201%020 LEN 20 - COP - File #5 COMM_CHK - 9,9

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00026

HNF-2346, Rev. 1

File #5 COMM_CHK Proj:PLC1

08:15:30 02/19/99

FILE_F:N021:1201%020 LEN 20 - C0P - File #5 COMM_CHK - 9

COMPARE
 PCU-1 TO PCU-2
 MSG FILE
 WITH PREVIOUS

5:0010 R6:10.DN
 R6:10.FD
 R6:10.IN - FSC - File #5 COMM_CHK - 9
 -| - File #5 COMM_CHK - 9
 -(U) - File #5 COMM_CHK - 9,10
 RES - File #5 COMM_CHK - 10
 R6:10.IN -| - File #5 COMM_CHK - 10,10
 - FSC - File #5 COMM_CHK - 9
 -| - File #5 COMM_CHK - 9
 -(U) - File #5 COMM_CHK - 9,10
 RES - File #5 COMM_CHK - 10
 -| - File #5 COMM_CHK - 10,10

*COMMUNICATION BETWEEN PCU-1 AND PCU-3

HEARTBEAT FROM PCU-3 TO PCU-1
 HB-31
 N19:3/1
 5:0011
 HEARTBEAT FROM PCU-1 TO PCU-3
 HB-13
 N19:1/3
 N19:1/3 - - ( ) - File #5 COMM_CHK - 11
 -| - File #5 COMM_CHK - 12
 -| - File #5 COMM_CHK - 12

HEARTBEAT FROM PCU-1 TO PCU-3
 HB-13
 N19:1/3
 5:0012
 COMMUN. LOSS WITH PCU-3
 ONE-SHOT
 B3/83
 [ONS]
 COMMUN. LOSS TIMER WITH PCU-3
 +--TOF
 Timer Off Delay
 Timer: T4:5
 Base (SEC): 1.0
 Preset: 5
 Accum: 0
 (EN)
 (DN)
 HEARTBEAT FROM PCU-1 TO PCU-3
 HB-13
 N19:1/3
 COMMUN. LOSS WITH PCU-3
 ONE-SHOT
 B3/84
 [ONS]

T4:5.DN - TOF - File #5 COMM_CHK - 12
 -| - File #5 COMM_CHK - 13

COMMUN. LOSS TIMER WITH PCU-3
 T4:5.DN
 5:0013
 COMMUN. WITH PCU-3
 IGNORED
 COM-13
 N14:0/3
 ( )
 N14:0/3 - - ( ) - File #5 COMM_CHK - 13
 -| - File #5 COMM_CHK - 14

N14:0/3 - -||- - File #5 COMM_CHK - 28

COMMUN. WITH
 PCU-3
 IGNORED
 COM-13
 N14:0/3
 N14:0/3

5:0014

R6:11.IN
 (U)

COMPARE
 PCU-1 TO PCU-3
 MSG FILE
 WITH PREVIOUS

MG11:1.EN

File Search/Compare (EN)
 Control: R6:11
 Length: 20 (DN)
 Position: 0
 Mode: ALL (ER)
 Expression:
 #N21:40 <> #N21:140

R6:11.FD

Copy File
 Source: #N21:40
 Dest: #N21:240
 Length: 20

SEND MSG
 FROM PCU-1
 TO PCU-3

Send/Receive Message (EN)
 Control Block: MG11:1 (DN)
 (ER)

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:1.DN B3/161

Copy File
 Source: #N21:240
 Dest: #N21:140
 Length: 20

R6:11.IN - FSC - File #5 COMM_CHK - 14
 - || - File #5 COMM_CHK - 14
 (U) - File #5 COMM_CHK - 14,15
 RES - File #5 COMM_CHK - 15
 - || - File #5 COMM_CHK - 15,15
 R6:11.IN - FSC - File #5 COMM_CHK - 14
 - || - File #5 COMM_CHK - 14
 (U) - File #5 COMM_CHK - 14,15
 RES - File #5 COMM_CHK - 15
 - || - File #5 COMM_CHK - 15,15
 FILE F:N021:040I%020 LEN 20 - COP - File #5 COMM_CHK - 14
 FILE F:N021:040I%020 LEN 20 - MSG - File #5 COMM_CHK - 14
 FILE F:N021:040I%020 LEN 20 - COP - File #5 COMM_CHK - 14
 FILE F:N021:040I%020 LEN 20 - MSG - File #5 COMM_CHK - 14
 FILE F:N021:240I%020 LEN 20 - COP - File #5 COMM_CHK - 14,14
 MG11:1.EN - MSG - File #5 COMM_CHK - 14
 - || - File #5 COMM_CHK - 14
 - || - File #5 COMM_CHK - 14

FILE F:N021:2401%020 LEN 20 - COP - File #5 COMM_CHK - 14,14
 FILE F:N021:1401%020 LEN 20 - COP - File #5 COMM_CHK - 14

COMPARE
 PCU-1 TO PCU-3
 MSG FILE
 WITH PREVIOUS

R6:11.IN - FSC - File #5 COMM_CHK - 14
 - | - File #5 COMM_CHK - 14
 - (U) - File #5 COMM_CHK - 14,15
 RES - File #5 COMM_CHK - 15
 - | - File #5 COMM_CHK - 15,15
 R6:11.IN - FSC - File #5 COMM_CHK - 14
 - | - File #5 COMM_CHK - 14
 - (U) - File #5 COMM_CHK - 14,15
 RES - File #5 COMM_CHK - 15
 - | - File #5 COMM_CHK - 15,15

COMMUNICATION BETWEEN PCU-1 AND PCU-4

HEARTBEAT
 FROM PCU-4
 TO PCU-1
 HB-41
 N19:4/1

HEARTBEAT
 FROM PCU-1
 TO PCU-4
 HB-14
 N19:1/4

HEARTBEAT COMMUN. LOSS
 FROM PCU-1 WITH PCU-4
 TO PCU-4 ONE-SHOT

COMMUN. LOSS
 TIMER WITH
 PCU-4

T4:6.DN - TOF - File #5 COMM_CHK - 17
 - | - File #5 COMM_CHK - 18

COMMUN. LOSS
 TIMER WITH
 PCU-4

COMMUN. WITH
 PCU-4
 IGNORED
 COM-14
 N14:0/4
 ( )

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00030

File #5 COMM_CHK Proj:PLC1

08:15:00 02/19/99

FILE F:N021:2601%020 LEN 20 - COP - File #5 COMM_CHK - 19,19
 FILE F:N021:1601%020 LEN 20 - COP - File #5 COMM_CHK - 19

COMPARE
 PCU-1 TO PCU-4
 MSG FILE
 WITH PREVIOUS

5:0020 R6:12.DN R6:12
 [RES]
 R6:12.FD R6:12.FD
 (U)

R6:12.IN - FSC - File #5 COMM_CHK - 19
 - [ ] - File #5 COMM_CHK - 19
 - (U) - File #5 COMM_CHK - 19,20
 RES - File #5 COMM_CHK - 20
 - [ ] - File #5 COMM_CHK - 20,20
 R6:12.IN - FSC - File #5 COMM_CHK - 19
 - [ ] - File #5 COMM_CHK - 19
 - (U) - File #5 COMM_CHK - 19,20
 RES - File #5 COMM_CHK - 20
 - [ ] - File #5 COMM_CHK - 20,20

*COMMUNICATION BETWEEN PCU-1 AND PCU-5

HEARTBEAT
 FROM PCU-5
 TO PCU-1
 HB-51
 N19:5/1

HEARTBEAT
 FROM PCU-1
 TO PCU-5
 HB-15
 N19:1/5

5:0021 N19:1/5 - ( ) - File #5 COMM_CHK - 21
 - [ ] - File #5 COMM_CHK - 22
 - [ ] - File #5 COMM_CHK - 22

HEARTBEAT COMMUN. LOSS
 FROM PCU-1 WITH PCU-5
 TO PCU-5 ONE-SHOT

COMMUN. LOSS
 TIMER WITH
 PCU-5

5:0022 N19:1/5 B3/87
 [ONS] +--TOF--+
 HEARTBEAT COMMUN. LOSS
 FROM PCU-1 WITH PCU-5
 TO PCU-5 ONE-SHOT
 HB-15
 N19:1/5 B3/88
 [ONS] +--Timer Off Delay--+ (EN)
 Timer: T4:7
 Base (SEC): 1.0 (DN)
 Preset: 5
 Accum: 0

T4:7.DN - TOF - File #5 COMM_CHK - 22
 - [ ] - File #5 COMM_CHK - 23

COMMUN. LOSS
 TIMER WITH
 PCU-5

COMMUN. WITH
 PCU-5
 IGNORED
 COM-15
 N14:0/5
 ( )

5:0023 T4:7.DN
 [ ]

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00031

File #5 COMM_CHK Proj:PLC1

08:15:00 02/19/99

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00032

HNF-2346, Rev. 1

File #5 COMM_CHK Proj:PLC1

08:15:01 02/19/99

FILE F:N021:2801%020 LEN 20 - CDP - File #5 COMM_CHK - 24,24
 FILE F:N021:1801%020 LEN 20 - CDP - File #5 COMM_CHK - 24

COMPARE
 PCU-1 TO PCU-5
 MSG FILE
 WITH PREVIOUS

COMMUN. WITH
 PCU-2
 IGNORED
 COM-12
 N14:0/2

5:0026

R6:2.IN

(U)

MG11:4.EN

```

+--FSC-----+
|File Search/Compare|-(EN)
+-----+
|Control:      R6:2|
|Length:       18|-(DN)
|Position:      0|
|Mode:         ALL|-(ER)
|Expression:    |
|#N14:150 <> #N22:100|

```

R6:2.FD

```

+--COP-----+
|Copy File|
|Source:   #N14:150|
|Dest:    #N22:150|
|Length:   18|

```

```

+--MSG-----+
|Send/Receive Message|-(EN)
|Control Block: MG11:4|-(DN)
|                  |-(ER)

```

MG11:4.DN B3/164

```

+--COP-----+
|Copy File|
|Source:   #N22:150|
|Dest:    #N22:100|
|Length:   18|

```

```

R6:2.IN  - FSC - File #5 COMM_CHK - 26
          -| | - File #5 COMM_CHK - 26
          -(U) - File #5 COMM_CHK - 26,27
          RES - File #5 COMM_CHK - 27
          -| | - File #5 COMM_CHK - 27,27
R6:2.IN  - FSC - File #5 COMM_CHK - 26
          -| | - File #5 COMM_CHK - 26
          -(U) - File #5 COMM_CHK - 26,27
          RES - File #5 COMM_CHK - 27
          -| | - File #5 COMM_CHK - 27,27
FILE_F: N014:150%018 LEN 18 - COP - File #5 COMM_CHK - 26
FILE_F: N014:150%018 LEN 18 - MSG - File #5 COMM_CHK - 26
FILE_F: N014:150%018 LEN 18 - COP - File #5 COMM_CHK - 26
FILE_F: N014:150%018 LEN 18 - MSG - File #5 COMM_CHK - 26
FILE_F: N022:150%018 LEN 18 - COP - File #5 COMM_CHK - 26,26
MG11:4.EN - MSG - File #5 COMM_CHK - 26
          -| | - File #5 COMM_CHK - 26
          -| | - File #5 COMM_CHK - 26
FILE_F: N022:150%018 LEN 18 - COP - File #5 COMM_CHK - 26,26

```

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00034

HNF-2346, Rev. 1

File #5 COMM_CHK Proj:PLC1

08:15:01 02/19/99

FILE _F:N022:1001%018 LEN 18 - C0P - File #5 COMM_CHK - 26

5:0027

R6:2.DN

R6:2
[RES]

R6:2.FD

R6:2.FD
(U)

R6:2.IN - FSC - File #5 COMM_CHK - 26
 -| - File #5 COMM_CHK - 26
 -(U) - File #5 COMM_CHK - 26,27
 RES - File #5 COMM_CHK - 27
 -| - File #5 COMM_CHK - 27,27
 R6:2.IN - FSC - File #5 COMM_CHK - 26
 -| - File #5 COMM_CHK - 26
 -(U) - File #5 COMM_CHK - 26,27
 RES - File #5 COMM_CHK - 27
 -| - File #5 COMM_CHK - 27,27

COMMUN. WITH
 PCU-3
 IGNORED
 COM-13
 N14:0/3

5:0028

R6:3.IN

(U)

MG11:5.EN

```

+--FSC-----+
+--| |-----+ File Search/Compare |-(EN)
+--| |-----+ Control: R6:3 |-(DN)
+--| |-----+ Length: 3 |-(ER)
+--| |-----+ Position: 0
+--| |-----+ Mode: ALL
+--| |-----+ Expression:
+--| |-----+ #N14:170 <> #N23:100

```

R6:3.FD

```

+--COP-----+
+--| |-----+ Copy File
+--| |-----+ Source: #N14:170
+--| |-----+ Dest: #N23:150
+--| |-----+ Length: 3

```

```

+--MSG-----+
+--| |-----+ Send/Receive Message |-(EN)
+--| |-----+ Control Block: MG11:5 |-(DN)
+--| |-----+ |-(ER)

```

MG11:5.DN B3/165

```

+--COP-----+
+--| |-----+ [ONS] Copy File
+--| |-----+ Source: #N23:150
+--| |-----+ Dest: #N23:100
+--| |-----+ Length: 3

```

```

R6:3.IN - FSC - File #5 COMM_CHK - 28
        - | | - File #5 COMM_CHK - 28
        - (U) - File #5 COMM_CHK - 28,29
        RES - File #5 COMM_CHK - 29
        - | | - File #5 COMM_CHK - 29,29
R6:3.IN - FSC - File #5 COMM_CHK - 28
        - | | - File #5 COMM_CHK - 28
        - (U) - File #5 COMM_CHK - 28,29
        RES - File #5 COMM_CHK - 29
        - | | - File #5 COMM_CHK - 29,29
FILE_F:N014:170I%003 LEN 3 - COP - File #5 COMM_CHK - 28
FILE_F:N014:170I%003 LEN 3 - MSG - File #5 COMM_CHK - 28
FILE_F:N014:170I%003 LEN 3 - COP - File #5 COMM_CHK - 28
FILE_F:N014:170I%003 LEN 3 - MSG - File #5 COMM_CHK - 28
FILE_F:N023:150I%003 LEN 3 - COP - File #5 COMM_CHK - 28,28
MG11:5.EN - MSG - File #5 COMM_CHK - 28
          - | | - File #5 COMM_CHK - 28
          - | | - File #5 COMM_CHK - 28
FILE_F:N023:150I%003 LEN 3 - COP - File #5 COMM_CHK - 28,28

```


Hanford Cross Site Transfer System (PCU-1)
COMMUNICATION HANDLING SUBROUTINE
Lockheed Martin Hanford Co.
Page:00036

08:15:02 02/19/99

FILE _F:N023:100I%003 LEN 3 - COP - File #5 COMM_CHK - 28

R6:3.DN

R6:3

- [RES]

R6:3.FD

R6:3.FD

---(U)

```

R6:3.IN - FSC - File #5 COMM CHK - 28
          -| -| - File #5 COMM CHK - 28
          - (U) - File #5 COMM CHK - 28,29
          RES - File #5 COMM CHK - 29
          -| -| - File #5 COMM CHK - 29,29
R6:3.IN - FSC - File #5 COMM CHK - 28
          -| -| - File #5 COMM CHK - 28
          - (U) - File #5 COMM CHK - 28,29
          RES - File #5 COMM CHK - 29
          -| -| - File #5 COMM CHK - 29,29

```

COMMUN. WITH
 PCU-4
 IGNORED
 COM-14
 N14:0/4
 -|/|-

5:0030

R6:4.IN
 -(U)-

MG11:6.EN

```

+--FSC-----+
-|/|- File Search/Compare -(EN)-
+--R6:4-----+
Control: R6:4 -(DN)
Length: 1
Position: 0
Mode: ALL -(ER)
Expression:
#N14:190 <> #N24:100
  
```

```

R6:4.FD +--COP-----+
-|/|- Copy File
Source: #N14:190
Dest: #N24:150
Length: 1
  
```

```

+--MSG-----+
+Send/Receive Message -(EN)-
Control Block: MG11:6 -(DN)
-(ER)
  
```

MG11:6.DN B3/166

```

-|/|- [ONS] +--COP-----+
Copy File
Source: #N24:150
Dest: #N24:100
Length: 1
  
```

```

R6:4.IN - FSC - File #5 COMM_CHK - 30
-|/|- File #5 COMM_CHK - 30
-(U)- File #5 COMM_CHK - 30,31
RES - File #5 COMM_CHK - 31
-|/|- File #5 COMM_CHK - 31,31
R6:4.IN - FSC - File #5 COMM_CHK - 30
-|/|- File #5 COMM_CHK - 30
-(U)- File #5 COMM_CHK - 30,31
RES - File #5 COMM_CHK - 31
-|/|- File #5 COMM_CHK - 31,31
FILE _F:N014:190%001 LEN 1 - COP - File #5 COMM_CHK - 30
FILE _F:N014:190%001 LEN 1 - COP - File #5 COMM_CHK - 30
FILE _F:N024:150%001 LEN 1 - COP - File #5 COMM_CHK - 30,30
MG11:6.EN - MSG - File #5 COMM_CHK - 30
-|/|- File #5 COMM_CHK - 30
-|/|- File #5 COMM_CHK - 30
FILE _F:N024:150%001 LEN 1 - COP - File #5 COMM_CHK - 30,30
FILE _F:N024:100%001 LEN 1 - COP - File #5 COMM_CHK - 30
  
```

Hanford Cross Site Transfer System (PCU-1)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00039

File #5 COMM_CHK Proj:PLC1

08:15:02 02/19/99

```
5:0033  +---+ R6:5.DN +-----+ R6:5 [RES] +---+
          | | |
          +---+ R6:5.FD +-----+ R6:5.FD +---+
          | | |
          +---+ (U) +---+

R6:5.IN - FSC - File #5 COMM_CHK - 32
        - | | - File #5 COMM_CHK - 32
        -(U) - File #5 COMM_CHK - 32,33
        RES - File #5 COMM_CHK - 33
        - | | - File #5 COMM_CHK - 33,33
R6:5.IN - FSC - File #5 COMM_CHK - 32
        - | | - File #5 COMM_CHK - 32
        -(U) - File #5 COMM_CHK - 32,33
        RES - File #5 COMM_CHK - 33
        - | | - File #5 COMM_CHK - 33,33

SUBROUTINE
5:0034  +---RET-----+
          |Return () |
          +-----+

5:0035  +-----[End]-
```

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
GENERAL CONTROL SEQUENCING FOR PCU #1
Lockheed Martin Hanford Co.
Page:00041

File #6 GEN_CTRL Proj:PLC1

08:15:03 02/19/99

	GENERAL CONTROL SEQUENCING SUBROUTINE	PROGRAM FILE #6 START OF SUBROUTINE COMMENT COIL
	+---SBR-----+ Subroutine +-----+-----+ B3/41 - -( ) - - File #6 GEN_CTRL - 0	B3/41 ( )
	*LEAK DETECTION CONTROL LOGIC, Y-72.1	
	INPUT SIGNAL TO 200-W MASTER SHUTDOWN CIRCUIT Y-72.1	INPUT SIGNAL TO 200-W MASTER SHUTDOWN Y-72.1 PCU-1 0:007/005
6:0001	N19:3/0 ----- / -----	771-0D16
	0:007/005 - -( ) - - File #6 GEN_CTRL - 1	

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
TRANSFER PUMP INTERLOCK LOGIC, Y-75.1
Lockheed Martin Hanford Co.
Page:00043

HNF-2346, Rev. 1

File #6 GEN_CTRL Proj:PLC1

08:15:03 02/19/99

File #6 GEN CTRL Proj:PLC1

Page: 00044

08:15:03 02/19/99

```

T4:11.DN - -|/- - File #6 GEN_CTRL - 6
TON      - File #6 GEN_CTRL - 7

START     TRANSFER
TRANSFER  PUMP          RESET TRANSFER
PUMP      P-102-SY-02A   PUMP RUN
P-102-SY-02A RECIRCULATION P-102-SY-02A
Y75        MODE Y-75.1    Y-75.1
HS-3102A   ZL-3102C
N14:120/6  N14:0/8       B3/76

-----|-----|-----|-----+---TOF-----+
6:0008 -----|-----|-----|-----|Timer Off Delay|- (EN)-
                                           Timer: T4:12
                                           Base (SEC): 0.01 - (DN)
                                           Preset: 150
                                           Accum: 150
                                           +-----+

T4:12.DN - TOF - File #6 GEN_CTRL - 8
         -|/- - File #6 GEN_CTRL - 9

                                START PUMP
                                P-102-SY-02A

                                Y75
                                MS-102-SY-A-1T
                                0:007/02
                                ( )
                                771-0016

6:0009 T4:12.DN
-----|-----
0:007/002 - -( ) - - File #6 GEN_CTRL - 9
           -|/- - File #6 GEN_CTRL - 10

START     START PUMP          START
TRANSFER  P-102-SY-02A        TRANSFER
PUMP      P-102-SY-02A        PUMP
P-102-SY-02A Y75             P-102-SY-02A
Y75        Y75               Y75
HS-3102A   MS-102-SY-A-1T    HS-3102A
N14:120/6  0:007/02         N14:120/6
6:0010 -----|-----
                               (U)
                               |
                               | 771-0D1
                               | TRANSFER
                               | PUMP
                               | P-102-SY-02A
                               | TRANSFER
                               | MODE Y-75.1
                               | ZL-3102D
                               | N14:0/9
                               | -----|-----
                               |
                               | RESET TRANSFER
                               | PUMP RUN
                               | P-102-SY-02A
                               | Y-75.1
                               |
                               | B3/76
                               | -----|-----
                               |

N14:120/6 - -|/- - File #6 GEN_CTRL - 8
           -(U)- - File #6 GEN_CTRL - 10
           -|/- - File #6 GEN_CTRL - 10

RESET TRANSFER  TRANSFER
PUMP RUN        PUMP
P-102-SY-02A   P-102-SY-02A
Y-75.1         RECIRCULATION
              MODE Y-75.1
              ZL-3102C
              N14:0/8
B3/76          N14:0/8

6:0011 -----|-----|-----|-----B3/75
                                         ( )

B3/75 - -( ) - - File #6 GEN_CTRL - 11
       -|/- - File #6 GEN_CTRL - 12

```

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
TRANSFER PUMP INTERLOCK LOGIC, Y-75.1
Lockheed Martin Hanford Co.

File #6 GEN_CTRL Proj:PLC1

Page:00045

08:15:03 02/19/99

6:0012	TRANS - PUMP P-102-SY-02A TRANSFER MODE STOP Y-75.1 B3/75	TANK 241-SY-102 LOW LEVEL LAL-3102 N14:0/14		STOP PUMP P-102-SY-02A [OFF=STOP] Y75 MS-102-SY-A-1P1 0:007/03
	-- --	-- --		ON 771-0D16 STOP PUMP P-102-SY-02A [OFF=STOP]
				Y75 MS-102-SY-A-1P2 0:007/04
				ON 771-0D16
	0:007/003 - - { } - - File #6 GEN_CTRL - 12 0:007/004 - - { } - - File #6 GEN_CTRL - 12			

*ENABLE THE SPEED RAMP REFERENCE WHEN THE CONTROLLER RUN OUTPUT IS ON. WHILE THE REFERENCE IS ENABLED,
 *SCALE THE SPEED REFERENCE AND MOVE THIS DESIRED SPEED INTO THE SPEED REFERENCE RAMP TARGET SETPOINT
 *WORKING REGISTER.

6:0013

RAMP SPEED
 REFERENCE
 TARGET
 SET POINT

+-MOV-----+
 Move
 Source: N14:140
 1630
 Dest: N7:310
 1630
 -----+

SPEED RAMP
 REFERENCE
 ENABLE

B3/310
 -( )

N14:140 - MOV - File #6 GEN_CTRL - 13
 N7:310 - MOV - File #6 GEN_CTRL - 13
 CLR - File #6 GEN_CTRL - 14
 NEQ - File #6 GEN_CTRL - 17
 JSR - File #6 GEN_CTRL - 18
 DIV - File #6 GEN_CTRL - 19
 B3/310 - -( ) - File #6 GEN_CTRL - 13
 - [/] - File #6 GEN_CTRL - 14
 - [/] - File #6 GEN_CTRL - 15,15

*WHEN THE RAMP REFERENCE IS NOT ENABLED, CLEAR (ZERO) THE SPEED REFERENCE RAMP TARGET SETPOINT REGISTER.
 *THIS FUNCTION ENABLES THE REFERENCE TO RAMP DOWN TO A STOP IF THE CONTROLLER HAS THE ABILITY TO STAY
 *ENERGIZED TO A LOW SPEED.

6:0014

SPEED RAMP
 REFERENCE
 ENABLE

B3/310

[/]

RAMP SPEED
 REFERENCE
 TARGET
 SET POINT

+-CLR-----+
 Clear
 Dest: N7:310
 1630
 -----+

RAMP REFERENCE
 COMMENT COIL

B3/314
 -( )

N7:310 - MOV - File #6 GEN_CTRL - 13
 CLR - File #6 GEN_CTRL - 14
 NEQ - File #6 GEN_CTRL - 17
 JSR - File #6 GEN_CTRL - 18
 DIV - File #6 GEN_CTRL - 19
 B3/314 - -( ) - File #6 GEN_CTRL - 14

*ENABLE THE SPEED RAMP ANY TIME THE REFERENCE IS ENABLED. IF THE CONTROL HAS THE ABILITY TO RAMP TO A
 *STOP, KEEP THE RAMP ENABLED AFTER THE REFERENCE IS DISABLED UNTIL EITHER THE REFERENCE (OR FEEDBACK IF
 *AVAILABLE) APPROACHES ZERO OR THE CONTROLLER 'ON' STATUS DROPS OUT.

* NOTE: THE RAMP INCREMENT 'MOV' SERVES ONLY AS AN EASY DISPLAY OF THE CURRENT VALUE.

*IF THE SPEED RAMP IS NOT ENABLED, PLACE A ZERO IN THE SPEED REFERENCE CURRENT SETPOINT REGISTER. THIS
 *REGISTER IS THE RAMP OUTPUT OR THE ACTUAL SPEED REFERENCE TO THE CONTROLLER.

*****
 *JUMP TO THE SPEED RAMP SUBROUTINE CONDITIONALLY WHEN THE RAMP IS ENABLED AND THE RAMP OUTPUT DOES NOT
 *EQUAL ITS INPUT. THE RAMP RUNS THE FIRST TIME THESE CONDITIONS ARE MET AND THEN EACH TIME THE RAMP
 *TIMER IS DONE. USE A HISTOGRAM ON THE RAMP DONE BIT TO VERIFY THE RAMP SCAN PERIOD WHEN ADJUSTING THE
 *RAMP TIMER FOR THE DESIRED RAMP PERIOD.
 *****

*****
 *JUMP TO THE RAMP SUBROUTINE WITH PASSED PARAMETERS:
 * INPUT PAR (1): DESIRED OR TARGET SPEED REFERENCE (RAMP INPUT)
 * INPUT PAR (2): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
 * INPUT PAR (3): MAXIMUM RAMP REFERENCE INCREMENT IN A SINGLE SCAN THROUGH THE SUBROUTINE
 * RETURN PAR (1): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
 * RETURN PAR (2): DIFFERENCE BETWEEN DESIRED (TARGET) AND ACTUAL (OUTPUT) REFERENCES
 * RETURN PAR (3): ABSOLUTE VALUE OF RAMP REFERENCE DIFFERENCE
 *****

```

U:11      - JSR   - File #6 GEN_CTRL - 18
          - SBR   - File #11 RAMP - 0
N7:310    - MOV   - File #6 GEN_CTRL - 13
          - CLR   - File #6 GEN_CTRL - 14
          - NEQ   - File #6 GEN_CTRL - 17
          - JSR   - File #6 GEN_CTRL - 18
          - DIV   - File #6 GEN_CTRL - 19
N7:311    - GRT   - File #6 GEN_CTRL - 15
          - CLR   - File #6 GEN_CTRL - 16
          - NEQ   - File #6 GEN_CTRL - 17
          - JSR   - File #6 GEN_CTRL - 18,18
N7:314    - MOV   - File #6 GEN_CTRL - 15,15
          - JSR   - File #6 GEN_CTRL - 18
N7:311    - GRT   - File #6 GEN_CTRL - 15
          - CLR   - File #6 GEN_CTRL - 16
          - NEQ   - File #6 GEN_CTRL - 17
          - JSR   - File #6 GEN_CTRL - 18,18
N7:312    - JSR   - File #6 GEN_CTRL - 18
N7:313    - JSR   - File #6 GEN_CTRL - 18
B3/316    - ( ) - File #6 GEN_CTRL - 18
  
```

*****MOVE THE RAMPED SPEED REFERENCE TO THE ACTUAL OUTPUT REGISTER WHICH IS CONNECTED TO THE CONTROLLER.*****

6:0019

CHEMICAL ADD
 PUMP P-3100B TO
 TANK TK-302-C
 % OF INLET FLOW
 REAL VALUE

```

+--DIV-----+
| Div                                     |
| Source A:  N7:310                       |
| Source B:  1630                         |
|           1000.0                        |
| Dest:      F8:3                         |
|           1.63                          |
+-----+
  
```

FLOW CONTROL
 CHEM ADD
 PUMP P-3100B
 P-3100B

```

+--MUL-----+
| Mul                                     |
| Source A:  F8:3                         |
|           1.63                          |
| Source B:  N20:1                        |
|           1                             |
| Dest:      N20:16                       |
|           2                             |
+-----+
  
```

FINAL SPEED
 REFERENCE
 COMMENT COIL

B3/317

( )

```

N7:310    - MOV   - File #6 GEN_CTRL - 13
          - CLR   - File #6 GEN_CTRL - 14
          - NEQ   - File #6 GEN_CTRL - 17
          - JSR   - File #6 GEN_CTRL - 18
          - DIV   - File #6 GEN_CTRL - 19
F8:3      - MUL   - File #6 GEN_CTRL - 19
          - DIV   - File #6 GEN_CTRL - 19
F8:3      - MUL   - File #6 GEN_CTRL - 19
          - DIV   - File #6 GEN_CTRL - 19
FILE _F:N020:0001%008 LEN 8 - COP - File #4 REG_10 - 3
          - File #5 COMM_CHK - 5
FILE _F:N020:0001%008 LEN 8 - MUL - File #6 GEN_CTRL - 19
FILE _F:N020:0001%008 LEN 8 - DIV - File #6 GEN_CTRL - 20
FILE _F:N020:0001%008 LEN 8 - LES - File #6 GEN_CTRL - 20
FILE _F:N020:0001%008 LEN 8 - FAL - File #9 DEMO - 15,15,15,15
N20:16    - COP   - File #4 REG_10 - 4,4
          - MUL   - File #6 GEN_CTRL - 19
  
```

Hanford Cross Site Transfer System (PCU-1)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00050

File #6 GEN_CTRL Proj:PLC1

08:15:04 02/19/99

B3/317 - ( ) - File #6 GEN_CTRL - 19

*ACCUMULATED FLOW INTO TANK TK-302-C SEQUENCING

RUN SPEED
 REFERENCE RAMP
 SUBROUTINE
 TIMER

T4:10.DN

6:0020

SCALED
 INLET FLOW TO
 TANK TK-302-C

+--DIV--+
 Div
 Source A: N20:1
 1
 Source B: F8:2
 59.232
 Dest: F8:0
 0

INLET FLOW
 TO TANK
 TK-302-C
 LINE 4
 FT-302C-2

SCALED
 INLET FLOW TO
 TANK TK-302-C

+--LES--+ +--CLR--+
 Less Than (A<B) | Clear
 Source A: N20:1 | Dest: F8:0
 1 | 0
 Source B: 1

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C

+--ADD--+
 Add
 Source A: F8:1
 19492.28
 Source B: F8:0
 0
 Dest: F8:1
 19492.28

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C

+--LES--+ +--CLR--+
 Less Than (A<B) | Clear
 Source A: F8:1
 19492.28 | Dest: F8:1
 Source B: 0.0 | 19492.28
 0.0

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C

+--GRT--+ +--MOV--+
 Greater Than (A>B) | Move
 Source A: F8:1 | Source: 51000.0
 19492.28 | 51000.0
 Source B: 51000.0 | Dest: F8:1
 51000.0 | 19492.28

FILE _F:N020:0001%008 LEN 8 - COP - File #4 REG_10 - 3
 File #5 COMM_CHK - 5
 FILE _F:N020:0001%008 LEN 8 - MUL - File #6 GEN_CTRL - 19
 FILE _F:N020:0001%008 LEN 8 - DIV - File #6 GEN_CTRL - 20

```

FILE _F:N020:0001%008 LEN 8 - LES - File #6 GEN_CTRL - 20
FILE _F:N020:0001%008 LEN 8 - FAL - File #9 DEMO - 15,15,15,15
F8:2 - DIV - File #6 GEN_CTRL - 20
F8:0 - ADD - File #6 GEN_CTRL - 20
      DIV - File #6 GEN_CTRL - 20
      CLR - File #6 GEN_CTRL - 20,23
F8:0 - ADD - File #6 GEN_CTRL - 20
      DIV - File #6 GEN_CTRL - 20
      CLR - File #6 GEN_CTRL - 20,23
F8:1 - ADD - File #6 GEN_CTRL - 20,20
      CLR - File #6 GEN_CTRL - 20
      MOV - File #6 GEN_CTRL - 20
      LES - File #6 GEN_CTRL - 20
      GRT - File #6 GEN_CTRL - 20
      CLR - File #6 GEN_CTRL - 21
      DIV - File #6 GEN_CTRL - 22
      SUB - File #6 GEN_CTRL - 22
      MOV - File #6 GEN_CTRL - 23
      CLR - File #6 GEN_CTRL - 23
      MOV - File #6 GEN_CTRL - 23
F8:0 - ADD - File #6 GEN_CTRL - 20
      DIV - File #6 GEN_CTRL - 20
      CLR - File #6 GEN_CTRL - 20,23
F8:1 - ADD - File #6 GEN_CTRL - 20,20
      CLR - File #6 GEN_CTRL - 20
      MOV - File #6 GEN_CTRL - 20
      LES - File #6 GEN_CTRL - 20
      GRT - File #6 GEN_CTRL - 20
      CLR - File #6 GEN_CTRL - 21
      DIV - File #6 GEN_CTRL - 22
      SUB - File #6 GEN_CTRL - 22
      MOV - File #6 GEN_CTRL - 23
      CLR - File #6 GEN_CTRL - 23
F8:1 - MOV - File #6 GEN_CTRL - 23
      ADD - File #6 GEN_CTRL - 20,20
      CLR - File #6 GEN_CTRL - 20
      MOV - File #6 GEN_CTRL - 20
      LES - File #6 GEN_CTRL - 20
      GRT - File #6 GEN_CTRL - 20
      CLR - File #6 GEN_CTRL - 21
      DIV - File #6 GEN_CTRL - 22
      SUB - File #6 GEN_CTRL - 22
      MOV - File #6 GEN_CTRL - 23
      CLR - File #6 GEN_CTRL - 23
      MOV - File #6 GEN_CTRL - 23

```

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C
 RESET
 HS-302C-2R
 N14:120/12

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C

6:0021

+--CLR-----+
 |Clear|
 |Dest: F8:1|
 |19492.28|
 +-----+

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C
 RESET
 HS-302C-2R
 N14:120/12
 +-----+(U)-----+

```

F8:1 - ADD - File #6 GEN_CTRL - 20,20
      CLR - File #6 GEN_CTRL - 20
      MOV - File #6 GEN_CTRL - 20
      LES - File #6 GEN_CTRL - 20
      GRT - File #6 GEN_CTRL - 20

```


APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00052

HNF-2346, Rev. 1

File #6 GEN_CTRL Proj:PLC1

08:15:04 02/19/99

F8:1 - CLR - File #6 GEN_CTRL - 21
 DIV - File #6 GEN_CTRL - 22
 SUB - File #6 GEN_CTRL - 22
 MOV - File #6 GEN_CTRL - 23
 CLR - File #6 GEN_CTRL - 23
 MOV - File #6 GEN_CTRL - 23
 N14:120/12 - -(U) - File #6 GEN_CTRL - 21
 -| - File #6 GEN_CTRL - 21

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C
 HIGH PORTION
 WORKING REG.

6:0022

+--DIV-----+
 Div
 Source A: F8:1
 Source B: 19492.28
 Dest: 1000.0
 1000.0
 19

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C
 WORKING HIGH
 PORTION

+--MUL-----+
 Mul
 Source A: N7:19
 Source B: 19
 Dest: 1000.0
 1000.0
 F8:4
 19000

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C
 LOW PORTION
 WORKING REG.

+--SUB-----+
 Sub
 Source A: F8:1
 Source B: 19492.28
 Dest: F8:4
 19000
 N7:18
 492

ACCUMULATED
 INLET FLOW TO
 TANK TK-302-C
 LOW PORTION
 F10-302C-2L

+--COP-----+
 Copy File
 Source: #N7:18
 Dest: #N14:58
 Length: 2

F8:1 - ADD - File #6 GEN_CTRL - 20,20
 CLR - File #6 GEN_CTRL - 20
 MOV - File #6 GEN_CTRL - 20
 LES - File #6 GEN_CTRL - 20
 CRT - File #6 GEN_CTRL - 20
 CLR - File #6 GEN_CTRL - 21
 DIV - File #6 GEN_CTRL - 22
 SUB - File #6 GEN_CTRL - 22
 MOV - File #6 GEN_CTRL - 23
 CLR - File #6 GEN_CTRL - 23
 MOV - File #6 GEN_CTRL - 23
 N7:19 - MUL - File #6 GEN_CTRL - 22
 DIV - File #6 GEN_CTRL - 22
 COP - File #6 GEN_CTRL - 22

Hanford Cross Site Transfer System (PCU-1)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page: 00053

File #6 GEN_CTRL Proj:PLC1

08:15:05 02/19/99

```

N7:19  - MUL - File #6 GEN_CTRL - 22
        DIV - File #6 GEN_CTRL - 22
        COP - File #6 GEN_CTRL - 22
F8:4    - SUB - File #6 GEN_CTRL - 22
        MUL - File #6 GEN_CTRL - 22
F8:1    - ADD - File #6 GEN_CTRL - 20,20
        CLR - File #6 GEN_CTRL - 20
        MOV - File #6 GEN_CTRL - 20
        LES - File #6 GEN_CTRL - 20
        GRT - File #6 GEN_CTRL - 20
        CLR - File #6 GEN_CTRL - 21
        DIV - File #6 GEN_CTRL - 22
        SUB - File #6 GEN_CTRL - 22
        MOV - File #6 GEN_CTRL - 23
        CLR - File #6 GEN_CTRL - 23
        MOV - File #6 GEN_CTRL - 23
F8:4    - SUB - File #6 GEN_CTRL - 22
        MUL - File #6 GEN_CTRL - 22
N7:18   - COP - File #6 GEN_CTRL - 22
        SUB - File #6 GEN_CTRL - 22
        COP - File #6 GEN_CTRL - 22
FILE _F:N007:018I%002 LEN 2 - COP - File #6 GEN_CTRL - 22
FILE _F:N014:058I%002 LEN 2 - COP - File #6 GEN_CTRL - 22

```

*****
 *FLOW ACCUMULATOR TEST SEQUENCING RUNG
 *****

*>>> EDIT THE B3/0 CONTACT TO B3/1 AND TEST EDITS.

*>>> WHEN THE TEST IS COMPLETED ABOUT 30 MINUTES LATER RECORD THE RESULTS.

*>>> UNTEST AND CANCEL EDITS RETURNING THIS CONTACT TO B3/0.
 *****

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00055

HNF-2346, Rev. 1

File #6 GEN_CTRL Proj:PLC1

08:15:05 02/19/99

Base (SEC):	1.0	-(DN)
Preset:	1800	
Accum:	0	

ACCUMULATED
 INLET FLOW FOR
 30 MINUTE TEST
 & CALIBRATION

T4:21.DN	B3/14	---MOV-----	+
-----	-----	[ONS]	Move
			Source: F8:1
			19492.28
			Dest: F8:11
			5246.784

```

F8:0  - ADD - File #6 GEN_CTRL - 20
      - DIV - File #6 GEN_CTRL - 20
      - CLR - File #6 GEN_CTRL - 20,23
F8:1  - ADD - File #6 GEN_CTRL - 20,20
      - CLR - File #6 GEN_CTRL - 20
      - MOV - File #6 GEN_CTRL - 20
      - LES - File #6 GEN_CTRL - 20
      - GRT - File #6 GEN_CTRL - 20
      - CLR - File #6 GEN_CTRL - 21
      - DIV - File #6 GEN_CTRL - 22
      - SUB - File #6 GEN_CTRL - 22
      - MOV - File #6 GEN_CTRL - 23
      - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23
F8:10 - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23
F8:11 - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23
T4:20.DN - TON - File #6 GEN_CTRL - 23
      - | | - File #6 GEN_CTRL - 23
F8:1  - ADD - File #6 GEN_CTRL - 20,20
      - CLR - File #6 GEN_CTRL - 20
      - MOV - File #6 GEN_CTRL - 20
      - LES - File #6 GEN_CTRL - 20
      - GRT - File #6 GEN_CTRL - 20
      - CLR - File #6 GEN_CTRL - 21
      - DIV - File #6 GEN_CTRL - 22
      - SUB - File #6 GEN_CTRL - 22
      - MOV - File #6 GEN_CTRL - 23
      - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23
F8:10 - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23
T4:21.DN - TON - File #6 GEN_CTRL - 23
      - | | - File #6 GEN_CTRL - 23
F8:1  - ADD - File #6 GEN_CTRL - 20,20
      - CLR - File #6 GEN_CTRL - 20
      - MOV - File #6 GEN_CTRL - 20
      - LES - File #6 GEN_CTRL - 20
      - GRT - File #6 GEN_CTRL - 20
      - CLR - File #6 GEN_CTRL - 21
      - DIV - File #6 GEN_CTRL - 22
      - SUB - File #6 GEN_CTRL - 22
      - MOV - File #6 GEN_CTRL - 23
      - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23
F8:11 - CLR - File #6 GEN_CTRL - 23
      - MOV - File #6 GEN_CTRL - 23

```

File #6 GEN_CTRL Proj:PLC1

08:15:05 02/19/99

6:0024 <pre> OVERRIDE OF 200-W MASTER SHUTDOWN Y-77.1 HS-058W N14:120/9 OVERRIDE OF 200-W MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 Y-77.1 YL-058W K-6241 N14:0/13 I:003/02 1771-IBD </pre>	N14:120/9 - (U) - File #6 GEN_CTRL - 24 N14:0/13 - ( ) - File #6 GEN_CTRL - 24 - ( ) - File #6 GEN_CTRL - 24 - / - File #6 GEN_CTRL - 24 - / - File #6 GEN_CTRL - 25	OVERRIDE OF 200-W TANK FARM MASTER SHUTDOWN TIMER Y-77.
6:0025 <pre> 200-W MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 K-6241 YL-058W I:003/02 N14:0/13 1771-IBD </pre>	T4:2.DN - TON - File #6 GEN_CTRL - 25 - - File #6 GEN_CTRL - 26	+--TON-----+ Timer On Delay - (EN) Timer: T4:2 Base (SEC): 1.0 - (DN) Preset: 600 Accum: 0 +-----+
6:0026 <pre> 200-W TANK FARM MASTER SHUTDOWN TIMER COMPLETE Y-77.1 T4:2.DN </pre>	N19:1/15 - ( ) - File #6 GEN_CTRL - 26	200-W MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 FLUSH PUMP P-3100A CONTROL LOGIC, ES-058-Y90 SH.1
 Lockheed Martin Hanford Co.
 Page:00057

HNF-2346, Rev. 1

File #6 GEN_CTRL Proj:PLC1

08:15:05 02/19/99

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 FLUSH PUMP P-3100A CONTROL LOGIC, ES-058-Y90 SH.1
 Lockheed Martin Hanford Co.
 Page:00058

HNF-2346, Rev. 1

File #6 GEN_CTRL Proj:PLC1

08:15:05 02/19/99

6:0031	START FLUSH PUMP P-3100A Y-90.1 HS-3100A1 N14:120/10	STOP FLUSH PUMP P-3100A INTERNAL Y-90.1 B3/80	+---T0F---+ Timer Off Delay Timer: T4:14 Base (SEC): 0.01 Preset: 150 Accum: 150	-(EN)- -(DN)
	T4:14.DN - T0F - File #6 GEN_CTRL - 31 -I - File #6 GEN_CTRL - 32			
	START PUMP P-3100A			
6:0032	FLUSH PUMP START TIMER T4:14.DN		Y-90.1 P-3100A-T 0:007/01 ---()--- 771-0D16	
	0:007/001 - -() - - File #6 GEN_CTRL - 32 -I - File #6 GEN_CTRL - 34,36			
6:0033	STOP FLUSH PUMP P-3100A INTERNAL Y-90.1 B3/80		STOP PUMP P-3100A Y-90.1 P-3100A-P 0:007/00 ---()--- 771-0D16	
	0:007/000 - -() - - File #6 GEN_CTRL - 33 -I - File #6 GEN_CTRL - 35			
6:0034	START FLUSH PUMP P-3100A Y-90.1 HS-3100A1 N14:120/10	START PUMP P-3100A Y-90.1 P-3100A-T 0:007/01	START FLUSH PUMP P-3100A Y-90.1 HS-3100A1 N14:120/10 ---()---	
	1771-0D1 TANK TK-302C-1 LEVEL BIT Y-90.1 LAL-302C1 N14:0/11 +-----+			
	N14:120/10 - -I - File #6 GEN_CTRL - 31 -(U)- File #6 GEN_CTRL - 34 -I - File #6 GEN_CTRL - 34			
6:0035	STOP FLUSH PUMP P-3100A Y-90.1 HS-3100A2 N14:120/11	STOP PUMP P-3100A Y-90.1 P-3100A-P 0:007/00 ---I - 1771-0D1	STOP FLUSH PUMP P-3100A Y-90.1 HS-3100A2 N14:120/11 ---()---	
	N14:120/11 - -I - File #6 GEN_CTRL - 29 -(U)- File #6 GEN_CTRL - 35 -I - File #6 GEN_CTRL - 35			

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 FLUSH PUMP P-3100A CONTROL LOGIC, ES-058-Y90 SH.1
 Lockheed Martin Hanford Co.
 Page:00059

HNF-2346, Rev. 1

File #6 GEN_CTRL Proj:PLC1

08:15:06 02/19/99

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
 Lockheed Martin Hanford Co.
 Page:00060

File #9 DEMO Proj:PLC1

08:15:06 02/19/99

*****
 THE NEXT FIVE RUNGS DEMONSTRATE SQUARE ROOT, POLYNOMIAL, EXPONENTIAL, LOGARITHM, AND NATURAL LOG. ENTER
 A VALUE IN F8:20 AND OBSERVE THE RESULTS IN THE APPROPRIATE REGISTER.
 *****

SQUARE ROOT
 DEMO OUTPUT

9:0000

+-CPT-----+
 Compute
 Dest: F8:21
 1
 Expression:
 F8:20 ** 0.5

F8:21 - CPT - File #9 DEMO - 0,0
 F8:20 - CPT - File #9 DEMO - 0,1,1,2,3,4
 MUL - File #9 DEMO - 5
 CPT - File #9 DEMO - 6

POLYNOMIAL
 DEMO OUTPUT

9:0001

+-CPT-----+
 Compute
 Dest: F8:22
 112
 Expression:
 ((2.0 * (F8:20 ** 2.0)) + (10.0 * F8:20)) + 100.0

F8:22 - CPT - File #9 DEMO - 1,1

EXPONENTIAL
 DEMO OUTPUT

9:0002

+-CPT-----+
 Compute
 Dest: F8:23
 1
 Expression:
 F8:20 ** 3.0

F8:23 - CPT - File #9 DEMO - 2,2
 F8:20 - CPT - File #9 DEMO - 0,1,1,2,3,4
 MUL - File #9 DEMO - 5
 CPT - File #9 DEMO - 6

LOGARITHM
 DEMO OUTPUT

9:0003

+-CPT-----+
 Compute
 Dest: F8:24
 0
 Expression:
 LOG F8:20

F8:24 - CPT - File #9 DEMO - 3,3

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
Lockheed Martin Hanford Co.
Page:00081

File #9 DEMO Proj:PLC1

08:15:08 02/19/99

9:0004

NATURAL LOG
DEMO OUTPUT

+.-CPT-----+
| Compute
| Dest: F8:25
| 0
| Expression:
| LN F8:20
+-----+

F8:25 - CPT - File #9 DEMO - 4,4

.....
 *MOVING AVERAGE (WITH WEIGHTING)
 .....

*>> F8:30 IS THE WEIGHTING FACTOR (K)
 *>> F8:30 = 0 USES ONLY THE PRESENT VALUE
 *>> F8:30 = 1 LOCKS THE OUTPUT AT THE PREVIOUS VALUE
 .....

9:0005

MOVING AVERAGE
 DEMO (1-K)
 FACTOR

+--SUB-----+
 |Sub|
 |Source A: 1.0|
 |1.0|
 |Source B: F8:30|
 |0.5|
 |Dest: F8:31|
 |0.5|
 +-----+

MOVING AVERAGE
 DEMO WEIGHTED
 PORTION OF
 NEW VALUE

+--MUL-----+
 |Mul|
 |Source A: F8:20|
 |1|
 |Source B: F8:31|
 |0.5|
 |Dest: F8:32|
 |0.5|
 +-----+

MOVING AVERAGE
 DEMO WEIGHTED
 PORTION OF
 PREVIOUS VALUE

+--MUL-----+
 |Mul|
 |Source A: F8:30|
 |0.5|
 |Source B: F8:33|
 |1|
 |Dest: F8:34|
 |0.5|
 +-----+

MOVING AVERAGE
 DEMO OUTPUT

+--ADD-----+
 |Add|
 |Source A: F8:32|
 |0.5|
 |Source B: F8:34|
 |0.5|
 |Dest: F8:33|
 |1|
 +-----+

F8:30 - SUB - File #9 DEMO - 5
 MUL - File #9 DEMO - 5
 F8:31 - SUB - File #9 DEMO - 5
 MUL - File #9 DEMO - 5
 F8:20 - CPT - File #9 DEMO - 0,1,1,2,3,4
 MUL - File #9 DEMO - 5
 CPT - File #9 DEMO - 6
 F8:31 - SUB - File #9 DEMO - 5
 MUL - File #9 DEMO - 5
 F8:32 - ADD - File #9 DEMO - 5
 MUL - File #9 DEMO - 5

```
F8:30      - SUB - File #9 DEMO - 5
           MUL - File #9 DEMO - 5
F8:33      - ADD - File #9 DEMO - 5
           MUL - File #9 DEMO - 5
F8:34      - ADD - File #9 DEMO - 5
           MUL - File #9 DEMO - 5
F8:32      - ADD - File #9 DEMO - 5
           MUL - File #9 DEMO - 5
F8:34      - ADD - File #9 DEMO - 5
           MUL - File #9 DEMO - 5
F8:33      - ADD - File #9 DEMO - 5
           MUL - File #9 DEMO - 5
```

NON-LINEAR FUNCTION GENERATOR

NON-LINEAR
FUNCTION GEN.
DEMO OUTPUT

9:0006

```
+--CPT-----+
| Compute      |
| Dest:  F8:26 |
|            1 |
| Expression:  |
| F8:20 ** 2.0 |
+-----+
```

```
F8:26      - CPT - File #9 DEMO - 6,6
F8:20      - CPT - File #9 DEMO - 0,1,1,2,3,4
           MUL - File #9 DEMO - 5
           CPT - File #9 DEMO - 6
```

FUNCTION OR LOOK-UP TABLE WITH INTERPOLATION

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
Lockheed Martin Hanford Co.
Page:00064

File #9 DEMO Proj:PLC1

08:15:06 02/19/99

9:0007

LOOK-UP TABLE
DEMO POINTER
(0 TO 4)

+--CPT-----+
|Compute
|Dest: N7:21
|0
|Expression:
|(N7:20 | 10.0) - 0.49999
+-----+

LOOK-UP TABLE
DEMO LOW
FILE POINTER
(30 TO 34)

+--ADD-----+
|Add
|Source A: N7:21
|0
|Source B: 30
|30
|Dest: N7:22
|30
+-----+

LOOK-UP TABLE
DEMO HIGH
FILE POINTER
(31 TO 35)

+--ADD-----+
|Add
|Source A: N7:22
|30
|Source B: 1
|1
|Dest: N7:23
|31
+-----+

LOOK-UP TABLE
DEMO VALUE
INTERPOLATION
RATIO

+--CPT-----+
|Compute
|Dest: N7:24
|5
|Expression:
|N7:20 - (N7:21 * 10)
+-----+

LOOK-UP TABLE
DEMO TABLE
RANGE FOR
INTERPOLATION

+--SUB-----+
|Sub
|Source A: N7:[N7:23]
|100
|Source B: N7:[N7:22]
|50
|Dest: N7:25
|50
+-----+

LOOK-UP TABLE
DEMO OUTPUT

+--CPT-----+
|Compute
|Dest: N7:26
+-----+

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
 Lockheed Martin Hanford Co.
 Page:00065

File #9 DEMO Proj:PLC1

08:15:06 02/19/99

Expression: 75
 $(N7:25 * (N7:24 | 10.0)) + N7:[N7:22]$

N7:21 - CPT - File #9 DEMO - 7,7,7
 ADD - File #9 DEMO - 7
 N7:21 - CPT - File #9 DEMO - 7,7,7
 ADD - File #9 DEMO - 7
 N7:22 - CPT - File #9 DEMO - 7
 ADD - File #9 DEMO - 7,7
 SUB - File #9 DEMO - 7
 N7:22 - CPT - File #9 DEMO - 7
 ADD - File #9 DEMO - 7,7
 SUB - File #9 DEMO - 7
 N7:23 - ADD - File #9 DEMO - 7
 SUB - File #9 DEMO - 7
 N7:24 - CPT - File #9 DEMO - 7,7,7
 N7:20 - CPT - File #9 DEMO - 7,7
 N7:[N7:23] - SUB - File #9 DEMO - 7
 N7:[N7:22] - CPT - File #9 DEMO - 7
 SUB - File #9 DEMO - 7
 N7:25 - CPT - File #9 DEMO - 7
 SUB - File #9 DEMO - 7
 N7:26 - CPT - File #9 DEMO - 7,7

*****
 *INTEGRATOR (KP AND KD SET TO ZERO)
 *****

INTEGRATOR
 DEMO ENABLE

B3/480

9:0008

INTEGRATOR
 DEMO CONTROL
 STRUCTURE

+-PID-----
 PID
 Control Block: PD16:0
 Process Variable: N7:27
 Tieback: 0
 Control Variable: N7:28
 +-----+

PD16:0 - PID - File #9 DEMO - 8
 N7:27 - PID - File #9 DEMO - 8
 N7:28 - PID - File #9 DEMO - 8

*****
 *EXCLUSIVE OR
 *****

EXCLUSIVE OR EXCLUSIVE OR
 DEMO INPUT #1 DEMO INPUT #2

B3/481

B3/482

EXCLUSIVE OR
 DEMO OUTPUT

B3/483

9:0009

EXCLUSIVE OR EXCLUSIVE OR
 DEMO INPUT #1 DEMO INPUT #2

B3/481

B3/482

B3/483 - -( ) - File #9 DEMO - 9

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
 Lockheed Martin Hanford Co.
 Page:00066

File #9 DEMO Proj:PLC1

08:15:07 02/19/99

J-K FLIP FLOP

J-K FLIP FLOP
DEMO INPUTJ-K FLIP FLOP
DEMO ONE SHOTJ-K FLIP FLOP
DEMO OUTPUTJ-K FLIP FLOP
DEMO OUTPUT

B3/484

B3/485

B3/486

B3/486

9:0010

[ONS]

/I/

(L)

J-K FLIP FLOP
DEMO INTERLOCK

B3/487

( )

J-K FLIP FLOP
DEMO OUTPUTJ-K FLIP FLOP
DEMO INTERLOCKJ-K FLIP FLOP
DEMO OUTPUT

B3/486

B3/487

B3/486

/I/

(U)

B3/486 - (L) - File #9 DEMO - 10
 - (U) - File #9 DEMO - 10
 - / - File #9 DEMO - 10
 B3/487 - ( ) - File #9 DEMO - 10
 - / - File #9 DEMO - 10
 B3/486 - (L) - File #9 DEMO - 10
 - (U) - File #9 DEMO - 10
 - / - File #9 DEMO - 10
 - / - File #9 DEMO - 10

ONE MINUTE
 SINGLE SCAN
 PULSE
 1_MIN_PULSE
 B377

9:0011

/I/

Q9:0

[JMP]

Q9:0 - JMP - File #9 DEMO - 11
 LBL - File #9 DEMO - 14

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
 Lockheed Martin Hanford Co.
 Page:00067

File #9 DEMO Proj:PLC1

08:15:07 02/19/99

9:0012	ALWAYS OFF OUTPUT ALWAYS OFF B3/0	REAL TIME CLOCK MINUTE ONE'S BIT S:22/0	ANALOG MODULE CHAN. 1 DATA UNDERRANGE N13:1/0 ( )
			ANALOG MODULE CHAN. 2 DATA UNDERRANGE N13:1/1 ( )
			ANALOG MODULE CHAN. 3 DATA UNDERRANGE N13:1/2 ( )
			ANALOG MODULE CHAN. 4 DATA UNDERRANGE N13:1/3 ( )
			ANALOG MODULE CHAN. 5 DATA UNDERRANGE N13:1/4 ( )
			THERM. MODULE CHAN. 1 DATA UNDERRANGE N13:79/0 ( )
			THERM. MODULE CHAN. 2 DATA UNDERRANGE N13:81/0 ( )
			THERM. MODULE CHAN. 3 DATA UNDERRANGE N13:83/0 ( )
			THERM. MODULE CHAN. 4 DATA UNDERRANGE N13:85/0 ( )
			THERM. MODULE CHAN. 5 DATA

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
 Lockheed Martin Hanford Co.
 Page:00068

File #9 DEMO Proj:PLC1

08:15:07 02/19/99

UNDERRANGE
 N13:87/0
 ( )

B3/488

N13:1/0 - - | - File #4 REG IO - 10
 N13:1/1 - - | - File #9 DEMO - 12
 N13:1/2 - - | - File #4 REG IO - 11
 N13:1/2 - - | - File #9 DEMO - 12
 N13:1/3 - - | - File #4 REG IO - 12
 N13:1/3 - - | - File #9 DEMO - 13
 N13:1/4 - - | - File #4 REG IO - 12
 N13:1/4 - - | - File #9 DEMO - 14
 N13:79/0 - - | - File #4 REG IO - 12
 N13:79/0 - - | - File #9 DEMO - 18
 N13:81/0 - - | - File #4 REG IO - 12
 N13:81/0 - - | - File #9 DEMO - 19
 N13:83/0 - - | - File #4 REG IO - 20
 N13:83/0 - - | - File #9 DEMO - 12
 N13:85/0 - - | - File #4 REG IO - 21
 N13:85/0 - - | - File #9 DEMO - 12
 N13:87/0 - - | - File #4 REG IO - 22
 N13:87/0 - - | - File #9 DEMO - 12
 B3/488 - - | - File #9 DEMO - 12
 B3/488 - - | - File #9 DEMO - 13,15

FLUSH PUMP
 P-3100A
 OUTLET FLOW
 FT-302C-1

9:0013 ---| |
 ---ADD---
 Add
 Source A: N20:0
 0
 1
 Source B:
 1
 Dest: N20:0
 0

FLUSH PUMP
 P-3100A
 OUTLET FLOW
 FT-302C-1

---LIM---
 Limit Test (Circular)
 Low Lim: 150
 150
 Test: N20:0
 0
 0
 High Lim: 0
 0

FLUSH PUMP
 P-3100A
 OUTLET FLOW
 FT-302C-1

---CLR---
 Clear
 Dest: N20:0
 0

N20:0 - COP - File #4 REG IO - 3,3
 File #5 COMM CHK - 5,5
 GRT - File #6 GEN CTRL - 27
 LIM - File #9 DEMO - 13
 ADD - File #9 DEMO - 13,13
 CLR - File #9 DEMO - 13
 FAL - File #9 DEMO - 15,15
 N20:0 - COP - File #4 REG IO - 3,3
 File #5 COMM CHK - 5,5
 GRT - File #6 GEN CTRL - 27
 LIM - File #9 DEMO - 13
 ADD - File #9 DEMO - 13,13
 CLR - File #9 DEMO - 13
 FAL - File #9 DEMO - 15

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
 Lockheed Martin Hanford Co.
 Page:00069

File #9 DEMO Proj:PLC1

08:15:07 02/19/99

N20:0 - FAL - File #9 DEMO - 15
 N20:0 - COP - File #4 REG_10 - 3,3
 - File #5 COMM_CHK - 5,5
 GRT - File #6 GEN_CTRL - 27
 LIM - File #9 DEMO - 13
 ADD - File #9 DEMO - 13,13
 CLR - File #9 DEMO - 13
 FAL - File #9 DEMO - 15,15

9:0014

09:0
[LBL]

B3/489

B3/489 - - ( ) - File #9 DEMO - 14

ONE MINUTE
 SINGLE SCAN
 PULSE
 1_MIN PULSE

9:0015

B377 B3/488

+--FAL--+
 +File Arithmetic/Logical+ (EN)-+
 Control: R6:6
 Length: 4 (DN)
 Position: 0
 Mode: ALL (ER)
 Dest: #N20:1
 Expression: 1
 #N20:0 + 10

TANK
 TK-302-C
 TEMPERATURE
 TE-302C-1

+--ADD--+
 Add
 Source A: N20:4
 Source B: 5
 10
 Dest: N20:8
 43

+--FAL--+
 +File Arithmetic/Logical+ (EN)-+
 Control: R6:7
 Length: 4 (DN)
 Position: 0
 Mode: ALL (ER)
 Dest: #N20:9
 54
 Expression: 1
 #N20:8 + 10

R6:6 - FAL - File #9 DEMO - 15
 FILE_F:N20:0001%008 LEN 8 - COP - File #4 REG_10 - 3
 File #5 COMM_CHK - 5
 FILE_F:N20:0001%008 LEN 8 - FAL - File #9 DEMO - 15,15
 FILE_F:N20:0001%008 LEN 8 - COP - File #4 REG_10 - 3
 File #5 COMM_CHK - 5
 FILE_F:N20:0001%008 LEN 8 - FAL - File #9 DEMO - 15
 FILE_F:N20:0001%008 LEN 8 - COP - File #4 REG_10 - 3
 File #5 COMM_CHK - 5
 FILE_F:N20:0001%008 LEN 8 - LES - File #6 GEN_CTRL - 2
 FILE_F:N20:0001%008 LEN 8 - ADD - File #9 DEMO - 15

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
Lockheed Martin Hanford Co.
Page:00070

File #9 DEMO Proj:PLC1

08:15:08 02/19/99

```
FILE _F:N020:0001%008 LEN 8 - FAL - File #9 DEMO - 15,15
N20:8 - DIV - File #4 REG IO - 8
      COP - File #5 COMM CHK - 5
      FAL - File #9 DEMO - 15
      ADD - File #9 DEMO - 15
      FAL - File #9 DEMO - 15
R6:7 - FAL - File #9 DEMO - 15
FILE _F:N020:0001%016 LEN 16 - COP - File #5 COMM CHK - 5
FILE _F:N020:0001%016 LEN 16 - FAL - File #9 DEMO - 15,15,15
FILE _F:N020:0001%016 LEN 16 - COP - File #5 COMM CHK - 5
FILE _F:N020:0001%016 LEN 16 - FAL - File #9 DEMO - 15
```

9:0016

-----[End]-----

*THIS SUBROUTINE IS AN 'STI' OR 'SELECTABLE TIMED INTERRUPT' PROGRAM FILE. THE PROCESSOR RUNS THIS
 *PROGRAM EVERY 100 mS (0.1 SECONDS) ON AN INTERRUPT BASIS. EACH TIME THE PROGRAM RUNS, REGISTERS N14:10
 *AND N21:39 ARE INCREMENTED BY ONE. THESE REGISTERS CAN BE MONITORED IN THE OIT (N14:10) AND PLC-2
 *(N21:39) TO DETERMINE THE EFFECTIVE COMMUNICATIONS SPEED BETWEEN THE TWO STATIONS.

10:0000

COMMUNICATIONS

TEST REGISTER

TO OIT

COM SPD_TST

+--ADD--+

Add
 Source A: N14:10
 16773

Source B: 1

Dest: N14:10
 16773

COMMUNICATIONS

TEST REGISTER

TO OIT

COM SPD_TST

+--LIM--+

Limit Test (Circular)
 Low Lim: 32000

Test: N14:10
 16773

High Lim: 0
 0

COMMUNICATIONS

TEST REGISTER

TO OIT

COM SPD_TST

+--CLR--+

Clear
 Dest: N14:10
 16773

COMMUNICATIONS

TEST REGISTER

TO PLC-2

+--MOV--+

Move
 Source: N14:10
 16773

Dest: N21:39
 16806

N14:10 - ADD - File #10 SPD_TEST - 0,0
 CLR - File #10 SPD_TEST - 0
 MOV - File #10 SPD_TEST - 0
 LIM - File #10 SPD_TEST - 0
 N14:10 - ADD - File #10 SPD_TEST - 0,0
 CLR - File #10 SPD_TEST - 0
 MOV - File #10 SPD_TEST - 0
 LIM - File #10 SPD_TEST - 0
 N14:10 - ADD - File #10 SPD_TEST - 0,0
 CLR - File #10 SPD_TEST - 0
 MOV - File #10 SPD_TEST - 0
 LIM - File #10 SPD_TEST - 0
 N14:10 - ADD - File #10 SPD_TEST - 0,0
 CLR - File #10 SPD_TEST - 0
 MOV - File #10 SPD_TEST - 0
 LIM - File #10 SPD_TEST - 0

FILE_F: N021:0201%020 LEN 20 - COP - File #5 COMM_CHK - 9
 FILE_F: N021:0201%020 LEN 20 - MSG - File #5 COMM_CHK - 9
 FILE_F: N021:0201%020 LEN 20 - MOV - File #10 SPD_TEST - 0

10:0001

[End]

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 PLC RAMP FUNCTION SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00072

HNF-2346, Rev. 1

File #11 RAMP Proj:PLC1

08:15:08 02/19/99

RAMP BLOCK
 SUBROUTINE
 RAMP_SBR

B3/300

( )

11:0000 +--SBR-----+
 Subroutine
 Input Par: N7:300
 Input Par: N7:301
 Input Par: N7:304
 +-----+

B3/300 - ( ) - File #11 RAMP - 0

*CALCULATE THE DIFFERENCE BETWEEN THE CURRENT AND TARGET SETPOINTS.

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKING REGISTER

11:0001

+--SUB-----+
 Sub
 Source A: N7:300
 1630
 Source B: N7:301
 1630
 Dest: N7:302
 80
 +-----+

N7:300 - SBR - File #11 RAMP - 0
 SUB - File #11 RAMP - 1
 MOV - File #11 RAMP - 5
 N7:301 - SBR - File #11 RAMP - 0
 SUB - File #11 RAMP - 1
 ADD - File #11 RAMP - 4
 SUB - File #11 RAMP - 4.4
 ADD - File #11 RAMP - 4
 MOV - File #11 RAMP - 5
 RET - File #11 RAMP - 6
 N7:302/15 - SUB - File #11 RAMP - 1
 NEG - File #11 RAMP - 2
 -| - File #11 RAMP - 2
 MOV - File #11 RAMP - 3
 -|| - File #11 RAMP - 3
 -| - File #11 RAMP - 4
 -| - File #11 RAMP - 4
 RET - File #11 RAMP - 6

THE NEXT TWO RUNGS CALCULATE THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN TARGET AND CURRENT SETPOINTS.

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKING REGISTER
 SIGN BIT
 RAMP DIFF NEG

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKING REGISTER

11:0002 N7:302/15
 -| -

+--NEG-----+
 Negate
 Source: N7:302
 80
 Dest: N7:303
 80
 +-----+

RAMP FUNCTION
 COMMENT COIL

B3/301

( )

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 PLC RAMP FUNCTION SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00073

HNF-2346, Rev. 1

File #11 RAMP Proj:PLC1

08:15:08 02/19/99

```

N7:302/15  - SUB  - File #11 RAMP - 1
            NEG  - File #11 RAMP - 2
            -| | - File #11 RAMP - 2
            MOV  - File #11 RAMP - 3
            -| | - File #11 RAMP - 3
            -| | - File #11 RAMP - 4
            -| | - File #11 RAMP - 4
            RET  - File #11 RAMP - 6
N7:303      - NEG  - File #11 RAMP - 2
            MOV  - File #11 RAMP - 3
            GRT  - File #11 RAMP - 4
            LEQ  - File #11 RAMP - 5
            RET  - File #11 RAMP - 6
B3/301      - ( ) - File #11 RAMP - 2

```

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKNG REGISTER
 SIGN BIT
 RAMP DIFF NEG

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKNG REGISTER

11:0003 N7:302/15
 -----| |-----

```

+---MOV-----+
| Move        |
| Source: N7:302 |
|           80  |
| Dest:   N7:303 |
|           80  |
+---+---+

```

```

N7:302/15  - SUB  - File #11 RAMP - 1
            NEG  - File #11 RAMP - 2
            -| | - File #11 RAMP - 2
            MOV  - File #11 RAMP - 3
            -| | - File #11 RAMP - 3
            -| | - File #11 RAMP - 4
            -| | - File #11 RAMP - 4
            RET  - File #11 RAMP - 6
N7:303      - NEG  - File #11 RAMP - 2
            MOV  - File #11 RAMP - 3
            GRT  - File #11 RAMP - 4
            LEQ  - File #11 RAMP - 5
            RET  - File #11 RAMP - 6

```

*****
 *IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS GREATER THAN THE
 *INCREMENT LIMIT, ADD OR
 *SUBTRACT THE LIMIT VALUE AS APPROPRIATE.
 *****

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKING REGISTER

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKING REGISTER S.P. RAMP BLOCK
 SIGN BIT CURRENT S.P.
 RAMP DIFF NEG WORKING REGISTER

11:0004

---GRT---
 Greater Than (A>B)
 Source A: N7:303
 80
 Source B: N7:304
 100

N7:302/15

---SUB---

Sub
 Source A: N7:301
 1630
 Source B: N7:304
 100
 Dest: N7:301
 1630

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKING REGISTER S.P. RAMP BLOCK
 SIGN BIT CURRENT S.P.
 RAMP DIFF NEG WORKING REGISTER

N7:302/15

---ADD---

Add
 Source A: N7:301
 1630
 Source B: N7:304
 100
 Dest: N7:301
 1630

RAMP FUNCTION
 COMMENT COIL

B3/302

( )

N7:301	- SBR	- File #11	RAMP	- 0
	SUB	- File #11	RAMP	- 1
	ADD	- File #11	RAMP	- 4
	SUB	- File #11	RAMP	- 4, 4
	ADD	- File #11	RAMP	- 4
	MOV	- File #11	RAMP	- 5
N7:304	- RET	- File #11	RAMP	- 6
	- SBR	- File #11	RAMP	- 0
	SUB	- File #11	RAMP	- 4
	ADD	- File #11	RAMP	- 4
	GRT	- File #11	RAMP	- 4
	LEQ	- File #11	RAMP	- 5
N7:301	- SBR	- File #11	RAMP	- 0
	SUB	- File #11	RAMP	- 1
	ADD	- File #11	RAMP	- 4
	SUB	- File #11	RAMP	- 4, 4
	ADD	- File #11	RAMP	- 4
	MOV	- File #11	RAMP	- 5
	RET	- File #11	RAMP	- 6
N7:301	- SBR	- File #11	RAMP	- 0
	SUB	- File #11	RAMP	- 1
	ADD	- File #11	RAMP	- 4
	SUB	- File #11	RAMP	- 4, 4
	ADD	- File #11	RAMP	- 4
	MOV	- File #11	RAMP	- 5
	RET	- File #11	RAMP	- 6
N7:304	- SBR	- File #11	RAMP	- 0
	SUB	- File #11	RAMP	- 4
	ADD	- File #11	RAMP	- 4
	GRT	- File #11	RAMP	- 4
	LEQ	- File #11	RAMP	- 5
N7:301	- SBR	- File #11	RAMP	- 0
	SUB	- File #11	RAMP	- 1
	ADD	- File #11	RAMP	- 4
	SUB	- File #11	RAMP	- 4

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
PLC RAMP FUNCTION SUBROUTINE
Lockheed Martin Hanford Co.
Page:00075

HNF-2346, Rev. 1

File #11 RAMP Proj:PLC1

08:15:08 02/19/99

```

N7:301  - SUB - File #11 RAMP - 4
          ADD - File #11 RAMP - 4
          MOV - File #11 RAMP - 5
          RET - File #11 RAMP - 6
B3/302  - -( ) - File #11 RAMP - 4

```

```

*IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS LESS THAN OR EQUAL
*TO THE INCREMENT LIMIT, SET
*THE CURRENT SETPOINT EQUAL TO THE TARGET SETPOINT.

```

S.P. RAMP BLOCK
S.P. DIFFERENCE
ABSOLUTE VALUE
WORKING REGISTER

S.P. RAMP BLOCK
CURRENT S.P.
WORKING REGISTER

```

11:0005  +---LEQ-----+
          Less Than or Equal (A<=B)
          Source A:  N7:303
                   80
          Source B:  N7:304
                   100

```

```

+---MOV-----+
          Move
          Source:  N7:300
                   1630
          Dest:    N7:301
                   1630

```

RAMP FUNCTION
COMMENT COIL

B3/303

-( )

```

N7:300  - SBR - File #11 RAMP - 0
          SUB - File #11 RAMP - 1
          MOV - File #11 RAMP - 5
N7:301  - SBR - File #11 RAMP - 0
          SUB - File #11 RAMP - 1
          ADD - File #11 RAMP - 4
          SUB - File #11 RAMP - 4, 4
          ADD - File #11 RAMP - 4
          MOV - File #11 RAMP - 5
          RET - File #11 RAMP - 6
B3/303  - -( ) - File #11 RAMP - 5

```

11:0006

```

+---RET-----+
          Return ( )
          Return Par: N7:301
          Return Par: N7:302
          Return Par: N7:303

```

```

N7:301  - SBR - File #11 RAMP - 0
          SUB - File #11 RAMP - 1
          ADD - File #11 RAMP - 4
          SUB - File #11 RAMP - 4, 4
          ADD - File #11 RAMP - 4
          MOV - File #11 RAMP - 5
          RET - File #11 RAMP - 6
N7:302/15 - SUB - File #11 RAMP - 1
          NEG - File #11 RAMP - 2
          -| | - File #11 RAMP - 2
          MOV - File #11 RAMP - 3
          -| | - File #11 RAMP - 3
          -| | - File #11 RAMP - 4
          -| | - File #11 RAMP - 4
          RET - File #11 RAMP - 6
N7:303  - NEG - File #11 RAMP - 2
          MOV - File #11 RAMP - 3
          GRT - File #11 RAMP - 4
          LEQ - File #11 RAMP - 5
          RET - File #11 RAMP - 6

```


APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
PLC RAMP FUNCTION SUBROUTINE
Lockheed Martin Hanford Co.
Page:00076

File #11 RAMP Proj:PLC1

08:15:09 02/19/99

11:0007

[End]

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00077

08:15:09 02/19/99

DB Form Report

Sorted By: Address

0:007		DIGITAL OUTPUT	REGISTER			
0:007/000	P-3100A-P	STOP PUMP	P-3100A			Y-90.1
0:007/001	P-3100A-T	START PUMP	P-3100A			Y-90.1
0:007/002	MS-102-SY-A-1T	START PUMP	P-102-SY-02A			Y75
0:007/003	MS-102-SY-A-1P1	STOP PUMP	P-102-SY-02A	OFF=STOP		Y75
0:007/004	MS-102-SY-A-1P2	STOP PUMP	P-102-SY-02A	OFF=STOP		Y75
0:007/005	PCU-1	INPUT SIGNAL	TO 200-W	MASTER	SHUTDOWN	Y-72.1
0:007/006						
0:007/007						
0:007/010						
0:007/011						
0:007/012						
0:007/013						
0:007/014						
0:007/015						
0:007/016						
0:007/017						
1:003		DIGITAL INPUT	REGISTER			
1:003/000	TSH-302C-4A	CIRCULATION	HEATER#1	HTR-302C-1	OUTLET TEMP	OFF = ALARM
1:003/001	TSH-302C-4B	CIRCULATION	HEATER #2	HTR-302C-2	OUTLET TEMP	OFF = ALARM
1:003/002	K-6241	200-W MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
1:003/003						
1:003/004	MS-102-SY-A-1X	TRANSFER PUMP	P-102-SY-02A	RUNNING AUX		
1:003/005	MS-102-SY-A-1EX	TRANSFER PUMP	P-102-SY-02A	ENABLED -	POWER IS ON	
1:003/006		FLUSH PUMP	RUN CONTACT			
1:003/007						
1:003/010						
1:003/011						
1:003/012						
1:003/013						
1:003/014						
1:003/015						
1:003/016						
1:003/017						
S:000/000		Processor	arithmetic	carry	flag	
S:000/001		Processor	arithmetic	underflow/	overflow	flag
S:000/002		Processor	arithmetic	zero	flag	
S:000/003		Processor	arithmetic	sign	flag	
S:001/000		Bad RAM	CHECKSUM	at power	up	
S:001/001		PLC-5 in	RUN mode			
S:001/002		PLC-5 in	TEST mode			
S:001/003		PLC-5 in	PROG mode			
S:001/004		PLC-5 is	burning an	EEPROM		
S:001/005		Download-	ing in	progress		
S:001/006		Test edits	enabled			
S:001/007		Mode	switch	in REMOTE		
S:001/008		Forces	enabled			
S:001/009		Forces	present			
S:001/010		EEPROM	success-	fully	Burned	
S:001/011		Perform-	ing online	program-	ming	
S:001/012		Processor	is in	DEBUG mode		
S:001/013		User	program	CHECKSUM	done	
S:001/014		Last scan	of ladder	or SFC	step	
S:001/015		First scan	of ladder	or SFC	step	
S:007		Logical Rack	Status Bits	For Racks 0-7		
S:007/000		Rack 0	Faulted			
S:007/001		Rack 1	Faulted			
S:007/002		Rack 2	Faulted			
S:007/003		Rack 3	Faulted			
S:007/004		Rack 4	Faulted			
S:007/005		Rack 5	Faulted			
S:007/006		Rack 6	Faulted			
S:007/007		Rack 7	Faulted			
S:007/008		Block Xfer	queue to	rack 0 is	full	
S:007/009		Block Xfer	queue to	rack 1 is	full	
S:007/010		Block Xfer	queue to	rack 2 is	full	
S:007/011		Block Xfer	queue to	rack 3 is	full	
S:007/012		Block Xfer	queue to	rack 4 is	full	
S:007/013		Block Xfer	queue to	rack 5 is	full	
S:007/014		Block Xfer	queue to	rack 6 is	full	
S:007/015		Block Xfer	queue to	rack 7 is	full	
S:008		Last	program	scan time	ladder &	SFC
S:009		Maximum	program	scan time	ladder &	SFC
S:010/000		Battery	is bad or	missing		
S:010/001		DH+ active	node table	changed		
S:010/002		STI	overlap			
S:010/003		EEPROM	trans-	ferred		

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00078

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:01 02/19/99

S:010/004	Edits	prevent	SFC	continuing	
S:010/005	Invalid	I/O status	file		
S:010/006	Memory	cartridge	battery	low	
S:010/007	No more	command	blocks	exist	
S:010/009	No MCP was	configured	to run		
S:010/010	MCP not	allowed			
S:010/011	PII word	number	isn't in	local rack	
S:010/012	User PII	routine	overlap		
S:010/013	No command	block	exists to	get PII	
S:010/014	Arithmetic	overflow	occurred		
S:010/015	SFC	lingering	action	overlap	
S:011/000	Bad	program	file		
S:011/001	Bad	address	in ladder	program	
S:011/002	Programmer	error			
S:011/003	SFC Fault				
S:011/004	Program	assembly	error		
S:011/005	Powerup	protection	fault		
S:011/006	Error not	defined			
S:011/007	User	generated	fault		
S:011/008	Watchdog	timer	fault		
S:011/009	Bad system	config-	uration		
S:011/010	Hardware	Error			
S:011/011	MCP file	does not	exist or	is not	ladder
S:011/012	PII file	does not	exist or	is not	ladder
S:011/013	STI file	does not	exist or	is not	ladder
S:011/014	Fault file	does not	exist or	is not	ladder
S:011/015	Non ladder	file			
S:012	Fault Code				
S:013	Program	file where	fault	occurred	
S:014	Rung	number	where	fault	occurred
S:016	I/O status	file			
S:017/000	Queue full	between	local and	remote I/O	
S:017/001	Queue full	servicing	channel 1A		
S:017/002	Queue full	servicing	channel 1B		
S:017/003	Queue full	servicing	channel 2A		
S:017/004	Queue full	servicing	channel 2B		
S:017/005	No modem	on serial	port		
S:017/006	Remote I/O	is greater	than image	size	
S:017/008	ASCII	instruct-	ion error		
S:017/009	Duplicate	node	address		
S:018	Real time	clock YEAR			
S:019	Real time	clock	MONTH		
S:020	Real time	clock DAY			
S:021	Real time	clock HOUR			
S:022	Real time	clock	MINUTE		
S:022/000	REAL TIME	CLOCK	MINUTE	ONE'S BIT	
S:023	Real time	clock	SECOND		
S:023/000	REAL TIME	CLOCK	SECOND	ONE'S BIT	
S:023/001	REAL TIME	CLOCK	SECOND	TWO'S BIT	
S:024	Indexed	Addressing	Offset		
S:025	Adapter	Image	File		
S:026/000	SFC	Restart/	Continue		
S:026/001	Start-up	protect-	ion after	power loss	
S:026/002	Local rack	is 1 if	set or 0	if bit = 0	
S:026/003	Complementary	Rack	Mode		
S:027/000	Rack 0	Inhibit			
S:027/001	Rack 1	Inhibit			
S:027/002	Rack 2	Inhibit			
S:027/003	Rack 3	Inhibit			
S:027/004	Rack 4	Inhibit			
S:027/005	Rack 5	Inhibit			
S:027/006	Rack 6	Inhibit			
S:027/007	Rack 7	Inhibit			
S:027/008	Rack 0	Reset			
S:027/009	Rack 1	Reset			
S:027/010	Rack 2	Reset			
S:027/011	Rack 3	Reset			
S:027/012	Rack 4	Reset			
S:027/013	Rack 5	Reset			
S:027/014	Rack 6	Reset			
S:027/015	Rack 7	Reset			
S:028	Watchdog	time	Setpoint		
S:029	Fault	routine	file	number	
S:030	STI	setpoint	(interval)		
S:031	STI	file	number		
S:032	Logical Rack	Status Bits	For Racks 10-17		
S:032/000	Rack 10	Faulted			

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00079

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:01 02/19/99

S:032/001	Rack 11	Faulted			
S:032/002	Rack 12	Faulted			
S:032/003	Rack 13	Faulted			
S:032/004	Rack 14	Faulted			
S:032/005	Rack 15	Faulted			
S:032/006	Rack 16	Faulted			
S:032/007	Rack 17	Faulted			
S:032/008	Block Xfer	queue to	rack 10 is	full	
S:032/009	Block Xfer	queue to	rack 11 is	full	
S:032/010	Block Xfer	queue to	rack 12 is	full	
S:032/011	Block Xfer	queue to	rack 13 is	full	
S:032/012	Block Xfer	queue to	rack 14 is	full	
S:032/013	Block Xfer	queue to	rack 15 is	full	
S:032/014	Block Xfer	queue to	rack 16 is	full	
S:032/015	Block Xfer	queue to	rack 17 is	full	
S:033/000	Rack 10	Inhibit			
S:033/001	Rack 11	Inhibit			
S:033/002	Rack 12	Inhibit			
S:033/003	Rack 13	Inhibit			
S:033/004	Rack 14	Inhibit			
S:033/005	Rack 15	Inhibit			
S:033/006	Rack 16	Inhibit			
S:033/007	Rack 17	Inhibit			
S:033/008	Rack 10	Reset			
S:033/009	Rack 11	Reset			
S:033/010	Rack 12	Reset			
S:033/011	Rack 13	Reset			
S:033/012	Rack 14	Reset			
S:033/013	Rack 15	Reset			
S:033/014	Rack 16	Reset			
S:033/015	Rack 17	Reset			
S:034/000	Rack 20	Faulted			
S:034/001	Rack 21	Faulted			
S:034/002	Rack 22	Faulted			
S:034/003	Rack 23	Faulted			
S:034/004	Rack 24	Faulted			
S:034/005	Rack 25	Faulted			
S:034/006	Rack 26	Faulted			
S:034/007	Rack 27	Faulted			
S:034/008	Block Xfer	queue to	rack 20 is	full	
S:034/009	Block Xfer	queue to	rack 21 is	full	
S:034/010	Block Xfer	queue to	rack 22 is	full	
S:034/011	Block Xfer	queue to	rack 23 is	full	
S:034/012	Block Xfer	queue to	rack 24 is	full	
S:034/013	Block Xfer	queue to	rack 25 is	full	
S:034/014	Block Xfer	queue to	rack 26 is	full	
S:034/015	Block Xfer	queue to	rack 27 is	full	
S:035/000	Rack 20	Inhibit			
S:035/001	Rack 21	Inhibit			
S:035/002	Rack 22	Inhibit			
S:035/003	Rack 23	Inhibit			
S:035/004	Rack 24	Inhibit			
S:035/005	Rack 25	Inhibit			
S:035/006	Rack 26	Inhibit			
S:035/007	Rack 27	Inhibit			
S:035/008	Rack 20	Reset			
S:035/009	Rack 21	Reset			
S:035/010	Rack 22	Reset			
S:035/011	Rack 23	Reset			
S:035/012	Rack 24	Reset			
S:035/013	Rack 25	Reset			
S:035/014	Rack 26	Reset			
S:035/015	Rack 27	Reset			
S:046	PII	file	number		
S:047	PII	module	group to	examine	
S:048	PII	bit	mask		
S:048/000	PII Module	Bit	1=Monitor	0=Ignore	
S:049	PII	compare	value		
S:049/000	PII Bit	1=false to	TRUE	0=	true to
S:050	PII	down	count		
S:051	PII	return	mask		
S:052	PII	accum-	tulator		
S:053	STI	last	scan time		
S:054	STI	max	scan time		
S:055	PII	last	scan time		
S:056	PII	max	scan time		
S:079/000	Main	control	program A	disable	bit

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00080

08:16:01 02/19/99

DB Form Report

Sorted By: Address

S:079/001	Main	control	program B	disable	bit
S:079/002	Main	control	program C	disable	bit
S:079/003	Main	control	program D	disable	bit
S:079/004	Main	control	program E	disable	bit
S:079/005	Main	control	program F	disable	bit
S:079/006	Main	control	program G	disable	bit
S:079/007	Main	control	program H	disable	bit
S:079/008	Main	control	program I	disable	bit
S:079/009	Main	control	program J	disable	bit
S:079/010	Main	control	program K	disable	bit
S:079/011	Main	control	program L	disable	bit
S:079/012	Main	control	program M	disable	bit
S:079/013	Main	control	program N	disable	bit
S:079/014	Main	control	program O	disable	bit
S:079/015	Main	control	program P	disable	bit
S:080	Main	control	program A	file	number
S:081	Program A	scan time			
S:082	Program A	maximum	scan time		
S:083	Main	control	program B	file	number
S:084	Program B	scan time			
S:085	Program B	maximum	scan time		
S:086	Main	control	program C	file	number
S:087	Program C	scan time			
S:088	Program C	maximum	scan time		
S:089	Main	control	program D	file	number
S:090	Program D	scan time			
S:091	Program D	maximum	scan time		
S:092	Main	control	program E	file	number
S:093	Program E	scan time			
S:094	Program E	maximum	scan time		
S:095	Main	control	program F	file	number
S:096	Program F	scan time			
S:097	Program F	maximum	scan time		
S:098	Main	control	program G	file	number
S:099	Program G	scan time			
S:100	Program G	maximum	scan time		
S:101	Main	control	program H	file	number
S:102	Program H	scan time			
S:103	Program H	maximum	scan time		
S:104	Main	control	program I	file	number
S:105	Program I	scan time			
S:106	Program I	maximum	scan time		
S:107	Main	control	program J	file	number
S:108	Program J	scan time			
S:109	Program J	maximum	scan time		
S:110	Main	control	program K	file	number
S:111	Program K	scan time			
S:112	Program K	maximum	scan time		
S:113	Main	control	program L	file	number
S:114	Program L	scan time			
S:115	Program L	maximum	scan time		
S:116	Main	control	program M	file	number
S:117	Program M	scan time			
S:118	Program M	maximum	scan time		
S:119	Main	control	program N	file	number
S:120	Program N	scan time			
S:121	Program N	maximum	scan time		
S:122	Main	control	program O	file	number
S:123	Program O	scan time			
S:124	Program O	maximum	scan time		
S:125	Main	control	program P	file	number
S:126	Program P	scan time			
S:127	Program P	maximum	scan time		
B003/000	ALWAYS OFF	ALWAYS OFF	OUTPUT		
B003/001	ALWAYS ON	ALWAYS ON	OUTPUT		
B003/002	1_SEC PULSE	ONE SECOND	SINGLE SCAN	PULSE	
B003/003	2_SEC PULSE	TWO SECOND	SINGLE SCAN	PULSE	
B003/004	HALF_SEC_FLASH	HALF SECOND	FLASHER		
B003/005	1_SEC_FLASH	ONE SECOND	FLASHER		
B003/006	2_SEC_FLASH	TWO SECOND	FLASHER		
B003/007	1_MIN_PULSE	ONE MINUTE	SINGLE SCAN	PULSE	
B003/008					
B003/009					
B003/010					
B003/011					
B003/012					
B003/013					

8003/014						
8003/015						
8003/001	TWO SCAN SUB-	DIVISIONS	REGISTER			
8003/016	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIRST SET)		
8003/017	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SECOND SET)		
8003/018	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRD SET)		
8003/019	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTH SET)		
8003/020	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTH SET)		
8003/021	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTH SET)		
8003/022	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SEVENTH SET)		
8003/023	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(EIGHTH SET)		
8003/024	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(NINTH SET)		
8003/025	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TENTH SET)		
8003/026	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(ELEVENTH SET)		
8003/027	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TWELFTH SET)		
8003/028	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRTEENTH SET)		
8003/029	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTEENTH SET)		
8003/030	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTEENTH SET)		
8003/031	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTEENTH SET)		
8003/032	ONE SECOND	RISING	ONE SHOT			
8003/033	ONE SECOND	FALLING	ONE SHOT			
8003/034	TWO SECOND	RISING	ONE SHOT			
8003/035	TWO SECOND	FALLING	ONE SHOT			
8003/036	PROGRAM FILE	JUMP-TO-SUBR.	CONTROL RUNGS	COMMENT COIL		
8003/037	MCP FILE #2	END OF PROGRAM	COMMENT COIL			
8003/038	FAULT ROUTINE	FILE #3	END OF PROGRAM	COMMENT COIL		
8003/039	PROGRAM	FILE #4 START	OF SUBROUTINE	COMMENT COIL		
8003/040	PROGRAM	FILE #5 START	OF SUBROUTINE	COMMENT COIL		
8003/041	PROGRAM	FILE #6 START	OF SUBROUTINE	COMMENT COIL		
8003/042						
8003/043						
8003/044						
8003/045						
8003/046						
8003/047						
8003/048	ANALOG MODULE	INPUT CHANNEL	UNDER OR OVER	RANGE ALARMS	NOT ACTIVE	
8003/050	ONE MINUTE	RISING	ONE SHOT			
8003/051	ONE MINUTE	FALLING	ONE SHOT			
8003/075	TRANS. PUMP	P-102-SY-02A	TRANSFER	MODE STOP	Y-75.1	
8003/076	RESET TRANSFER	PUMP RUN	P-102-SY-02A	Y-75.1		
8003/077	BOOSTER	PUMPS ARE	SHUTDOWN			
8003/078	PERMISSIVE	SCHEMES	1 / 2A / 2B	ENABLED	Y-75.1	
8003/079	FLUSH	WATER	FLOW BIT			
8003/080	STOP	FLUSH PUMP	P-3100A	INTERNAL	Y-90.1	
8003/081	COMMUN. LOSS	WITH PCU-2	ONE-SHOT			
8003/082	COMMUN. LOSS	WITH PCU-2	ONE-SHOT			
8003/083	COMMUN. LOSS	WITH PCU-3	ONE-SHOT			
8003/084	COMMUN. LOSS	WITH PCU-3	ONE-SHOT			
8003/085	COMMUN. LOSS	WITH PCU-4	ONE-SHOT			
8003/086	COMMUN. LOSS	WITH PCU-4	ONE-SHOT			
8003/087	COMMUN. LOSS	WITH PCU-5	ONE-SHOT			
8003/088	COMMUN. LOSS	WITH PCU-5	ONE-SHOT			
8003/200	COMMUN. LOSS	WITH OCS	ONE-SHOT			
8003/201	COMMUN. LOSS	WITH OCS	ONE-SHOT			
8003/300	RAMP BLOCK	SUBROUTINE	RAMP_SBR			
8003/301	RAMP FUNCTION	COMMENT COIL				
8003/302	RAMP FUNCTION	COMMENT COIL				
8003/303	RAMP FUNCTION	COMMENT COIL				
8003/310	SPEED RAMP	REFERENCE	ENABLE			
8003/311	SPEED RAMP	ENABLE				
8003/312	RAMP SPEED	REFERENCE	SET POINT	DIFFERENCE	ONE SHOT	
8003/313	START SPEED	REFERENCE	RAMP LOGIC			
8003/314	RAMP REFERENCE	COMMENT COIL				
8003/315	RAMP OUTPUT	COMMENT COIL				
8003/316	RAMP JSR	COMMENT COIL				
8003/317	FINAL SPEED	REFERENCE	COMMENT COIL			
8003/480	INTEGRATOR	DEMO ENABLE				
8003/481	EXCLUSIVE OR	DEMO INPUT #1				
8003/482	EXCLUSIVE OR	DEMO INPUT #2				
8003/483	EXCLUSIVE OR	DEMO OUTPUT				
8003/484	J-K FLIP FLOP	DEMO INPUT				
8003/485	J-K FLIP FLOP	DEMO ONE SHOT				
8003/486	J-K FLIP FLOP	DEMO OUTPUT				
8003/487	J-K FLIP FLOP	DEMO INTERLOCK				
T004:000	POWER-UP	SEQUENCING	DELAY			
T004:000.ACC						
T004:000.ON	POWER-UP	SEQUENCING	DELAY			

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00082

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

08:16:02 02/19/99

T004:000.PRE					
T004:000.TT					
T004:001	HALF SECOND	FLASHER TIMER			
T004:001.ACC					
T004:001.DN	HALF SECOND	FLASHER TIMER			
T004:001.PRE					
T004:001.TT					
T004:002	200-W TANK	FARM MASTER	SHUTDOWN	TIMER	Y-77
T004:002.ACC					
T004:002.DN	200-W TANK	FARM MASTER	SHUTDOWN	TIMER	COMPLETE Y-77
T004:002.PRE					
T004:002.TT					
T004:003.ACC	FLUSH PUMP	P-3100A	FAILURE	TIMER	Y-90.1
T004:003.DN	FLUSH PUMP	P-3100A	FAILURE TIMER	COMPLETE	Y-90.1
T004:003.PRE					
T004:003.TT					
T004:004	COMMON. LOSS	TIMER WITH	PCU-2		
T004:004.ACC					
T004:004.DN	COMMON. LOSS	TIMER WITH	PCU-2		
T004:004.PRE					
T004:004.TT					
T004:005	COMMON. LOSS	TIMER WITH	PCU-3		
T004:005.ACC					
T004:005.DN	COMMON. LOSS	TIMER WITH	PCU-3		
T004:005.PRE					
T004:005.TT					
T004:006	COMMON. LOSS	TIMER WITH	PCU-4		
T004:006.ACC					
T004:006.DN	COMMON. LOSS	TIMER WITH	PCU-4		
T004:006.PRE					
T004:006.TT					
T004:007	COMMON. LOSS	TIMER WITH	PCU-5		
T004:007.ACC					
T004:007.DN	COMMON. LOSS	TIMER WITH	PCU-5		
T004:007.PRE					
T004:007.TT					
T004:010	RUN SPEED	REFERENCE RAMP	SUBROUTINE	TIMER	
T004:010.DN	RUN SPEED	REFERENCE RAMP	SUBROUTINE	TIMER	
T004:014.DN	FLUSH PUMP	START TIMER			
T004:040	COMM LOSS	TIMER	WITH OCS		
T004:040.DN	COMM LOSS	TIMER	WITH OCS		
R006:000	TWO SCAN SUB-	DIVISIONS	CONTROL	REGISTER	
R006:000.EN	TWO SCAN SUB-	DIVISIONS	CONTROL	ENABLED	
R006:000.UL	TWO SCAN SUB-	DIVISIONS	CONTROL	UNLOAD	
R006:010	COMPARE	PCU-1 TO PCU-2	MSG FILE	WITH PREVIOUS	
R006:011	COMPARE	PCU-1 TO PCU-3	MSG FILE	WITH PREVIOUS	
R006:012	COMPARE	PCU-1 TO PCU-4	MSG FILE	WITH PREVIOUS	
R006:013	COMPARE	PCU-1 TO PCU-5	MSG FILE	WITH PREVIOUS	
N007:000					
N007:001					
N007:002					
N007:003					
N007:004					
N007:005					
N007:006					
N007:007					
N007:008					
N007:009					
N007:010	CHEMICAL	REFERENCE	FOR ADDING TO	TANK TK-302-C	
N007:018	ACCUMULATED	INLET FLOW TO	TANK TK-302-C	LOW PORTION	WORKING REG.
N007:019	ACCUMULATED	INLET FLOW TO	TANK TK-302-C	HIGH PORTION	WORKING REG.
N007:020	DEMO LOOK-UP	FUNCTION INPUT	(0 TO 40)		
N007:021	LOOK-UP TABLE	DEMO POINTER	(0 TO 4)		
N007:022	LOOK-UP TABLE	DEMO LOW	FILE POINTER	(30 TO 34)	
N007:023	LOOK-UP TABLE	DEMO HIGH	FILE POINTER	(31 TO 35)	
N007:024	LOOK-UP TABLE	DEMO VALUE	INTERPOLATION	RATIO	
N007:025	LOOK-UP TABLE	DEMO TABLE	RANGE FOR	INTERPOLATION	
N007:026	LOOK-UP TABLE	DEMO OUTPUT			
N007:027	INTEGRATOR	DEMO INPUT			
N007:028	INTEGRATOR	DEMO OUTPUT			
N007:300	S.P. RAMP BLOCK	TARGET S.P.	WORKING REGISTER		
N007:301	S.P. RAMP BLOCK	CURRENT S.P.	WORKING REGISTER		
N007:302	S.P. RAMP BLOCK	S.P. DIFFERENCE	WORKING REGISTER		
N007:302/015	S.P. RAMP BLOCK	S.P. DIFFERENCE	WORKING REGISTER	SIGN BIT	RAMP DIFF NEG
N007:303	S.P. RAMP BLOCK	S.P. DIFFERENCE	ABSOLUTE VALUE	WORKING REGISTER	
N007:304	S.P. RAMP BLOCK	RAMP INCREMENT	LIMIT	WORKING REGISTER	

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00083

08:16:03 02/19/99

DB Form Report Sorted By: Address

N007:310	RAMP SPEED	REFERENCE	TARGET	SET POINT	
N007:311	RAMP SPEED	REFERENCE	CURRENT	SET POINT	
N007:312	SPEED RAMP	REFERENCE	TO SET POINT	DIFFERENCE	
N007:313	SPEED RAMP	REFERENCE	TO SET POINT	DIFFERENCE	ABSOLUTE VALUE
N007:314	SPEED	REFERENCE	INCREMENT LIMIT		
N007:315	RAMP SPEED	REFERENCE	LOW SPEED	THRESHOLD	
F008:000	SCALED	INLET FLOW TO	TANK TK-302-C		
F008:001	ACCUMULATED	INLET FLOW TO	TANK TK-302-C		
F008:002	INLET FLOW TO	TANK TK-302-C	SCALE FACTOR		
F008:003	CHEMICAL ADD	PUMP P-3100B TO	TANK TK-302-C	% OF INLET FLOW	REAL VALUE
F008:004	ACCUMULATED	INLET FLOW TO	TANK TK-302-C	WORKING HIGH	PORTION
F008:010	ACCUMULATED	INLET FLOW FOR	15 MINUTE TEST	& CALIBRATION	
F008:011	ACCUMULATED	INLET FLOW FOR	30 MINUTE TEST	& CALIBRATION	
F008:020	DEMO FUNCTION	INPUT			
F008:021	SQUARE ROOT	DEMO OUTPUT			
F008:022	POLYNOMIAL	DEMO OUTPUT			
F008:023	EXPONENTIAL	DEMO OUTPUT			
F008:024	LOGARITHM	DEMO OUTPUT			
F008:025	NATURAL LOG	DEMO OUTPUT			
F008:026	NON-LINEAR	FUNCTION GEN.	DEMO OUTPUT		
F008:030	MOVING AVERAGE	DEMO WEIGHTING	FACTOR (K)		
F008:031	MOVING AVERAGE	DEMO (1-K)	FACTOR		
F008:032	MOVING AVERAGE	DEMO WEIGHTED	PORTION OF	NEW VALUE	
F008:033	MOVING AVERAGE	DEMO OUTPUT			
F008:034	MOVING AVERAGE	DEMO WEIGHTED	PORTION OF	PREVIOUS VALUE	
N010:000	REGISTER FOR	VERIFYING	FAULT ROUTINE	FILE OPERATION	
N010:007	Logical Rack	Fault Status	For Racks 0-7	And Racks 10-17	
N010:008	Last	scan time	ladder &	SFC	
N010:009	Maximum	program	scan time	ladder &	SFC
N010:010/000	Battery	is bad or	missing		
N010:010/001	DH+ active	node table	changed		
N010:010/002	STI	overlap			
N010:010/003	EPRDMM	trans-	ferred		
N010:010/004	Edits	prevent	file	continuing	
N010:010/005	Invalid	I/O status	battery	low	
N010:010/006	Memory	cartridge	blocks	exist	
N010:010/007	No more	command	to run		
N010:010/009	No MCP was	configured			
N010:010/010	MCP not	allowed			
N010:010/011	Pil word	number	isn't in	local rack	
N010:010/012	User Pil	routine	overlap		
N010:010/013	No command	block	exists to	get Pil	
N010:010/014	Arithmetic	overflow	occurred	ladder	
N010:010/015	SFC	lingering	action	overlap	
N010:011/000	Bad	program	file	program	
N010:011/001	Bad	address	in ladder		
N010:011/002	Programmer	error			
N010:011/003	SFC Fault				
N010:011/004	Program	assembly	error		
N010:011/005	Powerup	protection	fault		
N010:011/006	Error not	defined			
N010:011/007	User	generated	fault		
N010:011/008	Watchdog	timer	fault		
N010:011/009	Bad system	config-	uration		
N010:011/010	Hardware	Error			
N010:011/011	MCP file	does not	exist or	is not	ladder
N010:011/012	Pil file	does not	exist or	is not	ladder
N010:011/013	STI file	does not	exist or	is not	ladder
N010:011/014	Fault file	does not	exist or	is not	ladder
N010:011/015	Non ladder	file			
N010:012	Fault Code				
N010:013	Program	file where	fault	occurred	
N010:014	Runs	number	where	fault	occurred
N010:016	I/O status	file			
N010:017	REGISTER FOR	VERIFYING	FAULT ROUTINE	FILE OPERATION	
N010:017/000	Queue full	between	local and	remote I/O	
N010:017/001	Queue full	servicing	channel 1A		
N010:017/002	Queue full	servicing	channel 1B		
N010:017/003	Queue full	servicing	channel 2A		
N010:017/004	Queue full	servicing	channel 2B		
N010:017/005	No modem	on serial	port	size	
N010:017/006	Remote I/O	is greater	than image		
N010:017/008	ASCII	instruct-	ion error		
N010:017/009	Duplicate	node	address		
N010:018	Real time	clock YEAR			
N010:019	Real time	clock	MONTH		
N010:020	Real time	clock DAY			

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00084

DB Form Report

Sorted By: Address

08:16:03 02/19/99

NO10:021	Real time	clock HOUR			
NO10:022	Real time	clock	MINUTE		
NO10:023	Real time	clock	SECOND		
WG011:000	SEND MSG	FROM PCU-1	TO PCU-2		
WG011:001	SEND MSG	FROM PCU-1	TO PCU-3		
WG011:002	SEND MSG	FROM PCU-1	TO PCU-4		
WG011:003	SEND MSG	FROM PCU-1	TO PCU-5		
BT012:000					
BT012:001					
BT012:002					
BT012:003					
BT012:004					
BT012:005					
NO13:000/000	ANALOG MODULE	POWERED UP BUT	NOT CONFIGURED		
NO13:000/001	ONE OR MORE	CHANNELS ARE	UNDER OR OVER	RANGE	
NO13:001	ANALOG MODULE	UNDERRANGE	BITS REGISTER		
NO13:001/000	ANALOG MODULE	CHAN. 1 DATA	UNDERRANGE		
NO13:001/001	ANALOG MODULE	CHAN. 2 DATA	UNDERRANGE		
NO13:001/002	ANALOG MODULE	CHAN. 3 DATA	UNDERRANGE		
NO13:001/003	ANALOG MODULE	CHAN. 4 DATA	UNDERRANGE		
NO13:001/004	ANALOG MODULE	CHAN. 5 DATA	UNDERRANGE		
NO13:001/005	ANALOG MODULE	CHAN. 6 DATA	UNDERRANGE		
NO13:001/006	ANALOG MODULE	CHAN. 7 DATA	UNDERRANGE		
NO13:001/007	ANALOG MODULE	CHAN. 8 DATA	UNDERRANGE		
NO13:002	ANALOG MODULE	OVERRRANGE	BITS REGISTER		
NO13:002/000	ANALOG MODULE	CHAN. 1 DATA	OVERRRANGE		
NO13:002/001	ANALOG MODULE	CHAN. 2 DATA	OVERRRANGE		
NO13:002/002	ANALOG MODULE	CHAN. 3 DATA	OVERRRANGE		
NO13:002/003	ANALOG MODULE	CHAN. 4 DATA	OVERRRANGE		
NO13:002/004	ANALOG MODULE	CHAN. 5 DATA	OVERRRANGE		
NO13:002/005	ANALOG MODULE	CHAN. 6 DATA	OVERRRANGE		
NO13:002/006	ANALOG MODULE	CHAN. 7 DATA	OVERRRANGE		
NO13:002/007	ANALOG MODULE	CHAN. 8 DATA	OVERRRANGE		
NO13:004	FT-302C-1R	FLUSH PUMP	P-3100A	OUTLET FLOW	
NO13:005	FT-302C-2R	INLET FLOW	TO TANK	TK-302-C	LINE 4
NO13:006	LIT-302C-1R	TANK	TK-302-C	LEVEL	
NO13:007	IY-P102SY-02AR	PUMP	P-102-SY-02A	CURRENT	
NO13:008	LIT-WST-3102R	TANK	241-SY-102	LEVEL	INDICATION
NO13:009	SPARE	ANALOG	INPUT		
NO13:010	SPARE	ANALOG	INPUT		
NO13:011	SPARE	ANALOG	INPUT		
NO13:062	P-3100BR	FLOW CONTROL	CHEM ADD	PUMP P-3100B	
NO13:063	SPARE	ANALOG	OUTPUT		
NO13:064	SPARE	ANALOG	OUTPUT		
NO13:065	SPARE	ANALOG	OUTPUT		
NO13:079/000	TERM. MODULE	CHAN. 1 DATA	UNDERRANGE		
NO13:079/001	TERM. MODULE	CHAN. 1 DATA	UNDERRANGE		
NO13:080	TE-302C-1R	TANK	TK-302-C	TEMPERATURE	
NO13:081/000	TERM. MODULE	CHAN. 2 DATA	UNDERRANGE		
NO13:081/001	TERM. MODULE	CHAN. 2 DATA	UNDERRANGE		
NO13:082	TE-302C-2R	FLUSH PUMP	P-3100A	OUTLET TEMP	3 INCH LINE
NO13:083/000	TERM. MODULE	CHAN. 3 DATA	UNDERRANGE		
NO13:083/001	TERM. MODULE	CHAN. 3 DATA	UNDERRANGE		
NO13:084	SPARE	THERMOCOUPLE	INPUT		
NO13:085/000	TERM. MODULE	CHAN. 4 DATA	UNDERRANGE		
NO13:085/001	TERM. MODULE	CHAN. 4 DATA	UNDERRANGE		
NO13:086	SPARE	THERMOCOUPLE	INPUT		
NO13:087/000	TERM. MODULE	CHAN. 5 DATA	UNDERRANGE		
NO13:087/001	TERM. MODULE	CHAN. 5 DATA	UNDERRANGE		
NO13:088	SPARE	THERMOCOUPLE	INPUT		
NO13:089/000	TERM. MODULE	CHAN. 6 DATA	UNDERRANGE		
NO13:089/001	TERM. MODULE	CHAN. 6 DATA	UNDERRANGE		
NO13:090	SPARE	THERMOCOUPLE	INPUT		
NO13:091/000	TERM. MODULE	CHAN. 7 DATA	UNDERRANGE		
NO13:091/001	TERM. MODULE	CHAN. 7 DATA	UNDERRANGE		
NO13:092	SPARE	THERMOCOUPLE	INPUT		
NO13:093/000	TERM. MODULE	CHAN. 8 DATA	UNDERRANGE		
NO13:093/001	TERM. MODULE	CHAN. 8 DATA	UNDERRANGE		
NO13:094	SPARE	THERMOCOUPLE	INPUT		
NO13:094	SPARE	THERMOCOUPLE	INPUT		
NO14:000/000	HB PLC1 OCS	HEARTBEAT	FROM PLC-1	TO OCS	
NO14:000/001	COM-1 OCS	COMMUN. WITH	OCS	IGNORED	
NO14:000/002	COM-12	COMMUN. WITH	PCU-2	IGNORED	
NO14:000/003	COM-13	COMMUN. WITH	PCU-3	IGNORED	
NO14:000/004	COM-14	COMMUN. WITH	PCU-4	IGNORED	
NO14:000/005	COM-15	COMMUN. WITH	PCU-5	IGNORED	
NO14:000/006	BATT_BAD_PLCL1	PLC-1 BATTERY	IS BAD OR	MISSING	

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00085

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:04 02/19/99

N014:000/007							
N014:000/008	ZL-3102C	TRANSFER	PUMP	P-102-SY-02A	RECIRCULATION	MODE Y-75.1	
N014:000/009	ZL-3102D	TRANSFER	PUMP	P-102-SY-02A	TRANSFER	MODE Y-75.1	
N014:000/010							
N014:000/011	LAL-302C1	TANK	TK-302C-1	LEVEL BIT		Y-90.1	
N014:000/012	FAL-P3100A	FLUSH PUMP	P-3100A	LOW FLOW		Y-90.1	
N014:000/013	YL-058W	OVERRIDE OF	200-W	MASTER	SHUTDOWN	Y-77.1	
N014:000/014	LAL-3102	TANK	241-SY-102	LOW LEVEL			
N014:000/015							
N014:010	COM SPD_TST	COMMUNICATIONS	TEST REGISTER	TO OIT			
N014:011							
N014:011/000	FI-302C-1 A	ANALOG INPUT	OVER AND UNDER	RANGE STATUS	BITS TO OIT		
N014:011/001	FI-302C-2 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:011/002	LI-302C-1 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:011/003	LI-3102 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:011/004	LI-3102 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:011/005	PCU1-SP-AI-6 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:011/006	PCU1-SP-AI-7 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:011/007	PCU1-SP-AI-8 A	PCU-1 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:012/008	TI-302C-1 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/009	PCU1-SP-TI-2 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/010	TI-302C-2 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/011	PCU1-SP-TI-4 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/012	PCU1-SP-TI-5 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/013	PCU1-SP-TI-6 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/014	PCU1-SP-TI-7 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:012/015	PCU1-SP-TI-8 A	PCU-1 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:026		DIGITAL INPUT	REGISTER TO	OIT TERMINALS			
N014:026/000	TAH-302C-1A	CIRCULATION	HEATER #1	HTR-302C-1	OUTLET TEMP	OFF = ALARM	
N014:026/001	TAH-302C-1B	CIRCULATION	HEATER #2	HTR-302C-2	OUTLET TEMP	OFF = ALARM	
N014:026/002	XA-058W	200-W MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1	
N014:026/003	PCU1-SP-TI-03	SPARE DIGITAL	INPUT				
N014:026/004	P-102-SY-02A3	TRANSFER PUMP	P-102-SY-02A	RUNNING AUX			
N014:026/005	P-102-SY-02A4	TRANSFER PUMP	P-102-SY-02A	ENABLED -	POWER ON		
N014:026/006	P3100A3	FLUSH PUMP	RUN CONTACT				
N014:026/007	PCU1-SP-TI-07	SPARE DIGITAL	INPUT				
N014:026/008	PCU1-SP-TI-10	SPARE DIGITAL	INPUT				
N014:026/009	PCU1-SP-TI-11	SPARE DIGITAL	INPUT				
N014:026/010	PCU1-SP-TI-12	SPARE DIGITAL	INPUT				
N014:026/011	PCU1-SP-TI-13	SPARE DIGITAL	INPUT				
N014:026/012	PCU1-SP-TI-14	SPARE DIGITAL	INPUT				
N014:026/013	PCU1-SP-TI-15	SPARE DIGITAL	INPUT				
N014:026/014	PCU1-SP-TI-16	SPARE DIGITAL	INPUT				
N014:026/015	PCU1-SP-TI-17	SPARE DIGITAL	INPUT				
N014:027							
N014:028							
N014:029		DIGITAL OUTPUT	REGISTER TO	OIT TERMINALS			
N014:029/000	P-3100A2	STOP PUMP	P-3100A			Y-90.1	
N014:029/001	P-3100A1	START PUMP	P-3100A			Y-90.1	
N014:029/002	P-102-SY-02A1	START PUMP	P-102-SY-02A			Y75	
N014:029/003	P-102-SY-02A2	STOP PUMP	P-102-SY-02A				
N014:029/004	200W-S02	INPUT SIGNAL	TO 200-W	MASTER	SHUTDOWN	Y-72.1	
N014:029/005	PCU1-SP-07-05	SPARE DIGITAL	OUTPUT				
N014:029/006	PCU1-SP-07-06	SPARE DIGITAL	OUTPUT				
N014:029/007	PCU1-SP-07-07	SPARE DIGITAL	OUTPUT				
N014:029/008	PCU1-SP-07-10	SPARE DIGITAL	OUTPUT				
N014:029/009	PCU1-SP-07-11	SPARE DIGITAL	OUTPUT				
N014:029/010	PCU1-SP-07-12	SPARE DIGITAL	OUTPUT				
N014:029/011	PCU1-SP-07-13	SPARE DIGITAL	OUTPUT				
N014:029/012	PCU1-SP-07-14	SPARE DIGITAL	OUTPUT				
N014:029/013	PCU1-SP-07-15	SPARE DIGITAL	OUTPUT				
N014:029/014	PCU1-SP-07-16	SPARE DIGITAL	OUTPUT				
N014:029/015	PCU1-SP-07-17	SPARE DIGITAL	OUTPUT				
N014:030							
N014:031	FI-302C-1	FLUSH PUMP	P-3100A	OUTLET FLOW			
N014:032	FI-302C-2	INLET FLOW	TO TANK	TK-302-C	LINE 4		
N014:033	LI-302C-1	TANK	TK-302-C	LEVEL			
N014:034	LI-3102	PUMP	P-102-SY-02A	CURRENT			
N014:035	LI-3102	TANK	241-SY-102	LEVEL	INDICATION		
N014:036	PCU1-SP-AI-6	SPARE	ANALOG	INPUT			
	PCU1-SP-AI-7	SPARE	ANALOG	INPUT			
N014:037	PCU1-SP-AI-8	SPARE	ANALOG	INPUT			
N014:038	TI-302C-1	TANK	TK-302-C	TEMPERATURE			
N014:039	TI-302C-2	FLUSH PUMP	P-3100A	OUTLET TEMP	LINE 3 INCH		
N014:040	PCU1-SP-TI-3	SPARE	THERMOCOUPLE	INPUT			
N014:041	PCU1-SP-TI-4	SPARE	THERMOCOUPLE	INPUT			
N014:042	PCU1-SP-TI-5	SPARE	THERMOCOUPLE	INPUT			
N014:043	PCU1-SP-TI-6	SPARE	THERMOCOUPLE	INPUT			

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00086

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

08:16:04 02/19/99

N014:044	PCU1-SP-T1-7	SPARE	THERMOCOUPLE	INPUT		
N014:045	PCU1-SP-T1-8	SPARE	THERMOCOUPLE	INPUT		
N014:046	FIG-302C-2A	FLOW CONTROL	CHEM ADD	PUMP P-3100B		
N014:047	PCU1-SP-A0-2	SPARE	ANALOG	OUTPUT		
N014:048	PCU1-SP-A0-3	SPARE	ANALOG	OUTPUT		
N014:049	PCU1-SP-A0-4	SPARE	ANALOG	OUTPUT		
N014:050						
N014:051						
N014:052						
N014:053						
N014:054						
N014:058	FIQ-302C-2L	ACCUMULATED	INLET FLOW TO	TANK TK-302-C	LOW PORTION	
N014:059	FIQ-302C-2H	ACCUMULATED	INLET FLOW TO	TANK TK-302-C	HIGH PORTION	
N014:060						
N014:060/000	HS PLC3_OCS	HEARTBEAT	FROM PLC-3	TO OCS		
N014:060/001	COM-31	COMMUN. WITH	PCU-1	IGNORED		
N014:060/002	COM-32	COMMUN. WITH	PCU-2	IGNORED		
N014:060/003	COM-3_OCS	COMMUNICATION	WITH OCS	IGNORED		
N014:060/004	COM-34	COMMUN. WITH	PCU-4	IGNORED		
N014:060/005	COM-35	COMMUN. WITH	PCU-5	IGNORED		
N014:060/006	BATT_BAD_PLG3	PLC-3 BATTERY	IS BAD OR	MISSING		
N014:060/007						
N014:060/008						
N014:060/009						
N014:060/010						
N014:060/011						
N014:060/012	LDA-3151	LEAK DETECTED	AT VENT	STATION	6241-V SWMP	Y-72.1
N014:060/013	PAH-3187	VALVE	SOV-3187A/B	FAILURE		Y73
N014:060/014	PAH-3188	VALVE	SOV-3188A/B	FAILURE		Y73
N014:060/015	PAH-3185	VALVE	SOV-3185A/B	FAILURE		Y73
N014:061/000	ZA-3185A1	VALVE	FAILED	TO OPEN		Y71
N014:061/001	ZA-3185A2	VALVE	FAILED	TO CLOSE		Y71
N014:061/002	ZA-3185A	VALVE	POSITION	SWITCH FAILURE		Y71
N014:061/003	ZA-3185B1	VALVE	FAILED	TO OPEN		Y71
N014:061/004	ZA-3185B2	VALVE	FAILED	TO CLOSE		Y71
N014:061/005	ZA-3185B	VALVE	POSITION	SWITCH FAILURE		Y71
N014:061/006	ZA-3166A1	VALVE	FAILED	TO OPEN		Y71
N014:061/007	ZA-3166A2	VALVE	FAILED	TO CLOSE		Y71
N014:061/008	ZA-3166A	VALVE	POSITION	SWITCH FAILURE		Y71
N014:061/009	ZA-3166B1	VALVE	FAILED	TO OPEN		Y71
N014:061/010	ZA-3166B2	VALVE	FAILED	TO CLOSE		Y71
N014:061/011	ZA-3166B	VALVE	POSITION	SWITCH FAILURE		Y71
N014:061/012	ZA-3167A1	VALVE	FAILED	TO OPEN		Y88-1
N014:061/013	ZA-3167A2	VALVE	FAILED	TO CLOSE		Y88-1
N014:061/014	ZA-3167A	VALVE	POSITION	SWITCH FAILURE		Y88-1
N014:061/015						
N014:062/000	ZA-3167B1	VALVE	FAILED	TO OPEN		Y88-2
N014:062/001	ZA-3167B2	VALVE	FAILED	TO CLOSE		Y88-2
N014:062/002	ZA-3167B	VALVE	POSITION	SWITCH FAILURE		Y88-2
N014:062/003	ZA-3168A1	VALVE	FAILED	TO OPEN		Y81-3
N014:062/004	ZA-3168A2	VALVE	FAILED	TO CLOSE		Y81-3
N014:062/005	ZA-3168A	VALVE	POSITION	SWITCH FAILURE		Y81-3
N014:062/006	ZA-3168B1	VALVE	FAILED	TO OPEN		Y81-4
N014:062/007	ZA-3168B2	VALVE	FAILED	TO CLOSE		Y81-4
N014:062/008	ZA-3168B	VALVE	POSITION	SWITCH FAILURE		Y81-4
N014:062/009	ZA-3185A1	VALVE	FAILED	TO OPEN		Y81-1
N014:062/010	ZA-3185A2	VALVE	FAILED	TO CLOSE		Y81-1
N014:062/011	ZA-3185A	VALVE	POSITION	SWITCH FAILURE		Y81-1
N014:062/012	ZA-3185B1	VALVE	FAILED	TO OPEN		Y81-2
N014:062/013	ZA-3185B2	VALVE	FAILED	TO CLOSE		Y81-2
N014:062/014	ZA-3185B	VALVE	POSITION	SWITCH FAILURE		Y81-2
N014:062/015						
N014:063/000	TR_ON_1001	TRANSFER 1	INITIATED			Y-41.1
N014:063/001	TR_ON_1002A	TRANSFER 2A	INITIATED			Y-42.1
N014:063/002	TR_ON_1002B	TRANSFER 2B	INITIATED			Y-43.1
N014:063/003	TR_ON_1003	TRANSFER 3	INITIATED			Y-44.1
N014:063/004						
N014:063/005						
N014:063/006						
N014:063/007						
N014:063/008						
N014:063/009						
N014:063/010						
N014:063/011						
N014:063/012						
N014:063/013						
N014:063/014						

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00087

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

08:16:05 02/19/99

N014:063/015							
N014:064							
N014:064/000	TI-3126A A	PCU-3 INPUT	OVER AND UNDER	RANGE STATUS	BITS TO OIT		
N014:064/001	PCU3-SP-TI-2 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:064/002	TI-3126A A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:064/003	PCU3-SP-TI-4 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:064/004	PCU3-SP-TI-5 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:064/005	PCU3-SP-TI-6 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:064/006	PCU3-SP-TI-7 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:064/007	PCU3-SP-TI-8 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM		
N014:065/008	P1-3126A A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/009	P1-3126A A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/010	P1-3167 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/011	P1-3168 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/012	P1-3185 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/013	PCU3-SP-A1-6 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/014	PCU3-SP-A1-7 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:065/015	PCU3-SP-A1-8 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM		
N014:066		DIGITAL INPUT	REGISTER TO	OIT TERMINALS			
N014:066/000	ZLH-3165A	SOV-3165A	IS OPEN				Y70
N014:066/001	ZLL-3165A	SOV-3165A	IS CLOSED				Y70
N014:066/002	ZLL-3165B	SOV-3165B	IS OPEN				Y70
N014:066/003	ZLL-3165B	SOV-3165B	IS CLOSED				Y70
N014:066/004	ZLH-3166A	SOV-3166A	IS OPEN				Y70
N014:066/005	ZLL-3166A	SOV-3166A	IS CLOSED				Y70
N014:066/006	ZLH-3166B	SOV-3166B	IS OPEN				Y70
N014:066/007	ZLL-3166B	SOV-3166B	IS CLOSED				Y88-1
N014:066/008	ZLH-3167A	SOV-3167A	IS OPEN				Y88-1
N014:066/009	ZLL-3167A	SOV-3167A	IS CLOSED				Y88-1
N014:066/010	ZLH-3168A	SOV-3168A	IS OPEN				Y81-3
N014:066/011	ZLL-3168A	SOV-3168A	IS CLOSED				Y81-3
N014:066/012	ZLH-3168B	SOV-3168B	IS OPEN				Y-81-4
N014:066/013	ZLL-3168B	SOV-3168B	IS CLOSED				Y-81-4
N014:066/014	ZLH-3185A	SOV-3185A	IS OPEN				Y81-1
N014:066/015	ZLL-3185A	SOV-3185A	IS CLOSED				Y81-1
N014:067/000	ZLH-3185B	SOV-3185B	IS OPEN				Y81-2
N014:067/001	ZLL-3185B	SOV-3185B	IS CLOSED				Y81-2
N014:067/002	PCU3-SP-14-2	SPARE	DIGITAL	INPUT			
N014:067/003	PCU3-SP-14-3	SPARE	DIGITAL	INPUT			
N014:067/004	LDAH-3151	6241-V	SUMP LEAK	DETECTION			Y72
N014:067/005	LDA-3161	6241-V	ENCASEMENT	LEAK	DETECTION		Y72
N014:067/006	YA-3102A	ENCASEMENT	RUPTURE	DISK	ACTIVATED		OIT
N014:067/007	YA-3102B	ENCASEMENT	RUPTURE	DISK	ACTIVATED		OIT
N014:067/008	YA-3102C	ENCASEMENT	RUPTURE	DISK	ACTIVATED		OIT
N014:067/009	YA-3102D	ENCASEMENT	RUPTURE	DISK	ACTIVATED		OIT
N014:067/010	ZLH-3167B	SOV-3167B	IS OPEN				Y-88-2
N014:067/011	ZLL-3167B	SOV-3167B	IS CLOSED				Y-88-2
N014:067/012	PAL-3100B	LOW	COMPRESSOR	SA-CMP-3101B	PRESSURE		
N014:067/013	LDA-3151	SUMP LEAK	DETECTOR	FAILURE			Y72
N014:067/014	PCU3-SP-14-16	SPARE	DIGITAL	INPUT			
N014:067/015	PCU3-SP-14-17	SPARE	DIGITAL	INPUT			
N014:068		DIGITAL OUTPUT	REGISTER TO	OIT TERMINALS			
N014:068/000	SOV-3165A1	OPEN VALVE	SOV-3165A				Y71
N014:068/001	SOV-3165A2	CLOSE VALVE	SOV-3165A				Y71
N014:068/002	SOV-3165B1	OPEN VALVE	SOV-3165B				Y71
N014:068/003	SOV-3165B2	CLOSE VALVE	SOV-3165B				Y71
N014:068/004	SOV-3166A1	OPEN VALVE	SOV-3166A				Y71
N014:068/005	SOV-3166A2	CLOSE VALVE	SOV-3166A				Y71
N014:068/006	SOV-3166B1	OPEN VALVE	SOV-3166B				Y71
N014:068/007	SOV-3166B2	CLOSE VALVE	SOV-3166B				Y88-1
N014:068/008	SOV-3167A1	OPEN VALVE	SOV-3167A				Y88-1
N014:068/009	SOV-3167A2	CLOSE VALVE	SOV-3167A				Y81-3
N014:068/010	SOV-3168A1	OPEN VALVE	SOV-3168A				Y81-3
N014:068/011	SOV-3168A2	CLOSE VALVE	SOV-3168A				Y81-4
N014:068/012	SOV-3168B1	OPEN VALVE	SOV-3168B				Y81-4
N014:068/013	SOV-3168B2	CLOSE VALVE	SOV-3168B				Y81-1
N014:068/014	SOV-3185A1	OPEN VALVE	SOV-3185A				Y81-1
N014:068/015	SOV-3185A2	CLOSE VALVE	SOV-3185A				
N014:069/000	SOV-3185B1	OPEN VALVE	SOV-3185B				Y81-2
N014:069/001	SOV-3185B2	CLOSE VALVE	SOV-3185B				Y81-2
N014:069/002	P-3116-SD	SHUTDOWN	SUMP PUMP	P-3116			Y-82-1
N014:069/003	SOV-3167B1	OPEN VALVE	SOV-3167B				Y88-1
N014:069/004	SOV-3167B2	CLOSE VALVE	SOV-3167B				Y88-1
N014:069/005	PCU3-SP-07-05	SPARE DIGITAL	OUTPUT				
N014:069/006	PCU3-SP-07-06	SPARE DIGITAL	OUTPUT				
N014:069/007	PCU3-SP-07-07	SPARE DIGITAL	OUTPUT				
N014:069/008	PCU3-SP-07-10	SPARE DIGITAL	OUTPUT				

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00088

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:05 02/19/99

N014:069/009	PCU3-SP-07-11	SPARE	DIGITAL	OUTPUT			
N014:069/010	PCU3-SP-07-12	SPARE	DIGITAL	OUTPUT			
N014:069/011	PCU3-SP-07-13	SPARE	DIGITAL	OUTPUT			
N014:069/012	PCU3-SP-07-14	SPARE	DIGITAL	OUTPUT			
N014:069/013	PCU3-SP-07-15	SPARE	DIGITAL	OUTPUT			
N014:069/014	PCU3-SP-07-16	SPARE	DIGITAL	OUTPUT			
N014:069/015	PCU3-SP-07-17	SPARE	DIGITAL	OUTPUT			
N014:070	TI-3126A	LINE		WT-SNL-3150	TEMPERATURE		
N014:071	PCU3-SP-TI-2	SPARE		THERMOCOUPLE	INPUT		
N014:072	TI-3126B	LINE		WT-SLL-3160	TEMPERATURE		
N014:073	PCU3-SP-TI-4	SPARE		THERMOCOUPLE	INPUT		
N014:074	PCU3-SP-TI-5	SPARE		THERMOCOUPLE	INPUT		
N014:075	PCU3-SP-TI-6	SPARE		THERMOCOUPLE	INPUT		
N014:076	PCU3-SP-TI-7	SPARE		THERMOCOUPLE	INPUT		
N014:077	PCU3-SP-TI-8	SPARE		THERMOCOUPLE	INPUT		
N014:078	PI-3126A	LOSS OF	VACUUM		WT-SNL-3150		
N014:079	PI-3126B	LOSS OF	VACUUM		WT-SLL-3160		
N014:080	PI-3167	VALVE	SOV-3167A/B		PRESSURE		
N014:081	PI-3168	VALVE	SOV-3168A/B		PRESSURE		
N014:082	PI-3185	VALVE	SOV-3185A/B		PRESSURE		
N014:083	PCU3-SP-AI-6	SPARE		ANALOG	INPUT		
N014:084	PCU3-SP-AI-7	SPARE		ANALOG	INPUT		
N014:085	PCU3-SP-AI-8	SPARE		ANALOG	INPUT		
N014:086							
N014:087							
N014:088							
N014:089							
N014:090							
N014:090/000	HB PLC4_OCS	HEARTBEAT	FROM PLC-4		TO OCS		
N014:090/001	COM-41	COMMUN. WITH	PCU-1		IGNORED		
N014:090/002	COM-42	COMMUN. WITH	PCU-2		IGNORED		
N014:090/003	COM-43	COMMUN. WITH	PCU-3		IGNORED		
N014:090/004	COM-4_OCS	COMMUN. WITH	OCS		IGNORED		
N014:090/005	COM-45	COMMUN. WITH	PCU-5		IGNORED		
N014:090/006	BATT_BAD_PLC4	PLC-4 BATTERY	IS BAD OR		MISSING		
N014:090/007							
N014:090/008							
N014:090/009							
N014:090/010							
N014:090/011							
N014:090/012	YL-058E	OVERRIDE OF	200-E MASTER		SHUTDOWN		Y-77.1
N014:090/013							
N014:090/014							
N014:090/015							
N014:091							
N014:091/000	ZA-843-1	VALVE FAILED	TO REACH	POS. 1			Y71.2
N014:091/001	ZA-843-2	VALVE FAILED	TO REACH	POS. 2			Y71.2
N014:091/002	ZA-843-3	VALVE FAILED	TO REACH	POS. 3			Y71.2
N014:091/003	ZA-843	VALVE	POSITION	SWITCH FAILURE			Y71.2
N014:091/004	ZA-844-1	VALVE FAILED	TO REACH	POS. 1			Y71.3
N014:091/005	ZA-844-2	VALVE FAILED	TO REACH	POS. 2			Y71.3
N014:091/006	ZA-844-3	VALVE FAILED	TO REACH	POS. 3			Y71.3
N014:091/007	ZA-844	VALVE	POSITION	SWITCH FAILURE			Y71.3
N014:091/008	ZA-845-1	VALVE	FAILED	TO OPEN			Y-71
N014:091/009	ZA-845-2	VALVE	FAILED	TO CLOSE			Y-71
N014:091/010	ZA-845	VALVE	POSITION	SWITCH FAILURE			Y-71
N014:091/011	ZA-846-1	VALVE	FAILED	TO OPEN			Y-71
N014:091/012	ZA-846-2	VALVE	FAILED	TO CLOSE			Y-71
N014:091/013	ZA-846	VALVE	POSITION	SWITCH FAILURE			Y-71
N014:091/014							
N014:091/015							
N014:092							
N014:092/000	DI-850 A	PCU-4 INPUT	OVER AND UNDER	RANGE STATUS		BITS TO 011	
N014:092/001	LI-850 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:092/002	RI-851 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:092/003	FI-851 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:092/004	DI-853 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:092/005	LI-853 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:092/006	PI-841 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:092/007	PI-842 A	PCU-4 INPUT	ANALOG	OVER OR UNDER		RANGE ALARM	
N014:093							
N014:093/008	TI-841 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER		RANGE ALARM	
N014:093/009	PCU4-SP-TI-2 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER		RANGE ALARM	
N014:093/010	TI-842 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER		RANGE ALARM	
N014:093/011	PCU4-SP-TI-4 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER		RANGE ALARM	
N014:093/012	PCU4-SP-TI-5 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER		RANGE ALARM	
N014:093/013	PCU4-SP-TI-6 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER		RANGE ALARM	

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00089

DB Form Report

Sorted By: Address

08:16:06 02/19/99

N014:093/014	PCU4-SP-TI-7 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/015	PCU4-SP-TI-8 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:094		DIGITAL INPUT	REGISTER TO	OIT TERMINALS		
N014:094/000	ZLH-845	MOV-845	IS OPEN			Y71
N014:094/001	ZLH-845	MOV-845	IS CLOSED			Y71
N014:094/002	ZL-843-2	MOV-843	IS IN POSITION	2 (A-C)		Y71
N014:094/003	ZL-843-3	MOV-843	IS IN POSITION	3 (B-C)		Y71
N014:094/004	ZL-843-1	MOV-843	IS IN POSITION	1 (A-B)		Y71
N014:094/005	ZL-844-2	MOV-844	IS IN POSITION	2 (A-C)		Y71
N014:094/006	ZL-844-3	MOV-844	IS IN POSITION	3 (B-C)		Y71
N014:094/007	ZL-844-1	MOV-844	IS IN POSITION	1 (A-B)		Y71
N014:094/008	ZLH-846	MOV-846	IS OPEN			Y71
N014:094/009	ZLL-846	MOV-846	IS CLOSED			Y71
N014:094/010	YA-841	ENCASEMENT	RUPTURE DTSK	ACTIVATED		Y78
N014:094/011	YA-842	ENCASEMENT	RUPTURE DISK	ACTIVATED		Y78
N014:094/012	200E-S01	200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N014:094/013	RXA-852	RAD EQPT	FAILURE FROM	296-A-25 STACK	MONITOR	(OCS)
N014:094/014	LDA-841	244-A PUMP	PIT LEAK	DETECTION		Y72
N014:094/015	YL-841	ON/OFF STATUS	FOR PUMP	P-841		(OCS)
N014:095		DIGITAL OUTPUT	REGISTER TO	OIT TERMINALS		
N014:095/000	MOV-845-1	OPEN VALVE	MOV-845			Y71
N014:095/001	MOV-845-2	CLOSE VALVE	MOV-845			Y71
N014:095/002	MOV-843-2	VALVE 843 TO	POS. 2			Y71
N014:095/003	MOV-843-3	VALVE 843 TO	POS. 3			Y71
N014:095/004	MOV-843-1	VALVE 843 TO	POS. 1			Y71
N014:095/005	MOV-846-1	OPEN VALVE	MOV-846			Y71
N014:095/006	MOV-846-2	CLOSE VALVE	MOV-846			Y71
N014:095/007	MOV-844-2	VALVE 844 TO	POS. 2			Y71
N014:095/008	MOV-844-3	VALVE 844 TO	POS. 3			Y71
N014:095/013	PCU4-SP-07-15	SPARE DIGITAL	OUTPUT			
N014:095/014	PCU4-SP-07-16	SPARE DIGITAL	OUTPUT			
N014:095/015	PCU4-SP-07-17	SPARE DIGITAL	OUTPUT			
N014:096	DI-850	DENSITY	READING OF	244-A SUWP		
N014:097	LI-850	244-A SUWP	LEVEL	READING		
N014:098	RI-851	RADIATION	INDICATION	FROM 296-A-25	STACK MONITOR	
N014:099	FI-851	FLOW	INDICATION	FROM 296-A-25	STACK MONITOR	
N014:100	DI-853	DENSITY	READING OF	244-A	CATCH TANK	
N014:101	LI-853	244-A	CATCH TANK	LEVEL	READING	
N014:102	PI-841	VALVE	MOV-843/846	FAILURE		
N014:103	PI-842	VALVE	MOV-844/845	FAILURE		
N014:104	TI-841	LINE	WT-SLL-3150	TEMPERATURE		
N014:105	PCU4-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014:106	TI-842	LINE	WT-SLL-3160	TEMPERATURE		
N014:107	PCU4-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014:108	PCU4-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014:109	PCU4-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014:110	PCU4-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		
N014:111	PCU4-SP-TI-8	SPARE	THERMOCOUPLE	INPUT		
N014:112						
N014:113						
N014:114						
N014:120						
N014:120/000	HB_OCS_PLC1	HEARTBEAT	FROM OCS	TO PLC-1		
N014:120/001						
N014:120/002						
N014:120/003						
N014:120/004						
N014:120/005						
N014:120/006	HS-3102A	START	TRANSFER	PUMP	P-102-SY-02A	Y75
N014:120/007	HS-3102B	STOP	TRANSFER	PUMP	P-102-SY-02A	Y75
N014:120/008	HS-3102C	TRANSFER	PUMP	P-102-SY-02A	RECIRCULATION	Y-75.1
N014:120/009	HS-058W	OVERRIDE OF	MASTER	SHUTDOWN		Y-77.1
N014:120/010	HS-3100A1	START	FLUSH PUMP	P-3100A		Y-90.1
N014:120/011	HS-3100A2	STOP	FLUSH PUMP	P-3100A		Y-90.1
N014:120/012	HS-302C-2R	ACCUMULATED	INLET FLOW TO	TANK TK-302-C	RESET	
N014:120/013						
N014:120/014						
N014:120/015						
N014:121/000						
N014:121/001						
N014:121/002						
N014:121/003						
N014:121/004						
N014:121/005						
N014:121/006						
N014:121/007						
N014:121/008						

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00090

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:06 02/19/99

N014:121/009						
N014:121/010						
N014:121/011						
N014:121/012						
N014:121/013						
N014:121/014						
N014:121/015						
N014:140	FR-302C-2	CHEMICAL ADD	PUMP P-3100B TO	TANK TK-302-C	% OF INLET FLOW	REF FROM OIT
N014:141						
N014:150						
N014:150/000	HB_OCS_PLG2	HEARTBEAT	FROM OCS	TO PLC-2		
N014:150/001						
N014:150/002						
N014:150/003						
N014:150/004						
N014:150/005						
N014:150/006						
N014:150/007						
N014:150/008						
N014:150/009						
N014:150/010						
N014:150/011						
N014:150/012						
N014:150/013						
N014:150/014	HS-3182A1	OCS OPEN	VALVE	SOV-3182A		Y-71.1
N014:150/015	HS-3182A2	OCS CLOSE	VALVE	SOV-3182A		Y-71.1
N014:151/000						
N014:151/001						
N014:151/002						
N014:151/003	HS-3182B1	OCS OPEN	VALVE	SOV-3182B		Y-71.1
N014:151/004	HS-3182B2	OCS CLOSE	VALVE	SOV-3182B		Y-71.1
N014:151/005	HS-3183A1	OCS OPEN	VALVE	SOV-3183A		Y-71.1
N014:151/006	HS-3183A2	OCS CLOSE	VALVE	SOV-3183A		Y-71.1
N014:151/007	HS-3183B1	OCS OPEN	VALVE	SOV-3183B		Y-71.1
N014:151/008	HS-3183B2	OCS CLOSE	VALVE	SOV-3183B		Y-71.1
N014:151/009	HS-3184-1	OCS OPEN	VALVE	SOV-3184		Y-71.1
N014:151/010	HS-3184-2	OCS CLOSE	VALVE	SOV-3184		Y-71.1
N014:151/011						
N014:151/012						
N014:151/013						
N014:151/014						
N014:151/015						
N014:152						
N014:153						
N014:154						
N014:155						
N014:156/000	HS-3125A1	START	BOOSTER	PUMP	P-3125A	Y-74.1
N014:156/001	HS-3125A2	STOP	BOOSTER	PUMP	P-3125A	Y-74.1
N014:156/002	HS-3125B1	START	BOOSTER	PUMP	P-3125B	Y-74.2
N014:156/003	HS-3125B2	STOP	BOOSTER	PUMP	P-3125B	Y-74.2
N014:156/004	HS-3125-M	PID FOR PUMP	P-3125 A/B	MANUAL MODE		
N014:156/005	HS-3125A2	RESET	VALVES FOR	PUMP P-3125A		Y-79.1
N014:156/006	HS-3125AA1	OPEN	VALVE	MOV-3125AA		Y-79.1
N014:156/007	HS-3125AA2	CLOSE	VALVE	MOV-3125AA		Y-79.1
N014:156/008	HS-3125AB1	OPEN	VALVE	MOV-3125AB		Y-79.1
N014:156/009	HS-3125AB2	CLOSE	VALVE	MOV-3125AB		Y-79.1
N014:156/010	HS-3125AC1	OPEN	VALVE	MOV-3125AC		Y-79.1
N014:156/011	HS-3125AC2	CLOSE	VALVE	MOV-3125AC		Y-79.1
N014:156/012	HS-3125AD1	OPEN	VALVE	MOV-3125AD		Y-79.1
N014:156/013	HS-3125AD2	CLOSE	VALVE	MOV-3125AD		Y-79.1
N014:156/014	HS-3125AE1	OPEN	VALVE	MOV-3125AE		Y-79.1
N014:156/015	HS-3125AE2	CLOSE	VALVE	MOV-3125AE		Y-79.1
N014:157/000	HS-3125AF1	OPEN	VALVE	MOV-3125AF		Y-79.1
N014:157/001	HS-3125AF2	CLOSE	VALVE	MOV-3125AF		Y-79.1
N014:157/002	HS-3125AG1	OPEN	VALVE	MOV-3125AG		Y-79.1
N014:157/003	HS-3125AG2	CLOSE	VALVE	MOV-3125AG		Y-79.1
N014:157/004	HS-3125AH1	OPEN	VALVE	MOV-3125AH		Y-79.1
N014:157/005	HS-3125AH2	CLOSE	VALVE	MOV-3125AH		Y-79.1
N014:157/006	HS-3125AJ1	OPEN	VALVE	MOV-3125AJ		Y-79.2
N014:157/007	HS-3125AJ2	CLOSE	VALVE	MOV-3125AJ		Y-79.2
N014:157/008	HS-3125AK1	OPEN	VALVE	MOV-3125AK		Y-79.2
N014:157/009	HS-3125AK2	CLOSE	VALVE	MOV-3125AK		Y-79.2
N014:157/010	HS-3163-1	OPEN	VALVE	MOV-3163		Y-79.2
N014:157/011	HS-3163-2	CLOSE	VALVE	MOV-3163		Y-79.2
N014:157/012	HS-3125B1	INITIATE	DRAINING OF	PUMP P-3125B		Y-80.1
N014:157/013	HS-3125B2	RESET	VALVES FOR	PUMP P-3125B		Y-80.1
N014:157/014						

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00091

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:06 02/19/99

N014:157/015						
N014:158/000						
N014:158/001						
N014:158/002	HS-3125E1	OPEN VALVE	SOV-3125E			Y-83.1
N014:158/003	HS-3125E2	CLOSE VALVE	SOV-3125E			Y-83.1
N014:158/004	HS-3125C1	OPEN VALVE	SOV-3125C			Y-84.1
N014:158/005	HS-3125C2	CLOSE VALVE	SOV-3125C			Y-84.1
N014:158/006	HS-3125G1	OPEN VALVE	SOV-3125G			Y-84.1
N014:158/007	HS-3125G2	CLOSE VALVE	SOV-3125G			Y-84.1
N014:158/008	HS-3125D1	OPEN VALVE	SOV-3125D			Y-84.1
N014:158/009	HS-3125D2	CLOSE VALVE	SOV-3125D			Y-84.1
N014:158/010	HS-3173A1	OPEN VALVE	SOV-3173A			Y-87.1
N014:158/011	HS-3173A2	CLOSE VALVE	SOV-3173A			Y-87.1
N014:158/012	HS-3173B1	OPEN VALVE	SOV-3173B			Y-87.2
N014:158/013	HS-3173B2	CLOSE VALVE	SOV-3173B			Y-87.2
N014:158/014	HS-3156A1	OPEN VALVE	MOV-3156A			Y-89.1
N014:158/015	HS-3156A2	CLOSE VALVE	MOV-3156A			Y-89.1
N014:159/000	HS-3156B1	OPEN VALVE	MOV-3156B			Y-89.2
N014:159/001	HS-3156B2	CLOSE VALVE	MOV-3156B			Y-89.2
N014:159/002						
N014:159/003						
N014:159/004						
N014:159/005						
N014:159/006	HS-3125BA1	OPEN	VALVE	MOV-3125BA		Y-80.1
N014:159/007	HS-3125BA2	CLOSE	VALVE	MOV-3125BA		Y-80.1
N014:159/008	HS-3125BB1	OPEN	VALVE	MOV-3125BB		Y-80.1
N014:159/009	HS-3125BB2	CLOSE	VALVE	MOV-3125BB		Y-80.1
N014:159/010	HS-3125BC1	OPEN	VALVE	MOV-3125BC		Y-80.1
N014:159/011	HS-3125BC2	CLOSE	VALVE	MOV-3125BC		Y-80.1
N014:159/012	HS-3125BD1	OPEN	VALVE	MOV-3125BD		Y-80.1
N014:159/013	HS-3125BD2	CLOSE	VALVE	MOV-3125BD		Y-80.1
N014:159/014	HS-3125BE1	OPEN	VALVE	MOV-3125BE		Y-80.1
N014:159/015	HS-3125BE2	CLOSE	VALVE	MOV-3125BE		Y-80.1
N014:160/000	HS-3125BF1	OPEN	VALVE	MOV-3125BF		Y-80.1
N014:160/001	HS-3125BF2	CLOSE	VALVE	MOV-3125BF		Y-80.1
N014:160/002	HS-3125BG1	OPEN	VALVE	MOV-3125BG		Y-80.1
N014:160/003	HS-3125BG2	CLOSE	VALVE	MOV-3125BG		Y-80.1
N014:160/004	HS-3125BH1	OPEN	VALVE	MOV-3125BH		Y-80.1
N014:160/005	HS-3125BH2	CLOSE	VALVE	MOV-3125BH		Y-80.1
N014:160/006	HS-3125BJ1	OPEN	VALVE	MOV-3125BJ		Y-80.2
N014:160/007	HS-3125BJ2	CLOSE	VALVE	MOV-3125BJ		Y-80.2
N014:160/008	HS-3125BK1	OPEN	VALVE	MOV-3125BK		Y-80.2
N014:160/009	HS-3125BK2	CLOSE	VALVE	MOV-3125BK		Y-80.2
N014:160/010						
N014:160/011						
N014:160/012						
N014:160/013						
N014:160/014						
N014:160/015						
N014:161						
N014:162	PID-3125-FR	PUMP	P-3125 A/B	OUTLET FLOW	REFERENCE	FROM OIT
N014:163	PID-3125-KP	PUMP	P-3125 A/B	PID CONTROL	PROP. GAIN	FROM OIT
N014:164	PID-3125-KI	PUMP	P-3125 A/B	PID CONTROL	INTEG. GAIN	FROM OIT
N014:165	PID-3125-KD	PUMP	P-3125 A/B	PID CONTROL	DERIV. GAIN	FROM OIT
N014:166						
N014:167						
N014:170						
N014:170/000	HB_OCS_PLG3	HEARTBEAT	FROM OCS	TO PLC-3		
N014:170/001						
N014:170/002						
N014:170/003						
N014:170/004						
N014:170/005						
N014:170/006	HS-3185A1	OCS OPEN	VALVE	SOL-3185A		Y81-1
N014:170/007	HS-3185A2	OCS CLOSE	VALVE	SOL-3185A		Y81-1
N014:170/008	HS-3185B1	OCS OPEN	VALVE	SOL-3185B		Y81-2
N014:170/009	HS-3185B2	OCS CLOSE	VALVE	SOL-3185B		Y81-2
N014:170/010	HS-3168A1	OCS OPEN	VALVE	SOL-3168A		Y81-3
N014:170/011	HS-3168A2	OCS CLOSE	VALVE	SOL-3168A		Y81-3
N014:170/012	HS-3168B1	OCS OPEN	VALVE	SOL-3168B		Y81-4
N014:170/013	HS-3168B2	OCS CLOSE	VALVE	SOL-3168B		Y81-4
N014:170/014	HS-3165A1	OCS OPEN	VALVE	SOV-3165A		Y71
N014:170/015	HS-3165A2	OCS CLOSE	VALVE	SOV-3165A		Y71
N014:171						
N014:171/000						
N014:171/001	HS-1010A	LEAK DETECTION	OVERRIDE	Y-72.1		
N014:171/002	HS-1010B	LEAK DETECTION	OVERRIDE RESET	Y-72.1		

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00092

DB Form Report Sorted By: Address

08:16:07 02/19/99

N014:171/003	HS-3166A1	OCS OPEN	VALVE	SOV-3166A	Y71
N014:171/004	HS-3166A2	OCS CLOSE	VALVE	SOV-3166A	Y71
N014:171/005	HS-3165B1	OCS OPEN	VALVE	SOV-3165B	Y71
N014:171/006	HS-3165B2	OCS CLOSE	VALVE	SOV-3165B	Y71
N014:171/007	HS-3166B1	OCS OPEN	VALVE	SOV-3166B	Y71
N014:171/008	HS-3166B2	OCS CLOSE	VALVE	SOV-3166B	Y71
N014:171/009	HS-3167A1	OCS OPEN	VALVE	SOV-3167A	Y88-1
N014:171/010	HS-3167A2	OCS CLOSE	VALVE	SOV-3167A	Y88-1
N014:171/011	HS-3167B1	OCS OPEN	VALVE	SOV-3167B	Y87-2
N014:171/012	HS-3167B2	OCS CLOSE	VALVE	SOV-3167B	Y87-2
N014:171/013					
N014:171/014					
N014:171/015					
N014:172					
N014:172/000	HS-1000A	OCS INITIATE	TRANSFER		Y-70.1
N014:172/001	HS-1000B	OCS RESET	TRANSFER		Y-70.1
N014:172/002	HS-1001	OCS SELECT	TRANSFER	TYPE 1	Y-70.1
N014:172/003	HS-1002A	OCS SELECT	TRANSFER	TYPE 2A	Y-70.1
N014:172/004	HS-1002B	OCS SELECT	TRANSFER	TYPE 2B	Y-70.1
N014:172/005	HS-1003	OCS SELECT	TRANSFER	TYPE 3	Y-70.1
N014:172/006					
N014:172/007					
N014:172/008					
N014:172/009					
N014:172/010					
N014:172/011					
N014:172/012					
N014:172/013					
N014:172/014					
N014:172/015					
N014:173					
N014:174					
N014:190					
N014:190/000	HB_OCS_PLC4	HEARTBEAT	FROM OCS	TO PLC-4	
N014:190/001					
N014:190/002					
N014:190/003					
N014:190/004	HS-058E	OVERRIDE OF	200-E MASTER	SHUTDOWN	Y-77.1
N014:190/005					
N014:190/006	HS-843-1	OCS MOVE	VALVE MOV-843	TO POSITION 1	Y71
N014:190/007	HS-843-2	OCS MOVE	VALVE MOV-843	TO POSITION 2	Y71
N014:190/008	HS-843-3	OCS MOVE	VALVE MOV-843	TO POSITION 3	Y71
N014:190/009	HS-846-1	OCS OPEN	VALVE MOV-846	MOV-846	Y71
N014:190/010	HS-846-2	OCS CLOSE	VALVE MOV-846	MOV-846	Y71
N014:190/011	HS-844-1	OCS MOVE	VALVE MOV-844	TO POSITION 1	Y71
N014:190/012	HS-844-2	OCS MOVE	VALVE MOV-844	TO POSITION 2	Y71
N014:190/013	HS-844-3	OCS MOVE	VALVE MOV-844	TO POSITION 3	Y71
N014:190/014	HS-845-1	OCS OPEN	VALVE MOV-845	MOV-845	Y71
N014:190/015	HS-845-2	OCS CLOSE	VALVE MOV-845	MOV-845	Y71
N014:191					
N014:192					
N014:193					
N014:194					
N014:200					
N014:200/000	HB_OCS_PLC5	HEARTBEAT	FROM OCS	TO PLC-5	
N014:200/001					
N014:200/002					
N014:200/003					
N014:200/004					
N014:200/005					
N014:200/006					
N014:200/007					
N014:200/008					
N014:200/009					
N014:200/010					
N014:200/011					
N014:200/012					
N014:200/013					
N014:200/014					
N014:200/015					
N014:240					
N014:240/000	HB PLC2_OCS	HEARTBEAT	FROM PLC-2	TO OCS	
N014:240/001	COM-21	COMMON WITH	PCU-1	IGNORED	
N014:240/002	COM-2_OCS	COMMON WITH	OCS	IGNORED	
N014:240/003	COM-23	COMMON WITH	PCU-3	IGNORED	
N014:240/004	COM-24	COMMON WITH	PCU-4	IGNORED	
N014:240/005	COM-25	COMMON WITH	PCU-5	IGNORED	

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page.00093

DB Form Report

Sorted By: Address

08:16:07 02/19/99

N014: 240/006	BATT_BAD_PLC2	PLC-2 BATTERY	IS BAD OR	MISSING		
N014: 240/007						
N014: 240/008						
N014: 240/009						
N014: 240/010	PAH-3173	VALVE	SOV-3173A/B	FAILURE		Y-73.1
N014: 240/011	PAH-3182	VALVE	SOV-3182A/B	FAILURE		
N014: 240/012	PAH-3183	VALVE	SOV-3183A/B	FAILURE		
N014: 240/013	LDA-3150	LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
N014: 240/014	XA-3125A	BOOSTER	PUMP	P-3125A	FAILURE	Y-74.1
N014: 240/015	XA-3125B	BOOSTER	PUMP	P-3125B	FAILURE	Y-74.2
N014: 241/000						
N014: 241/001						
N014: 241/002						
N014: 241/003						
N014: 241/004	ZA-3182A2	VALVE	FAILED	TO CLOSE		Y-71.1
N014: 241/005						
N014: 241/006	ZA-3182A1	VALVE	FAILED	TO OPEN		Y-71.1
N014: 241/007						
N014: 241/008	ZA-3182A	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014: 241/009						
N014: 241/010						
N014: 241/011						
N014: 241/012	ZA-3182B2	VALVE	FAILED	TO CLOSE		Y-71.1
N014: 241/013						
N014: 241/014	ZA-3182B1	VALVE	FAILED	TO OPEN		Y-71.1
N014: 241/015						
N014: 242/000	ZA-3182B	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014: 242/001	ZA-3183A2	VALVE	FAILED	TO CLOSE		Y-71.1
N014: 242/002						
N014: 242/003	ZA-3183A1	VALVE	FAILED	TO OPEN		Y-71.1
N014: 242/004						
N014: 242/005	ZA-3183A	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014: 242/006	ZA-3183B2	VALVE	FAILED	TO CLOSE		Y-71.1
N014: 242/007						
N014: 242/008	ZA-3183B1	VALVE	FAILED	TO OPEN		Y-71.1
N014: 242/009						
N014: 242/010	ZA-3183B	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014: 242/011						
N014: 242/012						
N014: 242/013						
N014: 242/014	ZA-3184-2	VALVE	FAILED	TO CLOSE		Y-71.1
N014: 242/015						
N014: 243/000	ZA-3184-1	VALVE	FAILED	TO OPEN		Y-71.1
N014: 243/001						
N014: 243/002	ZA-3184	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014: 243/003						
N014: 243/004						
N014: 243/005						
N014: 243/006						
N014: 243/007						
N014: 243/008						
N014: 243/009						
N014: 243/010						
N014: 243/011						
N014: 243/012						
N014: 243/013						
N014: 243/014						
N014: 243/015						
N014: 244						
N014: 245						
N014: 246/000	TAH-3125A1	PUMP P-3125A	INBOARD	BEARING	HIGH TEMP.	Y-76.1
N014: 246/001	TAH-3125A2	PUMP P-3125A	OUTBOARD	BEARING	HIGH TEMP.	Y-76.1
N014: 246/002	PAH-3125C	BOOSTER	PUMP HIGH	DISCHARGE	PRESSURE	Y-78.1
N014: 246/003						
N014: 246/004						
N014: 246/005						
N014: 246/006	VAH-3125A1	PUMP P-3125A	HIGH MOTOR	VIBRATION		Y-76.1
N014: 246/007	VAH-3125A2	PUMP P-3125A	HIGH MOTOR	VIBRATION		Y-76.1
N014: 246/008						
N014: 246/009						
N014: 246/010						
N014: 246/011						
N014: 246/012						
N014: 246/013						
N014: 246/014						
N014: 246/015						
N014: 247/000	TAH-3125B1	PUMP P-3125B	INBOARD	BEARING	HIGH TEMP.	Y-76.1

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00094

DB Form Report

Sorted By: Address

08:16:08 02/19/99

N014: 247/001	TAH-3125B2	PUMP P-3125B	OUTBOARD	BEARING	HIGH TEMP	Y-76.1
N014: 247/002	PAH-3125D	BOOSTER	PUMP HIGH	DISCHARGE	PRESSURE	Y-78.1
N014: 247/003						
N014: 247/004						
N014: 247/005						
N014: 247/006	VAH-3125B1	PUMP P-3125B	HIGH MOTOR	VIBRATION		Y-76.1
N014: 247/007	VAH-3125B2	PUMP P-3125B	HIGH MOTOR	VIBRATION		Y-76.1
N014: 247/008						
N014: 247/009						
N014: 247/010						
N014: 247/011						
N014: 247/012						
N014: 247/013						
N014: 247/014						
N014: 247/015						
N014: 248/000	ZA-3125E2	VALVE	SOV-3125E	FAILED TO	CLOSE	Y-83.1
N014: 248/001	ZA-3125E1	VALVE	SOV-3125E	FAILED TO	OPEN	Y-83.1
N014: 248/002	ZA-3125E	VALVE	SOV-3125E	POSITION	SWITCH FAILURE	Y-83.1
N014: 248/003						
N014: 248/004						
N014: 248/005	ZA-3125C2	VALVE	SOV-3125C	FAILED TO	CLOSE	Y-84.1
N014: 248/006	ZA-3125C1	VALVE	SOV-3125C	FAILED TO	OPEN	Y-84.1
N014: 248/007	ZA-3125C	VALVE	SOV-3125C	POSITION	SWITCH FAILURE	Y-84.1
N014: 248/008	ZA-3125G2	VALVE	SOV-3125G	FAILED TO	CLOSE	Y-85.1
N014: 248/009	ZA-3125G1	VALVE	SOV-3125G	FAILED TO	OPEN	Y-85.1
N014: 248/010	ZA-3125G	VALVE	SOV-3125G	POSITION	SWITCH FAILURE	Y-85.1
N014: 248/011						
N014: 248/012						
N014: 248/013						
N014: 248/014						
N014: 248/015	ZA-3125D2	VALVE	SOV-3125D	FAILED TO	CLOSE	Y-86.1
N014: 249/000	ZA-3125D1	VALVE	SOV-3125D	FAILED TO	OPEN	Y-86.1
N014: 249/001	ZA-3125D	VALVE	SOV-3125D	POSITION	SWITCH FAILURE	Y-86.1
N014: 249/002	ZA-3173A2	VALVE	SOV-3173A	FAILED TO	CLOSE	Y-87.1
N014: 249/003	ZA-3173A1	VALVE	SOV-3173A	FAILED TO	OPEN	Y-87.1
N014: 249/004	ZA-3173A	VALVE	SOV-3173A	POSITION	SWITCH FAILURE	Y-87.1
N014: 249/005						
N014: 249/006						
N014: 249/007						
N014: 249/008						
N014: 249/009	ZA-3173B2	VALVE	SOV-3173B	FAILED TO	CLOSE	Y-87.2
N014: 249/010	ZA-3173B1	VALVE	SOV-3173B	FAILED TO	OPEN	Y-87.2
N014: 249/011	ZA-3173B	VALVE	SOV-3173B	POSITION	SWITCH FAILURE	Y-87.2
N014: 249/012	ZA-3156A2	VALVE	MOV-3156A	FAILED TO	CLOSE	Y-89.1
N014: 249/013	ZA-3156A1	VALVE	MOV-3156A	FAILED TO	OPEN	Y-89.1
N014: 249/014	ZA-3156A	VALVE	MOV-3156A	POSITION	SWITCH FAILURE	Y-89.1
N014: 250/000						
N014: 250/001						
N014: 250/002						
N014: 250/003	ZA-3156B2	VALVE	MOV-3156B	FAILED TO	CLOSE	Y-89.2
N014: 250/004	ZA-3156B1	VALVE	MOV-3156B	FAILED TO	OPEN	Y-89.2
N014: 250/005	ZA-3156B	VALVE	MOV-3156B	POSITION	SWITCH FAILURE	Y-89.2
N014: 250/006						
N014: 250/007						
N014: 250/008						
N014: 250/009						
N014: 250/010						
N014: 250/011						
N014: 250/012						
N014: 250/013						
N014: 250/014						
N014: 250/015						
N014: 251						
N014: 251/000	TI-3125B1 A	PCU-2 INPUT	OVER AND UNDER	RANGE STATUS	BITS TO 011	
N014: 251/001	TI-3125B2 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 251/002	TI-3125A1 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 251/003	TI-3125A2 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 251/004	PCU2-SP-R1-5 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 251/005	PCU2-SP-R1-6 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 251/006	PCU2-SP-R1-7 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 251/007	PCU2-SP-R1-8 A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014: 252/008	TI-3125A A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014: 252/009	PCU2-SP-T1-2 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014: 252/010	TI-3125B A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014: 252/011	PCU2-SP-T1-4 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014: 252/012	PCU2-SP-T1-5 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00095

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:08 02/19/99

N014:252/013	PCU2-SP-TI-6 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/014	PCU2-SP-TI-7 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/015	PCU2-SP-TI-8 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:253/000	FIC-3125A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/001	PI-3125A A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/002	PI-3125B A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/003	PI-3125C A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/004	PI-3125D A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/005	PI-3125E A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/006	SI-3125A A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/007	SI-3125B A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/008	VI-3125AT A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/009	VI-3125B1 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/010	VI-3125A2 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/011	VI-3125B2 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/012	PI-3173 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/013	PI-3182 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/014	PI-3183 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/015	PCU2-SP-AI-8 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:255						
N014:256		DIGITAL INPUT	REGISTER TO	01T TERMINALS		
N014:256/000	ZLH-3125BA	MOV-3125BA	IS OPEN			Y80-1
N014:256/001	ZLL-3125BA	MOV-3125BA	IS CLOSED			Y81-1
N014:256/002	ZLH-3125BB	MOV-3125BB	IS OPEN			Y80-1
N014:256/003	ZLL-3125BB	MOV-3125BB	IS CLOSED			Y81-1
N014:256/004	ZLH-3125BC	MOV-3125BC	IS OPEN			Y80-1
N014:256/005	ZLL-3125BC	MOV-3125BC	IS CLOSED			Y81-1
N014:256/006	ZLH-3125BD	MOV-3125BD	IS OPEN			Y80-1
N014:256/007	ZLL-3125BD	MOV-3125BD	IS CLOSED			Y81-1
N014:256/008	ZLH-3125BE	MOV-3125BE	IS OPEN			Y80-1
N014:256/009	ZLL-3125BE	MOV-3125BE	IS CLOSED			Y81-1
N014:256/010	ZLH-3125BF	MOV-3125BF	IS OPEN			Y80-1
N014:256/011	ZLL-3125BF	MOV-3125BF	IS CLOSED			Y81-1
N014:256/012	ZLH-3125BG	MOV-3125BG	IS OPEN			Y80-1
N014:256/013	ZLL-3125BG	MOV-3125BG	IS CLOSED			Y81-1
N014:256/014	ZLH-3125BH	MOV-3125BH	IS OPEN			Y80-1
N014:256/015	ZLL-3125BH	MOV-3125BH	IS CLOSED			Y81-1
N014:257/000	ZLH-3125BJ	MOV-3125BJ	IS OPEN			Y81-2
N014:257/001	ZLL-3125BJ	MOV-3125BJ	IS CLOSED			Y81-2
N014:257/002	ZLH-3125BK	MOV-3125BK	IS OPEN			Y81-2
N014:257/003	ZLL-3125BK	MOV-3125BK	IS CLOSED			Y81-2
N014:257/004	PCU2-SP-121-04	SPARE	DIGITAL	INPUT		
N014:257/005	PCU2-SP-121-05	SPARE	DIGITAL	INPUT		
N014:257/006	PCU2-SP-121-06	SPARE	DIGITAL	INPUT		
N014:257/007	PCU2-SP-121-07	SPARE	DIGITAL	INPUT		
N014:257/008	PCU2-SP-121-10	SPARE	DIGITAL	INPUT		
N014:257/009	PCU2-SP-121-11	SPARE	DIGITAL	INPUT		
N014:257/010	PCU2-SP-121-12	SPARE	DIGITAL	INPUT		
N014:257/011	PCU2-SP-121-13	SPARE	DIGITAL	INPUT		
N014:257/012	PCU2-SP-121-14	SPARE	DIGITAL	INPUT		
N014:257/013	PCU2-SP-121-15	SPARE	DIGITAL	INPUT		
N014:257/014	PCU2-SP-121-16	SPARE	DIGITAL	INPUT		
N014:257/015	PCU2-SP-121-17	SPARE	DIGITAL	INPUT		
N014:258/000	ZLH-3125AA	MOV-3125AA	IS OPEN			Y79-1
N014:258/001	ZLL-3125AA	MOV-3125AA	IS CLOSED			Y80-1
N014:258/002	ZLH-3125AB	MOV-3125AB	IS OPEN			Y79-1
N014:258/003	ZLL-3125AB	MOV-3125AB	IS CLOSED			Y80-1
N014:258/004	ZLH-3125AC	MOV-3125AC	IS OPEN			Y79-1
N014:258/005	ZLL-3125AC	MOV-3125AC	IS CLOSED			Y80-1
N014:258/006	ZLH-3125AD	MOV-3125AD	IS OPEN			Y79-1
N014:258/007	ZLL-3125AD	MOV-3125AD	IS CLOSED			Y80-1
N014:258/008	ZLH-3125AE	MOV-3125AE	IS OPEN			Y79-1
N014:258/009	ZLL-3125AE	MOV-3125AE	IS CLOSED			Y80-1
N014:258/010	ZLH-3125AF	MOV-3125AF	IS OPEN			Y79-1
N014:258/011	ZLL-3125AF	MOV-3125AF	IS CLOSED			Y80-1
N014:258/012	ZLH-3125AG	MOV-3125AG	IS OPEN			Y79-1
N014:258/013	ZLL-3125AG	MOV-3125AG	IS CLOSED			Y80-1
N014:258/014	ZLH-3125AH	MOV-3125AH	IS OPEN			Y79-1
N014:258/015	ZLL-3125AH	MOV-3125AH	IS CLOSED			Y80-1
N014:259/000	ZLH-3125AJ	MOV-3125AJ	IS OPEN			Y79-2
N014:259/001	ZLL-3125AJ	MOV-3125AJ	IS CLOSED			Y80-2
N014:259/002	ZLH-3125AK	MOV-3125AK	IS OPEN			Y79-2
N014:259/003	ZLL-3125AK	MOV-3125AK	IS CLOSED			Y80-2
N014:259/004	YA-3101A	ENCASEMENT	RUPTURE DISK	ACTIVATED		01T
N014:259/005	YA-3101B	ENCASEMENT	RUPTURE DISK	ACTIVATED		01T
N014:259/006	YA-3101C	ENCASEMENT	RUPTURE DISK	ACTIVATED		01T
N014:259/007	YA-3101D	ENCASEMENT	RUPTURE DISK	ACTIVATED		01T

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00096

DB Form Report

Sorted By: Address

08:16:09 02/19/99

N014: 259/008	YA-3101E	ENCASEMENT	RUPTURE DISK	ACTIVATED			01T
N014: 259/009	YA-3101F	ENCASEMENT	RUPTURE DISK	ACTIVATED			01T
N014: 259/010	YA-3101G	ENCASEMENT	RUPTURE DISK	ACTIVATED			01T
N014: 259/011	YA-3101H	ENCASEMENT	RUPTURE DISK	ACTIVATED			01T
N014: 259/012	PCU2-SP-123-14	SPARE	DIGITAL	INPUT			
N014: 259/013	PCU2-SP-123-15	SPARE	DIGITAL	INPUT			
N014: 259/014	PCU2-SP-123-16	SPARE	DIGITAL	INPUT			
N014: 259/015	PCU2-SP-123-17	SPARE	DIGITAL	INPUT			
N014: 260/000	ZLH-3125C	SOV-3125C	IS OPEN				Y84-1
N014: 260/001	ZLL-3125C	SOV-3125C	IS CLOSED				Y84-1
N014: 260/002	ZLH-3125D	SOV-3125D	IS OPEN				Y86-1
N014: 260/003	ZLL-3125D	SOV-3125D	IS CLOSED				Y86-1
N014: 260/004	ZLH-3125E	SOV-3125E	IS OPEN				Y83-1
N014: 260/005	ZLL-3125E	SOV-3125E	IS CLOSED				Y83-1
N014: 260/006	ZLH-3125G	SOV-3125G	IS OPEN				Y85-1
N014: 260/007	ZLL-3125G	SOV-3125G	IS CLOSED				Y85-1
N014: 260/008	ZLH-3173B	SOV-3173B	IS OPEN				Y87-2
N014: 260/009	ZLL-3173B	SOV-3173B	IS CLOSED				Y87-2
N014: 260/010	ZLH-3156B	MOV-3156B	IS OPEN				Y89-2
N014: 260/011	ZLL-3156B	MOV-3156B	IS CLOSED				Y89-2
N014: 260/012	ZLH-3163	SOV-3163	IS OPEN				
N014: 260/013	ZLL-3163	SOV-3163	IS CLOSED				
N014: 260/014	ZLH-3173A	SOV-3173A	IS OPEN				Y87-1
N014: 260/015	ZLL-3173A	SOV-3173A	IS CLOSED				Y87-1
N014: 261/000	ZLH-3182A	SOV-3182A	IS OPEN				Y71
N014: 261/001	ZLL-3182A	SOV-3182A	IS CLOSED				Y71
N014: 261/002	ZLH-3182B	SOV-3182B	IS OPEN				Y71
N014: 261/003	ZLL-3182B	SOV-3182B	IS CLOSED				Y71
N014: 261/004	ZLH-3183A	SOV-3183A	IS OPEN				Y71
N014: 261/005	ZLL-3183A	SOV-3183A	IS CLOSED				Y71
N014: 261/006	ZLH-3183B	SOV-3183B	IS OPEN				Y71
N014: 261/007	ZLL-3183B	SOV-3183B	IS CLOSED				Y71
N014: 261/008	ZLH-3184	SOV-3184	IS OPEN				Y71
N014: 261/009	ZLL-3184	SOV-3184	IS CLOSED				Y71
N014: 261/010	ZLH-3156A	MOV-3156A	IS OPEN				Y89-1
N014: 261/011	ZLL-3156A	MOV-3156A	IS CLOSED				Y89-1
N014: 261/012	YL-3125A3	LOCAL/REMOTE	STATUS FOR	P-3125A			01T
N014: 261/013	YL-3125B3	LOCAL/REMOTE	STATUS FOR	P-3125B			01T
N014: 261/014	TAH-3125A	PUMP P-3125A	MOTOR WINDING	TEMPERATURE	HIGH		Y76
N014: 261/015	TAH-3125B	PUMP P-3125B	MOTOR WINDING	TEMPERATURE	HIGH		Y76
N014: 262/000	FAH-3125A1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A			Y76
N014: 262/001	FAH-3125A2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A			Y76
N014: 262/002	FAH-3125B1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B			Y76
N014: 262/003	FAH-3125B2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B			Y76
N014: 262/004	LAL-3125A1	PUMP P-3125A	LOW OIL LEVEL				Y76
N014: 262/005	LAL-3125A2	PUMP P-3125A	LOW OIL LEVEL				Y76
N014: 262/006	LAL-3125B1	PUMP P-3125B	LOW OIL LEVEL				Y76
N014: 262/007	LAL-3125B2	PUMP P-3125B	LOW OIL LEVEL				Y76
N014: 262/008	LDA-3150	SUMP LEAK	DETECTOR	FAILURE			Y72
N014: 262/009	LDA-3160	6241-A	ENCASEMENT	LEAK DETECTION			Y72
N014: 262/010	LDAH-3150	6241-A SUMP	LEAK DETECTION				Y72
N014: 262/011	PAL-3125A2	PUMP P-3125A	SEAL FAILURE				Y76
N014: 262/012	PAL-3125B1	PUMP P-3125B	SEAL FAILURE				Y76
N014: 262/013	PAL-3125B2	PUMP P-3125B	SEAL FAILURE				Y76
N014: 262/014	PAL-3100A	LOW	COMPRESSOR	SA-CWP-3101A	PRESSURE		Y76
N014: 262/015	PAL-3125A1	PUMP P-3125A	SEAL FAILURE				Y76
N014: 263							
N014: 264							
N014: 265							
N014: 265/000	MOV-3125BA1	DIGITAL OUTPUT	REGISTER TO	01T TERMINALS			Y80-1
N014: 265/001	MOV-3125BA2	CLOSE VALVE	MOV-3125BA				Y80-1
N014: 265/002	MOV-3125BB1	OPEN VALVE	MOV-3125BB				Y80-1
N014: 265/003	MOV-3125BB2	CLOSE VALVE	MOV-3125BB				Y80-1
N014: 265/004	MOV-3125BC1	OPEN VALVE	MOV-3125BC				Y80-1
N014: 265/005	MOV-3125BC2	CLOSE VALVE	MOV-3125BC				Y80-1
N014: 265/006	MOV-3125BD1	OPEN VALVE	MOV-3125BD				Y80-1
N014: 265/007	MOV-3125BD2	CLOSE VALVE	MOV-3125BD				Y80-1
N014: 265/008	MOV-3125BE1	OPEN VALVE	MOV-3125BE				Y80-1
N014: 265/009	MOV-3125BE2	CLOSE VALVE	MOV-3125BE				Y80-1
N014: 265/010	MOV-3125BF1	OPEN VALVE	MOV-3125BF				Y80-1
N014: 265/011	MOV-3125BF2	CLOSE VALVE	MOV-3125BF				Y80-1
N014: 265/012	MOV-3125BG1	OPEN VALVE	MOV-3125BG				Y80-1
N014: 265/013	MOV-3125BG2	CLOSE VALVE	MOV-3125BG				Y80-1
N014: 265/014	MOV-3125BH1	OPEN VALVE	MOV-3125BH				Y80-1
N014: 265/015	MOV-3125BH2	CLOSE VALVE	MOV-3125BH				Y80-1
N014: 266/000	MOV-3125AA1	OPEN VALVE	MOV-3125AA				Y79-1
N014: 266/001	MOV-3125AA2	CLOSE VALVE	MOV-3125AA				Y79-1

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00097

DB Form Report

Sorted By: Address

08:16:09 02/19/99

N014:266/002	MOV-3125AB1	OPEN VALVE	MOV-3125AB			Y79-1
N014:266/003	MOV-3125AB2	CLOSE VALVE	MOV-3125AB			Y79-1
N014:266/004	MOV-3125AC1	OPEN VALVE	MOV-3125AC			Y79-1
N014:266/005	MOV-3125AC2	CLOSE VALVE	MOV-3125AC			Y79-1
N014:266/006	MOV-3125AD1	OPEN VALVE	MOV-3125AD			Y79-1
N014:266/007	MOV-3125AD2	CLOSE VALVE	MOV-3125AD			Y79-1
N014:266/008	MOV-3125AE1	OPEN VALVE	MOV-3125AE			Y79-1
N014:266/009	MOV-3125AE2	CLOSE VALVE	MOV-3125AE			Y79-1
N014:266/010	MOV-3125AF1	OPEN VALVE	MOV-3125AF			Y79-1
N014:266/011	MOV-3125AF2	CLOSE VALVE	MOV-3125AF			Y79-1
N014:266/012	MOV-3125AG1	OPEN VALVE	MOV-3125AG			Y79-1
N014:266/013	MOV-3125AG2	CLOSE VALVE	MOV-3125AG			Y79-1
N014:266/014	MOV-3125AH1	OPEN VALVE	MOV-3125AH			Y79-1
N014:266/015	MOV-3125AH2	CLOSE VALVE	MOV-3125AH			Y79-1
N014:267/000	MOV-3125AJ1	OPEN VALVE	MOV-3125AJ			Y79-2
N014:267/001	MOV-3125AJ2	CLOSE VALVE	MOV-3125AJ			Y79-2
N014:267/002	MOV-3125AK1	OPEN VALVE	MOV-3125AK			Y79-2
N014:267/003	MOV-3125AK2	CLOSE VALVE	MOV-3125AK			Y79-2
N014:267/004	MOV-3125BJ1	OPEN VALVE	MOV-3125BJ			Y80-2
N014:267/005	MOV-3125BJ2	CLOSE VALVE	MOV-3125BJ			Y80-2
N014:267/006	MOV-3125BK1	OPEN VALVE	MOV-3125BK			Y80-2
N014:267/007	MOV-3125BK2	CLOSE VALVE	MOV-3125BK			Y80-2
N014:267/008	P-3125A1	START PUMP	P-3125A			Y74-1
N014:267/009	P-3125A2	STOP PUMP	P-3125A			Y74-1
N014:267/010	P-3125B1	START PUMP	P-3125B			Y74-2
N014:267/011	P-3125B2	STOP PUMP	P-3125B			Y74-2
N014:267/012	P-3115	SHUTDOWN	SUMP PUMP	P-3115		Y-82.1
N014:267/013	PCU2-SP-035-15	SPARE	DIGITAL	OUTPUT		
N014:267/014	PCU2-SP-035-16	SPARE	DIGITAL	OUTPUT		
N014:267/015	PCU2-SP-035-17	SPARE	DIGITAL	OUTPUT		
N014:268/000	SOV-3125C1	OPEN VALVE	SOV-3125C			Y-84
N014:268/001	SOV-3125C2	CLOSE VALVE	SOV-3125C			Y-84
N014:268/002	SOV-3125D1	OPEN VALVE	SOV-3125D			Y-86
N014:268/003	SOV-3125D2	CLOSE VALVE	SOV-3125D			Y-86
N014:268/004	SOV-3125E1	OPEN VALVE	SOV-3125E			Y-83
N014:268/005	SOV-3125E2	CLOSE VALVE	SOV-3125E			Y-83
N014:268/006	SOV-3125G1	OPEN VALVE	SOV-3125G			Y-85
N014:268/007	SOV-3125G2	CLOSE VALVE	SOV-3125G			Y-85
N014:268/008	MOV-3156B1	OPEN VALVE	MOV-3156B			Y89-2
N014:268/009	MOV-3156B2	CLOSE VALVE	MOV-3156B			Y89-2
N014:268/010	MOV-3156A1	OPEN VALVE	MOV-3156A			Y89-1
N014:268/011	MOV-3156A2	CLOSE VALVE	MOV-3156A			Y89-1
N014:268/012	SOV-3163-1	OPEN VALVE	SOV-3163			Y80-2
N014:268/013	SOV-3163-2	CLOSE VALVE	SOV-3163			Y80-2
N014:268/014	SOV-3173A1	OPEN VALVE	SOV-3173A			Y87-1
N014:268/015	SOV-3173A2	CLOSE VALVE	SOV-3173A			Y87-1
N014:269/000	SOV-3173B1	OPEN VALVE	SOV-3173B			Y87-2
N014:269/001	SOV-3173B2	CLOSE VALVE	SOV-3173B			Y87-2
N014:269/002	SOV-3182A1	OPEN VALVE	SOV-3182A			Y71
N014:269/003	SOV-3182A2	CLOSE VALVE	SOV-3182A			Y71
N014:269/004	SOV-3182B1	OPEN VALVE	SOV-3182B			Y71
N014:269/005	SOV-3182B2	CLOSE VALVE	SOV-3182B			Y71
N014:269/006	SOV-3183A1	OPEN VALVE	SOV-3183A			Y71
N014:269/007	SOV-3183A2	CLOSE VALVE	SOV-3183A			Y71
N014:269/008	SOV-3183B1	OPEN VALVE	SOV-3183B			Y71
N014:269/009	SOV-3183B2	CLOSE VALVE	SOV-3183B			Y71
N014:269/010	SOV-3184-1	OPEN VALVE	SOV-3184			Y71
N014:269/011	SOV-3184-2	CLOSE VALVE	SOV-3184			Y71
N014:269/012	PCU2-SP-037-14	SPARE	DIGITAL	OUTPUT		
N014:269/013	PCU2-SP-037-15	SPARE	DIGITAL	OUTPUT		
N014:269/014	PCU2-SP-037-16	SPARE	DIGITAL	OUTPUT		
N014:269/015	PCU2-SP-037-17	SPARE	DIGITAL	OUTPUT		
N014:270	TI-3125B1	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N014:271	TI-3125B2	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N014:272	TI-3125A1	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N014:273	TI-3125A2	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N014:274	PCU2-SP-R1-5	SPARE	R. T. D. TEMP.	INPUT		
N014:275	PCU2-SP-R1-6	SPARE	R. T. D. TEMP.	INPUT		
N014:276	PCU2-SP-R1-7	SPARE	R. T. D. TEMP.	INPUT		
N014:277	PCU2-SP-R1-8	SPARE	R. T. D. TEMP.	INPUT		
N014:278	TI-3125A	PUMP P-3125A/B	OUTLET FLOW	TEMPERATURE	WT-SLL-3160	
N014:279	PCU2-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014:280	TI-3125B	LINE	WT-SNL-3150	TEMPERATURE		
N014:281	PCU2-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014:282	PCU2-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014:283	PCU2-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014:284	PCU2-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00098

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

08:16:10 02/19/99

N014: 285	PCU2-SP-T1-8	SPARE	THERMOCOUPLE	INPUT		
N014: 286	FIC-3125	PUMP	P-3125 A/B	OUTLET FLOW		
N014: 287	PI-3125A	PUMP P-3125A	INLET	PRESSURE		
N014: 288	PI-3125B	PUMP P-3125B	INLET	PRESSURE		
N014: 289	PI-3125C	PUMP P-3125A	OUTLET	PRESSURE		
N014: 290	PI-3125D	PUMP P-3125B	OUTLET	PRESSURE		
N014: 291	PI-3125E	LINE	WT-SNL-3150	PRESSURE		
N014: 292	SI-3125A	MOTOR SPEED	PUMP P-3125A			
N014: 293	SI-3125B	MOTOR SPEED	PUMP P-3125B			
N014: 294	VI-3125A1	PUMP P-3125A	BEARING	VIBRATION		
N014: 295	VI-3125B1	PUMP P-3125B	BEARING	VIBRATION		
N014: 296	VI-3125A2	PUMP P-3125A	BEARING	VIBRATION		
N014: 297	VI-3125B2	PUMP P-3125B	BEARING	VIBRATION		
N014: 298	PI-3173	VALVE	SOV-3173A/B	PRESSURE		
N014: 299	PI-3182	VALVE	SOV-3182A/B	PRESSURE		
N014: 300	PI-3183	VALVE	SOV-3183A/B	PRESSURE		
N014: 301	PCU2-SP-A1-8	SPARE	ANALOG	INPUT		
N014: 302	FIC-3125A	PUMP P-3125A	OUTLET FLOW	CONTROL	SIGNAL	
N014: 303	FIC-3125B	PUMP P-3125B	OUTLET FLOW	CONTROL	SIGNAL	
N014: 304	PCU2-SP-A0-3	SPARE	ANALOG	OUTPUT		
N014: 305	PCU2-SP-A0-4	SPARE	ANALOG	OUTPUT		
N014: 306	FIC-3125-E	PUMP	P-3125 A/B	PID CONTROL	ERROR	
N014: 307	FIC-3125-0	PUMP	P-3125 A/B	OUTLET FLOW /	DRIVE SPEED	REF OUTPUT
N014: 320						
N014: 320/000	HB PLC5_OCS	HEARTBEAT	FROM PLC-5	TO OCS		
N014: 320/001	COM-51	COMMUN. WITH	PCU-1	IGNORED		
N014: 320/002	COM-52	COMMUN. WITH	PCU-2	IGNORED		
N014: 320/003	COM-53	COMMUN. WITH	PCU-3	IGNORED		
N014: 320/004	COM-54	COMMUN. WITH	PCU-4	IGNORED		
N014: 320/005	COM-5_OCS	COMMUN. WITH	OCS	IGNORED		
N014: 320/006						
N014: 320/007	BATT_BAD PLC5	PLC-5 BATTERY	IS BAD OR	MISSING		
N014: 320/008						
N014: 320/009						
N014: 320/010						
N014: 320/011						
N014: 320/012						
N014: 320/013						
N014: 320/014						
N014: 320/015						
N014: 321						
N014: 321/000	LDA-3162	DIGITAL INPUT 244-A	REGISTER TO ENCASEMENT	OIT TERMINALS LEAK DETECTION		Y72
N014: 321/001	PCU5-SP-10-01	SPARE DIGITAL	INPUT			
N014: 321/002	PCU5-SP-10-02	SPARE DIGITAL	INPUT			
N014: 321/003	PCU5-SP-10-03	SPARE DIGITAL	INPUT			
N014: 321/004	PCU5-SP-10-04	SPARE DIGITAL	INPUT			
N014: 321/005	PCU5-SP-10-05	SPARE DIGITAL	INPUT			
N014: 321/006	PCU5-SP-10-06	SPARE DIGITAL	INPUT			
N014: 321/007	PCU5-SP-10-07	SPARE DIGITAL	INPUT			
N014: 321/008	PCU5-SP-10-10	SPARE DIGITAL	INPUT			
N014: 321/009	PCU5-SP-10-11	SPARE DIGITAL	INPUT			
N014: 321/010	PCU5-SP-10-12	SPARE DIGITAL	INPUT			
N014: 321/011	PCU5-SP-10-13	SPARE DIGITAL	INPUT			
N014: 321/012	PCU5-SP-10-14	SPARE DIGITAL	INPUT			
N014: 321/013	PCU5-SP-10-15	SPARE DIGITAL	INPUT			
N014: 321/014	PCU5-SP-10-16	SPARE DIGITAL	INPUT			
N014: 321/015	PCU5-SP-10-17	SPARE DIGITAL	INPUT			
PD016:000		INTEGRATOR	DEMO CONTROL	STRUCTURE		
N019: 001/000						
N019: 001/001						
N019: 001/002	HB-12	HEARTBEAT	FROM PCU-1	TO PCU-2		
N019: 001/003	HB-13	HEARTBEAT	FROM PCU-1	TO PCU-3		
N019: 001/004	HB-14	HEARTBEAT	FROM PCU-1	TO PCU-4		
N019: 001/005	HB-15	HEARTBEAT	FROM PCU-1	TO PCU-5		
N019: 001/006						
N019: 001/007						
N019: 001/008						
N019: 001/009						
N019: 001/010						
N019: 001/011						
N019: 001/012						
N019: 001/013						
N019: 001/014						
N019: 001/015						
N019: 002/000		200-W MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019: 002/001	HB-21	STOP BOOSTER	PUMP P-3125B &	TRANSFER PUMP	P-102-SY-02A	Y-74.2
N019: 002/002		HEARTBEAT	FROM PCU-2	TO PCU-1		
		STOP BOOSTER	PUMP P-3125A &	TRANSFER PUMP	P-102-SY-02A	Y-74.1

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00099

DB Form Report Sorted By: Address

08:16:10 02/19/99

N019:002/003	HB-23	HEARTBEAT	FROM PCU-2	TO PCU-3		
N019:002/004	HB-24	HEARTBEAT	FROM PCU-2	TO PCU-4		
N019:002/005	HB-25	HEARTBEAT	FROM PCU-2	TO PCU-5		
N019:002/006		LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
N019:002/007		LEAK DETECTED	IN LINE TO	DIVERSION	BOX 6241-A	Y-72.1
N019:002/008		SOV-3182A	VALVE	FAILURE		Y-71.1
N019:002/009		SOV-3182B	VALVE	FAILURE		Y-71.1
N019:002/010		SOV-3184	VALVE	FAILURE		Y-71.1
N019:002/011		SOV-3173A/B	VALVE	FAILURE		Y-73.1
N019:002/012		SOV-3183B	VALVE	FAILURE		Y-71.1
N019:002/013		SOV-3183A	VALVE	FAILURE		Y-71.1
N019:002/014		PUMP P-3125A	HIGH INLET	PRESSURE		Y-75.1
N019:002/015		PUMP P-3125B	HIGH INLET	PRESSURE		Y-75.1
N019:003/000		INPUT SIGNAL TO	200-W MASTER	SHUTDOWN	CIRCUIT	Y-72.1
N019:003/001	HB-31	HEARTBEAT	FROM PCU-3	TO PCU-1		
N019:003/002	HB-32	HEARTBEAT	FROM PCU-3	TO PCU-2		
N019:003/003						
N019:003/004	HB-34	HEARTBEAT	FROM PCU-3	TO PCU-4		
N019:003/005	HB-35	HEARTBEAT	FROM PCU-3	TO PCU-5		
N019:003/006						
N019:003/007		TRANSFER 2A	SHUTDOWN			Y-42.1
N019:003/008		TRANSFER 2B	SHUTDOWN			Y-43.1
N019:003/009						
N019:003/010		TRANSFER 1	INITIATED			Y-41.1
N019:003/011		TRANSFER 2A	INITIATED			Y-42.1
N019:003/012		TRANSFER 2B	INITIATED			Y-43.1
N019:003/013		TRANSFER 3	INITIATED			Y-44.1
N019:003/014						
N019:003/015		MASTER RESET				
N019:004/000						
N019:004/001	HB-41	HEARTBEAT	FROM PCU-4	TO PCU-1		
N019:004/002	HB-42	HEARTBEAT	FROM PCU-4	TO PCU-2		
N019:004/003	HB-43	HEARTBEAT	FROM PCU-4	TO PCU-3		
N019:004/004						
N019:004/005	HB-45	HEARTBEAT	FROM PCU-4	TO PCU-5		
N019:004/006						
N019:004/007		MOV-843	VALVE	FAILURE		Y71
N019:004/008		MOV-844	VALVE	FAILURE		Y71
N019:004/009		MOV-845	VALVE	FAILURE		Y71
N019:004/010		MOV-846	VALVE	FAILURE		Y71
N019:004/011		200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:004/012		RUPTURE	DISK FAILURE			Y-78.1
N019:004/013		LEAK DETECTED	AT 244-A LIFT	STATION	SUMP	Y-72.1
N019:004/014						
N019:004/015						
N019:005/000						
N019:005/001	HB-51	HEARTBEAT	FROM PCU-5	TO PCU-1		
N019:005/002	HB-52	HEARTBEAT	FROM PCU-5	TO PCU-2		
N019:005/003	HB-53	HEARTBEAT	FROM PCU-5	TO PCU-3		
N019:005/004	HB-54	HEARTBEAT	FROM PCU-5	TO PCU-4		
N019:005/005						
N019:005/006						
N019:005/007						
N019:005/008						
N019:005/009						
N019:005/010						
N019:005/011						
N019:005/012						
N019:005/013						
N019:005/014						
N019:005/015						
N020:000	FT-302C-1	LEAK DETECTED	IN LINE TO	244-A LIFT	STATION	Y72-1
N020:001	FT-302C-2	FLUSH PUMP	P-3100A	OUTLET FLOW		
N020:002	LIT-302C-1	INLET FLOW	TO TANK	TK-302-C	LINE 4	
N020:003	IY-P102SY-02A	TANK	TK-302-C	LEVEL		
N020:004	LIT-WST-3102	PUMP	P-102-SY-02A	CURRENT		
N020:005		TANK	241-SY-102	LEVEL	INDICATION	
N020:006		SPARE	ANALOG	INPUT		
N020:007		SPARE	ANALOG	INPUT		
N020:008	TE-302C-1	SPARE	ANALOG	INPUT		
		TANK	TK-302-C	TEMPERATURE		
N020:009	TE-302C-2	FLUSH PUMP	P-3100A	OUTLET TEMP	LINE 3	
N020:010		SPARE	THERMOCOUPLE	INPUT		
N020:011		SPARE	THERMOCOUPLE	INPUT		
N020:012		SPARE	THERMOCOUPLE	INPUT		
N020:013		SPARE	THERMOCOUPLE	INPUT		
N020:014		SPARE	THERMOCOUPLE	INPUT		
N020:015		SPARE	THERMOCOUPLE	INPUT		

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
WLS - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00100

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:11 02/19/99

N020:016	P-3100B	FLOW CONTROL	CHEM ADD	PUMP P-3100B		
N020:017		SPARE	ANALOG	OUTPUT		
N020:018		SPARE	ANALOG	OUTPUT		
N020:019		SPARE	ANALOG	OUTPUT		
N021:020		DH+ TRANSFER	TO PCU-2	DATA REGISTERS		
N021:020/000						
N021:020/001						
N021:020/002						
N021:020/003						
N021:020/004						
N021:020/005						
N021:020/006						
N021:020/007						
N021:020/008						
N021:020/009						
N021:020/010						
N021:020/011						
N021:020/012						
N021:020/013						
N021:020/014						
N021:020/015						
N021:021						
N021:022						
N021:023						
N021:024						
N021:029						
N021:040		COMMUNICATIONS	TEST REGISTER	TO PLC-2		
N021:040/000		DH+ TRANSFER	TO PCU-3	DATA REGISTERS		
N021:040/001						
N021:040/002						
N021:040/003						
N021:040/004						
N021:040/005						
N021:040/006						
N021:040/007						
N021:040/008						
N021:040/009						
N021:040/010						
N021:040/011						
N021:040/012						
N021:040/013						
N021:040/014						
N021:040/015						
N021:041						
N021:042						
N021:043						
N021:044						
N021:060						
N021:060/000		DH+ TRANSFER	TO PCU-4	DATA REGISTERS		
N021:060/001						
N021:060/002						
N021:060/003						
N021:060/004						
N021:060/005						
N021:060/006						
N021:060/007						
N021:060/008						
N021:060/009						
N021:060/010						
N021:060/011						
N021:080/012						
N021:080/013						
N021:080/014						
N021:080/015						
N021:081						
N021:082						
N021:083						
N021:084						
N021:080						
N021:080/000		DH+ TRANSFER	TO PCU-5	DATA REGISTERS		
N021:080/001						
N021:080/002						
N021:080/003						
N021:080/004						
N021:080/005						
N021:080/006						
N021:080/007						

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
WLS - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00101

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

08:16:11 02/19/99

N021:080/008					
N021:080/009					
N021:080/010					
N021:080/011					
N021:080/012					
N021:080/013					
N021:080/014					
N021:080/015					
N021:081					
N021:082					
N021:083					
N021:084					
N021:120	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N021:140	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N021:160	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N021:180	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N022:000	DH+ TRANSFER	FROM PCU-2	DATA REGISTERS		
N022:000/000					
N022:000/001					
N022:000/002					
N022:000/003					
N022:000/004					
N022:000/005					
N022:000/006					
N022:000/007					
N022:000/008					
N022:000/009					
N022:000/010					
N022:000/011					
N022:000/012					
N022:000/013					
N022:000/014					
N022:000/015					
N022:001					
N022:002					
N022:003					
N022:004					
N023:000	DH+ TRANSFER	FROM PCU-3	DATA REGISTERS		
N023:000/000					
N023:000/001					
N023:000/002					
N023:000/003					
N023:000/004					
N023:000/005					
N023:000/006					
N023:000/007					
N023:000/008					
N023:000/009					
N023:000/010					
N023:000/011					
N023:000/012					
N023:000/013					
N023:000/014					
N023:000/015					
N023:001					
N023:002					
N023:003					
N023:004					
N024:000	DH+ TRANSFER	FROM PCU-4	DATA REGISTERS		
N024:000/000					
N024:000/001					
N024:000/002					
N024:000/003					
N024:000/004					
N024:000/005					
N024:000/006					
N024:000/007					
N024:000/008					
N024:000/009					
N024:000/010					
N024:000/011					
N024:000/012					
N024:000/013					
N024:000/014					
N024:000/015					
N024:001					
N024:002					

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00102

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:12 02/19/99

N024:003					
N024:004					
N025:000	DH+ TRANSFER	FROM PCU-5	DATA REGISTERS		
N025:000/000					
N025:000/001					
N025:000/002					
N025:000/003					
N025:000/004					
N025:000/005					
N025:000/006					
N025:000/007					
N025:000/008					
N025:000/009					
N025:000/010					
N025:000/011					
N025:000/012					
N025:000/013					
N025:000/014					
N025:000/015					
N025:001					
N025:002					
N025:003					
N025:004					
DFILE:000	OUTPUTS	Output Reg	isters And	Bits	
DFILE:001	INPUTS	Input Regi	sters And	Bits	
DFILE:002	SYSTEM	System Sta	tus Variab	les	
DFILE:003	BITS	General in	ternal Bit	Addresses	
DFILE:004	TIMERS	General Ti	mer Addr	ses	
DFILE:005	COUNTERS	General Co	unter Addr	esses	
DFILE:006	CONTROL	General Co	ntrol Addr	esses	
DFILE:007	INTEGERS	General In	eger Addr	esses	
DFILE:008	FLOATING	General Fl	oating Poi	nt Address	es
DFILE:009	I/O STATUS	I/O Status	File (Use	d By The P	rocessor)
DFILE:010	PROC FLT	Stores Sys	tem Data 0	n A Proces	or Fault
DFILE:011	GEN MSG	General	DH-Plus Me	ssage Cont	rol File
DFILE:012	GEN BT	General	Block Tran	sfer Contr	ol File
DFILE:013	ANA RAW	Analog Dat	a File		
DFILE:014	OIM DATA	OCS Commun	ication Fi	le	
DFILE:016	PID CTRL	PID CONTR	L STRUCTUR	E	
DFILE:018	CONFIGIA	Channel 1A	Configura	tion Diag	File
DFILE:019	GLOBAL1A	Channel 1A	Config GI	obal Statu	s File
DFILE:020	ANA BUF	Analog I/O	Working F	ile	
DFILE:021	PLC1DATA	DATA FROM	PLC-1(DH+)		
DFILE:022	PLC2DATA	DATA FROM	PLC-2(DH+)		
DFILE:023	PLC3DATA	DATA FROM	PLC-3(DH+)		
DFILE:024	PLC4DATA	DATA FROM	PLC-4(DH+)		
DFILE:025	PLC5DATA	DATA FROM	PLC-5(DH+)		
N7:[N7:22]	LOOK-UP TABLE	DEMO LOW	VALUE BY	INDIRECT	
N7:[N7:23]	LOOK-UP TABLE	DEMO HIGH	VALUE BY	INDIRECT	
PFILE:000	[SYSTEM DA	TA STORAGE	HEADER]		
PFILE:002	PLC SEQUEN	CING DEMON	STRATION F	ILE	
PFILE:003	PROCESSOR	FAULT ROUT	INE		
PFILE:004	I/O HANDLI	NG FOR ANA	LOG AND OT	HER REGIST	ER I/O
PFILE:005	DATA HIGHW	AY + COMMU	NICATIONS	CHECK SUBR	OUTINE
PFILE:006	GENERAL CO	NITROL SEQU	ENCING SUB	ROUTINE	
PFILE:009	PLC SEQUEN	CING DEMON	STRATION F	ILE	
PFILE:010	COMMUNICAT	IONS SPEED	TEST SEQ.		
PFILE:011	REFERENCE	RAMP SUBRO	UTINE		
Q002:000	MAIN PROGRAM	FILE START-UP	JUMP TO JSR'S		
Q002:001	MAIN PROGRAM	FILE START-UP	JUMP TO END		
Q003:000	PROCESSOR	FAULT ROUTINE	JUMP TO END		
U:004	I/O HANDLING	FOR ANALOG OR	OTHER REG I/O	SUBROUTINE	
U:005	DATA HIGHWAY +	COMMUNICATIONS	CTRL & CHECK	SUBROUTINE	
U:006	GENERAL CONTROL	SEQUENCING	SUBROUTINE		
U:009	PLC SEQUENCING	DEMONSTRATION	PROGRAM FILE		
V:004	I/O HANDLING	FOR ANALOG OR	OTHER REG IN	SUBROUTINE	
V:005	SUBROUTINE				

Addr:B3/0
TITLE:GENERAL USE BITS AND TIMING FUNCTIONS
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF

Addr:B3/1
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON

Addr:B3/2
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY SECOND.

Addr:B3/3
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY TWO SECONDS.

Addr:B3/4
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/5
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/6
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/36
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING

Addr:B3/37
RUNG DESCRIPTION:
THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

Addr:B3/39
TITLE:ANALOG INPUTS BLOCK TRANSFER & DH+ MESSAGES SEQUENCING

Addr:B3/40
TITLE:COMMUNICATION HANDLING SUBROUTINE

Addr:B3/41
TITLE:GENERAL CONTROL SEQUENCING FOR PCU #1

Addr:B3/48
TITLE:ANALOG INPUT OVER / UNDER RANGE ALARMS

Addr:B3/79
TITLE:FLUSH PUMP P-3100A CONTROL LOGIC, ES-058-Y90 SH.1

Addr:B3/300
TITLE:PLC RAMP FUNCTION SUBROUTINE

Addr:B3/301
RUNG DESCRIPTION:
THE NEXT TWO RUNGS CALCULATE THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN TARGET AND CURRENT SETPOINTS.

Addr:B3/302
RUNG DESCRIPTION:
IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS GREATER THAN THE INCREMENT LIMIT,

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00104

DB Form Report Sorted By: Address

08:16:12 02/19/99

ADD OR
SUBTRACT THE LIMIT VALUE AS APPROPRIATE.

Addr:B3/303
RUNG DESCRIPTION:
IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS LESS THAN OR EQUAL TO THE INCREMENT LIMIT, SET THE CURRENT SETPOINT EQUAL TO THE TARGET SETPOINT.

Addr:B3/310
TITLE: SPEED REFERENCE RAMP CALL SEQUENCING
RUNG DESCRIPTION:
ENABLE THE SPEED RAMP REFERENCE WHEN THE CONTROLLER RUN OUTPUT IS ON. WHILE THE REFERENCE IS ENABLED, SCALE THE SPEED REFERENCE AND MOVE THIS DESIRED SPEED INTO THE SPEED REFERENCE RAMP TARGET SETPOINT WORKING REGISTER.

Addr:B3/311
RUNG DESCRIPTION:
ENABLE THE SPEED RAMP ANY TIME THE REFERENCE IS ENABLED. IF THE CONTROL HAS THE ABILITY TO RAMP TO A STOP, KEEP THE RAMP ENABLED AFTER THE REFERENCE IS DISABLED UNTIL EITHER THE REFERENCE (OR FEEDBACK IF AVAILABLE) APPROACHES ZERO OR THE CONTROLLER 'ON' STATUS DROPS OUT.

NOTE: THE RAMP INCREMENT 'MOV' SERVES ONLY AS AN EASY DISPLAY OF THE CURRENT VALUE.

Addr:B3/313
RUNG DESCRIPTION:
JUMP TO THE SPEED RAMP SUBROUTINE CONDITIONALLY WHEN THE RAMP IS ENABLED AND THE RAMP OUTPUT DOES NOT EQUAL ITS INPUT. THE RAMP RUNS THE FIRST TIME THESE CONDITIONS ARE MET AND THEN EACH TIME THE RAMP TIMER IS DONE. USE A HISTOGRAM ON THE RAMP DONE BIT TO VERIFY THE RAMP SCAN PERIOD WHEN ADJUSTING THE RAMP TIMER FOR THE DESIRED RAMP PERIOD.

Addr:B3/314
RUNG DESCRIPTION:
WHEN THE RAMP REFERENCE IS NOT ENABLED, CLEAR (ZERO) THE SPEED REFERENCE RAMP TARGET SETPOINT REGISTER. THIS FUNCTION ENABLES THE REFERENCE TO RAMP DOWN TO A STOP IF THE CONTROLLER HAS THE ABILITY TO STAY ENERGIZED TO A LOW SPEED.

Addr:B3/315
RUNG DESCRIPTION:
IF THE SPEED RAMP IS NOT ENABLED, PLACE A ZERO IN THE SPEED REFERENCE CURRENT SETPOINT REGISTER. THIS REGISTER IS THE RAMP OUTPUT OR THE ACTUAL SPEED REFERENCE TO THE CONTROLLER.

Addr:B3/316
RUNG DESCRIPTION:
JUMP TO THE RAMP SUBROUTINE WITH PASSED PARAMETERS:
INPUT PAR (1): DESIRED OR TARGET SPEED REFERENCE (RAMP INPUT)
INPUT PAR (2): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
INPUT PAR (3): MAXIMUM RAMP REFERENCE INCREMENT IN A SINGLE SCAN THROUGH THE SUBROUTINE
RETURN PAR (1): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
RETURN PAR (2): DIFFERENCE BETWEEN DESIRED (TARGET) AND ACTUAL (OUTPUT) REFERENCES
RETURN PAR (3): ABSOLUTE VALUE OF RAMP REFERENCE DIFFERENCE

Addr:B3/317
RUNG DESCRIPTION:
MOVE THE RAMPED SPEED REFERENCE TO THE ACTUAL OUTPUT REGISTER WHICH IS CONNECTED TO THE CONTROLLER.

Addr:B3/483
RUNG DESCRIPTION:
EXCLUSIVE OR

Addr:B3/486
RUNG DESCRIPTION:
J-K FLIP FLOP

Addr:B3:1
RUNG DESCRIPTION:
THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE BITS CAN BE USED TO DIVIDE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN

APPENDIX A

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-1)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00105

DB Form Report Sorted By: Address

08:16:12 02/19/99

TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

Addr:F8:1
RUNG DESCRIPTION:
ACCUMULATED FLOW INTO TANK TK-302-C SEQUENCING

Addr:F8:11
RUNG DESCRIPTION:
FLOW ACCUMULATOR TEST SEQUENCING RUNG

>>> EDIT THE B3/O CONTACT TO B3/1 AND TEST EDITS.
>>> WHEN THE TEST IS COMPLETED ABOUT 30 MINUTES LATER RECORD THE RESULTS.
>>> UNTEST AND CANCEL EDITS RETURNING THIS CONTACT TO B3/O.

Addr:F8:21
TITLE:PLC SEQUENCING DEMONSTRATION RUNGS (SCANNED ONCE A SECOND)
RUNG DESCRIPTION:
THE NEXT FIVE RUNGS DEMONSTRATE SQUARE ROOT, POLYNOMIAL, EXPONENTIAL, LOGARITHM, AND NATURAL LOG. ENTER A VALUE IN F8:20 AND OBSERVE THE RESULTS IN THE APPROPRIATE REGISTER.

Addr:F8:26
RUNG DESCRIPTION:
NON-LINEAR FUNCTION GENERATOR

Addr:F8:33
RUNG DESCRIPTION:
MOVING AVERAGE (WITH WEIGHTING)
>> F8:30 IS THE WEIGHTING FACTOR (K)
>> F8:30 = 0 USES ONLY THE PRESENT VALUE
>> F8:30 = 1 LOCKS THE OUTPUT AT THE PREVIOUS VALUE

Addr:N7:26
RUNG DESCRIPTION:
FUNCTION OR LOOK-UP TABLE WITH INTERPOLATION

Addr:N7:302
RUNG DESCRIPTION:
CALCULATE THE DIFFERENCE BETWEEN THE CURRENT AND TARGET SETPOINTS.

Addr:N14:0/13
TITLE:MASTER SHUTDOWN LOGIC, Y-77.1

Addr:N14:0/14
TITLE:TRANSFER PUMP INTERLOCK LOGIC, Y-75.1

Addr:N16:20/0
RUNG DESCRIPTION:
COMMUNICATIONS BETWEEN PCU-1 AND PCU-2

Addr:N16:40/1
RUNG DESCRIPTION:
COMMUNICATIONS BETWEEN PCU-1 AND PCU-3

Addr:N16:60/0
RUNG DESCRIPTION:
COMMUNICATIONS BETWEEN PCU-1 AND PCU-4

Addr:N16:80/0
RUNG DESCRIPTION:
COMMUNICATIONS BETWEEN PCU-1 AND PCU-5

Addr:N19:1/2
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-1 AND PCU-2

Addr:N19:1/3
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-1 AND PCU-3

APPENDIX A

Hanford Cross Site Transfer System (PCU-1)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00106

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

08:16:12 02/19/99

Addr:N19:1/4
 RUNG DESCRIPTION:
 COMMUNICATION BETWEEN PCU-1 AND PCU-4

Addr:N19:1/5
 RUNG DESCRIPTION:
 COMMUNICATION BETWEEN PCU-1 AND PCU-5

Addr:N21:39
 TITLE:COMMUNICATIONS SPEED CHECKING SUBROUTINE
 RUNG DESCRIPTION:
 THIS SUBROUTINE IS AN 'STI' OR 'SELECTABLE TIMED INTERRUPT' PROGRAM FILE. THE PROCESSOR RUNS THIS PROGRAM EVERY 100 MS (0.1 SECONDS) ON AN INTERRUPT BASIS. EACH TIME THE PROGRAM RUNS, REGISTERS N14:10 AND N21:39 ARE INCREMENTED BY ONE. THESE REGISTERS CAN BE MONITORED IN THE OIT (N14:10) AND PLC-2 (N21:39) TO DETERMINE THE EFFECTIVE COMMUNICATIONS SPEED BETWEEN THE TWO STATIONS.

Addr:N22:200
 TITLE:SEQUENCING TO HANDLE OIT DATA TO AND FROM THE OTHER PCU'S
 RUNG DESCRIPTION:
 THE FOLLOWING EIGHT RUNGS DISPERSE THE CONDENCED OIT PUSHBUTTON AND ENTRY DATA OUT TO THE APPROPRIATE PLC'S

Addr:0:007/05
 RUNG DESCRIPTION:
 LEAK DETECTION CONTROL LOGIC, Y-72.1

Addr:PD16:0
 RUNG DESCRIPTION:
 INTEGRATOR (KP AND KD SET TO ZERO)

Addr:Q2:1
 RUNG DESCRIPTION:
 THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING

Addr:Q3:0
 TITLE:PROCESSOR FAULT ROUTINE PROGRAM FILE.
 RUNG DESCRIPTION:
 THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL OCCURE ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN, A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE COPIED INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.

Addr:T4:0
 TITLE:MAINLINE PROGRAM INITIALIZATION JUMP
 RUNG DESCRIPTION:

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
 P.O. Box 28970
 Spokane, WA 99228-8970
 (509) 466-2656

THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
 THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS BEEN UPDATED ON POWERUP OR ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS BEEN READ. TIMER T4:0 IS USED TO SET THIS TIME DELAY.

Addr:T4:1
 RUNG DESCRIPTION:
 THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

WIntelligent LOGIC 5 - Rockwell Software Inc.

Project Name : PLC2.X5

Time/Date : 07:47:15 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Table of Contents
 Lockheed Martin Hanford Co.

07:49:00 02/19/99

Page	Rung	Description
1		Ladder Report
1	0	MAINLINE PROGRAM INITIALIZATION JUMP
2	2	GENERAL USE BITS AND TIMING FUNCTIONS
5	11	PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
7	0	PROCESSOR FAULT ROUTINE PROGRAM FILE
9	0	ANALOG INPUTS BLOCK TRANSFER SEQUENCING
17	15	ANALOG INPUT OVER / UNDER RANGE ALARMS
31	0	COMMUNICATION HANDLING SUBROUTINE
42	26	SEQUENCING FOR OIT DATA TO AND FROM PLC-1
47	0	VALVE SEQUENCING FOR SOV-3182A
52	14	VALVE SEQUENCING FOR SOV-3182B
57	27	VALVE SEQUENCING FOR SOV-3184
62	40	VALVE SEQUENCING FOR SOV-3183A
67	53	VALVE SEQUENCING FOR SOV-3183B
72	66	ISOLATION VALVE AND ENCASEMENT LEAK DETECTION SEQUENCING
75	0	BOOSTER PUMP P-3125A SEQUENCING
84	23	SPEED REFERENCE RAMP CALL SEQUENCING
92	33	BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING
97	46	BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING
102	0	SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
108	21	SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
114	41	SEQUENCING FOR THE COMMON DRAIN VALVE AND BOOSTER PUMP INTERLOCKS
116	0	VALVE SEQUENCING FOR SOV-3125E
131	0	SUMP PUMP P-3115 CONTROL
132	3	VALVE SEQUENCING FOR SOV-3173A
136	14	VALVE SEQUENCING FOR SOV-3173B
140	25	VALVE SEQUENCING FOR SOV-3156A
143	35	VALVE SEQUENCING FOR SOV-3156B
146	0	PLC RAMP FUNCTION SUBROUTINE
149		DT Form Report
149		DB Form Report

Sorted By: Address

Hanford Cross Site Transfer System (PCU-2)
 MAINLINE PROGRAM INITIALIZATION JUMP
 Lockheed Martin Hanford Co.
 Page:00001

File #2 MAIN Proj:PLC2

07:47:15 02/19/99

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
 P.O. Box 28970
 Spokane, WA 99228-8970
 (509) 466-2656

*THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
 *THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS
 *BEEN UPDATED ON POWERUP OR
 *ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS
 *BEEN READ. TIMER T4:0 IS
 *USED TO SET THIS TIME DELAY.

FIRST SCAN
 OF LADDER
 OR SFC
 STEP

POWER-UP
 SEQUENCING
 DELAY

2:0000 S:1/15

+--TOF-----+
 |Timer Off Delay|-(EN)-
 |Timer: T4:0|
 |Base (SEC): 0.01|-(DN)
 |Preset: 20|
 |Accum: 20|
 +-----+

T4:0.DN - 0,1,14

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

2:0001 T4:0.DN

Q2:0
 [JMP]

Q2:0 - 1,11

Hanford Cross Site Transfer System (PCU-2)
 GENERAL USE BITS AND TIMING FUNCTIONS
 Lockheed Martin Hanford Co.
 Page:00002

File #2 MAIN Proj:PLC2

07:47:16 02/19/99

.....
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF
 .....

ALWAYS OFF   ALWAYS OFF
 OUTPUT   OUTPUT
 ALWAYS OFF   ALWAYS OFF
 B3/0   B3/0

ALWAYS OFF
 OUTPUT
 ALWAYS OFF
 B3/0
 ( )

2:0002

B3/0   - 2,2, /2,6, [4]14, [5],3

.....
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON
 .....

ALWAYS ON
 OUTPUT
 ALWAYS ON
 B3/1
 ( )

2:0003

B3/1   - 3

.....
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE
 *LOGIC THAT IS TO BE EXECUTED ONCE EVERY SECOND.
 .....

REAL TIME   ONE SECOND
 CLOCK   RISING
 SECOND   ONE SHOT
 ONE'S BIT   ONE SHOT

ONE SECOND
 SINGLE SCAN
 PULSE
 1_SEC PULSE
 B3/2
 ( )

2:0004

S:23/0   B3/32
 [ONS]

REAL TIME   ONE SECOND
 CLOCK   FALLING
 SECOND   ONE SHOT
 ONE'S BIT   ONE SHOT

S:23/0   B3/33
 [ONS]

B3/2   - 4,7, [5],5,26

.....
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO
 *ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY TWO
 *SECONDS.
 .....

REAL TIME   TWO SECOND
 CLOCK   RISING
 SECOND   ONE SHOT
 TWO'S BIT   ONE SHOT

TWO SECOND
 SINGLE SCAN
 PULSE
 2_SEC PULSE
 B3/3
 ( )

2:0005

S:23/1   B3/34
 [ONS]

REAL TIME   TWO SECOND
 CLOCK   FALLING
 SECOND   ONE SHOT
 TWO'S BIT   ONE SHOT

S:23/1   B3/35
 [ONS]

Hanford Cross Site Transfer System (PCU-2)
GENERAL USE BITS AND TIMING FUNCTIONS
Lockheed Martin Hanford Co.
Page:00003

File #2 MAIN Proj:PLC2

07:47:16 02/19/99

B3/3 - 5,6,6

*THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING
*SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE
*SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT
*WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO
*B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND
*SINGLE SCAN PULSE. THESE BITS CAN BE USED TO DIVIDE
*PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR
*SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN
*TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING
*TO BE USED.

*THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

Hanford Cross Site Transfer System (PCU-2)
 GENERAL USE BITS AND TIMING FUNCTIONS
 Lockheed Martin Hanford Co.
 Page:00004

File #2 MAIN Proj:PLC2

07:47:16 02/19/99

*****
 *THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST
 *FLASHER ON OPERATOR OUTPUT DEVICES.
 *****

HALF SECOND
 FLASHER TIMER

HALF SECOND
 FLASHER
 HALF_SEC_FLASH
 B3/4
 ( )

2:0008 T4:1.DN
 -----|-----

B3/4 - 8

*****
 *THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL
 *FLASHER ON OPERATOR OUTPUT DEVICES.
 *****

REAL TIME
 CLOCK
 SECOND
 ONE'S BIT

ONE SECOND
 FLASHER
 1_SEC_FLASH
 B3/5
 ( )

2:0009 S:23/0
 -----|-----

B3/5 - 9

*****
 *THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW
 *FLASHER ON OPERATOR OUTPUT DEVICES.
 *****

REAL TIME
 CLOCK
 SECOND
 TWO'S BIT

TWO SECOND
 FLASHER
 2_SEC_FLASH
 B3/6
 ( )

2:0010 S:23/1
 -----|-----

B3/6 - 10

Hanford Cross Site Transfer System (PCU-2)
 PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
 Lockheed Martin Hanford Co.
 Page:00005

File #2 MAIN Proj:PLC2

07:47:16 02/19/99

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING
 *****

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

PROGRAM FILE
 JUMP-TO-SUBR.
 CONTROL RUNGS
 COMMENT COIL

2:0011 Q2:0
 [LBL]

B3/36
 ( )

B3/36 - 11

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

2:0012 +---JSR---+
 |Jump To Subroutine|
 |File #: U:4|
 +---+---+

U:4 - 12,[4]0

DATA HIGHWAY+
 COMMUNICATIONS
 CTRL & CHECK
 SUBROUTINE

2:0013 +---JSR---+
 |Jump To Subroutine|
 |File #: U:5|
 +---+---+

U:5 - 13,[5]0

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING
 *****

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO END

2:0014 T4:0,DN
 [ ]

Q2:1
 [JMP]

Q2:1 - 14,20

GENERAL FILE
 SUBROUTINE

2:0015 +---JSR---+
 |Jump To Subroutine|
 |File #: U:6|
 +---+---+

U:6 - 15,[6]0

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-2)
PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
Lockheed Martin Hanford Co.
Page:00006

File #2 MAIN Proj:PLC2

07:47:17 02/19/99

Address	Instruction	Label	Comment
2:0016	U:7 - 16,[7]0		JSR Jump To Subroutine File #: U:7
2:0017	U:8 - 17,[8]0		JSR Jump To Subroutine File #: U:8
2:0018	U:9 - 18,[9]0		JSR Jump To Subroutine File #: U:9
2:0019	U:10 - 19,[10]0		JSR Jump To Subroutine File #: U:10
*THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE			
MAIN PROGRAM FILE START-UP JUMP TO END		MCP FILE #2 END OF PROGRAM COMMENT COIL	
2:0020	Q2:1 [LBL]	B3/37	B3/37 ( )
2:0021	B3/37 - 20		[End]

Hanford Cross Site Transfer System (PCU-2)
 PROCESSOR FAULT ROUTINE PROGRAM FILE.
 Lockheed Martin Hanford Co.
 Page:00007

File #3 PRO_FLT Proj:PLC2

07:47:17 02/19/99

*****
 *THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE
 *PROCESSOR. FIRST SCAN WILL OCCURE
 *ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL
 *OCCURE ON POWER DOWN.
 *A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE
 *STATUS DATA WILL ONLY BE COPIED
 *INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN
 *RUNG ZERO.
 *****

FIRST SCAN
 OF LADDER
 OR SFC
 STEP

PROCESSOR
 FAULT ROUTINE
 JUMP TO END

S:1/15

Q3:0

3:0000

[JMP]

Q3:0 - [3]0,2

LOGICAL RACK
 STATUS BITS
 FOR RACKS 0-7

3:0001

+--BTD-----+
 Bit Field Distributor
 Source: S:7
 Source Bit: 0
 Dest: N10:7
 Dest Bit: 0
 Length: 8
 +-----+

Last
 program
 scan time
 ladder &
 SFC

+--COP-----+
 Copy File
 Source: #S:8
 Dest: #N10:8
 Length: 16
 +-----+

S:7 - [3]1
 N10:7 - [3]1
 N10:7 - [3]wf1
 N10:7 - [3]wf1

PROCESSOR
 FAULT ROUTINE
 JUMP TO END

FAULT ROUTINE
 FILE #3
 END OF PROGRAM
 COMMENT COIL

Q3:0

B3/38

3:0002

[LBL]

( )

B3/38 - [3]2

Hanford Cross Site Transfer System (PCU-2)
PROCESSOR FAULT ROUTINE PROGRAM FILE.
Lockheed Martin Hanford Co.
Page:00008

File #3 PRO_FLT Proj:PLC2

07:47:17 02/19/99

3:0003

REGISTER FOR
VERIFYING
FAULT ROUTINE
FILE OPERATION

+---ADD-----+
Add
Source A: N10:0 18
Source B: 1
Dest: N10:0 18
+-----+

N10:0 - [3]3,3
N10:0 - [3]3,3

3:0004

[End]

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00009

File #4 REG_10 Proj:PLC2

07:47:17 02/19/99

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

PROGRAM
 FILE #4 START
 OF SUBROUTINE
 COMMENT COIL

B3/39

4:0000 +---SBR-----+
 |Subroutine |
 +-----+

( )

B3/39 - [4]0

R.T.D. MODULE
 POWERED UP BUT
 NOT CONFIGURED

4:0001 N13:1/15 BT12:0.EN BT12:1.EN
 -----| |-----| |-----| |-----| |-----

+---BTW-----+
 Block Transfer Write
 Mod Type: 1771-N
 High Resolution Analog I/O
 Rack: 0
 Group: 3
 Module: 0
 Control Block: BT12:1
 Data File: N13:28
 Length: 59
 Continuous: N
 +-----+

-(EN)-

-(DN)

-(ER)

BT12:1.EN - [4]1,1/1,2
 N13:28 - [4]1,1

4:0002 BT12:0.EN BT12:1.EN
 -----| |-----| |-----| |-----| |-----

+---BTR-----+
 Block Transfer Read
 Mod Type: 1771-N
 High Resolution Analog I/O
 Rack: 0
 Group: 3
 Module: 0
 Control Block: BT12:0
 Data File: N13:0
 Length: 28
 Continuous: N
 +-----+

-(EN)-

-(DN)

-(ER)

BT12:0.EN - [4]1,2,1/2,3
 N13:0 - [4]2,2

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUTS BLOCK TRANSFER SEQUENCING
Lockheed Martin Hanford Co.
Page:00010

File #4 REG_10 Proj:PLC2

07:47:18 02/19/99

4:0003

BT12:0.DN

PUMP P-3125B
MOTOR INBOARD
BEARING
TEMPERATURE
TE-3125B1

+--DIV--+
Div
Source A: N13:5
538
Source B: 10
10
Dest: N20:0
54

PUMP P-3125B
MOTOR OUTBOARD
BEARING
TEMPERATURE
TE-3125B2

+--DIV--+
Div
Source A: N13:7
542
Source B: 10
10
Dest: N20:1
54

PUMP P-3125A
MOTOR INBOARD
BEARING
TEMPERATURE
TE-3125A1

+--DIV--+
Div
Source A: N13:9
540
Source B: 10
10
Dest: N20:2
54

PUMP P-3125A
MOTOR OUTBOARD
BEARING
TEMPERATURE
TE-3125A2

+--DIV--+
Div
Source A: N13:11
541
Source B: 10
10
Dest: N20:3
54

SPARE
R.T.D. TEMP.
INPUT

+--DIV--+
Div
Source A: N13:13
11660
Source B: 10
10
Dest: N20:4
1166

SPARE
R.T.D. TEMP.
INPUT

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00011

File #4 REG_10 Proj:PLC2

07:47:18 02/19/99

```

+--DIV-----+
|Div|
|Source A: N13:15|
|11660|
|Source B: 10|
|10|
|Dest: N20:5|
|1166|
+-----+

```

SPARE
 R.T.D. TEMP.
 INPUT

```

+--DIV-----+
|Div|
|Source A: N13:17|
|11660|
|Source B: 10|
|10|
|Dest: N20:6|
|1166|
+-----+

```

SPARE
 R.T.D. TEMP.
 INPUT

```

+--DIV-----+
|Div|
|Source A: N13:19|
|11660|
|Source B: 10|
|10|
|Dest: N20:7|
|1166|
+-----+

```

```

N13:5 - [4wf2,3
N20:0 - 43,[5]5,5,[7]50,51
N13:7 - 4wf2,3
N20:1 - 43,[5]5,[7]52,53
N13:9 - 4wf2,3
N20:2 - 43,[5]5,[7]37,38
N13:11 - 4wf2,3
N20:3 - 43,[5]5,[7]39,40
N13:13 - 4wf2,3
N20:4 - 43,[5]5
N13:15 - 4wf2,3
N20:5 - 43,[5]5
N13:17 - 4wf2,3
N20:6 - 43,[5]5
N13:19 - 4wf2,3
N20:7 - 43,[5]5

```

THERM. MODULE
 POWERED UP BUT
 NOT CONFIGURED

4:0004 N13:262/15 BT12:6.EN BT12:7.EN

```

+--BTW-----+
|Block Transfer Write|
|Mod Type: 1771-N|
|High Resolution Analog I/O|
|Rack: 0|
|Group: 0|
|Module: 0|
|Control Block: BT12:7|
|Data File: N13:289|
|Length: 59|
|Continuous: N|
+-----+

```

```

BT12:7.EN - [4]4,1/4,1/5
N13:289 - [4]4,4

```

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUTS BLOCK TRANSFER SEQUENCING
Lockheed Martin Hanford Co.
Page:00012

File #4 REG_10 Proj:PLC2

07:47:19 02/19/99

4:0005	BT12:6.EN BT12:7.EN -- / ----- / -----	+--BTR-----+ Block Transfer Read Mod Type: 1771-N High Resolution Analog I/O Rack: 0 Group: 0 Module: 0 Control Block: BT12:6 Data File: N13:261 Length: 28 Continuous: N	-(EN)- -(DN) -(ER)
	BT12:6.EN - [4]/4,5,/5,6 N13:261 - [4]5,5		

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUTS BLOCK TRANSFER SEQUENCING
Lockheed Martin Hanford Co.
Page:00013

File #4 REG_10.Proj:PLC2

07:47:19 02/19/99

4:0006

BT12:6.DN

PUMP P-3125A/B
OUTLET FLOW
TEMPERATURE
WT-SLL-3160
TE-3125A+---DIV-----+
Div
Source A: N13:266
534
Source B: 10
10
Dest: N20:8
53
+---DIV-----+SPARE
THERMOCOUPLE
INPUT+---DIV-----+
Div
Source A: N13:268
534
Source B: 10
10
Dest: N20:9
53
+---DIV-----+LINE
WT-SNL-3150
TEMPERATURE
TE-3125B+---DIV-----+
Div
Source A: N13:270
536
Source B: 10
10
Dest: N20:10
54
+---DIV-----+SPARE
THERMOCOUPLE
INPUT+---DIV-----+
Div
Source A: N13:272
536
Source B: 10
10
Dest: N20:11
54
+---DIV-----+SPARE
THERMOCOUPLE
INPUT+---DIV-----+
Div
Source A: N13:274
25016
Source B: 10
10
Dest: N20:12
2502
+---DIV-----+SPARE
THERMOCOUPLE
INPUT

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00014

File #4 REG_10 Proj:PLC2

07:47:19 02/19/99

N13:266 - 4|wf5,6
 N20:8 - 4|6,[5]5
 N13:268 - 4|wf5,6
 N20:9 - 4|6,[5]5
 N13:270 - 4|wf5,6
 N20:10 - 4|6,[5]5
 N13:272 - 4|wf5,6
 N20:11 - 4|6,[5]5
 N13:274 - 4|wf5,6
 N20:12 - 4|6,[5]5
 N13:276 - 4|wf5,6
 N20:13 - 4|6,[5]5
 N13:278 - 4|wf5,6
 N20:14 - 4|6,[5]5
 N13:280 - 4|wf5,6
 N20:15 - 4|6,[5]5

ANALOG MODULE
 POWERED UP BUT
 NOT CONFIGURED

N13:348/0 BT12:8.EN BT12:9.EN

4:0007

BT12:9.EN - 4|7,/7,/8
 N13:368 - 4|7,7

---DIV---
 Div
 Source A: N13:276
 Source B: 25016
 10
 10
 Dest: N20:13
 2502

SPARE
 THERMOCOUPLE
 INPUT

---DIV---
 Div
 Source A: N13:278
 Source B: 25016
 10
 10
 Dest: N20:14
 2502

SPARE
 THERMOCOUPLE
 INPUT

---DIV---
 Div
 Source A: N13:280
 Source B: 25016
 10
 10
 Dest: N20:15
 2502

---BTW---
 Block Transfer Write (EN)-
 Mod Type: 1771-IFE
 12 Bit Analog Input (DN)
 Rack: 0
 Group: 4 (ER)
 Module: 0
 Control Block: BT12:9
 Data File: N13:368
 Length: 21
 Continuous: N

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00015

File #4 REG_10 Proj:PLC2

07:47:20 02/19/99

4:0008	BT12:8.EN BT12:9.EN - / ----- / -----	+--BTR-----+ Block Transfer Read Mod Type: 1771-IFE 12 Bit Analog Input Rack: 0 Group: 4 Module: 0 Control Block: BT12:8 Data File: N13:348 Length: 12 Continuous: N +-----+	-(EN)- -(DN) -(ER)
	BT12:8.EN - [4]/7,8,/8,9 N13:348/1 - [4]7,8,8,32,33,34,35,36,37,38,39		
4:0009	BT12:8.DN - ----- -----	PUMP P-3125 A/B OUTLET FLOW FT-3125 +--COP-----+ Copy File Source: #N13:352 Dest: #N20:16 Length: 8 +-----+	-(EN)- -(DN) -(ER)
	\ - [4]wf8,9 \ - [4]wf9,[5],5 ANALOG MODULE POWERED UP BUT NOT CONFIGURED PT-3125C		
4:0010	N13:405/0 BT12:10.EN BT12:11.EN - ----- / ----- / -----	+--BTW-----+ Block Transfer Write Mod Type: 1771-IFE 12 Bit Analog Input Rack: 0 Group: 5 Module: 0 Control Block: BT12:11 Data File: N13:425 Length: 19 Continuous: N +-----+	-(EN)- -(DN) -(ER)
	BT12:11.EN - [4]/10,/10,/11 N13:425 - [4]10,10		
4:0011	BT12:10.EN BT12:11.EN - / ----- / -----	+--BTR-----+ Block Transfer Read Mod Type: 1771-IFE 12 Bit Analog Input Rack: 0 Group: 5 Module: 0 Control Block: BT12:10 Data File: N13:405 Length: 11 Continuous: N +-----+	-(EN)- -(DN) -(ER)
	BT12:10.EN - [4]/10,11,/11,12 N13:405/1 - [4]10,11,11,41,42,43,44,45,46,47,48		

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00016

File #4 REG_10 Proj:PLC2

07:47:21 02/19/99

4:0012

BT12:10.DN

PUMP P-3125A
 BEARING
 VIBRATION
 VT-3125A1

Copy File
 Source: #N13:409
 Dest: #N20:24
 Length: 8

\+ - [4]wf11,12
 \+ - [4]wf12,[5],5

4:0013

BT12:12.EN BT12:13.EN

PUMP P-3125A
 OUTLET FLOW
 CONTROL
 SIGNAL
 VSD-3125AR

Copy File
 Source: #N20:32
 Dest: #N13:467
 Length: 4

--BTW--
 Block Transfer Write
 Mod Type: 1771-0FE
 12 Bit Analog Output
 Rack: 0
 Group: 6
 Module: 0
 Control Block: BT12:13
 Data File: N13:467
 Length: 13
 Continuous: N

\T - [4]wf13
 \T - [4]wf13,13,[5]5
 BT12:13.EN - [4]13,13,14
 N13:467 - [4]13,13,13,13,[5]5,5

ALWAYS OFF
 OUTPUT
 ALWAYS OFF
 B3/0

4:0014

BT12:12.EN BT12:13.EN

--BTR--
 Block Transfer Read
 Mod Type: 1771-0FE
 12 Bit Analog Output
 Rack: 0
 Group: 6
 Module: 0
 Control Block: BT12:12
 Data File: N13:462
 Length: 5
 Continuous: N

BT12:12.EN - [4]13,14,14
 N13:462 - [4]14,14

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUT OVER / UNDER RANGE ALARMS
Lockheed Martin Hanford Co.
Page:00017

File #4 REG_10 Proj:PLC2

07:47:21 02/19/99

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUT OVER / UNDER RANGE ALARMS
Lockheed Martin Hanford Co.
Page:00018

File #4 REG_10 Proj:PLC2

07:47:21 02/19/99

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUT OVER / UNDER RANGE ALARMS
Lockheed Martin Hanford Co.
Page:00019

File #4 REG_10 Proj:PLC2

07:47:21 02/19/99

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUT OVER / UNDER RANGE ALARMS
Lockheed Martin Hanford Co.
Page:00020

File #4 REG_10 Proj:PLC2

07:47:22 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00021

File #4 REG_10 Proj:PLC2

07:47:22 02/19/99

N14:12/15		- [4]30			
ANALOG MODULE UNDERRANGE BITS REGISTER		ANALOG MODULE OVERRANGE BITS REGISTER		ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE	
4:0031	+-EQU-		+-EQU-		B3/48
	Equal (A=B)		Equal (A=B)		( )
	Source A: N13:349		Source A: N13:350		
	Source B: 1 0 0		Source B: 0 0 0		
B3/48 - [4]31,32,33,34,35,36,37,38,39					
ANALOG MODULE CHAN. 1 DATA UNDERRANGE		PUMP P-3125 A/B OUTLET FLOW TE-3125A FT-3125R		PCU-2 INPUT ANALOG OVER OR UNDER RANGE ALARM FIC-3125 A N14:13/0	
4:0032	N13:349/0		+-LIM-		( )
			Limit Test (Circular)		
			Low Lim: 1		
			Test: N13:352		
		High Lim: 0			
		-1			
		-1			
ANALOG MODULE CHAN. 1 DATA OVERRANGE					
N13:350/0					
ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE		ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE			
N13:348/1		B3/48			
N14:13/0		- [4]32			

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00022

File #4 REG_10 Proj:PLC2

07:47:22 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00023

File #4 REG_10 Proj:PLC2

07:47:22 02/19/99

N14:13/3 - [4]35

N14:13/4 - [4]36

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00024

File #4 REG_10 Proj:PLC2

07:47:23 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00026

File #4 REG_10 Proj:PLC2

07:47:23 02/19/99

4:0041	ANALOG MODULE CHAN. 1 DATA UNDERRANGE ST-3125A N13:406/0 ----- -----	PUMP P-3125A BEARING VIBRATION VT-3125A1R +-LIM-----+ Limit Test (Circular) Low Lim: 2 Test: N13:409 2 0 High Lim: -2 -2 -----+	PCU-2 INPUT ANALOG OVER OR UNDER RANGE ALARM VI-3125A1_A N14:14/8 ( )
	ANALOG MODULE CHAN. 1 DATA OVERRANGE N13:407/0 ----- -----	ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE PT-3125D ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE N13:405/1 83/49 ----- -----	PCU-2 INPUT ANALOG OVER OR UNDER RANGE ALARM VI-3125B1_A N14:14/9 ( )
4:0042	ANALOG MODULE CHAN. 2 DATA UNDERRANGE ST-3125B N13:406/1 ----- -----	PUMP P-3125B BEARING VIBRATION VT-3125B1R +-LIM-----+ Limit Test (Circular) Low Lim: 2 Test: N13:410 2 0 High Lim: -2 -2 -----+	PCU-2 INPUT ANALOG OVER OR UNDER RANGE ALARM VI-3125B1_A N14:14/9 ( )
N14:14/9	ANALOG MODULE CHAN. 2 DATA OVERRANGE N13:407/1 ----- -----	ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE PT-3125D ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE N13:405/1 83/49 ----- -----	

N14:14/9 - [4]42

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00027

File #4 REG 10 Proj:PLC2

07:47:23 02/19/99

N14:14/10 - [4]43

N14:14/11 - [4]44

ANALOG MODULE CHAN. 5 DATA UNDERRANGE	VALVE SOV-3173A/B PRESSURE PT-3173R	PCU-2 INPUT ANALOG OVER OR UNDER RANGE ALARM P1-3173 A N14:14/T2
N13:406/4	---LIM--- Limit Test (Circular) Low Lim: 4 Test: N13:413 High Lim: -1 -4 -4	( )
ANALOG MODULE CHAN. 5 DATA OVERRANGE	N13:407/4	
ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE PT-3125D	ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE	
N13:405/1	B3/49	
N14:14/12 - [4]45		
ANALOG MODULE CHAN. 6 DATA UNDERRANGE	VALVE SOV-3182A/B PRESSURE PT-3182R	PCU-2 INPUT ANALOG OVER OR UNDER RANGE ALARM P1-3182 A N14:14/T3
N13:406/5	---LIM--- Limit Test (Circular) Low Lim: 3 Test: N13:414 High Lim: -1 -3 -3	( )
ANALOG MODULE CHAN. 6 DATA OVERRANGE	N13:407/5	
ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE PT-3125D	ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE	
N13:405/1	B3/49	
N14:14/13 - [4]46		

Hanford Cross Site Transfer System (PCU-2)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00029

File #4 REG_10 Proj:PLC2

07:47:23 02/19/99

Hanford Cross Site Transfer System (PCU-2)
ANALOG INPUT OVER / UNDER RANGE ALARMS
Lockheed Martin Hanford Co.
Page:00030

File #4 REG_10.Proj:PLC2

07:47:23 02/19/99

4:0050

[End]

Hanford Cross Site Transfer System (PCU-2)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00031

File #5 COMM Proj:PLC2

07:47:23 02/19/99

	DATA HIGHWAY+ COMMUNICATIONS CTRL & CHECK SUBROUTINE		PROGRAM FILE#5 START OF SUBROUTINE COMMENT COIL
5:0000	+--SBR-----+ [Subroutine]		B3/40 ( )
	B3/40 - [5]0		
	*COMMUNICATION BETWEEN PCU-2 AND OCS		
5:0001	HEARTBEAT FROM OCS TO PLC-2 HB_OCS PLC2 N14:120/0 ----- / -----		HEARTBEAT FROM PLC-2 TO OCS HB PLC2_OCS N14:070 ( )
	N14:0/0 - [5]1,2,/2		
5:0002	HEARTBEAT FROM PLC-2 TO OCS HB PLC2_OCS N14:070 ----- -----	COMM LOSS ONE-SHOT B3/200 [ONS]	COMM LOSS TIMER WITH OCS +--TOF-----+ Timer Off Delay -(EN)- Timer: T4:40 Base (SEC): 1.0-(DN) Preset: 30 Accum: 30
	HEARTBEAT FROM PLC-2 TO OCS HB PLC2_OCS N14:070 ----- / -----	COMM LOSS ONE-SHOT B3/201 [ONS]	
	T4:40.DN - [5]2,/3		
5:0003	COMM LOSS TIMER WITH OCS T4:40.DN ----- / -----	ALWAYS OFF OUTPUT ALWAYS OFF B3/0 	COMMUN. WITH OCS IGNORED COM-2_OCS N14:072 ( )
	N14:0/2 - [5]3		
5:0004	BATTERY IS BAD OR MISSING S:10/0 ----- -----		PLC-2 BATTERY IS BAD OR MISSING BATT_BAD PLC2 N14:076 ( )
	N14:0/6 - [5]4		

Hanford Cross Site Transfer System (PCU-2)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00032

File #5 COMM Proj:PLC2

07:47:24 02/19/99

ONE SECOND
 SINGLE SCAN
 PULSE
 1_SEC PULSE
 B372

5:0005

DIGITAL INPUT
 REGISTER TO
 OIT TERMINALS

---COP---
 Copy File
 Source: #1:020
 Dest: #N14:16
 Length: 7

DIGITAL OUTPUT
 REGISTER TO
 OIT TERMINALS

---COP---
 Copy File
 Source: #0:033
 Dest: #N14:25
 Length: 5

PUMP P-3125B
 MOTOR
 BEARING
 TEMPERATURE
 TI-3125B1

---COP---
 Copy File
 Source: #N20:0
 Dest: #N14:30
 Length: 32

PUMP P-3125A
 OUTLET FLOW
 CONTROL
 SIGNAL
 FLC-3125A

---COP---
 Copy File
 Source: #N13:467
 Dest: #N14:62
 Length: 4

\+ - [5]wf5
 \+ - [5]wf5,30
 \+ - [5]wf5
 \+ - [5]wf5,30
 \+ - [5]wf5
 \+ - [5]wf5,30
 \+ - [4]wf13,13,[5]5
 \+ - [5]wf5,30

*****
 *COMMUNICATION BETWEEN PCU-2 AND PCU-1
 *****

HEARTBEAT
 FROM PCU-1
 TO PCU-2
 HB-12
 N19:1/2

5:0006

HEARTBEAT
 FROM PCU-2
 TO PCU-1
 HB-21
 N19:2/1

( )

N19:2/1 - [5]6,7,17

Hanford Cross Site Transfer System (PCU-2)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00033

File #5 COMM Proj:PLC2

07:47:24 02/19/99

```

HEARTBEAT      COMMUN. LOSS
FROM PCU-2     WITH PCU-1
TO PCU-1       ONE-SHOT
HB-21          B3/116
N19:2/1        B3/117
5:0007  +-----[ONS]-----+
+-----+-----+-----+
HEARTBEAT      COMMUN. LOSS
FROM PCU-2     WITH PCU-1
TO PCU-1       ONE-SHOT
HB-21          B3/117
N19:2/1        B3/117
+-----+-----+-----+
T4:81.DN      - [5]7,/8

COMMUN. LOSS
TIMER WITH
PCU-1
COMPLETE

5:0008  T4:81.DN
+-----+-----+-----+
N14:0/1      - [5]8,/9,/26,/27,/29,/30,/31,[7]7,18

COMMUN. LOSS
TIMER WITH
PCU-1

COMMUN. WITH
PCU-1
IGNORED
COM-21
N14:0/1
( )

+--TOF--+
Timer Off Delay  (EN)-
Timer: T4:81
Base (SEC): 1.0  (DN)
Preset: 5
Accum: 0
  
```

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00035

HNF-2346, Rev. 1

File #5 COMM Proj:PLC2

07:47:25 02/19/99

5:0014

COMMUN. WITH
 PCU-3
 IGNORED
 COM-23
 N14:0/3

-||-

R6:11.IN

(U)

COMPARE
 PCU-2 TO PCU-3
 MSG FILE
 WITH PREVIOUS

MG11:1.EN

+--FSC--
 File Search/Compare - (EN)
 Control: R6:11
 Length: 20 - (DN)
 Position: 0
 Mode: ALL - (ER)
 Expression:
 #N22:40 <> #N22:140

R6:11.FD

+--COP--
 Copy File
 Source: #N22:40
 Dest: #N22:240
 Length: 20

SEND MSG
 FROM PCU-2
 TO PCU-3

+--MSG--
 Send/Receive Message - (EN)
 Control Block: MG11:1 - (DN)
 - (ER)

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:1.DN 83/181

+--COP--
 Copy File
 Source: #N22:240
 Dest: #N22:140
 Length: 20

R6:11.IN - {5}14,14,14,15,15,15,15
 R6:11.IN - {5}14,14,14,15,15,15,15
 R6:11.IN - {5}wf14,14
 R6:11.IN - {5}wf14,14
 R6:11.IN - {5}wf14,14
 MG11:1.EN - {5}14,14,14
 MG11:1.EN - {5}wf14,14
 MG11:1.EN - {5}wf14

R6:12.IN - [5]19,19,19,20,20,20,20
 R6:12.IN - [5]19,19,19,20,20,20,20
 R6:12.IN - [5]wf19,19
 R6:12.IN - [5]wf19,19
 R6:12.IN - [5]wf19,19
 MG11:2.EN - [5]19,19,19
 MG11:2.EN - [5]wf19,19
 MG11:2.EN - [5]wf19

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00041

HNF-2346, Rev. 1

File #5 COMM Proj:PLC2

07:47:27 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
SEQUENCING FOR OIT DATA TO AND FROM PLC-1
Lockheed Martin Hanford Co.
Page:00042

HNF-2346, Rev. 1

File #5 COMM Proj:PLC2

07:48:00 02/19/99

5:0026 COMMUN. WITH ONE SECOND
PCU-1 SINGLE SCAN
IGNORED PULSE
COM-21 1_SEC PULSE
N14:0/1 B372

+--COP-----+
Copy File
Source: #N14:120
Dest: #N14:150
Length: 12
+-----+

PUMP
P-3125 A/B
OUTLET FLOW
REFERENCE
FROM OIT
PID-3125-FR_
+--COP-----+
Copy File
Source: #N14:140
Dest: #N14:162
Length: 6
+-----+

\ ~ - [5]wf26,29
\ ~ - [5]wf26,27,27,29
\ ~ - [5]wf26,29
\ ~ - [5]wf26,27,27,29

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.
 Page:00044

File #5 COMM Proj:PLC2

07:48:00 02/19/99

Hanford Cross Site Transfer System (PCU-2)
SEQUENCING FOR OIT DATA TO AND FROM PLC-1
Lockheed Martin Hanford Co.
Page:00046

File #5 COMM Proj:PLC2

07:48:01 02/19/99

File #6 Y71-Y72 Proj:PLC2

07:48:01 02/19/99

```

PROGRAM FILE#6
START OF SUBROUTINE COMMENT COIL

GENERAL FILE SUBROUTINE
+---SBR-----+
|Subroutine |-----B3/41
+---+-----+
6:0000

B3/41 - [6]0

OCS OPEN OCS CLOSE
VALVE VALVE
SOV-3182A SOV-3182A

Y-71.1 Y-71.1 MASTER RESET
HS-3182A1 HS-3182A2 N19:3/15
N14:120/14 N14:120/15

OPEN VALVE
SOV-3182A
BIT
Y-71.1

B3/324

6:0001

B3/324 - [6]1,1,2

OPEN VALVE
SOV-3182A
BIT
Y-71.1

B3/324

TRANSFER 1 INITIATED

Y-41.1
N19:3/10

TRANSFER 3 INITIATED

Y-44.1
N19:3/13

6:0002

0:037/002 - [6]2,12

OCS CLOSE OCS OPEN TRANSFER 1 TRANSFER 3
VALVE VALVE INITIATED INITIATED
SOV-3182A SOV-3182A

Y-71.1 Y-71.1 Y-41.1 Y-44.1
HS-3182A2 HS-3182A1 N19:3/10 N19:3/13
N14:120/15 N14:120/14

CLOSE VALVE
SOV-3182A
BIT
Y-71

B3/325

6:0003

```

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3182A
 Lockheed Martin Hanford Co.
 Page:00049

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:02 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3182A
 Lockheed Martin Hanford Co.
 Page:00051

File #6 Y71-Y72 Proj:PLC2

07:48:02 02/19/99

	OCS CLOSE VALVE SOV-3182A	CLOSE VALVE SOV-3182A		OCS CLOSE VALVE SOV-3182A
6:0013	Y-71.1 HS-3182A2 N14:120/15	Y71 SOV-3182A-C 0:037/03		Y-71.1 HS-3182A2 N14:120/15
	----- -----	----- -----		----- ----- (U)
		1771-0D1 OCS OPEN VALVE SOV-3182A		
		Y-71.1 HS-3182A1 N14:120/14		
	----- -----	----- -----		
		TRANSFER 1 INITIATED		
		Y-41.1 N19:3/10		
	----- -----	----- -----		
		TRANSFER 3 INITIATED		
		Y-44.1 N19:3/13		
	----- -----	----- -----		
	N14:120/15	- [6]/1,3,5,12,13,13		

	OCS OPEN VALVE SOV-3182B Y-71.1 HS-3182B1 N14:121/3	SOV-3182B IS OPEN Y71 ZSH-3182B I:025/02 1771-IBD	SOV-3182B VALVE FAILED TO OPEN DELAY +---TON---+ Timer On Delay Timer: T4:18 Base (SEC): 1.0 Preset: 5 Accum: 0 +-----+
6:0020	TRANSFER 1 INITIATED Y-41.1 N19:3/10 TRANSFER 3 INITIATED Y-44.1 N19:3/13 T4:18.EN		(EN) (DN)
	T4:18.EN - [6]20,20,21 SOV-3182B VALVE FAILED TO OPEN DELAY COMPLETE T4:18.DN		VALVE FAILED TO OPEN Y-71.1 ZA-3182B1 N14:1/14 ( )
6:0021			
	N14:1/14 - [6]21,22 VALVE FAILED TO OPEN Y-71.1 ZA-3182B1 N14:1/14		SOV-3182B VALVE FAILURE Y-71.1 N19:2/9 ( )
6:0022			
	VALVE POSITION SWITCH FAILURE Y-71.1 ZA-3182B N14:2/0 VALVE FAILED TO CLOSE Y-71.1 ZA-3182B2 N14:1/12		
	N19:2/9 - [6]22		

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3182B
 Lockheed Martin Hanford Co.
 Page:00055

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:03 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3182B
 Lockheed Martin Hanford Co.
 Page:00056

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:03 02/19/99

	OCS CLOSE VALVE SOV-3182B	CLOSE VALVE SOV-3182B	OCS CLOSE VALVE SOV-3182B
	Y-71.1 HS-3182B2 N14:121/4	Y71 SOV-3182B-C 0:037/05	Y-71.1 HS-3182B2 N14:121/4
6:0026	----- -----		----- -----
		1771-0D1 OCS OPEN VALVE SOV-3182B	
		Y-71.1 HS-3182B1 N14:121/3	
		----- -----	
		TRANSFER 1 INITIATED	
		Y-41.1 N19:3/10	
		----- -----	
		TRANSFER 3 INITIATED	
		Y-44.1 N19:3/13	
		----- -----	
	N14:121/4	- [6]/14,16,18,25,26,26	

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3184
 Lockheed Martin Hanford Co.
 Page:00057

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:03 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3184
 Lockheed Martin Hanford Co.
 Page:00058

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:03 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3184
 Lockheed Martin Hanford Co.
 Page:00059

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:04 02/19/99

6:0033	OCS OPEN VALVE SOV-3184 Y-71.1 HS-3184-1 N14:121/9 TRANSFER 1 INITIATED Y-41.1 N19:3/10 TRANSFER 3 INITIATED Y-44.1 N19:3/13 T4:27.EN T4:27.EN - [6]33,33,34	SOV-3184 IS OPEN Y71 ZSH-3184 I:025/10 1771-BD	SOV-3184 VALVE FAILED TO OPEN DELAY +---TON-----+ Timer On Delay (EN) Timer: T4:27 Base (SEC): 1.0 (DN) Preset: 5 Accum: 0 +-----+
6:0034	SOV-3184 VALVE FAILED TO OPEN DELAY COMPLETE T4:27.DN N14:3/0 - [6]34,35		VALVE FAILED TO OPEN Y-71.1 ZA-3184-1 N14:3/0 ( )
6:0035	VALVE FAILED TO OPEN Y-71.1 ZA-3184-1 N14:3/0 VALVE POSITION SWITCH FAILURE Y-71.1 ZA-3184 N14:3/2 VALVE FAILED TO CLOSE Y-71.1 ZA-3184-2 N14:2/14 N19:2/10 - [6]35		SOV-3184 VALVE FAILURE Y-71.1 N19:2/10 ( )

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3184
 Lockheed Martin Hanford Co.
 Page:00060

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:04 02/19/99

	OCS CLOSE VALVE SOV-3184	CLOSE VALVE SOV-3184		OCS CLOSE VALVE SOV-3184
	Y-71.1 HS-3184-2 N14:121/10	Y71 SOV-3184-C 0:037/13		Y-71.1 HS-3184-2 N14:121/10
6:0039	----- -----	----- -----		----- ----- (U)
		1771-0D1 OCS OPEN VALVE SOV-3184		
		Y-71.1 HS-3184-1 N14:121/9 ----- -----		
		TRANSFER 1 INITIATED		
		Y-41.1 N19:3/10 ----- -----		
		TRANSFER 3 INITIATED		
		Y-44.1 N19:3/13 ----- -----		
	N14:121/10	- [6]/27,29,31,38,39,39		

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3183A
 Lockheed Martin Hanford Co.
 Page:00062

File #6 Y71-Y72 Proj:PLC2

07:48:04 02/19/99

File #6 Y71-Y72 Proj:PLC2

07:48:05 02/19/99

OCS CLOSE
VALVE
SOV-3183A

CLOSE VALVE
S0V-3183A

OCS CLOSE
VALVE
SOV-3183A

Y-71.1
HS-3183A2
N14:121/6

Y71
S0V-3183A-C
0:037/07

Y-71.1
HS-3183A2
N14:121/6

6:0052

1771-0D1

OCS OPEN
VALVE
S0V-3183A

Y-71.1
HS-3183A1
N14:121/5

TRANSFER 2A
INITIATED

Y-42.1

N19:3/11

TRANSFER 2B
INITIATED

Y-43.1

N19:3/12

N14:121/6

- [6] / 40, 42, 44, 51, 52, 52

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3183B
 Lockheed Martin Hanford Co.
 Page:00067

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:05 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3183B
 Lockheed Martin Hanford Co.
 Page:00068

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:05 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3183B
 Lockheed Martin Hanford Co.
 Page:00069

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:05 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3183B
 Lockheed Martin Hanford Co.
 Page:00070

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:05 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3183B
 Lockheed Martin Hanford Co.
 Page:00071

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:06 02/19/99

OCS CLOSE VALVE SOV-3183B	CLOSE VALVE SOV-3183B	OCS CLOSE VALVE SOV-3183B
Y-71.1 HS-3183B2 N14:121/8	Y71 SOV-3183B-C 0:037/11	Y-71.1 HS-3183B2 N14:121/8
6:0065	----- -----	----- -----
	1771-0D1 OCS OPEN VALVE SOV-3183B	(U)
	Y-71.1 HS-3183B1 N14:121/7 ----- -----	
	TRANSFER 2A INITIATED	
	Y-42.1 N19:3/11 ----- -----	
	TRANSFER 2B INITIATED	
	Y-43.1 N19:3/12 ----- -----	
	----- -----	
N14:121/8	- [6]/53,55,57,64,65,65	

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
ISOLATION VALVE AND ENCASEMENT LEAK DETECTION SEQUENCING
Lockheed Martin Hanford Co.
Page:00073

HNF-2346, Rev. 1

File #6 Y71-Y72 Proj:PLC2

07:48:06 02/19/99

APPENDIX B

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-2)
ISOLATION VALVE AND ENCASEMENT LEAK DETECTION SEQUENCING
Lockheed Martin Hanford Co.
Page:00074

File #6 Y71-Y72 Proj:PLC2

07:48:06 02/19/99

6:0075

[End]

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00075

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:06 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00076

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:07 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00077

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:07 02/19/99

7:0007	BOOSTER START PUMP BOOSTER P-3125A PUMP FAILURE P-3125A Y-74.1 Y-74.1 XA-3125A N14:0/14 B3/87	STOP BOOSTER PUMP P-3125A & TRANSFER PUMP P-102-SY-02A Y-74.1 N19:2/2 ( )
	BOOSTER PUMP P-3125A DRAIN VALVES ALL CLOSED B3/73 / /	
	BOOSTER PUMP TROUBLE Y-76.1 B3/76 / /	
	RUPTURE DISK FAILURE Y-78.1 N19:4/12 / /	
	STOP BOOSTER PUMP P-3125A Y-74.1 HS-3125A2 N14:126/1 / /	
	BOOSTER PUMP HIGH DISCHARGE PRESSURE Y-78.1 PAH-3125C N14:6/2 / /	
	TRANSFER 2A SHUTDOWN Y-42.1 N19:3/7 / /	
	SOV-3125C IS OPEN Y84-1 ZSH-3125C I:024/00 / /	
	1771-IBD SOV-3125E IS OPEN Y83-1 ZSH-3125E I:024/04 / /	
	1771-IBD VALVE SOV-3125C FAILURE	

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00078

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:07 02/19/99

Y-84.1

B3/78

VALVE
 SOV-3125E
 FAILURE

Y-83.1

B3/79

BOOSTER PUMP
 INLET PRESSURE
 SIGNAL DELAY
 COMPLETE
 Y-74.1

T4:54.DN

COMMUN. WITH
 PCU-1
 IGNORED
 COM-21
 N14:0/1

SLURRY LINE
 HIGH PRESSURE
 AT PCU-4

N19:4/6

STOP BOOSTER
 PUMP P-3125A &
 TRANSFER PUMP
 P-102-SY-02A
 Y-74.1

N19:2/2

T4:11.DN

N19:2/2 - [7]7,7,8,/9,10

STOP BOOSTER
 PUMP P-3125A &
 TRANSFER PUMP
 P-102-SY-02A
 Y-74.1

7:0008

N19:2/2

Timer On Delay	-(EN)
Timer: T4:11	
Base (SEC): 0.01	-(DN)
Preset: 500	
Accum: 500	

T4:11.DN - [7]/7,8

STOP BOOSTER
 PUMP P-3125A &
 TRANSFER PUMP
 P-102-SY-02A
 Y-74.1

STOP PUMP
 P-3125A

7:0009

N19:2/2

Y74-1
 P-3125A-P
 0:035/11

0:035/011 - [7]9

771-0016

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00079

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:07 02/19/99

	START BOOSTER PUMP P-3125A Y-74.1 HS-3125A1 N14:126/0	START BOOSTER PUMP P-3125A Y-74.1 B3/87	START BOOSTER PUMP P-3125A Y-74.1 HS-3125A1 N14:126/0 (U)
7:0010		TRANSFER 2A INITIATED Y-42.1 N19:3/11 ----- STOP BOOSTER PUMP P-3125A & TRANSFER PUMP P-102-SY-02A Y-74.1 N19:2/2 -----	
	N14:126/0	- [7]1, /3, 10, 10	
	STOP BOOSTER PUMP P-3125A Y-74.1 HS-3125A2 N14:126/1	START BOOSTER PUMP P-3125A Y-74.1 B3/87	STOP BOOSTER PUMP P-3125A Y-74.1 HS-3125A2 N14:126/1 (U)
7:0011			
	N14:126/1	- [7]7, 11, 11	
	START BOOSTER PUMP P-3125B Y-74.2 HS-3125B1 N14:126/2	TRANSFER 2B INITIATED Y-43.1 N19:3/12	
7:0012			--TOF-- Timer Off Delay Timer: T4:99 Base (SEC): 1.0 Preset: 6 Accum: 6 --(EN)-- --(DN)--
	T4:99.DN	- [7]12, 13	
			START PUMP P-3125B
			Y74-2 P-3125B-T 0:035/12 ( ) 771-0016
7:0013	T4:99.DN		START BOOSTER PUMP P-3125B Y-74.2 B3/88 ( )
	0:035/012 B3/88	- [7]13, 23, /23, 26 - [7]13, 14, 16, 18, 21, /22, [9], /26, 36, /38, 48	

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00080

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:07 02/19/99

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00081

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:08 02/19/99

7:0018	BOOSTER START PUMP BOOSTER P-3125B PUMP FAILURE P-3125B Y-74.2 Y-74.2 XA-3125B N14:0/15 B3/88	STOP BOOSTER PUMP P-3125B & TRANSFER PUMP P-102-SY-02A Y-74.2
		N19:2/0 ( )
	BOOSTER PUMP P-3125B DRAIN VALVES ALL CLOSED	
	B3/74	
	BOOSTER PUMP TROUBLE Y-76.1	
	B3/82	
	RUPTURE DISK FAILURE	
	Y-78.1	
	N19:4/12	
	STOP BOOSTER PUMP P-3125B Y-74.2 HS-3125B2 N14:126/3	
	BOOSTER PUMP HIGH DISCHARGE PRESSURE Y-78.1 PAH-3125D N14:7/2	
	TRANSFER 2B SHUTDOWN	
	Y-43.1	
	N19:3/8	
	SOV-3125D IS OPEN	
	Y86-1 ZSH-3125D I:024/02 1771-1B0 SOV-3125G IS OPEN	
	Y85-1 ZSH-3125G I:024/06 1771-1B0 VALVE SOV-3125G FAILURE	

APPENDIX B

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00082

HNF-2346, Rev. 1

File #7 Y74-Y78 Proj:PLC2

07:48:08 02/19/99

Y-85.1

B3/84

VALVE
 SOV-3125D
 FAILURE

Y-86.1

B3/85

BOOSTER PUMP
 INLET PRESSUR
 SIGNAL DELAY
 COMPLETE
 Y-74.1

T4:56.DN

COMMUN. WITH
 PCU-1
 IGNORED
 COM-21
 N14:0/1

SLURRY LINE
 HIGH PRESSURE
 AT PCU-4

N19:4/6

STOP BOOSTER
 PUMP P-3125B &
 TRANSFER PUMP
 P-102-SY-02A
 Y-74.2

N19:2/0

T4:12.DN

N19:2/0 - [7]18,18,19, /20,21

STOP BOOSTER
 PUMP P-3125B &
 TRANSFER PUMP
 P-102-SY-02A
 Y-74.2

N19:2/0

7:0019

Timer On Delay	-(EN)-
Timer:	T4:12 (DN)
Base (SEC):	0.01
Preset:	500
Accum:	500

T4:12.DN - [7]/18,19

STOP BOOSTER
 PUMP P-3125B &
 TRANSFER PUMP
 P-102-SY-02A
 Y-74.2

STOP PUMP
 P-3125B

Y74-2
 P-3125B-P
 0:035/13
 ( )
 771-0016

N19:2/0

7:0020

0:035/013 - [7]20

	START BOOSTER PUMP P-3125B Y-74.2 HS-3125B1 N14:126/2	START BOOSTER PUMP P-3125B Y-74.2 B3/88	START BOOSTER PUMP P-3125B Y-74.2 HS-3125B1 N14:126/2 (U)
7:0021	----- -----	----- -----	----- -----
		TRANSFER 2B INITIATED	
		Y-43.1	
		N19:3/12 ----- -----	
		STOP BOOSTER PUMP P-3125B & TRANSFER PUMP P-102-SY-02A Y-74.2	
		N19:2/0 ----- -----	
	N14:126/2	- [7]12, /14, 21, 21	
	STOP BOOSTER PUMP P-3125B Y-74.2 HS-3125B2 N14:126/3	START BOOSTER PUMP P-3125B Y-74.2 B3/88	STOP BOOSTER PUMP P-3125B Y-74.2 HS-3125B2 N14:126/3 (U)
7:0022	----- -----	----- -----	----- -----
	N14:126/3	- [7]18, 22, 22	

Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00084

File #7 Y74-Y78 Proj:PLC2

07:48:08 02/19/99

*****
 *ENABLE THE SPEED RAMP REFERENCE WHEN THE CONTROLLER RUN OUTPUT IS ON. WHILE THE REFERENCE IS ENABLED,
 *SCALE THE SPEED REFERENCE
 *AND MOVE THIS DESIRED SPEED INTO THE SPEED REFERENCE RAMP TARGET SETPOINT WORKING REGISTER.
 *****

*****
 *WHEN THE RAMP REFERENCE IS NOT ENABLED, CLEAR (ZERO) THE SPEED REFERENCE RAMP TARGET SETPOINT REGISTER.
 *THIS FUNCTION ENABLES THE
 *REFERENCE TO RAMP DOWN TO A STOP IF THE CONTROLLER HAS THE ABILITY TO STAY ENERGIZED TO A LOW SPEED.
 *****

Hanford Cross Site Transfer System (PCU-2)
SPEED REFERENCE RAMP CALL SEQUENCING
Lockheed Martin Hanford Co.
Page:00085

07:48:08 02/19/99

B3/319

Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00086

File #7 Y74-Y78 Proj:PLC2

07:48:08 02/19/99

N7:314 - [7]27,27,30
 N7:314 - [7]27,27,30
 B3/311 - [7]25,26,27,28,29

*****
 *IF THE SPEED RAMP IS NOT ENABLED, PLACE A ZERO IN THE SPEED REFERENCE CURRENT SETPOINT REGISTER. THIS
 *REGISTER IS THE RAMP OUTPUT
 *OR THE ACTUAL SPEED REFERENCE TO THE CONTROLLER.
 *****

SPEED RAMP
 ENABLE

B3/311
 ---[/]---

RAMP SPEED
 REFERENCE
 CURRENT
 SET POINT

---CLR---
 Clear
 Dest: N7:311
 0

RAMP OUTPUT
 COMMENT COIL

B3/315
 ( )

N7:311 - [7]27,28,29,30,30,31,31,31,31,32
 B3/315 - [7]28

*****
 *JUMP TO THE SPEED RAMP SUBROUTINE CONDITIONALLY WHEN THE RAMP IS ENABLED AND THE RAMP OUTPUT DOES NOT
 *EQUAL ITS INPUT. THE RAMP
 RUNS THE FIRST TIME THESE CONDITIONS ARE MET AND THEN EACH TIME THE RAMP TIMER IS DONE. USE A HISTOGRAM
 *ON THE RAMP DONE BIT TO
 *VERIFY THE RAMP SCAN PERIOD WHEN ADJUSTING THE RAMP TIMER FOR THE DESIRED RAMP PERIOD.
 *****

SPEED RAMP
 ENABLE

B3/311
 ---| |---

PROC SECTION
 SPEED REFERENCE
 RAMP TIMER

T4:10.DN
 ---| |---

PROC SECTION
 SPEED REFERENCE
 RAMP TIMER

---TON---
 Timer On Delay
 Timer: T4:10
 Base (SEC): 0.01
 Preset: 25
 Accum: 0
 ---(-EN)
 ---(-DN)

RAMP SPEED
 REFERENCE
 TARGET
 SET POINT

RAMP SPEED
 REFERENCE
 SET POINT
 DIFFERENCE
 ONE SHOT

START SPEED
 REFERENCE
 RAMP LOGIC

---NEQ---
 Not Equal (A<>B)
 Source A: N7:310
 0
 Source B: N7:311
 0

B3/312
 ---[ONS]---

B3/313
 ( )

PROC SECTION
 SPEED REFERENCE
 RAMP TIMER

T4:10.DN
 ---| |---

T4:10.DN - [7]29,29,29,31
 B3/313 - [7]29,30

Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00087

File #7 Y74-Y78 Proj:PLC2

07:48:09 02/19/99

```

*****
* JUMP TO THE RAMP SUBROUTINE WITH PASSED PARAMETERS:
* INPUT PAR (1): DESIRED OR TARGET SPEED REFERENCE (RAMP INPUT)
* INPUT PAR (2): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
* INPUT PAR (3): MAXIMUM RAMP REFERENCE INCREMENT IN A SINGLE SCAN THROUGH THE SUBROUTINE
* RETURN PAR (1): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
* RETURN PAR (2): DIFFERENCE BETWEEN DESIRED (TARGET) AND ACTUAL (OUTPUT) REFERENCES
* RETURN PAR (3): ABSOLUTE VALUE OF RAMP REFERENCE DIFFERENCE
*****

```

START SPEED
 REFERENCE
 RAMP LOGIC

B3/313

7:0030

```

+---JSR-----+
| Jump To Subroutine |
| File #: U:11      |
| Input Par: N7:310  |
| Input Par: N7:311  |
| Input Par: N7:314  |
| Return Par: N7:311 |
| Return Par: N7:312 |
| Return Par: N7:313 |
+---+

```

RAMP JSR
 EXECUTED
 THIS SCAN

B3/316

( )

```

U:11      - 7|30,[11]0
N7:310    - 7|23,24,29,30
N7:311    - 7|27,28,29,30,30,31,31,31,31,32
N7:314    - 7|27,27,30
N7:311    - 7|27,28,29,30,30,31,31,31,31,32
N7:312    - 7|30
N7:313    - 7|30
B3/316    - 7|30

```

```

*****
* MOVE THE RAMPED SPEED REFERENCE TO THE ACTUAL OUTPUT REGISTER WHICH IS CONNECTED TO THE CONTROLLER.
*****

```


Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00088

File #7 Y74-Y78 Proj:PLC2

07:48:09 02/19/99

7:0031

PID FOR PUMP
 P-3125 A/B
 MANUAL MODE
 HS-3125-M
 N14:126/4

PD16:0.SWM

RAMP SPEED
 REFERENCE
 CURRENT
 SET POINT

B3/299

--[ONS]-

+-MOV-

Move

Source: PD16:0.0UT

930

Dest: N7:311

0

0

+-MUL-

Mul

Source A: N7:311

0

Source B: 22.5

22.5

Dest: PD16:0.S0

0

0

PUMP
 P-3125 A/B
 OUTLET FLOW
 PID SET POINT

+-MOV-

Move

Source: N7:311

0

Dest: PD16:0.SP

0

0

PID FOR PUMP
 P-3125 A/B
 MANUAL MODE
 HS-3125-M
 N14:126/4

PROC SECTION
 SPEED REFERENCE
 RAMP TIMER

PUMP
 P-3125 A/B
 OUTLET FLOW
 PID CONTROL

T4:10.DN

+-PID-

PID

Control Block: PD16:0

Process Variable: N20:16

Tieback: 0

Control Variable: N7:19

PID FOR PUMP
 P-3125 A/B
 MANUAL MODE
 HS-3125-M
 N14:126/4

PUMP P-3125A/B
 OUTLET FLOW /
 DRIVE SPEED
 REF WORKING
 REGISTER

+-MUL-

Mul

Source A: N7:311

0

Source B: 22.5

22.5

Dest: N7:19

0

0

PUMP P-3125A/B
 OUTLET FLOW /

PUMP
 P-3125 A/B

Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00089

File #7 Y74-Y78 Proj:PLC2

07:48:09 02/19/99

DRIVE SPEED REF WORKING REGISTER	OUTLET FLOW / DRIVE SPEED REF OUTPUT FIC-3125-0
+--LES-----+--MOV-----+	
Less Than (A<B)	Move
Source A: N7:19	Source: 0
Source B: 0	Dest: N14:79
0	0
0	0
+-----+-----+	
PUMP P-3125A/B	PUMP
OUTLET FLOW /	P-3125 A/B
DRIVE SPEED	OUTLET FLOW /
REF WORKING	DRIVE SPEED
REGISTER	REF OUTPUT FIC-3125-0
+--GRT-----+--MOV-----+	
Greater Than (A>B)	Move
Source A: N7:19	Source: 3600
Source B: 3600	Dest: N14:79
3600	0
0	0
+-----+-----+	
PUMP P-3125A/B	PUMP
OUTLET FLOW /	P-3125 A/B
DRIVE SPEED	OUTLET FLOW /
REF WORKING	DRIVE SPEED
REGISTER	REF OUTPUT FIC-3125-0
+--LIM-----+--MOV-----+	
Limit Test (Circular)	Move
Low Lim: 0	Source: N7:19
Test: N7:19	Dest: N14:79
High Lim: 3600	0
3600	0
+-----+-----+	
BOOSTER	PUMP P-3125A
PUMP P-3125A	OUTLET FLOW
STARTED	CONTROL
SUCCESSFULLY	SIGNAL
B3/318	VSD-3125A
+--MOV-----+--MOV-----+	
Move	Move
Source: N14:79	Source: N14:79
0	0
Dest: N20:32	Dest: N20:32
0	0
+-----+-----+	
BOOSTER	PUMP P-3125A
PUMP P-3125A	OUTLET FLOW
STARTED	CONTROL
SUCCESSFULLY	SIGNAL
B3/318	VSD-3125A
+--CLR-----+--CLR-----+	
Clear	Clear
Dest: N20:32	Dest: N20:32
0	0
+-----+-----+	
BOOSTER	PUMP P-3125B
PUMP P-3125B	OUTLET FLOW
STARTED	CONTROL
SUCCESSFULLY	SIGNAL
B3/319	VSD-3125B
+--MOV-----+--MOV-----+	
Move	Move
Source: N14:79	Source: N14:79
0	0
Dest: N20:33	Dest: N20:33
0	0
+-----+-----+	
BOOSTER	PUMP P-3125B
PUMP P-3125B	OUTLET FLOW

Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00090

File #7 Y74-Y78 Proj:PLC2

07:48:09 02/19/99

STARTED
 SUCCESSFULLY

CONTROL
 SIGNAL
 VSD-3125B

B3/319

+---CLR

Clear

Dest: N20:33

0

FINAL SPEED
 REFERENCE
 COMMENT COIL

B3/317

( )

```

PD16:0.SWM - 7|31,31,31,31,31,32,32,32
PD16:0.SWM - 7|31,31,31,31,31,32,32,32
N7:311      - 7|27,28,29,30,30,31,31,31,32
N7:311      - 7|27,28,29,30,30,31,31,31,32
PD16:0.SWM - 7|31,31,31,31,31,32,32,32
N7:311      - 7|27,28,29,30,30,31,31,31,32
PD16:0.SWM - 7|31,31,31,31,31,32,32,32
PD16:0.SWM - 7|31,31,31,31,31,32,32,32
N20:16      - 4|9,9,[5],5,[7]31,32
N7:19       - 7|31,31,31,31,31,31,31
N7:311      - 7|27,28,29,30,30,31,31,31,32
N7:19       - 7|31,31,31,31,31,31,31
N14:79      - 5|wf30,[7]31,31,31,31,31
N14:79      - 5|wf30,[7]31,31,31,31,31
N7:19       - 7|31,31,31,31,31,31,31
N14:79      - 5|wf30,[7]31,31,31,31,31
N14:79      - 5|wf30,[7]31,31,31,31,31
N20:32      - 4|13,13,[7]31,31
N20:32      - 4|13,13,[7]31,31
N14:79      - 5|wf30,[7]31,31,31,31,31
N20:33      - 4|wf13,[7]31,31
N20:33      - 4|wf13,[7]31,31
B3/317      - 7|31
  
```

Hanford Cross Site Transfer System (PCU-2)
 SPEED REFERENCE RAMP CALL SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00091

File #7 Y74-Y78 Proj:PLC2

07:48:10 02/19/99

7:0032

PUMP
 P-3125 A/B
 PID CONTROL
 PROP. GAIN
 FROM OIT

---DIV---
 Div
 Source A: N14:141
 80
 Source B: 100.0
 100.0
 Dest: PD16:0.KP
 0.8

PUMP
 P-3125 A/B
 PID CONTROL
 INTEG. GAIN
 FROM OIT

---DIV---
 Div
 Source A: N14:142
 6
 Source B: 100.0
 100.0
 Dest: PD16:0.KI
 0.06

PUMP
 P-3125 A/B
 PID CONTROL
 DERIV. GAIN
 FROM OIT

---DIV---
 Div
 Source A: N14:143
 0
 Source B: 100.0
 100.0
 Dest: PD16:0.KD
 0

PUMP
 P-3125 A/B
 OUTLET FLOW /
 DRIVE SPEED
 LOOP ERROR
 FIC-3125-E

---SUB---
 Sub
 Source A: N7:311
 0
 Source B: N20:16
 0
 Dest: N14:78
 0

N14:141 - [5]wf26,29,[7]32
 PD16:0.SWM - [7]31,31,31,31,31,32,32,32
 N14:142 - [5]wf26,29,[7]32
 PD16:0.SWM - [7]31,31,31,31,31,32,32,32
 N14:143 - [5]wf26,29,[7]32
 PD16:0.SWM - [7]31,31,31,31,31,32,32,32
 N7:311 - [7]27,28,29,30,30,31,31,31,31,32
 N20:16 - [4]9,9,[5]5,[7]31,32
 N14:78 - [5]30,30,[7]32

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00092

File #7 Y74-Y78 Proj:PLC2

07:48:10 02/19/99

	PUMP P-3125A INLET PRESSURE PT-3125A +---GRT---+ Greater Than (A>B) Source A: N20:17 1 Source B: N7:22 70 +---+		BOOSTER PUMP HIGH INLET PRESSURE Y-75.1 PAH-3125A N14:6/3 ( ) PUMP P-3125A HIGH INLET PRESSURE Y-75.1 N19:2/14 ( )
7:0033	N14:6/3 - [7]33 N19:2/14 - [7]33 PUMP P-3125A INLET PRESSURE PT-3125A +---LES---+ Less Than (A<B) Source A: N20:17 1 Source B: N7:24 10 +---+		B3/80 ( ) BOOSTER PUMP P-3125A LOW INLET PRESSURE Y-75.1
7:0034	B3/80 - [7]5,/6,34 PUMP P-3125A OUTLET PRESSURE PT-3125C +---GRT---+ Greater Than (A>B) Source A: N20:19 2 Source B: N7:26 50 +---+		B3/75 ( ) PUMP P-3125A IS RUNNING - ABOVE MINIMUM PRESSURE Y-78.1
7:0035	B3/75 - [7]/3,25,35 PUMP P-3125A OUTLET PRESSURE PT-3125C +---GRT---+ Greater Than (A>B) Source A: N20:19 2 Source B: N7:27 1250 +---+		BOOSTER PUMP HIGH DISCHARGE PRESSURE Y-78.1 PAH-3125C N14:6/2 ( )
7:0036	N14:6/2 - [7]7,36 PUMP P-3125A MOTOR INBOARD BEARING TEMPERATURE TE-3125A1 +---GRT---+ Greater Than (A>B) Source A: N20:2 54 Source B: N7:0 190 +---+		PUMP P-3125A INBOARD BEARING HIGH TEMP. ALARM Y-78.1 TAH-3125A1 N14:6/0 ( )
7:0037			

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING
 Lockheed Martin Hanford Co.

File #7 Y74-Y78 Proj:PLC2

Page:00093

07:48:10 02/19/99

	N14:6/0	- [7]37		
	PUMP P-3125A MOTOR INBOARD BEARING TEMPERATURE TE-3125A1			PUMP P-3125A INBOARD BEARING HIGH TEMP. FAULT Y-76.1
7:0038	+---GRT---+ Greater Than (A>B) Source A: N20:2 54 Source B: N7:2 200 +---+---+			B3/64 ( )
	B3/64	- [7]38,45		
	PUMP P-3125A MOTOR OUTBOARD BEARING TEMPERATURE TE-3125A2			PUMP P-3125A OUTBOARD BEARING HIGH TEMP. ALARM Y-76.1 TAN-3125A2 N14:6/1
7:0039	+---GRT---+ Greater Than (A>B) Source A: N20:3 54 Source B: N7:1 190 +---+---+			( )
	N14:6/1	- [7]39		
	PUMP P-3125A MOTOR OUTBOARD BEARING TEMPERATURE TE-3125A2			PUMP P-3125A OUTBOARD BEARING HIGH TEMP. FAULT Y-76.1
7:0040	+---GRT---+ Greater Than (A>B) Source A: N20:3 54 Source B: N7:3 200 +---+---+			B3/65 ( )
	B3/65	- [7]40,45		
	PUMP P-3125A BEARING VIBRATION VT-3125A1			PUMP P-3125A HIGH MOTOR VIBRATION ALARM Y-76.1 VAH-3125A1 N14:6/6
7:0041	+---GRT---+ Greater Than (A>B) Source A: N20:24 0 Source B: N7:4 30 +---+---+			( )
	N14:6/6	- [7]41		
	PUMP P-3125A BEARING VIBRATION VT-3125A1			PUMP P-3125A HIGH MOTOR VIBRATION FAILURE Y-76.1
7:0042	+---GRT---+ Greater Than (A>B) Source A: N20:24 0 Source B: N7:6 60 +---+---+			B3/66 ( )
	B3/66	- [7]42,45		

Hanford Cross Site Transfer System (PCU-2)
BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING
Lockheed Martin Hanford Co.
Page:00094

File #7 Y74-Y78 Proj:PLC2

07:48:11 02/19/99

	PUMP P-3125A BEARING VIBRATION VT-3125A2		PUMP P-3125A HIGH MOTOR VIBRATION ALARM Y-76.1 VAH-3125A2 N14:6/7
7:0043	+---GRT---+ Greater Than (A>B) Source A: N20:26 0 Source B: N7:5 30 +---+ N14:6/7 - [7]43		( )
	PUMP P-3125A BEARING VIBRATION VT-3125A2		PUMP P-3125A HIGH MOTOR VIBRATION FAILURE Y-76.1
7:0044	+---GRT---+ Greater Than (A>B) Source A: N20:26 0 Source B: N7:7 60 +---+ B3/67 - [7]44,45		B3/67 ( )

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00095

File #7 Y74-Y78 Proj:PLC2

07:48:11 02/19/99

	PUMP P-3125A INBOARD BEARING HIGH TEMP. FAULT Y-76.1	BOOSTER PUMP TROUBLE Y-76.1
7:0045	B3/64 	B3/76 ( )
	PUMP P-3125A OUTBOARD BEARING HIGH TEMP. FAULT Y-76.1	
	B3/65 	
	PUMP P-3125A MOTOR WINDING TEMP. HIGH [OFF = ALARM] Y76	
	TSH-3125A I:025/16 	
	1771-IBD	
	PUMP P-3125A SEAL FAILURE [OFF = ALARM] Y76	
	PSL-3125A1 I:026/17 	
	1771-IBD <i>CW</i>	
	PUMP P-3125A SEAL FAILURE [OFF = ALARM] Y76	
	PSL-3125A2 I:026/13 	
	1771-IBD <i>CW</i>	
	LOW AIR FLOW PUMP SEAL PUMP P-3125A [OFF = ALARM] Y76	
	FSH-3125A1 I:026/00 	
	1771-IBD	
	LOW AIR FLOW PUMP SEAL PUMP P-3125A [OFF = ALARM] Y76	
	FSH-3125A2 I:026/01 	
	1771-IBD	
	PUMP P-3125A LOW OIL LEVEL [OFF = ALARM] Y76	
	LSL-3125A1 I:026/04 	
	1771-IBD	
	PUMP P-3125A LOW OIL LEVEL [OFF = ALARM] Y76	
	LSL-3125A2 I:026/05 	
	1771-IBD	
	PUMP P-3125A HIGH MOTOR VIBRATION FAILURE	

Hanford Cross Site Transfer System (PCU-2)
BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING
Lockheed Martin Hanford Co.
Page:00096

File #7 Y74-Y78 Proj:PLC2

07:48:11 02/19/99

Y-76.1
B3/66
----- -----
PUMP P-3125A HIGH MOTOR VIBRATION FAILURE Y-76.1
B3/67
+----- -----+

B3/76 - [7]7,45

Hanford Cross Site Transfer System (PCU-2)
BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING
Lockheed Martin Hanford Co.

File #7 Y74-Y78 Proj:PLC2

Page: 00097

07:48:11 02/19/99

```

PUMP P-3125B
INLET
PRESSURE
PT-3125B
+-----+
7:0046 | Greater Than (A>B)
        | Source A:      N20:18
        |              1
        | Source B:      N7:23
        |              70

```

BOOSTER
PUMP HIGH
INLET
PRESSURE
Y-75.1
PAH-3125B
N14:7/3

PUMP P-3125B
HIGH INLET
PRESSURE
Y-75.1
N19:2/15

N14:7/3 - [7]46
N19:2/15 - [7]46

```

PUMP P-3125B
INLET
PRESSURE
PT-3125B
+-----+
7:0047 | Less Than (A<B)
        | Source A:  N20:18
        |                               1
        | Source B:  N7:25
        |                               10

```

BOOSTER
PUMP P-3125B
LOW INLET
PRESSURE
Y-75.1

B3/86

B3/86 - [7]16, 17, 47

```

PUMP P-3125B
OUTLET
PRESSURE
PT-3125D
+-----+
7:0048 | Greater Than (A>B)
      | Source A:      N20:20
      |              3
      | Source B:      N7:28
      |              50

```

PUMP P-3125B
IS RUNNING -
ABOVE MINIMUM
PRESSURE
Y-78.1

B3/81

83/81 - [7]/14, 26, 48

```

PUMP P-3125B
OUTLET
PRESSURE
PT-3125D
+---GR-----+
7:0049 | Greater Than (A>B)
        | Source A:      N20:20
        |               3
        | Source B:      N7:29
        |               1250

```

BOOSTER
PUMP HIGH
DISCHARGE
PRESSURE
Y-78.1
PAH-3125D
N14:7/2

N14:7/2 - [7]18.49

```

PUMP P-3125B
MOTOR INBOARD
BEARING
TEMPERATURE
TE-3125B1
+---GRT-----+
7:0050 | Greater Than (A>B)
        | Source A: N20:0
        |                    54
        | Source B: N7:11
        |                    190

```

PUMP P-3125B
INBOARD
BEARING HIGH
TEMP. ALARM
Y-76.1
TAH-3125B1
N14:7/0

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00098

File #7 Y74-Y78 Proj:PLC2

07:48:11 02/19/99

	N14:7/0	- [7]50		
	PUMP P-3125B MOTOR INBOARD BEARING TEMPERATURE TE-3125B1			PUMP P-3125B INBOARD BEARING HIGH TEMP. FAULT Y-76.1
7:0051	Greater Than (A>B) Source A: N20:1 54 Source B: N7:13 200			B3/68 ( )
	B3/68	- [7]51,58		
	PUMP P-3125B MOTOR OUTBOARD BEARING TEMPERATURE TE-3125B2			PUMP P-3125B OUTBOARD BEARING HIGH TEMP. ALARM Y-76.1 TAH-3125B2 N14:7/1
7:0052	Greater Than (A>B) Source A: N20:1 54 Source B: N7:12 190			( )
	N14:7/1	- [7]52		
	PUMP P-3125B MOTOR OUTBOARD BEARING TEMPERATURE TE-3125B2			PUMP P-3125B OUTBOARD BEARING HIGH TEMP. FAULT Y-76.1
7:0053	Greater Than (A>B) Source A: N20:1 54 Source B: N7:14 200			B3/69 ( )
	B3/69	- [7]53,58		
	PUMP P-3125B BEARING VIBRATION VT-3125B1			PUMP P-3125B HIGH MOTOR VIBRATION ALARM Y-76.1 VAH-3125B1 N14:7/6
7:0054	Greater Than (A>B) Source A: N20:25 0 Source B: N7:15 30			( )
	N14:7/6	- [7]54		
	PUMP P-3125B BEARING VIBRATION VT-3125B1			PUMP P-3125B HIGH MOTOR VIBRATION FAILURE Y-76.1
7:0055	Greater Than (A>B) Source A: N20:25 0 Source B: N7:17 60			B3/70 ( )
	B3/70	- [7]55,58		

Hanford Cross Site Transfer System (PCU-2)
BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING
Lockheed Martin Hanford Co.
Page:00099

File #7 Y74-Y78 Proj:PLC2

07:48:11 02/19/99

	PUMP P-3125B-2 BEARING VIBRATION VT-3125B2	PUMP P-3125B HIGH MOTOR VIBRATION ALARM Y-76.1 VAH-3125B2 N14:7/7
7:0056	+---GRT---+ Greater Than (A>B) Source A: N20:27 0 Source B: N7:16 30 +---+ N14:7/7 - [7]56	( )
	PUMP P-3125B-2 BEARING VIBRATION VT-3125B2	PUMP P-3125B HIGH MOTOR VIBRATION FAILURE Y-76.1
7:0057	+---GRT---+ Greater Than (A>B) Source A: N20:27 0 Source B: N7:18 60 +---+ B3/71 - [7]57,58	B3/71 ( )

Hanford Cross Site Transfer System (PCU-2)
 BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00100

File #7 Y74-Y78 Proj:PLC2

07:48:12 02/19/99

	PUMP P-3125B INBOARD BEARING HIGH TEMP. FAULT Y-76.1	BOOSTER PUMP TROUBLE Y-76.1
7:0058	B3/68 ----- ----- PUMP P-3125B OUTBOARD BEARING HIGH TEMP. FAULT Y-76.1	B3/82 ----- ----- ( )
	B3/69 ----- ----- PUMP P-3125B MOTOR WINDING TEMP. HIGH [OFF = ALARM] Y76 TSH-3125B I:025/17 ----- / ----- 1771-IBD PUMP P-3125B SEAL FAILURE [OFF = ALARM] Y76 PSL-3125B1 I:026/14 ----- / ----- 1771-IBD <i>CW</i> PUMP P-3125AB SEAL FAILURE [OFF = ALARM] Y76 PSL-3125B2 I:026/15 ----- / ----- 1771-IBD <i>CW</i> LOW AIR FLOW PUMP SEAL PUMP P-3125B [OFF = ALARM] Y76 FSH-3125B1 I:026/02 ----- / ----- 1771-IBD LOW AIR FLOW PUMP SEAL PUMP P-3125B [OFF = ALARM] Y76 FSH-3125B2 I:026/03 ----- / ----- 1771-IBD PUMP P-3125B LOW OIL LEVEL [OFF = ALARM] Y76 LSL-3125B1 I:026/06 ----- / ----- 1771-IBD PUMP P-3125B LOW OIL LEVEL [OFF = ALARM] Y76 LSL-3125B2 I:026/07 ----- / ----- 1771-IBD PUMP P-3125B HIGH MOTOR VIBRATION FAILURE	

Hanford Cross Site Transfer System (PCU-2)
BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING
Lockheed Martin Hanford Co.
Page:00101

File #7 Y74-Y78 Proj:PLC2

07:48:12 02/19/99

Y-76.1

B3/70

PUMP P-3125B
HIGH MOTOR
VIBRATION
FAILURE
Y-76.1

B3/71

B3/82

- [7]18,58

7:0059

+--RET-----+
|Return ()|
+-----+

7:0060

-[End]-

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00102

File #8 Y79-Y80 Proj:PLC2

07:48:12 02/19/99

		PROGRAM FILE#8 START OF SUBROUTINE COMMENT COIL	
		B3/43 ( )	
8:0000	+---SBR---+ Subroutine +-----+		
B3/43 - [8]0			
OPEN VALVE MOV-3125AA Y-79.1 HS-3125AA1 N14:126/6		OPEN VALVE MOV-3125AA Y79-1 MOV-3125AA-0 0:034/00	
8:0001	+-----+ +-----+	+-----+ +-----+	+-----+ +-----+
OPEN VALVE MOV-3125AA Y79-1 MOV-3125AA-0 0:034/00 1771-0D1		CLOSE VALVE MOV-3125AA Y-79.1 HS-3125AA2 N14:126/7	OPEN VALVE MOV-3125AA Y-79.1 HS-3125AA1 N14:126/6 (U)
0:034/000 - [8]1,1,1/2 N14:126/6 - [8]1,1			
OPEN VALVE MOV-3125AA Y79-1 MOV-3125AA-0 0:034/00 1771-0D1		CLOSE VALVE MOV-3125AA Y-79.1 HS-3125AA2 N14:126/7	CLOSE VALVE MOV-3125AA Y-79.1 HS-3125AA2 N14:126/7 (U)
8:0002	+-----+ +-----+	+-----+ +-----+	+-----+ +-----+
N14:126/7 - [8]1,1,2,2 0:034/001 - [8]2		CLOSE VALVE MOV-3125AA Y79-1 MOV-3125AA-C 0:034/01 771-0D16	
OPEN VALVE MOV-3125AB Y-79.1 HS-3125AB1 N14:126/8		OPEN VALVE MOV-3125AB Y79-1 MOV-3125AB-0 0:034/02	
8:0003	+-----+ +-----+	+-----+ +-----+	+-----+ +-----+
OPEN VALVE MOV-3125AB Y79-1 MOV-3125AB-0 0:034/02 1771-0D1		CLOSE VALVE MOV-3125AB Y-79.1 HS-3125AB2 N14:126/9	OPEN VALVE MOV-3125AB Y-79.1 HS-3125AB1 N14:126/8 (U)
0:034/002 - [8]3,3,1/4 N14:126/8 - [8]3,3			

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00103

File #8 Y79-Y80 Proj:PLC2

07:48:12 02/19/99

	OPEN VALVE MOV-3125AB Y79-1 MOV-3125AB-0 0:034/02 1771-0D1		CLOSE VALVE MOV-3125AB Y-79.1 HS-3125AB2 N14:126/9	CLOSE VALVE MOV-3125AB Y-79.1 HS-3125AB2 N14:126/9
8:0004	1771-0D1		1771-0D1	(U)
	N14:126/9 - [8]/3,4,4 0:034/003 - [8]4 OPEN VALVE MOV-3125AC Y-79.1 HS-3125AC1 N14:126/10		CLOSE VALVE MOV-3125AB Y79-1 MOV-3125AB-C 0:034/03 771-0D16	
	N14:126/9 - [8]/3,4,4 0:034/003 - [8]4 OPEN VALVE MOV-3125AC Y-79.1 HS-3125AC1 N14:126/10			OPEN VALVE MOV-3125AC Y79-1 MOV-3125AC-0 0:034/04
8:0005	1771-0D1		1771-0D16	(U)
	OPEN VALVE MOV-3125AC Y79-1 MOV-3125AC-0 0:034/04 1771-0D1	CLOSE VALVE MOV-3125AC Y-79.1 HS-3125AC2 N14:126/11		OPEN VALVE MOV-3125AC Y-79.1 HS-3125AC1 N14:126/10 (U)
	0:034/004 - [8]5,5,6 N14:126/10 - [8]5,5 OPEN VALVE MOV-3125AC Y79-1 MOV-3125AC-0 0:034/04		CLOSE VALVE MOV-3125AC Y-79.1 HS-3125AC2 N14:126/11	CLOSE VALVE MOV-3125AC Y-79.1 HS-3125AC2 N14:126/11
8:0006	1771-0D1		1771-0D16	(U)
	N14:126/11 - [8]/5,6,6 0:034/005 - [8]6 OPEN VALVE MOV-3125AD Y-79.1 HS-3125AD1 N14:126/12		CLOSE VALVE MOV-3125AC Y79-1 MOV-3125AC-C 0:034/05 771-0D16	
	N14:126/11 - [8]/5,6,6 0:034/005 - [8]6 OPEN VALVE MOV-3125AD Y-79.1 HS-3125AD1 N14:126/12			OPEN VALVE MOV-3125AD Y79-1 MOV-3125AD-0 0:034/06
8:0007	1771-0D1		1771-0D16	(U)
	OPEN VALVE MOV-3125AD Y79-1 MOV-3125AD-0 0:034/06 1771-0D1	CLOSE VALVE MOV-3125AD Y-79.1 HS-3125AD2 N14:126/13		OPEN VALVE MOV-3125AD Y-79.1 HS-3125AD1 N14:126/12 (U)

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
 Lockheed Martin Hanford Co.

File #8 Y79-Y80 Proj:PLC2

Page:00104

07:48:12 02/19/99

8:0008	0:034/006 - [8]7,7,/8 N14:126/12 - [8]7,7 OPEN VALVE MOV-3125AD Y79-1 MOV-3125AD-0 0:034/06 --- / --- 1771-0D1		CLOSE VALVE MOV-3125AD Y-79.1 HS-3125AD2 N14:126/13 --- ---(U)--- CLOSE VALVE MOV-3125AD Y79-1 MOV-3125AD-C 0:034/07 --- ---(U)--- 771-0D16
8:0009	N14:126/13 - [8]7,8,8 0:034/007 - [8]8 OPEN VALVE MOV-3125AE Y-79.1 HS-3125AE1 N14:126/14 --- / --- 1771-0D1	CLOSE VALVE MOV-3125AE Y-79.1 HS-3125AE2 N14:126/15 --- / ---	OPEN VALVE MOV-3125AE Y79-1 MOV-3125AE-0 0:034/10 --- ---(U)--- 771-0D16 OPEN VALVE MOV-3125AE Y-79.1 HS-3125AE1 N14:126/14 --- ---(U)---
8:0010	0:034/010 - [8]9,9,/10 N14:126/14 - [8]9,9 OPEN VALVE MOV-3125AE Y79-1 MOV-3125AE-0 0:034/10 --- / --- 1771-0D1		CLOSE VALVE MOV-3125AE Y-79.1 HS-3125AE2 N14:126/15 --- ---(U)--- CLOSE VALVE MOV-3125AE Y79-1 MOV-3125AE-C 0:034/11 --- ---(U)--- 771-0D16

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00105

File #8 Y79-Y80 Proj:PLC2

07:48:12 02/19/99

	OPEN VALVE MOV-3125AF Y-79.1 HS-3125AF1 N14:127/0			OPEN VALVE MOV-3125AF Y79-1 MOV-3125AF-0 0:034/12
8:0011	--- --- ---			--- --- ---
	OPEN VALVE MOV-3125AF Y79-1 MOV-3125AF-0 0:034/12 1771-0D1	CLOSE VALVE MOV-3125AF Y-79.1 HS-3125AF2 N14:127/1		OPEN VALVE MOV-3125AF Y-79.1 HS-3125AF1 N14:127/0 (U)
	--- --- ---	--- --- ---		--- --- ---
	0:034/012 - [8]11,11,12 N14:127/0 - [8]11,11			
	OPEN VALVE MOV-3125AF Y79-1 MOV-3125AF-0 0:034/12 1771-0D1		CLOSE VALVE MOV-3125AF Y-79.1 HS-3125AF2 N14:127/1	CLOSE VALVE MOV-3125AF Y-79.1 HS-3125AF2 N14:127/1 (U)
8:0012	--- --- ---		--- --- ---	--- --- ---
			CLOSE VALVE MOV-3125AF Y79-1 MOV-3125AF-C 0:034/13 771-0D16	--- --- ---
	N14:127/1 - [8]11,11,12,12 0:034/013 - [8]12			
	OPEN VALVE MOV-3125AG Y-79.1 HS-3125AG1 N14:127/2			OPEN VALVE MOV-3125AG Y79-1 MOV-3125AG-0 0:034/14
8:0013	--- --- ---			--- --- ---
	OPEN VALVE MOV-3125AG Y79-1 MOV-3125AG-0 0:034/14 1771-0D1	CLOSE VALVE MOV-3125AG Y-79.1 HS-3125AG2 N14:127/3		OPEN VALVE MOV-3125AG Y-79.1 HS-3125AG1 N14:127/2 (U)
	--- --- ---	--- --- ---		--- --- ---
	0:034/014 - [8]13,13,14 N14:127/2 - [8]13,13			
	OPEN VALVE MOV-3125AG Y79-1 MOV-3125AG-0 0:034/14 1771-0D1		CLOSE VALVE MOV-3125AG Y-79.1 HS-3125AG2 N14:127/3	CLOSE VALVE MOV-3125AG Y-79.1 HS-3125AG2 N14:127/3 (U)
8:0014	--- --- ---		--- --- ---	--- --- ---
			CLOSE VALVE MOV-3125AG Y79-1 MOV-3125AG-C 0:034/15 771-0D16	--- --- ---

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00106

File #8 Y79-Y80 Proj:PLC2

07:48:13 02/19/99

	N14:127/3 - [8]/13,14,14 0:034/015 - [8]14				OPEN VALVE MOV-3125AH	OPEN VALVE MOV-3125AH
	OPEN VALVE MOV-3125AH					
	Y-79.1 HS-3125AH1 N14:127/4					Y79-1 MOV-3125AH-0 0:034/16 --( )--
8:0015	OPEN VALVE MOV-3125AH	CLOSE VALVE MOV-3125AH				771-0D16 OPEN VALVE MOV-3125AH
	Y79-1 MOV-3125AH-0 0:034/16	Y-79.1 HS-3125AH2 N14:127/5				Y-79.1 HS-3125AH1 N14:127/4 --(U)--
	1771-0D1					
	0:034/016 - [8]15,15,16 N14:127/4 - [8]15,15					
	OPEN VALVE MOV-3125AH				CLOSE VALVE MOV-3125AH	CLOSE VALVE MOV-3125AH
	Y79-1 MOV-3125AH-0 0:034/16	Y-79.1 HS-3125AH2 N14:127/5			Y-79.1 HS-3125AH2 N14:127/5	Y-79.1 HS-3125AH2 N14:127/5 --(U)--
8:0016	1771-0D1					
					CLOSE VALVE MOV-3125AH	
					Y79-1 MOV-3125AH-C 0:034/17 --( )-- 771-0D16	
	N14:127/5 - [8]/15,16,16 0:034/017 - [8]16					
	OPEN VALVE MOV-3125AJ					OPEN VALVE MOV-3125AJ
	Y-79.2 HS-3125AJ1 N14:127/6					Y79-2 MOV-3125AJ-0 0:035/00 --( )--
8:0017	OPEN VALVE MOV-3125AJ	CLOSE VALVE MOV-3125AJ				771-0D16 OPEN VALVE MOV-3125AJ
	Y79-2 MOV-3125AJ-0 0:035/00	Y-79.2 HS-3125AJ2 N14:127/7				Y-79.2 HS-3125AJ1 N14:127/6 --(U)--
	1771-0D1					
	0:035/000 - [8]17,17,18 N14:127/6 - [8]17,17					

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00107

File #8 Y79-Y80 Proj:PLC2

07:48:13 02/19/99

	OPEN VALVE MOV-3125AJ Y79-2 MOV-3125AJ-0 0:035/00 1771-0D1	CLOSE VALVE MOV-3125AJ Y-79.2 HS-3125AJ2 N14:127/7 (U)
8:0018		
	N14:127/7 - [8]/17,18,18 0:035/001 - [8]18 OPEN VALVE MOV-3125AK Y-79.2 HS-3125AK1 N14:127/8	CLOSE VALVE MOV-3125AJ Y79-2 MOV-3125AJ-C 0:035/01 ( ) 771-0D16
	OPEN VALVE MOV-3125AK Y-79.2 HS-3125AK1 N14:127/8	OPEN VALVE MOV-3125AK Y79-2 MOV-3125AK-0 0:035/02 ( ) 771-0D16
8:0019		
	OPEN VALVE MOV-3125AK Y79-2 MOV-3125AK-0 0:035/02 1771-0D1	CLOSE VALVE MOV-3125AK Y-79.2 HS-3125AK2 N14:127/9 (U)
	0:035/002 - [8]19,19,/20 N14:127/8 - [8]19,19 OPEN VALVE MOV-3125AK Y79-2 MOV-3125AK-0 0:035/02 1771-0D1	CLOSE VALVE MOV-3125AK Y-79.2 HS-3125AK2 N14:127/9 (U)
	OPEN VALVE MOV-3125AK Y79-2 MOV-3125AK-0 0:035/02 1771-0D1	CLOSE VALVE MOV-3125AK Y79-2 MOV-3125AK-C 0:035/03 ( ) 771-0D16
8:0020		
	N14:127/9 - [8]/19,20,20 0:035/003 - [8]20	

Hanford Cross Site Transfer System (PCU-2)
SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
Lockheed Martin Hanford Co.
Page:00108

File #8 Y79-Y80 Proj:PLC2

07:48:13 02/19/99

	OPEN VALVE MOV-3125BA		OPEN VALVE MOV-3125BA
	Y-80.1 HS-3125BA1 N14:129/6		Y80-1 MOV-3125BA-0 0:033/00
8:0021	OPEN VALVE MOV-3125BA	CLOSE VALVE MOV-3125BA	771-0D16 OPEN VALVE MOV-3125BA
	Y80-1 MOV-3125BA-0 0:033/00	Y-80.1 HS-3125BA2 N14:129/7	Y-80.1 HS-3125BA1 N14:129/6 (U)
	1771-0D1		
	0:033/000 - [8]21,21, /22		
	N14:129/6 - [8]21,21		
	OPEN VALVE MOV-3125BA	CLOSE VALVE MOV-3125BA	CLOSE VALVE MOV-3125BA
	Y80-1 MOV-3125BA-0 0:033/00	Y-80.1 HS-3125BA2 N14:129/7	Y-80.1 HS-3125BA2 N14:129/7 (U)
8:0022	1771-0D1	CLOSE VALVE MOV-3125BA	
		Y80-1 MOV-3125BA-C 0:033/01 (U)	
		771-0D16	
	N14:129/7 - [8] /21,22,22		
	0:033/001 - [8]22		
	OPEN VALVE MOV-3125BB		OPEN VALVE MOV-3125BB
	Y-80.1 HS-3125BB1 N14:129/8		Y80-1 MOV-3125BB-0 0:033/02
8:0023	OPEN VALVE MOV-3125BB	CLOSE VALVE MOV-3125BB	771-0D16 OPEN VALVE MOV-3125BB
	Y80-1 MOV-3125BB-0 0:033/02	Y-80.1 HS-3125BB2 N14:129/9	Y-80.1 HS-3125BB1 N14:129/8 (U)
	1771-0D1		
	0:033/002 - [8]23,23, /24		
	N14:129/8 - [8]23,23		
	OPEN VALVE MOV-3125BB	CLOSE VALVE MOV-3125BB	CLOSE VALVE MOV-3125BB
	Y80-1 MOV-3125BB-0 0:033/02	Y-80.1 HS-3125BB2 N14:129/9	Y-80.1 HS-3125BB2 N14:129/9 (U)
8:0024	1771-0D1	CLOSE VALVE MOV-3125BB	
		Y80-1 MOV-3125BB-C 0:033/03 (U)	
		771-0D16	

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00109

File #8 Y79-Y80 Proj:PLC2

07:48:13 02/19/99

	N14:129/9 - [8]23,24,24 0:033/003 - [8]24		
	OPEN VALVE MOV-3125BC		OPEN VALVE MOV-3125BC
	Y-80.1 HS-3125BC1 N14:129/10		Y80-1 MOV-3125BC-0 0:033/04 --- ( ) ---
8:0025	+-----+-----+		+-----+-----+
	OPEN VALVE MOV-3125BC	CLOSE VALVE MOV-3125BC	771-0D16 OPEN VALVE MOV-3125BC
	Y80-1 MOV-3125BC-0 0:033/04 ----- 1771-0D1	Y-80.1 HS-3125BC2 N14:129/11 ----- 1771-0D1	Y-80.1 HS-3125BC1 N14:129/10 ----- (U)
	0:033/004 - [8]25,25, /26 N14:129/10 - [8]25,25		
	OPEN VALVE MOV-3125BC		CLOSE VALVE MOV-3125BC CLOSE VALVE MOV-3125BC
	Y80-1 MOV-3125BC-0 0:033/04 ----- 1771-0D1		Y-80.1 HS-3125BC2 N14:129/11 ----- (U)
8:0026	+-----+-----+		+-----+-----+
			CLOSE VALVE MOV-3125BC Y80-1 MOV-3125BC-C 0:033/05 ----- 771-0D16
	N14:129/11 - [8]25,26,26 0:033/005 - [8]26		
	OPEN VALVE MOV-3125BD		OPEN VALVE MOV-3125BD
	Y-80.1 HS-3125BD1 N14:129/12		Y80-1 MOV-3125BD-0 0:033/06 --- ( ) ---
8:0027	+-----+-----+		+-----+-----+
	OPEN VALVE MOV-3125BD	CLOSE VALVE MOV-3125BD	771-0D16 OPEN VALVE MOV-3125BD
	Y80-1 MOV-3125BD-0 0:033/06 ----- 1771-0D1	Y-80.1 HS-3125BD2 N14:129/13 ----- 1771-0D1	Y-80.1 HS-3125BD1 N14:129/12 ----- (U)
	0:033/006 - [8]27,27, /28 N14:129/12 - [8]27,27		

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00110

File #8 Y79-Y80 Proj:PLC2

07:48:14 02/19/99

8:0028	OPEN VALVE MOV-3125BD Y80-1 MOV-3125BD-0 0:033/06 1771-0D1		CLOSE VALVE MOV-3125BD Y-80.1 HS-3125BD2 N14:129/13	CLOSE VALVE MOV-3125BD Y-80.1 HS-3125BD2 N14:129/13
				(U)
8:0029	N14:129/13 - [8]/27,28,28 0:033/007 - [8]28 OPEN VALVE MOV-3125BE Y-80.1 HS-3125BE1 N14:129/14			OPEN VALVE MOV-3125BE Y80-1 MOV-3125BE-0 0:033/10 771-0D16
	OPEN VALVE MOV-3125BE Y80-1 MOV-3125BE-0 0:033/10 1771-0D1	CLOSE VALVE MOV-3125BE Y-80.1 HS-3125BE2 N14:129/15		OPEN VALVE MOV-3125BE Y-80.1 HS-3125BE1 N14:129/14 (U)
8:0030	0:033/010 - [8]29,29, /30 N14:129/14 - [8]29,29 OPEN VALVE MOV-3125BE Y80-1 MOV-3125BE-0 0:033/10 1771-0D1		CLOSE VALVE MOV-3125BE Y-80.1 HS-3125BE2 N14:129/15	CLOSE VALVE MOV-3125BE Y-80.1 HS-3125BE2 N14:129/15 (U)
				CLOSE VALVE MOV-3125BE Y80-1 MOV-3125BE-C 0:033/11 771-0D16
8:0031	N14:129/15 - [8]/29,30,30 0:033/011 - [8]30 OPEN VALVE MOV-3125BF Y-80.1 HS-3125BF1 N14:130/0			OPEN VALVE MOV-3125BF Y80-1 MOV-3125BF-0 0:033/12 771-0D16
	OPEN VALVE MOV-3125BF Y80-1 MOV-3125BF-0 0:033/12 1771-0D1	CLOSE VALVE MOV-3125BF Y-80.1 HS-3125BF2 N14:130/1		OPEN VALVE MOV-3125BF Y-80.1 HS-3125BF1 N14:130/0 (U)

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00111

File #8 Y79-Y80 Proj:PLC2

07:48:14 02/19/99

8:0032	0:033/012 - [8]31,31,/32 N14:130/0 - [8]31,31		
	OPEN VALVE MOV-3125BF	CLOSE VALVE MOV-3125BF	CLOSE VALVE MOV-3125BF
	Y80-1 MOV-3125BF-0 0:033/12 --- / --- 1771-0D1	Y-80.1 HS-3125BF2 N14:130/1	Y-80.1 HS-3125BF2 N14:130/1 ---(U)---
		CLOSE VALVE MOV-3125BF	
8:0033	N14:130/1 - [8]/31,32,32 0:033/013 - [8]32		
	OPEN VALVE MOV-3125BG		OPEN VALVE MOV-3125BG
	Y-80.1 HS-3125BG1 N14:130/2 --- / ---		Y80-1 MOV-3125BG-0 0:033/14 ---( )---
			771-0D16
	OPEN VALVE MOV-3125BG	CLOSE VALVE MOV-3125BG	OPEN VALVE MOV-3125BG
	Y80-1 MOV-3125BG-0 0:033/14 --- / ---	Y-80.1 HS-3125BG2 N14:130/3 --- / ---	Y-80.1 HS-3125BG1 N14:130/2 ---(U)---
	1771-0D1		
8:0034	0:033/014 - [8]33,33,/34 N14:130/2 - [8]33,33		
	OPEN VALVE MOV-3125BG	CLOSE VALVE MOV-3125BG	CLOSE VALVE MOV-3125BG
	Y80-1 MOV-3125BG-0 0:033/14 --- / ---	Y-80.1 HS-3125BG2 N14:130/3	Y-80.1 HS-3125BG2 N14:130/3 ---(U)---
	1771-0D1	CLOSE VALVE MOV-3125BG	
	N14:130/3 - [8]/33,34,34 0:033/015 - [8]34		

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
 Lockheed Martin Hanford Co.

File #8 Y79-Y80 Proj:PLC2

Page:00112

07:48:14 02/19/99

	OPEN VALVE MOV-3125BH		OPEN VALVE MOV-3125BH
	Y-80.1 HS-3125BH1 N14:130/4		Y80-1 MOV-3125BH-0 0:033/16
8:0035	OPEN VALVE MOV-3125BH	CLOSE VALVE MOV-3125BH	771-0D16 OPEN VALVE MOV-3125BH
	Y80-1 MOV-3125BH-0 0:033/16	Y-80.1 HS-3125BH2 N14:130/5	Y-80.1 HS-3125BH1 N14:130/4 (U)
	1771-0D1		
	0:033/016 - [8]35,35,136 N14:130/4 - [8]35,35		
	OPEN VALVE MOV-3125BH	CLOSE VALVE MOV-3125BH	CLOSE VALVE MOV-3125BH
	Y80-1 MOV-3125BH-0 0:033/16	Y-80.1 HS-3125BH2 N14:130/5	Y-80.1 HS-3125BH2 N14:130/5 (U)
8:0036	1771-0D1	CLOSE VALVE MOV-3125BH	
		Y80-1 MOV-3125BH-C 0:033/17 (U)	771-0D16
	N14:130/5 - [8]35,36,36 0:033/017 - [8]36		
	OPEN VALVE MOV-3125BJ		OPEN VALVE MOV-3125BJ
	Y-80.2 HS-3125BJ1 N14:130/6		Y80-2 MOV-3125BJ-0 0:035/04 (U)
8:0037	OPEN VALVE MOV-3125BJ	CLOSE VALVE MOV-3125BJ	771-0D16 OPEN VALVE MOV-3125BJ
	Y80-2 MOV-3125BJ-0 0:035/04	Y-80.2 HS-3125BJ2 N14:130/7	Y-80.2 HS-3125BJ1 N14:130/6 (U)
	1771-0D1		
	0:035/004 - [8]37,37,138 N14:130/6 - [8]37,37		
	OPEN VALVE MOV-3125BJ	CLOSE VALVE MOV-3125BJ	CLOSE VALVE MOV-3125BJ
	Y80-2 MOV-3125BJ-0 0:035/04	Y-80.2 HS-3125BJ2 N14:130/7	Y-80.2 HS-3125BJ2 N14:130/7 (U)
8:0038	1771-0D1	CLOSE VALVE MOV-3125BJ	
		Y80-2 MOV-3125BJ-C 0:035/05 (U)	771-0D16

Hanford Cross Site Transfer System (PCU-2)
 SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES
 Lockheed Martin Hanford Co.
 Page:00113

File #8 Y79-Y80 Proj:PLC2

07:48:14 02/19/99

	N14:130/7 - [8]/37,38,38 0:035/005 - [8]38			
	OPEN VALVE MOV-3125BK			OPEN VALVE MOV-3125BK
	Y-80.2 HS-3125BK1 N14:130/8			Y80-2 MOV-3125BK-0 0:035/06
8:0039				---( )---
	OPEN VALVE MOV-3125BK	CLOSE VALVE MOV-3125BK		771-0D16 OPEN VALVE MOV-3125BK
	Y80-2 MOV-3125BK-0 0:035/06	Y-80.2 HS-3125BK2 N14:130/9		Y-80.2 HS-3125BK1 N14:130/8
	--- ---	- / ---		---(U)---
	1771-0D1			
	0:035/006 - [8]39,39,140			
	N14:130/8 - [8]39,39			
	OPEN VALVE MOV-3125BK		CLOSE VALVE MOV-3125BK	CLOSE VALVE MOV-3125BK
	Y80-2 MOV-3125BK-0 0:035/06		Y-80.2 HS-3125BK2 N14:130/9	Y-80.2 HS-3125BK2 N14:130/9
8:0040	--- ---			---(U)---
	1771-0D1			
			CLOSE VALVE MOV-3125BK	
			Y80-2 MOV-3125BK-C 0:035/07	
			---( )---	771-0D16
	N14:130/9 - [8]/39,40,40			
	0:035/007 - [8]40			

Hanford Cross Site Transfer System (PCU-2)
SEQUENCING FOR THE COMMON DRAIN VALVE AND BOOSTER PUMP INTERLOCKS
Lockheed Martin Hanford Co.

File #8 Y79-Y80 Proj:PLC2

Page:00114

07:48:14 02/19/99

	OPEN VALVE MOV-3163								OPEN VALVE SOV-3163
	Y-79.2 HS-3163-1 N14:127/10								Y80-2 SOV-3163-0 0:036/14
8:0041	-----								( ) 771-0D16
	OPEN VALVE SOV-3163	CLOSE VALVE MOV-3163						OPEN VALVE MOV-3163	
	Y80-2 SOV-3163-0 0:036/14	Y-79.2 HS-3163-2 N14:127/11						Y-79.2 HS-3163-1 N14:127/10	
	-----								(U)
	1771-0D1								
	0:036/014 - [8]41,41,42 N14:127/10 - [8]41,41								
	OPEN VALVE SOV-3163							CLOSE VALVE MOV-3163	CLOSE VALVE MOV-3163
	Y80-2 SOV-3163-0 0:036/14							Y-79.2 HS-3163-2 N14:127/11	Y-79.2 HS-3163-2 N14:127/11
8:0042	-----								(U)
	1771-0D1							CLOSE VALVE SOV-3163	
								Y80-2 SOV-3163-C 0:036/15	
								771-0D16	
	N14:127/11 - [8]41,42,42 0:036/015 - [8]42								
	MOV-3125AA IS CLOSED	MOV-3125AB IS CLOSED	MOV-3125AC IS CLOSED	MOV-3125AD IS CLOSED	MOV-3125AE IS CLOSED	MOV-3125AF IS CLOSED	MOV-3125AG IS CLOSED	MOV-3125AH IS CLOSED	MOV-3125AI IS CLOSED
	Y80-1 ZSL-3125AA I:022/01	Y80-1 ZSL-3125AB I:022/03	Y80-1 ZSL-3125AC I:022/05	Y80-1 ZSL-3125AD I:022/07	Y80-1 ZSL-3125AE I:022/11	Y80-1 ZSL-3125AF I:022/13	Y80-1 ZSL-3125AG I:022/15	Y80-1 ZSL-3125AH I:022/17	Y80-1 ZSL-3125AI I:022/19
8:0043	-----								
AH	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD
D	MOV-3125AJ IS CLOSED	MOV-3125AK IS CLOSED	SOV-3163 IS CLOSED	BOOSTER PUMP P-3125A DRAIN VALVES ALL CLOSED					
	Y80-2 ZSL-3125AJ I:023/01	Y80-2 ZSL-3125AK I:023/03	Y-80.2 ZSL-3163 I:024/15	B3/73					
AH	-----								
17	1771-1BD	1771-1BD	1771-1BD	( )					
BD	-----								
	B3/73	- [7]/7,[8]43							
	MOV-3125BA IS CLOSED	MOV-3125BB IS CLOSED	MOV-3125BC IS CLOSED	MOV-3125BD IS CLOSED	MOV-3125BE IS CLOSED	MOV-3125BF IS CLOSED	MOV-3125BG IS CLOSED	MOV-3125BH IS CLOSED	MOV-3125BI IS CLOSED
	Y81-1 ZSL-3125BA I:020/01	Y81-1 ZSL-3125BB I:020/03	Y81-1 ZSL-3125BC I:020/05	Y81-1 ZSL-3125BD I:020/07	Y81-1 ZSL-3125BE I:020/11	Y81-1 ZSL-3125BF I:020/13	Y81-1 ZSL-3125BG I:020/15	Y81-1 ZSL-3125BH I:020/17	Y81-1 ZSL-3125BI I:020/19
8:0044	-----								
BH	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD	1771-1BD
D	MOV-3125BJ IS CLOSED	MOV-3125BK IS CLOSED	SOV-3163 IS CLOSED	BOOSTER PUMP P-3125B DRAIN VALVES ALL CLOSED					
	Y81-2 ZSL-3125BJ I:021/01	Y81-2 ZSL-3125BK I:021/03	Y-80.2 ZSL-3163 I:024/15	B3/74					
BH	-----								
17	1771-1BD	1771-1BD	1771-1BD	( )					
BD	-----								

Hanford Cross Site Transfer System (PCU-2)
SEQUENCING FOR THE COMMON DRAIN VALVE AND BOOSTER PUMP INTERLOCKS
Lockheed Martin Hanford Co.

File #8 Y79-Y80 Proj:PLC2

Page:00115

07:48:15 02/19/99

B3/74

- [7]/18,[8]44

8:0045

+--RET--+
+Return ()+
+-----+

8:0046

-[End]-

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125E
 Lockheed Martin Hanford Co.
 Page:00116

File #9 Y83-Y86 Proj:PLC2

07:48:15 02/19/99

PROGRAM FILE#9
 START OF
 SUBROUTINE
 COMMENT COIL

9:0000	+--SBR-----+ Subroutine +-----+				B3/44 ( )
	B3/44 - [9]0				
	OPEN VALVE SOV-3125E	CLOSE VALVE SOV-3125E			OPEN VALVE SOV-3125E
	Y-83.1 HS-3125E1 N14:128/2	Y-83.1 HS-3125E2 N14:128/3	MASTER RESET N19:3/15		Y-83 SOV-3125E-0 0:036/04
9:0001	+-----+ Subroutine +-----+				771-0D16
	OPEN VALVE SOV-3125E				
	Y-83 SOV-3125E-0 0:036/04				
	1771-0D1				
	0:036/004 - [9]1,1,11				
	CLOSE VALVE SOV-3125E	OPEN VALVE SOV-3125E	START BOOSTER PUMP P-3125A Y-74.1		CLOSE VALVE SOV-3125E BIT Y-83
	Y-83.1 HS-3125E2 N14:128/3	Y-83.1 HS-3125E1 N14:128/2	B3/87		B3/345
9:0002	+-----+ Subroutine +-----+				( )
	CLOSE VALVE SOV-3125E BIT Y-83				
	B3/345				
	B3/345 - [9]2,2,3				
	CLOSE VALVE SOV-3125E BIT Y-83				CLOSE VALVE SOV-3125E
	B3/345				Y-83 SOV-3125E-C 0:036/05
9:0003	+-----+ Subroutine +-----+				771-0D16
	MASTER RESET N19:3/15				
	0:036/005 - [9]3,12				

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125E
 Lockheed Martin Hanford Co.
 Page:00117

File #9 Y83-Y86 Proj:PLC2

07:48:15 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3125E
Lockheed Martin Hanford Co.
Page:00118

File #9 Y83-Y86 Proj:PLC2

07:48:15 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3125E
Lockheed Martin Hanford Co.
Page:00119

File #9 Y83-Y86 Proj:PLC2

07:48:16 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125C
 Lockheed Martin Hanford Co.
 Page:00120

File #9 Y83-Y86 Proj:PLC2

07:48:16 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125C
 Lockheed Martin Hanford Co.
 Page:00121

File #9 Y83-Y86 Proj:PLC2

07:48:16 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125C
 Lockheed Martin Hanford Co.
 Page:00122

File #9 Y83-Y86 Proj:PLC2

07:48:16 02/19/99

	T4:62.DN - [9]21,22	
	VALVE SOV-3125C POS. SWITCH FAIL. DELAY CMP	VALVE SOV-3125C POSITION SWITCH FAILURE Y-84.1 ZA-3125C N14:8/9 ( )
9:0022	T4:62.DN ----- -----	
	N14:8/9 - [9]20,22	
	OPEN VALVE SOV-3125C	OPEN VALVE SOV-3125C OPEN VALVE SOV-3125C
9:0023	Y-84.1 HS-3125C1 N14:128/4	Y-84 SOV-3125C-0 0:036/00 Y-84.1 HS-3125C1 N14:128/4 (U)
	1771-0D1 CLOSE VALVE SOV-3125C	
	Y-84.1 HS-3125C2 N14:128/5 ----- -----	
	MASTER RESET N19:3/15 +----- -----+	
	N14:128/4 - [9]13,14,18,23,23,24	
	CLOSE VALVE SOV-3125C	CLOSE VALVE SOV-3125C CLOSE VALVE SOV-3125C
9:0024	Y-84.1 HS-3125C2 N14:128/5	Y-84 SOV-3125C-C 0:036/01 Y-84.1 HS-3125C2 N14:128/5 (U)
	1771-0D1 OPEN VALVE SOV-3125C	
	Y-84.1 HS-3125C1 N14:128/4 ----- -----	
	START BOOSTER PUMP P-3125A Y-74.1 B3/87 +----- -----+	
	N14:128/5 - [9]/13,14,16,23,24,24	

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125G
 Lockheed Martin Hanford Co.
 Page:00123

File #9 Y83-Y86 Proj:PLC2

07:48:16 02/19/99

07:48:16 02/19/99

CLOSE VALVE SOV-3125G IS CLOSED

Y-84.1
HS-3125G2
N14:128/7

Y85-1
ZSL-3125G
I:024/07
1771-1BD

MASTER RESET
N19:3/15

VALVE
SOV-3125G
FAILED TO CLS.
DELAY
T4:63.EN

T4:63.EN - [9]28,28,29

VALVE
SOV-3125G
FAILED TO CLS.
DELAY COMPLT.

T4:63.DN

N14:8/10 - [9]29,32

OPEN VALVE
SOV-3125G

Y84.1
HS-3125G1
N14:128/6

Y85-1
ZSH-3125G
I:024/06
1771-1BD

VALVE
SOV-3125G
FAILED TO OPEN.
DELAY
T4:64.EN

T4:64.EN - [9]30,30,31

VALVE
SOV-3125G
FAILED TO OPEN.
DELAY COMPLT.

T4:64.DN

N14:8/12 - [9]31,32

VALVE SOV-3125G FAILED TO CLS. DELAY Y-85.1

TON

Timer On Delay
Timer: T4:63
Base (SEC): 1.0
Preset: 10
Accum: 0

(-EN)
(-DN)

VALVE
SOV-3125G
FAILED TO OPEN.
DELAY
Y-85.1

TON

Timer On Delay
Timer: T4:64
Base (SEC): 1.0
Preset: 10
Accum: 0

(-EN)
(-DN)

VALVE
SOV-3125G
FAILED TO OPEN
OPEN
Y-85.1
ZA-3125G1
N14:8/12
( )

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125G
 Lockheed Martin Hanford Co.
 Page:00125

File #9 Y83-Y86 Proj:PLC2

07:48:17 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3125G
Lockheed Martin Hanford Co.
Page: 00126

File #9 Y83-Y86 Proj:PLC2

07:48:17 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125D
 Lockheed Martin Hanford Co.
 Page:00127

File #9 Y83-Y86 Proj:PLC2

07:48:17 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3125D
Lockheed Martin Hanford Co.
Page:00128

File #9 Y83-Y86 Proj:PLC2

07:48:17 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3125D
 Lockheed Martin Hanford Co.
 Page:00129

File #9 Y83-Y86 Proj:PLC2

07:48:18 02/19/99

	T4:68.DN - [9]45,46	
9:0046	VALVE SOV-3125D POS. SWITH FAIL. DELAY CMP T4:68.DN ----- -----	VALVE SOV-3125D POSITION SWITCH FAILURE Y-86.1 ZA-3125D N14:9/3 -----( )-----
	N14:9/3 - [9]44,46	
9:0047	OPEN VALVE SOV-3125D Y-84.1 HS-3125D1 N14:128/8 ----- -----	OPEN VALVE SOV-3125D Y-86 SOV-3125D-0 0:036/02 Y-84.1 HS-3125D1 N14:128/8 -----(U)-----
	1771-0D1 CLOSE VALVE SOV-3125D Y-84.1 HS-3125D2 N14:128/9 ----- ----- MASTER RESET N19:3/15 ----- -----	
	N14:128/8 - [9]37,138,42,47,48	
9:0048	CLOSE VALVE SOV-3125D Y-84.1 HS-3125D2 N14:128/9 ----- -----	CLOSE VALVE SOV-3125D Y-86 SOV-3125D-C 0:036/03 Y-84.1 HS-3125D2 N14:128/9 -----(U)-----
	1771-0D1 OPEN VALVE SOV-3125D Y-84.1 HS-3125D1 N14:128/8 ----- ----- START BOOSTER PUMP P-3125B Y-74.2 B3/88 ----- -----	
	N14:128/9 - [9]/37,38,40,47,48,48	
9:0049		---RET----- Return ( ) ----- -----

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3125E
Lockheed Martin Hanford Co.
Page:00130

File #9 Y83-Y86 Proj:PLC2

07:48:18 02/19/99

9:0050

[End]

Hanford Cross Site Transfer System (PCU-2)
 SUMP PUMP P-3115 CONTROL
 Lockheed Martin Hanford Co.
 Page:00131

File #10 Y87-Y89 Proj:PLC2

07:48:18 02/19/99

			PROGRAM FILE#10 START OF SUBROUTINE COMMENT COIL
10:0000	<pre> +--SBR-----+ Subroutine +-----+ </pre>		B3/45 ( )
	<pre> B3/45 - [10]0 SOV-3173A SOV-3173B IS CLOSED IS CLOSED </pre>		SHUTDOWN SUMP PUMP P-3115
10:0001	<pre> Y87-1 Y87-2 ZSL-3173A ZSL-3173B I:024/17 I:024/11 ----- / ----- / ----- 1771-IBD 1771-IBD </pre>		Y-82.1 P-3115-SD 0:035/14 771-0D16
	<pre> 0:035/014 - [10]1 </pre>		
10:0002	<pre> SUPERNATE LINE WT-SNL-3150 PRESSURE PT-3125E +--GRT-----+ Greater Than (A>B) Source A: N20:21 0 Source B: N7:30 2 +-----+ </pre>		SUPERNATE LINE WT-SNL-3150 CONTAINS PRESSURE INTERLOCK B3/335 ( )
	<pre> B3/335 - [10]2,/3,12,/14,23 </pre>		

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3173A
 Lockheed Martin Hanford Co.
 Page:00132

File #10 Y87-Y89 Proj:PLC2

07:48:18 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3173A
 Lockheed Martin Hanford Co.
 Page:00133

File #10 Y87-Y89 Proj:PLC2

07:48:18 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3173A
 Lockheed Martin Hanford Co.
 Page:00134

File #10 Y87-Y89 Proj:PLC2

07:48:18 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3173A
Lockheed Martin Hanford Co.
Page:00135

File #10 Y87-Y89 Proj:PLC2

07:48:18 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3173B
 Lockheed Martin Hanford Co.
 Page:00136

File #10 Y87-Y89 Proj:PLC2

07:48:19 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3173B
 Lockheed Martin Hanford Co.
 Page:00137

File #10 Y87-Y89 Proj:PLC2

07:48:19 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3173B
 Lockheed Martin Hanford Co.
 Page:00138

File #10 Y87-Y89 Proj:PLC2

07:48:19 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3173B
Lockheed Martin Hanford Co.
Page:00139

File #10 Y87-Y89 Proj:PLC2

07:48:19 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3156A
 Lockheed Martin Hanford Co.
 Page:00140

File #10 Y87-Y89 Proj:PLC2

07:48:19 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3156A
 Lockheed Martin Hanford Co.
 Page:00141

File #10 Y87-Y89 Proj:PLC2

07:48:19 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3156A
Lockheed Martin Hanford Co.
Page:00142

File #10 Y87-Y89 Proj:PLC2

07:48:20 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 VALVE SEQUENCING FOR SOV-3156B
 Lockheed Martin Hanford Co.
 Page:00143

File #10 Y87-Y89 Proj:PLC2

07:48:20 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3156B
Lockheed Martin Hanford Co.
Page:00144

File #10 Y87-Y89 Proj:PLC2

07:48:20 02/19/99

Hanford Cross Site Transfer System (PCU-2)
VALVE SEQUENCING FOR SOV-3156B
Lockheed Martin Hanford Co.
Page: 00145

File #10 Y87-Y89 Proj:PLC2

07:48:20 02/19/99

Hanford Cross Site Transfer System (PCU-2)
 PLC RAMP FUNCTION SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00146

File #11 RAMP Proj:PLC2

07:48:20 02/19/99

11:0000

```

+---SBR-----+
|Subroutine|
|Input  Par: N7:300|
|Input  Par: N7:301|
|Input  Par: N7:304|
+-----+

```

RAMP BLOCK
 SUBROUTINE
 RAMP_SBR

B3/300

( )

B3/300 - [11]0

CALCULATE THE DIFFERENCE BETWEEN THE CURRENT AND TARGET SETPOINTS.

11:0001

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKING REGISTER

```

+---SUB-----+
|Sub|
|Source A: N7:300|
|           20|
|Source B: N7:301|
|           1|
|Dest:    N7:302|
|           20|
+-----+

```

```

N7:300 - [11]0,1,5
N7:301 - [11]0,1,4,4,4,4,5,6
N7:302/15 - [11]1,2,2,3,/3,4,/4,6

```

THE NEXT TWO RUNGS CALCULATE THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN TARGET AND CURRENT SETPOINTS.

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKING REGISTER
 SIGN BIT
 RAMP DIFF NEG

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKING REGISTER

N7:302/15

11:0002

```

+---NEG-----+
|Negate|
|Source: N7:302|
|           20|
|Dest:   N7:303|
|           20|
+-----+

```

RAMP FUNCTION
 COMMENT COIL

B3/301

( )

```

N7:302/15 - [11]1,2,2,3,/3,4,/4,6
N7:303 - [11]2,3,4,5,6
B3/301 - [11]2

```

Hanford Cross Site Transfer System (PCU-2)
 PLC RAMP FUNCTION SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00147

File #11 RAMP Proj:PLC2

07:48:21 02/19/99

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKNG REGISTER
 SIGN BIT
 RAMP DIFF NEG

N7:302/15

11:0003

|/|

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKNG REGISTER

---MOV---
 Move
 Source: N7:302
 20
 Dest: N7:303
 20

N7:302/15 - [11]1,2,2,3,1/3,4,1/4,6
 N7:303 - [11]2,3,4,5,6

*****
 *IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS GREATER THAN THE
 *INCREMENT LIMIT, ADD OR
 *SUBTRACT THE LIMIT VALUE AS APPROPRIATE.
 *****

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKNG REGISTER

11:0004

---GRT---
 Greater Than (A>B)
 Source A: N7:303
 20
 Source B: N7:304
 1

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKNG REGISTER S.P. RAMP BLOCK
 SIGN BIT CURRENT S.P.
 RAMP DIFF NEG WORKNG REGISTER

N7:302/15

---SUB---

Sub
 Source A: N7:301
 1
 Source B: N7:304
 1
 Dest: N7:301
 1

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 WORKNG REGISTER S.P. RAMP BLOCK
 SIGN BIT CURRENT S.P.
 RAMP DIFF NEG WORKNG REGISTER

N7:302/15

---ADD---

Add
 Source A: N7:301
 1
 Source B: N7:304
 1
 Dest: N7:301
 1

RAMP FUNCTION
 COMMENT COIL

B3/302

( )

N7:301 - [11]0,1,4,4,4,4,5,6
 N7:304 - [11]0,4,4,4,5
 N7:301 - [11]0,1,4,4,4,4,5,6
 N7:301 - [11]0,1,4,4,4,4,5,6
 N7:304 - [11]0,4,4,4,5
 N7:301 - [11]0,1,4,4,4,4,5,6
 B3/302 - [11]4

Hanford Cross Site Transfer System (PCU-2)
 PLC RAMP FUNCTION SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00148

File #11 RAMP Proj:PLC2

07:48:21 02/19/99

*****
 *IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS LESS THAN OR EQUAL
 *TO THE INCREMENT LIMIT, SET
 *THE CURRENT SETPOINT EQUAL TO THE TARGET SETPOINT.
 *****

S.P. RAMP BLOCK
 S.P. DIFFERENCE
 ABSOLUTE VALUE
 WORKNG REGISTER

S.P. RAMP BLOCK
 CURRENT S.P.
 WORKNG REGISTER

11:0005 +--LEQ-----+
 Less Than or Equal (A<=B)
 Source A: N7:303
 20
 Source B: N7:304
 1

+--MOV-----+
 Move
 Source: N7:300
 20
 Dest: N7:301
 1

RAMP FUNCTION
 COMMENT COIL
 B3/303
 ( )

N7:300 - [11]0,1,5
 N7:301 - [11]0,1,4,4,4,4,5,6
 B3/303 - [11]5

11:0006 +--RET-----+
 Return ()
 Return Par: N7:301
 Return Par: N7:302
 Return Par: N7:303

N7:301 - [11]0,1,4,4,4,4,5,6
 N7:302/15 - [11]1,2,2,3,3,4,4,4,6
 N7:303 - [11]2,3,4,5,6

11:0007 -----[End]-----

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

DB Form Report Sorted By: Address

Page: 00149

07:48:21 02/19/99

		DIGITAL OUTPUT	REGISTER			
0:033						
0:033/000	MOV-3125BA-0	OPEN VALVE	MOV-3125BA			Y80-1
0:033/001	MOV-3125BA-C	CLOSE VALVE	MOV-3125BA			Y80-1
0:033/002	MOV-3125BB-0	OPEN VALVE	MOV-3125BB			Y80-1
0:033/003	MOV-3125BB-C	CLOSE VALVE	MOV-3125BB			Y80-1
0:033/004	MOV-3125BC-0	OPEN VALVE	MOV-3125BC			Y80-1
0:033/005	MOV-3125BC-C	CLOSE VALVE	MOV-3125BC			Y80-1
0:033/006	MOV-3125BD-0	OPEN VALVE	MOV-3125BD			Y80-1
0:033/007	MOV-3125BD-C	CLOSE VALVE	MOV-3125BD			Y80-1
0:033/010	MOV-3125BE-0	OPEN VALVE	MOV-3125BE			Y80-1
0:033/011	MOV-3125BE-C	CLOSE VALVE	MOV-3125BE			Y80-1
0:033/012	MOV-3125BF-0	OPEN VALVE	MOV-3125BF			Y80-1
0:033/013	MOV-3125BF-C	CLOSE VALVE	MOV-3125BF			Y80-1
0:033/014	MOV-3125BG-0	OPEN VALVE	MOV-3125BG			Y80-1
0:033/015	MOV-3125BG-C	CLOSE VALVE	MOV-3125BG			Y80-1
0:033/016	MOV-3125BH-0	OPEN VALVE	MOV-3125BH			Y80-1
0:033/017	MOV-3125BH-C	CLOSE VALVE	MOV-3125BH			Y80-1
0:034/000	MOV-3125AA-0	OPEN VALVE	MOV-3125AA			Y79-1
0:034/001	MOV-3125AA-C	CLOSE VALVE	MOV-3125AA			Y79-1
0:034/002	MOV-3125AB-0	OPEN VALVE	MOV-3125AB			Y79-1
0:034/003	MOV-3125AB-C	CLOSE VALVE	MOV-3125AB			Y79-1
0:034/004	MOV-3125AC-0	OPEN VALVE	MOV-3125AC			Y79-1
0:034/005	MOV-3125AC-C	CLOSE VALVE	MOV-3125AC			Y79-1
0:034/006	MOV-3125AD-0	OPEN VALVE	MOV-3125AD			Y79-1
0:034/007	MOV-3125AD-C	CLOSE VALVE	MOV-3125AD			Y79-1
0:034/010	MOV-3125AE-0	OPEN VALVE	MOV-3125AE			Y79-1
0:034/011	MOV-3125AE-C	CLOSE VALVE	MOV-3125AE			Y79-1
0:034/012	MOV-3125AF-0	OPEN VALVE	MOV-3125AF			Y79-1
0:034/013	MOV-3125AF-C	CLOSE VALVE	MOV-3125AF			Y79-1
0:034/014	MOV-3125AG-0	OPEN VALVE	MOV-3125AG			Y79-1
0:034/015	MOV-3125AG-C	CLOSE VALVE	MOV-3125AG			Y79-1
0:034/016	MOV-3125AH-0	OPEN VALVE	MOV-3125AH			Y79-1
0:034/017	MOV-3125AH-C	CLOSE VALVE	MOV-3125AH			Y79-1
0:035/000	MOV-3125AJ-0	OPEN VALVE	MOV-3125AJ			Y79-2
0:035/001	MOV-3125AJ-C	CLOSE VALVE	MOV-3125AJ			Y79-2
0:035/002	MOV-3125AK-0	OPEN VALVE	MOV-3125AK			Y79-2
0:035/003	MOV-3125AK-C	CLOSE VALVE	MOV-3125AK			Y79-2
0:035/004	MOV-3125BJ-0	OPEN VALVE	MOV-3125BJ			Y80-2
0:035/005	MOV-3125BJ-C	CLOSE VALVE	MOV-3125BJ			Y80-2
0:035/006	MOV-3125BK-0	OPEN VALVE	MOV-3125BK			Y80-2
0:035/007	MOV-3125BK-C	CLOSE VALVE	MOV-3125BK			Y80-2
0:035/010	P-3125A-T	START PUMP	P-3125A			Y74-1
0:035/011	P-3125A-P	STOP PUMP	P-3125A			Y74-1
0:035/012	P-3125B-T	START PUMP	P-3125B			Y74-2
0:035/013	P-3125B-P	STOP PUMP	P-3125B			Y74-2
0:035/014	P-3115-SD	SHUTDOWN	SUMP PUMP	P-3115		Y-82.1
0:035/015		SPARE	DIGITAL OUTPUT			
0:035/016		SPARE	DIGITAL OUTPUT			
0:035/017		SPARE	DIGITAL OUTPUT			
0:036/000	SOV-3125C-0	OPEN VALVE	SOV-3125C			Y-84
0:036/001	SOV-3125C-C	CLOSE VALVE	SOV-3125C			Y-84
0:036/002	SOV-3125D-0	OPEN VALVE	SOV-3125D			Y-86
0:036/003	SOV-3125D-C	CLOSE VALVE	SOV-3125D			Y-86
0:036/004	SOV-3125E-0	OPEN VALVE	SOV-3125E			Y-85
0:036/005	SOV-3125E-C	CLOSE VALVE	SOV-3125E			Y-85
0:036/006	SOV-3125G-0	OPEN VALVE	SOV-3125G			Y-85
0:036/007	SOV-3125G-C	CLOSE VALVE	SOV-3125G			Y-85
0:036/010	MOV-3156B-0	OPEN VALVE	MOV-3156B			Y89-2
0:036/011	MOV-3156B-C	CLOSE VALVE	MOV-3156B			Y89-2
0:036/012	MOV-3156A-0	OPEN VALVE	MOV-3156A			Y89-1
0:036/013	MOV-3156A-C	CLOSE VALVE	MOV-3156A			Y89-1
0:036/014	SOV-3163-0	OPEN VALVE	SOV-3163			Y80-2
0:036/015	SOV-3163-C	CLOSE VALVE	SOV-3163			Y80-2
0:036/016	SOV-3173A-0	OPEN VALVE	SOV-3173A			Y87-1
0:036/017	SOV-3173A-C	CLOSE VALVE	SOV-3173A			Y87-1
0:037/000	SOV-3173B-0	OPEN VALVE	SOV-3173B			Y87-2
0:037/001	SOV-3173B-C	CLOSE VALVE	SOV-3173B			Y87-2
0:037/002	SOV-3182A-0	OPEN VALVE	SOV-3182A			Y71
0:037/003	SOV-3182A-C	CLOSE VALVE	SOV-3182A			Y71
0:037/004	SOV-3182B-0	OPEN VALVE	SOV-3182B			Y71
0:037/005	SOV-3182B-C	CLOSE VALVE	SOV-3182B			Y71
0:037/006	SOV-3183A-0	OPEN VALVE	SOV-3183A			Y71
0:037/007	SOV-3183A-C	CLOSE VALVE	SOV-3183A			Y71
0:037/010	SOV-3183B-0	OPEN VALVE	SOV-3183B			Y71
0:037/011	SOV-3183B-C	CLOSE VALVE	SOV-3183B			Y71
0:037/012	SOV-3184-0	OPEN VALVE	SOV-3184			Y71
0:037/013	SOV-3184-C	CLOSE VALVE	SOV-3184			Y71

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00150

DB Form Report Sorted By: Address

07:48:13 02/19/99

0:037/014		SPARE	DIGITAL	OUTPUT		
0:037/015		SPARE	DIGITAL	OUTPUT		
0:037/016		SPARE	DIGITAL	OUTPUT		
0:037/017		SPARE	DIGITAL	OUTPUT		
1:020		DIGITAL INPUT	REGISTER			
1:020/000	ZSH-3125BA	MOV-3125BA	IS OPEN			Y80-1
1:020/001	ZSL-3125BA	MOV-3125BA	IS CLOSED			Y81-1
1:020/002	ZSH-3125BB	MOV-3125BB	IS OPEN			Y80-1
1:020/003	ZSL-3125BB	MOV-3125BB	IS CLOSED			Y81-1
1:020/004	ZSH-3125BC	MOV-3125BC	IS OPEN			Y80-1
1:020/005	ZSL-3125BC	MOV-3125BC	IS CLOSED			Y81-1
1:020/006	ZSH-3125BD	MOV-3125BD	IS OPEN			Y80-1
1:020/007	ZSL-3125BD	MOV-3125BD	IS CLOSED			Y81-1
1:020/010	ZSH-3125BE	MOV-3125BE	IS OPEN			Y80-1
1:020/011	ZSL-3125BE	MOV-3125BE	IS CLOSED			Y81-1
1:020/012	ZSH-3125BF	MOV-3125BF	IS OPEN			Y80-1
1:020/013	ZSL-3125BF	MOV-3125BF	IS CLOSED			Y81-1
1:020/014	ZSH-3125BG	MOV-3125BG	IS OPEN			Y80-1
1:020/015	ZSL-3125BG	MOV-3125BG	IS CLOSED			Y81-1
1:020/016	ZSH-3125BH	MOV-3125BH	IS OPEN			Y80-1
1:020/017	ZSL-3125BH	MOV-3125BH	IS CLOSED			Y81-1
1:021/000	ZSH-3125BJ	MOV-3125BJ	IS OPEN			Y81-2
1:021/001	ZSL-3125BJ	MOV-3125BJ	IS CLOSED			Y81-2
1:021/002	ZSH-3125BK	MOV-3125BK	IS OPEN			Y81-2
1:021/003	ZSL-3125BK	MOV-3125BK	IS CLOSED			Y81-2
1:021/004		SPARE	DIGITAL	INPUT		
1:021/005		SPARE	DIGITAL	INPUT		
1:021/006		SPARE	DIGITAL	INPUT		
1:021/007		SPARE	DIGITAL	INPUT		
1:021/010		SPARE	DIGITAL	INPUT		
1:021/011		SPARE	DIGITAL	INPUT		
1:021/012		SPARE	DIGITAL	INPUT		
1:021/013		SPARE	DIGITAL	INPUT		
1:021/014		SPARE	DIGITAL	INPUT		
1:021/015		SPARE	DIGITAL	INPUT		
1:021/016		SPARE	DIGITAL	INPUT		
1:021/017		SPARE	DIGITAL	INPUT		
1:022/000	ZSH-3125AA	MOV-3125AA	IS OPEN			Y79-1
1:022/001	ZSL-3125AA	MOV-3125AA	IS CLOSED			Y80-1
1:022/002	ZSH-3125AB	MOV-3125AB	IS OPEN			Y79-1
1:022/003	ZSL-3125AB	MOV-3125AB	IS CLOSED			Y80-1
1:022/004	ZSH-3125AC	MOV-3125AC	IS OPEN			Y79-1
1:022/005	ZSL-3125AC	MOV-3125AC	IS CLOSED			Y80-1
1:022/006	ZSH-3125AD	MOV-3125AD	IS OPEN			Y79-1
1:022/007	ZSL-3125AD	MOV-3125AD	IS CLOSED			Y80-1
1:022/010	ZSH-3125AE	MOV-3125AE	IS OPEN			Y79-1
1:022/011	ZSL-3125AE	MOV-3125AE	IS CLOSED			Y80-1
1:022/012	ZSH-3125AF	MOV-3125AF	IS OPEN			Y79-1
1:022/013	ZSL-3125AF	MOV-3125AF	IS CLOSED			Y80-1
1:022/014	ZSH-3125AG	MOV-3125AG	IS OPEN			Y79-1
1:022/015	ZSL-3125AG	MOV-3125AG	IS CLOSED			Y80-1
1:022/016	ZSH-3125AH	MOV-3125AH	IS OPEN			Y79-1
1:022/017	ZSL-3125AH	MOV-3125AH	IS CLOSED			Y80-1
1:023/000	ZSH-3125AJ	MOV-3125AJ	IS OPEN			Y79-2
1:023/001	ZSL-3125AJ	MOV-3125AJ	IS CLOSED			Y80-2
1:023/002	ZSH-3125AK	MOV-3125AK	IS OPEN			Y79-2
1:023/003	ZSL-3125AK	MOV-3125AK	IS CLOSED			Y80-2
1:023/004	YAS-3101A	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/005	YAS-3101B	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/006	YAS-3101C	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/007	YAS-3101D	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/010	YAS-3101E	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/011	YAS-3101F	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/012	YAS-3101G	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/013	YAS-3101H	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:023/014		SPARE	DIGITAL	INPUT		
1:023/015		SPARE	DIGITAL	INPUT		
1:023/016		SPARE	DIGITAL	INPUT		
1:023/017		SPARE	DIGITAL	INPUT		
1:024/000	ZSH-3125C	SOV-3125C	IS OPEN			Y84-1
1:024/001	ZSL-3125C	SOV-3125C	IS CLOSED			Y84-1
1:024/002	ZSH-3125D	SOV-3125D	IS OPEN			Y86-1
1:024/003	ZSL-3125D	SOV-3125D	IS CLOSED			Y86-1
1:024/004	ZSH-3125E	SOV-3125E	IS OPEN			Y83-1
1:024/005	ZSL-3125E	SOV-3125E	IS CLOSED			Y83-1
1:024/006	ZSH-3125G	SOV-3125G	IS OPEN			Y85-1
1:024/007	ZSL-3125G	SOV-3125G	IS CLOSED			Y85-1

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page: 00151

DB Form Report

Sorted By: Address

07:48:14 02/19/99

I:024/010	ZSH-3173B	SOV-3173B	IS OPEN				Y87-2
I:024/011	ZSL-3173B	SOV-3173B	IS CLOSED				Y87-2
I:024/012	ZSH-3156B	MOV-3156B	IS OPEN				Y89-2
I:024/013	ZSL-3156B	MOV-3156B	IS CLOSED				Y89-2
I:024/014	ZSH-3163	SOV-3163	IS OPEN				
I:024/015	ZSL-3163	SOV-3163	IS CLOSED				V-80 2
I:024/016	ZSH-3173A	SOV-3173A	IS OPEN				Y87-1
I:024/017	ZSL-3173A	SOV-3173A	IS CLOSED				Y87-1
I:025/000	ZSH-3182A	SOV-3182A	IS OPEN				Y71
I:025/001	ZSL-3182A	SOV-3182A	IS CLOSED				Y71
I:025/002	ZSH-3182B	SOV-3182B	IS OPEN				Y71
I:025/003	ZSL-3182B	SOV-3182B	IS CLOSED				Y71
I:025/004	ZSH-3183A	SOV-3183A	IS OPEN				Y71
I:025/005	ZSL-3183A	SOV-3183A	IS CLOSED				Y71
I:025/006	ZSH-3183B	SOV-3183B	IS OPEN				Y71
I:025/007	ZSL-3183B	SOV-3183B	IS CLOSED				Y71
I:025/010	ZSH-3184	SOV-3184	IS OPEN				Y71
I:025/011	ZSL-3184	SOV-3184	IS CLOSED				Y71
I:025/012	ZSH-3156A	MOV-3156A	IS OPEN				Y89-1
I:025/013	ZSL-3156A	MOV-3156A	IS CLOSED				Y89-1
I:025/014	HS-3125A3	LOCAL/REMOTE	STATUS FOR	P-3125A			01T
I:025/015	HS-3125B3	LOCAL/REMOTE	STATUS FOR	P-3125B			01T
I:025/016	TSH-3125A	PUMP P-3125A	MOTOR WINDING	TEMP. HIGH	OFF = ALARM		Y76
I:025/017	TSH-3125B	PUMP P-3125B	MOTOR WINDING	TEMP. HIGH	OFF = ALARM		Y76
I:026/000	FSH-3125A1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A	OFF = ALARM		Y76
I:026/001	FSH-3125A2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A	OFF = ALARM		Y76
I:026/002	FSH-3125B1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B	OFF = ALARM		Y76
I:026/003	FSH-3125B2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B	OFF = ALARM		Y76
I:026/004	LSL-3125A1	PUMP P-3125A	LOW OIL LEVEL	OFF = ALARM			Y76
I:026/005	LSL-3125A2	PUMP P-3125A	LOW OIL LEVEL	OFF = ALARM			Y76
I:026/006	LSL-3125B1	PUMP P-3125B	LOW OIL LEVEL	OFF = ALARM			Y76
I:026/007	LSL-3125B2	PUMP P-3125B	LOW OIL LEVEL	OFF = ALARM			Y76
I:026/010	LDXS-3150	6241-A SUMP	LEAK DETECTION	OFF=ALARM			Y72
I:026/011	LDK-3160	6241-A	ENCASEMENT	LEAK DETECTION	OFF = ALARM		Y72.1
I:026/012	LDSH-3150	SUMP LEAK	DETECTOR	FAILURE	OFF=FAILURE		Y72
I:026/013	PSL-3125A2	PUMP P-3125A	SEAL FAILURE	OFF = ALARM			Y76
I:026/014	PSL-3125B1	PUMP P-3125B	SEAL FAILURE	OFF = ALARM			Y76
I:026/015	PSL-3125B2	PUMP P-3125AB	SEAL FAILURE	OFF = ALARM			Y76
I:026/016	PSL-3100A	LOW	COMPRESSOR	SA-CMP-3101A	PRESSURE		
I:026/017	PSL-3125A1	PUMP P-3125A	SEAL FAILURE	OFF = ALARM			Y76
S:000/000		PROCESSOR	ARITHMETIC	CARRY		FLAG	FLAG
S:000/001		PROCESSOR	ARITHMETIC	UNDERFLOW/		OVERFLOW	
S:000/002		PROCESSOR	ARITHMETIC	ZERO		FLAG	
S:000/003		PROCESSOR	ARITHMETIC	SIGN		FLAG	
S:001/000		BAD RAM	CHECKSUM	AT POWER		UP	
S:001/001		PLC-5 IN	RUN MODE				
S:001/002		PLC-5 IN	TEST MODE				
S:001/003		PLC-5 IN	PROG MODE				
S:001/004		PLC-5 IS	BURNING AN	EEPROM			
S:001/005		DOWNLOAD-	ING IN	PROGRESS			
S:001/006		TEST EDITS	ENABLED				
S:001/007		MODE	SWITCH	IN REMOTE			
S:001/008		FORCES	ENABLED				
S:001/009		FORCES	PRESENT				
S:001/010		EEPROM	SUCCESS-	FULLY		BURNED	
S:001/011		PERFORM-	ING ONLINE	PROGRAM-		MING	
S:001/012		PROCESSOR	IS IN	DEBUG MODE			
S:001/013		USER	PROGRAM	CHECKSUM		DONE	
S:001/014		LAST SCAN	OF LADDER	OR SFC		STEP	
S:001/015		FIRST SCAN	OF LADDER	OR SFC		STEP	
S:007		LOGICAL RACK	STATUS BITS	FOR RACKS 0-7			
S:007/000		RACK 0	FAULTED				
S:007/001		RACK 1	FAULTED				
S:007/002		RACK 2	FAULTED				
S:007/003		RACK 3	FAULTED				
S:007/004		RACK 4	FAULTED				
S:007/005		RACK 5	FAULTED				
S:007/006		RACK 6	FAULTED				
S:007/007		RACK 7	FAULTED				
S:007/008		BLOCK XFER	QUEUE TO	RACK 0 IS	FULL		
S:007/009		BLOCK XFER	QUEUE TO	RACK 1 IS	FULL		
S:007/010		BLOCK XFER	QUEUE TO	RACK 2 IS	FULL		
S:007/011		BLOCK XFER	QUEUE TO	RACK 3 IS	FULL		
S:007/012		BLOCK XFER	QUEUE TO	RACK 4 IS	FULL		
S:007/013		BLOCK XFER	QUEUE TO	RACK 5 IS	FULL		
S:007/014		BLOCK XFER	QUEUE TO	RACK 6 IS	FULL		
S:007/015		BLOCK XFER	QUEUE TO	RACK 7 IS	FULL		SFC

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00152

DB Form Report Sorted By: Address

07:48:14 02/19/99

S:008	LAST	PROGRAM	SCAN TIME	LADDER &	SFC
S:009	MAXIMUM	PROGRAM	SCAN TIME	LADDER &	
S:010/000	BATTERY	IS BAD OR	MISSING		
S:010/001	DH+ ACTIVE	NODE TABLE	CHANGED		
S:010/002	STI	OVERLAP			
S:010/003	EEPROM	TRANS	FERRED		
S:010/004	EDITS	PREVENT	SFC	CONTINUING	
S:010/005	INVALID	I/O STATUS	FILE		
S:010/006	MEMORY	CARDIDGE	BATTERY	LOW	
S:010/007	NO MORE	COMMAND	BLOCKS	EXIST	
S:010/009	NO MCP WAS	CONFIGURED	TO RUN		
S:010/010	MCP NOT	ALLOWED			
S:010/011	P11 WORD	NUMBER	ISN'T IN	LOCAL RACK	
S:010/012	USER P11	ROUTINE	OVERLAP		
S:010/013	NO COMMAND	BLOCK	EXISTS TO	GET P11	
S:010/014	ARITHMETIC	OVERFLOW	OCCURRED		
S:010/015	SFC	LINGERING	ACTION	OVERLAP	
S:011/000	BAD	PROGRAM	FILE		
S:011/001	BAD	ADDRESS	IN LADDER	PROGRAM	
S:011/002	PROGRAMMER	ERROR			
S:011/003	SFC FAULT				
S:011/004	PROGRAM	ASSEMBLY	ERROR		
S:011/005	POWERUP	PROTECTION	FAULT		
S:011/006	ERROR NOT	DEFINED			
S:011/007	USER	GENERATED	FAULT		
S:011/008	WATCHDOG	TIMER	FAULT		
S:011/009	BAD SYSTEM	CONF IS-	URATION		
S:011/010	HARDWARE	ERROR			
S:011/011	MCP FILE	DOES NOT	EXIST OR	IS NOT	LADDER
S:011/012	P11 FILE	DOES NOT	EXIST OR	IS NOT	LADDER
S:011/013	STI FILE	DOES NOT	EXIST OR	IS NOT	LADDER
S:011/014	FAULT FILE	DOES NOT	EXIST OR	IS NOT	
S:011/015	NON LADDER	FILE			
S:012	FAULT CODE				
S:013	PROGRAM	FILE WHERE	FAULT	OCCURRED	OCCURRED
S:014	RUNG	NUMBER	WHERE	FAULT	
S:016	I/O STATUS	FILE			
S:017/000	QUEUE FULL	BETWEEN	LOCAL AND	REMOTE I/O	
S:017/001	QUEUE FULL	SERVICING	CHANNEL 1A		
S:017/002	QUEUE FULL	SERVICING	CHANNEL 1B		
S:017/003	QUEUE FULL	SERVICING	CHANNEL 2A		
S:017/004	QUEUE FULL	SERVICING	CHANNEL 2B		
S:017/005	NO MODEM	ON SERIAL	PORT		
S:017/006	REMOTE I/O	IS GREATER	THAN IMAGE	SIZE	
S:017/008	ASCII	INSTRUCT-	ION ERROR		
S:017/009	DUPLICATE	NODE	ADDRESS		
S:018	REAL TIME	CLOCK YEAR			
S:019	REAL TIME	CLOCK	MONTH		
S:020	REAL TIME	CLOCK DAY			
S:021	REAL TIME	CLOCK HOUR			
S:022	REAL TIME	CLOCK	MINUTE		
S:023	REAL TIME	CLOCK	SECOND		
S:023/000	REAL TIME	CLOCK	SECOND	ONE'S BIT	
S:023/001	REAL TIME	CLOCK	SECOND	TWO'S BIT	
S:024	INDEXED	ADDRESSING	OFFSET		
S:025	ADAPTER	IMAGE	FILE		
S:026/000	SFC	RESTART	CONTINUE		
S:026/001	START-UP	PROTECT-	ION AFTER	POWER LOSS	
S:026/002	LOCAL RACK	IS 1 IF	SET OR 0	IF BIT = 0	
S:026/003	COMPLEMENTARY	RACK	MODE		
S:027/000	RACK 0	INHIBIT			
S:027/001	RACK 1	INHIBIT			
S:027/002	RACK 2	INHIBIT			
S:027/003	RACK 3	INHIBIT			
S:027/004	RACK 4	INHIBIT			
S:027/005	RACK 5	INHIBIT			
S:027/006	RACK 6	INHIBIT			
S:027/007	RACK 7	INHIBIT			
S:027/008	RACK 0	RESET			
S:027/009	RACK 1	RESET			
S:027/010	RACK 2	RESET			
S:027/011	RACK 3	RESET			
S:027/012	RACK 4	RESET			
S:027/013	RACK 5	RESET			
S:027/014	RACK 6	RESET			
S:027/015	RACK 7	RESET			
S:028	WATCHDOG	TIMER	SETPOINT		

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00153

DB Form Report

Sorted By: Address

07:48:14 02/19/99

S:029	FAULT	ROUTINE	FILE	NUMBER	
S:030	STI	SETPOINT	(INTERVAL)		
S:031	STI	FILE	NUMBER		
S:032	LOGICAL RACK	STATUS BITS	FOR RACKS 10-17		
S:032/000	RACK 10	FAULTED			
S:032/001	RACK 11	FAULTED			
S:032/002	RACK 12	FAULTED			
S:032/003	RACK 13	FAULTED			
S:032/004	RACK 14	FAULTED			
S:032/005	RACK 15	FAULTED			
S:032/006	RACK 16	FAULTED			
S:032/007	RACK 17	FAULTED			
S:032/008	BLOCK XFER	QUEUE TO	RACK 10 IS	FULL	
S:032/009	BLOCK XFER	QUEUE TO	RACK 11 IS	FULL	
S:032/010	BLOCK XFER	QUEUE TO	RACK 12 IS	FULL	
S:032/011	BLOCK XFER	QUEUE TO	RACK 13 IS	FULL	
S:032/012	BLOCK XFER	QUEUE TO	RACK 14 IS	FULL	
S:032/013	BLOCK XFER	QUEUE TO	RACK 15 IS	FULL	
S:032/014	BLOCK XFER	QUEUE TO	RACK 16 IS	FULL	
S:032/015	BLOCK XFER	QUEUE TO	RACK 17 IS	FULL	
S:033/000	RACK 10	INHIBIT			
S:033/001	RACK 11	INHIBIT			
S:033/002	RACK 12	INHIBIT			
S:033/003	RACK 13	INHIBIT			
S:033/004	RACK 14	INHIBIT			
S:033/005	RACK 15	INHIBIT			
S:033/006	RACK 16	INHIBIT			
S:033/007	RACK 17	INHIBIT			
S:033/008	RACK 10	RESET			
S:033/009	RACK 11	RESET			
S:033/010	RACK 12	RESET			
S:033/011	RACK 13	RESET			
S:033/012	RACK 14	RESET			
S:033/013	RACK 15	RESET			
S:033/014	RACK 16	RESET			
S:033/015	RACK 17	RESET			
S:034/000	RACK 20	FAULTED			
S:034/001	RACK 21	FAULTED			
S:034/002	RACK 22	FAULTED			
S:034/003	RACK 23	FAULTED			
S:034/004	RACK 24	FAULTED			
S:034/005	RACK 25	FAULTED			
S:034/006	RACK 26	FAULTED			
S:034/007	RACK 27	FAULTED			
S:034/008	BLOCK XFER	QUEUE TO	RACK 20 IS	FULL	
S:034/009	BLOCK XFER	QUEUE TO	RACK 21 IS	FULL	
S:034/010	BLOCK XFER	QUEUE TO	RACK 22 IS	FULL	
S:034/011	BLOCK XFER	QUEUE TO	RACK 23 IS	FULL	
S:034/012	BLOCK XFER	QUEUE TO	RACK 24 IS	FULL	
S:034/013	BLOCK XFER	QUEUE TO	RACK 25 IS	FULL	
S:034/014	BLOCK XFER	QUEUE TO	RACK 26 IS	FULL	
S:034/015	BLOCK XFER	QUEUE TO	RACK 27 IS	FULL	
S:035/000	RACK 20	INHIBIT			
S:035/001	RACK 21	INHIBIT			
S:035/002	RACK 22	INHIBIT			
S:035/003	RACK 23	INHIBIT			
S:035/004	RACK 24	INHIBIT			
S:035/005	RACK 25	INHIBIT			
S:035/006	RACK 26	INHIBIT			
S:035/007	RACK 27	INHIBIT			
S:035/008	RACK 20	RESET			
S:035/009	RACK 21	RESET			
S:035/010	RACK 22	RESET			
S:035/011	RACK 23	RESET			
S:035/012	RACK 24	RESET			
S:035/013	RACK 25	RESET			
S:035/014	RACK 26	RESET			
S:035/015	RACK 27	RESET			
S:046	PII	FILE	NUMBER		
S:047	PII	MODULE	GROUP TO	EXAMINE	
S:048	PII BIT	MASK			
S:048/000	PII MODULE	BIT	1=MONITOR	0=IGNORE	
S:049	PII	COMPARE	VALUE		TRUE TO
S:049/000	PII BIT	1=FALSE TO	TRUE	0=	
S:050	PII DOWN	COUNT			
S:051	PII RETURN	MASK			
S:052	PII ACCUM-	ULATOR			

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00154

DB Form Report Sorted By: Address

07:48:15 02/19/99

S:053	STI LAST	SCAN TIME			
S:054	STI MAX	SCAN TIME			
S:055	PII LAST	SCAN TIME			
S:056	PII MAX	SCAN TIME			
S:079/000	MAIN	CONTROL	PROGRAM A	DISABLE	BIT
S:079/001	MAIN	CONTROL	PROGRAM B	DISABLE	BIT
S:079/002	MAIN	CONTROL	PROGRAM C	DISABLE	BIT
S:079/003	MAIN	CONTROL	PROGRAM D	DISABLE	BIT
S:079/004	MAIN	CONTROL	PROGRAM E	DISABLE	BIT
S:079/005	MAIN	CONTROL	PROGRAM F	DISABLE	BIT
S:079/006	MAIN	CONTROL	PROGRAM G	DISABLE	BIT
S:079/007	MAIN	CONTROL	PROGRAM H	DISABLE	BIT
S:079/008	MAIN	CONTROL	PROGRAM I	DISABLE	BIT
S:079/009	MAIN	CONTROL	PROGRAM J	DISABLE	BIT
S:079/010	MAIN	CONTROL	PROGRAM K	DISABLE	BIT
S:079/011	MAIN	CONTROL	PROGRAM L	DISABLE	BIT
S:079/012	MAIN	CONTROL	PROGRAM M	DISABLE	BIT
S:079/013	MAIN	CONTROL	PROGRAM N	DISABLE	BIT
S:079/014	MAIN	CONTROL	PROGRAM O	DISABLE	BIT
S:079/015	MAIN	CONTROL	PROGRAM P	DISABLE	NUMBER
S:080	MAIN	CONTROL	PROGRAM A	FILE	
S:081	PROGRAM A	SCAN TIME			
S:082	PROGRAM A	MAXIMUM	SCAN TIME		NUMBER
S:083	MAIN	CONTROL	PROGRAM B	FILE	
S:084	PROGRAM B	SCAN TIME			
S:085	PROGRAM B	MAXIMUM	SCAN TIME		NUMBER
S:086	MAIN	CONTROL	PROGRAM C	FILE	
S:087	PROGRAM C	SCAN TIME			
S:088	PROGRAM C	MAXIMUM	SCAN TIME		NUMBER
S:089	MAIN	CONTROL	PROGRAM D	FILE	
S:090	PROGRAM D	SCAN TIME			
S:091	PROGRAM D	MAXIMUM	SCAN TIME		NUMBER
S:092	MAIN	CONTROL	PROGRAM E	FILE	
S:093	PROGRAM E	SCAN TIME			
S:094	PROGRAM E	MAXIMUM	SCAN TIME		NUMBER
S:095	MAIN	CONTROL	PROGRAM F	FILE	
S:096	PROGRAM F	SCAN TIME			
S:097	PROGRAM F	MAXIMUM	SCAN TIME		NUMBER
S:098	MAIN	CONTROL	PROGRAM G	FILE	
S:099	PROGRAM G	SCAN TIME			
S:100	PROGRAM G	MAXIMUM	SCAN TIME		NUMBER
S:101	MAIN	CONTROL	PROGRAM H	FILE	
S:102	PROGRAM H	SCAN TIME			
S:103	PROGRAM H	MAXIMUM	SCAN TIME		NUMBER
S:104	MAIN	CONTROL	PROGRAM I	FILE	
S:105	PROGRAM I	SCAN TIME			
S:106	PROGRAM I	MAXIMUM	SCAN TIME		NUMBER
S:107	MAIN	CONTROL	PROGRAM J	FILE	
S:108	PROGRAM J	SCAN TIME			
S:109	PROGRAM J	MAXIMUM	SCAN TIME		NUMBER
S:110	MAIN	CONTROL	PROGRAM K	FILE	
S:111	PROGRAM K	SCAN TIME			
S:112	PROGRAM K	MAXIMUM	SCAN TIME		NUMBER
S:113	MAIN	CONTROL	PROGRAM L	FILE	
S:114	PROGRAM L	SCAN TIME			
S:115	PROGRAM L	MAXIMUM	SCAN TIME		NUMBER
S:116	MAIN	CONTROL	PROGRAM M	FILE	
S:117	PROGRAM M	SCAN TIME			
S:118	PROGRAM M	MAXIMUM	SCAN TIME		NUMBER
S:119	MAIN	CONTROL	PROGRAM N	FILE	
S:120	PROGRAM N	SCAN TIME			
S:121	PROGRAM N	MAXIMUM	SCAN TIME		NUMBER
S:122	MAIN	CONTROL	PROGRAM O	FILE	
S:123	PROGRAM O	SCAN TIME			
S:124	PROGRAM O	MAXIMUM	SCAN TIME		NUMBER
S:125	MAIN	CONTROL	PROGRAM P	FILE	
S:126	PROGRAM P	SCAN TIME			
S:127	PROGRAM P	MAXIMUM	SCAN TIME		
B003/000	ALWAYS OFF	ALWAYS OFF	OUTPUT		
B003/001	ALWAYS ON	ALWAYS ON	OUTPUT		
B003/002	1_SEC PULSE	ONE SECOND	SINGLE SCAN	PULSE	
B003/003	2_SEC PULSE	TWO SECOND	SINGLE SCAN		
B003/004	HALF_SEC_FLASH	HALF SECOND	FLASHER		
B003/005	1_SEC_FLASH	ONE SECOND	FLASHER		
B003/006	2_SEC_FLASH	TWO SECOND	FLASHER		
B003/007					
B003/008					

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00155

DB Form Report

Sorted By: Address

07:48:15 02/19/99

8003/009						
8003/010						
8003/011						
8003/012						
8003/013						
8003/014						
8003/015						
8003/001	TWO SCAN SUB-	DIVISIONS	REGISTER			
8003/016	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIRST SET)		
8003/017	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SECOND SET)		
8003/018	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRD SET)		
8003/019	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTH SET)		
8003/020	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTH SET)		
8003/021	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTH SET)		
8003/022	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SEVENTH SET)		
8003/023	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(EIGHTH SET)		
8003/024	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(NINTH SET)		
8003/025	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TENTH SET)		
8003/026	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(ELEVENTH SET)		
8003/027	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TWELFTH SET)		
8003/028						
8003/029	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRTNTH SET)		
8003/030	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTNTH SET)		
8003/031	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTEENTH SET)		
8003/032	ONE SECOND	RISING	ONE SHOT	(SIXTEENTH SET)		
8003/033	ONE SECOND	FALLING	ONE SHOT			
8003/034	TWO SECOND	RISING	ONE SHOT			
8003/035	TWO SECOND	FALLING	ONE SHOT			
8003/036	PROGRAM FILE	JUMP-TO-SUBR.	CONTROL RUNGS	COMMENT COIL		
8003/037	MCP FILE #2	END OF PROGRAM	COMMENT COIL			
8003/038						
8003/039	FAULT ROUTINE	FILE #3	END OF PROGRAM	COMMENT COIL		
8003/040	PROGRAM FILE#5	START OF	END OF SUBROUTINE	COMMENT COIL		
8003/041	PROGRAM FILE#6	START OF	SUBROUTINE	COMMENT COIL		
8003/042	PROGRAM FILE#7	START OF	SUBROUTINE	COMMENT COIL		
8003/043	PROGRAM FILE#8	START OF	SUBROUTINE	COMMENT COIL		
8003/044	PROGRAM FILE#9	START OF	SUBROUTINE	COMMENT COIL		
8003/045	PROGRAM FILE#10	START OF	SUBROUTINE	COMMENT COIL		
8003/046						
8003/047						
8003/048						
8003/049	ANALOG MODULE	INPUT CHANNEL	UNDER OR OVER	RANGE ALARMS	NOT ACTIVE	
8003/050	ANALOG MODULE	INPUT CHANNEL	UNDER OR OVER	RANGE ALARMS	NOT ACTIVE	
8003/051	PUMP P-3125A	INBOARD	BEARING HIGH	TEMP. FAULT	Y-76.1	
8003/052	PUMP P-3125A	OUTBOARD	BEARING HIGH	TEMP. FAULT	Y-76.1	
8003/053	PUMP P-3125A	HIGH MOTOR	VIBRATION	FAILURE	Y-76.1	
8003/054	PUMP P-3125A	HIGH MOTOR	VIBRATION	FAILURE	Y-76.1	
8003/055	PUMP P-3125B	INBOARD	BEARING HIGH	TEMP. FAULT	Y-76.1	
8003/056	PUMP P-3125B	OUTBOARD	BEARING HIGH	TEMP. FAULT	Y-76.1	
8003/057	PUMP P-3125B	HIGH MOTOR	VIBRATION	FAILURE	Y-76.1	
8003/058	PUMP P-3125B	HIGH MOTOR	VIBRATION	FAILURE	Y-76.1	
8003/059						
8003/060						
8003/061						
8003/062						
8003/063						
8003/064						
8003/065						
8003/066						
8003/067						
8003/068						
8003/069						
8003/070						
8003/071						
8003/072						
8003/073	BOOSTER	PUMP P-3125A	DRAIN VALVES	ALL CLOSED		
8003/074	BOOSTER	PUMP P-3125B	DRAIN VALVES	ALL CLOSED		
8003/075	PUMP P-3125A	IS RUNNING -	ABOVE MINIMUM	PRESSURE	Y-78.1	
8003/076	BOOSTER	PUMP	TROUBLE		Y-76.1	
8003/077	VALVE	SOV-3125C	FAILURE		Y-84.1	
8003/078	VALVE	SOV-3125E	FAILURE		Y-83.1	
8003/079	BOOSTER	PUMP P-3125A	LOW INLET	PRESSURE	Y-75.1	
8003/080	PUMP P-3125B	IS RUNNING -	ABOVE MINIMUM	PRESSURE	Y-78.1	
8003/081	BOOSTER	PUMP	TROUBLE		Y-76.1	
8003/082	BOOSTER	PUMP	FAILURE		Y-85.1	
8003/083	VALVE	SOV-3125G	FAILURE			
8003/084						
8003/085						
8003/086	VALVE	SOV-3125D	FAILURE		Y-86.1	
8003/087	BOOSTER	PUMP P-3125B	LOW INLET	PRESSURE	Y-75.1	
8003/088	START	BOOSTER	PUMP	P-3125A	Y-74.1	
8003/089	START	BOOSTER	PUMP	P-3125B	Y-74.2	
8003/090	CLOSE VALVE	SOV-3163	BIT		Y-80.2	
8003/091	CLOSE	VALVE	MOV-3125AA	BIT	Y-79.1	
8003/092	CLOSE	VALVE	MOV-3125AB	BIT	Y-79.1	
8003/093	CLOSE	VALVE	MOV-3125AC	BIT	Y-79.1	
8003/094	CLOSE	VALVE	MOV-3125AD	BIT	Y-79.1	
8003/095	CLOSE	VALVE	MOV-3125AE	BIT	Y-79.1	
8003/096						
8003/097	CLOSE	VALVE	MOV-3125AF	BIT	Y-79.1	
8003/098	CLOSE	VALVE	MOV-3125AG	BIT	Y-79.1	
8003/099	CLOSE	VALVE	MOV-3125AH	BIT	Y-79.1	
8003/100	CLOSE	VALVE	MOV-3125AJ	BIT	Y-79.2	
8003/101	CLOSE	VALVE	MOV-3125AK	BIT	Y-79.2	
8003/102	CLOSE	VALVE	MOV-3125AL	BIT	Y-80.1	
8003/103	CLOSE	VALVE	MOV-3125AM	BIT	Y-80.1	

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00156

DB Form Report. Sorted By: Address

07:48:16 02/19/99

8003/104	CLOSE	VALVE	MOV-31258C	BIT	Y-80.1
8003/105	CLOSE	VALVE	MOV-31258D	BIT	Y-80.1
8003/106	CLOSE	VALVE	MOV-31258E	BIT	Y-80.1
8003/107	CLOSE	VALVE	MOV-31258F	BIT	Y-80.1
8003/108	CLOSE	VALVE	MOV-31258G	BIT	Y-80.1
8003/109	CLOSE	VALVE	MOV-31258H	BIT	Y-80.1
8003/110	CLOSE	VALVE	MOV-31258J	BIT	Y-80.2
8003/111	CLOSE	VALVE	MOV-31258K	BIT	Y-80.2
8003/112	VALVE	SOV-3173A/B	PRESSURE	POSSIBLE LEAK	Y-73.1
8003/113	VALVE	SOV-3182A/B	PRESSURE	POSSIBLE LEAK	Y-73.1
8003/114	VALVE	SOV-3183A/B	PRESSURE	POSSIBLE LEAK	Y-73.1
8003/116	COMMUN. LOSS	WITH PCU-1	ONE SHOT		
8003/117	COMMUN. LOSS	WITH PCU-1	ONE SHOT		
8003/118	COMMUN. LOSS	WITH PCU-3	ONE SHOT		
8003/119	COMMUN. LOSS	WITH PCU-3	ONE SHOT		
8003/120	COMMUN. LOSS	WITH PCU-4	ONE SHOT		
8003/121	COMMUN. LOSS	WITH PCU-4	ONE SHOT		
8003/122	COMMUN. LOSS	WITH PCU-5	ONE SHOT		
8003/123	COMMUN. LOSS	WITH PCU-5	ONE SHOT		
8003/200	COMM LOSS	ONE SHOT			
8003/201	COMM LOSS	ONE SHOT			
8003/300	RAMP BLOCK	SUBROUTINE	RAMP_SBR		
8003/301	RAMP FUNCTION	COMMENT C01L			
8003/302	RAMP FUNCTION	COMMENT C01L			
8003/303	RAMP FUNCTION	COMMENT C01L			
8003/304	OPEN VALVE	SOV-3184	BIT	Y-71	
8003/305	CLOSE VALVE	SOV-3184	BIT	Y-71	
8003/306	OPEN VALVE	SOV-3183A	BIT	Y-71.1	
8003/307	CLOSE VALVE	SOV-3183A	BIT	Y-71.1	
8003/308	OPEN VALVE	SOV-3183B	BIT	Y-71.1	
8003/309	CLOSE VALVE	SOV-3183B	BIT	Y-71.1	
8003/310	SPEED RAMP	REFERENCE	ENABLE		
8003/311	SPEED RAMP	REFERENCE	ENABLE		
8003/312	RAMP SPEED	REFERENCE	SET POINT	DIFFERENCE	ONE SHOT
8003/313	START SPEED	REFERENCE	RAMP LOGIC		
8003/314	RAMP REFERENCE	COMMENT C01L			
8003/315	RAMP OUTPUT	COMMENT C01L			
8003/316	RAMP JSR	EXECUTED	THIS SCAN		
8003/317	FINAL SPEED	REFERENCE	COMMENT C01L		
8003/318	BOOSTER	PUMP P-3125A	STARTED	SUCCESSFULLY	
8003/319	BOOSTER	PUMP P-3125B	STARTED	SUCCESSFULLY	
8003/324	OPEN VALVE	SOV-3182A	BIT	Y-71.1	
8003/325	CLOSE VALVE	SOV-3182A	BIT	Y-71.1	
8003/326	OPEN VALVE	SOV-3182B	BIT	Y-71.1	
8003/327	CLOSE VALVE	SOV-3182B	BIT	Y-71.1	
8003/330	INITIATE	DRAINING OF	PUMP P-3125A		Y-79.1
8003/331	RESET	VALVES FOR	PUMP P-3125A		Y-79.1
8003/332	INITIATE	DRAINING OF	PUMP P-3125B		Y-80.1
8003/333	RESET	VALVES FOR	PUMP P-3125B		Y-80.1
8003/335	SUPERNATE LINE	WT-SNL-3150	CONTAINS	PRESSURE	INTERLOCK
8003/336	CLOSE VALVE	SOV-3173A	INTERNAL		
8003/337	CLOSE VALVE	SOV-3173B	INTERNAL		
8003/338	CLOSE VALVE	MOV-3156A	INTERNAL		
8003/339	CLOSE VALVE	MOV-3156B	INTERNAL		
8003/340	OPEN VALVE	SOV-3125C	BIT	Y-84	
8003/341	CLOSE VALVE	SOV-3125C	BIT	Y-84	
8003/342	OPEN VALVE	SOV-3125D	BIT	Y-84.1	
8003/343	CLOSE VALVE	SOV-3125D	BIT	Y-84.1	
8003/344					
8003/345	CLOSE VALVE	SOV-3125E	BIT	Y-83	
8003/346					
8003/347	CLOSE VALVE	SOV-3125G	BIT	Y-85	
T004:000	POWER-UP	SEQUENCING	DELAY		
T004:000.ACC					
T004:000.DN	POWER-UP	SEQUENCING	DELAY		
T004:000.PRE					
T004:000.TT					
T004:001	HALF SECOND	FLASHER TIMER			
T004:001.ACC					
T004:001.DN	HALF SECOND	FLASHER TIMER			
T004:001.PRE					
T004:001.TT					
T004:010					
T004:010.DN	PROC SECTION	SPEED REFERENCE	RAMP TIMER		
T004:014	PROC SECTION	SPEED REFERENCE	RAMP TIMER		
T004:014.ACC	SOV-3182A	VALVE FAILED	TO CLOSE	DELAY	
T004:014.DN	SOV-3182A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00157

DB Form Report Sorted By: Address

07:48:16 02/19/99

TO04:014.PRE					
TO04:014.TT					
TO04:015	SOV-3182A	VALVE FAILED	TO OPEN	DELAY	
TO04:015.ACC					
TO04:015.DN	SOV-3182A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:015.PRE					
TO04:015.TT					
TO04:016	SOV-3182A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:016.ACC					
TO04:016.DN	SOV-3182A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:016.PRE					
TO04:016.TT					
TO04:017	SOV-3182B	VALVE FAILED	TO CLOSE	DELAY	
TO04:017.ACC					
TO04:017.DN	SOV-3182B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:017.PRE					
TO04:017.TT					
TO04:018	SOV-3182B	VALVE FAILED	TO OPEN	DELAY	
TO04:018.ACC					
TO04:018.DN	SOV-3182B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:018.PRE					
TO04:018.TT					
TO04:019	SOV-3182B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:019.ACC					
TO04:019.DN	SOV-3182B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:019.PRE					
TO04:019.TT					
TO04:020	SOV-3183A	VALVE FAILED	TO CLOSE	DELAY	
TO04:020.ACC					
TO04:020.DN	SOV-3183A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:020.PRE					
TO04:020.TT					
TO04:021	SOV-3183A	VALVE FAILED	TO OPEN	DELAY	
TO04:021.ACC					
TO04:021.DN					
TO04:021.PRE					
TO04:021.TT					
TO04:021DN	SOV-3183A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:022	SOV-3183A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:022.ACC					
TO04:022.DN					
TO04:022.PRE	SOV-3183A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:022.TT					
TO04:023	SOV-3183B	VALVE FAILED	TO CLOSE	DELAY	
TO04:023.ACC					
TO04:023.DN	SOV-3183B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:023.PRE					
TO04:023.TT					
TO04:024	SOV-3183B	VALVE FAILED	TO OPEN	DELAY	
TO04:024.ACC					
TO04:024.DN					
TO04:024.PRE	SOV-3183B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:024.TT					
TO04:025	SOV-3183B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:025.ACC					
TO04:025.DN	SOV-3183B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:025.PRE					
TO04:025.TT					
TO04:026	SOV-3184	VALVE FAILED	TO CLOSE	DELAY	
TO04:026.ACC					
TO04:026.DN					
TO04:026.PRE	SOV-3184	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:026.TT					
TO04:027	SOV-3184	VALVE FAILED	TO OPEN	DELAY	
TO04:027.ACC					
TO04:027.DN	SOV-3184	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:027.PRE					
TO04:027.TT					
TO04:028	SOV-3184	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:028.ACC					
TO04:028.DN					
TO04:028.PRE	SOV-3184	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:028.TT					
TO04:040	COMM LOSS	TIMER	WITH OCS		
TO04:040.DN	COMM LOSS	TIMER	WITH OCS		
TO04:053	BOOSTER PUMP	P-3125A	FAILURE DELAY		Y-74.1
TO04:053.ACC					

Hanford Cross Site Transfer System (PCU-2)

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00158

DB Form Report Sorted By: Address

07:48:17 02/19/99

T004:053.DN	BOOSTER PUMP	P-3125A	FAILURE DELAY	COMPLETE	Y-74.1
T004:053.PRE					
T004:053.TT					
T004:054	BOOSTER PUMP	INLET PRESSUR	SIGNAL DELAY		Y-74.1
T004:054.ACC					
T004:054.DN	BOOSTER PUMP	INLET PRESSURE	SIGNAL DELAY	COMPLETE	Y-74.1
T004:054.PRE					
T004:054.TT					
T004:055	BOOSTER PUMP	P-3125B	FAILURE DELAY		Y-74.1
T004:055.ACC					
T004:055.DN	BOOSTER PUMP	P-3125B	FAILURE DELAY	COMPLETE	Y-74.1
T004:055.PRE					
T004:055.TT					
T004:056	BOOSTER PUMP	INLET PRESSUR	SIGNAL DELAY		Y-74.2
T004:056.ACC					
T004:056.DN	BOOSTER PUMP	INLET PRESSUR	SIGNAL DELAY	COMPLETE	Y-74.1
T004:056.PRE					
T004:056.TT					
T004:057	VALVE	SOV-3125E	FAILED TO CLS.	DELAY	Y-83.1
T004:057.ACC					
T004:057.DN	VALVE	SOV-3125E	FAILED TO CLS.	DELAY COMPLY.	
T004:057.EN	VALVE	SOV-3125E	FAILED TO CLS.	DELAY	
T004:057.PRE					
T004:057.TT					
T004:058	VALVE	SOV-3125E	FAILED TO OPEN.	DELAY	Y-83.1
T004:058.ACC					
T004:058.DN	VALVE	SOV-3125E	FAILED TO OPEN.	DELAY COMPLY.	
T004:058.EN	VALVE	SOV-3125E	FAILED TO OPEN.	DELAY	
T004:058.PRE					
T004:058.TT					
T004:059	VALVE	SOV-3125E	POS. SWITCH	FAIL. DELAY	Y-83.1
T004:059.ACC					
T004:059.DN	VALVE	SOV-3125E	POS. SWITCH	FAIL. DELAY CMP	
T004:059.EN					
T004:059.PRE					
T004:059.TT					
T004:060	VALVE	SOV-3125C	FAILED TO CLS.	DELAY	Y-84.1
T004:060.ACC					
T004:060.DN	VALVE	SOV-3125C	FAILED TO CLS.	DELAY COMPLY.	
T004:060.EN	VALVE	SOV-3125C	FAILED TO CLS.	DELAY	
T004:060.PRE					
T004:060.TT					
T004:061	VALVE	SOV-3125C	FAILED TO OPEN.	DELAY	Y-84.1
T004:061.ACC					
T004:061.DN	VALVE	SOV-3125C	FAILED TO OPEN.	DELAY COMPLY.	
T004:061.EN	VALVE	SOV-3125C	FAILED TO OPEN.	DELAY	
T004:061.PRE					
T004:061.TT					
T004:062	VALVE	SOV-3125C	POS. SWITCH	FAIL. DELAY	Y-84.1
T004:062.ACC					
T004:062.DN	VALVE	SOV-3125C	POS. SWITCH	FAIL. DELAY CMP	
T004:062.EN					
T004:062.PRE					
T004:062.TT					
T004:063	VALVE	SOV-3125G	FAILED TO CLS.	DELAY	Y-85.1
T004:063.ACC					
T004:063.DN	VALVE	SOV-3125G	FAILED TO CLS.	DELAY COMPLY.	
T004:063.EN	VALVE	SOV-3125G	FAILED TO CLS.	DELAY	
T004:063.PRE					
T004:063.TT					
T004:064	VALVE	SOV-3125G	FAILED TO OPEN.	DELAY	Y-85.1
T004:064.ACC					
T004:064.DN	VALVE	SOV-3125G	FAILED TO OPEN.	DELAY COMPLY.	
T004:064.EN	VALVE	SOV-3125G	FAILED TO OPEN.	DELAY	
T004:064.PRE					
T004:064.TT					
T004:065	VALVE	SOV-3125G	POS. SWITCH	FAIL. DELAY	Y-85.1
T004:065.ACC					
T004:065.DN	VALVE	SOV-3125G	POS. SWITCH	FAIL. DELAY CMP	
T004:065.EN					
T004:065.PRE					
T004:065.TT					
T004:066	VALVE	SOV-3125D	FAILED TO CLS.	DELAY	Y-86.1
T004:066.ACC					
T004:066.DN	VALVE	SOV-3125D	FAILED TO CLS.	DELAY COMPLY.	
T004:066.EN	VALVE	SOV-3125D	FAILED TO CLS.	DELAY	
T004:066.PRE					

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00159

DB Form Report Sorted By: Address

07:48:17 02/19/99

T004:066.TT						
T004:067	VALVE	S0V-3125D	FAILED TO OPEN.	DELAY	Y-86.1	
T004:067.ACC						
T004:067.DN	VALVE	S0V-3125D	FAILED TO OPEN.	DELAY COMPLY.		
T004:067.EN	VALVE	S0V-3125D	FAILED TO OPEN.	DELAY		
T004:067.PRE						
T004:067.TT						
T004:068	VALVE	S0V-3125D	POS. SWITCH	FAIL. DELAY	Y-86.1	
T004:068.ACC						
T004:068.DN	VALVE	S0V-3125D	POS. SWITCH	FAIL. DELAY CMP		
T004:068.EN						
T004:068.PRE						
T004:068.TT						
T004:069	VALVE	S0V-3173A	FAILED TO CLS.	DELAY	Y-87.1	
T004:069.ACC						
T004:069.DN	VALVE	S0V-3173A	FAILED TO CLS.	DELAY COMPLY.		
T004:069.EN	VALVE	S0V-3173A	FAILED TO CLS.	DELAY		
T004:069.PRE						
T004:069.TT						
T004:070	VALVE	S0V-3173A	FAILED TO OPEN.	DELAY	Y-87.1	
T004:070.ACC						
T004:070.DN	VALVE	S0V-3173A	FAILED TO OPEN.	DELAY COMPLY.		
T004:070.EN	VALVE	S0V-3173A	FAILED TO OPEN.	DELAY		
T004:070.PRE						
T004:070.TT						
T004:071	VALVE	S0V-3173A	POS. SWITCH	FAIL. DELAY	Y-87.1	
T004:071.ACC						
T004:071.DN	VALVE	S0V-3173A	POS. SWITCH	FAIL. DELAY CMP		
T004:071.EN						
T004:071.PRE						
T004:071.TT						
T004:072	VALVE	S0V-3173B	FAILED TO CLS.	DELAY	Y-87.2	
T004:072.ACC						
T004:072.DN	VALVE	S0V-3173B	FAILED TO CLS.	DELAY COMPLY.		
T004:072.EN	VALVE	S0V-3173B	FAILED TO CLS.	DELAY		
T004:072.PRE						
T004:072.TT						
T004:073	VALVE	S0V-3173B	FAILED TO OPEN.	DELAY	Y-87.2	
T004:073.ACC						
T004:073.DN	VALVE	S0V-3173B	FAILED TO OPEN.	DELAY COMPLY.		
T004:073.EN	VALVE	S0V-3173B	FAILED TO OPEN.	DELAY		
T004:073.PRE						
T004:073.TT						
T004:074	VALVE	S0V-3173B	POS. SWITCH	FAIL. DELAY	Y-87.2	
T004:074.ACC						
T004:074.DN	VALVE	S0V-3173B	POS. SWITCH	FAIL. DELAY CMP		
T004:074.EN						
T004:074.PRE						
T004:074.TT						
T004:075	VALVE	MOV-3156A	FAILED TO CLS.	DELAY	Y-89.1	
T004:075.ACC						
T004:075.DN	VALVE	MOV-3156A	FAILED TO CLS.	DELAY COMPLY.		
T004:075.EN	VALVE	MOV-3156A	FAILED TO CLS.	DELAY		
T004:075.PRE						
T004:075.TT						
T004:076	VALVE	MOV-3156A	FAILED TO OPEN.	DELAY	Y-89.1	
T004:076.ACC						
T004:076.DN	VALVE	MOV-3156A	FAILED TO OPEN.	DELAY COMPLY.		
T004:076.EN	VALVE	MOV-3156A	FAILED TO OPEN.	DELAY		
T004:076.PRE						
T004:076.TT						
T004:077	VALVE	MOV-3156A	POS. SWITCH	FAIL. DELAY	Y-89.1	
T004:077.ACC						
T004:077.DN	VALVE	MOV-3156A	POS. SWITCH	FAIL. DELAY CMP		
T004:077.EN						
T004:077.PRE						
T004:077.TT						
T004:078	VALVE	MOV-3156B	FAILED TO CLS.	DELAY	Y-89.2	
T004:078.ACC						
T004:078.DN	VALVE	MOV-3156B	FAILED TO CLS.	DELAY COMPLY.		
T004:078.EN	VALVE	MOV-3156B	FAILED TO CLS.	DELAY		
T004:078.PRE						
T004:078.TT						
T004:079	VALVE	MOV-3156B	FAILED TO OPEN.	DELAY	Y-89.2	
T004:079.ACC						
T004:079.DN	VALVE	MOV-3156B	FAILED TO OPEN.	DELAY COMPLY.		
T004:079.EN	VALVE	MOV-3156B	FAILED TO OPEN.	DELAY		

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00160

07:48:18 02/19/99

DB Form Report

Sorted By: Address

TO04:079.PRE					
TO04:079.TT					
TO04:080	VALVE	MOV-3156B	POS. SWITH	FAIL. DELAY	Y-89.2
TO04:080.ACC					
TO04:080.DN	VALVE	MOV-3156B	POS. SWITH	FAIL. DELAY CWP	
TO04:080.EN					
TO04:080.PRE					
TO04:080.TT					
TO04:081	COMMUN. LOSS	TIMER WITH	PCU-1		
TO04:081.ACC					
TO04:081.DN	COMMUN. LOSS	TIMER WITH	PCU-1	COMPLETE	
TO04:081.PRE					
TO04:081.TT					
TO04:082	COMMUN. LOSS	TIMER WITH	PCU-3		
TO04:082.ACC					
TO04:082.DN	COMMUN. LOSS	TIMER WITH	PCU-3	COMPLETE	
TO04:082.PRE					
TO04:082.TT					
TO04:083	COMMUN. LOSS	TIMER WITH	PCU-4		
TO04:083.ACC					
TO04:083.DN	COMMUN. LOSS	TIMER WITH	PCU-4	COMPLETE	
TO04:083.PRE					
TO04:083.TT					
TO04:084	COMMUN. LOSS	TIMER WITH	PCU-5		
TO04:084.ACC					
TO04:084.DN	COMMUN. LOSS	TIMER WITH	PCU-5	COMPLETE	
TO04:084.PRE					
TO04:084.TT					
RO06:000	TWO SCAN SUB-	DIVISIONS	CONTROL	REGISTER	
RO06:000.EN	TWO SCAN SUB-	DIVISIONS	CONTROL	ENABLED	
RO06:000.UL					
RO06:010	TWO SCAN SUB-	DIVISIONS	CONTROL	UNLOAD	
RO06:011	COMPARE	PCU-2 TO PCU-1	MSG FILE	WITH PREVIOUS	
RO06:012	COMPARE	PCU-2 TO PCU-3	MSG FILE	WITH PREVIOUS	
RO06:013	COMPARE	PCU-2 TO PCU-4	MSG FILE	WITH PREVIOUS	
RO06:014	COMPARE	PCU-2 TO PCU-5	MSG FILE	WITH PREVIOUS	
NO07:000	PUMP P-3125A	MOTOR INBOARD	BEARING HIGH	TEMP. ALARM	THRESHOLD
NO07:001	PUMP P-3125A	MOTOR OUTBOARD	BEARING HIGH	TEMP. ALARM	THRESHOLD
NO07:002	PUMP P-3125A	MOTOR INBOARD	BEARING HIGH	TEMP. FAULT	THRESHOLD
NO07:003	PUMP P-3125A	MOTOR OUTBOARD	BEARING HIGH	TEMP. FAULT	THRESHOLD
NO07:004	PUMP P-3125A-1	BEARING HIGH	VIBRATION ALM	THRESHOLD	
NO07:005	PUMP P-3125A-2	BEARING HIGH	VIBRATION ALM	THRESHOLD	
NO07:006	PUMP P-3125A-1	BEARING HIGH	VIBRATION FLT	THRESHOLD	
NO07:007	PUMP P-3125A-2	BEARING HIGH	VIBRATION FLT	THRESHOLD	
NO07:008	VALVE	SOV-3173A/B	PRESSURE -	POSSIBLE LEAK	THRESHOLD
NO07:009	VALVE	SOV-3182A/B	PRESSURE -	POSSIBLE LEAK	THRESHOLD
NO07:010	VALVE	SOV-3183A/B	PRESSURE -	POSSIBLE LEAK	THRESHOLD
NO07:011	PUMP P-3125B	MOTOR INBOARD	BEARING HIGH	TEMP. ALARM	THRESHOLD
NO07:012	PUMP P-3125B	MOTOR OUTBOARD	BEARING HIGH	TEMP. ALARM	THRESHOLD
NO07:013	PUMP P-3125B	MOTOR INBOARD	BEARING HIGH	TEMP. FAULT	THRESHOLD
NO07:014	PUMP P-3125B	MOTOR OUTBOARD	BEARING HIGH	TEMP. FAULT	THRESHOLD
NO07:015	PUMP P-3125B-1	BEARING HIGH	VIBRATION ALM	THRESHOLD	
NO07:016	PUMP P-3125B-2	BEARING HIGH	VIBRATION ALM	THRESHOLD	
NO07:017	PUMP P-3125B-1	BEARING HIGH	VIBRATION FLT	THRESHOLD	
NO07:018	PUMP P-3125B-2	BEARING HIGH	VIBRATION FLT	THRESHOLD	
NO07:019	PUMP P-3125A/B	OUTLET FLOW /	DRIVE SPEED	REF WORKING	REGISTER
NO07:022	PUMP P-3125A	HIGH INLET	PRESSURE	THRESHOLD	
NO07:023	PUMP P-3125B	HIGH INLET	PRESSURE	THRESHOLD	
NO07:024	PUMP P-3125A	LOW INLET	PRESSURE	THRESHOLD	
NO07:025	PUMP P-3125B	LOW INLET	PRESSURE	THRESHOLD	
NO07:026	PUMP P-3125A	MINIMUM OUTLET	PRESSURE	THRESHOLD	
NO07:027	PUMP P-3125A	HIGH OUTLET	PRESSURE	THRESHOLD	
NO07:028	PUMP P-3125B	MINIMUM OUTLET	PRESSURE	THRESHOLD	
NO07:029	PUMP P-3125B	HIGH OUTLET	PRESSURE	THRESHOLD	
NO07:030	SUPERNATE LINE	WT-SNL-3150	PRESSURE	INTERLOCK	THRESHOLD
NO07:300	S.P. RAMP BLOCK	TARGET S.P.	WORKING REGISTER		
NO07:301	S.P. RAMP BLOCK	CURRENT S.P.	WORKING REGISTER		
NO07:302	S.P. RAMP BLOCK	S.P. DIFFERENCE	WORKING REGISTER		
NO07:302/015	S.P. RAMP BLOCK	S.P. DIFFERENCE	WORKING REGISTER	SIGN BIT	RAMP DIFF NEG
NO07:303	S.P. RAMP BLOCK	ABSOLUTE VALUE	WORKING REGISTER		
NO07:304	S.P. RAMP BLOCK	RAMP INCREMENT	LIMIT	WORKING REGISTER	
NO07:310	RAMP SPEED	REFERENCE	TARGET	SET POINT	
NO07:311	RAMP SPEED	REFERENCE	CURRENT	SET POINT	
NO07:312	SPEED RAMP	REFERENCE	TO SET POINT	DIFFERENCE	
NO07:313	SPEED RAMP	REFERENCE	TO SET POINT	DIFFERENCE	ABSOLUTE VALUE
NO07:314	SPEED	REFERENCE	TO SET POINT	DIFFERENCE	
NO07:315	RAMP SPEED	REFERENCE	INCREMENT LIMIT	THRESHOLD	
NO10:000	REGISTER FOR	VERIFYING	LOW SPEED	THRESHOLD	
			FAULT ROUTINE	FILE OPERATION	

Hanford Cross Site Transfer System (PCU-2)

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00161

DB Form Report

Sorted By: Address

07:48:18 02/19/99

N010:007	Logical Rack	Fault Status	For Racks 0-7	And Racks 10-17	
N010:008	Last	program	scan time	ladder &	SFC
N010:009	Maximum	program	scan time	ladder &	SFC
N010:010					
N010:010/000	Battery	is bad or	missing		
N010:010/001	DH+ active	node table	changed		
N010:010/002	STI	overlap			
N010:010/003	EEPROM	trans-	ferred		
N010:010/004	Edits	prevent	SFC	continuing	
N010:010/005	Invalid	I/O status	file		
N010:010/006	Memory	cartridge	battery	low	
N010:010/007	No more	command	blocks	exist	
N010:010/009	No MCP was	configured	to run		
N010:010/010	MCP not	allowed			
N010:010/011	P11 word	number	isn't in	Local rack	
N010:010/012	User P11	routine	overlap		
N010:010/013	No command	block	exists to	get P11	
N010:010/014	Arithmetic	overflow	occurred		
N010:010/015	SFC	lingering	action	overlap	
N010:011					
N010:011/000	Bad	program	file		
N010:011/001	Bad	address	in ladder	program	
N010:011/002	Programmer	error			
N010:011/003	SFC Fault				
N010:011/004	Program	assembly	error		
N010:011/005	Powerup	protection	fault		
N010:011/006	Error not	defined			
N010:011/007	User	generated	fault		
N010:011/008	Watchdog	timer	fault		
N010:011/009	Bad system	config-	uration		
N010:011/010					
N010:011/011	Hardware	Error			
N010:011/011	MCP file	does not	exist or	is not	ladder
N010:011/012	P11 file	does not	exist or	is not	ladder
N010:011/013	STI file	does not	exist or	is not	ladder
N010:011/014	Fault file	does not	exist or	is not	ladder
N010:011/015	Non ladder	file			
N010:012	Fault Code				
N010:013	Program	file where	fault	occurred	
N010:014	Rung	number	where	fault	occurred
N010:015					
N010:016	I/O status	file			
N010:017	REGISTER FOR	VERIFYING	FAULTY ROUTINE	FILE OPERATION	
N010:017/000	Queue full	between	local and	remote I/O	
N010:017/001	Queue full	servicing	channel 1A		
N010:017/002	Queue full	servicing	channel 1B		
N010:017/003	Queue full	servicing	channel 2A		
N010:017/004	Queue full	servicing	channel 2B		
N010:017/005	No modem	on serial	port		
N010:017/006	Remote I/O	is greater	than image	size	
N010:017/008	ASCII	instruct-	ion error		
N010:017/009					
N010:018	Duplicate	node	address		
N010:019	Real time	clock YEAR			
N010:020	Real time	clock	MONTH		
N010:021	Real time	clock DAY			
N010:022	Real time	clock HOUR			
N010:023	Real time	clock	MINUTE		
MG011:000	SEND MSG	FROM PCU-2	TO PCU-1		
MG011:001	SEND MSG	FROM PCU-2	TO PCU-3		
MG011:002	SEND MSG	FROM PCU-2	TO PCU-4		
MG011:003	SEND MSG	FROM PCU-2	TO PCU-5		
BT012:000					
BT012:001					
BT012:006					
BT012:007					
BT012:008					
BT012:009					
BT012:010					
BT012:011					
BT012:012					
BT012:013					
N013:001/015	R.T.D. MODULE	POWERED UP BUT	NOT CONFIGURED		
N013:004/000	R.T.D. MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:004/001	R.T.D. MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:005	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N013:006/000	R.T.D. MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:006/001	R.T.D. MODULE	CHAN. 2 DATA	UNDERRANGE		

TE-3125B1R

Hanford Cross Site Transfer System (PCU-2)

 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00162

DB Form Report Sorted By: Address

07:48:19 02/19/99

N013:007	TE-3125B2R	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N013:008/000		R.T.D. MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:008/001		R.T.D. MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:009	TE-3125A1R	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N013:010/000		R.T.D. MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:010/001		R.T.D. MODULE	CHAN. 4 DATA	OVERRRANGE		
N013:011	TE-3125A2R	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N013:012/000		R.T.D. MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:012/001		R.T.D. MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:013		SPARE	R.T.D. TEMP.	INPUT		
N013:014/000		R.T.D. MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:014/001		R.T.D. MODULE	CHAN. 6 DATA	OVERRRANGE		
N013:015		SPARE	R.T.D. TEMP.	INPUT		
N013:016/000		R.T.D. MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:016/001		R.T.D. MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:017		SPARE	R.T.D. TEMP.	INPUT		
N013:018/000		R.T.D. MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:018/001		R.T.D. MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:019		SPARE	R.T.D. TEMP.	INPUT		
N013:262/015		THERM. MODULE	POWERED UP BUT	NOT CONFIGURED		
N013:265/000		THERM. MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:265/001		THERM. MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:266	TE-3125AR	PUMP P-3125A/B	OUTLET FLOW	TEMPERATURE	WT-SLL-3160	
N013:267/000		THERM. MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:267/001		THERM. MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:268		SPARE	THERMOCOUPLE	INPUT		
N013:269/000		THERM. MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:269/001		THERM. MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:270	TE-3125BR	LINE	WT-SNL-3150	TEMPERATURE		
N013:271/000		THERM. MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:271		SPARE	THERMOCOUPLE	INPUT		
N013:273/000		THERM. MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:273/001		THERM. MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:274		SPARE	THERMOCOUPLE	INPUT		
N013:275/000		THERM. MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:275/001		THERM. MODULE	CHAN. 6 DATA	OVERRRANGE		
N013:276		SPARE	THERMOCOUPLE	INPUT		
N013:277/000		THERM. MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:277/001		THERM. MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:278		SPARE	THERMOCOUPLE	INPUT		
N013:279/000		THERM. MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:279/001		THERM. MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:280		SPARE	THERMOCOUPLE	INPUT		
N013:348/000		ANALOG MODULE	POWERED UP BUT	NOT CONFIGURED	RANGE	
N013:348/001		ONE OR MORE	CHANNELS ARE	UNDER OR OVER		
N013:349		ANALOG MODULE	UNDERRANGE	BITS REGISTER		
N013:349/000		ANALOG MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:349/001		ANALOG MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:349/002		ANALOG MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:349/003		ANALOG MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:349/004		ANALOG MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:349/005		ANALOG MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:349/006		ANALOG MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:349/007		ANALOG MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:350		ANALOG MODULE	OVERRRANGE	BITS REGISTER		
N013:350/000		ANALOG MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:350/001		ANALOG MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:350/002		ANALOG MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:350/003		ANALOG MODULE	CHAN. 4 DATA	OVERRRANGE		TE-3125B1 TE-3125B2
N013:350/004		ANALOG MODULE	CHAN. 5 DATA	OVERRRANGE		TE-3125A1
N013:350/005		ANALOG MODULE	CHAN. 6 DATA	OVERRRANGE		TE-3125A2
N013:350/006		ANALOG MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:350/007		ANALOG MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:352	FT-3125R	PUMP	P-3125 A/B	OUTLET FLOW	TE-3125A	
N013:353	PT-3125AR	PUMP P-3125A	INLET	PRESSURE		
N013:354	PT-3125BR	PUMP P-3125B	INLET	PRESSURE	TE-3125B	
N013:355	PT-3125CR	PUMP P-3125A	OUTLET	PRESSURE		
N013:356	PT-3125DR	PUMP P-3125B	OUTLET	PRESSURE		
N013:357	PT-3125ER	LINE	WT-SNL-3150	PRESSURE	FT-3125	
N013:358	ST-3125AR	MOTOR SPEED	PUMP P-3125A			PT-3125A
N013:359	ST-3125BR	MOTOR SPEED	PUMP P-3125B			PT-3125B
N013:405/000		ANALOG MODULE	POWERED UP BUT	NOT CONFIGURED		PT-3125C
N013:405/001		ONE OR MORE	CHANNELS ARE	UNDER OR OVER	RANGE	PT-3125D
N013:406		ANALOG MODULE	UNDERRANGE	BITS REGISTER		PT-3125E
N013:406/000		ANALOG MODULE	CHAN. 1 DATA	UNDERRANGE		ST-3125A
N013:406/001		ANALOG MODULE	CHAN. 2 DATA	UNDERRANGE		ST-3125B

Hanford Cross Site Transfer System (PCU-2)

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00163

DB Form Report

Sorted By: Address

07:48:19 02/19/99

N013:406/002		ANALOG MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:406/003		ANALOG MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:406/004		ANALOG MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:406/005		ANALOG MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:406/006		ANALOG MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:406/007		ANALOG MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:407		ANALOG MODULE	OVERRRANGE	BITS REGISTER		
N013:407/000		ANALOG MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:407/001		ANALOG MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:407/002		ANALOG MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:407/003		ANALOG MODULE	CHAN. 4 DATA	OVERRRANGE		
N013:407/004		ANALOG MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:407/005		ANALOG MODULE	CHAN. 6 DATA	OVERRRANGE		
N013:407/006		ANALOG MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:407/007		ANALOG MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:409	VT-3125A1R	PUMP P-3125A	BEARING	VIBRATION		
N013:410	VT-3125B1R	PUMP P-3125B	BEARING	VIBRATION		
N013:411	VT-3125A2R	PUMP P-3125A	BEARING	VIBRATION		
N013:412	VT-3125B2R	PUMP P-3125B	BEARING	VIBRATION		
N013:413	PT-3173R	VALVE	SOV-3173A/B	PRESSURE		
N013:414	PT-3182R	VALVE	SOV-3182A/B	PRESSURE		
N013:415	PT-3183R	VALVE	SOV-3183A/B	PRESSURE		
N013:416		SPARE	ANALOG	INPUT		
N013:467	VSD-3125AR	PUMP P-3125A	OUTLET FLOW	CONTROL	SIGNAL	
N013:468	VSD-3125BR	PUMP P-3125B	OUTLET FLOW	CONTROL	SIGNAL	
N013:469		SPARE	ANALOG	OUTPUT		
N013:470		SPARE	ANALOG	OUTPUT		
N014:000						
N014:000/000	HB PLC2_OCS	HEARTBEAT	FROM PLC-2	TO OCS		
N014:000/001	COM-21	COMMUN. WITH	PCU-1	IGNORED		
N014:000/002	COM-2_OCS	COMMUN. WITH	PCS	IGNORED		
N014:000/003	COM-23	COMMUN. WITH	PCU-3	IGNORED		
N014:000/004	COM-24	COMMUN. WITH	PCU-4	IGNORED		
N014:000/005	COM-25	COMMUN. WITH	PCU-5	IGNORED		
N014:000/006	BATT_BAD_PLC2	PLC-2 BATTERY	IS BAD OR	MISSING		
N014:000/007						
N014:000/008						
N014:000/009						
N014:000/010	PAH-3173	VALVE	SOV-3173A/B	FAILURE		Y-73.1
N014:000/011	PAH-3182	VALVE	SOV-3182A/B	FAILURE		
N014:000/012	PAH-3183	VALVE	SOV-3183A/B	FAILURE		
N014:000/013	LDA-3150	LEAK DETECTED	AT DIVERSION	BOX 624T-A	SUMP	Y-72.1
N014:000/014	XA-3125A	BOOSTER	P-3125A	FAILURE	FAILURE	Y-74.1
N014:000/015	XA-3125B	BOOSTER	P-3125B	FAILURE	FAILURE	Y-74.2
N014:001/000						
N014:001/001						
N014:001/002						
N014:001/003						
N014:001/004	ZA-3182A2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:001/005						
N014:001/006	ZA-3182A1	VALVE	FAILED	TO OPEN		Y-71.1
N014:001/007						
N014:001/008	ZA-3182A	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:001/009						
N014:001/010						
N014:001/011						
N014:001/012	ZA-3182B2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:001/013						
N014:001/014	ZA-3182B1	VALVE	FAILED	TO OPEN		Y-71.1
N014:001/015						
N014:002/000	ZA-3182B	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:002/001	ZA-3183A2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:002/002						
N014:002/003	ZA-3183A1	VALVE	FAILED	TO OPEN		Y-71.1
N014:002/004						
N014:002/005	ZA-3183A	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:002/006	ZA-3183B2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:002/007						
N014:002/008	ZA-3183B1	VALVE	FAILED	TO OPEN		Y-71.1
N014:002/009						
N014:002/010						
N014:002/011	ZA-3183B	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:002/012						
N014:002/013						
N014:002/014	ZA-3184-2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:002/015						
N014:003/000	ZA-3184-1	VALVE	FAILED	TO OPEN		Y-71.1

Hanford Cross Site Transfer System (PCU-2)

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00164

DB Form Report

Sorted By: Address

07:48:19 02/19/99

N014:003/001	ZA-3184	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:003/002						
N014:003/003						
N014:003/004						
N014:003/005						
N014:003/006						
N014:003/007						
N014:003/008						
N014:003/009						
N014:003/010						
N014:003/011						
N014:003/012						
N014:003/013						
N014:003/014						
N014:003/015						
N014:006/000	TAH-3125A1	PUMP P-3125A	INBOARD	BEARING HIGH	TEMP. ALARM	Y-76.1
N014:006/001	TAH-3125A2	PUMP P-3125A	OUTBOARD	BEARING HIGH	TEMP. ALARM	Y-76.1
N014:006/002	PAH-3125C	BOOSTER	PUMP HIGH	DISCHARGE	PRESSURE	Y-78.1
N014:006/003	PAH-3125A	BOOSTER	PUMP HIGH	INLET	PRESSURE	Y-75.1
N014:006/004	PAL-3125A	BOOSTER PUMP	LOW INLET	PRESSURE		Y-74.1
N014:006/005						
N014:006/006	VAH-3125A1	PUMP P-3125A	HIGH MOTOR	VIBRATION	ALARM	Y-76.1
N014:006/007	VAH-3125A2	PUMP P-3125A	HIGH MOTOR	VIBRATION	ALARM	Y-76.1
N014:006/008						
N014:006/009						
N014:006/010						
N014:006/011						
N014:006/012						
N014:006/013						
N014:006/014						
N014:006/015						
N014:007/000	TAH-3125B1	PUMP P-3125B	INBOARD	BEARING HIGH	TEMP. ALARM	Y-76.1
N014:007/001	TAH-3125B2	PUMP P-3125B	OUTBOARD	BEARING HIGH	TEMP. ALARM	Y-76.1
N014:007/002	PAH-3125D	BOOSTER	PUMP HIGH	DISCHARGE	PRESSURE	Y-78.1
N014:007/003	PAH-3125B	BOOSTER	PUMP HIGH	INLET	PRESSURE	Y-75.1
N014:007/004	PAL-3125B	BOOSTER PUMP	LOW INLET	PRESSURE		Y-74.2
N014:007/005						
N014:007/006	VAH-3125B1	PUMP P-3125B	HIGH MOTOR	VIBRATION	ALARM	Y-76.1
N014:007/007	VAH-3125B2	PUMP P-3125B	HIGH MOTOR	VIBRATION	ALARM	Y-76.1
N014:007/008						
N014:007/009						
N014:007/010						
N014:007/011						
N014:007/012						
N014:007/013						
N014:007/014						
N014:007/015						
N014:008/000	ZA-3125E2	VALVE	SOV-3125E	FAILED TO	CLOSE	Y-83.1
N014:008/001						
N014:008/002	ZA-3125E1	VALVE	SOV-3125E	FAILED TO	OPEN	Y-83.1
N014:008/003						
N014:008/004	ZA-3125E	VALVE	SOV-3125E	POSITION	SWITCH FAILURE	Y-83.1
N014:008/005	ZA-3125C2	VALVE	SOV-3125C	FAILED TO	CLOSE	Y-84.1
N014:008/006						
N014:008/007	ZA-3125C1	VALVE	SOV-3125C	FAILED TO	OPEN	Y-84.1
N014:008/008						
N014:008/009	ZA-3125C	VALVE	SOV-3125C	POSITION	SWITCH FAILURE	Y-84.1
N014:008/010	ZA-3125G2	VALVE	SOV-3125G	FAILED TO	CLOSE	Y-85.1
N014:008/011						
N014:008/012	ZA-3125G1	VALVE	SOV-3125G	FAILED TO	OPEN	Y-85.1
N014:008/013						
N014:008/014	ZA-3125G	VALVE	SOV-3125G	POSITION	SWITCH FAILURE	Y-85.1
N014:008/015	ZA-3125D2	VALVE	SOV-3125D	FAILED TO	CLOSE	Y-86.1
N014:009/000						
N014:009/001	ZA-3125D1	VALVE	SOV-3125D	FAILED TO	OPEN	Y-86.1
N014:009/002						
N014:009/003	ZA-3125D	VALVE	SOV-3125D	POSITION	SWITCH FAILURE	Y-86.1
N014:009/004	ZA-3173A2	VALVE	SOV-3173A	FAILED TO	CLOSE	Y-87.1
N014:009/005						
N014:009/006	ZA-3173A1	VALVE	SOV-3173A	FAILED TO	OPEN	Y-87.1
N014:009/007						
N014:009/008	ZA-3173A	VALVE	SOV-3173A	POSITION	SWITCH FAILURE	Y-87.1
N014:009/009	ZA-3173B2	VALVE	SOV-3173B	FAILED TO	CLOSE	Y-87.2
N014:009/010						
N014:009/011	ZA-3173B1	VALVE	SOV-3173B	FAILED TO	OPEN	Y-87.2
N014:009/012						
N014:009/013	ZA-3173B	VALVE	SOV-3173B	POSITION	SWITCH FAILURE	Y-87.2

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page: 00165

DB Form Report

Sorted By: Address

07:48:20 02/19/99

N014:009/014	ZA-3156A2	VALVE	MOV-3156A	FAILED TO	CLOSE	Y-89.1
N014:009/015						
N014:010/000	ZA-3156A1	VALVE	MOV-3156A	FAILED TO	OPEN	Y-89.1
N014:010/001						
N014:010/002	ZA-3156A	VALVE	MOV-3156A	POSITION	SWITCH FAILURE	Y-89.1
N014:010/003	ZA-3156B2	VALVE	MOV-3156B	FAILED TO	CLOSE	Y-89.2
N014:010/004						
N014:010/005	ZA-3156B1	VALVE	MOV-3156B	FAILED TO	OPEN	Y-89.2
N014:010/006						
N014:010/007	ZA-3156B	VALVE	MOV-3156B	POSITION	SWITCH FAILURE	Y-89.2
N014:010/008						
N014:010/009						
N014:010/010						
N014:010/011						
N014:010/012						
N014:010/013						
N014:010/014						
N014:010/015						
N014:011						
N014:011/000	TI-3125B1_A	PCU-2 INPUT	OVER AND UNDER R.T.D. TEMP.	RANGE STATUS OVER OR UNDER	BITS TO G11 RANGE ALARM	
N014:011/001	TI-3125B2_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/002	TI-3125A1_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/003	TI-3125A2_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/004	PCU2-SP-R1-5_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/005	PCU2-SP-R1-6_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/006	PCU2-SP-R1-7_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/007	PCU2-SP-R1-8_A	PCU-2 INPUT	R.T.D. TEMP.	OVER OR UNDER	RANGE ALARM	
N014:011/008						
N014:011/009						
N014:011/010						
N014:011/011						
N014:011/012						
N014:011/013						
N014:011/014						
N014:011/015						
N014:012/000						
N014:012/001						
N014:012/002						
N014:012/003						
N014:012/004						
N014:012/005						
N014:012/006						
N014:012/007						
N014:012/008	TI-3125A_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/009	PCU2-SP-T1-2_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/010	TI-3125B_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/011	PCU2-SP-T1-4_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/012	PCU2-SP-T1-5_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/013	PCU2-SP-T1-6_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/014	PCU2-SP-T1-7_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/015	PCU2-SP-T1-8_A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:013/000	FIC-3125A_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/001	PI-3125A_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/002	PI-3125B_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/003	PI-3125C_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/004	PI-3125D_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/005	PI-3125E_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/006	SI-3125A_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/007	SI-3125B_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:013/008						
N014:013/009						
N014:013/010						
N014:013/011						
N014:013/012						
N014:013/013						
N014:013/014						
N014:013/015						
N014:014/000						
N014:014/001						
N014:014/002						
N014:014/003						
N014:014/004						
N014:014/005						
N014:014/006						
N014:014/007						
N014:014/008	VI-3125A1_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:014/009	VI-3125B1_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00166

DB Form Report

Sorted By: Address

07:48:20 02/19/99

N014:014/010	VI-3125A2_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:014/011	VI-3125B2_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:014/012	PI-3173_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:014/013	PI-3182_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:014/014	PI-3183_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:014/015	PCU2-SP-AT-8_A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:016		DIGITAL INPUT	REGISTER TO	OIT TERMINALS		
N014:016/000	ZLH-3125BA	MOV-3125BA	IS OPEN			Y80-1
N014:016/001	ZLL-3125BA	MOV-3125BA	IS CLOSED			Y81-1
N014:016/002	ZLH-3125BB	MOV-3125BB	IS OPEN			Y80-1
N014:016/003	ZLL-3125BB	MOV-3125BB	IS CLOSED			Y81-1
N014:016/004	ZLH-3125BC	MOV-3125BC	IS OPEN			Y80-1
N014:016/005	ZLL-3125BC	MOV-3125BC	IS CLOSED			Y81-1
N014:016/006	ZLH-3125BD	MOV-3125BD	IS OPEN			Y80-1
N014:016/007	ZLL-3125BD	MOV-3125BD	IS CLOSED			Y81-1
N014:016/008	ZLH-3125BE	MOV-3125BE	IS OPEN			Y80-1
N014:016/009	ZLL-3125BE	MOV-3125BE	IS CLOSED			Y81-1
N014:016/010	ZLH-3125BF	MOV-3125BF	IS OPEN			Y80-1
N014:016/011	ZLL-3125BF	MOV-3125BF	IS CLOSED			Y81-1
N014:016/012	ZLH-3125BG	MOV-3125BG	IS OPEN			Y80-1
N014:016/013	ZLL-3125BG	MOV-3125BG	IS CLOSED			Y81-1
N014:016/014	ZLH-3125BH	MOV-3125BH	IS OPEN			Y80-1
N014:016/015	ZLL-3125BH	MOV-3125BH	IS CLOSED			Y81-1
N014:017/000	ZLH-3125BJ	MOV-3125BJ	IS OPEN			Y81-2
N014:017/001	ZLL-3125BJ	MOV-3125BJ	IS CLOSED			Y81-2
N014:017/002	ZLH-3125BK	MOV-3125BK	IS OPEN			Y81-2
N014:017/003	ZLL-3125BK	MOV-3125BK	IS CLOSED			Y81-2
N014:017/004	PCU2-SP-121-04	SPARE	DIGITAL	INPUT		
N014:017/005	PCU2-SP-121-05	SPARE	DIGITAL	INPUT		
N014:017/006	PCU2-SP-121-06	SPARE	DIGITAL	INPUT		
N014:017/007	PCU2-SP-121-07	SPARE	DIGITAL	INPUT		
N014:017/008	PCU2-SP-121-10	SPARE	DIGITAL	INPUT		
N014:017/009	PCU2-SP-121-11	SPARE	DIGITAL	INPUT		
N014:017/010	PCU2-SP-121-12	SPARE	DIGITAL	INPUT		
N014:017/011	PCU2-SP-121-13	SPARE	DIGITAL	INPUT		
N014:017/012	PCU2-SP-121-14	SPARE	DIGITAL	INPUT		
N014:017/013	PCU2-SP-121-15	SPARE	DIGITAL	INPUT		
N014:017/014	PCU2-SP-121-16	SPARE	DIGITAL	INPUT		
N014:017/015	PCU2-SP-121-17	SPARE	DIGITAL	INPUT		
N014:018/000	ZLH-3125AA	MOV-3125AA	IS OPEN			Y79-1
N014:018/001	ZLL-3125AA	MOV-3125AA	IS CLOSED			Y80-1
N014:018/002	ZLH-3125AB	MOV-3125AB	IS OPEN			Y79-1
N014:018/003	ZLL-3125AB	MOV-3125AB	IS CLOSED			Y80-1
N014:018/004	ZLH-3125AC	MOV-3125AC	IS OPEN			Y79-1
N014:018/005	ZLL-3125AC	MOV-3125AC	IS CLOSED			Y80-1
N014:018/006	ZLH-3125AD	MOV-3125AD	IS OPEN			Y79-1
N014:018/007	ZLL-3125AD	MOV-3125AD	IS CLOSED			Y80-1
N014:018/008	ZLH-3125AE	MOV-3125AE	IS OPEN			Y80-1
N014:018/009	ZLL-3125AE	MOV-3125AE	IS CLOSED			Y79-1
N014:018/010	ZLH-3125AF	MOV-3125AF	IS OPEN			Y79-1
N014:018/011	ZLL-3125AF	MOV-3125AF	IS CLOSED			Y80-1
N014:018/012	ZLH-3125AG	MOV-3125AG	IS OPEN			Y79-1
N014:018/013	ZLL-3125AG	MOV-3125AG	IS CLOSED			Y80-1
N014:018/014	ZLH-3125AH	MOV-3125AH	IS OPEN			Y79-1
N014:018/015	ZLL-3125AH	MOV-3125AH	IS CLOSED			Y80-1
N014:019/000	ZLH-3125AJ	MOV-3125AJ	IS OPEN			Y79-2
N014:019/001	ZLL-3125AJ	MOV-3125AJ	IS CLOSED			Y80-2
N014:019/002	ZLH-3125AK	MOV-3125AK	IS OPEN			Y79-2
N014:019/003	ZLL-3125AK	MOV-3125AK	IS CLOSED			Y80-2
N014:019/004	YA-3101A	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/005	YA-3101B	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/006	YA-3101C	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/007	YA-3101D	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/008	YA-3101E	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/009	YA-3101F	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/010	YA-3101G	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/011	YA-3101H	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	OIT
N014:019/012	PCU2-SP-123-14	SPARE	DIGITAL	INPUT		
N014:019/013	PCU2-SP-123-15	SPARE	DIGITAL	INPUT		
N014:019/014	PCU2-SP-123-16	SPARE	DIGITAL	INPUT		
N014:019/015	PCU2-SP-123-17	SPARE	DIGITAL	INPUT		
N014:020/000	ZLH-3125C	SOV-3125C	IS OPEN			Y84-1
N014:020/001	ZLL-3125C	SOV-3125C	IS CLOSED			Y84-1
N014:020/002	ZLH-3125D	SOV-3125D	IS OPEN			Y86-1
N014:020/003	ZLL-3125D	SOV-3125D	IS CLOSED			Y86-1
N014:020/004	ZLH-3125E	SOV-3125E	IS OPEN			Y83-1
N014:020/005	ZLL-3125E	SOV-3125E	IS CLOSED			Y83-1

Hanford Cross Site Transfer System (PCU-2)

WLS - Data Base Form Report
Lockheed Martin Hanford Co.

DB Form Report

Sorted By: Address

Page:00167

07:48:21 02/19/99

N014:020/006	ZLH-31256	SOV-3125G	IS OPEN				Y85-1
N014:020/007	ZLL-31256	SOV-3125G	IS CLOSED				Y85-1
N014:020/008	ZLH-3173B	SOV-3173B	IS OPEN				Y87-2
N014:020/009	ZLL-3173B	SOV-3173B	IS CLOSED				Y89-2
N014:020/010	ZLH-3156B	MOV-3156B	IS OPEN				Y89-2
N014:020/011	ZLL-3156B	MOV-3156B	IS CLOSED				Y89-2
N014:020/012	ZLH-3163	SOV-3163	IS OPEN				
N014:020/013	ZLL-3163	SOV-3163	IS CLOSED				
N014:020/014	ZLH-3173A	SOV-3173A	IS OPEN				Y87-1
N014:020/015	ZLL-3173A	SOV-3173A	IS CLOSED				Y87-1
N014:021/000	ZLH-3182A	SOV-3182A	IS OPEN				Y71
N014:021/001	ZLL-3182A	SOV-3182A	IS CLOSED				Y71
N014:021/002	ZLH-3182B	SOV-3182B	IS OPEN				Y71
N014:021/003	ZLL-3182B	SOV-3182B	IS CLOSED				Y71
N014:021/004	ZLH-3183A	SOV-3183A	IS OPEN				Y71
N014:021/005	ZLL-3183A	SOV-3183A	IS CLOSED				Y71
N014:021/006	ZLH-3183B	SOV-3183B	IS OPEN				Y71
N014:021/007	ZLL-3183B	SOV-3183B	IS CLOSED				Y71
N014:021/008	ZLH-3184	SOV-3184	IS OPEN				Y71
N014:021/009	ZLL-3184	SOV-3184	IS CLOSED				Y71
N014:021/010	ZLH-3156A	MOV-3156A	IS OPEN				Y89-1
N014:021/011	ZLL-3156A	MOV-3156A	IS CLOSED				Y89-1
N014:021/012	YL-3125A3	LOCAL/REMOTE	STATUS FOR	P-3125A			OIT
N014:021/013	YL-3125B3	LOCAL/REMOTE	STATUS FOR	P-3125B			OIT
N014:021/014	TAH-3125A	PUMP P-3125A	MOTOR WINDING	TEMP. HIGH		OFF = ALARM	Y76
N014:021/015	TAH-3125B	PUMP P-3125B	MOTOR WINDING	TEMP. HIGH		OFF = ALARM	Y76
N014:022/000	FAH-3125A1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A			Y76
N014:022/001	FAH-3125A2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A			Y76
N014:022/002	FAH-3125B1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B			Y76
N014:022/003	FAH-3125B2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B			Y76
N014:022/004	LAL-3125A1	PUMP P-3125A	LOW OIL LEVEL	OFF = ALARM			Y76
N014:022/005	LAL-3125A2	PUMP P-3125A	LOW OIL LEVEL	OFF = ALARM			Y76
N014:022/006	LAL-3125B1	PUMP P-3125B	LOW OIL LEVEL	OFF = ALARM			Y76
N014:022/007	LAL-3125B2	PUMP P-3125B	LOW OIL LEVEL	OFF = ALARM			Y76
N014:022/008	LDAH-3150	SUMP LEAK	DETECTOR	FAILURE			Y72
N014:022/009	LDA-3160	6241-A	ENCASEMENT	LEAK DETECTION		OFF = ALARM	Y72
N014:022/010	LDXA-3150	6241-A SUMP	LEAK DETECTION				Y72
N014:022/011	PAL-3125A2	PUMP P-3125A	SEAL FAILURE				Y76
N014:022/012	PAL-3125B1	PUMP P-3125B	SEAL FAILURE				Y76
N014:022/013	PAL-3125B2	PUMP P-3125B	SEAL FAILURE				Y76
N014:022/014	PAL-3100A	LOW	COMPRESSOR	SA-CMP-3101A		PRESSURE	
N014:022/015	PAL-3125A1	PUMP P-3125A	SEAL FAILURE				Y76
N014:023							
N014:024							
N014:025		DIGITAL OUTPUT	REGISTER TO	OIT TERMINALS			
N014:025/000	MOV-3125BA1	OPEN VALVE	MOV-3125BA				Y80-1
N014:025/001	MOV-3125BA2	CLOSE VALVE	MOV-3125BA				Y80-1
N014:025/002	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/003	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:025/004	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/005	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:025/006	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/007	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:025/008	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/009	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:025/010	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/011	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:025/012	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/013	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:025/014	MOV-3125B1	OPEN VALVE	MOV-3125B				Y80-1
N014:025/015	MOV-3125B2	CLOSE VALVE	MOV-3125B				Y80-1
N014:026/000	MOV-3125A1	OPEN VALVE	MOV-3125A				Y79-1
N014:026/001	MOV-3125A2	CLOSE VALVE	MOV-3125A				Y79-1
N014:026/002	MOV-3125AB1	OPEN VALVE	MOV-3125AB				Y79-1
N014:026/003	MOV-3125AB2	CLOSE VALVE	MOV-3125AB				Y79-1
N014:026/004	MOV-3125AC1	OPEN VALVE	MOV-3125AC				Y79-1
N014:026/005	MOV-3125AC2	CLOSE VALVE	MOV-3125AC				Y79-1
N014:026/006	MOV-3125AD1	OPEN VALVE	MOV-3125AD				Y79-1
N014:026/007	MOV-3125AD2	CLOSE VALVE	MOV-3125AD				Y79-1
N014:026/008	MOV-3125AE1	OPEN VALVE	MOV-3125AE				Y79-1
N014:026/009	MOV-3125AE2	CLOSE VALVE	MOV-3125AE				Y79-1
N014:026/010	MOV-3125AF1	OPEN VALVE	MOV-3125AF				Y79-1
N014:026/011	MOV-3125AF2	CLOSE VALVE	MOV-3125AF				Y79-1
N014:026/012	MOV-3125AG1	OPEN VALVE	MOV-3125AG				Y79-1
N014:026/013	MOV-3125AG2	CLOSE VALVE	MOV-3125AG				Y79-1
N014:026/014	MOV-3125AH1	OPEN VALVE	MOV-3125AH				Y79-1
N014:026/015	MOV-3125AH2	CLOSE VALVE	MOV-3125AH				Y79-1

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00168

DB Form Report. Sorted By: Address

07:48:21 02/19/99

N014:027/000	MOV-3125AJ1	OPEN VALVE	MOV-3125AJ			Y79-2
N014:027/001	MOV-3125AJ2	CLOSE VALVE	MOV-3125AJ			Y79-2
N014:027/002	MOV-3125AK1	OPEN VALVE	MOV-3125AK			Y79-2
N014:027/003	MOV-3125AK2	CLOSE VALVE	MOV-3125AK			Y79-2
N014:027/004	MOV-3125BJ1	OPEN VALVE	MOV-3125BJ			Y80-2
N014:027/005	MOV-3125BJ2	CLOSE VALVE	MOV-3125BJ			Y80-2
N014:027/006	MOV-3125BK1	OPEN VALVE	MOV-3125BK			Y80-2
N014:027/007	MOV-3125BK2	CLOSE VALVE	MOV-3125BK			Y80-2
N014:027/008	P-3125A1	START PUMP	P-3125A			Y74-1
N014:027/009	P-3125A2	STOP PUMP	P-3125A			Y74-1
N014:027/010	P-3125B1	START PUMP	P-3125B			Y74-2
N014:027/011	P-3125B2	STOP PUMP	P-3125B			Y74-2
N014:027/012	P-3115	SHUTDOWN	SUMP PUMP	P-3115		Y-82.1
N014:027/013	PCU2-SP-035-15	SPARE	DIGITAL	OUTPUT		
N014:027/014	PCU2-SP-035-16	SPARE	DIGITAL	OUTPUT		
N014:027/015	PCU2-SP-035-17	SPARE	DIGITAL	OUTPUT		
N014:028/000	SOV-3125C1	OPEN VALVE	SOV-3125C			Y-84
N014:028/001	SOV-3125C2	CLOSE VALVE	SOV-3125C			Y-84
N014:028/002	SOV-3125D1	OPEN VALVE	SOV-3125D			Y-86
N014:028/003	SOV-3125D2	CLOSE VALVE	SOV-3125D			Y-86
N014:028/004	SOV-3125E1	OPEN VALVE	SOV-3125E			Y-83
N014:028/005	SOV-3125E2	CLOSE VALVE	SOV-3125E			Y-83
N014:028/006	SOV-3125G1	OPEN VALVE	SOV-3125G			Y-85
N014:028/007	SOV-3125G2	CLOSE VALVE	SOV-3125G			Y-85
N014:028/008	MOV-3156B1	OPEN VALVE	MOV-3156B			Y89-2
N014:028/009	MOV-3156B2	CLOSE VALVE	MOV-3156B			Y89-2
N014:028/010	MOV-3156A1	OPEN VALVE	MOV-3156A			Y89-1
N014:028/011	MOV-3156A2	CLOSE VALVE	MOV-3156A			Y89-1
N014:028/012	SOV-3163-1	OPEN VALVE	SOV-3163			Y80-2
N014:028/013	SOV-3163-2	CLOSE VALVE	SOV-3163			Y80-2
N014:028/015	SOV-3173A2	CLOSE VALVE	SOV-3173A			Y87-1
N014:029/000	SOV-3173B1	OPEN VALVE	SOV-3173B			Y87-2
N014:029/001	SOV-3173B2	CLOSE VALVE	SOV-3173B			Y87-2
N014:029/002	SOV-3182A1	OPEN VALVE	SOV-3182A			Y71
N014:029/003	SOV-3182A2	CLOSE VALVE	SOV-3182A			Y71
N014:029/004	SOV-3182B1	OPEN VALVE	SOV-3182B			Y71
N014:029/005	SOV-3182B2	CLOSE VALVE	SOV-3182B			Y71
N014:029/006	SOV-3183A1	OPEN VALVE	SOV-3183A			Y71
N014:029/007	SOV-3183A2	CLOSE VALVE	SOV-3183A			Y71
N014:029/008	SOV-3183B1	OPEN VALVE	SOV-3183B			Y71
N014:029/009	SOV-3183B2	CLOSE VALVE	SOV-3183B			Y71
N014:029/010	SOV-3184-1	OPEN VALVE	SOV-3184			Y71
N014:029/011	SOV-3184-2	CLOSE VALVE	SOV-3184			Y71
N014:029/012	PCU2-SP-037-14	SPARE	DIGITAL	OUTPUT		
N014:029/013	PCU2-SP-037-15	SPARE	DIGITAL	OUTPUT		
N014:029/015	PCU2-SP-037-17	SPARE	DIGITAL	OUTPUT		
N014:030	TI-3125B1	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N014:031	TI-3125B2	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N014:032	TI-3125A1	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N014:033	TI-3125A2	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N014:034	PCU2-SP-R1-5	SPARE	R.T.D. TEMP.	INPUT		
N014:035	PCU2-SP-R1-6	SPARE	R.T.D. TEMP.	INPUT		
N014:036	PCU2-SP-R1-7	SPARE	R.T.D. TEMP.	INPUT		
N014:037	PCU2-SP-R1-8	SPARE	R.T.D. TEMP.	INPUT		
N014:038	TI-3125A	PUMP P-3125A/B	OUTLET FLOW	TEMPERATURE	WT-SLL-3160	
N014:039	PCU2-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014:040	TI-3125B	LINE	WT-SNL-3150	TEMPERATURE		
N014:041	PCU2-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014:042	PCU2-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014:043	PCU2-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014:044	PCU2-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		
N014:045	PCU2-SP-TI-8	SPARE	THERMOCOUPLE	INPUT		
N014:046	FIC-3125	PUMP	P-3125 A/B	OUTLET FLOW		
N014:047	PI-3125A	PUMP P-3125A	INLET	PRESSURE		
N014:048	PI-3125B	PUMP P-3125B	INLET	PRESSURE		
N014:049	PI-3125C	PUMP P-3125A	OUTLET	PRESSURE		
N014:050	PI-3125D	PUMP P-3125B	OUTLET	PRESSURE		
N014:051	PI-3125E	LINE	WT-SNL-3150	PRESSURE		
N014:052	SI-3125A	MOTOR SPEED	PUMP P-3125A			
N014:053	SI-3125B	MOTOR SPEED	PUMP P-3125B			
N014:054	VI-3125A1	PUMP P-3125A	BEARING	VIBRATION		
N014:055	VI-3125B1	PUMP P-3125B	BEARING	VIBRATION		
N014:056	VI-3125A2	PUMP P-3125A	BEARING	VIBRATION		
N014:057	VI-3125B2	PUMP P-3125B	BEARING	VIBRATION		
N014:058	PI-3173	VALVE	SOV-3173A/B	PRESSURE		
N014:059	PI-3182	VALVE	SOV-3182A/B	PRESSURE		
N014:060	PI-3183	VALVE	SOV-3183A/B	PRESSURE		

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00169

DB Form Report

Sorted By: Address

07:48:22 02/19/99

N014:0061	PCU2-SP-A1-8	SPARE	ANALOG	INPUT		
N014:0062	FIC-3125A	PUMP P-3125A	OUTLET FLOW	CONTROL	SIGNAL	
N014:0063	FIC-3125B	PUMP P-3125B	OUTLET FLOW	CONTROL	SIGNAL	
N014:0064	PCU2-SP-A0-3	SPARE	ANALOG	OUTPUT		
N014:0065	PCU2-SP-A0-4	SPARE	ANALOG	OUTPUT		
N014:0066						
N014:0067						
N014:0068						
N014:0069						
N014:0078	FIC-3125-E	PUMP	P-3125 A/B	OUTLET FLOW /	DRIVE SPEED	LOOP ERROR
N014:0079	FIC-3125-0	PUMP	P-3125 A/B	OUTLET FLOW /	DRIVE SPEED	REF OUTPUT
N014:120						
N014:120/000	HB_OCS_PLC2	HEARTBEAT	FROM OCS	TO PLC-2		
N014:120/001						
N014:120/002						
N014:120/003						
N014:120/004						
N014:120/005						
N014:120/006						
N014:120/007						
N014:120/008						
N014:120/009						
N014:120/010						
N014:120/011						
N014:120/012						
N014:120/013						
N014:120/014	HS-3182A1	OCS OPEN	VALVE	SOV-3182A		Y-71.1
N014:120/015	HS-3182A2	OCS CLOSE	VALVE	SOV-3182A		Y-71.1
N014:121/000						
N014:121/001						
N014:121/002						
N014:121/003	HS-3182B1	OCS OPEN	VALVE	SOV-3182B		Y-71.1
N014:121/004	HS-3182B2	OCS CLOSE	VALVE	SOV-3182B		Y-71.1
N014:121/005	HS-3183A1	OCS OPEN	VALVE	SOV-3183A		Y-71.1
N014:121/006	HS-3183A2	OCS CLOSE	VALVE	SOV-3183A		Y-71.1
N014:121/007	HS-3183B1	OCS OPEN	VALVE	SOV-3183B		Y-71.1
N014:121/008	HS-3183B2	OCS CLOSE	VALVE	SOV-3183B		Y-71.1
N014:121/009	HS-3184-1	OCS OPEN	VALVE	SOV-3184		Y-71.1
N014:121/010	HS-3184-2	OCS CLOSE	VALVE	SOV-3184		Y-71.1
N014:121/011						
N014:121/012						
N014:121/013						
N014:121/014						
N014:121/015						
N014:126/000	HS-3125A1	START	BOOSTER	PUMP	P-3125A	Y-74.1
N014:126/001	HS-3125A2	STOP	BOOSTER	PUMP	P-3125A	Y-74.1
N014:126/002	HS-3125B1	START	BOOSTER	PUMP	P-3125B	Y-74.2
N014:126/003	HS-3125B2	STOP	BOOSTER	PUMP	P-3125B	Y-74.2
N014:126/004	HS-3125-M	PID FOR PUMP	P-3125 A/B	MANUAL MODE		
N014:126/005	HS-3125AZ	RESET	VALVES FOR	PUMP P-3125A		Y-79.1
N014:126/006	HS-3125AA1	OPEN	VALVE	MOV-3125AA		Y-79.1
N014:126/007	HS-3125AA2	CLOSE	VALVE	MOV-3125AA		Y-79.1
N014:126/008	HS-3125AB1	OPEN	VALVE	MOV-3125AB		Y-79.1
N014:126/009	HS-3125AB2	CLOSE	VALVE	MOV-3125AB		Y-79.1
N014:126/010	HS-3125AC1	OPEN	VALVE	MOV-3125AC		Y-79.1
N014:126/011	HS-3125AC2	CLOSE	VALVE	MOV-3125AC		Y-79.1
N014:126/012	HS-3125AD1	OPEN	VALVE	MOV-3125AD		Y-79.1
N014:126/013	HS-3125AD2	CLOSE	VALVE	MOV-3125AD		Y-79.1
N014:126/014	HS-3125AE1	OPEN	VALVE	MOV-3125AE		Y-79.1
N014:126/015	HS-3125AE2	CLOSE	VALVE	MOV-3125AE		Y-79.1
N014:127/000	HS-3125AF1	OPEN	VALVE	MOV-3125AF		Y-79.1
N014:127/001	HS-3125AF2	CLOSE	VALVE	MOV-3125AF		Y-79.1
N014:127/002	HS-3125AG1	OPEN	VALVE	MOV-3125AG		Y-79.1
N014:127/003	HS-3125AG2	CLOSE	VALVE	MOV-3125AG		Y-79.1
N014:127/004	HS-3125AH1	OPEN	VALVE	MOV-3125AH		Y-79.1
N014:127/005	HS-3125AH2	CLOSE	VALVE	MOV-3125AH		Y-79.1
N014:127/006	HS-3125AJ1	OPEN	VALVE	MOV-3125AJ		Y-79.2
N014:127/007	HS-3125AJ2	CLOSE	VALVE	MOV-3125AJ		Y-79.2
N014:127/008	HS-3125AK1	OPEN	VALVE	MOV-3125AK		Y-79.2
N014:127/009	HS-3125AK2	CLOSE	VALVE	MOV-3125AK		Y-79.2
N014:127/010	HS-3163-1	OPEN	VALVE	MOV-3163		Y-79.2
N014:127/011	HS-3163-2	CLOSE	VALVE	MOV-3163		Y-79.2
N014:127/012	HS-3125BY	INITIATE	DRAINING OF	PUMP P-3125B		Y-80.1
N014:127/013	HS-3125BZ	RESET	VALVES FOR	PUMP P-3125B		Y-80.1
N014:127/014						
N014:127/015						
N014:128/000						

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

DB Form Report. Sorted By: Address

Page:00170

07:48:22 02/19/99

N014:128/001						
N014:128/002	HS-3125E1	OPEN VALVE	SOV-3125E			Y-83.1
N014:128/003	HS-3125E2	CLOSE VALVE	SOV-3125E			Y-83.1
N014:128/004	HS-3125C1	OPEN VALVE	SOV-3125C			Y-84.1
N014:128/005	HS-3125C2	CLOSE VALVE	SOV-3125C			Y-84.1
N014:128/006	HS-3125G1	OPEN VALVE	SOV-3125G			Y-84.1
N014:128/007	HS-3125G2	CLOSE VALVE	SOV-3125G			Y-84.1
N014:128/008	HS-3125D1	OPEN VALVE	SOV-3125D			Y-84.1
N014:128/009	HS-3125D2	CLOSE VALVE	SOV-3125D			Y-84.1
N014:128/010	HS-3173A1	OPEN VALVE	SOV-3173A			Y-87.1
N014:128/011	HS-3173A2	CLOSE VALVE	SOV-3173A			Y-87.1
N014:128/012	HS-3173B1	OPEN VALVE	SOV-3173B			Y-87.2
N014:128/013	HS-3173B2	CLOSE VALVE	SOV-3173B			Y-87.2
N014:128/014	HS-3156A1	OPEN VALVE	MOV-3156A			Y-89.1
N014:128/015	HS-3156A2	CLOSE VALVE	MOV-3156A			Y-89.1
N014:129/000	HS-3156B1	OPEN VALVE	MOV-3156B			Y-89.2
N014:129/001	HS-3156B2	CLOSE VALVE	MOV-3156B			Y-89.2
N014:129/002						
N014:129/003						
N014:129/004						
N014:129/005						
N014:129/006	HS-3125BA1	OPEN	VALVE	MOV-3125BA		Y-80.1
N014:129/007	HS-3125BA2	CLOSE	VALVE	MOV-3125BA		Y-80.1
N014:129/008	HS-3125BB1	OPEN	VALVE	MOV-3125BB		Y-80.1
N014:129/009	HS-3125BB2	CLOSE	VALVE	MOV-3125BB		Y-80.1
N014:129/010	HS-3125BC1	OPEN	VALVE	MOV-3125BC		Y-80.1
N014:129/011	HS-3125BC2	CLOSE	VALVE	MOV-3125BC		Y-80.1
N014:129/012	HS-3125BD1	OPEN	VALVE	MOV-3125BD		Y-80.1
N014:129/013	HS-3125BD2	CLOSE	VALVE	MOV-3125BD		Y-80.1
N014:129/014	HS-3125BE1	OPEN	VALVE	MOV-3125BE		Y-80.1
N014:129/015	HS-3125BE2	CLOSE	VALVE	MOV-3125BE		Y-80.1
N014:130/000	HS-3125BF1	OPEN	VALVE	MOV-3125BF		Y-80.1
N014:130/001	HS-3125BF2	CLOSE	VALVE	MOV-3125BF		Y-80.1
N014:130/002	HS-3125BG1	OPEN	VALVE	MOV-3125BG		Y-80.1
N014:130/003	HS-3125BG2	CLOSE	VALVE	MOV-3125BG		Y-80.1
N014:130/004	HS-3125BH1	OPEN	VALVE	MOV-3125BH		Y-80.1
N014:130/005	HS-3125BH2	CLOSE	VALVE	MOV-3125BH		Y-80.1
N014:130/006	HS-3125BJ1	OPEN	VALVE	MOV-3125BJ		Y-80.2
N014:130/007	HS-3125BJ2	CLOSE	VALVE	MOV-3125BJ		Y-80.2
N014:130/008	HS-3125BK1	OPEN	VALVE	MOV-3125BK		Y-80.2
N014:130/009	HS-3125BK2	CLOSE	VALVE	MOV-3125BK		Y-80.2
N014:130/010						
N014:130/011						
N014:130/012						
N014:130/013						
N014:130/014						
N014:130/015						
N014:140	PID-3125-FR	PUMP	P-3125 A/B	OUTLET FLOW	REFERENCE	FROM OIT
N014:141	PID-3125-KP	PUMP	P-3125 A/B	PID CONTROL	PROP. GAIN	FROM OIT
N014:142	PID-3125-KI	PUMP	P-3125 A/B	PID CONTROL	INTEG. GAIN	FROM OIT
N014:143	PID-3125-KD	PUMP	P-3125 A/B	PID CONTROL	DERIV. GAIN	FROM OIT
N014:144						
N014:145						
N014:150						
N014:150/000	HB_OCS_PL2	HEARTBEAT	FROM OCS	TO PLC-2		
N014:150/001						
N014:150/002						
N014:150/003						
N014:150/004						
N014:150/005						
N014:150/006						
N014:150/007						
N014:150/008						
N014:150/009						
N014:150/010						
N014:150/011						
N014:150/012						
N014:150/013						
N014:150/014	HS-3182A1	OCS OPEN	VALVE	SOV-3182A		Y-71.1
N014:150/015	HS-3182A2	OCS CLOSE	VALVE	SOV-3182A		Y-71.1
N014:151						
N014:151/000						
N014:151/001						
N014:151/002						
N014:151/003	HS-3182B1	OCS OPEN	VALVE	SOV-3182B		Y-71.1
N014:151/004	HS-3182B2	OCS CLOSE	VALVE	SOV-3182B		Y-71.1
N014:151/005	HS-3183A1	OCS OPEN	VALVE	SOV-3183A		Y-71.1

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00171

DB Form Report

Sorted By: Address

07:48:23 02/19/99

N014:151/006	HS-3183A2	OCS CLOSE	VALVE	SOV-3183A		Y-71.1
N014:151/007	HS-3183B1	OCS OPEN	VALVE	SOV-3183B		Y-71.1
N014:151/008	HS-3183B2	OCS CLOSE	VALVE	SOV-3183B		Y-71.1
N014:151/009	HS-3184-1	OCS OPEN	VALVE	SOV-3184		Y-71.1
N014:151/010	HS-3184-2	OCS CLOSE	VALVE	SOV-3184		Y-71.1
N014:151/011						
N014:151/012						
N014:151/013						
N014:151/014						
N014:151/015						
N014:152						
N014:153						
N014:154						
N014:156/000	HS-3125A1	START	BOOSTER	PUMP	P-3125A	Y-74.1
N014:156/001	HS-3125A2	STOP	BOOSTER	PUMP	P-3125A	Y-74.1
N014:156/002	HS-3125B1	START	BOOSTER	PUMP	P-3125B	Y-74.2
N014:156/003	HS-3125B2	STOP	BOOSTER	PUMP	P-3125B	Y-74.2
N014:156/004	HS-3125-H	PID FOR PUMP	P-3125 A/B	ANNUAL MODE		
N014:156/005	HS-3125A2	RESET	VALVES FOR	PUMP P-3125A		Y-79.1
N014:156/006	HS-3125AA1	OPEN	VALVE	MOV-3125AA		Y-79.1
N014:156/007	HS-3125AA2	CLOSE	VALVE	MOV-3125AA		Y-79.1
N014:156/008	HS-3125AB1	OPEN	VALVE	MOV-3125AB		Y-79.1
N014:156/009	HS-3125AB2	CLOSE	VALVE	MOV-3125AB		Y-79.1
N014:156/010	HS-3125AC1	OPEN	VALVE	MOV-3125AC		Y-79.1
N014:156/011	HS-3125AC2	CLOSE	VALVE	MOV-3125AC		Y-79.1
N014:156/012	HS-3125AD1	OPEN	VALVE	MOV-3125AD		Y-79.1
N014:156/013	HS-3125AD2	CLOSE	VALVE	MOV-3125AD		Y-79.1
N014:156/014	HS-3125AE1	OPEN	VALVE	MOV-3125AE		Y-79.1
N014:156/015	HS-3125AE2	CLOSE	VALVE	MOV-3125AE		Y-79.1
N014:157/000	HS-3125AF1	OPEN	VALVE	MOV-3125AF		Y-79.1
N014:157/001	HS-3125AF2	CLOSE	VALVE	MOV-3125AF		Y-79.1
N014:157/002	HS-3125AG1	OPEN	VALVE	MOV-3125AG		Y-79.1
N014:157/003	HS-3125AG2	CLOSE	VALVE	MOV-3125AG		Y-79.1
N014:157/004	HS-3125AH1	OPEN	VALVE	MOV-3125AH		Y-79.1
N014:157/005	HS-3125AH2	CLOSE	VALVE	MOV-3125AH		Y-79.1
N014:157/006	HS-3125AJ1	OPEN	VALVE	MOV-3125AJ		Y-79.2
N014:157/007	HS-3125AJ2	CLOSE	VALVE	MOV-3125AJ		Y-79.2
N014:157/008	HS-3125AK1	OPEN	VALVE	MOV-3125AK		Y-79.2
N014:157/009	HS-3125AK2	CLOSE	VALVE	MOV-3125AK		Y-79.2
N014:157/010	HS-3163-1	OPEN	VALVE	MOV-3163		Y-79.2
N014:157/011	HS-3163-2	CLOSE	VALVE	MOV-3163		Y-79.2
N014:157/012	HS-3125BY	INITIATE	DRAINING OF	PUMP P-3125B		Y-80.1
N014:157/013	HS-3125BZ	RESET	VALVES FOR	PUMP P-3125B		Y-80.1
N014:157/014						
N014:157/015						
N014:158/000						
N014:158/001						
N014:158/002	HS-3125E1	OPEN VALVE	SOV-3125E			Y-83.1
N014:158/003	HS-3125E2	CLOSE VALVE	SOV-3125E			Y-83.1
N014:158/004	HS-3125C1	OPEN VALVE	SOV-3125C			Y-84.1
N014:158/005	HS-3125C2	CLOSE VALVE	SOV-3125C			Y-84.1
N014:158/006	HS-3125G1	OPEN VALVE	SOV-3125G			Y-84.1
N014:158/007	HS-3125G2	CLOSE VALVE	SOV-3125G			Y-84.1
N014:158/008	HS-3125D1	OPEN VALVE	SOV-3125D			Y-84.1
N014:158/009	HS-3125D2	CLOSE VALVE	SOV-3125D			Y-84.1
N014:158/010	HS-3173A1	OPEN VALVE	SOV-3173A			Y-87.1
N014:158/011	HS-3173A2	CLOSE VALVE	SOV-3173A			Y-87.1
N014:158/012	HS-3173B1	OPEN VALVE	SOV-3173B			Y-87.2
N014:158/013	HS-3173B2	CLOSE VALVE	SOV-3173B			Y-87.2
N014:158/014	HS-3156A1	OPEN VALVE	MOV-3156A			Y-89.1
N014:158/015	HS-3156A2	CLOSE VALVE	MOV-3156A			Y-89.1
N014:159/000	HS-3156B1	OPEN VALVE	MOV-3156B			Y-89.2
N014:159/001	HS-3156B2	CLOSE VALVE	MOV-3156B			Y-89.2
N014:159/002						
N014:159/003						
N014:159/004						
N014:159/005						
N014:159/006	HS-3125BA1	OPEN	VALVE	MOV-3125BA		Y-80.1
N014:159/007	HS-3125BA2	CLOSE	VALVE	MOV-3125BA		Y-80.1
N014:159/008	HS-3125BB1	OPEN	VALVE	MOV-3125BB		Y-80.1
N014:159/009	HS-3125BB2	CLOSE	VALVE	MOV-3125BB		Y-80.1
N014:159/010	HS-3125BC1	OPEN	VALVE	MOV-3125BC		Y-80.1
N014:159/011	HS-3125BC2	CLOSE	VALVE	MOV-3125BC		Y-80.1
N014:159/012	HS-3125BD1	OPEN	VALVE	MOV-3125BD		Y-80.1
N014:159/013	HS-3125BD2	CLOSE	VALVE	MOV-3125BD		Y-80.1
N014:159/014	HS-3125BE1	OPEN	VALVE	MOV-3125BE		Y-80.1
N014:159/015	HS-3125BE2	CLOSE	VALVE	MOV-3125BE		Y-80.1

Hanford Cross Site Transfer System (PCU-2)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00172

DB Form Report Sorted By: Address

07:48:23 02/19/99

N014:160/000	HS-3125BF1	OPEN	VALVE	MOV-3125BF		Y-80.1
N014:160/001	HS-3125BF2	CLOSE	VALVE	MOV-3125BF		Y-80.1
N014:160/002	HS-3125BG1	OPEN	VALVE	MOV-3125BG		Y-80.1
N014:160/006	HS-3125BJ1	OPEN	VALVE	MOV-3125BJ		Y-80.2
N014:160/007	HS-3125BJ2	CLOSE	VALVE	MOV-3125BJ		Y-80.2
N014:160/008	HS-3125BK1	OPEN	VALVE	MOV-3125BK		Y-80.2
N014:160/009	HS-3125BK2	CLOSE	VALVE	MOV-3125BK		Y-80.2
N014:160/010						
N014:160/011						
N014:160/012						
N014:160/013						
N014:160/014						
N014:160/015						
N014:162	PID-3125-FR	PUMP	P-3125 A/B	OUTLET FLOW	REFERENCE	FROM OIT
N014:163	PID-3125-KP	PUMP	P-3125 A/B	PID CONTROL	PROP. GAIN	FROM OIT
N014:164	PID-3125-KI	PUMP	P-3125 A/B	PID CONTROL	INTEG. GAIN	FROM OIT
N014:165	PID-3125-KD	PUMP	P-3125 A/B	PID CONTROL	DERIV. GAIN	FROM OIT
N014:166						
N014:167						
N014:240						
N014:240/000	HB_PLC2_OCS	HEARTBEAT	FROM PLC-2	TO OCS		
N014:240/001	COM-21	COMMUN. WITH	PCU-1	IGNORED		
N014:240/002	COM-2_OCS	COMMUN. WITH	OCS	IGNORED		
N014:240/003	COM-23	COMMUN. WITH	PCU-3	IGNORED		
N014:240/004	COM-24	COMMUN. WITH	PCU-4	IGNORED		
N014:240/005	COM-25	COMMUN. WITH	PCU-5	IGNORED		
N014:240/006	BATT_BAD_PLC2	PLC-2 BATTERY	IS BAD OR	MISSING		
N014:240/007						
N014:240/008						
N014:240/009						
N014:240/010	PAH-3173	VALVE	SOV-3173A/B	FAILURE		Y-73.1
N014:240/011	PAH-3182	VALVE	SOV-3182A/B	FAILURE		
N014:240/012	PAH-3183	VALVE	SOV-3183A/B	FAILURE		
N014:240/013	LDA-3150	LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
N014:240/014	XA-3125A	BOOSTER	PUMP	P-3125A	FAILURE	Y-74.1
N014:240/015	XA-3125B	BOOSTER	PUMP	P-3125B	FAILURE	Y-74.2
N014:241/000						
N014:241/001						
N014:241/002						
N014:241/003						
N014:241/004	ZA-3182A2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:241/005						
N014:241/006	ZA-3182A1	VALVE	FAILED	TO OPEN		Y-71.1
N014:241/007						
N014:241/008	ZA-3182A	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:241/009						
N014:241/010						
N014:241/011						
N014:241/012	ZA-3182B2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:241/013						
N014:241/014	ZA-3182B1	VALVE	FAILED	TO OPEN		Y-71.1
N014:241/015						
N014:242/000	ZA-3182B	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:242/001	ZA-3183A2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:242/002						
N014:242/003	ZA-3183A1	VALVE	FAILED	TO OPEN		Y-71.1
N014:242/004						
N014:242/005	ZA-3183A	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:242/006	ZA-3183B2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:242/007						
N014:242/008	ZA-3183B1	VALVE	FAILED	TO OPEN		Y-71.1
N014:242/009						
N014:242/010	ZA-3183B	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:242/011						
N014:242/012						
N014:242/013						
N014:242/014	ZA-3184-2	VALVE	FAILED	TO CLOSE		Y-71.1
N014:242/015						
N014:243/000	ZA-3184-1	VALVE	FAILED	TO OPEN		Y-71.1
N014:243/001						
N014:243/002	ZA-3184	VALVE	POSITION	SWITCH FAILURE		Y-71.1
N014:243/003						
N014:243/004						
N014:243/005						
N014:243/006						
N014:243/007						
N014:243/008						

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00173

DB Form Report Sorted By: Address

07:48:24 02/19/99

N014: 243/009						
N014: 243/010						
N014: 243/011						
N014: 243/012						
N014: 243/013						
N014: 243/014						
N014: 243/015						
N014: 246/000	TAH-3125A1	PUMP P-3125A	INBOARD	BEARING	HIGH TEMP	Y-78.1
N014: 246/001	TAH-3125A2	PUMP P-3125A	OUTBOARD	BEARING	HIGH TEMP	Y-76.1
N014: 246/002	PAH-3125C	BOOSTER	PUMP HIGH	DISCHARGE	PRESSURE	Y-78.1
N014: 246/003	PAH-3125A	BOOSTER	PUMP HIGH	INLET	PRESSURE	Y-78.1
N014: 246/004						
N014: 246/005						
N014: 246/006	VAH-3125A1	PUMP P-3125A	HIGH MOTOR	VIBRATION		Y-76.1
N014: 246/007	VAH-3125A2	PUMP P-3125A	HIGH MOTOR	VIBRATION		Y-76.1
N014: 246/008						
N014: 246/009						
N014: 246/010						
N014: 246/011						
N014: 246/012						
N014: 246/013						
N014: 246/014						
N014: 246/015						
N014: 247/000	TAH-3125B1	PUMP P-3125B	INBOARD	BEARING	HIGH TEMP	Y-76.1
N014: 247/001	TAH-3125B2	PUMP P-3125B	OUTBOARD	BEARING	HIGH TEMP	Y-76.1
N014: 247/002	PAH-3125D	BOOSTER	PUMP HIGH	DISCHARGE	PRESSURE	Y-78.1
N014: 247/003	PAH-3125B	BOOSTER	PUMP HIGH	INLET	PRESSURE	Y-78.1
N014: 247/004						
N014: 247/008						
N014: 247/009						
N014: 247/010						
N014: 247/011						
N014: 247/012						
N014: 247/013						
N014: 247/014						
N014: 247/015						
N014: 248/000	ZA-3125E2	VALVE	SOV-3125E	FAILED TO	CLOSE	Y-83.1
N014: 248/001						
N014: 248/002	ZA-3125E1	VALVE	SOV-3125E	FAILED TO	OPEN	Y-83.1
N014: 248/003						
N014: 248/004	ZA-3125E	VALVE	SOV-3125E	POSITION	SWITCH FAILURE	Y-83.1
N014: 248/005	ZA-3125C2	VALVE	SOV-3125C	FAILED TO	CLOSE	Y-84.1
N014: 248/006						
N014: 248/007	ZA-3125C1	VALVE	SOV-3125C	FAILED TO	OPEN	Y-84.1
N014: 248/008						
N014: 248/009	ZA-3125C	VALVE	SOV-3125C	POSITION	SWITCH FAILURE	Y-84.1
N014: 248/010	ZA-3125G2	VALVE	SOV-3125G	FAILED TO	CLOSE	Y-85.1
N014: 248/011						
N014: 248/012	ZA-3125G1	VALVE	SOV-3125G	FAILED TO	OPEN	Y-85.1
N014: 248/013						
N014: 248/014	ZA-3125G	VALVE	SOV-3125G	POSITION	SWITCH FAILURE	Y-85.1
N014: 248/015	ZA-3125D2	VALVE	SOV-3125D	FAILED TO	CLOSE	Y-86.1
N014: 249/000						
N014: 249/001	ZA-3125D1	VALVE	SOV-3125D	FAILED TO	OPEN	Y-86.1
N014: 249/002						
N014: 249/003	ZA-3125D	VALVE	SOV-3125D	POSITION	SWITCH FAILURE	Y-86.1
N014: 249/004	ZA-3173A2	VALVE	SOV-3173A	FAILED TO	CLOSE	Y-87.1
N014: 249/005						
N014: 249/006	ZA-3173A1	VALVE	SOV-3173A	FAILED TO	OPEN	Y-87.1
N014: 249/007						
N014: 249/008	ZA-3173A	VALVE	SOV-3173A	POSITION	SWITCH FAILURE	Y-87.1
N014: 249/009	ZA-3173B2	VALVE	SOV-3173B	FAILED TO	CLOSE	Y-87.2
N014: 249/010						
N014: 249/011	ZA-3173B1	VALVE	SOV-3173B	FAILED TO	OPEN	Y-87.2
N014: 249/012						
N014: 249/013	ZA-3173B	VALVE	SOV-3173B	POSITION	SWITCH FAILURE	Y-87.2
N014: 249/014	ZA-3156A2	VALVE	MOV-3156A	FAILED TO	CLOSE	Y-89.1
N014: 249/015						
N014: 250/000	ZA-3156A1	VALVE	MOV-3156A	FAILED TO	OPEN	Y-89.1
N014: 250/001						
N014: 250/002	ZA-3156A	VALVE	MOV-3156A	POSITION	SWITCH FAILURE	Y-89.1
N014: 250/003	ZA-3156B2	VALVE	MOV-3156B	FAILED TO	CLOSE	Y-89.2
N014: 250/004						
N014: 250/005	ZA-3156B1	VALVE	MOV-3156B	FAILED TO	OPEN	Y-89.2
N014: 250/006						
N014: 250/007	ZA-3156B	VALVE	MOV-3156B	POSITION	SWITCH FAILURE	Y-89.2
N014: 250/008						

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00174

DB Form Report Sorted By: Address

07:48:24 02/19/99

N014:250/009						
N014:250/010						
N014:250/011						
N014:250/012						
N014:251/012						
N014:251/013						
N014:251/014						
N014:251/015						
N014:252/000						
N014:252/001						
N014:252/002						
N014:252/003						
N014:252/004						
N014:252/005						
N014:252/006						
N014:252/007						
N014:252/008	TI-3125A A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/009	PCU2-SP-TI-2 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/010	TI-3125B A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/011	PCU2-SP-TI-4 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/012	PCU2-SP-TI-5 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/013	PCU2-SP-TI-6 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/014	PCU2-SP-TI-7 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:252/015	PCU2-SP-TI-8 A	PCU-2 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:253/000	FIC-3125 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/001	PI-3125A A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/002	PI-3125B A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/003	PI-3125C A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/004	PI-3125D A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/005	PI-3125E A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/006	SI-3125A A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:253/007	SI-3125B A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/008	VI-3125AT A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/009	VI-3125B1 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/010	VI-3125A2 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/011	VI-3125B2 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/012	PI-3173 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/013	PI-3182 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/014	PI-3183 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:254/015	PCU2-SP-AI-8 A	PCU-2 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:256		DIGITAL INPUT	REGISTER TO	OIT TERMINALS		
N014:256/000	ZLH-3125BA	MOV-3125BA	IS OPEN		Y80-1	
N014:256/001	ZLL-3125BA	MOV-3125BA	IS CLOSED		Y81-1	
N014:256/002	ZLH-3125BB	MOV-3125BB	IS OPEN		Y80-1	
N014:256/003	ZLL-3125BB	MOV-3125BB	IS CLOSED		Y81-1	
N014:256/004	ZLH-3125BC	MOV-3125BC	IS OPEN		Y80-1	
N014:256/005	ZLL-3125BC	MOV-3125BC	IS CLOSED		Y81-1	
N014:256/006	ZLH-3125BD	MOV-3125BD	IS OPEN		Y80-1	
N014:256/007	ZLL-3125BD	MOV-3125BD	IS CLOSED		Y81-1	
N014:256/008	ZLH-3125BE	MOV-3125BE	IS OPEN		Y80-1	
N014:256/009	ZLL-3125BE	MOV-3125BE	IS CLOSED		Y81-1	
N014:256/010	ZLH-3125BF	MOV-3125BF	IS OPEN		Y80-1	
N014:256/011	ZLL-3125BF	MOV-3125BF	IS CLOSED		Y81-1	
N014:256/012	ZLH-3125BG	MOV-3125BG	IS OPEN		Y80-1	
N014:256/013	ZLL-3125BG	MOV-3125BG	IS CLOSED		Y81-1	
N014:256/014	ZLH-3125BH	MOV-3125BH	IS OPEN		Y80-1	
N014:256/015	ZLL-3125BH	MOV-3125BH	IS CLOSED		Y81-1	
N014:257/000	ZLH-3125BJ	MOV-3125BJ	IS OPEN		Y81-2	
N014:257/001	ZLL-3125BJ	MOV-3125BJ	IS CLOSED		Y81-2	
N014:257/002	ZLH-3125BK	MOV-3125BK	IS OPEN		Y81-2	
N014:257/003	ZLL-3125BK	MOV-3125BK	IS CLOSED		Y81-2	
N014:257/004	PCU2-SP-121-04	SPARE	DIGITAL	INPUT		
N014:257/005	PCU2-SP-121-05	SPARE	DIGITAL	INPUT		
N014:257/006	PCU2-SP-121-06	SPARE	DIGITAL	INPUT		
N014:257/007	PCU2-SP-121-07	SPARE	DIGITAL	INPUT		
N014:257/008	PCU2-SP-121-10	SPARE	DIGITAL	INPUT		
N014:257/009	PCU2-SP-121-11	SPARE	DIGITAL	INPUT		
N014:257/010	PCU2-SP-121-12	SPARE	DIGITAL	INPUT		
N014:257/011	PCU2-SP-121-13	SPARE	DIGITAL	INPUT		
N014:257/012	PCU2-SP-121-14	SPARE	DIGITAL	INPUT		
N014:257/013	PCU2-SP-121-15	SPARE	DIGITAL	INPUT		
N014:257/014	PCU2-SP-121-16	SPARE	DIGITAL	INPUT		
N014:257/015	PCU2-SP-121-17	SPARE	DIGITAL	INPUT		
N014:258/000	ZLH-3125AA	MOV-3125AA	IS OPEN		Y79-1	
N014:258/001	ZLL-3125AA	MOV-3125AA	IS CLOSED		Y80-1	
N014:258/002	ZLH-3125AB	MOV-3125AB	IS OPEN		Y79-1	
N014:258/003	ZLL-3125AB	MOV-3125AB	IS CLOSED		Y80-1	

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00175

DB Form Report Sorted By: Address

07:48:25 02/19/99

N014:258/004	ZLH-3125AC	MOV-3125AC	IS OPEN			Y79-1
N014:258/005	ZLL-3125AC	MOV-3125AC	IS CLOSED			Y80-1
N014:258/006	ZLH-3125AD	MOV-3125AD	IS OPEN			Y79-1
N014:258/007	ZLL-3125AD	MOV-3125AD	IS CLOSED			Y80-1
N014:258/008	ZLH-3125AE	MOV-3125AE	IS OPEN			Y79-1
N014:258/009	ZLL-3125AE	MOV-3125AE	IS CLOSED			Y80-1
N014:258/010	ZLH-3125AF	MOV-3125AF	IS OPEN			Y79-1
N014:258/011	ZLL-3125AF	MOV-3125AF	IS CLOSED			Y80-1
N014:258/012	ZLH-3125AG	MOV-3125AG	IS OPEN			Y79-1
N014:259/013	PCU2-SP-123-15	SPARE	DIGITAL	TNPUT		
N014:259/014	PCU2-SP-123-16	SPARE	DIGITAL	INPUT		
N014:259/015	PCU2-SP-123-17	SPARE	DIGITAL	INPUT		
N014:260/000	ZLH-3125C	SOV-3125C	IS OPEN			Y84-1
N014:260/001	ZLL-3125C	SOV-3125C	IS CLOSED			Y84-1
N014:260/002	ZLH-3125D	SOV-3125D	IS OPEN			Y86-1
N014:260/003	ZLL-3125D	SOV-3125D	IS CLOSED			Y86-1
N014:260/004	ZLH-3125E	SOV-3125E	IS OPEN			Y83-1
N014:260/005	ZLL-3125E	SOV-3125E	IS CLOSED			Y83-1
N014:260/006	ZLH-3125G	SOV-3125G	IS OPEN			Y85-1
N014:260/007	ZLL-3125G	SOV-3125G	IS CLOSED			Y85-1
N014:260/008	ZLH-3173B	SOV-3173B	IS OPEN			Y87-2
N014:260/009	ZLL-3173B	SOV-3173B	IS CLOSED			Y87-2
N014:260/010	ZLH-3156B	MOV-3156B	IS OPEN			Y89-2
N014:260/011	ZLL-3156B	MOV-3156B	IS CLOSED			Y89-2
N014:260/012	ZLH-3163	SOV-3163	IS OPEN			
N014:260/013	ZLL-3163	SOV-3163	IS CLOSED			
N014:260/014	ZLH-3173A	SOV-3173A	IS OPEN			Y87-1
N014:260/015	ZLL-3173A	SOV-3173A	IS CLOSED			Y87-1
N014:261/000	ZLH-3182A	SOV-3182A	IS OPEN			Y71
N014:261/001	ZLL-3182A	SOV-3182A	IS CLOSED			Y71
N014:261/002	ZLH-3182B	SOV-3182B	IS OPEN			Y71
N014:261/003	ZLL-3182B	SOV-3182B	IS CLOSED			Y71
N014:261/004	ZLH-3183A	SOV-3183A	IS OPEN			Y71
N014:261/005	ZLL-3183A	SOV-3183A	IS CLOSED			Y71
N014:261/006	ZLH-3183B	SOV-3183B	IS OPEN			Y71
N014:261/007	ZLL-3183B	SOV-3183B	IS CLOSED			Y71
N014:261/008	ZLH-3184	SOV-3184	IS OPEN			Y71
N014:261/009	ZLL-3184	SOV-3184	IS CLOSED			Y71
N014:261/010	ZLH-3156A	MOV-3156A	IS OPEN			Y89-1
N014:261/011	ZLL-3156A	MOV-3156A	IS CLOSED			Y89-1
N014:261/012	YL-3125A3	LOCAL/REMOTE	STATUS FOR	P-3125A		01T
N014:261/013	YL-3125B3	LOCAL/REMOTE	STATUS FOR	P-3125B		01T
N014:261/014	TAH-3125A	PUMP P-3125A	MOTOR WINDING	TEMP. HIGH	OFF = ALARM	Y76
N014:261/015	TAH-3125B	PUMP P-3125B	MOTOR WINDING	TEMP. HIGH	OFF = ALARM	Y76
N014:262/000	FAH-3125A1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A		Y76
N014:262/001	FAH-3125A2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125A		Y76
N014:262/002	FAH-3125B1	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B		Y76
N014:262/003	FAH-3125B2	LOW AIR FLOW	PUMP SEAL	PUMP P-3125B		Y76
N014:262/004	LAL-3125A1	PUMP P-3125A	LOW OIL LEVEL			Y76
N014:262/005	LAL-3125A2	PUMP P-3125A	LOW OIL LEVEL			Y76
N014:262/006	LAL-3125B1	PUMP P-3125B	LOW OIL LEVEL			Y76
N014:262/007	LAL-3125B2	PUMP P-3125B	LOW OIL LEVEL			Y76
N014:262/008	LDAH-3150	SUMP LEAK	DETECTOR	FAILURE		Y72
N014:262/009	LDA-3160	6241-A	ENCASEMENT	LEAK DETECTION	TOFF = ALARM	Y72
N014:262/010	LDAH-3150	6241-A SUMP	LEAK DETECTION	SEAL FAILURE		Y76
N014:262/011	PAL-3125A2	PUMP P-3125A	SEAL FAILURE			Y76
N014:262/012	PAL-3125B1	PUMP P-3125B	SEAL FAILURE			Y76
N014:262/013	PAL-3125B2	PUMP P-3125B	SEAL FAILURE			Y76
N014:262/014	PAL-3100A	LOW	COMPRESSOR	SA-CHP-3101A	PRESSURE	Y76
N014:262/015	PAL-3125A1	PUMP P-3125A	SEAL FAILURE			Y76
N014:263						
N014:265/000	MOV-3125BA1	OPEN VALVE	MOV-3125BA			Y80-1
N014:265/001	MOV-3125BA2	CLOSE VALVE	MOV-3125BA			Y80-1
N014:265/004	MOV-3125BC1	OPEN VALVE	MOV-3125BC			Y80-1
N014:265/005	MOV-3125BC2	CLOSE VALVE	MOV-3125BC			Y80-1
N014:265/006	MOV-3125BD1	OPEN VALVE	MOV-3125BD			Y80-1
N014:265/007	MOV-3125BD2	CLOSE VALVE	MOV-3125BD			Y80-1
N014:265/008	MOV-3125BE1	OPEN VALVE	MOV-3125BE			Y80-1
N014:265/009	MOV-3125BE2	CLOSE VALVE	MOV-3125BE			Y80-1
N014:265/010	MOV-3125BF1	OPEN VALVE	MOV-3125BF			Y80-1
N014:265/011	MOV-3125BF2	CLOSE VALVE	MOV-3125BF			Y80-1
N014:265/012	MOV-3125BG1	OPEN VALVE	MOV-3125BG			Y80-1
N014:265/013	MOV-3125BG2	CLOSE VALVE	MOV-3125BG			Y80-1
N014:265/014	MOV-3125BH1	OPEN VALVE	MOV-3125BH			Y80-1
N014:265/015	MOV-3125BH2	CLOSE VALVE	MOV-3125BH			Y80-1
N014:266/000	MOV-3125AA1	OPEN VALVE	MOV-3125AA			Y79-1
N014:266/001	MOV-3125AA2	CLOSE VALVE	MOV-3125AA			Y79-1

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

DB Form Report

Sorted By: Address

Page:00176

07:48:25 02/19/99

N014: 266/002	MOV-3125AB1	OPEN VALVE	MOV-3125AB			Y79-1
N014: 266/003	MOV-3125AB2	CLOSE VALVE	MOV-3125AB			Y79-1
N014: 266/004	MOV-3125AC1	OPEN VALVE	MOV-3125AC			Y79-1
N014: 266/005	MOV-3125AC2	CLOSE VALVE	MOV-3125AC			Y79-1
N014: 266/006	MOV-3125AD1	OPEN VALVE	MOV-3125AD			Y79-1
N014: 266/007	MOV-3125AD2	CLOSE VALVE	MOV-3125AD			Y79-1
N014: 266/008	MOV-3125AE1	OPEN VALVE	MOV-3125AE			Y79-1
N014: 266/009	MOV-3125AE2	CLOSE VALVE	MOV-3125AE			Y79-1
N014: 266/010	MOV-3125AF1	OPEN VALVE	MOV-3125AF			Y79-1
N014: 266/011	MOV-3125AF2	CLOSE VALVE	MOV-3125AF			Y79-1
N014: 266/012	MOV-3125AG1	OPEN VALVE	MOV-3125AG			Y79-1
N014: 266/013	MOV-3125AG2	CLOSE VALVE	MOV-3125AG			Y79-1
N014: 266/014	MOV-3125AH1	OPEN VALVE	MOV-3125AH			Y79-1
N014: 266/015	MOV-3125AH2	CLOSE VALVE	MOV-3125AH			Y79-1
N014: 267/000	MOV-3125AJ1	OPEN VALVE	MOV-3125AJ			Y79-2
N014: 267/001	MOV-3125AJ2	CLOSE VALVE	MOV-3125AJ			Y79-2
N014: 267/002	MOV-3125AK1	OPEN VALVE	MOV-3125AK			Y79-2
N014: 267/003	MOV-3125AK2	CLOSE VALVE	MOV-3125AK			Y79-2
N014: 267/004	MOV-3125BJ1	OPEN VALVE	MOV-3125BJ			Y80-2
N014: 267/005	MOV-3125BJ2	CLOSE VALVE	MOV-3125BJ			Y80-2
N014: 267/006	MOV-3125BK1	OPEN VALVE	MOV-3125BK			Y80-2
N014: 267/007	MOV-3125BK2	CLOSE VALVE	MOV-3125BK			Y80-2
N014: 267/008	P-3125A1	START PUMP	P-3125A			Y74-1
N014: 267/009	P-3125A2	STOP PUMP	P-3125A			Y74-1
N014: 267/010	P-3125B1	START PUMP	P-3125B			Y74-2
N014: 267/011	P-3125B2	STOP PUMP	P-3125B			Y74-2
N014: 267/012	P-3115	SHUTDOWN	SUMP PUMP	P-3115		Y-82.1
N014: 267/013	PCU2-SP-035-15	SPARE	DIGITAL	OUTPUT		
N014: 267/014	PCU2-SP-035-16	SPARE	DIGITAL	OUTPUT		
N014: 267/015	PCU2-SP-035-17	SPARE	DIGITAL	OUTPUT		
N014: 268/000	SOV-3125C1	OPEN VALVE	SOV-3125C			Y-84
N014: 268/001	SOV-3125C2	CLOSE VALVE	SOV-3125C			Y-84
N014: 268/002	SOV-3125D1	OPEN VALVE	SOV-3125D			Y-86
N014: 268/003	SOV-3125D2	CLOSE VALVE	SOV-3125D			Y-86
N014: 268/004	SOV-3125E1	OPEN VALVE	SOV-3125E			Y-83
N014: 268/005	SOV-3125E2	CLOSE VALVE	SOV-3125E			Y-83
N014: 268/006	SOV-3125G1	OPEN VALVE	SOV-3125G			Y-85
N014: 268/007	SOV-3125G2	CLOSE VALVE	SOV-3125G			Y-85
N014: 268/008	MOV-3156B1	OPEN VALVE	MOV-3156B			Y89-2
N014: 268/009	MOV-3156B2	CLOSE VALVE	MOV-3156B			Y89-2
N014: 268/010	MOV-3156A1	OPEN VALVE	MOV-3156A			Y89-1
N014: 268/011	MOV-3156A2	CLOSE VALVE	MOV-3156A			Y89-1
N014: 268/012	SOV-3163-1	OPEN VALVE	SOV-3163			Y80-2
N014: 268/013	SOV-3163-2	CLOSE VALVE	SOV-3163			Y80-2
N014: 268/015	SOV-3173A2	CLOSE VALVE	SOV-3173A			Y87-1
N014: 269/000	SOV-3173B1	OPEN VALVE	SOV-3173B			Y87-2
N014: 269/001	SOV-3173B2	CLOSE VALVE	SOV-3173B			Y87-2
N014: 269/002	SOV-3182A1	OPEN VALVE	SOV-3182A			Y71
N014: 269/003	SOV-3182A2	CLOSE VALVE	SOV-3182A			Y71
N014: 269/004	SOV-3182B1	OPEN VALVE	SOV-3182B			Y71
N014: 269/005	SOV-3182B2	CLOSE VALVE	SOV-3182B			Y71
N014: 269/006	SOV-3183A1	OPEN VALVE	SOV-3183A			Y71
N014: 269/007	SOV-3183A2	CLOSE VALVE	SOV-3183A			Y71
N014: 269/008	SOV-3183B1	OPEN VALVE	SOV-3183B			Y71
N014: 269/009	SOV-3183B2	CLOSE VALVE	SOV-3183B			Y71
N014: 269/010	SOV-3184-1	OPEN VALVE	SOV-3184			Y71
N014: 269/011	SOV-3184-2	CLOSE VALVE	SOV-3184			Y71
N014: 269/012	PCU2-SP-037-14	SPARE	DIGITAL	OUTPUT		
N014: 269/013	PCU2-SP-037-15	SPARE	DIGITAL	OUTPUT		
N014: 269/015	PCU2-SP-037-17	SPARE	DIGITAL	OUTPUT		
N014: 270	TI-3125B1	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N014: 271	TI-3125B2	PUMP P-3125B	MOTOR	BEARING	TEMPERATURE	
N014: 272	TI-3125A1	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N014: 273	TI-3125A2	PUMP P-3125A	MOTOR	BEARING	TEMPERATURE	
N014: 274	PCU2-SP-R1-5	SPARE	R.T.D. TEMP.	INPUT		
N014: 275	PCU2-SP-R1-6	SPARE	R.T.D. TEMP.	INPUT		
N014: 276	PCU2-SP-R1-7	SPARE	R.T.D. TEMP.	INPUT		
N014: 277	PCU2-SP-R1-8	SPARE	R.T.D. TEMP.	INPUT		
N014: 278	TI-3125A	PUMP P-3125A/B	OUTLET FLOW	TEMPERATURE	WT-SLL-3160	
N014: 279	PCU2-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014: 280	TI-3125B	LINE	WT-SNL-3150	TEMPERATURE		
N014: 281	PCU2-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014: 282	PCU2-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014: 283	PCU2-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014: 284	PCU2-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		
N014: 285	PCU2-SP-TI-8	SPARE	THERMOCOUPLE	INPUT		
N014: 286	FIC-3125	PUMP	P-3125 A/B	OUTLET FLOW		

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00177

DB Form Report Sorted By: Address

07:48:26 02/19/99

N014:287	PI-3125A	PUMP P-3125A	INLET	PRESSURE		
N014:288	PI-3125B	PUMP P-3125B	INLET	PRESSURE		
N014:289	PI-3125C	PUMP P-3125A	OUTLET	PRESSURE		
N014:290	PI-3125D	PUMP P-3125B	OUTLET	PRESSURE		
N014:291	PI-3125E	LINE	WT-SNL-31250	PRESSURE		
N014:292	S1-3125A	MOTOR SPEED	PUMP P-3125A			
N014:293	S1-3125B	MOTOR SPEED	PUMP P-3125B			
N014:294	VI-3125A1	PUMP P-3125A	BEARING	VIBRATION		
N014:295	VI-3125B1	PUMP P-3125B	BEARING	VIBRATION		
N014:296	VI-3125A2	PUMP P-3125A	BEARING	VIBRATION		
N014:297	VI-3125B2	PUMP P-3125B	BEARING	VIBRATION		
N014:298	PI-3173	VALVE	SOV-3173A/B	PRESSURE		
N014:299	PI-3182	VALVE	SOV-3182A/B	PRESSURE		
N014:300	PI-3183	VALVE	SOV-3183A/B	PRESSURE		
N014:301	PCU2-SP-A1-8	SPARE	ANALOG	INPUT		
N014:302	FIC-3125A	PUMP P-3125A	OUTLET FLOW	CONTROL	SIGNAL	
N014:303	FIC-3125B	PUMP P-3125B	OUTLET FLOW	CONTROL	SIGNAL	
N014:304	PCU2-SP-A0-3	SPARE	ANALOG	OUTPUT		
N014:305	PCU2-SP-A0-4	SPARE	ANALOG	OUTPUT		
N014:306	FIC-3125-E	PUMP	P-3125 A/B	OUTLET FLOW /	DRIVE SPEED	LOOP ERROR
N014:307	FIC-3125-0	PUMP	P-3125 A/B	OUTLET FLOW /	DRIVE SPEED	REF OUTPUT
PD016:000		PUMP	P-3125 A/B	OUTLET FLOW	PID CONTROL	
PD016:000.KD		PUMP	P-3125 A/B	PID CONTROL	DERIV. GAIN	FROM OIT
PD016:000.KI		PUMP	P-3125 A/B	PID CONTROL	INTEG. GAIN	FROM OIT
PD016:000.KP		PUMP	P-3125 A/B	PID CONTROL	PROP. GAIN	FROM OIT
PD016:000.SP		PUMP	P-3125 A/B	OUTLET FLOW	PID SET POINT	
N019:001/000						
N019:001/001						
N019:001/002	HB-12	HEARTBEAT	FROM PCU-1	TO PCU-2		
N019:001/003	HB-13	HEARTBEAT	FROM PCU-1	TO PCU-3		
N019:001/004	HB-14	HEARTBEAT	FROM PCU-1	TO PCU-4		
N019:001/005	HB-15	HEARTBEAT	FROM PCU-1	TO PCU-5		
N019:001/006						
N019:001/007						
N019:001/008						
N019:001/009						
N019:001/010						
N019:001/011						
N019:001/012						
N019:001/013						
N019:001/014						
N019:001/015		200-W MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:002/000		STOP BOOSTER	PUMP P-3125B &	TRANSFER PUMP	P-102-SY-02A	Y-74.2
N019:002/001	HB-21	HEARTBEAT	FROM PCU-2	TO PCU-1		
N019:002/002		STOP BOOSTER	PUMP P-3125A &	TRANSFER PUMP	P-102-SY-02A	Y-74.1
N019:002/003	HB-23	HEARTBEAT	FROM PCU-2	TO PCU-3		
N019:002/004	HB-24	HEARTBEAT	FROM PCU-2	TO PCU-4		
N019:002/005	HB-25	HEARTBEAT	FROM PCU-2	TO PCU-5		
N019:002/006		LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
N019:002/007		LEAK DETECTED	IN LINE TO	DIVERSION	BOX 6241-A	Y-72.1
N019:002/008		SOV-3182A	VALVE	FAILURE		Y-71.1
N019:002/009		SOV-3182B	VALVE	FAILURE		Y-71.1
N019:002/010		SOV-3184	VALVE	FAILURE		Y-71.1
N019:002/011		SOV-3173A/B	VALVE	FAILURE		Y-73.1
N019:002/012		SOV-3183B	VALVE	FAILURE		Y-71.1
N019:002/013		SOV-3183A	VALVE	FAILURE		Y-71.1
N019:002/014		PUMP P-3125A	HIGH INLET	PRESSURE		Y-75.1
N019:002/015		PUMP P-3125B	HIGH INLET	PRESSURE		Y-75.1
N019:003/000		INPUT SIGNAL TO	200-W MASTER	SHUTDOWN	CIRCUIT	Y-72.1
N019:003/001	HB-31	HEARTBEAT	FROM PCU-3	TO PCU-1		
N019:003/002	HB-32	HEARTBEAT	FROM PCU-3	TO PCU-2		
N019:003/003	HB-34	HEARTBEAT	FROM PCU-3	TO PCU-4		
N019:003/004	HB-35	HEARTBEAT	FROM PCU-3	TO PCU-5		
N019:003/005		TRANSFER 2A	SHUTDOWN			Y-42.1
N019:003/006		TRANSFER 2B	SHUTDOWN			Y-43.1
N019:003/007		TRANSFER 1	INITIATED			Y-41.1
N019:003/008		TRANSFER 2A	INITIATED			Y-42.1
N019:003/009		TRANSFER 2B	INITIATED			Y-43.1
N019:003/010		TRANSFER 3	INITIATED			Y-44.1
N019:003/011		MASTER RESET				
N019:003/012						
N019:003/013						
N019:003/014						
N019:003/015						
N019:004/000						
N019:004/001	HB-41	HEARTBEAT	FROM PCU-4	TO PCU-1		
N019:004/002	HB-42	HEARTBEAT	FROM PCU-4	TO PCU-2		

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

DB Form Report

Sorted By: Address

Page:00178

07:48:26 02/19/99

N019:004/003	HB-43	HEARTBEAT	FROM PCU-4	TO PCU-3		
N019:004/004						
N019:004/005	HB-45	HEARTBEAT	FROM PCU-4	TO PCU-5		
N019:004/006		SLURRY LINE	HIGH PRESSURE	AT PCU-4		
N019:004/007		MOV-843	VALVE	FAILURE		Y71
N019:004/008		MOV-844	VALVE	FAILURE		Y71
N019:004/009		MOV-845	VALVE	FAILURE		Y71
N019:004/010		MOV-846	VALVE	FAILURE		Y71
N019:004/011		200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:004/012		RUPTURE	DISK FAILURE			Y-78.1
N019:004/013		LEAK DETECTED	AT 244-A LIFT	STATION	SUMP	Y-72.1
N019:004/014						
N019:004/015						
N019:005/000						
N019:005/001	HB-51	HEARTBEAT	FROM PCU-5	TO PCU-1		
N019:005/002	HB-52	HEARTBEAT	FROM PCU-5	TO PCU-2		
N019:005/003	HB-53	HEARTBEAT	FROM PCU-5	TO PCU-3		
N019:005/004	HB-54	HEARTBEAT	FROM PCU-5	TO PCU-4		
N019:005/005						
N019:005/006						
N019:005/007						
N019:005/008						
N019:005/009						
N019:005/010						
N019:005/011						
N019:005/012						
N019:005/013						
N019:005/014						
N019:005/015		LEAK DETECTED	IN LINE TO	244-A LIFT	STATION	Y72-1
N020:000	TE-3125B1	PUMP P-3125B	MOTOR INBOARD	BEARING	TEMPERATURE	
N020:001	TE-3125B2	PUMP P-3125B	MOTOR OUTBOARD	BEARING	TEMPERATURE	
N020:002	TE-3125A1	PUMP P-3125A	MOTOR INBOARD	BEARING	TEMPERATURE	
N020:003	TE-3125A2	PUMP P-3125A	MOTOR OUTBOARD	BEARING	TEMPERATURE	
N020:004		SPARE	R. T. D. TEMP.	INPUT		
N020:005		SPARE	R. T. D. TEMP.	INPUT		
N020:006		SPARE	R. T. D. TEMP.	INPUT		
N020:007		SPARE	R. T. D. TEMP.	INPUT		
N020:008	TE-3125A	PUMP P-3125A/B	OUTLET FLOW	TEMPERATURE	WT-SLL-3160	
N020:009		SPARE	THERMOCOUPLE	INPUT		
N020:010	TE-3125B	LINE	WT-SNL-3150	TEMPERATURE		
N020:011		SPARE	THERMOCOUPLE	INPUT		
N020:012		SPARE	THERMOCOUPLE	INPUT		
N020:013		SPARE	THERMOCOUPLE	INPUT		
N020:014		SPARE	THERMOCOUPLE	INPUT		
N020:015		SPARE	THERMOCOUPLE	INPUT		
N020:016	FT-3125	PUMP	P-3125 A/B	OUTLET FLOW		
N020:017	PT-3125A	PUMP P-3125A	INLET	PRESSURE		
N020:018	PT-3125B	PUMP P-3125B	INLET	PRESSURE		
N020:019	PT-3125C	PUMP P-3125C	OUTLET	PRESSURE		
N020:020	PT-3125D	PUMP P-3125D	OUTLET	PRESSURE		
N020:021	PT-3125E	SUPERNATE LINE	WT-SNL-3150	PRESSURE		
N020:022	ST-3125A	MOTOR SPEED	PUMP P-3125A			
N020:023	ST-3125B	MOTOR SPEED	PUMP P-3125B			
N020:024	VT-3125A1	PUMP P-3125A	BEARING	VIBRATION		
N020:025	VT-3125B1	PUMP P-3125B	BEARING	VIBRATION		
N020:026	VT-3125A2	PUMP P-3125A	BEARING	VIBRATION		
N020:027	VT-3125B2	PUMP P-3125B-2	BEARING	VIBRATION		
N020:028	PT-3173	VALVE	SOV-3173A/B	PRESSURE		
N020:029	PT-3182	VALVE	SOV-3182A/B	PRESSURE		
N020:030	PT-3183	VALVE	SOV-3183A/B	PRESSURE		
N020:031		SPARE	ANALOG	INPUT		
N020:032	VSD-3125A	PUMP P-3125A	OUTLET FLOW	CONTROL	SIGNAL	
N020:033	VSD-3125B	PUMP P-3125B	OUTLET FLOW	CONTROL	SIGNAL	
N020:034		SPARE	ANALOG	OUTPUT		
N020:035		SPARE	ANALOG	OUTPUT		
N021:020		DH+ TRANSFER	FROM PCU-1	DATA REGISTERS		
N021:020/000						
N021:020/001						
N021:020/002						
N021:020/003						
N021:020/004						
N021:020/005						
N021:020/006						
N021:020/007						
N021:020/008						
N021:020/009						
N021:020/010						

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00179

DB Form Report

Sorted By: Address

07:48:27 02/19/99

N021:020/011					
N021:020/012					
N021:020/013					
N021:020/014					
N021:020/015					
N021:021					
N021:022					
N021:023					
N021:024					
N022:000	DH+ TRANSFER	TO PCU-1	DATA REGISTERS		
N022:000/000					
N022:000/001					
N022:000/002					
N022:000/003					
N022:000/004					
N022:000/005					
N022:000/006					
N022:000/007					
N022:000/008					
N022:000/009					
N022:000/010					
N022:000/011					
N022:000/012					
N022:000/013					
N022:000/014					
N022:000/015					
N022:001					
N022:002					
N022:003					
N022:004					
N022:040	DH+ TRANSFER	TO PCU-3	DATA REGISTERS		
N022:040/000					
N022:040/001					
N022:040/002					
N022:040/003					
N022:040/004					
N022:040/005					
N022:040/006					
N022:040/007					
N022:040/008					
N022:040/009					
N022:040/010					
N022:040/011					
N022:040/012					
N022:040/013					
N022:040/014					
N022:040/015					
N022:041					
N022:042					
N022:043					
N022:044					
N022:060	DH+ TRANSFER	TO PCU-4	DATA REGISTERS		
N022:060/000					
N022:060/001					
N022:060/002					
N022:060/003					
N022:060/004					
N022:060/005					
N022:060/006					
N022:060/007					
N022:060/008					
N022:060/009					
N022:060/010					
N022:060/011					
N022:060/012					
N022:060/013					
N022:060/014					
N022:060/015					
N022:061					
N022:062					
N022:063					
N022:064					
N022:080	DH+ TRANSFER	TO PCU-5	DATA REGISTERS		
N022:080/000					
N022:080/001					
N022:080/002					
N022:080/003					

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00180

DB Form Report Sorted By: Address

07:48:27 02/19/99

N022:080/004					
N022:080/005					
N022:080/006					
N022:080/007					
N022:080/008					
N022:080/009					
N022:080/010					
N022:080/011					
N022:080/012					
N022:080/013					
N022:080/014					
N022:080/015					
N022:081					
N022:082					
N022:083					
N022:084					
N022:100	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N022:140	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N022:160	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N022:180	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N023:020	DH+ TRANSFER	FROM PCU-3	DATA REGISTERS		
N023:020/000					
N023:020/001					
N023:020/002					
N023:020/003					
N023:020/004					
N023:020/005					
N023:020/006					
N023:020/007					
N023:020/008					
N023:020/009					
N023:020/010					
N023:020/011					
N023:020/012					
N023:020/013					
N023:020/014					
N023:020/015					
N023:021					
N023:022					
N023:023					
N023:024					
N024:020	DH+ TRANSFER	FROM PCU-4	DATA REGISTERS		
N024:020/000					
N024:020/001					
N024:020/002					
N024:020/003					
N024:020/004					
N024:020/005					
N024:020/006					
N024:020/007					
N024:020/008					
N024:020/009					
N024:020/010					
N024:020/011					
N024:020/012					
N024:020/013					
N024:020/014					
N024:020/015					
N024:021					
N024:022					
N024:023					
N024:024					
N025:020	DH+ TRANSFER	FROM PCU-5	DATA REGISTERS		
N025:020/000					
N025:020/001					
N025:020/002					
N025:020/003					
N025:020/004					
N025:020/005					
N025:020/006					
N025:020/007					
N025:020/008					
N025:020/009					
N025:020/010					
N025:020/011					
N025:020/012					
N025:020/013					

Hanford Cross Site Transfer System (PCU-2)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00181

DB Form Report Sorted By: Address

07:49:00 02/19/99

N025:020/014					
N025:020/015					
N025:021					
N025:022					
N025:023					
N025:024					
DFILE:000	OUTPUTS	Output Reg	isters And	Bits	
DFILE:001	INPUTS	Input Regi	sters And	Bits	
DFILE:002	SYSTEM	System Sta	tus Variab	les	
DFILE:003	BITS	General In	ternal Bit	Addresses	
DFILE:004	TIMERS	General Ti	mer Address	ses	
DFILE:005	COUNTERS	General Co	unter Addr	esses	
DFILE:006	CONTROL	General Co	ntrol Addr	esses	
DFILE:007	INTEGERS	General In	teger Addr	esses	
DFILE:008	FLOATING	General Fl	oating Poi	nt Address	as
DFILE:009	I/O STATUS	I/O Status	File (Use	d By The P	rocessor)
DFILE:010	PROC FLT	Stores Sys	tem Data 0	n A Proces	sor Fault
DFILE:011	GEN MSG	General	DH-Plus Me	ssage Cont	rol File
DFILE:012	GEN BT	General	Block Tran	sfer Contr	ol File
DFILE:013	ANA_RAW	Analog Dat	a File		
DFILE:014	OIM DATA	OCS Commu	ication Fi	le	
DFILE:016	PID_CTRL	PID CONTR	L STRUCTUR	E	
DFILE:017	CONFIG1B	Channel 1B	Configura	tion Diag	File
DFILE:018	CONFIG1A	Channel 1A	Configura	tion Diag	File
DFILE:019	GLOBAL1A	Channel 1A	Config G1	obal Statu	s File
DFILE:020	ANA BUF	Analog I/O	Working F	ile	
DFILE:021	PLC1DATA	DATA FROM	PLC-1(DH+)		
DFILE:022	PLC2DATA	DATA FROM	PLC-2(DH+)		
DFILE:023	PLC3DATA	DATA FROM	PLC-3(DH+)		
DFILE:024	PLC4DATA	DATA FROM	PLC-4(DH+)		
DFILE:025	PLC5DATA	DATA FROM	PLC-5(DH+)		
PFILE:000	SYSTEM DA	TA STORAGE	HEADER		
PFILE:002	MAIN PROG	AW FILE			
PFILE:003	PROCESSOR	FAULT ROUT	INE INPUTS		
PFILE:004	I/O HANDL	NG FOR ANA	LOG AND OT	HER REGIST	
PFILE:005	COMMUNICAT	ION			
PFILE:006	TRANSFER V	ALVE SEQUE	NCING		
PFILE:007	PUMP SEQUE	NCING			
PFILE:008	P-3125 A/B	DRAIN VAL	VE SEQUENC	ING	
PFILE:009	P-3125 A/B	INLET / O	UTLET VALV	E SEQUENC	NG
PFILE:010	P-3115 VAL	VE SEQUENC	ING		
PFILE:011	REFERENCE	RAMP SEQUE	NCING		
Q002:000	MAIN PROGRAM	FILE START-UP	JUMP TO JSR'S		
Q002:001	MAIN PROGRAM	FILE START-UP	JUMP TO END		
Q003:000	PROCESSOR	FAULT ROUTINE	JUMP TO END		
U:004	I/O HANDLING	FOR ANALOG OR	OTHER REG I70	SUBROUTINE	
U:005	DATA HIGHWAY+	COMMUNICATIONS	CTRL & CHECK	SUBROUTINE	
U:006	GENERAL FILE	SUBROUTINE			
V:004	I/O HANDLING	FOR ANALOG OR	OTHER REG IN	SUBROUTINE	
V:005	SUBROUTINE				

DB Form Report   Sorted By: Address

07:49:00 02/19/99

Addr:B3/0

TITLE:GENERAL USE BITS AND TIMING FUNCTIONS
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF

Addr:B3/1

RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON

Addr:B3/2

RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY SECOND.

Addr:B3/3

RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY TWO SECONDS.

Addr:B3/4

RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/5

RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/6

RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/36

TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING

Addr:B3/37

RUNG DESCRIPTION:
THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

Addr:B3/39

TITLE:ANALOG INPUTS BLOCK TRANSFER SEQUENCING

Addr:B3/40

TITLE:COMMUNICATION HANDLING SUBROUTINE

Addr:B3/41

TITLE:VALVE SEQUENCING FOR SOV-3182A

Addr:B3/42

TITLE:BOOSTER PUMP P-3125A SEQUENCING

Addr:B3/43

TITLE:SEQUENCING FOR THE BOOSTER PUMP P-3125A DRAIN VALVES

Addr:B3/44

TITLE:VALVE SEQUENCING FOR SOV-3125E

Addr:B3/45

TITLE:SUMP PUMP P-3115 CONTROL.

Hanford Cross Site Transfer System (PCU-2)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00183

DB Form Report Sorted By: Address

07:49:00 02/19/99

Addr:B3/112
TITLE:ISOLATION VALVE AND ENCASEMENT LEAK DETECTION SEQUENCING

Addr:B3/300
TITLE:PLC RAMP FUNCTION SUBROUTINE

Addr:B3/301
RUNG DESCRIPTION:
THE NEXT TWO RUNGS CALCULATE THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN TARGET AND CURRENT SETPOINTS.

Addr:B3/302
RUNG DESCRIPTION:
IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS GREATER THAN THE INCREMENT LIMIT,
ADD OR
SUBTRACT THE LIMIT VALUE AS APPROPRIATE.

Addr:B3/303
RUNG DESCRIPTION:
IF THE ABSOLUTE VALUE OF THE DIFFERENCE BETWEEN THE TARGET AND CURRENT SETPOINTS IS LESS THAN OR EQUAL TO THE
INCREMENT LIMIT, SET
THE CURRENT SETPOINT EQUAL TO THE TARGET SETPOINT.

Addr:B3/304
TITLE:VALVE SEQUENCING FOR SOV-3184

Addr:B3/306
TITLE:VALVE SEQUENCING FOR SOV-3183A

Addr:B3/308
TITLE:VALVE SEQUENCING FOR SOV-3183B

Addr:B3/310
TITLE:SPEED REFERENCE RAMP CALL SEQUENCING
RUNG DESCRIPTION:
ENABLE THE SPEED RAMP REFERENCE WHEN THE CONTROLLER RUN OUTPUT IS ON. WHILE THE REFERENCE IS ENABLED, SCALE THE
SPEED REFERENCE
AND MOVE THIS DESIRED SPEED INTO THE SPEED REFERENCE RAMP TARGET SETPOINT WORKING REGISTER.

Addr:B3/311
RUNG DESCRIPTION:
ENABLE THE SPEED RAMP ANY TIME THE REFERENCE IS ENABLED. IF THE CONTROL HAS THE ABILITY TO RAMP TO A STOP, KEEP THE
RAMP ENABLED
AFTER THE REFERENCE IS DISABLED UNTIL EITHER THE REFERENCE (OR FEEDBACK IF AVAILABLE) APPROACHES ZERO OR THE
CONTROLLER "ON" STATUS
DROPS OUT.

NOTE: THE RAMP INCREMENT 'MOV' SERVES ONLY AS AN EASY DISPLAY OF THE CURRENT VALUE.

Addr:B3/313
RUNG DESCRIPTION:
JUMP TO THE SPEED RAMP SUBROUTINE CONDITIONALLY WHEN THE RAMP IS ENABLED AND THE RAMP OUTPUT DOES NOT EQUAL ITS
INPUT. THE RAMP
RUNS THE FIRST TIME THESE CONDITIONS ARE MET AND THEN EACH TIME THE RAMP TIMER IS DONE. USE A HISTOGRAM ON THE RAMP
DONE BIT TO
VERIFY THE RAMP SCAN PERIOD WHEN ADJUSTING THE RAMP TIMER FOR THE DESIRED RAMP PERIOD.

Addr:B3/314
RUNG DESCRIPTION:
WHEN THE RAMP REFERENCE IS NOT ENABLED, CLEAR (ZERO) THE SPEED REFERENCE RAMP TARGET SETPOINT REGISTER. THIS
FUNCTION ENABLES THE
REFERENCE TO RAMP DOWN TO A STOP IF THE CONTROLLER HAS THE ABILITY TO STAY ENERGIZED TO A LOW SPEED.

Addr:B3/315
RUNG DESCRIPTION:
IF THE SPEED RAMP IS NOT ENABLED, PLACE A ZERO IN THE SPEED REFERENCE CURRENT SETPOINT REGISTER. THIS REGISTER IS
THE RAMP OUTPUT
OR THE ACTUAL SPEED REFERENCE TO THE CONTROLLER.

Hanford Cross Site Transfer System (PCU-2)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00184

DB Form Report   Sorted By: Address

07:49:00 02/19/99

Addr:B3/316

RUNG DESCRIPTION:

JUMP TO THE RAMP SUBROUTINE WITH PASSED PARAMETERS:

INPUT PAR (1): DESIRED OR TARGET SPEED REFERENCE (RAMP INPUT)
INPUT PAR (2): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
INPUT PAR (3): MAXIMUM RAMP REFERENCE INCREMENT IN A SINGLE SCAN THROUGH THE SUBROUTINE
RETURN PAR (1): ACTUAL SPEED REFERENCE TO CONTROLLER (RAMP OUTPUT)
RETURN PAR (2): DIFFERENCE BETWEEN DESIRED (TARGET) AND ACTUAL (OUTPUT) REFERENCES
RETURN PAR (3): ABSOLUTE VALUE OF RAMP REFERENCE DIFFERENCE

Addr:B3/317

RUNG DESCRIPTION:

MOVE THE RAMPED SPEED REFERENCE TO THE ACTUAL OUTPUT REGISTER WHICH IS CONNECTED TO THE CONTROLLER.

Addr:B3/326

TITLE:VALVE SEQUENCING FOR SOV-3182B

Addr:B3/340

TITLE:VALVE SEQUENCING FOR SOV-3125C

Addr:B3/342

TITLE:VALVE SEQUENCING FOR SOV-3125D

Addr:B3/346

TITLE:VALVE SEQUENCING FOR SOV-3125G

Addr:B3:1

RUNG DESCRIPTION:

THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE BITS CAN BE USED TO DIVIDE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

Addr:N7:302

RUNG DESCRIPTION:

CALCULATE THE DIFFERENCE BETWEEN THE CURRENT AND TARGET SETPOINTS.

Addr:N7:311

RUNG DESCRIPTION:

IF THE PROCESS SECTION IS "NOT" IN PROGRESSIVE JOG, PLACE A ZERO IN THE PROCESS SECTION SPEED REFERENCE CURRENT SETPOINT REGISTER.

Addr:N14:0/0

RUNG DESCRIPTION:

COMMUNICATION BETWEEN PCU-2 AND OCS

Addr:N14:11/0

TITLE:ANALOG INPUT OVER / UNDER RANGE ALARMS

Addr:N14:127/10

TITLE:SEQUENCING FOR THE COMMON DRAIN VALVE AND BOOSTER PUMP INTERLOCKS

Addr:N14:129/6

TITLE:SEQUENCING FOR THE BOOSTER PUMP P-3125B DRAIN VALVES

Addr:N14:129/15

RUNG DESCRIPTION:

DRAIN VALVE MOV-3125BF LOGIC

Addr:N14:162

TITLE:SEQUENCING FOR OIT DATA TO AND FROM PLC-1

Hanford Cross Site Transfer System (PCU-2)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00185

DB Form Report Sorted By: Address

07:49:00 02/19/99

Addr:N19:2/1
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-2 AND PCU-1

Addr:N19:2/3
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-2 AND PCU-3

Addr:N19:2/4
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-2 AND PCU-4

Addr:N19:2/5
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-2 AND PCU-5

Addr:N19:2/14
TITLE:BOOSTER PUMP P-3125A ANALOG CONTROL AND TROUBLE SEQUENCING

Addr:N19:2/15
TITLE:BOOSTER PUMP P-3125B ANALOG CONTROL AND TROUBLE SEQUENCING

Addr:0:035/12
TITLE:BOOSTER PUMP P-3125B SEQUENCING

Addr:0:036/10
TITLE:VALVE SEQUENCING FOR SOV-3156B

Addr:0:036/12
TITLE:VALVE SEQUENCING FOR SOV-3156A

Addr:0:036/16
TITLE:VALVE SEQUENCING FOR SOV-3173A

Addr:0:037/00
TITLE:VALVE SEQUENCING FOR SOV-3173B

Addr:02:1
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING

Addr:03:0
TITLE:PROCESSOR FAULT ROUTINE PROGRAM FILE.
RUNG DESCRIPTION:
THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE
PROCESSOR. FIRST SCAN WILL OCCURE
ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL
OCCURE ON POWER DOWN,
A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE
STATUS DATA WILL ONLY BE COPIED
INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN
RUNG ZERO.

Addr:T4:0
TITLE:MAINLINE PROGRAM INITIALIZATION JUMP
RUNG DESCRIPTION:

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
P.O. Box 28970
Spokane, WA 99228-8970
(509) 466-2656

THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS BEEN UPDATED
ON POWERUP OR
ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS BEEN READ.
TIMER T4:0 IS
USED TO SET THIS TIME DELAY.

Hanford Cross Site Transfer System (PCU-2)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00186

DB Form Report

Sorted By: Address

07:49:00 02/19/99

Addr:T4:1

RUNG DESCRIPTION:

THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

Addr:T4:10

RUNG DESCRIPTION:

IF THE PROCESS SECTION IS IN PROGRESSIVE JOG THIS RUNG DETERMINES IF THE RAMP LOGIC SHOULD BE EXECUTED THIS SCAN.

**This document was too large to scan
as a single document; therefore, it has
been divided into smaller sections.**

Section 2 of 2

Document Information			
Document #	HNF-2346	Revision	1
Title	PROJECT W-058 MONITOR & CONTROL SYS LOGIC		
Date	2/22/99		
Originator	ROBERTS JB	Originator Co.	LMSI
Recipient		Recipient Co.	
References	ECN-651363		
Keywords			
Projects			
Other Information			

WIntelligent LOGIC 5 - Rockwell Software Inc.

Project Name : PLC3.X5

Time/Date : 07:28:19 02/19/99

Page	Rung	Description
1		Ladder Report
1	0	MAINLINE PROGRAM INITIALIZATION JUMP
2	2	GENERAL USE BITS AND TIMING FUNCTIONS
6	12	PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
9	0	PROCESSOR FAULT ROUTINE PROGRAM FILE.
11	0	ANALOG INPUTS BLOCK TRANSFER SEQUENCING
15	7	ANALOG INPUT OVER / UNDER RANGE ALARMS
22	0	COMMUNICATION HANDLING SUBROUTINE
32	26	SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
37	0	SEQUENCING FOR TRANSFER VALVE SOV-3165A, Y-71.1
42	14	SEQUENCING FOR TRANSFER VALVE SOV-3166A, Y-71.1
51	40	SEQUENCING FOR TRANSFER VALVE SOV-3166B, Y-71.1
56	0	SEQUENCING FOR VENT VALVE SOV-3185A, Y-81.1
60	12	SEQUENCING FOR VENT VALVE SOV-3185B, Y-81.2
64	23	SEQUENCING FOR VENT VALVE SOV-3188A, Y-81.3
68	34	SEQUENCING FOR VENT VALVE SOV-3188B, Y-81.4
72	0	MISCELLANEOUS INTERLOCK LOGIC, Y-82.1
73	4	SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167A, Y-88.1
77	15	SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167B, Y-88.2
81	0	TRANSFER PERMISSIVES LOGIC, ES-058-Y70 SH.1
89	0	241-SY-A TO 241-A-B TRANSFER SCHEME # 1, Y-41.1
91	4	241-SY-B TO 241-A-A TRANSFER SCHEME # 2A, Y-42.1
93	7	241-SY-B TO 241-A-A TRANSFER SCHEME # 2B, Y-43.1
94	9	241-A-B TO 241-SY-A TRANSFER SCHEME # 3, Y-44.1
95	0	File #12 Y72-Y73 Proj:PLC3
99	10	VALVE LEAK LOGIC Y-73.1
102		DT Form Report
102		DB Form Report Sorted By: Address

Hanford Cross Site Transfer System (PCU-3)
 MAINLINE PROGRAM INITIALIZATION JUMP
 Lockheed Martin Hanford Co.
 Page:00001

File #2 MAIN Proj:PLC3

07:28:19 02/19/99

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
 P.O. Box 28970
 Spokane, WA 99228-8970
 (509) 466-2656

*THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
 *THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS
 *BEEN UPDATED ON POWERUP OR
 *ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS
 *BEEN READ. TIMER T4:0 IS
 *USED TO SET THIS TIME DELAY.

First scan
 of ladder
 or SFC
 step

S:1/15

2:0000

POWER-UP
 SEQUENCING
 DELAY

Timer Off Delay	-(EN)
Timer: T4:0	
Base (SEC): 0.01	-(DN)
Preset: 20	
Accum: 20	

T4:0.DN - TOF - File #2 MAIN - 0
 -| | - File #2 MAIN - 1,15

POWER-UP
 SEQUENCING
 DELAY

T4:0.DN

2:0001

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

Q2:0

[JMP]

Q2:0 - JMP - File #2 MAIN - 1
 LBL - File #2 MAIN - 12

.....
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF
 .....

2:0002	ALWAYS OFF OUTPUT ALWAYS OFF B3/0	ALWAYS OFF OUTPUT ALWAYS OFF B3/0	ALWAYS OFF OUTPUT ALWAYS OFF B3/0
	----- ----- / -----		----- ----- / -----

B3/0   - - { } - - File #2 MAIN - 2
              - { } - - File #2 MAIN - 2
              - / | - - File #2 MAIN - 2
              BSL - - File #2 MAIN - 7
              - | | - - File #5 COMM - 3
                               File #6 Y71 - 3,16,48

.....
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON
 .....

2:0003		ALWAYS ON OUTPUT ALWAYS ON B3/1
	----- ----- / -----	----- ----- / -----

B3/1   - - ( ) - - File #2 MAIN - 3

.....
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE
 *EXECUTED ONCE EVERY SECOND.
 .....

2:0004	REAL TIME CLOCK SECOND ONE'S BIT	ONE SECOND RISING ONE SHOT	ONE SECOND SINGLE SCAN PULSE 1_SEC PULSE B3/2
	S:23/0 B3/32	[ONS]	----- ----- / -----

REAL TIME
CLOCK
SECOND
ONE'S BIT

ONE SECOND
FALLING
ONE SHOT

S:23/0   B3/33

[ONS]

B3/2   - - { } - - File #2 MAIN - 4
              - | - - File #2 MAIN - 8
                               File #5 COMM - 5,26

HNF-2346, Rev. 1

07:28:20 02/19/99

B3/7   - -( ) - - File #2 MAIN - 6

File #2 MAIN Proj:PLC3

07:28:20 02/19/99

THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1 THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE B3:2 TO B3:16 BITS CAN BE USED TO DIVIDE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

FILE _F:B003:001I%001 LEN 1 - BSL - File #2 MAIN - 7

REG:0.UL	BSL	File #2	File #2
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
B3:0	-	File #2	MAIN - 2
	-	File #2	MAIN - 2
	-	File #2	MAIN - 2
	-	File #2	MAIN - 2
	-	File #2	MAIN - 7
	-	File #5	COMM - 3
	-	File #6	Y71 - 3,16,48
R6:0.UL	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
B3:1	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7
	-	File #2	MAIN - 7

*THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 GENERAL USE BITS AND TIMING FUNCTIONS
 Lockheed Martin Hanford Co.
 Page:00005

HNF-2346, Rev. 1

File #2 MAIN Proj:PLC3

07:28:20 02/19/99

2:0008	ONE SECOND SINGLE SCAN PULSE 1_SEC PULSE B372	HALF SECOND FLASHER TIMER	+---TOF---+ Timer Off Delay -(EN)- Timer: T4:1 Base (SEC): 0.01 -(DN) Preset: 50 Accum: 50
	T4:1.DN - TOF - File #2 MAIN - 8 -I - File #2 MAIN - 9		
*THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT * *DEVICES.			
2:0009	HALF SECOND FLASHER TIMER T4:1.DN	HALF SECOND FLASHER HALF_SEC FLASH B3/4	-( )
	B3/4 - -( ) - File #2 MAIN - 9		
*THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT * *DEVICES.			
2:0010	REAL TIME CLOCK SECOND ONE'S BIT S:23/0	ONE SECOND FLASHER 1_SEC FLASH B375	-( )
	B3/5 - -( ) - File #2 MAIN - 10		
*THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT * *DEVICES.			
2:0011	REAL TIME CLOCK SECOND TWO'S BIT S:23/1	TWO SECOND FLASHER 2_SEC FLASH B376	-( )
	B3/6 - -( ) - File #2 MAIN - 11		

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING
 *****

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

PROGRAM FILE
 JUMP-TO-SUBR.
 CONTROL RUNGS
 COMMENT COIL

2:0012 ----- Q2:0 ----- B3/36
 [LBL] ----- ( ) -----

B3/36 - - ( ) - - File #2 MAIN - 12

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

2:0013 ----- +---JSR-----+
 |Jump To Subroutine|
 |File #: U:4|
 +-----+-----+

U:4 - JSR - File #2 MAIN - 13
 SBR - File #4 REG_10 - 0

DATA HIGHWAY +
 COMMUNICATION
 CTRL & CHECK
 SUBROUTINE

2:0014 ----- +---JSR-----+
 |Jump To Subroutine|
 |File #: U:5|
 +-----+-----+

U:5 - JSR - File #2 MAIN - 14
 SBR - File #5 COMM - 0

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING
 *****

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO END

2:0015 ----- T4:0.DN ----- Q2:1
 | | ----- [JMP] -----

Q2:1 - JMP - File #2 MAIN - 15
 LBL - File #2 MAIN - 22

TR-R VALVES
 CONTROL
 SUBROUTINE

2:0016 ----- +---JSR-----+
 |Jump To Subroutine|
 |File #: U:6|
 +-----+-----+

U:6 - JSR - File #2 MAIN - 16
 SBR - File #6 Y71 - 0

			VENT VALVES CONTROL SUBROUTINE
2:0017			+---JSR-----+ Jump To Subroutine File #: U:7 +-----+
	U:7	- JSR - File #2 MAIN - 17 SBR - File #7 Y81 - 0	
			SUMP PUMP. CONTROL SUBROUTINE
2:0018			+---JSR-----+ Jump To Subroutine File #: U:8 +-----+
	U:8	- JSR - File #2 MAIN - 18 SBR - File #8 Y82&Y-88 - 0	
			INITIATE TRANSFER SUBROUTINE
2:0019			+---JSR-----+ Jump To Subroutine File #: U:10 +-----+
	U:10	- JSR - File #2 MAIN - 19 SBR - File #10 Y70 - 0	
			TRANSFER 1-2A-2B-3 SUBROUTINE
2:0020			+---JSR-----+ Jump To Subroutine File #: U:11 +-----+
	U:11	- JSR - File #2 MAIN - 20 SBR - File #11 Y41-Y44 - 0	
			LEAK DETECTION CONTROL SUBROUTINE
2:0021			+---JSR-----+ Jump To Subroutine File #: U:12 +-----+
	U:12	- JSR - File #2 MAIN - 21 SBR - File #12 Y72-Y73 - 0	

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
Lockheed Martin Hanford Co.
Page:00008

File #2 MAIN Proj:PLC3

07:28:21 02/19/99

THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

MAIN PROGRAM
FILE START-UP
JUMP TO END

MCP FILE #2
END OF PROGRAM
COMMENT COIL

2:0022 Q2:1
-----[LBL]-----

B3/37
--( )--

B3/37 - -( ) - - File #2 MAIN - 22

2:0023 -----[End]-----

*THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL
 *OCCURE
 *ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN,
 *A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE
 *COPIED
 *INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.

First scan
 of ladder
 or SFC
 step

PROCESSOR
 FAULT ROUTINE
 JUMP TO END

S:1/15

Q3:0

3:0000

[JMP]

Q3:0

- JMP - File #3 PRO_FLT - 0
 LBL - File #3 PRO_FLT - 2

Logical Rack
 Status Bits
 For Racks 0-7

3:0001

+-BTD-----+
 Bit Field Distributor
 Source: S:7
 0
 Source Bit: 0
 Dest: N10:7
 0
 Dest Bit: 0
 Length: 8

Last
 program
 scan time
 ladder &
 SFC

+-COP-----+
 Copy File
 Source: #S:8
 Dest: #N10:8
 Length: 16

S:7 - BTD - File #3 PRO_FLT - 1
 N10:7 - BTD - File #3 PRO_FLT - 1
 FILE _F:S002:008\%016 LEN 16 - COP - File #3 PRO_FLT - 1
 FILE _F:N10:008\%016 LEN 16 - COP - File #3 PRO_FLT - 1

PROCESSOR
 FAULT ROUTINE
 JUMP TO END

FAULT ROUTINE
 FILE #3 END
 OF PROGRAM
 COMMENT COIL

Q3:0

B3/38

3:0002

[LBL]

( )

B3/38

- ( ) - File #3 PRO_FLT - 2

REGISTER FOR
 VERIFYING
 FAULT ROUTINE
 FILE OPERATION

3:0003

+-ADD-----+
 Add
 Source A: N10:0
 18
 Source B: 1
 1
 Dest: N10:0
 18

APPENDIX C

HNH-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
PROCESSOR FAULT ROUTINE PROGRAM FILE.
Lockheed Martin Hanford Co.

File #3 PRO_FLT Proj:PLC3

Page:00010

07:28:21 02/19/99

N10:0 - ADD - File #3 PRO_FLT - 3,3
N10:0 - ADD - File #3 PRO_FLT - 3,3

3:0004

---[End]---

Hanford Cross Site Transfer System (PCU-3)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00011

File #4 REG_10 Proj:PLC3

07:28:21 02/19/99

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

PROGRAM
 FILE #4 START
 OF SUBROUTINE
 COMMENT COIL

4:0000 +--SBR-----+
 |Subroutine |
 +-----+

B3/39

B3/39 - - ( ) - File #4 REG_10 - 0

4:0001 BT12:0.EN BT12:1.EN
 ---|/|-----|/|---

+--BTW-----+
 Block Transfer Write
 Mod Type: 1771-N
 High Resolution Analog I/O
 Rack: 0
 Group: 0
 Module: 0
 Control Block: BT12:1
 Data File: N13:28
 Length: 59
 Continuous: N
 +-----+

BT12:1.EN - BTW - File #4 REG_10 - 1
 -|/| - File #4 REG_10 - 1,2
 N13:28 - BTW - File #4 REG_10 - 1,1

4:0002 BT12:1.EN BT12:0.EN
 ---|/|-----|/|---

+--BTR-----+
 Block Transfer Read
 Mod Type: 1771-N
 High Resolution Analog I/O
 Rack: 0
 Group: 0
 Module: 0
 Control Block: BT12:0
 Data File: N13:0
 Length: 28
 Continuous: N
 +-----+

BT12:0.EN - -|/| - File #4 REG_10 - 1
 BTR - File #4 REG_10 - 2
 -|/| - File #4 REG_10 - 2
 -| - File #4 REG_10 - 3
 N13:0 - BTR - File #4 REG_10 - 2,2

4:0003

BT12:0.DN

LINE
WT-SNL-3150
TEMPERATURE
TE-3126A+--DIV--+
Div
Source A: N13:5 453
Source B: 10
Dest: N20:0 45SPARE
THERMOCOUPLE
INPUT+--DIV--+
Div
Source A: N13:7 453
Source B: 10
Dest: N20:1 45LINE
WT-SLL-3160
TEMPERATURE
TE-3126B+--DIV--+
Div
Source A: N13:9 456
Source B: 10
Dest: N20:2 46SPARE
THERMOCOUPLE
INPUT+--DIV--+
Div
Source A: N13:11 456
Source B: 10
Dest: N20:3 46SPARE
THERMOCOUPLE
INPUT+--DIV--+
Div
Source A: N13:13 25016
Source B: 10
Dest: N20:4 2502SPARE
THERMOCOUPLE
INPUT

Hanford Cross Site Transfer System (PCU-3)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00013

File #4 REG_10 Proj:PLC3

07:28:22 02/19/99

```

+---DIV-----+
|Div          |
|Source A:    |N13:15
|              |25016
|Source B:    |10
|              |10
|Dest:        |N20:5
|              |2502
+---+

```

SPARE
 THERMOCOUPLE
 INPUT

```

+---DIV-----+
|Div          |
|Source A:    |N13:17
|              |25016
|Source B:    |10
|              |10
|Dest:        |N20:6
|              |2502
+---+

```

SPARE
 THERMOCOUPLE
 INPUT

```

+---DIV-----+
|Div          |
|Source A:    |N13:19
|              |25016
|Source B:    |10
|              |10
|Dest:        |N20:7
|              |2502
+---+

```

```

FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:0 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5,5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:1 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:2 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:3 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:4 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:5 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:6 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5
FILE_F:N013:0001%028 LEN 28 - BTR - File #4 REG_10 - 2
FILE_F:N013:0001%028 LEN 28 - DIV - File #4 REG_10 - 3
N20:7 - DIV - File #4 REG_10 - 3
      COP - File #5 COMM - 5

```

Hanford Cross Site Transfer System (PCU-3)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00014

File #4 REG_10 Proj:PLC3

07:28:22 02/19/99

ANALOG MODULE
 POWERED UP BUT
 NOT CONFIGURED

4:0004 N13:87/0 BT12:3.EN BT12:2.EN

```
--BTW--
Block Transfer Write  (EN)-
Mod Type: 1771-IFE
12 Bit Analog Input (DN)
Rack: 0
Group: 1 (ER)
Module: 0
Control Block: BT12:3
Data File: N13:107
Length: 21
Continuous: N
```

BT12:3.EN - BTW - File #4 REG_10 - 4
 -|/|- File #4 REG_10 - 4,5
 N13:107 - BTW - File #4 REG_10 - 4,4

4:0005 BT12:2.EN BT12:3.EN

```
--BTR--
Block Transfer Read  (EN)-
Mod Type: 1771-IFE
12 Bit Analog Input (DN)
Rack: 0
Group: 1 (ER)
Module: 0
Control Block: BT12:2
Data File: N13:87
Length: 12
Continuous: N
```

BT12:2.EN - -|/|- File #4 REG_10 - 4
 BTR - File #4 REG_10 - 5
 -|/|- File #4 REG_10 - 5
 -|/|- File #4 REG_10 - 6
 N13:87/1 - -|/|- File #4 REG_10 - 4
 BTR - File #4 REG_10 - 5,5
 -|/|- File #4 REG_10 - 16,17,18,19,20,21,22,23

4:0006 BT12:2.DN

LOSS OF
 VACUUM
 WT-SNL-3150
 PT-3126A

```
--COP--
Copy File
Source: #N13:91
Dest: #N20:8
Length: 8
```

FILE _F:N013:0871%012 LEN 12 - BTR - File #4 REG_10 - 5
 FILE _F:N013:0871%012 LEN 12 - COP - File #4 REG_10 - 6
 FILE _F:N020:0081%008 LEN 8 - COP - File #4 REG_10 - 6
 File #5 COMM - 5

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00016

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC3

07:28:23 02/19/99

N14:11/3 - - ( ) - - File #4 REG_10 - 10

THERM. MODULE
 CHAN. 5 DATA
 UNDERRANGE

PCU-3 INPUT
 THERMOCOUPLE
 OVER OR UNDER
 RANGE ALARM
 PCU3-SP-TI-5_A
 N14:11/4
 - - ( ) - -

4:0011 N13:12/0

THERM. MODULE
 CHAN. 5 DATA
 OVERRANGE

N13:12/1

N14:11/4 - - ( ) - - File #4 REG_10 - 11

THERM. MODULE
 CHAN. 6 DATA
 UNDERRANGE

PCU-3 INPUT
 THERMOCOUPLE
 OVER OR UNDER
 RANGE ALARM
 PCU3-SP-TI-6_A
 N14:11/5
 - - ( ) - -

4:0012 N13:14/0

THERM. MODULE
 CHAN. 6 DATA
 OVERRANGE

N13:14/1

N14:11/5 - - ( ) - - File #4 REG_10 - 12

THERM. MODULE
 CHAN. 7 DATA
 UNDERRANGE

PCU-3 INPUT
 THERMOCOUPLE
 OVER OR UNDER
 RANGE ALARM
 PCU3-SP-TI-7_A
 N14:11/6
 - - ( ) - -

4:0013 N13:16/0

THERM. MODULE
 CHAN. 7 DATA
 OVERRANGE

N13:16/1

N14:11/6 - - ( ) - - File #4 REG_10 - 13

THERM. MODULE
 CHAN. 8 DATA
 UNDERRANGE

PCU-3 INPUT
 THERMOCOUPLE
 OVER OR UNDER
 RANGE ALARM
 PCU3-SP-TI-8_A
 N14:11/7
 - - ( ) - -

4:0014 N13:18/0

THERM. MODULE
 CHAN. 8 DATA
 OVERRANGE

N13:18/1

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 ANALOG INPUT OVER / UNDER RANGE ALARMS
 Lockheed Martin Hanford Co.
 Page:00017

HNF-2346, Rev. 1

File #4 REG_10 Proj:PLC3

07:28:23 02/19/99

N14:11/7 - - ( ) - - File #4 REG_10 - 14

ANALOG MODULE
 UNDERRANGE
 BITS REGISTER

ANALOG MODULE
 OVERRANGE
 BITS REGISTER

ANALOG MODULE
 INPUT CHANNEL
 UNDER OR OVER
 RANGE ALARMS
 NOT ACTIVE

4:0015 +---EQU---+ +---EQU---+
Equal (A=B)		Equal (A=B)
Source A: N13:88		Source A: N13:89
228		0
Source B: 0		Source B: 0
0		0

B3/48

( )

B3/48

- - ( ) - - File #4 REG_10 - 15
 - | - - File #4 REG_10 - 16,17,18,19,20,21,22,23

ANALOG MODULE
 CHAN. 1 DATA
 UNDERRANGE

LOSS OF
 VACUUM
 WT-SNL-3150
 PT-3126AR

PCU-3 INPUT
 ANALOG
 OVER OR UNDER
 RANGE ALARM
 PI-3126A A
 N14:12/8

4:0016 +---LIM---+
N13:88/0		Limit Test (Circular)
		Low Lim: 3
		Test: N13:91 2
		High Lim: -3
		-3

ANALOG MODULE
 CHAN. 1 DATA
 OVERRANGE

N13:89/0

ONE OR MORE
 CHANNELS ARE
 UNDER OR OVER
 RANGE

ANALOG MODULE
 INPUT CHANNEL
 UNDER OR OVER
 RANGE ALARMS
 NOT ACTIVE

N13:87/1

B3/48

N14:12/8 - - ( ) - - File #4 REG_10 - 16

File #4 REG_10 Proj:PLC3

07:28:23 02/19/99

N14:12/13 - ( ) - File #4 REG_10 - 21

N14:12/14 - ( ) - File #4 REG_10 - 22

File #4 REG_10 Proj:PLC3

07:28:23 02/19/99

```

ANALOG MODULE      SPARE
CHAN. 8 DATA      ANALOG
UNDERRANGE         INPUT

PCU-3 INPUT
ANALOG
OVER OR UNDER
RANGE ALARM
PCU3-SP-A1-8_A
N14:12/15
( )

4:0023  N13:88/7  +--LIM-----+
          | |      | Limit Test (Circular) |
          | |      | Low Lim:              |
          | |      | 1                     |
          | |      | Test:      N13:98     |
          | |      | -1025                |
          | |      | High Lim:            |
          | |      | -1                   |
          | |      | -1                   |
          | |      +-----+

ANALOG MODULE
CHAN. 8 DATA
OVERRANGE

N13:89/7
| |
+-----+

ONE OR MORE      ANALOG MODULE
CHANNELS ARE     INPUT CHANNEL
UNDER OR OVER    UNDER OR OVER
RANGE            RANGE ALARMS
                 NOT ACTIVE

N13:87/1         83/48
+-----+

N14:12/15  - -( ) - File #4 REG_10 - 23

I/O HANDLING
FOR ANALOG OR
OTHER REG I/O
SUBROUTINE

4:0024  +--RET-----+
          |Return ( ) |
          +-----+

4:0025  +-----+
          |End|
  
```

File #5 COMM Proj:PLC3

07:28:24 02/19/99

```

DATA HIGHWAY +
COMMUNICATION
CTRL & CHECK
SUBROUTINE
PROGRAM
FILE #5 START
OF SUBROUTINE
COMMENT COIL

5:0000 +--SBR-----+
|Subroutine |-----B3/40
+-----+
B3/40 - ( ) - File #5 COMM - 0

*COMMUNICATION BETWEEN PCU-3 AND OCS

HEARTBEAT
FROM PLC-3
TO OCS
HB PLC3_OCS
N14:070
HEARTBEAT
FROM OCS
TO PLC-3
HB OCS PLC3
NT4:120/0

5:0001 ---|/|---
N14:120/0 - ( ) - File #5 COMM - 1
- | - File #5 COMM - 2
- |/ - File #5 COMM - 2

HEARTBEAT
FROM OCS
TO PLC-3
HB OCS PLC3
NT4:120/0
COMM LOSS
TIMER
WITH OCS

5:0002 ---|/|---[ONS]
HEARTBEAT
FROM OCS
TO PLC-3
HB OCS PLC3
NT4:120/0
COMM LOSS
ONE-SHOT
B3/200
+--TOF-----+
|Timer: Off Delay |-(EN)-
|Timer: T4:40 |
|Base (SEC): 1.0 |-(DN)
|Preset: 40 |
|Accum: 40 |
+-----+
HEARTBEAT
FROM OCS
TO PLC-3
HB OCS PLC3
NT4:120/0
COMM LOSS
ONE-SHOT
B3/201
+-----|/|---[ONS]---

T4:40.DN - TOF - File #5 COMM - 2
-|/| - File #5 COMM - 3

ALWAYS OFF
OUTPUT
ALWAYS OFF
B3/0
T4:40.DN
5:0003 ---|/|---
N14:0/3 - ( ) - File #5 COMM - 3

Battery
is bad or
missing
S:10/0
PLC-3 BATTERY
IS BAD OR
MISSING
BATT BAD PLC3
NT4:076

5:0004 ---|/|---
N14:0/6 - ( ) - File #5 COMM - 4

```

ONE SECOND
 SINGLE SCAN
 PULSE
 1_SEC PULSE
 B372

5:0005

DIGITAL INPUT
 REGISTER TO
 OIT TERMINALS

+-COP-----+
 Copy File
 Source: #1:003
 Dest: #N14:24
 Length: 2
 +-----+

DIGITAL OUTPUT
 REGISTER TO
 OIT TERMINALS

+-COP-----+
 Copy File
 Source: #0:006
 Dest: #N14:28
 Length: 2
 +-----+

LINE
 WT-SWL-3150
 TEMPERATURE
 TI-3126A

+-COP-----+
 Copy File
 Source: #N20:0
 Dest: #N14:30
 Length: 16
 +-----+

FILE_F:1001:0031%002 LEN 2 - COP - File #5 COMM - 5
 FILE_F:N014:0241%002 LEN 2 - COP - File #5 COMM - 5,30
 FILE_F:0000:0061%002 LEN 2 - COP - File #5 COMM - 5
 FILE_F:N014:0281%002 LEN 2 - COP - File #5 COMM - 5,30
 FILE_F:N020:0001%016 LEN 16 - COP - File #5 COMM - 5
 FILE_F:N014:0301%016 LEN 16 - COP - File #5 COMM - 5,30

*****
 *COMMUNICATION BETWEEN PCU-3 AND PCU-1
 *****

HEARTBEAT
 FROM PCU-1
 TO PCU-3
 HB-13
 N19:1/3

5:0006

HEARTBEAT
 FROM PCU-3
 TO PCU-1
 HB-31
 N19:3/1

( )

N19:3/1 - ( ) - File #5 COMM - 6
 - | - File #5 COMM - 7
 - | - File #5 COMM - 7

HEARTBEAT PCU-1
 FROM PCU-3 COMMUN. LOSS
 TO PCU-1 ONE-SHOT
 HB-31
 N19:3/1 B3/99
 [ONS]

5:0007

COMMUN. LOSS
 TIMER WITH
 PCU-1

+-TOF-----+
 Timer Off Delay |-(EN)-
 Timer: T4:32
 Base (SEC): 1.0 |-(DN)-
 Preset: 5
 Accum: 0
 +-----+

HEARTBEAT PCU-1
 FROM PCU-3 COMMUN. LOSS
 TO PCU-1 ONE-SHOT
 HB-31
 N19:3/1 B3/100
 [ONS]

Hanford Cross Site Transfer System (PCU-3)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00024

File #5 COMM Proj:PLC3

07:28:24 02/19/99

```

R6:10.IN - | | - File #5 COMM - 10
R6:10.IN - FSC - File #5 COMM - 9
          - | | - File #5 COMM - 9
          - (U) - File #5 COMM - 9,10
          RES - File #5 COMM - 10
          - | | - File #5 COMM - 10,10
FILE F:N023:0001%020 LEN 20 - COP - File #5 COMM - 9
FILE F:N023:0001%020 LEN 20 - MSG - File #5 COMM - 9
FILE F:N023:0001%020 LEN 20 - COP - File #5 COMM - 9
FILE F:N023:0001%020 LEN 20 - MSG - File #5 COMM - 9
FILE F:N023:2001%020 LEN 20 - COP - File #5 COMM - 9,9
MG11:0.EN - MSG - File #5 COMM - 9
          - | | - File #5 COMM - 9
          - /| - File #5 COMM - 9
FILE F:N023:2001%020 LEN 20 - COP - File #5 COMM - 9,9
FILE F:N023:1001%020 LEN 20 - COP - File #5 COMM - 9
  
```

COMPARE
 PCU-3 TO PCU-1
 MSG FILE
 WITH PREVIOUS

*****
 *COMMUNICATION BETWEEN PCU-3 AND PCU-2
 *****

```

N19:3/2 - ( ) - File #5 COMM - 11
        - | | - File #5 COMM - 12
        - /| - File #5 COMM - 12
  
```

Hanford Cross Site Transfer System (PCU-3)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00026

File #5 COMM Proj:PLC3

07:28:25 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00027

File #5 COMM Proj:PLC3

07:28:25 02/19/99

```

R6:11.IN - | | - File #5 COMM - 15
R6:11.IN - FSC - File #5 COMM - 14
          - | | - File #5 COMM - 14
          - (U) - File #5 COMM - 14,15
          RES - File #5 COMM - 15
          - | | - File #5 COMM - 15,15
FILE F:N023:0201%020 LEN 20 - COP - File #5 COMM - 14
FILE F:N023:0201%020 LEN 20 - MSG - File #5 COMM - 14
FILE F:N023:0201%020 LEN 20 - COP - File #5 COMM - 14
FILE F:N023:0201%020 LEN 20 - MSG - File #5 COMM - 14
FILE F:N023:2201%020 LEN 20 - COP - File #5 COMM - 14,14
MG11:T.EN - MSG - File #5 COMM - 14
          - | | - File #5 COMM - 14
          - | | - File #5 COMM - 14
FILE F:N023:2201%020 LEN 20 - COP - File #5 COMM - 14,14
FILE F:N023:1201%020 LEN 20 - COP - File #5 COMM - 14
  
```

COMPARE
 PCU-3 TO PCU-2
 MSG FILE
 WITH PREVIOUS

```

R6:11.IN - FSC - File #5 COMM - 14
          - | | - File #5 COMM - 14
          - (U) - File #5 COMM - 14,15
          RES - File #5 COMM - 15
          - | | - File #5 COMM - 15,15
R6:11.IN - FSC - File #5 COMM - 14
          - | | - File #5 COMM - 14
          - (U) - File #5 COMM - 14,15
          RES - File #5 COMM - 15
          - | | - File #5 COMM - 15,15
  
```

*****
 COMMUNICATION BETWEEN PCU-3 AND PCU-4
 *****

HEARTBEAT
 FROM PCU-4
 TO PCU-3
 HB-43
 N19:4/3

HEARTBEAT
 FROM PCU-3
 TO PCU-4
 HB-34
 N19:3/4

HEARTBEAT
 FROM PCU-3
 TO PCU-4
 HB-34
 N19:3/4

PCU-4
 COMMUN. LOSS
 ONE-SHOT
 B3/103
 [ONS]

COMMUN. LOSS
 TIMER WITH
 PCU-4

Hanford Cross Site Transfer System (PCU-3)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00028

File #5 COMM Proj:PLC3

07:28:26 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00029

File #5 COMM Proj:PLC3

07:28:26 02/19/99

```

R6:12.IN - | | - File #5 COMM - 20
R6:12.IN - FSC - File #5 COMM - 19
          - | | - File #5 COMM - 19
          - (U) - File #5 COMM - 19,20
          RES - File #5 COMM - 20
          - | | - File #5 COMM - 20,20
FILE F:N023:0601%020 LEN 20 - COP - File #5 COMM - 19
FILE F:N023:0601%020 LEN 20 - MSG - File #5 COMM - 19
FILE F:N023:0601%020 LEN 20 - COP - File #5 COMM - 19
FILE F:N023:0601%020 LEN 20 - MSG - File #5 COMM - 19
FILE F:N023:2601%020 LEN 20 - COP - File #5 COMM - 19,19
MG11:2.EN - MSG - File #5 COMM - 19
          - | | - File #5 COMM - 19
          - | | - File #5 COMM - 19
FILE F:N023:2601%020 LEN 20 - COP - File #5 COMM - 19,19
FILE F:N023:1601%020 LEN 20 - COP - File #5 COMM - 19
  
```

COMPARE
 PCU-3 TO PCU-4
 MSG FILE
 WITH PREVIOUS

```

5:0020 R6:12.DN +-----+-----+
          | | |
          +-----+-----+
          R6:12.FD
          +-----+-----+
          | | |
          +-----+-----+
          R6:12.FD
          +-----+-----+
          | | |
          +-----+-----+
          R6:12.IN - FSC - File #5 COMM - 19
          - | | - File #5 COMM - 19
          - (U) - File #5 COMM - 19,20
          RES - File #5 COMM - 20
          - | | - File #5 COMM - 20,20
R6:12.IN - FSC - File #5 COMM - 19
          - | | - File #5 COMM - 19
          - (U) - File #5 COMM - 19,20
          RES - File #5 COMM - 20
          - | | - File #5 COMM - 20,20
  
```

*COMMUNICATION BETWEEN PCU-3 AND PCU-5

```

5:0021 HEARTBEAT FROM PCU-5 TO PCU-3
        HB-53
        N19:5/3
        - | | -
        +-----+-----+
        HEARTBEAT FROM PCU-5 TO PCU-3
        HB-35
        N19:3/5
        - ( ) -
        +-----+-----+
        N19:3/5 - ( ) - File #5 COMM - 21
        - | | - File #5 COMM - 22
        - | | - File #5 COMM - 22
  
```

```

5:0022 HEARTBEAT FROM PCU-3 TO PCU-5
        HB-35
        N19:3/5
        B3/105
        - | | - [ONS]
        +-----+-----+
        HEARTBEAT FROM PCU-3 TO PCU-5
        HB-35
        N19:3/5
        B3/106
        - | | - [ONS]
        +-----+-----+
        COMMUN. LOSS
        TIMER WITH
        PCU-5
        +-----+-----+
        +--TOF-----+
        Timer Off Delay |-(EN)-
        Timer: T4:35
        Base (SEC): 1.0 |-(DN)-
        Preset: 5
        Accum: 0
        +-----+-----+
  
```

Hanford Cross Site Transfer System (PCU-3)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00030

File #5 COMM Proj:PLC3

07:28:27 02/19/99

File #5 COMM Proj:PLC3

07:28:27 02/19/99

```

R6:13.1N      - | | - File #5 COMM - 25
R6:13.1N      - FSC - File #5 COMM - 24
              - | | - File #5 COMM - 24
              - (U) - File #5 COMM - 24,25
              RES - File #5 COMM - 25
              - | | - File #5 COMM - 25,25
FILE F:NO23:0801%020 LEN 20 - COP - File #5 COMM - 24
FILE F:NO23:0801%020 LEN 20 - MSG - File #5 COMM - 24
FILE F:NO23:0801%020 LEN 20 - COP - File #5 COMM - 24
FILE F:NO23:0801%020 LEN 20 - MSG - File #5 COMM - 24
FILE F:NO23:2801%020 LEN 20 - COP - File #5 COMM - 24,24
MG11:3.EN     - MSG - File #5 COMM - 24
              - | | - File #5 COMM - 24
              - | | - File #5 COMM - 24
FILE F:NO23:2801%020 LEN 20 - COP - File #5 COMM - 24,24
FILE F:NO23:1801%020 LEN 20 - COP - File #5 COMM - 24

```

COMPARE
PCU-3 TO PCU-5
MSG FILE
WITH PREVIOUS

5:0025 | R6:13.DN | -+ - - - | | - - - +

R6:13
-[RES]

R6:13.FD

R6:13.FD
 --- (U) ---

```

R6:13.IN - FSC - File #5 COMM - 24
          - | - File #5 COMM - 24
          - (U) - File #5 COMM - 24,25
          RES - File #5 COMM - 25
          - | - File #5 COMM - 25,25
R6:13.IN - FSC - File #5 COMM - 24
          - | - File #5 COMM - 24
          - (U) - File #5 COMM - 24,25
          RES - File #5 COMM - 25
          - | - File #5 COMM - 25,25

```

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.

File #5 COMM Proj:PLC3

Page:00032

07:29:00 02/19/99

5:0026 COMMUN. WITH ONE SECOND
 PCU-1 SINGLE SCAN
 IGNORED PULSE
 COM-31 1_SEC PULSE
 N14:0/1 B372

+-COP-+
 Copy File
 Source: #N14:120
 Dest: #N14:170
 Length: 3

FILE _F:N014:120I%003 LEN 3 - COP - File #5 COMM - 26,29
 FILE _F:N014:170I%003 LEN 3 - COP - File #5 COMM - 26,27
 FILE _F:N014:170I%003 LEN 3 - MSG - File #5 COMM - 27
 FILE _F:N014:170I%003 LEN 3 - COP - File #5 COMM - 29

5:0027 COMMUN. WITH
 PCU-1
 IGNORED
 COM-31
 N14:0/1

R6:15.IN
 (U)

MG11:5.EN

+-FSC-+
 File Search/Compare
 Control: R6:15
 Length: 3
 Position: 0
 Mode: ALL
 Expression:
 #N14:170 <> #N21:0

R6:15.FD

+-COP-+
 Copy File
 Source: #N14:170
 Dest: #N21:20
 Length: 3

+-MSG-+
 Send/Receive Message
 Control Block: MG11:5
 -(EN)
 -(DN)
 -(ER)

MG11:5.DN B3/165

+-COP-+
 Copy File
 Source: #N21:20
 Dest: #N21:0
 Length: 3

R6:15.IN - FSC - File #5 COMM - 27
 -| - File #5 COMM - 27

File #5 COMM Proj:PLC3

07:29:00 02/19/99

```

R6:15.1N      - (U) - File #5 COMM - 27,28
                RES - File #5 COMM - 28
                - | - File #5 COMM - 28,28
R6:15.1N      - FSC - File #5 COMM - 27
                - | - File #5 COMM - 27
                - (U) - File #5 COMM - 27,28
                RES - File #5 COMM - 28
                - | - File #5 COMM - 28,28
FILE F:N014:1701003 LEN 3 - COP - File #5 COMM - 26,27
FILE F:N014:1701003 LEN 3 - MSG - File #5 COMM - 27
FILE F:N014:1701003 LEN 3 - COP - File #5 COMM - 29
FILE F:N014:1701003 LEN 3 - COP - File #5 COMM - 26,27
FILE F:N014:1701003 LEN 3 - MSG - File #5 COMM - 27
FILE F:N014:1701003 LEN 3 - COP - File #5 COMM - 29
FILE F:N021:0201003 LEN 3 - COP - File #5 COMM - 27,27
MG11:5.EN      - MSG - File #5 COMM - 27
                - | - File #5 COMM - 27
                - | - File #5 COMM - 27
FILE F:N021:0201003 LEN 3 - COP - File #5 COMM - 27,27
FILE F:N021:0001003 LEN 3 - COP - File #5 COMM - 27

```

```

sequenceDiagram
    participant T as 5:0028
    participant R6 as R6:15
    T->>R6: R6:15.DN
    Note over R6: [RES]
    R6-->>T: R6:15.FD
    Note over R6: (U)
  
```

R6:15.1N	-	FSC	-	File	#5	COMM	-	27
	-	(U)	-	File	#5	COMM	-	27
	-	RES	-	File	#5	COMM	-	27,28
R6:15.1N	-	FSC	-	File	#5	COMM	-	28,28
	-	(U)	-	File	#5	COMM	-	27
	-	RES	-	File	#5	COMM	-	27,28
	-		-	File	#5	COMM	-	28
	-		-	File	#5	COMM	-	28,28

COMMUN. WITH
PCU-1
IGNORED
COM-31
N14:0/1

5:0029 ----- Copy File -----
 Source: #N14:170
 Dest: #N14:120
 Length: 3

```
FILE F:N014:1701%003 LEN 3 - COP - File #5 COMM - 26,27
FILE F:N014:1701%003 LEN 3 - MSG - File #5 COMM - 27
FILE F:N014:1701%003 LEN 3 - COP - File #5 COMM - 29
FILE F:N014:1201%003 LEN 3 - COP - File #5 COMM - 26,29
```

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
Lockheed Martin Hanford Co.
Page:00034

File #5 COMM Proj:PLC3

07:29:00 02/19/99

COMMUN. WITH
PCU-1
IGNORED
COM-31
N14:0/1
5:0030 - I/I

+--COP-----+
Copy File
Source: #N14:0
Dest: #N14:60
Length: 4
+-----+

+--COP-----+
Copy File
Source: #N14:11
Dest: #N14:64
Length: 2
+-----+

+--COP-----+
Copy File
Source: #N14:24
Dest: #N14:66
Length: 2
+-----+

+--COP-----+
Copy File
Source: #N14:28
Dest: #N14:68
Length: 18
+-----+

FILE F:N014:0001%004 LEN 4 - COP - File #5 COMM - 30
FILE F:N014:0601%004 LEN 4 - COP - File #5 COMM - 30,31
FILE F:N014:0601%004 LEN 4 - MSG - File #5 COMM - 31
FILE F:N014:0111%002 LEN 2 - COP - File #5 COMM - 30
FILE F:N014:0641%002 LEN 2 - COP - File #5 COMM - 30
FILE F:N014:0641%002 LEN 2 - MSG - File #5 COMM - 31
FILE F:N014:0641%002 LEN 2 - COP - File #5 COMM - 31
FILE F:N014:0241%002 LEN 2 - COP - File #5 COMM - 5,30
FILE F:N014:0661%002 LEN 2 - COP - File #5 COMM - 30
FILE F:N014:0661%002 LEN 2 - MSG - File #5 COMM - 31
FILE F:N014:0661%002 LEN 2 - COP - File #5 COMM - 31
FILE F:N014:0281%002 LEN 2 - COP - File #5 COMM - 5,30
FILE F:N014:0681%018 LEN 18 - COP - File #5 COMM - 30
FILE F:N014:0681%018 LEN 18 - MSG - File #5 COMM - 31
FILE F:N014:0681%018 LEN 18 - COP - File #5 COMM - 31

COMMUN. WITH
 PCU-1
 IGNORED
 COM-31
 N14:0/1

5:0031

R6:14.IN
 (U)

MG11:6.EN

```

+---FSC-----+
+---|/|-----+ File Search/Compare |-(EN)-
Control:      R6:14
Length:       26 |-(DN)
Position:     0
Mode:         ALL |-(ER)
Expression:
#N14:60 <=> #N21:100
  
```

R6:14.FD

```

+---COP-----+
+---| |-----+ Copy File
Source:      #N14:60
Dest:       #N21:150
Length:      26
  
```

```

+---MSG-----+
+---| |-----+ Send/Receive Message |-(EN)-
Control Block: MG11:6 |-(DN)
                    |-(ER)
  
```

MG11:6.DN B3/164

```

+---COP-----+
+---| |-----+ [ONS] Copy File
Source:      #N21:150
Dest:       #N21:100
Length:      26
  
```

```

R6:14.IN  - FSC - File #5 COMM - 31
          - | | - File #5 COMM - 31
          - (U) - File #5 COMM - 31,32
          RES - File #5 COMM - 32
          - | | - File #5 COMM - 32,32
R6:14.IN  - FSC - File #5 COMM - 31
          - | | - File #5 COMM - 31
          - (U) - File #5 COMM - 31,32
          RES - File #5 COMM - 32
          - | | - File #5 COMM - 32,32
FILE _F:N014:0601X004 LEN 4 - COP - File #5 COMM - 30,31
FILE _F:N014:0601X004 LEN 4 - MSG - File #5 COMM - 31
FILE _F:N014:0601X004 LEN 4 - COP - File #5 COMM - 30,31
FILE _F:N014:0601X004 LEN 4 - MSG - File #5 COMM - 31
FILE _F:N021:1501X026 LEN 26 - COP - File #5 COMM - 31,31
MG11:6.EN - MSG - File #5 COMM - 31
          - | | - File #5 COMM - 31
          - |/| - File #5 COMM - 31
FILE _F:N021:1501X026 LEN 26 - COP - File #5 COMM - 31,31
  
```

FILE _F:NO21:1001%026 LEN 26 - COP - File #5 COMM - 31

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3165A, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00037

File #6 Y71 Proj:PLC3

07:29:01 02/19/99

	TR-R VALVES CONTROL SUBROUTINE		PROGRAM FILE #6 START OF SUBROUTINE COMMENT COIL
6:0000	+--SBR-----+ Subroutine		B3/41 -( )
	B3/41 - ( ) - File #6 Y71 - 0		
	OCS OPEN OCS CLOSE VALVE VALVE SOV-3165A SOV-3165A		OPEN VALVE SOV-3165A BIT
	Y71 Y71 MASTER RESET		
6:0001	HS-3165A1 HS-3165A2 N19:3/15 N14:120/14 N14:120/15		B3/300 -( )
	OPEN VALVE SOV-3165A BIT		
	B3/300		
	B3/300 - ( ) - File #6 Y71 - 1 - ( ) - File #6 Y71 - 1,2,47 - ( ) - File #6 Y71 - 54		
	OPEN VALVE SOV-3165A BIT		OPEN VALVE SOV-3165A
	B3/300		Y71 SOV-3165A-0 0:006/00 771-0D16
6:0002	TRANSFER 1 INITIATED		
	Y-41.1 TR_ON 1001 N14:3/0		
	TRANSFER 3 INITIATED		
	Y-44.1 TR_ON 1003 N14:3/3		
0:006/000	- ( ) - File #6 Y71 - 2 - ( ) - File #6 Y71 - 12 - ( ) - File #6 Y71 - 47		

Hanford Cross Site Transfer System (PCU-3)
SEQUENCING FOR TRANSFER VALVE SOV-3165A, Y-71.1
Lockheed Martin Hanford Co.
Page:00038

HNF-2346, Rev. 1

File #6 Y71 Proj:PLC3

07:29:02 02/19/99

Hanford Cross Site Transfer System (PCU-3)
SEQUENCING FOR TRANSFER VALVE SOV-3165A, Y-71.1
Lockheed Martin Hanford Co.
Page:00039

HNF-2346, Rev. 1

File #6 Y71 Proj:PLC3

07:29:02 02/19/99

SOV-3165A
VALVE FAILED
TO CLOSE
DELAY COMPLETE

VALVE
FAILED
TO CLOSE

Y71
ZA-3165A2
N14:1/1

```

6:0006|-----|T4:14.DN|

```

N14:1/1 - - ( ) - - File #6 Y71 - 6
- | - - File #6 Y71 - 9

OCS OPEN
VALVE
SOV-3165A

S0V-3165A
IS OPEN

SOV-3165A
VALVE FAILED
TO OPEN
DELAY

6.0007 | +-----| |-----|

Y71
HS-3165A1
N14:120/14

Y70
ZSH-3165A
1:003/00
-----|/|---
1771-LBD

```

+-----+
| Timer On Delay |-(EN)
| Timer:         |T4:15
| Base (SEC):    |1.0  -(DN)
| Preset:        |10
| Accum:         |0
+-----+

```

TRANSFER 1
INITIATED

Y-41.1
TR ON 1001
N14:3/0

TRANSFER 3
INITIATED

Y-44.1
TR 0N 1003
N14:3/3

S0V-3165A
VALVE FAILED
TO OPEN
DELAY

T4:15-EN

```
T4:15.EN      - TON      - File #6 Y71 - 7
               - | | - - File #6 Y71 - 7,8
               TON      - File #6 Y71 - 15
               - | | - - File #6 Y71 - 15
```

S0V-3165A
VALVE FAILED
TO OPEN
DELAY COMPLETE

VALVE
FAILED
TO OPEN

Y71
ZA-3165A1
N14:1/0

6:0008	----	14.15.0N		--

N14:1/0 - - ( ) - - File #6 Y71 - 8
- | | - - File #6 Y71 - 9

	OCS OPEN VALVE SOV-3165A	OPEN VALVE SOV-3165A		OCS OPEN VALVE SOV-3165A
	Y71 HS-3165A1 N14:120/14	Y71 SOV-3165A-0 0:006/00		Y71 HS-3165A1 N14:120/14 (U)
6:0012		771-0D1 OCS CLOSE VALVE SOV-3165A Y71 HS-3165A2 N14:120/15 MASTER RESET N19:3/15		
	N14:120/14	- / - File #6 Y71 - 1 - / - File #6 Y71 - 3 - / - File #6 Y71 - 7,12 - (U) - File #6 Y71 - 12 - / - File #6 Y71 - 13,15 - / - File #6 Y71 - 16,55		
	OCS CLOSE VALVE SOV-3165A	CLOSE VALVE SOV-3165A		OCS CLOSE VALVE SOV-3165A
	Y71 HS-3165A2 N14:120/15	Y71 SOV-3165A-C 0:006/01		Y71 HS-3165A2 N14:120/15 (U)
6:0013		1771-0D1 OCS OPEN VALVE SOV-3165A Y71 HS-3165A1 N14:120/14 TRANSFER 1 INITIATED Y-41.1 TR_ON 1001 N14:3/0 TRANSFER 3 INITIATED Y-44.1 TR_ON 1003 N14:3/3		
	N14:120/15	- / - File #6 Y71 - 1 - / - File #6 Y71 - 3,5,12,13 - (U) - File #6 Y71 - 13 - / - File #6 Y71 - 16 - / - File #6 Y71 - 54 - / - File #6 Y71 - 55		

File #6 Y71 Proj:PLC3

07:29:02 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3166A, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00044

File #6 Y71 Proj:PLC3

07:29:03 02/19/99

File #6 Y71 Proj:PLC3

07:29:03 02/19/99

OCS CLOSE VALVE SOV-3166A	CLOSE VALVE SOV-3166A	OCS CLOSE VALVE SOV-3166A
Y71 HS-3166A2 N14:121/4	Y71 SOV-3166A-C 0:006/05	Y71 HS-3166A2 N14:121/4 (U)
6:0026		
	1771-0D1 OCS OPEN VALVE SOV-3166A Y71 HS-3166A1 N14:121/3 ----- -----	
	TRANSFER 1 INITIATED	
	Y-41.1 TR ON 1001 N14:3/0 ----- -----	
	TRANSFER 3 INITIATED	
	Y-44.1 TR ON 1003 N14:3/3 ----- -----	
N14:121/4	- - - File #6 Y71 - 2 - - - File #6 Y71 - 14 - - - File #6 Y71 - 16,18,25,26 -(U) - - File #6 Y71 - 26	
OCS OPEN VALVE SOV-3165B	OCS CLOSE VALVE SOV-3165B	OPEN VALVE SOV-3165B BIT
Y71 HS-3165B1 N14:121/5	Y71 HS-3165B2 N14:121/6	MASTER RESET N19:3/15 B3/304 ( )
6:0027		
OPEN VALVE SOV-3165B BIT B3/304		
B3/304	- - ( ) - - File #6 Y71 - 27 - - - File #6 Y71 - 27,28	

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3166A, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00047

File #6 Y71 Proj:PLC3

07:29:03 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3165A, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00048

File #6 Y71 Proj:PLC3

07:29:03 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3166A, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00050

File #6 Y71 Proj:PLC3

07:29:04 02/19/99

	OCS OPEN VALVE SOV-3165B Y71 HS-3165B1 N14:121/5	OPEN VALVE SOV-3165B Y71 SOV-3165B-0 0:006/02	OCS OPEN VALVE SOV-3165B Y71 HS-3165B1 N14:121/5 -(U)
6:0038		1771-0D1 OCS CLOSE VALVE SOV-3165B Y71 HS-3165B2 N14:121/6 MASTER RESET N19:3/15	
	N14:121/5	- - - - File #6 Y71 - 27 - / - - File #6 Y71 - 29 - - - File #6 Y71 - 33, 38 - (U) - - File #6 Y71 - 38 - - - File #6 Y71 - 39	
	OCS CLOSE VALVE SOV-3165B Y71 HS-3165B2 N14:121/6	CLOSE VALVE SOV-3165B Y71 SOV-3165B-C 0:006/03	OCS CLOSE VALVE SOV-3165B Y71 HS-3165B2 N14:121/6 -(U)
6:0039		1771-0D1 OCS OPEN VALVE SOV-3165B Y71 HS-3165B1 N14:121/5 TRANSFER 2A INITIATED Y-42.1 N19:3/11 TRANSFER 2B INITIATED Y-43.1 N19:3/12	
	N14:121/6	- - / - - File #6 Y71 - 27 - - - File #6 Y71 - 29, 31, 38, 39 - (U) - - File #6 Y71 - 39	

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3166B, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00051

File #6 Y71 Proj:PLC3

07:29:04 02/19/99

	OCS OPEN VALVE SOV-3166B	OCS CLOSE VALVE SOV-3166B		OPEN VALVE SOV-3166B BIT
	Y71 HS-3166B1 N14:121/7	Y71 HS-3166B2 N14:121/8	MASTER RESET N19:3/15	B3/306
6:0040	+			+
	OPEN VALVE SOV-3166B BIT			
	B3/306			
	+			+
	B3/306	- - ( ) - - File #6 Y71 - 40		
		- - - File #6 Y71 - 40,41		
	OPEN VALVE SOV-3166B BIT			OPEN VALVE SOV-3166B
	B3/306			Y71 SOV-3166B-0 0:006/06
6:0041	+			+
	TRANSFER 2A INITIATED			771-0D16
	Y-42.1 N19:3/11			
	+			+
	TRANSFER 2B INITIATED			
	Y-43.1 N19:3/12			
	+			+
	0:006/006	- - ( ) - - File #6 Y71 - 41		
		- - - File #6 Y71 - 51		
	OCS CLOSE VALVE SOV-3166B	OCS OPEN VALVE SOV-3166B	TRANSFER 2A INITIATED	TRANSFER 2B INITIATED
	Y71 HS-3166B2 N14:121/8	Y71 HS-3166B1 N14:121/7	Y-42.1 N19:3/11	Y-43.1 N19:3/12
6:0042	+			+
	CLOSE VALVE SOV-3166B BIT			CLOSE VALVE SOV-3166B BIT
	B3/307			B3/307
	+			+
	B3/307	- - ( ) - - File #6 Y71 - 42		
		- - - File #6 Y71 - 42,43		

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3166B, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00053

HNF-2346, Rev. 1

File #6 Y71 Proj:PLC3

07:29:04 02/19/99

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR TRANSFER VALVE SOV-3166B, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00054

HNF-2346, Rev. 1

File #6 Y71 Proj:PLC3

07:29:05 02/19/99

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
SEQUENCING FOR TRANSFER VALVE SOV-3166B, Y-71.1
Lockheed Martin Hanford Co.
Page:00055

HNF-2346, Rev. 1

File #6 Y71 Proj:PLC3

07:29:05 02/19/99

	OCS CLOSE VALVE SOV-3166B	CLOSE VALVE SOV-3166B	OCS CLOSE VALVE SOV-3166B
	Y71 HS-3166B2 N14:121/8	Y71 SOV-3166B-C 0:006/07	Y71 HS-3166B2 N14:121/8 (U)
6:0052	----- -----		
	1771-001		
	OCS OPEN VALVE SOV-3166B		
	Y71 HS-3166B1 N14:121/7 ----- -----		
	TRANSFER 2A INITIATED		
	Y-42.1		
	N19:3/11 ----- -----		
	TRANSFER 2B INITIATED		
	Y-43.1		
	N19:3/12 ----- -----		
	N14:121/8 - - /- - File #6 Y71 - 40 - /- - File #6 Y71 - 42,44,51,52 -(U) - File #6 Y71 - 52		
	TR-R VALVES CONTROL SUBROUTINE		
6:0053	+--RET-----+ - Return () -		
6:0054	-----[End]-----		

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3185A, Y-81.1
 Lockheed Martin Hanford Co.
 Page:00057

HNF-2346, Rev. 1

File #7 Y81 Proj:PLC3

07:29:05 02/19/99

	SOV-3185A IS CLOSED	SOV-3185A IS OPEN	SOV-3185A VALVE POSITION SWITCH FAILURE DELAY
	Y81-1 ZSL-3185A I:003/17	Y81-1 ZSH-3185A I:003/16	---TON---
7:0008	1771-IBD	1771-IBD	Timer On Delay (EN)
	SOV-3185A IS CLOSED	SOV-3185A IS OPEN	Timer: T4:10
	Y81-1 ZSL-3185A I:003/17	Y81-1 ZSH-3185A I:003/16	Base (SEC): 1.0 (DN)
	1771-IBD	1771-IBD	Preset: 5
			Accum: 0
	T4:10.DN	- TON - File #7 Y81 - 8	
		- - File #7 Y81 - 9	
	SOV-3185A VALVE POSITION SWITCH FAILURE DELAY COMPLETE		VALVE POSITION SWITCH FAILURE
	T4:10.DN		Y81-1 ZA-3185A N14:2/11
7:0009			( )
	N14:2/11	- ( ) - File #7 Y81 - 9	
	OCS OPEN VALVE SOL-3185A	OPEN VALVE SOV-3185A	OCS OPEN VALVE SOL-3185A
	Y81-1 HS-3185A1 N14:120/6	Y81-1 SOV-3185A-0 O:006/16	Y81-1 HS-3185A1 N14:120/6
7:0010		1771-0D1	(U)
		SUPERNATE LINE HIGH PRESSURE INTERLOCK	
		B3/76	
		OCS CLOSE VALVE SOL-3185A	
		Y81-1 HS-3185A2 N14:120/7	
	N14:120/6	- - File #7 Y81 - 1	
		- - File #7 Y81 - 2	
		- - File #7 Y81 - 6,10	
		- (U) - File #7 Y81 - 10	
		- - File #7 Y81 - 11	

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3185A, Y-81.1
 Lockheed Martin Hanford Co.

HNF-2346, Rev. 1

File #7 Y81 Proj:PLC3

Page:00059

07:29:05 02/19/99

	OCS CLOSE VALVE SOL-3185A	CLOSE VALVE SOV-3185A	OCS CLOSE VALVE SOL-3185A
	Y81-1 HS-3185A2 N14:120/7	Y81-1 SOV-3185A-C 0:006/17	Y81-1 HS-3185A2 N14:120/7
7:0011	----- -----	----- -----	----- ----- (U)
		1771-0D1 OCS OPEN VALVE SOL-3185A	
		Y81-1 HS-3185A1 N14:120/6 ----- -----	
		MASTER RESET N19:3/15 +----- -----+	
N14:120/7	- - / - -	- - / - -	- - / - -
	- - -	- - -	- - -
	-(U) - -	-(U) - -	-(U) - -
	- File #7 Y81 - 1	- File #7 Y81 - 2,4,10,11	- File #7 Y81 - 11

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3185B, Y-81.2
 Lockheed Martin Hanford Co.
 Page:00060

HNF-2346, Rev. 1

File #7 Y81 Proj:PLC3

07:29:06 02/19/99

	SOV-3185B IS CLOSED	SOV-3185B IS OPEN	SOV-3185B VALVE POSITION SWITCH FAILURE DELAY
	Y81-2 ZSL-3185B I:004/01	Y81-2 ZSH-3185B I:004/00	
7:0019	1771-1BD SOV-3185B IS CLOSED	1771-1BD SOV-3185B IS OPEN	TON Timer On Delay Timer: T4:11 Base (SEC): 1.0 Preset: 5 Accum: 0
	Y81-2 ZSL-3185B I:004/01	Y81-2 ZSH-3185B I:004/00	
	1771-1BD	1771-1BD	
	T4:11.DN	- TON - File #7 Y81 - 19 - I - File #7 Y81 - 20	
	SOV-3185B VALVE POSITION SWITCH FAILURE DELAY COMPLETE		VALVE POSITION SWITCH FAILURE
7:0020	T4:11.DN		Y81-2 ZA-3185B N14:2/14 ( )
	N14:2/14	- ( ) - File #7 Y81 - 20	
	OCS OPEN VALVE SOL-3185B	OPEN VALVE SOV-3185B	OCS OPEN VALVE SOL-3185B
	Y81-2 HS-3185B1 N14:120/8	Y81-2 SOV-3185B-0 0:007/00	Y81-2 HS-3185B1 N14:120/8 (U)
7:0021	1771-0D1		
	SUPERNATE LINE HIGH PRESSURE INTERLOCK		
	B3/75		
	OCS CLOSE VALVE SOL-3185B		
	Y81-2 HS-3185B2 N14:120/9		
N14:120/8	- I - File #7 Y81 - 12 - I - File #7 Y81 - 13 - I - File #7 Y81 - 17, 21 - (U) - File #7 Y81 - 21 - I - File #7 Y81 - 22		

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3185B, Y-81.2
 Lockheed Martin Hanford Co.
 Page:00063

HNF-2346, Rev. 1

File #7 Y81 Proj:PLC3

07:29:06 02/19/99

	OCS CLOSE VALVE SOL-3185B	CLOSE VALVE SOV-3185B	OCS CLOSE VALVE SOL-3185B
	Y81-2 HS-3185B2 N14:120/9	Y81-2 SOV-3185B-C 0:007/01	Y81-2 HS-3185B2 N14:120/9
7:0022	----- -----	----- -----	----- -----
		1771-0D1 OCS OPEN VALVE SOL-3185B	
		Y81-2 HS-3185B1 N14:120/8	
		----- -----	
		MASTER RESET	
		N19:3/15	
		----- -----	
N14:120/9	- - / -	- File #7 Y81 - 12	
	- -	- File #7 Y81 - 13,15,21,22	
	-(U) -	- File #7 Y81 - 22	

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3168A, Y-81.3
 Lockheed Martin Hanford Co.
 Page:00064

HNF-2346, Rev. 1

File #7 Y81 Proj:PLC3

07:29:06 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3168B, Y-81.4
 Lockheed Martin Hanford Co.
 Page:00068

File #7 Y81 Proj:PLC3

07:29:07 02/19/99

```

OCS OPEN                               OCS CLOSE
VALVE                                  VALVE
SOL-3168B                             SOL-3168B

Y81-4                                  Y81-4
HS-3168B1                             HS-3168B2
N14:120/12                             N14:120/13
B3/78                                  N19:3/15
MASTER RESET                           MASTER RESET

SLURRY LINE
HIGH PRESSURE
INTERLOCK

OPEN VALVE
SOV-3168B

Y81-4
SOV-3168B-0
0:006/14
1771-0D1

0:006/014  - - ( ) - - File #7 Y81 - 34
            - | - - File #7 Y81 - 34,43

OCS CLOSE                               OCS OPEN
VALVE                                  VALVE
SOL-3168B                             SOL-3168B

Y81-4                                  Y81-4
HS-3168B2                             HS-3168B1
N14:120/13                             N14:120/12
N19:3/15
MASTER RESET                           MASTER RESET

CLOSE VALVE
SOV-3168B
BIT

Y-81.4

B3/311

B3/311  - - ( ) - - File #7 Y81 - 35
        - | - - File #7 Y81 - 35,36

CLOSE VALVE
SOV-3168B
BIT

Y-81.4

B3/311

7:0036  +-----+-----+-----+-----+
| MASTER RESET |
| N19:3/15    |
+-----+-----+-----+-----+

0:006/015  - - ( ) - - File #7 Y81 - 36
            - | - - File #7 Y81 - 44

OPEN VALVE
SOV-3168B

Y81-4
SOV-3168B-0
0:006/14
771-0D16

CLOSE VALVE
SOV-3168B
BIT

Y-81.4

B3/311

Y81-4
SOV-3168B-C
0:006/15
771-0D16
  
```

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR VENT VALVE SOV-3168B, Y-81.4
 Lockheed Martin Hanford Co.
 Page:00069

File #7 Y81 Proj:PLC3

07:29:07 02/19/99

	SOV-3168B IS CLOSED	SOV-3168B IS OPEN		SOV-3168B VALVE POSITION SWITCH FAILURE DELAY	
	Y-81-4 ZSL-3168B I:003/15	Y-81-4 ZSH-3168B I:003/14			
7:0041	1771-IBD SOV-3168B IS CLOSED	1771-IBD SOV-3168B IS OPEN		TON Timer On Delay Timer: T4:13 Base (SEC): 1.0 Preset: 5 Accum: 0	(EN) (DN)
	Y-81-4 ZSL-3168B I:003/15	Y-81-4 ZSH-3168B I:003/14			
	1771-IBD	1771-IBD			
	T4:13.DN	- TON - File #7 Y81 - 41 -I - File #7 Y81 - 42			
	SOV-3168B VALVE POSITION SWITCH FAILURE DELAY COMPLETE			VALVE POSITION SWITCH FAILURE	
7:0042	T4:13.DN			Y81-4 ZA-3168B N14:2/8	( )
	N14:2/8	- ( ) - File #7 Y81 - 42			
	OCS OPEN VALVE SOL-3168B	OPEN VALVE SOV-3168B		OCS OPEN VALVE SOL-3168B	
	Y81-4 HS-3168B1 N14:120/12	Y81-4 SOV-3168B-0 O:006/14		Y81-4 HS-3168B1 N14:120/12	(U)
7:0043	1771-0D1				
	SLURRY LINE HIGH PRESSURE INTERLOCK				
	B3/78				
	OCS CLOSE VALVE SOL-3168B				
	Y81-4 HS-3168B2 N14:120/13				
	N14:120/12	-I - File #7 Y81 - 34 -I - File #7 Y81 - 35 -I - File #7 Y81 - 39, 43 -(U)- File #7 Y81 - 43 -I - File #7 Y81 - 44			

```
-----+-----+-----+
OCS CLOSE      CLOSE VALVE      OCS CLOSE
VALVE          SOV-3168B          VALVE
SOL-3168B                                           SOL-3168B

Y81-4          Y81-4          Y81-4
HS-3168B2     SOV-3168B-C     HS-3168B2
N14:120/13    0:006/15       N14:120/13
7:0044 -----+-----+-----+ (U)-----+
|                                     |
| 1771-0D1                          |
| OCS OPEN                          |
| VALVE                            |
| SOL-3168B                        |
|                                     |
| Y81-4                            |
| HS-3168B1                        |
| N14:120/12                        |
| -----+-----+                  |
|                                     |
| MASTER RESET                      |
| N19:3/15                          |
| -----+-----+                  |
|                                     |
N14:120/13 - -|/| - - File #7 Y81 - 34
              - -| - - File #7 Y81 - 35,37,43,44
              -(U) - - File #7 Y81 - 44

                                     VENT VALVES
                                     CONTROL
                                     SUBROUTINE
7:0045 -----+---RET---+
              |Return ()|
              +-----+

7:0046 -----+-----+-----+ [End]-
```

SUMP PUMP CONTROL SUBROUTINE		PROGRAM FILE #8 START OF SUBROUTINE COMMENT COIL
8:0000	<pre> +-SBR-----+ Subroutine +-----+ </pre>	<pre> B3/43 ( ) </pre>
B3/43 - - ( ) - File #8 Y82&Y-88 - 0		
	<pre> SOV-3167A SOV-3167B IS CLOSED IS CLOSED </pre>	SHUTDOWN SUMP PUMP P-3116
8:0001	<pre> Y88-1 Y-88.2 ZSL-3167A ZSL-3167B I:003/11 I:004/13 1771-IBD 1771-IBD </pre>	<pre> Y-82.1 P-3116 0:007/02 ( ) 771-0016 </pre>
0:007/002 - - ( ) - File #8 Y82&Y-88 - 1		
8:0002	<pre> LOSS OF VACUUM WT-SNL-3150 PT-3126A +-GRT-----+ Greater Than (A>B) Source A: N20:8 2 Source B: N7:0 2 +-----+ </pre>	<pre> SUPERNATE LINE HIGH PRESSURE INTERLOCK B3/75 ( ) SUPERNATE LINE HIGH PRESSURE INTERLOCK B3/76 ( ) </pre>
B3/75 - - - File #7 Y81 - 12 - - File #7 Y81 - 21 - ( ) - File #8 Y82&Y-88 - 2 - - File #8 Y82&Y-88 - 4 - - File #8 Y82&Y-88 - 13 - - File #8 Y82&Y-88 - 15 - - File #8 Y82&Y-88 - 24 B3/76 - - - File #7 Y81 - 1 - - File #7 Y81 - 10 - ( ) - File #8 Y82&Y-88 - 2		
8:0003	<pre> LOSS OF VACUUM WT-SLL-3160 PT-3126B +-GRT-----+ Greater Than (A>B) Source A: N20:9 -6 Source B: N7:1 2 +-----+ </pre>	<pre> SLURRY LINE HIGH PRESSURE INTERLOCK B3/77 ( ) SLURRY LINE HIGH PRESSURE INTERLOCK B3/78 ( ) </pre>
B3/77 - - - File #7 Y81 - 23 - - File #7 Y81 - 32 - ( ) - File #8 Y82&Y-88 - 3 B3/78 - - - File #7 Y81 - 34 - - File #7 Y81 - 43 - ( ) - File #8 Y82&Y-88 - 3		

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167A, Y-88.1
 Lockheed Martin Hanford Co.

File #8 Y82&Y-88 Proj:PLC3

Page:00074

07:29:08 02/19/99

	OCS CLOSE VALVE SOV-3167A	SOV-3167A IS CLOSED	SOV-3167A VALVE FAILED TO CLOSE DELAY Y-88.1
8:0007	Y88-1 HS-3167A2 N14:121/10	Y88-1 ZSL-3167A I:003/11 1771-1BD	TON On Delay Timer: T4:26 Base (SEC): 1.0 Preset: 10 Accum: 0 -(EN)- -(DN)
	MASTER RESET N19:3/15		
	SOV-3167A VALVE FAILED TO CLOSE DELAY T4:26.EN		
	T4:26.EN	- TON - File #8 Y82&Y-88 - 7 -I - File #8 Y82&Y-88 - 7,8	
8:0008	SOV-3167A VALVE FAILED TO CLOSE DELAY COMPLETE T4:26.DN		VALVE FAILED TO CLOSE Y88-1 ZA-3167A2 N14:1/13 -( )
	N14:1/13	- -( ) - File #8 Y82&Y-88 - 8	
8:0009	OCS OPEN VALVE SOV-3167A Y88-1 HS-3167A1 N14:121/9	SOV-3167A IS OPEN Y88-1 ZSH-3167A I:003/10 1771-1BD	SOV-3167A VALVE FAILED TO OPEN DELAY TON On Delay Timer: T4:27 Base (SEC): 1.0 Preset: 10 Accum: 0 -(EN)- -(DN)
	SOV-3167A VALVE FAILED TO OPEN DELAY T4:27.EN		
	T4:27.EN	- TON - File #8 Y82&Y-88 - 9 -I - File #8 Y82&Y-88 - 9,10	
8:0010	SOV-3167A VALVE FAILED TO OPEN DELAY COMPLETE T4:27.DN		VALVE FAILED TO OPEN Y88-1 ZA-3167A1 N14:1/12 -( )
	N14:1/12	- -( ) - File #8 Y82&Y-88 - 10	

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167A, Y-88.1
 Lockheed Martin Hanford Co.
 Page:00075

HNF-2346, Rev. 1

File #8 Y82&Y-88 Proj:PLC3

07:29:08 02/19/99

	SOV-3167A IS CLOSED	SOV-3167A IS OPEN		SOV-3167A VALVE POSITION SWITCH FAILURE DELAY	
8:0011	Y88-1 ZSL-3167A I:003/11	Y88-1 ZSH-3167A I:003/10			
	1771-IBD	1771-IBD		+-TON-----+	
	SOV-3167A IS CLOSED	SOV-3167A IS OPEN		Timer On Delay	-(EN)-
				Timer: T4:28	
				Base (SEC): 1.0	-(DN)
				Presel: 5	
				Accum: 0	
	Y88-1 ZSL-3167A I:003/11	Y88-1 ZSH-3167A I:003/10			
	1771-IBD	1771-IBD			
	T4:28.DN	- TON - File #8 Y82&Y-88 - 11			
		- - File #8 Y82&Y-88 - 12			
	SOV-3167A VALVE POSITION SWITCH FAILURE DELAY COMPLETE			VALVE POSITION SWITCH FAILURE	
8:0012	T4:28.DN			Y88-1 ZA-3167A N14:1/14	
				( )	
	N14:1/14	- - ( ) - File #8 Y82&Y-88 - 12			
	OCS OPEN VALVE SOV-3167A	OPEN VALVE SOV-3167A		OCS OPEN VALVE SOV-3167A	
8:0013	Y88-1 HS-3167A1 N14:121/9	Y88-1 SOV-3167A-0 O:006/10		Y88-1 HS-3167A1 N14:121/9	
		1771-0D1			-(U)
		OCS CLOSE VALVE SOV-3167A			
		Y88-1 HS-3167A2 N14:121/10			
		MASTER RESET			
		N19:3/15			
		SUPERNATE LINE HIGH PRESSURE INTERLOCK			
		B3/75			
N14:121/9	- - - File #8 Y82&Y-88 - 4				
	- - File #8 Y82&Y-88 - 5				
	- - File #8 Y82&Y-88 - 9 13				
	-(U) - File #8 Y82&Y-88 - 13				
	- - File #8 Y82&Y-88 - 14				

File #8 Y82&Y-88 Proj:PLC3

07:29:08 02/19/99

	OCS CLOSE VALVE SOV-3167A	OCS CLOSE VALVE SOV-3167A	OCS CLOSE VALVE SOV-3167A
	Y88-1 HS-3167A2 N14:121/10	Y88-1 SOV-3167A-C 0:006/11	Y88-1 HS-3167A2 N14:121/10
8:0014	1771-0D1 OCS OPEN VALVE SOV-3167A Y88-1 HS-3167A1 N14:121/9		(U)
N14:121/10	- - / - - File #8 Y82&Y-88 - 4 - - / - - File #8 Y82&Y-88 - 5,7,13,14 -(U) - - File #8 Y82&Y-88 - 14		

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167B, Y-88.2
 Lockheed Martin Hanford Co.
 Page:00077

HNF-2346, Rev. 1

File #8 Y82&Y-88 Proj:PLC3

07:29:08 02/19/99

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167B, Y-88.2
 Lockheed Martin Hanford Co.
 Page:00078

File #8 Y82&Y-88 Proj:PLC3

07:29:09 02/19/99

	SOV-3167B IS CLOSED	SOV-3167B IS OPEN		SOV-3167B VALVE POSITION SWITCH FAILURE DELAY	
	Y-88.2 ZSL-3167B I:004/13	Y-88.2 ZSH-3167B I:004/12			
8:0022	1771-1BD SOV-3167B IS CLOSED	1771-1BD SOV-3167B IS OPEN		TON Timer On Delay Timer: T4:31 Base (SEC): 1.0 Preset: 5 Accum: 0	(-EN)- (-DN)
	Y-88.2 ZSL-3167B I:004/13	Y-88.2 ZSH-3167B I:004/12			
	1771-1BD	1771-1BD			
	T4:31.DN	- TON - File #8 Y82&Y-88 - 22 - I - File #8 Y82&Y-88 - 23			
	SOV-3167B VALVE POSITION SWITCH FAILURE DELAY COMPLETE			VALVE POSITION SWITCH FAILURE	
8:0023	T4:31.DN			Y88-2 ZA-3167B N14:2/2	( )
	N14:2/2	- ( ) - File #8 Y82&Y-88 - 23			
	OCS OPEN VALVE SOV-3167B	OPEN VALVE SOV-3167B		OCS OPEN VALVE SOV-3167B	
8:0024	Y87-2 HS-3167B1 N14:121/11	Y88-1 SOV-3167B-0 O:007/03		Y87-2 HS-3167B1 N14:121/11	(U)
	1771-0D1 OCS CLOSE VALVE SOV-3167B				
	Y87-2 HS-3167B2 N14:121/12				
	MASTER RESET N19:3/15				
	SUPERNATE LINE HIGH PRESSURE INTERLOCK				
	B3/75				
N14:121/11	- I - File #8 Y82&Y-88 - 15 - I - File #8 Y82&Y-88 - 16 - I - File #8 Y82&Y-88 - 20,24 - (U) - File #8 Y82&Y-88 - 24 - I - File #8 Y82&Y-88 - 25				

Hanford Cross Site Transfer System (PCU-3)
 SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167B, Y-88.2
 Lockheed Martin Hanford Co.
 Page:00080

07:29:09 02/19/99

[End] -

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
TRANSFER PERMISSIVES LOGIC, ES-058-Y70 SH.1
Lockheed Martin Hanford Co.
Page:00081

HNF-2346, Rev. 1

File #10 Y70 Proj:PLC3

07:29:09 02/19/99

	INITIATE TRANSFER SUBROUTINE	PROGRAM FILE #10 START OF SUBROUTINE COMMENT COIL
10:0000	+-SBR-----+ Subroutine -----+ +-+-----+	B3/45 -( )-----
	B3/45 - -( ) - File #10 Y70 - 0	
	*****TRANSFER SEQUENCE MASTER LOCK-OUT AND INITIATE CONTROLS*****	
	OCS INITIATE TRANSFER	INITIATE TRANSFER
10:0001	Y-70.1 HS-1000A N14:122/0 +-----+ +-----+ INITIATE TRANSFER Y70 MASTER RESET B3/64 N19:3/15 +-----+ +-----+	Y70 B3/64 ( )-----
	B3/64 - -( ) - File #10 Y70 - 1 - - File #10 Y70 - 1,3,9,13,17,21	

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
TRANSFER PERMISSIVES LOGIC, ES-058-Y70 SH.1
Lockheed Martin Hanford Co.
Page:00082

HNF-2346, Rev. 1

File #10 Y70 Proj:PLC3

07:29:09 02/19/99

10:0002	TRANSFER 1 LOCKOUT	TRANSFER 2-A LOCKOUT	OCS INITIATE TRANSFER	TRANSFER LOCK OUT BIT
	Y70	Y70	Y-70.1 HS-1000A N14:122/0	Y-70.1 B3/65
	B3/67	B3/69		( )
	TRANSFER 1 LOCKOUT	TRANSFER 2-B LOCKOUT		
	Y70	Y70		MASTER RESET
	B3/67	B3/71		N19:3/15
	( )	( )		( )
	TRANSFER 1 LOCKOUT	TRANSFER 3 LOCKOUT		
	Y70	Y70		
	B3/67	B3/73		
	( )	( )		
	TRANSFER 2-A LOCKOUT	TRANSFER 2-B LOCKOUT		
	Y70	Y70		
	B3/69	B3/71		
	( )	( )		
	TRANSFER 2-A LOCKOUT	TRANSFER 3 LOCKOUT		
	Y70	Y70		
	B3/69	B3/73		
	( )	( )		
	TRANSFER 2-B LOCKOUT	TRANSFER 3 LOCKOUT		
	Y70	Y70		
	B3/71	B3/73		
	( )	( )		
	OCS RESET TRANSFER			
	Y-70.1 HS-1000B N14:122/1			
	( )			
	MASTER RESET			
	N19:3/15			
	( )			

B3/65 - ( ) - File #10 Y70 - 2
N19:3/15 - / - File #6 Y71 - 1
- / - File #6 Y71 - 4,5,12
- / - File #6 Y71 - 14
- / - File #6 Y71 - 17,18,25
- / - File #6 Y71 - 27
- / - File #6 Y71 - 30,31,38
- / - File #6 Y71 - 40
- / - File #6 Y71 - 43,44,51
- / - File #6 Y71 - 54

	N19:3/15	- / - File #7 Y81 - 1,2			
		- / - File #7 Y81 - 3,4,11			
		- / - File #7 Y81 - 12,13			
		- / - File #7 Y81 - 14,15,22			
		- / - File #7 Y81 - 23,24			
		- / - File #7 Y81 - 25,26,33			
		- / - File #7 Y81 - 34,35			
		- / - File #7 Y81 - 36,37,44			
		- / - File #8 Y82&Y-88 - 4			
		- / - File #8 Y82&Y-88 - 6,7,13			
		- / - File #8 Y82&Y-88 - 15			
		- / - File #8 Y82&Y-88 - 17,18,24			
		- / - File #10 Y70 - 1			
		- / - File #10 Y70 - 2			
		- / - File #10 Y70 - 2			
		- / - File #10 Y70 - 4			
		- / - File #10 Y70 - 5,8,12,16,20,53			
		- / - File #11 Y41-Y44 - 1			
		- / - File #11 Y41-Y44 - 4,7,7			
		- / - File #11 Y41-Y44 - 9			
	OCS INITIATE TRANSFER	INITIATE TRANSFER		OCS INITIATE TRANSFER	
	Y-70.1 HS-1000A N14:122/0	Y70 B3/64		Y-70.1 HS-1000A N14:122/0	
10:0003				(U)	
	N14:122/0	- / - File #10 Y70 - 1			
		- / - File #10 Y70 - 2			
		- / - File #10 Y70 - 3			
		(U) - File #10 Y70 - 3			
		- / - File #10 Y70 - 4			
	OCS RESET TRANSFER			OCS RESET TRANSFER	
	Y-70.1 HS-1000B N14:122/1	MASTER RESET N19:3/15		Y-70.1 HS-1000B N14:122/1	
10:0004				(U)	
		OCS INITIATE TRANSFER			
		Y-70.1 HS-1000A N14:122/0			
	N14:122/1	- / - File #10 Y70 - 2			
		(U) - File #10 Y70 - 4			
		- / - File #10 Y70 - 4			

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 TRANSFER PERMISSIVES LOGIC, ES-058-Y70 SH.1
 Lockheed Martin Hanford Co.
 Page:00084

HNF-2346, Rev. 1

File #10 Y70 Proj:PLC3

07:29:10 02/19/99

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
TRANSFER PERMISSIVES LOGIC, ES-058-Y70 SH.1
Lockheed Martin Hanford Co.
Page:00088

HNF-2346, Rev. 1

File #10 Y70 Proj:PLC3

07:29:10 02/19/99

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 241-SY-A TO 241-A-B TRANSFER SCHEME # 1, Y-41.1
 Lockheed Martin Hanford Co.
 Page:00089

HNF-2346, Rev. 1

File #11 Y41-Y44 Proj:PLC3

07:29:11 02/19/99

	TRANSFER 1-2A-2B-3 SUBROUTINE				PROGRAM FILE #11 START OF SUBROUTINE COMMENT COIL	
11:0000	+--SBR-----+ Subroutine				B3/46 --( )--	
	B3/46 - -( ) - File #11 Y41-Y44 - 0					
	INITIATE TRANSFER 1 241-SY-A TO 241-A-B Y70	MASTER RESET	TRANSFER 1 & 3 VALVE FAILURE Y71	200-E MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1	INTERNAL FIT SCREEN BIT	
					Y-41.1	
11:0001	B3/68	N19:3/15	B3/97	N19:4/11	B3/107 --( )--	
	TRANSFER 1 INITIATED					
	Y-41.1 TR ON 1001 N14:3/0					
	+-----+-----+-----+-----+-----+-----+					
	B3/107 - -( ) - File #11 Y41-Y44 - 1 - - File #11 Y41-Y44 - 2					
	INTERNAL FIT SCREEN BIT	VALVE LEAK TRANSFER SCHEMES 1 & 3	TRANSFER LINE LEAK DETECTED Y72 LDA-TR-LINE		TRANSFER 1 INITIATED	
	Y-41.1	Y73			Y-41.1	
11:0002	B3/107	B3/81	N14:0/11		N19:3/10 --( )--	
			TRANSFER 1 INITIATED			
			Y-41.1 TR ON 1001 N14:3/0 --( )--			
	+-----+-----+-----+-----+-----+-----+					
	N19:3/10 - -( ) - File #11 Y41-Y44 - 2 N14:3/0 - - File #6 Y71 - 2 - - File #6 Y71 - 2 - - File #6 Y71 - 3 - - File #6 Y71 - 6,7,13,15,15 - - File #6 Y71 - 16,16 - - File #6 Y71 - 20,26,47 - - File #6 Y71 - 55 - - File #11 Y41-Y44 - 1 - ( ) - File #11 Y41-Y44 - 2					

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 241-SY-A TO 241-A-B TRANSFER SCHEME # 1, Y-41.1
 Lockheed Martin Hanford Co.
 Page:00090

HNF-2346, Rev. 1

File #11 Y41-Y44 Proj:PLC3

07:29:11 02/19/99

	SOV-3165A VALVE FAILURE Y70		TRANSFER 1 & 3 VALVE FAILURE Y71
11:0003	B3/80		B3/97
	SOV-3166A VALVE FAILURE Y71		
	B3/88		
	SOV-3184 VALVE FAILURE Y-71.1		
	N19:2/10		
	SOV-3182A VALVE FAILURE Y-71.1		
	N19:2/8		
	SOV-3182B VALVE FAILURE Y-71.1		
	N19:2/9		
	MOV-843 VALVE FAILURE Y71		
	N19:4/7		
	MOV-846 VALVE FAILURE Y71		
	N19:4/10		
B3/97	- / - File #11 Y41-Y44 - 1 - () - File #11 Y41-Y44 - 3 - / - File #11 Y41-Y44 - 9		

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 241-SY-B TO 241-A-A TRANSFER SCHEME # 2A, Y-42.1
 Lockheed Martin Hanford Co.
 Page:00091

HNF-2346, Rev. 1

File #11 Y41-Y44 Proj:PLC3

07:29:11 02/19/99

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 241-SY-B TO 241-A-A TRANSFER SCHEME # 2A, Y-42.1
 Lockheed Martin Hanford Co.
 Page:00092

File #11 Y41-Y44 Proj:PLC3

07:29:11 02/19/99

	S0V-3165B VALVE FAILURE Y71		TRANSFER 2A & 2B VALVE FAILURE Y71
11:0006	B3/84		B3/98
	S0V-3166B VALVE FAILURE Y71		( )
	B3/92		
	S0V-3183B VALVE FAILURE Y-71.1		
	N19:2/12		
	S0V-3183A VALVE FAILURE Y-71.1		
	N19:2/13		
	MOV-844 VALVE FAILURE Y71		
	N19:4/8		
	MOV-845 VALVE FAILURE Y71		
	N19:4/9		
B3/98	- - - - File #11 Y41-Y44 - 4 - ( ) - File #11 Y41-Y44 - 6 - - File #11 Y41-Y44 - 7,7		

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 241-SY-B TO 241-A-A TRANSFER SCHEME # 2B, Y-43.1
 Lockheed Martin Hanford Co.
 Page:00093

File #11 Y41-Y44 Proj:PLC3

07:29:11 02/19/99

Hanford Cross Site Transfer System (PCU-3)
 241-A-B TO 241-SY-A TRANSFER SCHEME # 3, Y-44.1
 Lockheed Martin Hanford Co.
 Page:00094

File #11 Y41-Y44 Proj:PLC3

07:29:11 02/19/99

	INITIATE TRANSFER 3 241-A-B TO 241-SY-A Y70	MASTER RESET	TRANSFER 1 & 3 VALVE FAILURE Y71	200-W MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1	INTERNAL FIT SCREEN BIT
	B3/74	N19:3/15	B3/97	N19:1/15	B3/108
11:0009	+	+	+	+	+
	TRANSFER 3 INITIATED				
	Y-44.1 TR ON 1003 N14:3/3				
	+	+	+	+	+
	B3/108	- ( ) - File #11 Y41-Y44 - 9			
		- ( ) - File #11 Y41-Y44 - 10			
	INTERNAL FIT SCREEN BIT	VALVE LEAK TRANSFER SCHEMES 1 & 3	TRANSFER LINE LEAK DETECTED Y72		TRANSFER 3 INITIATED
	Y-41.1	Y73	LDA-TR-LINE N14:0/11		Y-44.1
	B3/108	B3/81		N19:3/13	
11:0010	+	+	+	+	+
					TRANSFER 3 INITIATED
					Y-44.1 TR ON 1003 N14:3/3
					+
	N19:3/13	- ( ) - File #11 Y41-Y44 - 10			
	N14:3/3	- ( ) - File #6 Y71 - 2			
		- ( ) - File #6 Y71 - 3			
		- ( ) - File #6 Y71 - 6,7,13,15,15			
		- ( ) - File #6 Y71 - 16,16			
		- ( ) - File #6 Y71 - 20,26,47			
		- ( ) - File #6 Y71 - 55			
		- ( ) - File #11 Y41-Y44 - 9			
		- ( ) - File #11 Y41-Y44 - 10			
					TRANSFER 1-2A-2B-3 SUBROUTINE
					+--RET-----+
11:0011					+Return ( ) +
					+
11:0012					[End]-

	LEAK DETECTION CONTROL SUBROUTINE		PROGRAM FILE #12 START OF SUBROUTINE COMMENT COIL
12:0000	+--SBR-----+ Subroutine +-----+		B3/47 ( )
	B3/47 - - ( ) - File #12 Y72-Y73 - 0		
	LEAK DETECTION SEQUENCING RESET Y-72.1 HS-1010B N14:121/2		LEAK DETECTION RESET CONTROL Y-72.1 B3/96 ( )
12:0001	----- -----		LEAK DETECTION SEQUENCING RESET Y-72.1 HS-1010B N14:121/2 (U)
	B3/96 - - ( ) - File #12 Y72-Y73 - 1 N14:121/2 - - (U) - File #12 Y72-Y73 - 1 - - ( ) - File #12 Y72-Y73 - 1		
	LEAK DETECTED AT DIVERSION BOX 6241-A SUMP Y-72.1	LEAK DETECTION RESET CONTROL Y-72.1	LEAK DETECTED AT DIVER. BOX 6241-A SUMP BIT Y-72.1
12:0002	N19:2/6 ----- -----	B3/96 ----- -----	B3/86 ( )
	LEAK DETECTED AT DIVER. BOX 6241-A SUMP BIT Y-72.1 B3/86 ----- -----		
	B3/86 - - ( ) - File #12 Y72-Y73 - 2 - - ( ) - File #12 Y72-Y73 - 2,9		
	LEAK DETECTED IN LINE TO DIVERSION BOX 6241-A Y-72.1	LEAK DETECTION RESET CONTROL Y-72.1	LEAK DETECTED IN LINE TO DIVERS. BOX 6241-A BIT Y-72.1
12:0003	N19:2/7 ----- -----	B3/96 ----- -----	B3/90 ( )
	LEAK DETECTED IN LINE TO DIVERS. BOX 6241-A BIT Y-72.1 B3/90 ----- -----		
	B3/90 - - ( ) - File #12 Y72-Y73 - 3 - - ( ) - File #12 Y72-Y73 - 3,9		

12:0004	6241-V SUMP LEAK DETECTOR [OFF=FAILURE] Y72 LDXS-3151 I:004/04 1771-IBD SUMP LEAK DETECTION [OFF=ALARM] Y72 LDSH-3151 I:004/15 1771-IBD	N14:0/12 - - ( ) - - File #12 Y72-Y73 - 4 - - - File #12 Y72-Y73 - 5	LEAK DETECTED AT VENT STATION 6241-V SUMP Y-72.1 LDA-3151 N14:0/12 ( )
12:0005	LEAK DETECTED AT VENT STATION 6241-V SUMP Y-72.1 B3/94	LEAK DETECTION RESET CONTROL Y-72.1 B3/96	LEAK DETECTED AT VENT STATION 6241-V SUMP Y-72.1 B3/94 ( )
12:0006	6241-V ENCASMENT LEAK DETECTION [OFF = ALARM] Y72 LDK-3161 I:004/05 1771-IBD LEAK DETECTED IN LINE TO VENT STATION 6241-V BIT Y-72.1 B3/95	LEAK DETECTION RESET CONTROL Y-72.1 B3/96	LEAK DETECTED IN LINE TO VENT STATION 6241-V BIT Y-72.1 B3/95 ( )
		B3/95 - - ( ) - - File #12 Y72-Y73 - 6 - - - File #12 Y72-Y73 - 6,9	

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 Ladder Report
 Lockheed Martin Hanford Co.
 Page:00097

HNF-2346, Rev. 1

File #12 Y72-Y73 Proj:PLC3

07:29:12 02/19/99

	LEAK DETECTED IN LINE TO 244-A LIFT STATION Y72-1	LEAK DETECTION RESET CONTROL Y-72.1	LEAK DETECTED IN LINE TO 244-A LIFT STATION BIT Y-72.1
	N19:5/15	B3/96	B3/109
12:0007	+	+	+
	LEAK DETECTED IN LINE TO 244-A LIFT STATION BIT Y-72.1		
	B3/109		
	+	+	+
	B3/109	- - ( ) - - File #12 Y72-Y73 - 7 - - - File #12 Y72-Y73 - 7,9	
	LEAK DETECTED AT 244-A LIFT STATION SUMP Y-72.1	LEAK DETECTION RESET CONTROL Y-72.1	LEAK DETECTED AT 244-A LIFT STATION BIT Y-72.1
	N19:4/13	B3/96	B3/110
12:0008	+	+	+
	LEAK DETECTED AT 244-A LIFT STATION BIT Y-72.1		
	B3/110		
	+	+	+
	B3/110	- - ( ) - - File #12 Y72-Y73 - 8 - - - File #12 Y72-Y73 - 8,9	

APPENDIX C

Hanford Cross Site Transfer System (PCU-3)
 Ladder Report
 Lockheed Martin Hanford Co.
 Page:00098

HNF-2346, Rev. 1

File #12 Y72-Y73 Proj:PLC3

07:29:12 02/19/99

12:0009	LEAK DETECTED AT DIVER. BOX 6241-A SUMP BIT Y-72.1	TRANSFER LINE LEAK DETECTED Y72 LDA-TR-LINE N14:0/11
	B3/86	N14:0/11
	LEAK DETECTED IN LINE TO DIVERS. BOX 6241-A BIT Y-72.1	INPUT SIGNAL TO 200-W MASTER SHUTDOWN CIRCUIT Y-72.1
	B3/90	N19:3/0
	LEAK DETECTED AT VENT STATION 6241-V SUMP Y-72.1	
	B3/94	
	LEAK DETECTED IN LINE TO VENT STATION 6241-V BIT Y-72.1	
	B3/95	
	LEAK DETECTED IN LINE TO 244-A LIFT STATION BIT Y-72.1	
	B3/109	
	LEAK DETECTED AT 244-A LIFT STATION BIT Y-72.1	
	B3/110	
N14:0/11	- - / - - File #11 Y41-Y44 - 2 - - - - File #11 Y41-Y44 - 4, 7, 7 - - / - - File #11 Y41-Y44 - 10	
N19:3/0	- - { } - - File #12 Y72-Y73 - 9	

	VALVE SOV-3167A/B PRESSURE PT-3167 +--GRT-- Greater Than (A>B) Source A: N20:10 1 Source B: N7:2 10 +-----+ B3/111 - - ( ) - - File #12 Y72-Y73 - 10 - - - File #12 Y72-Y73 - 11	VALVE SOV-3167A/B PRESSURE DETECTED - POSSIBLE LEAK B3/111
12:0010	VALVE SOV-3167A/B PRESSURE DETECTED - POSSIBLE LEAK Y88-1 ZSL-3167A 1:003/11 B3/111 - - ( ) - - File #12 Y72-Y73 - 10 - - - File #12 Y72-Y73 - 11	VALVE SOV-3167A/B FAILURE Y73 PAH-3167 N14:0/13
12:0011	SOV-3167B IS CLOSED 1771-IBD SOV-3167B IS CLOSED Y-88.2 ZSL-3167B 1:004/13 +-----+ 1771-IBD	
	N14:0/13 - - ( ) - - File #12 Y72-Y73 - 11 - - - File #12 Y72-Y73 - 16	
	VALVE SOV-3168A/B PRESSURE PT-3168 +--GRT-- Greater Than (A>B) Source A: N20:11 2 Source B: N7:3 10 +-----+ B3/85 - - ( ) - - File #11 Y41-Y44 - 4,7,7 - - - File #12 Y72-Y73 - 12 - - - File #12 Y72-Y73 - 13	VALVE SOV-3168A/B PRESSURE DETECTED - POSSIBLE LEAK B3/85
12:0012	VALVE SOV-3168A/B PRESSURE DETECTED - POSSIBLE LEAK Y81-3 ZSL-3168A 1:003/13 B3/85 - - ( ) - - File #11 Y41-Y44 - 4,7,7 - - - File #12 Y72-Y73 - 12 - - - File #12 Y72-Y73 - 13	VALVE SOV-3168A/B FAILURE Y73 PAH-3168 N14:0/14
12:0013	SOV-3168B IS CLOSED 1771-IBD SOV-3168B IS CLOSED Y-81-4 ZSL-3168B 1:003/15 +-----+ 1771-IBD	
	N14:0/14 - - ( ) - - File #12 Y72-Y73 - 13	

Hanford Cross Site Transfer System (PCU-3)

VALVE LEAK LOGIC Y-73.1
Lockheed Martin Hanford Co.

File #12 Y72-Y73 Proj:PLC3

Page:00100

07:29:12 02/19/99

	VALVE SOV-3185A/B PRESSURE PT-3185	VALVE SOV-3185A/B PRESSURE DETECTED - POSSIBLE LEAK
12:0014	+---GRT---+ Greater Than (A>B) Source A: N20:12 -2 Source B: N7:4 10 +-----+	B3/112 -( )
	B3/112 - ( ) - - File #12 Y72-Y73 - 14 - - - File #12 Y72-Y73 - 15	
	VALVE SOV-3185A SOV-3185A/B IS CLOSED PRESSURE DETECTED - POSSIBLE LEAK Y81-1 ZSL-3185A I:003/17	VALVE SOV-3185A/B FAILURE Y73 PAH-3185 N14:0/15
12:0015	B3/112 - - - +-----+ 1771-IBD SOV-3185B IS CLOSED Y81-2 ZSL-3185B I:004/01 +-----+ 1771-IBD	-( )
	N14:0/15 - ( ) - - File #12 Y72-Y73 - 15 - - - File #12 Y72-Y73 - 16	
	VALVE SOV-3167A/B FAILURE Y73 PAH-3167 N14:0/13	VALVE LEAK TRANSFER SCHEMES 1 & 3 Y73
12:0016	+-----+ SOV-3173A/B VALVE FAILURE Y-73.1 N19:2/11 +-----+ VALVE SOV-3185A/B FAILURE Y73 PAH-3185 N14:0/15 +-----+	B3/81 -( )
	B3/81 - / - - File #11 Y41-Y44 - 2,10 - ( ) - - File #12 Y72-Y73 - 16	
12:0017		LEAK DETECTION CONTROL SUBROUTINE +---RET---+ Return ( )

Hanford Cross Site Transfer System (PCU-3)
VALVE LEAK LOGIC Y-73.1
Lockheed Martin Hanford Co.
Page:00101

File #12 Y72-Y73 Proj:PLC3

07:29:13 02/19/99

12:0018

[End]

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00102

DB Form Report Sorted By: Address

07:29:13 02/19/99

0:006		OUTPUT BIT	REGISTER			
0:006/000	SOV-3165A-0	OPEN VALVE	SOV-3165A			Y71
0:006/001	SOV-3165A-C	CLOSE VALVE	SOV-3165A			Y71
0:006/002	SOV-3165B-0	OPEN VALVE	SOV-3165B			Y71
0:006/003	SOV-3165B-C	CLOSE VALVE	SOV-3165B			Y71
0:006/004	SOV-3166A-0	OPEN VALVE	SOV-3166A			Y71
0:006/005	SOV-3166A-C	CLOSE VALVE	SOV-3166A			Y71
0:006/006	SOV-3166B-0	OPEN VALVE	SOV-3166B			Y71
0:006/007	SOV-3166B-C	CLOSE VALVE	SOV-3166B			Y71
0:006/010	SOV-3167A-0	OPEN VALVE	SOV-3167A			Y88-1
0:006/011	SOV-3167A-C	CLOSE VALVE	SOV-3167A			Y88-1
0:006/012	SOV-3168A-0	OPEN VALVE	SOV-3168A			Y81-3
0:006/013	SOV-3168A-C	CLOSE VALVE	SOV-3168A			Y81-3
0:006/014	SOV-3168B-0	OPEN VALVE	SOV-3168B			Y81-4
0:006/015	SOV-3168B-C	CLOSE VALVE	SOV-3168B			Y81-4
0:006/016	SOV-3185A-0	OPEN VALVE	SOV-3185A			Y81-1
0:006/017	SOV-3185A-C	CLOSE VALVE	SOV-3185A			Y81-1
0:007/000	SOV-3185B-0	OPEN VALVE	SOV-3185B			Y81-2
0:007/001	SOV-3185B-C	CLOSE VALVE	SOV-3185B			Y81-2
0:007/002	P-3116	SHUTDOWN	SUMP PUMP	P-3116		Y-82.1
0:007/003	SOV-3167B-0	OPEN VALVE	SOV-3167B			Y88-1
0:007/004	SOV-3167B-C	CLOSE VALVE	SOV-3167B			Y88-1
0:007/005		SPARE	DIGITAL	OUTPUT		
0:007/006		SPARE	DIGITAL	OUTPUT		
0:007/007		SPARE	DIGITAL	OUTPUT		
0:007/010		SPARE	DIGITAL	OUTPUT		
0:007/011		SPARE	DIGITAL	OUTPUT		
0:007/012		SPARE	DIGITAL	OUTPUT		
0:007/013		SPARE	DIGITAL	OUTPUT		
0:007/014		SPARE	DIGITAL	OUTPUT		
0:007/015		SPARE	DIGITAL	OUTPUT		
0:007/016		SPARE	DIGITAL	OUTPUT		
0:007/017		SPARE	DIGITAL	OUTPUT		
1:003		INPUT BIT	REGISTER			
1:003/000	ZSH-3165A	SOV-3165A	IS OPEN			Y70
1:003/001	ZSL-3165A	SOV-3165A	IS CLOSED			Y70
1:003/002	ZSH-3165B	SOV-3165B	IS OPEN			Y70
1:003/003	ZSL-3165B	SOV-3165B	IS CLOSED			Y70
1:003/004	ZSH-3166A	SOV-3166A	IS OPEN			Y70
1:003/005	ZSL-3166A	SOV-3166A	IS CLOSED			Y70
1:003/006	ZSH-3166B	SOV-3166B	IS OPEN			Y70
1:003/007	ZSL-3166B	SOV-3166B	IS CLOSED			Y70
1:003/010	ZSH-3167A	SOV-3167A	IS OPEN			Y88-1
1:003/011	ZSL-3167A	SOV-3167A	IS CLOSED			Y88-1
1:003/012	ZSH-3168A	SOV-3168A	IS OPEN			Y81-3
1:003/013	ZSL-3168A	SOV-3168A	IS CLOSED			Y81-3
1:003/014	ZSH-3168B	SOV-3168B	IS OPEN			Y-81-4
1:003/015	ZSL-3168B	SOV-3168B	IS CLOSED			Y-81-4
1:003/016	ZSH-3185A	SOV-3185A	IS OPEN			Y81-1
1:003/017	ZSL-3185A	SOV-3185A	IS CLOSED			Y81-1
1:004/000	ZSH-3185B	SOV-3185B	IS OPEN			Y81-2
1:004/001	ZSL-3185B	SOV-3185B	IS CLOSED			Y81-2
1:004/002		SPARE	DIGITAL	INPUT		
1:004/003		SPARE	DIGITAL	INPUT		
1:004/004	LDXS-3151	6241-V	SUMP LEAK	DETECTOR	OFF=FAILURE	Y72
1:004/005	LDK-3161	6241-V	ENCASEMENT	LEAK DETECTION	OFF = ALARM	Y72
1:004/006	YAS-3102A	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:004/007	YAS-3102B	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:004/010	YAS-3102C	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:004/011	YAS-3102D	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	01T
1:004/012	ZSH-3167B	SOV-3167B	IS OPEN			Y-88.2
1:004/013	ZSL-3167B	SOV-3167B	IS CLOSED			Y-88.2
1:004/014	PSL-3100B	LOW	COMPRESSOR	SA-CMP-3101B	PRESSURE	
1:004/015	LDSh-3151	SUMP LEAK	DETECTION	[OFF=ALARM]		Y72
1:004/016		SPARE	DIGITAL	INPUT		
1:004/017		SPARE	DIGITAL	INPUT		
S:000/000		Processor	arithmetic	carry	flag	
S:000/001		Processor	arithmetic	underflow/	overflow	flag
S:000/002		Processor	arithmetic	zero	flag	
S:000/003		Processor	arithmetic	sign	flag	
S:001/000		Bad RAM	CHECKSUM	at power	up	
S:001/001		PLC-5 in	RUN mode			
S:001/002		PLC-5 in	TEST mode			
S:001/003		PLC-5 in	PROG mode			
S:001/004		PLC-5 is	burning an	EEPROM		
S:001/005		Download-	ing in	progress		
S:001/006		Test edits	enabled			

Hanford Cross Site Transfer System (PCU-3)
 WLS Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00103

DB Form Report Sorted By: Address

07:29:27 02/19/99

S:001/007	Mode	switch	in REMOTE		
S:001/008	Forces	enabled			
S:001/009	Forces	present			
S:001/010	EEPROM	success-	fully	Burned	
S:001/011	Perform-	ing online	program-	ming	
S:001/012	Processor	is in	DEBUG mode		
S:001/013	User	program	CHECKSUM	done	
S:001/014	Last scan	of ladder	or SFC	step	
S:001/015	First scan	of ladder	or SFC	step	
S:007	Logical Rack	Status Bits	For Racks 0-7		
S:007/000	Rack 0	Faulted			
S:007/001	Rack 1	Faulted			
S:007/002	Rack 2	Faulted			
S:007/003	Rack 3	Faulted			
S:007/004	Rack 4	Faulted			
S:007/005	Rack 5	Faulted			
S:007/006	Rack 6	Faulted			
S:007/007	Rack 7	Faulted			
S:007/008	Block Xfer	queue to	rack 0 is	full	
S:007/009	Block Xfer	queue to	rack 1 is	full	
S:007/010	Block Xfer	queue to	rack 2 is	full	
S:007/011	Block Xfer	queue to	rack 3 is	full	
S:007/012	Block Xfer	queue to	rack 4 is	full	
S:007/013	Block Xfer	queue to	rack 5 is	full	
S:007/014	Block Xfer	queue to	rack 6 is	full	
S:007/015	Block Xfer	queue to	rack 7 is	full	
S:008	Last	program	scan time	ladder &	SFC
S:009	Maximum	program	scan time	ladder &	SFC
S:010/000	Battery	is bad or	missing		
S:010/001	DH+ active	node table	changed		
S:010/002	STI	overlap			
S:010/003	EEPROM	trans-	ferred		
S:010/004	Edits	prevent	SFC	continuing	
S:010/005	Invalid	I/O status	file		
S:010/006	Memory	cartridge	baENery	low	
S:010/007	No more	command	blocks	exist	
S:010/009	No MCP was	configured	to run		
S:010/010	MCP not	allowed			
S:010/011	Pll word	number	isn't in	local rack	
S:010/012	User Pll	routine	overlap		
S:010/013	No command	block	exists to	get Pll	
S:010/014	Arithmetic	overflow	occurred		
S:010/015	SFC	lingering	action	overlap	
S:011/000	Bad	program	file		
S:011/001	Bad	address	in ladder	program	
S:011/002	Programmer	error			
S:011/003	SFC Fault				
S:011/004	Program	assembly	error		
S:011/005	Powerup	protection	fault		
S:011/006	Error not	defined			
S:011/007	User	generated	fault		
S:011/008	Watchdog	timer	fault		
S:011/009	Bad system	config-	uration		
S:011/010	Hardware	Error			
S:011/011	MCP file	does not	exist or	is not	ladder
S:011/012	Pll file	does not	exist or	is not	ladder
S:011/013	STI file	does not	exist or	is not	ladder
S:011/014	Fault file	does not	exist or	is not	ladder
S:011/015	Non ladder	file			
S:012	Fault Code				
S:013	Program	file where	fault	occurred	
S:014	Rung	number	where	fault	occurred
S:016	I/O status	file			
S:017/000	Queue full	between	Local and	remote I/O	
S:017/001	Queue full	servicing	channel 1A		
S:017/002	Queue full	servicing	channel 1B		
S:017/003	Queue full	servicing	channel 2A		
S:017/004	Queue full	servicing	channel 2B		
S:017/005	No modem	on serial	port		
S:017/006	Remote I/O	is greater	than image	size	
S:017/008	ASCII	instruct-	ion error		
S:017/009	Duplicate	node	address		
S:018	Real time	clock YEAR			
S:019	Real time	clock	MONTH		
S:020	Real time	clock DAY			
S:021	Real time	clock HOUR			
S:022	Real time	clock	MINUTE		

Hanford Cross Site Transfer System (PCU-3)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00104

DB Form Report

Sorted By: Address

07:29:28 02/19/99

S:022/000	REAL TIME	CLOCK	MINUTE	ONE'S BIT	
S:023	Real time	clock	SECOND		
S:023/000	REAL TIME	CLOCK	SECOND	ONE'S BIT	
S:023/001	REAL TIME	CLOCK	SECOND	TWO'S BIT	
S:024	Indexed	Addressing	Offset		
S:025	Adapter	Image	File		
S:026/000	SFC	Restart/	Continue		
S:026/001	Start-up	protect-	ion after	power loss	
S:026/002	Local rack	is 1 if	set or 0	if bit = 0	
S:026/003	Complementary	Rack	Mode		
S:027/000	Rack 0	Inhibit			
S:027/001	Rack 1	Inhibit			
S:027/002	Rack 2	Inhibit			
S:027/003	Rack 3	Inhibit			
S:027/004	Rack 4	Inhibit			
S:027/005	Rack 5	Inhibit			
S:027/006	Rack 6	Inhibit			
S:027/007	Rack 7	Inhibit			
S:027/008	Rack 0	Reset			
S:027/009	Rack 1	Reset			
S:027/010	Rack 2	Reset			
S:027/011	Rack 3	Reset			
S:027/012	Rack 4	Reset			
S:027/013	Rack 5	Reset			
S:027/014	Rack 6	Reset			
S:027/015	Rack 7	Reset			
S:028	Watchdog	Timer	Setpoint		
S:029	Fault	routine	file	number	
S:030	STI	setpoint	(interval)		
S:031	STI	file	number		
S:032	Logical Rack	Status Bits	For Racks 10-17		
S:032/000	Rack 10	Faulted			
S:032/001	Rack 11	Faulted			
S:032/002	Rack 12	Faulted			
S:032/003	Rack 13	Faulted			
S:032/004	Rack 14	Faulted			
S:032/005	Rack 15	Faulted			
S:032/006	Rack 16	Faulted			
S:032/007	Rack 17	Faulted			
S:032/008	Block Xfer	queue to	rack 10 is	full	
S:032/009	Block Xfer	queue to	rack 11 is	full	
S:032/010	Block Xfer	queue to	rack 12 is	full	
S:032/011	Block Xfer	queue to	rack 13 is	full	
S:032/012	Block Xfer	queue to	rack 14 is	full	
S:032/013	Block Xfer	queue to	rack 15 is	full	
S:032/014	Block Xfer	queue to	rack 16 is	full	
S:032/015	Block Xfer	queue to	rack 17 is	full	
S:033/000	Rack 10	Inhibit			
S:033/001	Rack 11	Inhibit			
S:033/002	Rack 12	Inhibit			
S:033/003	Rack 13	Inhibit			
S:033/004	Rack 14	Inhibit			
S:033/005	Rack 15	Inhibit			
S:033/006	Rack 16	Inhibit			
S:033/007	Rack 17	Inhibit			
S:033/008	Rack 10	Reset			
S:033/009	Rack 11	Reset			
S:033/010	Rack 12	Reset			
S:033/011	Rack 13	Reset			
S:033/012	Rack 14	Reset			
S:033/013	Rack 15	Reset			
S:033/014	Rack 16	Reset			
S:033/015	Rack 17	Reset			
S:034/000	Rack 20	Faulted			
S:034/001	Rack 21	Faulted			
S:034/002	Rack 22	Faulted			
S:034/003	Rack 23	Faulted			
S:034/004	Rack 24	Faulted			
S:034/005	Rack 25	Faulted			
S:034/006	Rack 26	Faulted			
S:034/007	Rack 27	Faulted			
S:034/008	Block Xfer	queue to	rack 20 is	full	
S:034/009	Block Xfer	queue to	rack 21 is	full	
S:034/010	Block Xfer	queue to	rack 22 is	full	
S:034/011	Block Xfer	queue to	rack 23 is	full	
S:034/012	Block Xfer	queue to	rack 24 is	full	
S:034/013	Block Xfer	queue to	rack 25 is	full	

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00105

DB Form Report Sorted By: Address

07:29:28 02/19/99

S:034/014	Block Xfer	queue to	rack 26 is	full	
S:034/015	Block Xfer	queue to	rack 27 is	full	
S:035/000	Rack 20	Inhibit			
S:035/001	Rack 21	Inhibit			
S:035/002	Rack 22	Inhibit			
S:035/003	Rack 23	Inhibit			
S:035/004	Rack 24	Inhibit			
S:035/005	Rack 25	Inhibit			
S:035/006	Rack 26	Inhibit			
S:035/007	Rack 27	Inhibit			
S:035/008	Rack 20	Reset			
S:035/009	Rack 21	Reset			
S:035/010	Rack 22	Reset			
S:035/011	Rack 23	Reset			
S:035/012	Rack 24	Reset			
S:035/013	Rack 25	Reset			
S:035/014	Rack 26	Reset			
S:035/015	Rack 27	Reset			
S:046	P11	file	number	examine	
S:047	P11	module	group to		
S:048	P11 bit	mask			
S:048/000	P11 Module	Bit	1=Monitor	0=Ignore	
S:049	P11	compare	value		
S:049/000	P11 Bit	1=false to	TRUE	0=	true to
S:050	P11 down	count			
S:051	P11 return	mask			
S:052	P11 accum	ulator			
S:053	STI last	scan time			
S:054	STI max	scan time			
S:055	P11 last	scan time			
S:056	P11 max	scan time			
S:079/000	Main	control	program A	disable	bit
S:079/001	Main	control	program B	disable	bit
S:079/002	Main	control	program C	disable	bit
S:079/003	Main	control	program D	disable	bit
S:079/004	Main	control	program E	disable	bit
S:079/005	Main	control	program F	disable	bit
S:079/006	Main	control	program G	disable	bit
S:079/007	Main	control	program H	disable	bit
S:079/008	Main	control	program I	disable	bit
S:079/009	Main	control	program J	disable	bit
S:079/010	Main	control	program K	disable	bit
S:079/011	Main	control	program L	disable	bit
S:079/012	Main	control	program M	disable	bit
S:079/013	Main	control	program N	disable	bit
S:079/014	Main	control	program O	disable	bit
S:079/015	Main	control	program P	disable	bit
S:080	Main	control	program A	file	number
S:081	Program A	scan time			
S:082	Program A	maximum	scan time		
S:083	Main	control	program B	file	number
S:084	Program B	scan time			
S:085	Program B	maximum	scan time		
S:086	Main	control	program C	file	number
S:087	Program C	scan time			
S:088	Program C	maximum	scan time		
S:089	Main	control	program D	file	number
S:090	Program D	scan time			
S:091	Program D	maximum	scan time		
S:092	Main	control	program E	file	number
S:093	Program E	scan time			
S:094	Program E	maximum	scan time		
S:095	Main	control	program F	file	number
S:096	Program F	scan time			
S:097	Program F	maximum	scan time		
S:098	Main	control	program G	file	number
S:099	Program G	scan time			
S:100	Program G	maximum	scan time		
S:101	Main	control	program H	file	number
S:102	Program H	scan time			
S:103	Program H	maximum	scan time		
S:104	Main	control	program I	file	number
S:105	Program I	scan time			
S:106	Program I	maximum	scan time		
S:107	Main	control	program J	file	number
S:108	Program J	scan time			
S:109	Program J	maximum	scan time		

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00106

DB Form Report Sorted By: Address

07:29:28 02/19/99

S:110	_____	Main	control	program K	file	number
S:111	_____	Program K	scan time	_____	_____	_____
S:112	_____	Program K	maximum	scan time	_____	_____
S:113	_____	Main	control	program L	file	number
S:114	_____	Program L	scan time	_____	_____	_____
S:115	_____	Program L	maximum	scan time	_____	_____
S:116	_____	Main	control	program M	file	number
S:117	_____	Program M	scan time	_____	_____	_____
S:118	_____	Program M	maximum	scan time	_____	_____
S:119	_____	Main	control	program N	file	number
S:120	_____	Program N	scan time	_____	_____	_____
S:121	_____	Program N	maximum	scan time	_____	_____
S:122	_____	Main	control	program O	file	number
S:123	_____	Program O	scan time	_____	_____	_____
S:124	_____	Program O	maximum	scan time	_____	_____
S:125	_____	Main	control	program P	file	number
S:126	_____	Program P	scan time	_____	_____	_____
S:127	_____	Program P	maximum	scan time	_____	_____
B003/000	ALWAYS OFF	ALWAYS OFF	OUTPUT	_____	_____	_____
B003/001	ALWAYS ON	ALWAYS ON	OUTPUT	_____	_____	_____
B003/002	1 SEC PULSE	ONE SECOND	SINGLE SCAN	PULSE	_____	_____
B003/003	2 SEC PULSE	TWO SECOND	SINGLE SCAN	PULSE	_____	_____
B003/004	HALF SEC FLASH	HALF SECOND	FLASHER	_____	_____	_____
B003/005	1 SEC FLASH	ONE SECOND	FLASHER	_____	_____	_____
B003/006	2 SEC FLASH	TWO SECOND	FLASHER	_____	_____	_____
B003/007	1 MIN PULSE	ONE MINUTE	SINGLE SCAN	PULSE	_____	_____
B003/008	_____	_____	_____	_____	_____	_____
B003/009	_____	_____	_____	_____	_____	_____
B003/010	_____	_____	_____	_____	_____	_____
B003/011	_____	_____	_____	_____	_____	_____
B003/012	_____	_____	_____	_____	_____	_____
B003/013	_____	_____	_____	_____	_____	_____
B003/014	_____	_____	_____	_____	_____	_____
B003/015	_____	_____	_____	_____	_____	_____
B003/001	_____	TWO SCAN SUB-	DIVISIONS	REGISTER	_____	_____
B003/016	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIRST SET)	_____
B003/017	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SECOND SET)	_____
B003/018	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRD SET)	_____
B003/019	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTH SET)	_____
B003/020	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTH SET)	_____
B003/021	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTH SET)	_____
B003/022	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SEVENTH SET)	_____
B003/023	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(EIGHTH SET)	_____
B003/024	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(NINTH SET)	_____
B003/025	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TENTH SET)	_____
B003/026	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(ELEVENTH SET)	_____
B003/027	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TWELFTH SET)	_____
B003/028	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRTNTH SET)	_____
B003/029	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTNTH SET)	_____
B003/030	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTEENTH SET)	_____
B003/031	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTEENTH SET)	_____
B003/032	_____	ONE SECOND	RISING	ONE SHOT	_____	_____
B003/033	_____	ONE SECOND	FALLING	ONE SHOT	_____	_____
B003/034	_____	TWO SECOND	RISING	ONE SHOT	_____	_____
B003/035	_____	TWO SECOND	FALLING	ONE SHOT	_____	_____
B003/036	_____	PROGRAM FILE	JUMP-TO-SUBR.	CONTROL RUNGS	COMMENT COIL	_____
B003/037	_____	MCP FILE #2	END OF PROGRAM	COMMENT COIL	_____	_____
B003/038	_____	FAULT ROUTINE	FILE #3 END	OF PROGRAM	COMMENT COIL	_____
B003/039	_____	PROGRAM	FILE #4 START	OF SUBROUTINE	COMMENT COIL	_____
B003/040	_____	PROGRAM	FILE #5 START	OF SUBROUTINE	COMMENT COIL	_____
B003/041	_____	PROGRAM	FILE #6 START	OF SUBROUTINE	COMMENT COIL	_____
B003/042	_____	PROGRAM	FILE #7 START	OF SUBROUTINE	COMMENT COIL	_____
B003/043	_____	PROGRAM	FILE #8 START	OF SUBROUTINE	COMMENT COIL	_____
B003/044	_____	_____	_____	_____	_____	_____
B003/045	_____	PROGRAM	FILE #10 START	OF SUBROUTINE	COMMENT COIL	_____
B003/046	_____	PROGRAM	FILE #11 START	OF SUBROUTINE	COMMENT COIL	_____
B003/047	_____	PROGRAM	FILE #12 START	OF SUBROUTINE	COMMENT COIL	_____
B003/048	_____	ANALOG MODULE	INPUT CHANNEL	UNDER OR OVER	RANGE ALARMS	NOT ACTIVE
B003/050	_____	ONE MINUTE	RISING	ONE SHOT	_____	_____
B003/051	_____	ONE MINUTE	FALLING	ONE SHOT	_____	_____
B003/064	_____	INITIATE	TRANSFER	_____	_____	Y70
B003/065	_____	TRANSFER	LOCK OUT BIT	_____	_____	Y-70.1
B003/066	_____	TRANSFER	MASTER	LOCKOUT	_____	Y70
B003/067	_____	TRANSFER 1	LOCKOUT	_____	_____	Y70
B003/068	_____	INITIATE	TRANSFER 1	241-SY-A TO	241-A-B	Y70
B003/069	_____	TRANSFER 2-A	LOCKOUT	_____	_____	Y70
B003/070	_____	INITIATE	TRANSFER 2-A	241-SY-B TO	241-A-A	Y70

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00107

DB Form Report Sorted By: Address

07:29:29 02/19/99

B003/071	TRANSFER 2-B	LOCKOUT			Y70
B003/072	INITIATE	TRANSFER 2-B	241-SY-B TO	241-A-A	Y70
B003/073	TRANSFER 3	LOCKOUT			Y70
B003/074	INITIATE	TRANSFER 3	241-A-B TO	241-SY-A	Y70
B003/075	SUPERNATE LINE	HIGH PRESSURE	INTERLOCK		
B003/076	SUPERNATE LINE	HIGH PRESSURE	INTERLOCK		
B003/077	SLURRY LINE	HIGH PRESSURE	INTERLOCK		
B003/078	SLURRY LINE	HIGH PRESSURE	INTERLOCK		
B003/080	SOV-3165A	VALVE	FAILURE		Y70
B003/081	VALVE LEAK	TRANSFER	SCHEMES 1 & 3		Y73
B003/084	SOV-3165B	VALVE	FAILURE		Y71
B003/085	VALVE	SOV-3168A/B	PRESSURE	DETECTED -	POSSIBLE LEAK
B003/086	LEAK DETECTED	AT DIVER. BOX	6241-A SUMP	BIT	Y-72.1
B003/088	SOV-3166A	VALVE	FAILURE		Y71
B003/089	SCHEME 2B	SHUTDOWN BIT			
B003/090	LEAK DETECTED	IN LINE TO	DIVERS. BOX	6241-A BIT	Y-72.1
B003/092	SOV-3166B	VALVE	FAILURE		Y71
B003/093	SCHEME 2A	SHUTDOWN BIT			
B003/094	LEAK DETECTED	AT VENT STATION	6241-V SUMP		Y-72.1
B003/095	LEAK DETECTED	IN LINE TO	VENT STATION	6241-V BIT	Y-72.1
B003/096	LEAK DETECTION	RESET CONTROL			Y-72.1
B003/097	TRANSFER	1 & 3	VALVE	FAILURE	Y71
B003/098	TRANSFER	2A & 2B	VALVE	FAILURE	Y71
B003/099	PCU-1	COMMUN. LOSS	ONE-SHOT		
B003/100	PCU-1	COMMUN. LOSS	ONE-SHOT		
B003/101	PCU-2	COMMUN. LOSS	ONE-SHOT		
B003/102	PCU-2	COMMUN. LOSS	ONE-SHOT		
B003/103	PCU-4	COMMUN. LOSS	ONE-SHOT		
B003/104	PCU-4	COMMUN. LOSS	ONE-SHOT		
B003/105	PCU-5	COMMUN. LOSS	ONE-SHOT		
B003/106	PCU-5	COMMUN. LOSS	ONE-SHOT		
B003/107	INTERNAL FIT	SCREEN BIT			Y-41.1
B003/108	INTERNAL FIT	SCREEN BIT			Y-41.1
B003/109	LEAK DETECTED	IN LINE TO	244-A LIFT	STATION BIT	Y-72.1
B003/110	LEAK DETECTED	AT 244-A LIFT	STATION BIT		Y-72.1
B003/111	VALVE	SOV-3167A/B	PRESSURE	DETECTED -	POSSIBLE LEAK
B003/112	VALVE	SOV-3185A/B	PRESSURE	DETECTED -	POSSIBLE LEAK
B003/113	CLOSE VALVE	SOV-3167A	INTERNAL		
B003/114	CLOSE VALVE	SOV-3167B	INTERNAL		
B003/200	COMM LOSS	ONE-SHOT			
B003/201	COMM LOSS	ONE-SHOT			
B003/300	OPEN VALVE	SOV-3165A	BIT		
B003/301	CLOSE VALVE	SOV-3165A	BIT		
B003/302	OPEN VALVE	SOV-3166A	BIT		
B003/303	CLOSE VALVE	SOV-3166A	BIT		
B003/304	OPEN VALVE	SOV-3165B	BIT		
B003/305	CLOSE VALVE	SOV-3165B	BIT		
B003/306	OPEN VALVE	SOV-3166B	BIT		
B003/307	CLOSE VALVE	SOV-3166B	BIT		
B003/308	CLOSE VALVE	SOV-3185A	BIT		Y-81.1
B003/309	CLOSE VALVE	SOV-3185B	BIT		Y-81.2
B003/310	CLOSE VALVE	SOV-3168A	BIT		Y-81.3
B003/311	CLOSE VALVE	SOV-3168B	BIT		Y-81.4
T004:000	POWER-UP	SEQUENCING	DELAY		
T004:000.ACC	POWER-UP	SEQUENCING	DELAY		
T004:000.DN					
T004:000.EN					
T004:000.PRE					
T004:000.TT					
T004:001	HALF SECOND	FLASHER TIMER			
T004:001.ACC					
T004:001.DN					
T004:001.EN					
T004:001.PRE					
T004:001.TT					
T004:002	SOV-3185A	VALVE FAILED	TO CLOSE	DELAY	
T004:002.ACC					
T004:002.DN	SOV-3185A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
T004:002.EN	SOV-3185A	VALVE FAILED	TO CLOSE	DELAY	
T004:002.PRE					
T004:002.TT					
T004:003	SOV-3185A	VALVE FAILED	TO OPEN	DELAY	
T004:003.ACC					
T004:003.DN	SOV-3185A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
T004:003.EN	SOV-3185A	VALVE FAILED	TO OPEN	DELAY	
T004:003.PRE					
T004:003.TT					

Hanford Cross Site Transfer System (PCU-3)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00108

DB Form Report

Sorted By: Address

07:29:29 02/19/99

TO04:004	SOV-3185B	VALVE FAILED	TO CLOSE	DELAY	
TO04:004.ACC					
TO04:004.DN	SOV-3185B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:004.EN	SOV-3185B	VALVE FAILED	TO CLOSE	DELAY	
TO04:004.PRE					
TO04:004.TT					
TO04:005	SOV-3185B	VALVE FAILED	TO OPEN	DELAY	
TO04:005.ACC					
TO04:005.DN	SOV-3185B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:005.EN	SOV-3185B	VALVE FAILED	TO OPEN	DELAY	
TO04:005.PRE					
TO04:005.TT					
TO04:006	SOV-3168A	VALVE FAILED	TO CLOSE	DELAY	
TO04:006.ACC					
TO04:006.DN	SOV-3168A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:006.EN	SOV-3168A	VALVE FAILED	TO CLOSE	DELAY	
TO04:006.PRE					
TO04:006.TT					
TO04:007	SOV-3168A	VALVE FAILED	TO OPEN	DELAY	
TO04:007.ACC					
TO04:007.DN	SOV-3168A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:007.EN	SOV-3168A	VALVE FAILED	TO OPEN	DELAY	
TO04:007.PRE					
TO04:007.TT					
TO04:008	SOV-3168B	VALVE FAILED	TO CLOSE	DELAY	
TO04:008.ACC					
TO04:008.DN	SOV-3168B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:008.EN	SOV-3168B	VALVE FAILED	TO CLOSE	DELAY	
TO04:008.PRE					
TO04:008.TT					
TO04:009	SOV-3168B	VALVE FAILED	TO OPEN	DELAY	
TO04:009.ACC					
TO04:009.DN					
TO04:009.EN	SOV-3168B	VALVE FAILED	TO OPEN	DELAY	
TO04:009.PRE					
TO04:009.TT					
TO04:009DN	SOV-3168B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:010	SOV-3185A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:010.ACC					
TO04:010.DN	SOV-3185A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:010.EN	SOV-3185A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:010.PRE					
TO04:010.TT					
TO04:011	SOV-3185B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:011.ACC					
TO04:011.DN	SOV-3185B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:011.EN	SOV-3185B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:011.PRE					
TO04:011.TT					
TO04:012	SOV-3168A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:012.ACC					
TO04:012.DN	SOV-3168A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:012.EN	SOV-3168A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:012.PRE					
TO04:012.TT					
TO04:013	SOV-3168B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:013.ACC					
TO04:013.DN	SOV-3168B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:013.EN	SOV-3168B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:013.PRE					
TO04:013.TT					
TO04:014	SOV-3165A	VALVE FAILED	TO CLOSE	DELAY	
TO04:014.ACC					
TO04:014.DN	SOV-3165A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:014.EN	SOV-3165A	VALVE FAILED	TO CLOSE	DELAY	
TO04:014.PRE					
TO04:014.TT					
TO04:015	SOV-3165A	VALVE FAILED	TO OPEN	DELAY	
TO04:015.ACC					
TO04:015.DN	SOV-3165A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:015.EN	SOV-3165A	VALVE FAILED	TO OPEN	DELAY	
TO04:015.PRE					
TO04:015.TT					
TO04:016	SOV-3165A	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:016.ACC					
TO04:016.DN	SOV-3165A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:016.EN	SOV-3165A	VALVE POSITION	SWITCH FAILURE	DELAY	

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00109

DB Form Report

Sorted By: Address

07:29:30 02/19/99

T004:016. PRE					
T004:016. TT					
T004:017	SOV-3166A	VALVE FAILED	TO CLOSE	DELAY	
T004:017. ACC					
T004:017. DN	SOV-3166A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
T004:017. EN	SOV-3166A	VALVE FAILED	TO CLOSE	DELAY	
T004:017. PRE					
T004:017. TT					
T004:018	SOV-3166A	VALVE FAILED	TO OPEN	DELAY	
T004:018. ACC					
T004:018. DN	SOV-3166A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
T004:018. EN	SOV-3166A	VALVE FAILED	TO OPEN	DELAY	
T004:018. PRE					
T004:018. TT					
T004:019	SOV-3166A	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:019. ACC					
T004:019. DN	SOV-3166A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
T004:019. EN	SOV-3166A	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:019. PRE					
T004:019. TT					
T004:020	SOV-3165B	VALVE FAILED	TO CLOSE	DELAY	
T004:020. ACC					
T004:020. DN	SOV-3165B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
T004:020. EN	SOV-3165B	VALVE FAILED	TO CLOSE	DELAY	
T004:020. PRE					
T004:020. TT					
T004:021	SOV-3165B	VALVE FAILED	TO OPEN	DELAY	
T004:021. ACC					
T004:021. DN					
T004:021. EN	SOV-3165B	VALVE FAILED	TO OPEN	DELAY	
T004:021. PRE					
T004:021. TT					
T004:021					
T004:021. ACC					
T004:021. DN					
T004:021. EN					
T004:021. PRE					
T004:021. TT					
T004:021	SOV-3165B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
T004:021. TT	SOV-3165B	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:022					
T004:022. ACC	SOV-3165B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
T004:022. DN	SOV-3165B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
T004:022. EN	SOV-3165B	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:022. PRE					
T004:022. TT					
T004:023	SOV-3166B	VALVE FAILED	TO CLOSE	DELAY	
T004:023. ACC					
T004:023. DN	SOV-3166B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
T004:023. EN	SOV-3166B	VALVE FAILED	TO CLOSE	DELAY	
T004:023. PRE					
T004:023. TT					
T004:024	SOV-3166B	VALVE FAILED	TO OPEN	DELAY	
T004:024. ACC					
T004:024. DN	SOV-3166B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
T004:024. EN	SOV-3166B	VALVE FAILED	TO OPEN	DELAY	
T004:024. PRE					
T004:024. TT					
T004:024					
T004:024. TT	SOV-3166B	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:025					
T004:025. ACC					
T004:025. DN	SOV-3166B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
T004:025. EN	SOV-3166B	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:025. PRE					
T004:025. TT					
T004:026	SOV-3167A	VALVE FAILED	TO CLOSE	DELAY	Y-88.1
T004:026. ACC					
T004:026. DN	SOV-3167A	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
T004:026. EN					
T004:026. PRE	SOV-3167A	VALVE FAILED	TO CLOSE	DELAY	
T004:026. TT					
T004:027	SOV-3167A	VALVE FAILED	TO OPEN	DELAY	
T004:027. ACC					
T004:027. DN	SOV-3167A	VALVE FAILED	TO OPEN	DELAY COMPLETE	
T004:027. EN	SOV-3167A	VALVE FAILED	TO OPEN	DELAY	
T004:027. PRE					
T004:027. TT					
T004:028	SOV-3167A	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:028. ACC					
T004:028. DN	SOV-3167A	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
T004:028. EN	SOV-3167A	VALVE POSITION	SWITCH FAILURE	DELAY	
T004:028. PRE					
T004:028. TT					
T004:029	SOV-3167B	VALVE FAILED	TO CLOSE	DELAY	
T004:029. ACC					

Hanford Cross Site Transfer System (PCU-3)
 WL5 Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00110

DB Form Report

Sorted By: Address

07:29:30 02/19/99

TO04:029.DN	SOV-3167B	VALVE FAILED	TO CLOSE	DELAY COMPLETE	
TO04:029.EN	SOV-3167B	VALVE FAILED	TO CLOSE	DELAY	
TO04:029.PRE					
TO04:029.TT					
TO04:030	SOV-3167B	VALVE FAILED	TO OPEN	DELAY	
TO04:030.ACC					
TO04:030.DN	SOV-3167B	VALVE FAILED	TO OPEN	DELAY COMPLETE	
TO04:030.EN	SOV-3167B	VALVE FAILED	TO OPEN	DELAY	
TO04:030.PRE					
TO04:030.TT					
TO04:031	SOV-3167B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:031.ACC					
TO04:031.DN	SOV-3167B	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	
TO04:031.EN	SOV-3167B	VALVE POSITION	SWITCH FAILURE	DELAY	
TO04:031.PRE					
TO04:031.TT					
TO04:032	COMMON. LOSS	TIMER WITH	PCU-1		
TO04:032.ACC					
TO04:032.DN	COMMON. LOSS	TIMER WITH	PCU-1	COMPLETE	
TO04:032.EN					
TO04:032.PRE					
TO04:032.TT					
TO04:033	COMMON. LOSS	TIMER WITH	PCU-2		
TO04:033.ACC					
TO04:033.DN	COMMON. LOSS	TIMER WITH	PCU-2	COMPLETE	
TO04:033.EN					
TO04:033.PRE					
TO04:033.TT					
TO04:034	COMMON. LOSS	TIMER WITH	PCU-4		
TO04:034.ACC					
TO04:034.DN	COMMON. LOSS	TIMER WITH	PCU-4	COMPLETE	
TO04:034.EN					
TO04:034.PRE					
TO04:034.TT					
TO04:035	COMMON. LOSS	TIMER WITH	PCU-5		
TO04:035.ACC					
TO04:035.DN	COMMON. LOSS	TIMER WITH	PCU-5	COMPLETE	
TO04:035.EN					
TO04:035.PRE					
TO04:035.TT					
TO04:040	COMM LOSS	TIMER	WITH OCS		
RO06:000	TWO SCAN SUB-	DIVISIONS	CONTROL	REGISTER	
RO06:000.EN	TWO SCAN SUB-	DIVISIONS	CONTROL	ENABLED	
RO06:000.UL	TWO SCAN SUB-	DIVISIONS	CONTROL	UNLOAD	
RO06:010	COMPARE	PCU-3 TO PCU-1	MSG FILE	WITH PREVIOUS	
RO06:011	COMPARE	PCU-3 TO PCU-2	MSG FILE	WITH PREVIOUS	
RO06:012	COMPARE	PCU-3 TO PCU-4	MSG FILE	WITH PREVIOUS	
RO06:013	COMPARE	PCU-3 TO PCU-5	MSG FILE	WITH PREVIOUS	
NO07:000					
NO07:001					
NO07:002					
NO07:003					
NO07:004					
NO07:005					
NO07:006					
NO07:007					
NO07:008					
NO07:009					
NO10:000	REGISTER FOR	VERIFYING	FAULTY ROUTINE	FILE OPERATION	
NO10:007	Logical Rack	Fault Status	For Racks 0-7	And Racks 10-17	
NO10:008	Last	program	scan time	ladder &	SFC
NO10:009	Maximum	program	scan time	ladder &	SFC
NO10:010/000	baENery	is bad or	missing		
NO10:010/001	DI+ active	node table	changed		
NO10:010/002	STI	overlap			
NO10:010/003	EEPROM	trans-	ferred		
NO10:010/004	Edits	prevent	SFC	continuing	
NO10:010/005	Invalid	I/O status	file		
NO10:010/006	Memory	cartridge	baENery	low	
NO10:010/007	No more	command	blocks	exist	
NO10:010/009	No MCP was	configured	to run		
NO10:010/010	MCP not	allowed			
NO10:010/011	PIL word	number	isn't in	local rack	
NO10:010/012	User PIL	routine	overlap		
NO10:010/013	No command	block	exists to	get PIL	
NO10:010/014	Arithmetic	overflow	occurred		
NO10:010/015	SFC	lingering	action	overlap	

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00111

DB Form Report

Sorted By: Address

07:29:31 02/19/99

N010:011/000	Bad	program	file		
N010:011/001	Bad	address	in ladder	program	
N010:011/002	Programmer	error			
N010:011/003	SFC Fault				
N010:011/004	Program	assembly	error		
N010:011/005	Powerup	protection	fault		
N010:011/006	Error not	defined			
N010:011/007	User	generated	fault		
N010:011/008	Watchdog	timer	fault		
N010:011/009	Bad system	config-	uration		
N010:011/010	Hardware	Error			
N010:011/011	HCP file	does not	exist or	is not	ladder
N010:011/012	PII file	does not	exist or	is not	ladder
N010:011/013	STI file	does not	exist or	is not	ladder
N010:011/014	Fault file	does not	exist or	is not	ladder
N010:011/015	Non ladder	file			
N010:012	Fault Code				
N010:013	Program	file where	fault	occurred	
N010:014	Rung	number	where	fault	occurred
N010:016	I/O status	file			
N010:017	REGISTER FOR	VERIFYING	FAULT ROUTINE	FILE OPERATION	
N010:017/000	Queue full	between	local and	remote I/O	
N010:017/001	Queue full	servicing	channel 1A		
N010:017/002	Queue full	servicing	channel 1B		
N010:017/003	Queue full	servicing	channel 2A		
N010:017/004	Queue full	servicing	channel 2B		
N010:017/005	No modem	on serial	port		
N010:017/006	Remote I/O	is greater	than image	size	
N010:017/008	ASCII	instruct-	ion error		
N010:017/009	Duplicate	node	address		
N010:018	Real time	clock YEAR			
N010:019	Real time	clock	MONTH		
N010:020	Real time	clock DAY			
N010:021	Real time	clock HOUR			
N010:022	Real time	clock	MINUTE		
N010:023	Real time	clock	SECOND		
MG011:000	SEND MSG	FROM PCU-3	TO PCU-1		
MG011:001	SEND MSG	FROM PCU-3	TO PCU-2		
MG011:002	SEND MSG	FROM PCU-3	TO PCU-4		
MG011:003	SEND MSG	FROM PCU-3	TO PCU-5		
BT012:000					
BT012:001					
BT012:002					
BT012:003					
N013:001/015	THERM. MODULE	POWERED UP BUT	NOT CONFIGURED		
N013:004/000	THERM. MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:004/001	THERM. MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:005	YE-3126AR	LINE	WT-SNL-3150	TEMPERATURE	
N013:006					
N013:006/000	THERM. MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:006/001					
N013:007	THERM. MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:008/000	SPARE	THERMOCOUPLE	INPUT		
N013:008/001	THERM. MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:009	YE-3126BR	THERM. MODULE	CHAN. 3 DATA	OVERRRANGE	
N013:010/000	LINE	WT-SLL-3160	TEMPERATURE		
N013:010/001	THERM. MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:011	THERM. MODULE	CHAN. 4 DATA	OVERRRANGE		
N013:012/000	SPARE	THERMOCOUPLE	INPUT		
N013:012/001	THERM. MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:013	THERM. MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:014/000	SPARE	THERMOCOUPLE	INPUT		
N013:014/001	THERM. MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:015	SPARE	THERMOCOUPLE	INPUT		
N013:016/000	THERM. MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:016/001	THERM. MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:017	SPARE	THERMOCOUPLE	INPUT		
N013:018/000	THERM. MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:018/001	THERM. MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:019	SPARE	THERMOCOUPLE	INPUT		
N013:087/000	ANALOG MODULE	POWERED UP BUT	NOT CONFIGURED		
N013:087/001	ONE OR MORE	CHANNELS ARE	UNDER OR OVER	RANGE	
N013:088	ANALOG MODULE	UNDERRANGE	BITS REGISTER		
N013:088/000	ANALOG MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:088/001	ANALOG MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:088/002	ANALOG MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:088/003	ANALOG MODULE	CHAN. 4 DATA	UNDERRANGE		

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00112

DB Form Report

Sorted By: Address

07:29:31 02/19/99

N013:088/004	ANALOG MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:088/005	ANALOG MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:088/006	ANALOG MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:088/007	ANALOG MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:089	ANALOG MODULE	OVERRRANGE	BITS REGISTER		
N013:089/000	ANALOG MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:089/001	ANALOG MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:089/002	ANALOG MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:089/003	ANALOG MODULE	CHAN. 4 DATA	OVERRRANGE		
N013:089/004	ANALOG MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:089/005	ANALOG MODULE	CHAN. 6 DATA	OVERRRANGE		
N013:089/006	ANALOG MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:089/007	ANALOG MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:091	PT-3126AR	LOSS OF VACUUM	WT-SML-3150		
N013:092	PT-3126BR	LOSS OF VACUUM	WT-SLL-3160		
N013:093	PT-3167R	VALVE	SOV-3167A/B	PRESSURE	
N013:094	PT-3168R	VALVE	SOV-3168A/B	PRESSURE	
N013:095	PT-3185R	VALVE	SOV-3185A/B	PRESSURE	
N013:096	SPARE	ANALOG	INPUT		
N013:097	SPARE	ANALOG	INPUT		
N013:098	SPARE	ANALOG	INPUT		
N014:000					
N014:000/000	HB PLC3_OCS	HEARTBEAT	FROM PLC-3	TO OCS	
N014:000/001	COM-31	COMMUN. WITH	PCU-1	IGNORED	
N014:000/002	COM-32	COMMUN. WITH	PCU-2	IGNORED	
N014:000/003	COM-3_OCS	COMMUNICATION	WITH OCS	IGNORED	
N014:000/004	COM-34	COMMUN. WITH	PCU-4	IGNORED	
N014:000/005	COM-35	COMMUN. WITH	PCU-5	IGNORED	
N014:000/006	BATT_BAD_PLCS	PLC-3 BATTERY	IS BAD OR	MISSING	
N014:000/007					
N014:000/008					
N014:000/009					
N014:000/010					
N014:000/011	LDA-TR-LINE	TRANSFER	LINE	LEAK	DETECTED
N014:000/012	LDA-3151	LEAK DETECTED	AT VENT	STATION	6241-V SURP
N014:000/013	PAH-3167	VALVE	SOV-3167A/B	FAILURE	Y72
N014:000/014	PAH-3168	VALVE	SOV-3168A/B	FAILURE	Y73
N014:000/015	PAH-3185	VALVE	SOV-3185A/B	FAILURE	Y73
N014:001					
N014:001/000	ZA-3165A1	VALVE	FAILED	TO OPEN	Y71
N014:001/001	ZA-3165A2	VALVE	FAILED	TO CLOSE	Y71
N014:001/002	ZA-3165A	VALVE	POSITION	SWITCH FAILURE	Y71
N014:001/003	ZA-3165B1	VALVE	FAILED	TO OPEN	Y71
N014:001/004	ZA-3165B2	VALVE	FAILED	TO CLOSE	Y71
N014:001/005	ZA-3165B	VALVE	POSITION	SWITCH FAILURE	Y71
N014:001/006	ZA-3166A1	VALVE	FAILED	TO OPEN	Y71
N014:001/007	ZA-3166A2	VALVE	FAILED	TO CLOSE	Y71
N014:001/008	ZA-3166A	VALVE	POSITION	SWITCH FAILURE	Y71
N014:001/009	ZA-3166B1	VALVE	FAILED	TO OPEN	Y71
N014:001/010	ZA-3166B2	VALVE	FAILED	TO CLOSE	Y71
N014:001/011	ZA-3166B	VALVE	POSITION	SWITCH FAILURE	Y71
N014:001/012	ZA-3167A1	VALVE	FAILED	TO OPEN	Y88-1
N014:001/013	ZA-3167A2	VALVE	FAILED	TO CLOSE	Y88-1
N014:001/014	ZA-3167A	VALVE	POSITION	SWITCH FAILURE	Y88-1
N014:002					
N014:002/000	ZA-3167B1	VALVE	FAILED	TO OPEN	Y88-2
N014:002/001	ZA-3167B2	VALVE	FAILED	TO CLOSE	Y88-2
N014:002/002	ZA-3167B	VALVE	POSITION	SWITCH FAILURE	Y88-2
N014:002/003	ZA-3168A1	VALVE	FAILED	TO OPEN	Y81-3
N014:002/004	ZA-3168A2	VALVE	FAILED	TO CLOSE	Y81-3
N014:002/005	ZA-3168A	VALVE	POSITION	SWITCH FAILURE	Y81-3
N014:002/006	ZA-3168B1	VALVE	FAILED	TO OPEN	Y81-4
N014:002/007	ZA-3168B2	VALVE	FAILED	TO CLOSE	Y81-4
N014:002/008	ZA-3168B	VALVE	POSITION	SWITCH FAILURE	Y81-4
N014:002/009	ZA-3185A1	VALVE	FAILED	TO OPEN	Y81-1
N014:002/010	ZA-3185A2	VALVE	FAILED	TO CLOSE	Y81-1
N014:002/011	ZA-3185A	VALVE	POSITION	SWITCH FAILURE	Y81-1
N014:002/012	ZA-3185B1	VALVE	FAILED	TO OPEN	Y81-2
N014:002/013	ZA-3185B2	VALVE	FAILED	TO CLOSE	Y81-2
N014:002/014	ZA-3185B	VALVE	POSITION	SWITCH FAILURE	Y81-2
N014:002/015					
N014:003/000	TR_ON_1001	TRANSFER 1	INITIATED		Y-41.1
N014:003/001	TR_ON_1002A	TRANSFER 2A	INITIATED		Y-42.1
N014:003/002	TR_ON_1002B	TRANSFER 2B	INITIATED		Y-43.1
N014:003/003	TR_ON_1003	TRANSFER 3	INITIATED		Y-44.1
N014:003/004	TR_EN_1001	ENABLE	TRANSFER 1	241-SY-A TO 241-A-B	Y-70.1

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00113

DB Form Report

Sorted By: Address

07:29:00 02/19/99

N014:003/005	TR EN 1002A	ENABLE	TRANSFER 2-A	241-SY-B TO	241-A-A	Y-70.1
N014:003/006	TR EN 1002B	ENABLE	TRANSFER 2-B	241-SY-B TO	241-A-A	Y-70.1
N014:003/007	TR EN 1003	ENABLE	TRANSFER 3	241-A-B TO	241-SY-A	Y-70.1
N014:003/008						
N014:003/009						
N014:003/010						
N014:003/011						
N014:003/012						
N014:003/013						
N014:003/014						
N014:003/015						
N014:011						
N014:011/000	TI-3126A	PCU-3 INPUT	OVER AND UNDER	RANGE STATUS	BITS TO OIT	
N014:011/001	PCU3-SP-TI-2 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:011/002	TI-3126B A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:011/003	PCU3-SP-TI-4 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:011/004	PCU3-SP-TI-5 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:011/005	PCU3-SP-TI-6 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:011/006	PCU3-SP-TI-7 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:011/007	PCU3-SP-TI-8 A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	Y70
N014:012/008	PI-3126A A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/009	PI-3126B A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/010	PI-3167 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/011	PI-3168 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/012	PI-3185 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/013	PCU3-SP-AI-6 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/014	PCU3-SP-AI-7 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:012/015	PCU3-SP-AI-8 A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	Y70
N014:024		DIGITAL INPUT	REGISTER TO	OIT TERMINALS		
N014:024/000	ZLH-3165A	SOV-3165A	IS OPEN			Y70
N014:024/001	ZLL-3165A	SOV-3165A	IS CLOSED			Y70
N014:024/002	ZLL-3165B	SOV-3165B	IS OPEN			Y70
N014:024/003	ZLL-3165B	SOV-3165B	IS CLOSED			Y70
N014:024/004	ZLH-3166A	SOV-3166A	IS OPEN			Y70
N014:024/005	ZLL-3166A	SOV-3166A	IS CLOSED			Y70
N014:024/006	ZLH-3166B	SOV-3166B	IS OPEN			Y70
N014:024/007	ZLL-3166B	SOV-3166B	IS CLOSED			Y70
N014:024/008	ZLH-3167A	SOV-3167A	IS OPEN			Y88-1
N014:024/009	ZLL-3167A	SOV-3167A	IS CLOSED			Y88-1
N014:024/010	ZLH-3168A	SOV-3168A	IS OPEN			Y81-3
N014:024/011	ZLH-3168A	SOV-3168A	IS CLOSED			Y81-3
N014:024/012	ZLH-3168B	SOV-3168B	IS OPEN			Y-81-4
N014:024/013	ZLL-3168B	SOV-3168B	IS CLOSED			Y-81-4
N014:024/014	ZLH-3185A	SOV-3185A	IS OPEN			Y81-1
N014:024/015	ZLL-3185A	SOV-3185A	IS CLOSED			Y81-1
N014:025						
N014:025/000	ZLH-3185B	SOV-3185B	IS OPEN			Y81-2
N014:025/001	ZLL-3185B	SOV-3185B	IS CLOSED			Y81-2
N014:025/002	PCU3-SP-14-2	SPARE	DIGITAL	INPUT		
N014:025/003	PCU3-SP-14-3	SPARE	DIGITAL	INPUT		
N014:025/004	LDA-3151	6241-V	SUMP LEAK	DETECTION		Y72
N014:025/005	LDA-3161	6241-V	ENCASEMENT	LEAK DETECTION	OFF = ALARM	Y72
N014:025/006	YA-3102A	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	OIT
N014:025/007	YA-3102B	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	OIT
N014:025/008	YA-3102C	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	OIT
N014:025/009	YA-3102D	ENCASEMENT	RUPTURE DISK	ACTIVATED	OFF = ALARM	OIT
N014:025/010	ZLH-3167B	SOV-3167B	IS OPEN			Y-88.2
N014:025/011	ZLL-3167B	SOV-3167B	IS CLOSED			Y-88.2
N014:025/012	PAL-3100B	LOW	COMPRESSOR	SA-CMP-3101B	PRESSURE	
N014:025/013	LDAH-3151	SUMP LEAK	DETECTION			Y72
N014:025/014	PCU3-SP-14-16	SPARE	DIGITAL	INPUT		
N014:025/015	PCU3-SP-14-17	SPARE	DIGITAL	INPUT		
N014:026						
N014:027						
N014:028						
N014:028/000	SOV-3165A1	OPEN VALVE	REGISTER TO	OIT TERMINALS		Y71
N014:028/001	SOV-3165A2	CLOSE VALVE	SOV-3165A			Y71
N014:028/002	SOV-3165B1	OPEN VALVE	SOV-3165B			Y71
N014:028/003	SOV-3165B2	CLOSE VALVE	SOV-3165B			Y71
N014:028/004	SOV-3166A1	OPEN VALVE	SOV-3166A			Y71
N014:028/005	SOV-3166A2	CLOSE VALVE	SOV-3166A			Y71
N014:028/006	SOV-3166B1	OPEN VALVE	SOV-3166B			Y71
N014:028/007	SOV-3166B2	CLOSE VALVE	SOV-3166B			Y88-1
N014:028/008	SOV-3167A1	OPEN VALVE	SOV-3167A			Y88-1
N014:028/009	SOV-3167A2	CLOSE VALVE	SOV-3167A			Y81-3
N014:028/010	SOV-3168A1	OPEN VALVE	SOV-3168A			Y81-3
N014:028/011	SOV-3168A2	CLOSE VALVE	SOV-3168A			Y81-4

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page: 00114

DB Form Report Sorted By: Address

07:29:00 02/19/99

N014: 028/012	SOV-3168B1	OPEN VALVE	SOV-3168B			Y81-4
N014: 028/013	SOV-3168B2	CLOSE VALVE	SOV-3168B			Y81-1
N014: 028/014	SOV-3185A1	OPEN VALVE	SOV-3185A			Y81-1
N014: 028/015	SOV-3185A2	CLOSE VALVE	SOV-3185A			
N014: 029						
N014: 029/000	SOV-3185B1	OPEN VALVE	SOV-3185B			Y81-2
N014: 029/001	SOV-3185B2	CLOSE VALVE	SOV-3185B			Y81-2
N014: 029/002	P-3116-SD	SHUTDOWN	SUMP PUMP	P-3116		Y-82.1
N014: 029/003	SOV-3167B1	OPEN VALVE	SOV-3167B			Y88-1
N014: 029/004	SOV-3167B2	CLOSE VALVE	SOV-3167B			Y88-1
N014: 029/005	PCU3-SP-07-05	SPARE DIGITAL	OUTPUT			
N014: 029/006	PCU3-SP-07-06	SPARE DIGITAL	OUTPUT			
N014: 029/007	PCU3-SP-07-07	SPARE DIGITAL	OUTPUT			
N014: 029/008	PCU3-SP-07-10	SPARE DIGITAL	OUTPUT			
N014: 029/009	PCU3-SP-07-11	SPARE DIGITAL	OUTPUT			
N014: 029/010	PCU3-SP-07-12	SPARE DIGITAL	OUTPUT			
N014: 029/011	PCU3-SP-07-13	SPARE DIGITAL	OUTPUT			
N014: 029/012	PCU3-SP-07-14	SPARE DIGITAL	OUTPUT			
N014: 029/013	PCU3-SP-07-15	SPARE DIGITAL	OUTPUT			
N014: 029/014	PCU3-SP-07-16	SPARE DIGITAL	OUTPUT			
N014: 029/015	PCU3-SP-07-17	SPARE DIGITAL	OUTPUT			
N014: 030	TI-3126A	LINE	WT-SNL-3150	TEMPERATURE		
N014: 031	PCU3-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014: 032	TI-3126B	LINE	WT-SLL-3160	TEMPERATURE		
N014: 033	PCU3-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014: 034	PCU3-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014: 035	PCU3-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014: 036	PCU3-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		
N014: 037	PCU3-SP-TI-8	SPARE	THERMOCOUPLE	INPUT		
N014: 038	PI-3126A	LOSS OF	VACUUM	WT-SNL-3150		
N014: 039	PI-3126B	LOSS OF	VACUUM	WT-SLL-3160		
N014: 040	PI-3167	VALVE	SOV-3167A/B	PRESSURE		
N014: 041	PI-3168	VALVE	SOV-3168A/B	PRESSURE		
N014: 042	PI-3185	VALVE	SOV-3185A/B	PRESSURE		
N014: 043	PCU3-SP-AI-6	SPARE	ANALOG	INPUT		
N014: 044	PCU3-SP-AI-7	SPARE	ANALOG	INPUT		
N014: 045	PCU3-SP-AI-8	SPARE	ANALOG	INPUT		
N014: 046						
N014: 047						
N014: 048						
N014: 049						
N014: 060/000	HB PLC3 OCS	HEARTBEAT	FROM PLC-3	TO OCS		
N014: 060/001	COM-31	COMMUN. WITH	PCU-1	IGNORED		
N014: 060/002	COM-32	COMMUN. WITH	PCU-2	IGNORED		
N014: 060/003	COM-3 OCS	COMMUNICATION	WITH OCS	IGNORED		
N014: 060/004	COM-34	COMMUN. WITH	PCU-4	IGNORED		
N014: 060/005	COM-35	COMMUN. WITH	PCU-5	IGNORED		
N014: 060/006	BATT BAD PLC3	PLC-3 BATTERY	IS BAD OR	MISSING		
N014: 060/007						
N014: 060/008						
N014: 060/009						
N014: 060/010						
N014: 060/011	LDA-TR-LINE	TRANSFER	LINE	LEAK	DETECTED	Y72
N014: 060/012	LDA-3151	LEAK DETECTED	AIR VENT	STATION	6241-V SUMP	Y-72.1
N014: 060/013	PAH-3167	VALVE	SOV-3167A/B	FAILURE		Y73
N014: 060/014	PAH-3168	VALVE	SOV-3168A/B	FAILURE		Y73
N014: 060/015	PAH-3185	VALVE	SOV-3185A/B	FAILURE		Y73
N014: 061/000	ZA-3165A1	VALVE	FAILED	TO OPEN		Y71
N014: 061/001	ZA-3165A2	VALVE	FAILED	TO CLOSE		Y71
N014: 061/002	ZA-3165A	VALVE	POSITION	SWITCH FAILURE		Y71
N014: 061/003	ZA-3165B1	VALVE	FAILED	TO OPEN		Y71
N014: 061/004	ZA-3165B2	VALVE	FAILED	TO CLOSE		Y71
N014: 061/005	ZA-3165B	VALVE	POSITION	SWITCH FAILURE		Y71
N014: 061/006	ZA-3166A1	VALVE	FAILED	TO OPEN		Y71
N014: 061/007	ZA-3166A2	VALVE	FAILED	TO CLOSE		Y71
N014: 061/008	ZA-3166A	VALVE	POSITION	SWITCH FAILURE		Y71
N014: 061/009	ZA-3166B1	VALVE	FAILED	TO OPEN		Y71
N014: 061/010	ZA-3166B2	VALVE	FAILED	TO CLOSE		Y71
N014: 061/011	ZA-3166B	VALVE	POSITION	SWITCH FAILURE		Y71
N014: 061/012	ZA-3167A1	VALVE	FAILED	TO OPEN		Y88-1
N014: 061/013	ZA-3167A2	VALVE	FAILED	TO CLOSE		Y88-1
N014: 061/014	ZA-3167A	VALVE	POSITION	SWITCH FAILURE		Y88-1
N014: 061/015						
N014: 062/000	ZA-3167B1	VALVE	FAILED	TO OPEN		Y88-2
N014: 062/001	ZA-3167B2	VALVE	FAILED	TO CLOSE		Y88-2
N014: 062/002	ZA-3167B	VALVE	POSITION	SWITCH FAILURE		Y88-2
N014: 062/003	ZA-3168A1	VALVE	FAILED	TO OPEN		Y81-3

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00115

DB Form Report Sorted By: Address

07:29:01 02/19/99

N014:062/004	ZA-3168A2	VALVE	FAILED	TO CLOSE		Y81-3
N014:062/005	ZA-3168A	VALVE	POSITION	SWITCH FAILURE		Y81-3
N014:062/006	ZA-3168B1	VALVE	FAILED	TO OPEN		Y81-4
N014:062/007	ZA-3168B2	VALVE	FAILED	TO CLOSE		Y81-4
N014:062/008	ZA-3168B	VALVE	POSITION	SWITCH FAILURE		Y81-4
N014:062/009	ZA-3185A1	VALVE	FAILED	TO OPEN		Y81-1
N014:062/010	ZA-3185A2	VALVE	FAILED	TO CLOSE		Y81-1
N014:062/011	ZA-3185A	VALVE	POSITION	SWITCH FAILURE		Y81-1
N014:062/012	ZA-3185B1	VALVE	FAILED	TO OPEN		Y81-2
N014:062/013	ZA-3185B2	VALVE	FAILED	TO CLOSE		Y81-2
N014:062/014	ZA-3185B	VALVE	POSITION	SWITCH FAILURE		Y81-2
N014:063/000	TR_ON_1001	TRANSFER 1	INITIATED			Y-41.1
N014:063/001	TR_ON_1002A	TRANSFER 2A	INITIATED			Y-42.1
N014:063/002	TR_ON_1002B	TRANSFER 2B	INITIATED			Y-43.1
N014:063/003	TR_ON_1003	TRANSFER 3	INITIATED			Y-44.1
N014:063/004	TR_EN_1001	ENABLE	TRANSFER 1	241-SY-A TO	241-A-B	Y-70.1
N014:063/005	TR_EN_1002A	ENABLE	TRANSFER 2-A	241-SY-B TO	241-A-A	Y-70.1
N014:063/006	TR_EN_1002B	ENABLE	TRANSFER 2-B	241-SY-B TO	241-A-A	Y-70.1
N014:063/007	TR_EN_1003	ENABLE	TRANSFER 3	241-A-B TO	241-SY-A	Y-70.1
N014:063/008						
N014:063/009						
N014:063/010						
N014:063/011						
N014:063/012						
N014:063/013						
N014:063/014						
N014:063/015						
N014:064/000	TI-3126A_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/001	PCU3-SP-TI-2_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/002	TI-3126B_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/003	PCU3-SP-TI-4_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/004	PCU3-SP-TI-5_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/005	PCU3-SP-TI-6_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/006	PCU3-SP-TI-7_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:064/007	PCU3-SP-TI-8_A	PCU-3 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:065/008	PI-3126A_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/009	PI-3126B_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/010	PI-3167_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/011	PI-3168_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/012	PI-3185_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/013	PCU3-SP-AI-6_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/014	PCU3-SP-AI-7_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:065/015	PCU3-SP-AI-8_A	PCU-3 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:066/000	ZLH-3165A	SOV-3165A	IS OPEN			Y70
N014:066/001	ZLH-3165A	SOV-3165A	IS CLOSED			Y70
N014:066/002	ZLH-3165B	SOV-3165B	IS OPEN			Y70
N014:066/003	ZLH-3165B	SOV-3165B	IS CLOSED			Y70
N014:066/004	ZLH-3166A	SOV-3166A	IS OPEN			Y70
N014:066/005	ZLH-3166A	SOV-3166A	IS CLOSED			Y70
N014:066/006	ZLH-3166B	SOV-3166B	IS OPEN			Y70
N014:066/007	ZLH-3166B	SOV-3166B	IS CLOSED			Y70
N014:066/008	ZLH-3167A	SOV-3167A	IS OPEN			Y88-1
N014:066/009	ZLH-3167A	SOV-3167A	IS CLOSED			Y88-1
N014:066/010	ZLH-3168A	SOV-3168A	IS OPEN			Y81-3
N014:066/011	ZLH-3168A	SOV-3168A	IS CLOSED			Y81-3
N014:066/012	ZLH-3168B	SOV-3168B	IS OPEN			Y-81.4
N014:066/013	ZLH-3168B	SOV-3168B	IS CLOSED			Y-81.4
N014:066/014	ZLH-3185A	SOV-3185A	IS OPEN			Y81-1
N014:066/015	ZLH-3185A	SOV-3185A	IS CLOSED			Y81-1
N014:067/000	ZLH-3185B	SOV-3185B	IS OPEN			Y81-2
N014:067/001	ZLH-3185B	SOV-3185B	IS CLOSED			Y81-2
N014:067/002	PCU3-SP-14-2	SPARE	DIGITAL	INPUT		
N014:067/003	PCU3-SP-14-3	SPARE	DIGITAL	INPUT		
N014:067/004	LDA-3151	6241-V	SUMP LEAK	DETECTION		Y72
N014:067/005	LDA-3161	6241-V	ENCASEMENT	LEAK DETECTION	[OFF = ALARM]	Y72
N014:067/006	YA-3102A	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	01T
N014:067/007	YA-3102B	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	01T
N014:067/008	YA-3102C	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	01T
N014:067/009	YA-3102D	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	01T
N014:067/010	ZLH-3167B	SOV-3167B	IS OPEN			Y-88.2
N014:067/011	ZLH-3167B	SOV-3167B	IS CLOSED			
N014:067/012	PAL-3100B	LOW	COMPRESSOR	SA-CMP-3101B	PRESSURE	Y-88.2
N014:067/013	LDAH-3151	SUMP LEAK	DETECTOR			Y72
N014:067/014	PCU3-SP-14-16	SPARE	DIGITAL	INPUT		
N014:067/015	PCU3-SP-14-17	SPARE	DIGITAL	INPUT		
N014:068/000	SOV-3165A1	OPEN VALVE	SOV-3165A			Y71
N014:068/001	SOV-3165A2	CLOSE VALVE	SOV-3165A			Y71

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page: 00118

DB Form Report Sorted By: Address

07:29:01 02/19/99

N014:068/002	SOV-3165B1	OPEN VALVE	SOV-3165B			Y71
N014:068/003	SOV-3165B2	CLOSE VALVE	SOV-3165B			Y71
N014:068/004	SOV-3166A1	OPEN VALVE	SOV-3166A			Y71
N014:068/005	SOV-3166A2	CLOSE VALVE	SOV-3166A			Y71
N014:068/006	SOV-3166B1	OPEN VALVE	SOV-3166B			Y71
N014:068/007	SOV-3166B2	CLOSE VALVE	SOV-3166B			Y88-1
N014:068/008	SOV-3167A1	OPEN VALVE	SOV-3167A			Y88-1
N014:068/009	SOV-3167A2	CLOSE VALVE	SOV-3167A			Y81-3
N014:068/010	SOV-3168A1	OPEN VALVE	SOV-3168A			Y81-3
N014:068/011	SOV-3168A2	CLOSE VALVE	SOV-3168A			Y81-4
N014:068/012	SOV-3168B1	OPEN VALVE	SOV-3168B			Y81-4
N014:068/013	SOV-3168B2	CLOSE VALVE	SOV-3168B			Y81-1
N014:068/014	SOV-3185A1	OPEN VALVE	SOV-3185A			Y81-1
N014:068/015	SOV-3185A2	CLOSE VALVE	SOV-3185A			
N014:069/000	SOV-3185B1	OPEN VALVE	SOV-3185B			Y81-2
N014:069/001	SOV-3185B2	CLOSE VALVE	SOV-3185B			Y81-2
N014:069/002	P-3116-SD	SHUTDOWN	SUMP PUMP	P-3116		Y-82.1
N014:069/003	SOV-3167B1	OPEN VALVE	SOV-3167B			Y88-1
N014:069/004	SOV-3167B2	CLOSE VALVE	SOV-3167B			Y88-1
N014:069/005	PCU3-SP-07-05	SPARE DIGITAL	OUTPUT			
N014:069/006	PCU3-SP-07-06	SPARE DIGITAL	OUTPUT			
N014:069/007	PCU3-SP-07-07	SPARE DIGITAL	OUTPUT			
N014:069/008	PCU3-SP-07-10	SPARE DIGITAL	OUTPUT			
N014:069/009	PCU3-SP-07-11	SPARE DIGITAL	OUTPUT			
N014:069/010	PCU3-SP-07-12	SPARE DIGITAL	OUTPUT			
N014:069/011	PCU3-SP-07-13	SPARE DIGITAL	OUTPUT			
N014:069/012	PCU3-SP-07-14	SPARE DIGITAL	OUTPUT			
N014:069/013	PCU3-SP-07-15	SPARE DIGITAL	OUTPUT			
N014:069/014	PCU3-SP-07-16	SPARE DIGITAL	OUTPUT			
N014:069/015	PCU3-SP-07-17	SPARE DIGITAL	OUTPUT			
N014:070	T1-3126A	LINE	WT-SNL-3150	TEMPERATURE		
N014:071	PCU3-SP-T1-2	SPARE	THERMOCOUPLE	INPUT		
N014:072	T1-3126B	LINE	WT-SLL-3160	TEMPERATURE		
N014:073	PCU3-SP-T1-4	SPARE	THERMOCOUPLE	INPUT		
N014:074	PCU3-SP-T1-5	SPARE	THERMOCOUPLE	INPUT		
N014:075	PCU3-SP-T1-6	SPARE	THERMOCOUPLE	INPUT		
N014:076	PCU3-SP-T1-7	SPARE	THERMOCOUPLE	INPUT		
N014:077	PCU3-SP-T1-8	SPARE	THERMOCOUPLE	INPUT		
N014:078	P1-3126A	LOSS OF	VACUUM	WT-SNL-3150		
N014:079	P1-3126B	LOSS OF	VACUUM	WT-SLL-3160		
N014:080	P1-3167	VALVE	SOV-3167A/B	PRESSURE		
N014:081	P1-3168	VALVE	SOV-3168A/B	PRESSURE		
N014:082	P1-3185	VALVE	SOV-3185A/B	PRESSURE		
N014:083	PCU3-SP-A1-6	SPARE	ANALOG	INPUT		
N014:084	PCU3-SP-A1-7	SPARE	ANALOG	INPUT		
N014:085	PCU3-SP-A1-8	SPARE	ANALOG	INPUT		
N014:120	HB_OCS_PLC3	HEARTBEAT	FROM OCS	TO PLC-3		
N014:120/000						
N014:120/001						
N014:120/002						
N014:120/003						
N014:120/004						
N014:120/005						
N014:120/006	HS-3185A1	OCS OPEN	VALVE	SOL-3185A		Y81-1
N014:120/007	HS-3185A2	OCS CLOSE	VALVE	SOL-3185A		Y81-1
N014:120/008	HS-3185B1	OCS OPEN	VALVE	SOL-3185B		Y81-2
N014:120/009	HS-3185B2	OCS CLOSE	VALVE	SOL-3185B		Y81-2
N014:120/010	HS-3168A1	OCS OPEN	VALVE	SOL-3168A		Y81-3
N014:120/011	HS-3168A2	OCS CLOSE	VALVE	SOL-3168A		Y81-3
N014:120/012	HS-3168B1	OCS OPEN	VALVE	SOL-3168B		Y81-4
N014:120/013	HS-3168B2	OCS CLOSE	VALVE	SOL-3168B		Y81-4
N014:120/014	HS-3165A1	OCS OPEN	VALVE	SOV-3165A		Y71
N014:120/015	HS-3165A2	OCS CLOSE	VALVE	SOV-3165A		Y71
N014:121						
N014:121/000	HS-1010A	LEAK DETECTION	OVERRIDE	Y-72.1		
N014:121/001	HS-1010B	LEAK DETECTION	SEQUENCING	RESET	Y-72.1	
N014:121/002	HS-3166A1	OCS OPEN	VALVE	SOV-3166A		Y71
N014:121/003	HS-3166A2	OCS CLOSE	VALVE	SOV-3166A		Y71
N014:121/004	HS-3165B1	OCS OPEN	VALVE	SOV-3165B		Y71
N014:121/005						
N014:121/006	HS-3165B2	OCS CLOSE	VALVE	SOV-3165B		Y71
N014:121/007	HS-3166B1	OCS OPEN	VALVE	SOV-3166B		Y71
N014:121/008	HS-3166B2	OCS CLOSE	VALVE	SOV-3166B		Y71
N014:121/009	HS-3167A1	OCS OPEN	VALVE	SOV-3167A		Y88-1
N014:121/010	HS-3167A2	OCS CLOSE	VALVE	SOV-3167A		Y88-1
N014:121/011	HS-3167B1	OCS OPEN	VALVE	SOV-3167B		Y87-2
N014:121/012	HS-3167B2	OCS CLOSE	VALVE	SOV-3167B		Y87-2

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

DB Form Report

Sorted By: Address

Page:00117

07:29:02 02/19/99

N014:121/013					
N014:121/014					
N014:121/015					
N014:122					
N014:122/000	HS-1000A	OCS INITIATE	TRANSFER		Y-70.1
N014:122/001	HS-1000B	OCS RESET	TRANSFER		Y-70.1
N014:122/002	HS-1001	OCS SELECT	TRANSFER	TYPE 1	Y-70.1
N014:122/003	HS-1002A	OCS SELECT	TRANSFER	TYPE 2A	Y-70.1
N014:122/004	HS-1002B	OCS SELECT	TRANSFER	TYPE 2B	Y-70.1
N014:122/005	HS-1003	OCS SELECT	TRANSFER	TYPE 3	Y-70.1
N014:122/006					
N014:122/007					
N014:122/008					
N014:122/009					
N014:122/010					
N014:122/011					
N014:122/012					
N014:122/013					
N014:122/014					
N014:122/015					
N014:123/000					
N014:151					
N014:152					
N014:153					
N014:154					
N014:170/000	HB_OCS_PLCS	HEARTBEAT	FROM OCS	TO PLC-3	
N014:170/001					
N014:170/002					
N014:170/003					
N014:170/004					
N014:170/005					
N014:170/006	HS-3185A1	OCS OPEN	VALVE	SOL-3185A	Y81-1
N014:170/007	HS-3185A2	OCS CLOSE	VALVE	SOL-3185A	Y81-1
N014:170/008	HS-3185B1	OCS OPEN	VALVE	SOL-3185B	Y81-2
N014:170/009	HS-3185B2	OCS CLOSE	VALVE	SOL-3185B	Y81-2
N014:170/010	HS-3168A1	OCS OPEN	VALVE	SOL-3168A	Y81-3
N014:170/011	HS-3168A2	OCS CLOSE	VALVE	SOL-3168A	Y81-3
N014:170/012	HS-3168B1	OCS OPEN	VALVE	SOL-3168B	Y81-4
N014:170/013	HS-3168B2	OCS CLOSE	VALVE	SOL-3168B	Y81-4
N014:170/014	HS-3165A1	OCS OPEN	VALVE	SOV-3165A	Y71
N014:170/015	HS-3165A2	OCS CLOSE	VALVE	SOV-3165A	Y71
N014:171/000					
N014:171/001	HS-1010A	LEAK DETECTION	OVERRIDE	Y-72.1	
N014:171/002	HS-1010B	LEAK DETECTION	SEQUENCING	RESET	Y-72.1
N014:171/003	HS-3166A1	OCS OPEN	VALVE	SOV-3166A	Y71
N014:171/004	HS-3166A2	OCS CLOSE	VALVE	SOV-3166A	Y71
N014:171/005	HS-3165B1	OCS OPEN	VALVE	SOV-3165B	Y71
N014:171/006	HS-3165B2	OCS CLOSE	VALVE	SOV-3165B	Y71
N014:171/007	HS-3166B1	OCS OPEN	VALVE	SOV-3166B	Y71
N014:171/008	HS-3166B2	OCS CLOSE	VALVE	SOV-3166B	Y71
N014:171/009	HS-3167A1	OCS OPEN	VALVE	SOV-3167A	Y88-1
N014:171/010	HS-3167A2	OCS CLOSE	VALVE	SOV-3167A	Y88-1
N014:171/011	HS-3167B1	OCS OPEN	VALVE	SOV-3167B	Y87-2
N014:171/012	HS-3167B2	OCS CLOSE	VALVE	SOV-3167B	Y87-2
N014:171/013					
N014:171/014					
N014:171/015					
N014:172/000	HS-1000A	OCS INITIATE	TRANSFER		Y-70.1
N014:172/001	HS-1000B	OCS RESET	TRANSFER		Y-70.1
N014:172/002	HS-1001	OCS SELECT	TRANSFER	TYPE 1	Y-70.1
N014:172/003	HS-1002A	OCS SELECT	TRANSFER	TYPE 2A	Y-70.1
N014:172/004	HS-1002B	OCS SELECT	TRANSFER	TYPE 2B	Y-70.1
N014:172/005	HS-1003	OCS SELECT	TRANSFER	TYPE 3	Y-70.1
N014:172/006					
N014:172/007					
N014:172/008					
N014:172/009					
N014:172/010					
N014:172/011					
N014:172/012					
N014:172/013					
N014:172/014					
N014:172/015					
N019:001/000					
N019:001/001					
N019:001/002	HB-12	HEARTBEAT	FROM PCU-1	TO PCU-2	
N019:001/003	HB-13	HEARTBEAT	FROM PCU-1	TO PCU-3	

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00118

DB Form Report

Sorted By: Address

07:29:02 02/19/99

N019:001/004	HB-14	HEARTBEAT	FROM PCU-1	TO PCU-4		
N019:001/005	HB-15	HEARTBEAT	FROM PCU-1	TO PCU-5		
N019:001/006						
N019:001/007						
N019:001/008						
N019:001/009						
N019:001/010						
N019:001/011						
N019:001/012						
N019:001/013						
N019:001/014						
N019:001/015						
N019:002/000		200-W MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:002/001	HB-21	STOP BOOSTER	PUMP P-3125B &	TRANSFER PUMP	P-102-SY-02A	Y-74.2
N019:002/002		HEARTBEAT	FROM PCU-2	TO PCU-1		
N019:002/003		STOP BOOSTER	PUMP P-3125A &	TRANSFER PUMP	P-102-SY-02A	Y-74.1
N019:002/004	HB-23	HEARTBEAT	FROM PCU-2	TO PCU-3		
N019:002/005	HB-24	HEARTBEAT	FROM PCU-2	TO PCU-4		
N019:002/006	HB-25	HEARTBEAT	FROM PCU-2	TO PCU-5		
N019:002/007		LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
		LEAK DETECTED	IN LINE TO	DIVERSION	BOX 6241-A	Y-72.1
N019:002/008		SOV-3182A	VALVE	FAILURE		Y-71.1
N019:002/009		SOV-3182B	VALVE	FAILURE		Y-71.1
N019:002/010		SOV-3184	VALVE	FAILURE		Y-71.1
N019:002/011		SOV-3173A/B	VALVE	FAILURE		Y-73.1
N019:002/012		SOV-3183B	VALVE	FAILURE		Y-71.1
N019:002/013		SOV-3183A	VALVE	FAILURE		Y-71.1
N019:002/014		PUMP P-3125A	HIGH INLET	PRESSURE		Y-75.1
N019:002/015		PUMP P-3125B	HIGH INLET	PRESSURE		Y-75.1
N019:003/000		INPUT SIGNAL TO	200-W MASTER	SHUTDOWN	CIRCUIT	Y-72.1
N019:003/001	HB-31	HEARTBEAT	FROM PCU-3	TO PCU-1		
N019:003/002						
N019:003/003	HB-32	HEARTBEAT	FROM PCU-3	TO PCU-2		
N019:003/004	HB-34	HEARTBEAT	FROM PCU-3	TO PCU-4		
N019:003/005	HB-35	HEARTBEAT	FROM PCU-3	TO PCU-5		
N019:003/006						
N019:003/007		TRANSFER 2A	SHUTDOWN			Y-42.1
N019:003/008		TRANSFER 2B	SHUTDOWN			Y-43.1
N019:003/009						
N019:003/010		TRANSFER 1	INITIATED			Y-41.1
N019:003/011		TRANSFER 2A	INITIATED			Y-42.1
N019:003/012		TRANSFER 2B	INITIATED			Y-43.1
N019:003/013		TRANSFER 3	INITIATED			Y-44.1
N019:003/014						
N019:003/015		MASTER RESET				
N019:004/001	HB-41	HEARTBEAT	FROM PCU-4	TO PCU-1		
N019:004/002	HB-42	HEARTBEAT	FROM PCU-4	TO PCU-2		
N019:004/003	HB-43	HEARTBEAT	FROM PCU-4	TO PCU-3		
N019:004/004						
N019:004/005	HB-45	HEARTBEAT	FROM PCU-4	TO PCU-5		
N019:004/006						
N019:004/007		MOV-843	VALVE	FAILURE		Y71
N019:004/008		MOV-844	VALVE	FAILURE		Y71
N019:004/009		MOV-845	VALVE	FAILURE		Y71
N019:004/010		MOV-846	VALVE	FAILURE		Y71
N019:004/011		200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:004/012		RUPTURE	DISK FAILURE			Y-78.1
N019:004/013		LEAK DETECTED	AT 244-A LIFT	STATION	SUMP	Y-72.1
N019:004/014						
N019:004/015						
N019:005/000						
N019:005/001	HB-51	HEARTBEAT	FROM PCU-5	TO PCU-1		
N019:005/002	HB-52	HEARTBEAT	FROM PCU-5	TO PCU-2		
N019:005/003	HB-53	HEARTBEAT	FROM PCU-5	TO PCU-3		
N019:005/004	HB-54	HEARTBEAT	FROM PCU-5	TO PCU-4		
N019:005/005						
N019:005/006						
N019:005/007						
N019:005/008						
N019:005/009						
N019:005/010						
N019:005/011						
N019:005/012						
N019:005/013						
N019:005/014						
N019:005/015						
N020:000	YE-3126A	LEAK DETECTED	IN LINE TO	244-A LIFT	STATION	Y72-1
		LINE	WT-SNL-3150	TEMPERATURE		

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00119

DB Form Report Sorted By: Address

07:29:02 02/19/99

N020:001		SPARE	THERMOCOUPLE	INPUT		
N020:002	TE-3126B	LINE	WT-SLL-3160	TEMPERATURE		
N020:003		SPARE	THERMOCOUPLE	INPUT		
N020:004		SPARE	THERMOCOUPLE	INPUT		
N020:005		SPARE	THERMOCOUPLE	INPUT		
N020:006		SPARE	THERMOCOUPLE	INPUT		
N020:007		SPARE	THERMOCOUPLE	INPUT		
N020:008	PT-3126A	LOSS OF	VACUUM	WT-SNL-3150		
N020:009	PT-3126B	LOSS OF	VACUUM	WT-SLL-3160		
N020:010	PT-3167	VALVE	SOV-3167A/B	PRESSURE		
N020:011	PT-3168	VALVE	SOV-3168A/B	PRESSURE		
N020:012	PT-3185	VALVE	SOV-3185A/B	PRESSURE		
N020:013		SPARE	ANALOG	INPUT		
N020:014		SPARE	ANALOG	INPUT		
N020:015		SPARE	ANALOG	INPUT		
N021:040		DH+ TRANSFER	FROM PCU-1	DATA REGISTERS		
N021:040/000						
N021:040/001						
N021:040/002						
N021:040/003						
N021:040/004						
N021:040/005						
N021:040/006						
N021:040/007						
N021:040/008						
N021:040/009						
N021:040/010						
N021:040/011						
N021:040/012						
N021:040/013						
N021:040/014						
N021:040/015						
N021:041						
N021:042						
N021:043						
N021:044						
N022:040		DH+ TRANSFER	FROM PCU-2	DATA REGISTERS		
N022:040/000						
N022:040/001						
N022:040/002						
N022:040/003						
N022:040/004						
N022:040/005						
N022:040/006						
N022:040/007						
N022:040/008						
N022:040/009						
N022:040/010						
N022:040/011						
N022:040/012						
N022:040/013						
N022:040/014						
N022:040/015						
N022:041						
N022:042						
N022:043						
N022:044						
N023:000		DH+ TRANSFER	TO PCU-1	DATA REGISTERS		
N023:000/000						
N023:000/001						
N023:000/002						
N023:000/003						
N023:000/004						
N023:000/005						
N023:000/006						
N023:000/007						
N023:000/008						
N023:000/009						
N023:000/010						
N023:000/011						
N023:000/012						
N023:000/013						
N023:000/014						
N023:000/015						
N023:001						
N023:002						
N023:003						

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00120

DB Form Report

Sorted By: Address

07:29:03 02/19/99

N023:004					
N023:020	DH+ TRANSFER	TO PCU-2	DATA REGISTERS		
N023:020/000					
N023:020/001					
N023:020/002					
N023:020/003					
N023:020/004					
N023:020/005					
N023:020/006					
N023:020/007					
N023:020/008					
N023:020/009					
N023:020/010					
N023:020/011					
N023:020/012					
N023:020/013					
N023:020/014					
N023:020/015					
N023:021					
N023:022					
N023:023					
N023:024					
N023:060	DH+ TRANSFER	TO PCU-4	DATA REGISTERS		
N023:060/000					
N023:060/001					
N023:060/002					
N023:060/003					
N023:060/004					
N023:060/005					
N023:060/006					
N023:060/007					
N023:060/008					
N023:060/009					
N023:060/010					
N023:060/011					
N023:060/012					
N023:060/013					
N023:060/014					
N023:060/015					
N023:061					
N023:062					
N023:063					
N023:064					
N023:080	DH+ TRANSFER	TO PCU-5	DATA REGISTERS		
N023:080/000					
N023:080/001					
N023:080/002					
N023:080/003					
N023:080/004					
N023:080/005					
N023:080/006					
N023:080/007					
N023:080/008					
N023:080/009					
N023:080/010					
N023:080/011					
N023:080/012					
N023:080/013					
N023:080/014					
N023:080/015					
N023:081					
N023:082					
N023:083					
N023:084					
N023:100	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N023:120	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N023:160	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N023:180	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N024:040	DH+ TRANSFER	FROM PCU-4	DATA REGISTERS		
N024:040/000					
N024:040/001					
N024:040/002					
N024:040/003					
N024:040/004					
N024:040/005					
N024:040/006					
N024:040/007					

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00121

DB Form Report

Sorted By: Address

07:29:03 02/19/99

N024:040/008					
N024:040/009					
N024:040/010					
N024:040/011					
N024:040/012					
N024:040/013					
N024:040/014					
N024:040/015					
N024:041					
N024:042					
N024:043					
N024:044					
N025:040					
N025:040/000		DH+ TRANSFER	FROM PCU-5	DATA REGISTERS	
N025:040/001					
N025:040/002					
N025:040/003					
N025:040/004					
N025:040/005					
N025:040/006					
N025:040/007					
N025:040/008					
N025:040/009					
N025:040/010					
N025:040/011					
N025:040/012					
N025:040/013					
N025:040/014					
N025:040/015					
N025:041					
N025:042					
N025:043					
N025:044					
DFILE:000		OUTPUTS	Output Reg	isters And	Bits
DFILE:001		INPUTS	Input Regl	sters And	Bits
DFILE:002		SYSTEM	System Sta	tus Variab	les
DFILE:003		BITS	General In	ternal Bit	Addresses
DFILE:004		TIMERS	General Ti	mer Address	ses
DFILE:005		COUNTERS	General Co	unter Addr	esses
DFILE:006		CONTROL	General Co	ntrol Addr	esses
DFILE:007		INTEGERS	General In	teger Addr	esses
DFILE:008		FLOATING	General Fl	oating Poi	nt Address
DFILE:009		I/O STATUS	I/O Status	File (Use	d By The P
DFILE:010		PROC FLT	Stores Sys	tem Data 0	n A Proces
DFILE:011		GEN MSG	General	DH-Plus Me	ssage Cont
DFILE:012		GEN BIT	General	Block Tran	sfer Contr
DFILE:013		ANA RAW	Analog Dat	a File	
DFILE:014		O1X DATA	OCS Commun	ication Fi	le
DFILE:018		CONFIG1A	Channel 1A	Configura	tion Diag
DFILE:019		GLOBAL1A	Channel 1A	Config GI	lobal Statu
DFILE:020		ANA BUF	Analog I/O	Working F	ile
DFILE:021		PLC1DATA	DATA FROM	PLC-1(DH+)	
DFILE:022		PLC2DATA	DATA FROM	PLC-2(DH+)	
DFILE:023		PLC3DATA	DATA FROM	PLC-3(DH+)	
DFILE:024		PLC4DATA	DATA FROM	PLC-4(DH+)	
DFILE:025		PLC5DATA	DATA FROM	PLC-5(DH+)	
PFILE:000		[SYSTEM DA	TA STORAGE	HEADER]	
PFILE:002		MAIN PROGR	AM FILE		
PFILE:003		PROCESSOR	FAULT ROUT	INE	
PFILE:004		I/O HANDLI	NG FOR ANA	LOG AND OT	HER REGIST
PFILE:005		COMMUNICAT	ION		
PFILE:006		TRANSFER V	ALVES LOGI	C	
PFILE:007		VENT VALVE	S LOGIC		
PFILE:008		SUMP PUMP	VALVES AND	MISCELLAN	EDUS INTER
PFILE:010		TRANSFER 1	INITIATE SE	QUENCING	LOCK LOGIC
PFILE:011		TRANSFER 1	- 2A - 2B	- 3 SELEC	ITION
PFILE:012		LEAK DETEC	TION CONTR	OL LOGIC	
Q002:000		MAIN PROGRAM	FILE START-UP	JUMP TO JSR'S	
Q002:001		MAIN PROGRAM	FILE START-UP	JUMP TO END	
Q003:000		PROCESSOR	FAULT ROUTINE	JUMP TO END	
U:004		I/O HANDLING	FOR ANALOG OR	OTHER REG I/O	SUBROUTINE
U:005		DATA HIGHWAY +	COMMUNICATION	CTRL & CHECK	SUBROUTINE
U:006		TR-R VALVES	CONTROL	SUBROUTINE	
U:007		VENT VALVES	CONTROL	SUBROUTINE	
U:008		SUMP PUMP	CONTROL	SUBROUTINE	
U:010		INITIATE	TRANSFER	SUBROUTINE	
U:011		TRANSFER	1-2A-2B-3	SUBROUTINE	

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00122

DB Form Report

Sorted By: Address

07:29:04 02/19/99

U:012	_____	LEAK	DETECTION	CONTROL	SUBROUTINE	_____
V:004	_____	I/O HANDLING	FOR ANALOG OR	OTHER REG I/O	SUBROUTINE	_____
V:005	_____	DATA HIGHWAY	COMMUNICATION	CTRL & CHECK	SUBROUTINE	_____
V:006	_____	TR-R VALVES	CONTROL	SUBROUTINE	_____	_____
V:007	_____	VENT VALVES	CONTROL	SUBROUTINE	_____	_____
V:008	_____	SUMP PUMP	CONTROL	SUBROUTINE	_____	_____
V:010	_____	INITIATE	TRANSFER	SUBROUTINE	_____	_____
V:011	_____	TRANSFER	1-2A-2B-3	SUBROUTINE	_____	_____
V:012	_____	LEAK	DETECTION	CONTROL	SUBROUTINE	_____

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00123

DB Form Report   Sorted By: Address

07:29:04 02/19/99

Addr:B3/0
TITLE:GENERAL USE BITS AND TIMING FUNCTIONS
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF

Addr:B3/1
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON

Addr:B3/2
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY SECOND.

Addr:B3/3
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY TWO SECONDS.

Addr:B3/4
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/5
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/6
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/36
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING

Addr:B3/37
RUNG DESCRIPTION:
THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

Addr:B3/39
TITLE:ANALOG INPUTS BLOCK TRANSFER SEQUENCING

Addr:B3/40
TITLE:COMMUNICATION HANDLING SUBROUTINE

Addr:B3/41
TITLE:SEQUENCING FOR TRANSFER VALVE SOV-3165A, Y-71.1

Addr:B3/42
TITLE:SEQUENCING FOR VENT VALVE SOV-3185A, Y-81.1

Addr:B3/45
TITLE:TRANSFER PERMISSIVES LOGIC, ES-058-Y70 SH.1

Addr:B3/46
TITLE:241-SY-A TO 241-A-B TRANSFER SCHEME # 1, Y-41.1

Addr:B3/64
RUNG DESCRIPTION:
TRANSFER SEQUENCE MASTER LOCK-OUT AND INITIATE CONTROLS

Addr:B3/67
RUNG DESCRIPTION:
TRANSFER SEQUENCE #1 LOCK-OUT AND INITIATE CONTROLS

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00124

DB Form Report   Sorted By: Address

07:29:04 02/19/99

Addr:B3/69
RUNG DESCRIPTION:
TRANSFER SEQUENCE #2A LOCK-OUT AND INITIATE CONTROLS

Addr:B3/71
RUNG DESCRIPTION:
TRANSFER SEQUENCE #2B LOCK-OUT AND INITIATE CONTROLS

Addr:B3/73
RUNG DESCRIPTION:
TRANSFER SEQUENCE #3 LOCK-OUT AND INITIATE CONTROLS

Addr:B3/89
TITLE:241-SY-B TO 241-A-A TRANSFER SCHEME # 2B, Y-43.1

Addr:B3/93
TITLE:241-SY-B TO 241-A-A TRANSFER SCHEME # 2A, Y-42.1

Addr:B3/108
TITLE:241-A-B TO 241-SY-A TRANSFER SCHEME # 3, Y-44.1

Addr:B3/111
TITLE:VALVE LEAK LOGIC Y-73.1

Addr:B3/302
TITLE:SEQUENCING FOR TRANSFER VALVE SOV-3166A, Y-71.1

Addr:B3/306
TITLE:SEQUENCING FOR TRANSFER VALVE SOV-3166B, Y-71.1

Addr:B3:1
RUNG DESCRIPTION:
THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE BITS CAN BE USED TO DIVIDE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

Addr:N14:11/0
TITLE:ANALOG INPUT OVER / UNDER RANGE ALARMS

Addr:N14:120/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND OCS

Addr:N14:170
TITLE:SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1

Addr:N16:0/8
TITLE:PCU-3 COMMUNICATION
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-1

Addr:N16:20/4
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-2

Addr:N16:60/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-4

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00125

DB Form Report Sorted By: Address

07:29:04 02/19/99

Addr:N16:80/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-5

Addr:N19:3/1
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-1

Addr:N19:3/2
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-2

Addr:N19:3/4
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-4

Addr:N19:3/5
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-3 AND PCU-5

Addr:N21:40
RUNG DESCRIPTION:
OIT DATA HANDSHAKE BACK THROUGH PCU-1

Addr:N23:0
RUNG DESCRIPTION:
THE NEXT TWO RUNGS ECHO THE OIT PUSHBUTTON UNLATCHES BACK TO THE OSC

Addr:0:006/10
TITLE:SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167A, Y-88.1

Addr:0:006/12
TITLE:SEQUENCING FOR VENT VALVE SOV-3168A, Y-81.3

Addr:0:006/14
TITLE:SEQUENCING FOR VENT VALVE SOV-3168B, Y-81.4

Addr:0:007/00
TITLE:SEQUENCING FOR VENT VALVE SOV-3185B, Y-81.2

Addr:0:007/03
TITLE:SEQUENCING FOR SUMP PUMP P-3115 OUTLET VALVE SOV-3167B, Y-88.2

Addr:02:1
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING

Addr:Q3:0
TITLE:PROCESSOR FAULT ROUTINE PROGRAM FILE.
RUNG DESCRIPTION:
THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL OCCURE ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN, A PROCESSOR FAULT AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE COPIED INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.

Addr:RUNG008-0000
TITLE:MISCELLANEOUS INTERLOCK LOGIC, Y-82.1

Addr:T4:0
TITLE:MAINLINE PROGRAM INITIALIZATION JUMP
RUNG DESCRIPTION:

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
P.O. Box 28970
Spokane, WA 99228-8970
(509) 466-2656

APPENDIX C

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-3)

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00126

DB Form Report

Sorted By: Address

07:29:04 02/19/99

THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS BEEN UPDATED
ON POWERUP OR
ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS BEEN READ.
TIMER T4:0 IS
USED TO SET THIS TIME DELAY.

Addr:T4:1

RUNG DESCRIPTION:

THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

WINTelligent LOGIC 5 - Rockwell Software Inc.

Project Name : PLC4.X5

Time/Date : 07:03:04 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
WL5 - Table of Contents
Lockheed Martin Hanford Co.

HNF-2346, Rev. 1

07:03:05 02/19/99

Page	Rung	Description
1		Ladder Report
1	0	MAINLINE PROGRAM INITIALIZATION JUMP
2	2	GENERAL USE BITS AND TIMING FUNCTIONS
5	11	PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
7	0	PROCESSOR FAULT ROUTINE PROGRAM FILE
9	0	ANALOG INPUTS BLOCK TRANSFER SEQUENCING
13	7	PCU-4 OIT FILE
20	0	COMMUNICATION HANDLING SUBROUTINE
30	26	SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
35	0	SCHEME 3 241-A-B TO 241-SY-A LOGIC, Y-44.1
36	2	SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
42	18	SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3
48	34	SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1
53	47	SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1
58	60	LEAK DETECTION LOGIC, Y-72
59	64	BOOSTER PUMP INTERLOCK, Y-78
61		DT Form Report
61		DB Form Report Sorted By: Address

APPENDIX D

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-4)
 MAINLINE PROGRAM INITIALIZATION JUMP
 Lockheed Martin Hanford Co.
 Page:00001

File #2 Proj:PLC4

07:03:05 02/19/99

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
 P.O. Box 28970
 Spokane, WA 99228-8970
 (509) 466-2656

*THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
 *THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS
 *BEEN UPDATED ON POWERUP OR
 *ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS
 *BEEN READ. TIMER T4:0 IS
 *USED TO SET THIS TIME DELAY.

First scan
 of ladder
 or SFC
 step

POWER-UP
 SEQUENCING
 DELAY

S:1/15

2:0000		+--TOF--+		Timer Off Delay		-(EN)-	
		Timer:		T4:0			
		Base (SEC):		0.01		-(DN)	
		Preset:		20			
		Accum:		20			

T4:0.DN - 0,1,14

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

T4:0.DN

2:0001		Q2:0		-[JMP]-	

Q2:0 - 1,11

APPENDIX D

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-4)
 GENERAL USE BITS AND TIMING FUNCTIONS
 Lockheed Martin Hanford Co.
 Page:00002

File #2 Proj:PLC4

07:03:06 02/19/99

.....
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF
 .....

ALWAYS OFF ALWAYS OFF
 OUTPUT OUTPUT
 ALWAYS OFF ALWAYS OFF
 B3/0 B3/0

ALWAYS OFF
 OUTPUT
 ALWAYS OFF
 B3/0
 ( )

2:0002

B3/0 - 2,2, /2,6, [5]3, [6],39,41,44,47

.....
 *THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON
 .....

ALWAYS ON
 OUTPUT
 ALWAYS ON
 B3/1
 ( )

2:0003

B3/1 - 3

.....
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED
 *ONCE EVERY SECOND.
 .....

REAL TIME
 CLOCK ONE SECOND
 SECOND RISING
 ONE'S BIT ONE SHOT

ONE SECOND
 SINGLE SCAN
 PULSE
 1_SEC PULSE
 B3/2
 ( )

2:0004

S:23/0 B3/32
 -| |-----[ONS]-----

REAL TIME
 CLOCK ONE SECOND
 SECOND FALLING
 ONE'S BIT ONE SHOT

S:23/0 B3/33
 -| |-----[ONS]-----

B3/2 - 4,7, [5],5,26

.....
 *THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE
 *EXECUTED ONCE EVERY TWO
 *SECONDS.
 .....

REAL TIME
 CLOCK TWO SECOND
 SECOND RISING
 TWO'S BIT ONE SHOT

TWO SECOND
 SINGLE SCAN
 PULSE
 2_SEC PULSE
 B3/3
 ( )

2:0005

S:23/1 B3/34
 -| |-----[ONS]-----

REAL TIME
 CLOCK TWO SECOND
 SECOND FALLING
 TWO'S BIT ONE SHOT

S:23/1 B3/35
 -| |-----[ONS]-----

B3/3 - 5,6,6

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 GENERAL USE BITS AND TIMING FUNCTIONS
 Lockheed Martin Hanford Co.
 Page:00003

HNF-2346, Rev. 1

07:03:06 02/19/99

File #2 Proj:PLC4

*THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM
 *B3/16 TO B3/31 WILL BE
 *SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF
 *A ONE IS LOADED INTO
 *B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE
 *BITS CAN BE USED TO DIVIDE
 *PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS.
 *THE PLC PROGRAM SCAN
 *TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

*THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

*****
 *THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT
 *DEVICES.
 *****

HALF SECOND
 FLASHER TIMER

HALF SECOND
 FLASHER
 HALF_SEC FLASH
 B3/4

T4:1.DN

2:0008

B3/4 - 8

*****
 *THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT
 *DEVICES.
 *****

REAL TIME
 CLOCK
 SECOND
 ONE'S BIT

ONE SECOND
 FLASHER
 1_SEC FLASH
 B3/5

S:23/0

2:0009

B3/5 - 9

*****
 *THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT
 *DEVICES.
 *****

REAL TIME
 CLOCK
 SECOND
 TWO'S BIT

TWO SECOND
 FLASHER
 2_SEC FLASH
 B3/6

S:23/1

2:0010

B3/6 - 10

*THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

PROGRAM FILE
 JUMP-TO-SUBR.
 CONTROL RUNGS
 COMMENT COIL

2:0011 Q2:0 [LBL] B3/36 - 11 ( )

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

2:0012 +--JSR--
 |Jump To Subroutine|
 |File #: U:4|

U:4 - 12,[4]0

DATA HIGHWAY +
 CTRL & CHECK
 COMMUNICATION
 SUBROUTINE

2:0013 +--JSR--
 |Jump To Subroutine|
 |File #: U:5|

U:5 - 13,[5]0

*THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO END

2:0014 T4:0.DN Q2:1 [JMP]

Q2:1 - 14,16

GENERAL FILE
 SUBROUTINE

2:0015 +--JSR--
 |Jump To Subroutine|
 |File #: U:6|

U:6 - 15,[6]0

*THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

APPENDIX D

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-4)
PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
Lockheed Martin Hanford Co.
Page:00006

File #2 Proj:PLC4

07:03:07 02/19/99

	MAIN PROGRAM		MCP FILE #2
	FILE START-UP		END OF PROGRAM
	JUMP TO END		COMMENT COIL
2:0016	02:1		B3/37
	[LBL]		( )
	B3/37	- 16	
2:0017			[End]

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
PROCESSOR FAULT ROUTINE PROGRAM FILE.
Lockheed Martin Hanford Co.
Page:00007

HNF-2346, Rev. 1

File #3 Proj:PLC4

07:03:07 02/19/99

*****
*THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL OCCURE
*ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN.
*A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE
*COPIED
*INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.
*****

First scan
of ladder
or SFC
step

S:1/15

PROCESSOR
FAULT ROUTINE
JUMP TO END

3:0000

Q3:0
[JMP]

Q3:0 - [3]0,2

Logical Rack
Status Bits
For Racks 0-7

3:0001

+-BDT-----+
| Bit Field Distributor |
| Source: S:7 |
| Source Bit: 0 |
| Dest: N10:7 |
| Dest Bit: 0 |
| Length: 8 |
+-----+

Last
program
scan time
ladder &
SFC

+-COP-----+
| Copy File |
| Source: #S:8 |
| Dest: #N10:8 |
| Length: 16 |
+-----+

S:7 - [3]1
N10:7 - [3]1
N10:7 - [3]wf1
N10:7 - [3]wf1

PROCESSOR
FAULT ROUTINE
JUMP TO END

FAULT ROUTINE
FILE #3
END OF PROGRAM
COMMENT COIL

3:0002 Q3:0
-----[LBL]-----

B3/38
( )

B3/38 - [3]2

REGISTER FOR
VERIFYING
FAULT ROUTINE
FILE OPERATION

3:0003

+-ADD-----+
| Add |
| Source A: N10:0 |
| Source B: 18 |
| Dest: N10:0 |
| 1 |
| 18 |
+-----+

N10:0 - [3]3,3

APPENDIX D

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-4)

PROCESSOR FAULT ROUTINE PROGRAM FILE.

Lockheed Martin Hanford Co.

Page:00008

07:03:07 02/19/99

File #3 Proj:PLC4

N10:0 - [3]3,3

3:0004

--[End]--

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00009

HNF-2346, Rev. 1

File #4 Proj:PLC4

07:03:07 02/19/99

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

PROGRAM
 FILE #4 START
 OF SUBROUTINE
 COMMENT COIL

4:0000 +--SBR--+
 |Subroutine|

B3/39

( )

B3/39 - [4]0

ANALOG MODULE
 POWERED UP BUT
 NOT CONFIGURED

4:0001 N13:0/0 BT12:1.EN BT12:1.EN
 | | | |

+--BTW--+
 |Block Transfer Write|-(EN)-
 |Mod Type: 1771-IFE|
 |12 Bit Analog Input|-(DN)
 |Rack: 0|
 |Group: 0|
 |Module: 0|-(ER)
 |Control Block: BT12:1|
 |Data File: N13:20|
 |Length: 21|
 |Continuous: N|

BT12:1.EN - [4]1,/1,/1,/2
 N13:20 - [4]1,1

4:0002 BT12:0.EN BT12:1.EN
 | | | |

+--BTR--+
 |Block Transfer Read|-(EN)-
 |Mod Type: 1771-IFE|
 |12 Bit Analog Input|-(DN)
 |Rack: 0|
 |Group: 0|
 |Module: 0|-(ER)
 |Control Block: BT12:0|
 |Data File: N13:0|
 |Length: 12|
 |Continuous: N|

BT12:0.EN - [4]2,/2,3
 N13:0/1 - [4]1,2,2,8,9,10,11,12,13,14,15

4:0003 BT12:0.DN
 | |

DENSITY
 READING OF
 244-A SUMP
 DY-850

+--COP--+
 |Copy File|
 |Source: #N13:4|
 |Dest: #N20:0|
 |Length: 8|

f * - [4]wf2,3
 f * - [4]wf3,[5],5

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00010

HNF-2346, Rev. 1

File #4 Proj:PLC4

07:03:08 02/19/99

4:0004 BT12:2.EN BT12:3.EN
 ---|/|-----|/|-----

+-BTW-
 Block Transfer Write
 Mod Type: 1771-N
 High Resolution Analog I/O
 Rack: 0
 Group: 1
 Module: 0
 Control Block: BT12:3
 Data File: N13:85
 Length: 59
 Continuous: N
 - (EN)-
 - (DN)
 - (ER)

BT12:3.EN - [4]4, /4, /5
 N13:85 - [4]4,4

4:0005 BT12:2.EN BT12:3.EN
 ---|/|-----|/|-----

+-BTR-
 Block Transfer Read
 Mod Type: 1771-N
 High Resolution Analog I/O
 Rack: 0
 Group: 1
 Module: 0
 Control Block: BT12:2
 Data File: N13:57
 Length: 28
 Continuous: N
 - (EN)-
 - (DN)
 - (ER)

BT12:2.EN - [4]4, 5, /5, 6
 N13:57 - [4]5,5

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
ANALOG INPUTS BLOCK TRANSFER SEQUENCING
Lockheed Martin Hanford Co.
Page:00011

HNF-2346, Rev. 1

07:03:08 02/19/99

File #4 Proj:PLC4

4:0006

BT12:2.DN

LINE
WT-SLL-3150
TEMPERATURE
TI-841

+-DIV-+-
Div
Source A: N13:62 532
Source B: 10
Dest: N20:8 10
53

SPARE
THERMOCOUPLE
INPUT

+-DIV-+-
Div
Source A: N13:64 486
Source B: 10
Dest: N20:9 10
49

LINE
WT-SLL-3160
TEMPERATURE
TI-842

+-DIV-+-
Div
Source A: N13:66 25016
Source B: 10
Dest: N20:10 10
2502

SPARE
THERMOCOUPLE
INPUT

+-DIV-+-
Div
Source A: N13:68 25016
Source B: 10
Dest: N20:11 10
2502

SPARE
THERMOCOUPLE
INPUT

+-DIV-+-
Div
Source A: N13:70 25016
Source B: 10
Dest: N20:12 10
2502

SPARE
THERMOCOUPLE
INPUT

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 ANALOG INPUTS BLOCK TRANSFER SEQUENCING
 Lockheed Martin Hanford Co.
 Page:00012

HNF-2346, Rev. 1

File #4 Proj:PLC4

07:03:08 02/19/99

N13:62	-	4	wf5,6
N20:8	-	4	6,[5]5
N13:64	-	4	wf5,6
N20:9	-	4	6,[5]5
N13:66	-	4	wf5,6
N20:10	-	4	6,[5]5
N13:68	-	4	wf5,6
N20:11	-	4	6,[5]5
N13:70	-	4	wf5,6
N20:12	-	4	6,[5]5
N13:72	-	4	wf5,6
N20:13	-	4	6,[5]5
N13:74	-	4	wf5,6
N20:14	-	4	6,[5]5
N13:76	-	4	wf5,6
N20:15	-	4	6,[5]5

Div	
Source A:	N13:72
	25016
Source B:	10
	10
Dest:	N20:13
	2502

SPARE
 THERMOCOUPLE
 INPUT

--DIV--	
Div	
Source A:	N13:74
	25016
Source B:	10
	10
Dest:	N20:14
	2502

SPARE
 THERMOCOUPLE
 INPUT

--DIV--	
Div	
Source A:	N13:76
	25016
Source B:	10
	10
Dest:	N20:15
	2502

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

PCU-4 OIT FILE

Lockheed Martin Hanford Co.

Page:00013

File #4 Proj:PLC4

07:03:09 02/19/99

	ANALOG MODULE UNDERRANGE BITS REGISTER	ANALOG MODULE OVERRANGE BITS REGISTER	ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE
4:0007	+-EQU- Equal (A=B) Source A: N13:1 Source B: 205 0 0 +-EQU- Equal (A=B) Source A: N13:2 Source B: 0 0 0		B3/48 ( )
	B3/48	- [4]7,8,9,10,11,12,13,14,15	
4:0008	ANALOG MODULE CHAN. 1 DATA UNDERRANGE N13:1/0 - -	DENSITY READING OF 244-A SUMP DY-850R +-LIM- Limit Test (Circular) Low Lim: 11 Test: N13:4 10 High Lim: 9 9	PCU-4 INPUT ANALOG OVER OR UNDER RANGE ALARM DI-850 A N14:11/0 ( )
	ANALOG MODULE CHAN. 1 DATA OVERRANGE N13:2/0 - -		
	ONE OR MORE CHANNELS ARE UNDER OR OVER RANGE N13:0/1 - -	ANALOG MODULE INPUT CHANNEL UNDER OR OVER RANGE ALARMS NOT ACTIVE B3/48 - -	
	N14:11/0	- [4]8	

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 PCU-4 OIT FILE
 Lockheed Martin Hanford Co.
 Page:00014

HNF-2346, Rev. 1

07:03:09 02/19/99

File #4 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

PCU-4 OIT FILE

Lockheed Martin Hanford Co.

Page:00015

File #4 Proj:PLC4

07:03:09 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

PCU-4 OIT FILE

Lockheed Martin Hanford Co.

Page:00016

File #4 Proj:PLC4

07:03:09 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 PCU-4 OIT FILE
 Lockheed Martin Hanford Co.
 Page:00017

HNF-2346, Rev. 1

07:03:09 02/19/99

File #4 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

File #4 Proj:PLC4

PCU-4 OIT FILE
Lockheed Martin Hanford Co.
Page:00018

07:03:09 02/19/99

THERM. MODULE
CHAN. 3 DATA
UNDERRANGE

N13:65/0

4:0018

PCU-4 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
TE-842 A
N14:12/10
( )THERM. MODULE
CHAN. 3 DATA
OVERRANGE

N13:65/1

N14:12/10 - [4]18

THERM. MODULE
CHAN. 4 DATA
UNDERRANGE

N13:67/0

4:0019

PCU-4 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU4-SP-T1-4 A
N14:12/11
( )THERM. MODULE
CHAN. 4 DATA
OVERRANGE

N13:67/1

N14:12/11 - [4]19

THERM. MODULE
CHAN. 5 DATA
UNDERRANGE

N13:69/0

4:0020

PCU-4 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU4-SP-T1-5 A
N14:12/12
( )THERM. MODULE
CHAN. 5 DATA
OVERRANGE

N13:69/1

N14:12/12 - [4]20

THERM. MODULE
CHAN. 6 DATA
UNDERRANGE

N13:71/0

4:0021

PCU-4 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU4-SP-T1-6 A
N14:12/13
( )THERM. MODULE
CHAN. 6 DATA
OVERRANGE

N13:71/1

N14:12/13 - [4]21

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

PCU-4 OIT FILE

Lockheed Martin Hanford Co.

Page:00019

File #4 Proj:PLC4

07:03:10 02/19/99

THERM. MODULE
CHAN. 7 DATA
UNDERRANGE

N13:73/0

4:0022

PCU-4 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU4-SP-TI-7 A
N14:12/14
( )THERM. MODULE
CHAN. 7 DATA
OVERRANGE

N13:73/1

N14:12/14 - [4]22

THERM. MODULE
CHAN. 8 DATA
UNDERRANGE

N13:75/0

4:0023

PCU-4 INPUT
THERMOCOUPLE
OVER OR UNDER
RANGE ALARM
PCU4-SP-TI-8 A
N14:12/15
( )THERM. MODULE
CHAN. 8 DATA
OVERRANGE

N13:75/1

N14:12/15 - [4]23

I/O HANDLING
FOR ANALOG OR
OTHER REG IN
SUBROUTINE

4:0024

+--RET-----+
|Return () |
+-----+

4:0025

-----[End]-----

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00020

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:10 02/19/99

DATA HIGHWAY +
 CTRL & CHECK
 COMMUNICATION
 SUBROUTINE

PROGRAM
 FILE #5 START
 OF SUBROUTINE
 COMMENT COIL

5:0000 +--SBR-----+
 |Subroutine|-----+
 +-----+-----+

B3/40
 ( )-----

B3/40 - [5]0

*COMMUNICATION BETWEEN PCU-4 AND OCS

HEARTBEAT
 FROM OCS
 TO PLC-4
 HB OCS PLC4
 N14:120/0

HEARTBEAT
 FROM PLC-4
 TO OCS
 HB PLC4 OCS
 N14:070
 ( )-----

5:0001 | |-----+
 +-----+-----+

N14:0/0 - [5]1,2,/2

HEARTBEAT COMMUN.LOSS
 FROM PLC-4 WITH OCS
 TO OCS ONE SHOT
 HB PLC4 OCS

COMM LOSS
 TIMER
 WITH OCS

5:0002 N14:070 B3/200
 | |-----+
 +-----+-----+

+--TOF-----+
 |Timer Off Delay|-(EN)-
 |Timer: T4:40|
 |Base (SEC): 1.0|-(DN)-
 |Preset: 60|
 |Accum: 60|
 +-----+-----+

HEARTBEAT COMMUN.LOSS
 FROM PLC-4 WITH OCS
 TO OCS ONE SHOT
 HB PLC4 OCS

N14:070 B3/201

| |-----+
 +-----+-----+

T4:40.DN - [5]2,/3

ALWAYS OFF
 OUTPUT
 ALWAYS OFF

COMMUN. WITH
 OCS
 IGNORED
 COM-4 OCS
 N14:0/4
 ( )-----

5:0003 T4:40.DN B3/0
 | |-----+
 +-----+-----+

N14:0/4 - [5]3

Battery
 is bad or
 missing

PLC-4 BATTERY
 IS BAD OR
 MISSING
 BATT BAD PLC4
 N14:076
 ( )-----

5:0004 S:10/0
 | |-----+
 +-----+-----+

N14:0/6 - [5]4

File #5 COMM_FILE Proj:PLC4

ONE SECOND
SINGLE SCAN
PULSE
1_SEC PULSE
B372

5:0005

DIGITAL INPUT
REGISTER TO
OIT TERMINALS

```

+--MOV-----+
| Move |
| Source: 1:003 |
|           25129 |
| Dest:  N14:26 |
|           25129 |
+-----+

```

DIGITAL OUTPUT
REGISTER TO
OIT TERMINALS

```

+--MOV-----+
| Move |
| Source: 0:007 |
|           264 |
| Dest:  N14:29 |
|           264 |
+-----+

```

DENSITY
READING OF
244-A SUMP
DI-850

```

+--COP-----+
| Copy File |
| Source:  #N20:0 |
| Dest:    #N14:30 |
| Length:   16 |
+-----+

```

```

1:003/016 - [5]5,[6]6,/8,/10,/12,12,12,12,/12,12,12,12,/12,/22,/24,/26,/28,28,28,28,/28,28,28,28,/28,/38,
N14:26    - [5]5,30
0:007/012 - [5]5,[6]1,2,3,4,5,15,16,17,19,21,21,31,32,33,35,37,45,46,47,47,48,50,58,59,69
N14:29    - [5]5,30,30
N14:29    - [4]wf3,[5],5
N14:29    - [5]wf5,30

```

*COMMUNICATION BETWEEN PCU-4 AND PCU-1

HEARTBEAT
FROM PCU-1
TO PCU-4
HB-14
N19:1/4

5:0006

HEARTBEAT
FROM PCU-4
TO PCU-1
HB-41
N19:4/1
( )

N19:4/1 - [5]6,7,/7

HEARTBEAT COMMUN. LOSS
FROM PCU-4 WITH PCU-1
TO PCU-1 ONE SHOT
HB-41
N19:4/1 B376

5:0007

[ONS]

COMMUN. LOSS
TIMER
WITH PCU-1

```

+--TOF-----+
| Timer Off Delay |-(EN)-
| Timer:  T4:15 |
| Base (SEC): 1.0 |-(DN)-
| Preset:    10 |
| Accum:     0 |
+-----+

```

HEARTBEAT COMMUN. LOSS
FROM PCU-4 WITH PCU-1
TO PCU-1 ONE SHOT
HB-41
N19:4/1 B377

[ONS]

T4:15 DN - [5]7,/8

File #5 COMM_FILE Proj:PLC4

07:03:11 02/19/99

COMMUN. LOSS
TIMER
WITH PCU-1

T4:15.DN

5:0008

COMMUN. WITH
PCU-1
IGNORED
COM-41
N14:0/1
----- ( ) -----

N14:0/1 - [5]8, /9, /26, /27, /29, /30, /31

COMMUN. WITH
PCU-1

COM-41
N14:0/1

5:0009

R6:10.1N
---(U)---

COMPARE
PCU-4 TO PCU-1
MSG FILE
WITH PREVIOUS

MG11:0.EN

```

+-----+-----+
| File Search/Compare | (EN) |
| Control:             | R6:10 |
| Length:              | 20    | (DN) |
| Position:            | 0     |
| Mode:                | ALL   | (ER) |
| Expression:          |       |
| #N24:0 <> #N24:100 |       |
+-----+-----+

```

R6:10.FD

```

+---COP-----+
| Copy File
| Source:  #N24:0
| Dest:    #N24:200
| Length:  20

```

SEND MSG
FROM PCU-4
TO PCU-1

```

+---MSG-----+
+|Send/Receive Message|-(EN)-
|Control Block: MG11:0|-(DN)-
|                         |-(ER)-
+-----+

```

DH+ MESSAGE INSTRUCTION COMPARATIVE REGISTERS

MG11:O.DN B3/160
-----[ONS]

```

+---C0P-----
| Copy File
| Source:  #N24:200
| Dest:    #N24:100
| Length:  20

```

R6:10.IN	-	5	9,9,9,10,10,10,10
R6:10.IN	-	5	9,9,9,10,10,10,10
R6:10.IN	-	5	wf9,9
R6:10.IN	-	5	wf9,9
R6:10.IN	-	5	wf9,9
MG11:0.EN	-	5	9,9,9
MG11:0.EN	-	5	wf9,9
MG11:0.EN	-	5	wf9

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00023

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:11 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00024

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:11 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00025

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:12 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
COMMUNICATION HANDLING SUBROUTINE
Lockheed Martin Hanford Co.
Page:00026

HNF-2346, Rev. 1

07:03:12 02/19/99

File #5 COMM_FILE Proj:PLC4

5:0019

COMMUN. WITH
PCU-3
IGNORED
COM-43
N14:0/3

R6:12.IN

(U)

COMPARE
PCU-4 TO PCU-3
MSG FILE
WITH PREVIOUS

MG11:2.EN

---|/|---

+--FSC-----+
File Search/Compare |-(EN)
Control: R6:12
Length: 20 |-(DN)
Position: 0
Mode: ALL |-(ER)
Expression:
#N24:40 <> #N24:140

R6:12.FD

+---| |---

+--COP-----+
Copy File
Source: #N24:40
Dest: #N24:240
Length: 20

SEND MSG
FROM PCU-4
TO PCU-3

+--MSG-----+
Send/Receive Message |-(EN)
Control Block: MG11:2 |-(DN)
|-(ER)

DH+ MESSAGE
INSTRUCTION
COMPARATIVE
REGISTERS

MG11:2.DN B3/162

---| |---[ONS]---

+--COP-----+
Copy File
Source: #N24:240
Dest: #N24:140
Length: 20

R6:12.IN - [5]19,19,19,20,20,20,20
R6:12.IN - [5]19,19,19,20,20,20,20
R6:12.IN - [5]wf19,19
R6:12.IN - [5]wf19,19
R6:12.IN - [5]wf19,19
MG11:2.EN - [5]19,19,19
MG11:2.EN - [5]wf19,19
MG11:2.EN - [5]wf19

COMPARE
PCU-4 TO PCU-3
MSG FILE
WITH PREVIOUS

The diagram shows a timing sequence for R6:12. The total duration is 5.0020. The signals are as follows:

Signal	State / Label	Approximate Time Interval
R6:12.DN	High	0 to 0.5
R6:12.DN	Low	0.5 to 4.5
R6:12.RES	High	4.5 to 5.0020
R6:12.FD	Low	0 to 0.5
R6:12.FD	High	0.5 to 4.5
R6:12.FD	Low	4.5 to 5.0020

```
R6:12.IN - {5}19,19,19,20,20,20,20
R6:12.IN - {5}19,19,19,20,20,20,20
```

*COMMUNICATION BETWEEN PCU-4 AND PCU-5

HEARTBEAT
FROM PCU-5
TO PCU-4
HB-54
N19:5/4

HEARTBEAT
FROM PCU-4
TO PCU-5
HB-45
N19:4/5

5:0021 ---|/|----- ( )-----

N19:4/5 - [5]21,22,122

HEARTBEAT COMMUN. LOSS
FROM PCU-4 WITH PCU-5
TO PCU-5 ONE SHOT
HB-45
N19:4/5 B3/82

COMMUN. LOSS
TIMER
WITH PCU-5

```

5:0022 +-----+ [ONS] -----+-----+ Timer Off Delay |-(EN)-

```

HEARTBEAT	COMMUN. LOSS
FROM PCU-4	WITH PCU-5
TO PCU-5	ONE SHOT
HB-45	
N19:4/5	B3/83

```

+-----TOF-----+
-|Timer Off Delay|- (EN)-
-|Timer:          T4:18|
-|Base (SEC):     1.0|- (DN)
-|Preset:         5|
-|Accum:          0|

```

T4:18.DN - [5]22./23

COMMUN. LOSS
TIMER
WITH PCU-5

COMMUN. WITH
PCU-5
IGNORED
COM-45
N14:0/5

5:0023 | 14:18:DN | N14:079 | ( )

N14:0/5 - [5]23, /24

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00029

HNH-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:14 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.
 Page:00030

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:14 02/19/99

5:0026 COMMUN. WITH ONE SECOND
 PCU-1 SINGLE SCAN
 IGNORED PULSE
 COM-41 1_SEC PULSE
 N14:0/1 B372
 -|/| -| |

f+ - [5]wf26,29
 f+ - [5]wf26,27,29

+-COP-
 Copy File
 Source: #N14:120
 Dest: #N14:190
 Length: 1

5:0027 COMMUN. WITH
 PCU-1
 IGNORED
 COM-41
 N14:0/1
 -|/|

R6:15.IN
 (U)

MG11:5.EN

+-FSC-
 File Search/Compare
 Control: R6:15
 Length: 1
 Position: 0
 Mode: ALL
 Expression:
 #N14:190 <> #N21:0
 -(EN)
 -(DN)
 -(ER)

R6:15.FD

+-COP-
 Copy File
 Source: #N14:190
 Dest: #N21:20
 Length: 1

+-MSG-
 Send/Receive Message
 Control Block: MG11:5
 -(EN)
 -(DN)
 -(ER)

MG11:5.DN B3/165

+-COP-
 Copy File
 Source: #N21:20
 Dest: #N21:0
 Length: 1
 [ONS]

R6:15.IN - [5]27,27,27,28,28,28,28
 R6:15.IN - [5]27,27,27,28,28,28,28
 R6:15.IN - [5]wf26,27,29
 R6:15.IN - [5]wf26,27,29
 R6:15.IN - [5]wf27,27

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.
 Page:00031

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:14 02/19/99

MG11:5.EN - [5]27,27, /27
 MG11:5.EN - [5]wf27,27
 MG11:5.EN - [5]wf27

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
Lockheed Martin Hanford Co.
Page:00032

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC4

07:03:14 02/19/99

COMMUN. WITH
PCU-1
IGNORED
COM-41
N14:0/1
--|/|

5:0030

+--COP-----+
| Copy File |
| Source: #N14:0 |
| Dest: #N14:90 |
| Length: 2 |
+-----+

+--COP-----+
| Copy File |
| Source: #N14:11 |
| Dest: #N14:92 |
| Length: 2 |
+-----+

+--MOV-----+
| Move |
| Source: N14:26 |
| 25129 |
| Dest: N14:94 |
| 25129 |
+-----+

+--COP-----+
| Copy File |
| Source: #N14:29 |
| Dest: #N14:95 |
| Length: 17 |
+-----+

f - [5]wf30
f - [5]wf30,31,31
f - [5]wf30
f - [5]wf30,31,31
N14:26 - [5]15,30
N14:94 - [5]30,31,31
N14:94 - [5]wf30
N14:94 - [5]wf30,31,31

File #5 COMM_FILE Proj:PLC4

5:0031

COMMUN. WITH
 PCU-1
 IGNORED
 COM-41
 N14:0/1

R6:14.IN

(U)

MG11:6.EN

```

+--FSC-----+
|File Search/Compare|-(EN)-----+
|Control:   R6:14   |
|Length:    22      |-(DN)-----+
|Position:   0      |
|Mode:      ALL     |-(ER)-----+
|Expression:  #N14:90 <> #N21:100|
+-----+
  
```

R6:14.FD

```

+--COP-----+
|Copy File|
|Source:  #N14:90|
|Dest:   #N21:150|
|Length:   22    |
+-----+
  
```

```

+--MSG-----+
|Send/Receive Message|-(EN)---+
|Control Block: MG11:6|-(DN)---+
|                     |-(ER)---+
+-----+
  
```

MG11:6.DN B3/164

```

+--COP-----+
|Copy File|
|Source:  #N21:150|
|Dest:   #N21:100|
|Length:   22    |
+-----+
  
```

```

R6:14.IN - [5]31,31,31,32,32,32,32
R6:14.IN - [5]31,31,31,32,32,32,32
R6:14.IN - [5]wf30,31,31
R6:14.IN - [5]wf30,31,31
R6:14.IN - [5]wf31,31
MG11:6.EN - [5]31,31,/31
MG11:6.EN - [5]wf31,31
MG11:6.EN - [5]wf31
  
```

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1
Lockheed Martin Hanford Co.
Page:00034

HNF-2346, Rev. 1

07:03:15 02/19/99

File #5 COMM_FILE Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SCHEME 3 241-A-B TO 241-SY-A LOGIC, Y-44.1
Lockheed Martin Hanford Co.
Page:00035

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:15 02/19/99

	GENERAL FILE	PROGRAM
	SUBROUTINE	FILE #6 START
		OF SUBROUTINE
		COMMENT COIL
6:0000	+--SBR-----+	B3/41
	Subroutine	( )
	+-----+	
	B3/41 - [6]0	
	TRANSFER 3	START PERM.
	INITIATED	CONTACT FOR
		200-E TRANSF.
	Y-44.1	PUMP
		Y-44.1
		P-200E
6:0001	N19:3/13	0:007/12
	-----	( )
		771-0D16
	0:007/012 - [6]1	

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
 Lockheed Martin Hanford Co.
 Page:00036

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:16 02/19/99

	OCS MOVE VALVE MOV-843 TO POSITION 1	TRANSFER 1 INITIATED	TRANSFER 3 INITIATED	OCS MOVE VALVE MOV-843 TO POSITION 2	OCS MOVE VALVE MOV-843 TO POSITION 3	MOVE VALVE 843 TO POSITION 1 [A >> B]
	Y71 HS-843-1 N14:120/6	Y-41.1 N19:3/10	Y-44.1 N19:3/13	Y71 HS-843-2 N14:120/7	Y71 HS-843-3 N14:120/8	Y71 MOV-843-1F 0:007/02 771-0016
6:0002	MOVE VALVE 843 TO POSITION 1 [A >> B] Y71 MOV-843-1F 0:007/02 1771-001					
	0:007/002 - [6]2,15,69					
	OCS MOVE VALVE MOV-843 TO POSITION 2	OCS MOVE VALVE MOV-843 TO POSITION 1	OCS MOVE VALVE MOV-843 TO POSITION 3			MOVE VALVE MOV-843 TO POS. 2 BIT
	Y71 HS-843-2 N14:120/7	Y71 HS-843-1 N14:120/6	Y71 HS-843-3 N14:120/8			Y-71.2 B3/84
6:0003	MOVE VALVE MOV-843 TO POS. 2 BIT Y-71.2 B3/84					
	B3/84 - [6]2,3,4					
	MOVE VALVE MOV-843 TO POS. 2 BIT Y-71.2 B3/84					MOVE VALVE 843 TO POSITION 2 [A >> C] Y71 MOV-843-2F 0:007/03 771-0016
6:0004	TRANSFER 1 INITIATED Y-41.1 N19:3/10 TRANSFER 3 INITIATED Y-44.1 N19:3/13					
	0:007/003 - [6]4,16					

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
 Lockheed Martin Hanford Co.
 Page:00037

HNF-2346, Rev. 1

07:03:16 02/19/99

File #6 Proj:PLC4

	OCS MOVE VALVE MOV-843 TO POSITION 3	TRANSFER 1 INITIATED	TRANSFER 3 INITIATED	OCS MOVE VALVE MOV-843 TO POSITION 1	OCS MOVE VALVE MOV-843 TO POSITION 2	MOVE VALVE 843 TO POSITION 3 [B >> C]
	Y71 HS-843-3 N14:120/8	Y-41.1 N19:3/10	Y-44.1 N19:3/13	Y71 HS-843-1 N14:120/6	Y71 HS-843-2 N14:120/7	Y71 MOV-843-3F 0:007/04 771-0D16
6:0005	----- -----					
	MOVE VALVE 843 TO POSITION 3 [B >> C]					
	Y71 MOV-843-3F 0:007/04 1771-0D1					
	----- -----					
	0:007/004 - [6]3,5,17					
	OCS MOVE VALVE MOV-843 TO POSITION 1	MOV-843 IS IN POSITION 1 [A >> B]				MOV-843 VALVE FAILED TO POS.1 DELAY Y71
	Y71 HS-843-1 N14:120/6	Y71 ZS-843-1 1:003/02				
6:0006	----- -----					
	MOV-843 VALVE FAILED TO POS.1 DELAY Y71	1771-18D				TON- Timer On Delay (EN) Timer: T4:3 Base (SEC): 1.0 (DN) Preset: 10 Accum: 0
	T4:3.EN					
	----- -----					
	T4:3.EN - [6]6,6,7					
	MOV-843 VALVE FAILED TO POS.1 DELAY COMPLETE Y71					VALVE FAILED TO REACH POS. 1 Y71.2 ZA-843-1 N14:1/0
6:0007	----- -----					
	T4:3.DN					( )
	N14:1/0 - [6]7,14					

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
 Lockheed Martin Hanford Co.
 Page:00038

HNF-2346, Rev. 1

07:03:16 02/19/99

File #6 Proj:PLC4

6:0008	OCS MOVE VALVE MOV-843 TO POSITION 2	MOV-843 IS IN POSITION 2 [A >> C]	MOV-843 VALVE FAILED TO POS.2 DELAY Y71
	Y71 HS-843-2 N14:120/7	Y71 ZS-843-2 I:003/03	<pre> +--TON-----+ Timer On Delay -(EN)- Timer: T4:2 Base (SEC): 1.0 -(DN)- Preset: 10 Accum: 0 +-----+ </pre>
	TRANSFER 1 INITIATED	1771-IBD	
	Y-41.1		
	N19:3/10		
	TRANSFER 3 INITIATED		
	Y-44.1		
	N19:3/13		
	MOV-843 VALVE FAILED TO POS.2		
	T4:2.EN		
	T4:2.EN - [6]8,8,9		
	MOV-843 VALVE FAILED TO POS.2 DELAY COMPLETE Y71		VALVE FAILED TO REACH POS. 2
6:0009	T4:2.DN		Y71.2 ZA-843-2 N14:1/1 ( )
	N14:1/1 - [6]9,14		
	OCS MOVE VALVE MOV-843 TO POSITION 3	MOV-843 IS IN POSITION 3 [B >> C]	MOV-843 VALVE FAILED TO POS.3 DELAY Y71
	Y71 HS-843-3 N14:120/8	Y71 ZS-843-3 I:003/04	
6:0010	TRANSFER 1 INITIATED	1771-IBD	<pre> +--TON-----+ Timer On Delay -(EN)- Timer: T4:4 Base (SEC): 1.0 -(DN)- Preset: 10 Accum: 0 +-----+ </pre>
	MOV-843 VALVE FAILED TO POS.3		
	T4:4.EN		
	T4:4.EN - [6]10,10,11		
	MOV-843 VALVE FAILED TO POS.3 DELAY COMPLETE Y71		VALVE FAILED TO REACH POS. 3
6:0011	T4:4.DN		Y71.2 ZA-843-3 N14:1/2 ( )
	N14:1/2 - [6]11,14		

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
 Lockheed Martin Hanford Co.
 Page:00039

HNF-2346, Rev. 1

07:03:16 02/19/99

File #6 Proj:PLC4

6:0012

MOV-843 IS
 IN POSITION 1
 [A >> B]

Y71

ZS-843-1
 I:003/02

MOV-843 IS
 IN POSITION 2
 [A >> C]

Y71

ZS-843-2
 I:003/03

1771-IBD

1771-IBD

MOV-843 IS
 IN POSITION 1
 [A >> B]

MOV-843 IS
 IN POSITION 3
 [B >> C]

Y71

Y71

ZS-843-1
 I:003/02

ZS-843-3
 I:003/04

1771-IBD

1771-IBD

MOV-843 IS
 IN POSITION 2
 [A >> C]

MOV-843 IS
 IN POSITION 3
 [B >> C]

Y71

Y71

ZS-843-2
 I:003/03

ZS-843-3
 I:003/04

1771-IBD

1771-IBD

MOV-843 IS
 IN POSITION 1
 [A >> B]

MOV-843 IS
 IN POSITION 2
 [A >> C]

MOV-843 IS
 IN POSITION 3
 [B >> C]

Y71

Y71

Y71

ZS-843-1
 I:003/02

ZS-843-2
 I:003/03

ZS-843-3
 I:003/04

1771-IBD

1771-IBD

1771-IBD

T4:19.DN - [6]12,13

MOV-843
 VALVE POSIT.
 SWITH FAIL.
 DELAY COMPL.

T4:19.DN

VALVE
 POSITION
 SWITCH FAILURE

Y71.2

ZA-843
 N14:1/3

6:0013

N14:1/3 - [6]13,14

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
 Lockheed Martin Hanford Co.
 Page:00040

HNF-2346, Rev. 1

07:03:16 02/19/99

File #6 Proj:PLC4

6:0014	VALVE FAILED TO REACH POS. 1	Y71.2 ZA-843-1 N14:1/0	MOV-843 VALVE FAILURE	Y71	N19:4/7
	VALVE FAILED TO REACH POS. 2	Y71.2 ZA-843-2 N14:1/1			
	VALVE FAILED TO REACH POS. 3	Y71.2 ZA-843-3 N14:1/2			
	VALVE POSITION SWITCH FAILURE	Y71.2 ZA-843 N14:1/3			
N19:4/7 - [6]14	OCS MOVE VALVE MOV-843 TO POSITION 1	MOVE VALVE 843 TO POSITION 1 [A >> B]	OCS MOVE VALVE MOV-843 TO POSITION 1		
6:0015	Y71 HS-843-1 N14:120/6	Y71 MOV-843-1F 0:007/02	Y71 HS-843-1 N14:120/6	(U)	
	1771-001 OCS MOVE VALVE MOV-843 TO POSITION 2				
	Y71 HS-843-2 N14:120/7				
	OCS MOVE VALVE MOV-843 TO POSITION 3				
	Y71 HS-843-3 N14:120/8				
	TRANSFER 1 INITIATED				
	Y-41.1 N19:3/10				
	TRANSFER 3 INITIATED				
	Y-44.1 N19:3/13				

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2
 Lockheed Martin Hanford Co.
 Page:00041

HNF-2346, Rev. 1

07:03:16 02/19/99

File #6 Proj:PLC4

6:0016	N14:120/6 - [6]2,/3,/5,6,15,15,16,17 OCS MOVE VALVE MOV-843 TO POSITION 2 MOVE VALVE 843 TO POSITION 2 [A >> C] OCS MOVE VALVE MOV-843 TO POSITION 2 Y71 HS-843-2 N14:120/7 Y71 MOV-843-2F 0:007/03 Y71 HS-843-2 N14:120/7 (U)
6:0017	N14:120/7 - [6]2,3,/5,8,15,16,16,17 OCS MOVE VALVE MOV-843 TO POSITION 3 MOVE VALVE 843 TO POSITION 3 [B >> C] OCS MOVE VALVE MOV-843 TO POSITION 3 Y71 HS-843-3 N14:120/8 Y71 MOV-843-3F 0:007/04 Y71 HS-843-3 N14:120/8 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 1 MOVE VALVE 843 TO POSITION 1 [A >> C] OCS MOVE VALVE MOV-843 TO POSITION 1 Y71 HS-843-1 N14:120/6 Y71 MOV-843-1F 0:007/03 Y71 HS-843-1 N14:120/6 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 2 MOVE VALVE 843 TO POSITION 2 [B >> C] OCS MOVE VALVE MOV-843 TO POSITION 2 Y71 HS-843-2 N14:120/7 Y71 MOV-843-2F 0:007/03 Y71 HS-843-2 N14:120/7 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 3 MOVE VALVE 843 TO POSITION 3 [B >> C] OCS MOVE VALVE MOV-843 TO POSITION 3 Y71 HS-843-3 N14:120/8 Y71 MOV-843-3F 0:007/04 Y71 HS-843-3 N14:120/8 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 1 MOVE VALVE 843 TO POSITION 1 [A >> C] OCS MOVE VALVE MOV-843 TO POSITION 1 Y71 HS-843-1 N14:120/6 Y71 MOV-843-1F 0:007/03 Y71 HS-843-1 N14:120/6 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 2 MOVE VALVE 843 TO POSITION 2 [B >> C] OCS MOVE VALVE MOV-843 TO POSITION 2 Y71 HS-843-2 N14:120/7 Y71 MOV-843-2F 0:007/03 Y71 HS-843-2 N14:120/7 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 3 MOVE VALVE 843 TO POSITION 3 [B >> C] OCS MOVE VALVE MOV-843 TO POSITION 3 Y71 HS-843-3 N14:120/8 Y71 MOV-843-3F 0:007/04 Y71 HS-843-3 N14:120/8 (U)
6:0017	N14:120/8 - [6]2,/3,5,10,15,16,17,17 OCS MOVE VALVE MOV-843 TO POSITION 1 MOVE VALVE 843 TO POSITION 1 [A >> C] OCS MOVE VALVE MOV-843 TO POSITION 1 Y71 HS-843-1 N14:120/6 Y71 MOV-843-1F 0:007/03 Y71 HS-843-1 N14:120/6 (U)

File #6 Proj:PLC4

07:03:16 02/19/99

Address	Operation	Source	Destination	Comments
6:0018	MOVE VALVE MOV-844 TO POS.1 BIT	HS-844-1 N14:120/11		
6:0019	TRANSFER 2A INITIATED			
6:0020	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-2 N14:120/12		
6:0021	TRANSFER 2B INITIATED			
6:0022	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-3 N14:120/13		
6:0023	TRANSFER 2C INITIATED			
6:0024	MOVE VALVE 843 TO POSITION 1 [A >> C]	HS-844-1 N14:120/11		
6:0025	TRANSFER 2A INITIATED			
6:0026	MOVE VALVE 844 TO POSITION 2 [A >> C]	HS-844-2 N14:120/12		
6:0027	TRANSFER 2B INITIATED			
6:0028	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0029	TRANSFER 2C INITIATED			
6:0030	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-1 N14:120/11		
6:0031	TRANSFER 2A INITIATED			
6:0032	MOVE VALVE 843 TO POSITION 1 [A >> C]	HS-844-2 N14:120/12		
6:0033	TRANSFER 2B INITIATED			
6:0034	MOVE VALVE 844 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0035	TRANSFER 2C INITIATED			
6:0036	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-1 N14:120/11		
6:0037	TRANSFER 2A INITIATED			
6:0038	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-2 N14:120/12		
6:0039	TRANSFER 2B INITIATED			
6:0040	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0041	TRANSFER 2C INITIATED			
6:0042	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-1 N14:120/11		
6:0043	TRANSFER 2A INITIATED			
6:0044	MOVE VALVE 843 TO POSITION 1 [A >> C]	HS-844-2 N14:120/12		
6:0045	TRANSFER 2B INITIATED			
6:0046	MOVE VALVE 844 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0047	TRANSFER 2C INITIATED			
6:0048	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-1 N14:120/11		
6:0049	TRANSFER 2A INITIATED			
6:0050	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-2 N14:120/12		
6:0051	TRANSFER 2B INITIATED			
6:0052	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0053	TRANSFER 2C INITIATED			
6:0054	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-1 N14:120/11		
6:0055	TRANSFER 2A INITIATED			
6:0056	MOVE VALVE 843 TO POSITION 1 [A >> C]	HS-844-2 N14:120/12		
6:0057	TRANSFER 2B INITIATED			
6:0058	MOVE VALVE 844 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0059	TRANSFER 2C INITIATED			
6:0060	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-1 N14:120/11		
6:0061	TRANSFER 2A INITIATED			
6:0062	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-2 N14:120/12		
6:0063	TRANSFER 2B INITIATED			
6:0064	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0065	TRANSFER 2C INITIATED			
6:0066	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-1 N14:120/11		
6:0067	TRANSFER 2A INITIATED			
6:0068	MOVE VALVE 843 TO POSITION 1 [A >> C]	HS-844-2 N14:120/12		
6:0069	TRANSFER 2B INITIATED			
6:0070	MOVE VALVE 844 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0071	TRANSFER 2C INITIATED			
6:0072	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-1 N14:120/11		
6:0073	TRANSFER 2A INITIATED			
6:0074	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-2 N14:120/12		
6:0075	TRANSFER 2B INITIATED			
6:0076	MOVE VALVE 843 TO POSITION 2 [A >> C]	HS-844-3 N14:120/13		
6:0077	TRANSFER 2C INITIATED			
6:0078	MOVE VALVE 844 TO POSITION 1 [A >> B]	HS-844-1 N14:120/11		

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3
 Lockheed Martin Hanford Co.
 Page:00043

HNF-2346, Rev. 1

07:03:17 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3
 Lockheed Martin Hanford Co.
 Page:00044

HNF-2346, Rev. 1

07:03:17 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3
 Lockheed Martin Hanford Co.
 Page:00045

HNF-2346, Rev. 1

07:03:17 02/19/99

File #6 Proj:PLC4

6:0028

MOV-844 IS   MOV-844 IS
 IN POSITION 1   IN POSITION 2
 [A >> B]   [A >> C]

Y71   Y71
 ZS-844-1   ZS-844-2
 I:003/05   I:003/06

1771-IBDON   1771-IBDOFF
 MOV-844 IS   MOV-844 IS
 IN POSITION 1   IN POSITION 3
 [A >> B]   [B >> C]

Y71   Y71
 ZS-844-1   ZS-844-3
 I:003/05   I:003/07

1771-IBDON   1771-IBDOFF
 MOV-844 IS   MOV-844 IS
 IN POSITION 2   IN POSITION 3
 [A >> C]   [B >> C]

Y71   Y71
 ZS-844-2   ZS-844-3
 I:003/06   I:003/07

1771-IBDOFF   1771-IBDOFF   MOV-844 IS
 MOV-844 IS   MOV-844 IS   IN POSITION 3
 IN POSITION 1   IN POSITION 2   [B >> C]
 [A >> B]   [A >> C]

Y71   Y71   Y71
 ZS-844-1   ZS-844-2   ZS-844-3
 I:003/05   I:003/06   I:003/07

1771-IBDON   1771-IBDOFF   1771-IBDOFF

T4:20.DN   - [6]28,29

MOV-844
 VALVE POSIT.
 SWITCH FAIL.
 DELAY COMPL.

T4:20.DN

6:0029

VALVE
 POSITION
 SWITCH FAILURE

Y71.3
 ZA-844
 N14:1/7

N14:1/7   - [6]29,30

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3
 Lockheed Martin Hanford Co.
 Page:00046

HNF-2346, Rev. 1

07:03:17 02/19/99

File #6 Proj:PLC4

OCS MOVE
 VALVE MOV-844
 TO POSITION 1

Y71
 HS-844-1
 N14:120/11
 (U)

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3
Lockheed Martin Hanford Co.
Page:00047

HNF-2346, Rev. 1

07:03:17 02/19/99

File #6 Proj:PLC4

N14:120/11 - [6]/18,/21,22,31,31,32,33,/47

OCS MOVE
VALVE MOV-844
TO POSITION 2

MOVE VALVE 843
TO POSITION 2
[A >> C]

OCS MOVE
VALVE MOV-844
TO POSITION 2

Y71
HS-844-2
N14:120/12

Y71
MOV-844-2F
0:007/10

Y71
HS-844-2
N14:120/12
(U)

6:0032

4771-001
OCS MOVE
VALVE MOV-844
TO POSITION 1

Y71
HS-844-1
N14:120/11

OCS MOVE
VALVE MOV-844
TO POSITION 3

Y71
HS-844-3
N14:120/13

TRANSFER 2A
INITIATED

Y-42.1

N19:3/11

TRANSFER 2B
INITIATED

Y-43.1

N19:3/12

N14:120/12 - [6]/18,/21,24,31,32,32,33,47

OCS MOVE
VALVE MOV-844
TO POSITION 3

MOVE VALVE 844
TO POSITION 3
[B >> C]

OCS MOVE
VALVE MOV-844
TO POSITION 3

Y71
HS-844-3
N14:120/13

Y71
MOV-844-3F
0:007/11

Y71
HS-844-3
N14:120/13
(U)

6:0033

4771-001
OCS MOVE
VALVE MOV-844
TO POSITION 1

Y71
HS-844-1
N14:120/11

OCS MOVE
VALVE MOV-844
TO POSITION 2

Y71
HS-844-2
N14:120/12

N14:120/13 - [6]/18,21,26,31,32,33,33,/47

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00048

HNF-2346, Rev. 1

07:03:17 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00049

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:18 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00050

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:18 02/19/99

	OCS OPEN VALVE MOV-845 Y71 HS-845-1 N14:120/14	MOV-845 IS OPEN Y71 ZSH-845 I:003/00		MOV-845 VALVE FAILED TO OPEN DELAY Y71
6:0040	--- --- --- ---	--- --- --- ---	--- --- --- ---	+---TON---+ Timer On Delay T4:12 Timer: T4:12 Base (SEC): 1.0 Preset: 5 Accum: 0
	TRANSFER 2A INITIATED	1771-IBDON		---(EN)--- Base (SEC): 1.0 Preset: 5 Accum: 0
	Y-42.1 N19:3/11			
	TRANSFER 2B INITIATED			
	Y-43.1 N19:3/12			
	T4:12.EN			
	T4:12.EN - [6]40,40,41			
	MOV-845 VALVE FAILED TO OPEN DELAY COMPLETE Y71	ALWAYS OFF OUTPUT ALWAYS OFF B3/D		VALVE FAILED TO OPEN
6:0041	T4:12.DN	--- --- --- ---		Y-71 ZA-845-1 N14:1/8 ---( )---
	N14:1/8 - [6]41,44			
	MOV-845 IS CLOSED	MOV-845 IS OPEN		MOV-845 VALVE POSITION SWITCH FAILURE DELAY Y71
	Y71 ZSL-845 I:003/01	Y71 ZSH-845 I:003/00		
6:0042	--- --- --- ---	--- --- --- ---	--- --- --- ---	+---TON---+ Timer On Delay T4:13 Timer: T4:13 Base (SEC): 1.0 Preset: 5 Accum: 0
	1771-IBDOFF MOV-845 IS CLOSED	1771-IBDON MOV-845 IS OPEN		---(EN)--- Base (SEC): 1.0 Preset: 5 Accum: 0
	Y71 ZSL-845 I:003/01	Y71 ZSH-845 I:003/00		
	1771-IBDOFF	1771-IBDON		
	T4:13.DN - [6]42,43			
	MOV-845 VALVE POSITION SWITCH FAILURE DELAY COMPLETE Y71			VALVE POSITION SWITCH FAILURE
6:0043	T4:13.DN	--- --- --- ---		Y-71 ZA-845 N14:1/10 ---( )---
	N14:1/10 - [6]43,44			

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1
Lockheed Martin Hanford Co.
Page:00051

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:18 02/19/99

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1
Lockheed Martin Hanford Co.
Page:00052

HNF-2346, Rev. 1

07:03:18 02/19/99

File #6 Proj:PLC4

6:0046

OCS CLOSE
VALVE
MOV-845

CLOSE VALVE
MOV-845

OCS CLOSE
VALVE
MOV-845

Y71
HS-845-2
N14:120/15

Y71
MOV-845-C
0:007/01

Y71
HS-845-2
N14:120/15
(U)

1771-001
OCS OPEN
VALVE
MOV-845

Y71
HS-845-1
N14:120/14

TRANSFER 2A
INITIATED

Y-42.1

N19:3/11

TRANSFER 2B
INITIATED

Y-43.1

N19:3/12

N14:120/15 - [6]/34,36,38,45,46,46

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00053

HNF-2346, Rev. 1

07:03:18 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00054

HNF-2346, Rev. 1

07:03:18 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00055

HNF-2346, Rev. 1

07:03:19 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1
 Lockheed Martin Hanford Co.
 Page:00056

HNF-2346, Rev. 1

07:03:19 02/19/99

File #6 Proj:PLC4

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1
Lockheed Martin Hanford Co.
Page:00057

HNF-2346, Rev. 1

07:03:19 02/19/99

File #6 Proj:PLC4

6:0059

OCS CLOSE
VALVE
MOV-846

CLOSE VALVE
MOV-846

OCS CLOSE
VALVE
MOV-846

Y71
HS-846-2
N14:120/10

Y71
MOV-846-C
0:007/06

Y71
HS-846-2
N14:120/10
(U)

1771-001
OCS OPEN
VALVE
MOV-846

Y71
HS-846-1
N14:120/9

TRANSFER 1
INITIATED

Y-41.1

N19:3/10

TRANSFER 3
INITIATED

Y-44.1

N19:3/13

N14:120/10 - [6]/47,49,51,58,59,59

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
LEAK DETECTION LOGIC, Y-72
Lockheed Martin Hanford Co.
Page:00058

HNF-2346, Rev. 1

07:03:19 02/19/99

File #6 Proj:PLC4

6:0060	244-A PUMP PIT LEAK DETECTION (OFF=ALARM) Y72 LDK-PP I:003/16 1771-1BD	LEAK DETECTED AT 244-A LIFT STATION SUMP Y-72.1 N19:4/13 ( )			
	N19:4/13 - [6]60				
6:0061	OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 HS-058E N14:120/4	OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 HS-058E N14:120/4 (U)			
	<table border="1"> <tr> <td> OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 YL-058E N14:0/12 </td> <td> 200-E MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 KMS-244A-1 I:003/14 1771-1BD </td> </tr> </table>	OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 YL-058E N14:0/12	200-E MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 KMS-244A-1 I:003/14 1771-1BD	<table border="1"> <tr> <td> OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 YL-058E N14:0/12 </td> </tr> </table>	OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 YL-058E N14:0/12
OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 YL-058E N14:0/12	200-E MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 KMS-244A-1 I:003/14 1771-1BD				
OVERRIDE OF 200-E MASTER SHUTDOWN Y-77.1 YL-058E N14:0/12					
	N14:120/4 - [6]61,61 N14:0/12 - [6]61,61,/62				
6:0062	200-E MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 KMS-244A-1 I:003/14 1771-1BD	200-E TANK FARM MASTER SHUTDOWN TIMER Y-77.1 +--TON--+ Timer On Delay T4:14 Timer: T4:14 Base (SEC): 1.0 Preset: 600 Accum: 0 +-----+			
	T4:14.DN - [6]62,63	+-(EN)- +-(DN)-			
6:0063	200-E TANK FARM MASTER SHUTDOWN TIMER Y-77.1 T4:14.DN	200-E MASTER SHUTDOWN CIRCUIT ACTIVATED Y-77.1 N19:4/11 ( )			
	N19:4/11 - [6]63				

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 BOOSTER PUMP INTERLOCK, Y-78
 Lockheed Martin Hanford Co.
 Page:00059

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:19 02/19/99

	ENCASUREMENT RUPTURE DISK ACTIVATED [OFF = ALARM] Y78 YAS-841 I:003/12	RUPTURE DISK FAILURE Y-78.1 N19:4/12
6:0064	1771-IBD ENCASUREMENT RUPTURE DISK ACTIVATED [OFF = ALARM] Y78 YAS-842 I:003/13	( )
	1771-IBD N19:4/12 - [6]64	
	RADIATION INDICATION FROM 296-A-25 STACK MONITOR RY-851	STACK 296-A-25 HIGH RADIATION RAH-851 N14:0/13
6:0065	+--GRT-----+ Greater Than (A>B) Source A: N20:2 -736 Source B: N7:0 2500	( )
	N14:0/13 - [6]65	
	FLOW INDICATION FROM 296-A-25 STACK MONITOR FY-851	STACK 296-A-25 LOW FLOW FAL-851 N14:0/14
6:0066	+--LES-----+ Less Than (A<B) Source A: N20:3 -75 Source B: N7:1 50	( )
	N14:0/14 - [6]66	
	SLURRY LINE PRESSURE PT-842	SLURRY LINE HIGH PRESSURE PAH-842 N14:0/15
6:0067	+--GRT-----+ Greater Than (A>B) Source A: N20:7 -75 Source B: N7:2 200	( )
	SLURRY LINE HIGH PRESSURE AT PCU-4 N19:4/6	( )
	N14:0/15 - [6]87	
	N19:4/6 - [6]67	
6:0068		+--RET-----+ Return ( )

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
BOOSTER PUMP INTERLOCK, Y-78
Lockheed Martin Hanford Co.
Page:00060

HNF-2346, Rev. 1

File #6 Proj:PLC4

07:03:19 02/19/99

6:0069

[End]

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00061

DB Form Report

Sorted By: Address

07:03:19 02/19/99

0:007		DIGITAL OUTPUT REGISTER			
0:007/000	MOV-845-0	OPEN VALVE	MOV-845		
0:007/001	MOV-845-C	CLOSE VALVE	MOV-845		Y71
0:007/002	MOV-843-1F	MOVE VALVE 843	TO POSITION 1	[A >> B]	Y71
0:007/003	MOV-843-2F	MOVE VALVE 843	TO POSITION 2	[A >> B]	Y71
0:007/004	MOV-843-3F	MOVE VALVE 843	TO POSITION 3	[B >> C]	Y71
0:007/005	MOV-846-0	OPEN VALVE	MOV-846		Y71
0:007/006	MOV-846-C	CLOSE VALVE	MOV-846		Y71
0:007/007	MOV-844-1F	MOVE VALVE 844	TO POSITION 1	[A >> B]	Y71
0:007/010	MOV-844-2F	MOVE VALVE 843	TO POSITION 2	[A >> C]	Y71
0:007/011	MOV-844-3F	MOVE VALVE 844	TO POSITION 3	[B >> C]	Y71
0:007/012	P-200E	START PERM.	CONTACT FOR	200-E TRANSF.	PUMP Y-44.1
0:007/014					
0:007/015					
0:007/016					
0:007/017					
1:003		DIGITAL INPUT REGISTER			
1:003/000	ZSH-845	MOV-845	IS OPEN		Y71
1:003/001	ZSL-845	MOV-845	IS CLOSED		Y71
1:003/002	ZS-843-1	MOV-843 IS	IN POSITION 1	[A >> B]	Y71
1:003/003	ZS-843-2	MOV-843 IS	IN POSITION 2	[A >> C]	Y71
1:003/004	ZS-843-3	MOV-843 IS	IN POSITION 3	[B >> C]	Y71
1:003/005	ZS-844-1	MOV-844 IS	IN POSITION 1	[A >> B]	Y71
1:003/006	ZS-844-2	MOV-844 IS	IN POSITION 2	[A >> B]	Y71
1:003/007	ZS-844-3	MOV-844 IS	IN POSITION 3	[B >> C]	Y71
1:003/010	ZSH-846	MOV-846	IS OPEN		Y71
1:003/011	ZSL-846	MOV-846	IS CLOSED		Y71
1:003/012	YAS-841	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM] Y78
1:003/013	YAS-842	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM] Y78
1:003/014	KMS-244A-1	200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED Y-77.1
1:003/015	RXA-EXH-1-2	RAD EQPT	FAILURE FROM	296-A-25 STACK	MONITOR (OFF=ALARM) (OFF=ALARM)
1:003/016	LDK-PP	241-A PUMP	PIT LEAK	DETECTION	Y72
1:003/017	WST-P-841	ON/OFF STATUS	FOR PUMP	P-841 (PUMP ON)	(OCS)
S:000/000		Processor	arithmetic	carry	flag
S:000/001		Processor	arithmetic	underflow	overflow flag
S:000/002		Processor	arithmetic	zero	flag
S:000/003		Processor	arithmetic	sign	flag
S:001/000		Bad RAM	CHECKSUM	at power	up
S:001/001		PLC-5 in	RUN mode		
S:001/002		PLC-5 in	TEST mode		
S:001/003		PLC-5 in	PROG mode		
S:001/004		PLC-5 is	burning an	EEPROM	
S:001/005		Download-	ing in	progress	
S:001/006		Test edits	enabled		
S:001/007		Mode	switch	In REMOTE	
S:001/008		Forces	enabled		
S:001/009		Forces	present		
S:001/010		EEPROM	success-	fully	Burned
S:001/011		Perform-	ing online	program-	ming
S:001/012		Processor	is in	DEBUG mode	
S:001/013		User	program	CHECKSUM	done
S:001/014		Last scan	of ladder	or SFC	step
S:001/015		First scan	of ladder	or SFC	step
S:007/000		Logical Rack	Status Bits	For Racks 0-7	
S:007/001		Rack 0	Faulted		
S:007/002		Rack 1	Faulted		
S:007/003		Rack 2	Faulted		
S:007/004		Rack 3	Faulted		
S:007/005		Rack 4	Faulted		
S:007/006		Rack 5	Faulted		
S:007/007		Rack 6	Faulted		
S:007/008		Rack 7	Faulted		
S:007/009		Block Xfer	queue to	rack 0 is	full
S:007/010		Block Xfer	queue to	rack 1 is	full
S:007/011		Block Xfer	queue to	rack 2 is	full
S:007/012		Block Xfer	queue to	rack 3 is	full
S:007/013		Block Xfer	queue to	rack 4 is	full
S:007/014		Block Xfer	queue to	rack 5 is	full
S:007/015		Block Xfer	queue to	rack 6 is	full
S:007/016		Block Xfer	queue to	rack 7 is	full
S:008		Last	program	scan time	ladder & SFC
S:009		Maximum	program	scan time	ladder & SFC
S:010/000		Battery	is bad or	missing	
S:010/001		DH+ active	node table	changed	
S:010/002		STI	overlap		
S:010/003		EEPROM	trans-	ferred	
S:010/004		Edits	prevent	SFC	continuing
S:010/005		Invalid	I/O status	file	
S:010/006		Memory	cartridge	battery	low

S:010/007	No more	command	blocks	exist	
S:010/009	No MCP was	configured	to run		
S:010/010	MCP not	allowed			
S:010/011	Pll word	number	isn't in	local rack	
S:010/012	User Pll	routine	overlap		
S:010/013	No command	block	exists to	get Pll	
S:010/014	Arithmetic	overflow	occurred		
S:010/015	SFC	lingering	action	overlap	
S:011/000	Bad	program	file		
S:011/001	Bad	address	in ladder	program	
S:011/002	Programmer	error			
S:011/003	SFC Fault				
S:011/004	Program	assembly	error		
S:011/005	Powerup	protection	fault		
S:011/006	Error not	defined			
S:011/007	User	generated	fault		
S:011/008	Watchdog	timer	fault		
S:011/009	Bad system	config-	uration		
S:011/010	Hardware	Error			
S:011/011	MCP file	does not	exist or	is not	ladder
S:011/012	Pll file	does not	exist or	is not	ladder
S:011/013	STl file	does not	exist or	is not	ladder
S:011/014	Fault file	does not	exist or	is not	ladder
S:011/015	Non ladder	file			
S:012	Fault Code				
S:013	Program	file where	fault	occurred	
S:014	Runq	number	where	fault	occurred
S:016	I/O status	file			
S:017/000	Queue full	between	local and	remote I/O	
S:017/001	Queue full	servicing	channel 1A		
S:017/002	Queue full	servicing	channel 1B		
S:017/003	Queue full	servicing	channel 2A		
S:017/004	Queue full	servicing	channel 2B		
S:017/005	No modem	on serial	port		
S:017/006	Remote I/O	is greater	than image	size	
S:017/008	ASCII	instruct-	ion error		
S:017/009	Duplicate	node	address		
S:018	Real time	clock YEAR			
S:019	Real time	clock	MONTH		
S:020	Real time	clock DAY			
S:021	Real time	clock HOUR			
S:022	Real time	clock	MINUTE		
S:023	Real time	clock	SECOND		
S:023/000	REAL TIME	CLOCK	SECOND	ONE'S BIT	
S:023/001	REAL TIME	CLOCK	SECOND	TWO'S BIT	
S:024	Indexed	Addressing	Offset		
S:025	Adapter	Image	File		
S:026/000	SFC	Restart/	Continue		
S:026/001	Start-up	protect-	ion after	power loss	
S:026/002	Local rack	is 1 if	set or 0	if bit = 0	
S:026/003	Complementary	Rack	Mode		
S:027/000	Rack 0	Inhibit			
S:027/001	Rack 1	Inhibit			
S:027/002	Rack 2	Inhibit			
S:027/003	Rack 3	Inhibit			
S:027/004	Rack 4	Inhibit			
S:027/005	Rack 5	Inhibit			
S:027/006	Rack 6	Inhibit			
S:027/007	Rack 7	Inhibit			
S:027/008	Rack 0	Reset			
S:027/009	Rack 1	Reset			
S:027/010	Rack 2	Reset			
S:027/011	Rack 3	Reset			
S:027/012	Rack 4	Reset			
S:027/013	Rack 5	Reset			
S:027/014	Rack 6	Reset			
S:027/015	Rack 7	Reset			
S:028	Watchdog	Timer	Setpoint		
S:029	Fault	routine	file	number	
S:030	STl	setpoint	(interval)		
S:031	STl	file	number		
S:032	Logical Rack	Status Bits	For Racks 10-17		
S:032/000	Rack 10	Faulted			
S:032/001	Rack 11	Faulted			
S:032/002	Rack 12	Faulted			
S:032/003	Rack 13	Faulted			
S:032/004	Rack 14	Faulted			
S:032/005	Rack 15	Faulted			
S:032/006	Rack 16	Faulted			

DB Form Report

Sorted By: Address

07:03:31 02/19/99

S:032/007	Rack 17	Faulted			
S:032/008	Block Xfer	queue to	rack 10 is	full	
S:032/009	Block Xfer	queue to	rack 11 is	full	
S:032/010	Block Xfer	queue to	rack 12 is	full	
S:032/011	Block Xfer	queue to	rack 13 is	full	
S:032/012	Block Xfer	queue to	rack 14 is	full	
S:032/013	Block Xfer	queue to	rack 15 is	full	
S:032/014	Block Xfer	queue to	rack 16 is	full	
S:032/015	Block Xfer	queue to	rack 17 is	full	
S:033/000	Rack 10	Inhibit			
S:033/001	Rack 11	Inhibit			
S:033/002	Rack 12	Inhibit			
S:033/003	Rack 13	Inhibit			
S:033/004	Rack 14	Inhibit			
S:033/005	Rack 15	Inhibit			
S:033/006	Rack 16	Inhibit			
S:033/007	Rack 17	Inhibit			
S:033/008	Rack 10	Reset			
S:033/009	Rack 11	Reset			
S:033/010	Rack 12	Reset			
S:033/011	Rack 13	Reset			
S:033/012	Rack 14	Reset			
S:033/013	Rack 15	Reset			
S:033/014	Rack 16	Reset			
S:033/015	Rack 17	Reset			
S:034/000	Rack 20	Faulted			
S:034/001	Rack 21	Faulted			
S:034/002	Rack 22	Faulted			
S:034/003	Rack 23	Faulted			
S:034/004	Rack 24	Faulted			
S:034/005	Rack 25	Faulted			
S:034/006	Rack 26	Faulted			
S:034/007	Block Xfer	queue to	rack 20 is	full	
S:034/008	Block Xfer	queue to	rack 21 is	full	
S:034/009	Block Xfer	queue to	rack 22 is	full	
S:034/010	Block Xfer	queue to	rack 23 is	full	
S:034/012	Block Xfer	queue to	rack 24 is	full	
S:034/013	Block Xfer	queue to	rack 25 is	full	
S:034/014	Block Xfer	queue to	rack 26 is	full	
S:034/015	Block Xfer	queue to	rack 27 is	full	
S:035/000	Rack 20	Inhibit			
S:035/001	Rack 21	Inhibit			
S:035/002	Rack 22	Inhibit			
S:035/003	Rack 23	Inhibit			
S:035/004	Rack 24	Inhibit			
S:035/005	Rack 25	Inhibit			
S:035/006	Rack 26	Inhibit			
S:035/007	Rack 27	Inhibit			
S:035/008	Rack 20	Reset			
S:035/009	Rack 21	Reset			
S:035/010	Rack 22	Reset			
S:035/011	Rack 23	Reset			
S:035/012	Rack 24	Reset			
S:035/013	Rack 25	Reset			
S:035/014	Rack 26	Reset			
S:035/015	Rack 27	Reset			
S:046	Pil	file	number		
S:047	Pil	module	group to	examine	
S:048	Pil bit	mask			
S:048/000	Pil Module	Bit	1=Monitor	0=Ignore	
S:049	Pil	compare	value		
S:049/000	Pil Bit	1=false to	TRUE	0=	true to
S:050	Pil down	count			
S:051	Pil return	mask			
S:052	Pil accum-	ulator			
S:053	STI last	scan time			
S:054	STI max	scan time			
S:055	Pil last	scan time			
S:056	Pil max	scan time			
S:079/000	Main	control	program A	disable	bit
S:079/001	Main	control	program B	disable	bit
S:079/002	Main	control	program C	disable	bit
S:079/003	Main	control	program D	disable	bit
S:079/004	Main	control	program E	disable	bit
S:079/005	Main	control	program F	disable	bit
S:079/006	Main	control	program G	disable	bit
S:079/007	Main	control	program H	disable	bit
S:079/008	Main	control	program I	disable	bit

DB Form Report Sorted By: Address

07:03:31 02/19/99

S:079/009	_____	Main	control	_____	program J	disable	_____	bit	_____
S:079/010	_____	Main	control	_____	program K	disable	_____	bit	_____
S:079/011	_____	Main	control	_____	program L	disable	_____	bit	_____
S:079/012	_____	Main	control	_____	program M	disable	_____	bit	_____
S:079/013	_____	Main	control	_____	program N	disable	_____	bit	_____
S:079/014	_____	Main	control	_____	program O	disable	_____	bit	_____
S:079/015	_____	Main	control	_____	program P	disable	_____	bit	_____
S:080	_____	Main	control	_____	program A	file	_____	number	_____
S:081	_____	Program A	scan time	_____	_____	_____	_____	_____	_____
S:082	_____	Program A	maximum	_____	scan time	_____	_____	_____	_____
S:083	_____	Main	control	_____	program B	file	_____	number	_____
S:084	_____	Program B	scan time	_____	_____	_____	_____	_____	_____
S:085	_____	Program B	maximum	_____	scan time	_____	_____	_____	_____
S:086	_____	Main	control	_____	program C	file	_____	number	_____
S:087	_____	Program C	scan time	_____	_____	_____	_____	_____	_____
S:088	_____	Program C	maximum	_____	scan time	_____	_____	_____	_____
S:089	_____	Main	control	_____	program D	file	_____	number	_____
S:090	_____	Program D	scan time	_____	_____	_____	_____	_____	_____
S:091	_____	Program D	maximum	_____	scan time	_____	_____	_____	_____
S:092	_____	Main	control	_____	program E	file	_____	number	_____
S:093	_____	Program E	scan time	_____	_____	_____	_____	_____	_____
S:094	_____	Program E	maximum	_____	scan time	_____	_____	_____	_____
S:095	_____	Main	control	_____	program F	file	_____	number	_____
S:096	_____	Program F	scan time	_____	_____	_____	_____	_____	_____
S:097	_____	Program F	maximum	_____	scan time	_____	_____	_____	_____
S:098	_____	Main	control	_____	program G	file	_____	number	_____
S:099	_____	Program G	scan time	_____	_____	_____	_____	_____	_____
S:100	_____	Program G	maximum	_____	scan time	_____	_____	_____	_____
S:101	_____	Main	control	_____	program H	file	_____	number	_____
S:102	_____	Program H	scan time	_____	_____	_____	_____	_____	_____
S:103	_____	Program H	maximum	_____	scan time	_____	_____	_____	_____
S:104	_____	Main	control	_____	program I	file	_____	number	_____
S:105	_____	Program I	scan time	_____	_____	_____	_____	_____	_____
S:106	_____	Program I	maximum	_____	scan time	_____	_____	_____	_____
S:107	_____	Main	control	_____	program J	file	_____	number	_____
S:108	_____	Program J	scan time	_____	_____	_____	_____	_____	_____
S:109	_____	Program J	maximum	_____	scan time	_____	_____	_____	_____
S:110	_____	Main	control	_____	program K	file	_____	number	_____
S:111	_____	Program K	scan time	_____	_____	_____	_____	_____	_____
S:112	_____	Program K	maximum	_____	scan time	_____	_____	_____	_____
S:113	_____	Main	control	_____	program L	file	_____	number	_____
S:114	_____	Program L	scan time	_____	_____	_____	_____	_____	_____
S:115	_____	Program L	maximum	_____	scan time	_____	_____	_____	_____
S:116	_____	Main	control	_____	program M	file	_____	number	_____
S:117	_____	Program M	scan time	_____	_____	_____	_____	_____	_____
S:118	_____	Program M	maximum	_____	scan time	_____	_____	_____	_____
S:119	_____	Main	control	_____	program N	file	_____	number	_____
S:120	_____	Program N	scan time	_____	_____	_____	_____	_____	_____
S:121	_____	Program N	maximum	_____	scan time	_____	_____	_____	_____
S:122	_____	Main	control	_____	program O	file	_____	number	_____
S:123	_____	Program O	scan time	_____	_____	_____	_____	_____	_____
S:124	_____	Program O	maximum	_____	scan time	_____	_____	_____	_____
S:125	_____	Main	control	_____	program P	file	_____	number	_____
S:126	_____	Program P	scan time	_____	_____	_____	_____	_____	_____
S:127	_____	Program P	maximum	_____	scan time	_____	_____	_____	_____
8003/000	ALWAYS OFF	ALWAYS OFF	OUTPUT	_____	_____	_____	_____	_____	_____
8003/001	ALWAYS ON	ALWAYS ON	OUTPUT	_____	_____	_____	_____	_____	_____
8003/002	1_SEC_PULSE	ONE SECOND	SINGLE SCAN	PULSE	_____	_____	_____	_____	_____
8003/003	2_SEC_PULSE	TWO SECOND	SINGLE SCAN	PULSE	_____	_____	_____	_____	_____
8003/004	HALF_SEC_FLASH	HALF SECOND	FLASHER	_____	_____	_____	_____	_____	_____
8003/005	1_SEC_FLASH	ONE SECOND	FLASHER	_____	_____	_____	_____	_____	_____
8003/006	2_SEC_FLASH	TWO SECOND	FLASHER	_____	_____	_____	_____	_____	_____
8003/007	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/008	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/009	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/010	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/011	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/012	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/013	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/014	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/015	_____	_____	_____	_____	_____	_____	_____	_____	_____
8003/001	_____	TWO SCAN SUB-	DIVISIONS	REGISTER	_____	_____	_____	_____	_____
8003/016	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIRST SET)	_____	_____	_____	_____
8003/017	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SECOND SET)	_____	_____	_____	_____
8003/018	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRD SET)	_____	_____	_____	_____
8003/019	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTH SET)	_____	_____	_____	_____
8003/020	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTH SET)	_____	_____	_____	_____
8003/021	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTH SET)	_____	_____	_____	_____
8003/022	_____	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SEVENTH SET)	_____	_____	_____	_____

DB Form Report

Sorted By: Address

BO03/023	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(EIGHTH SET)	
BO03/024	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(NINTH SET)	
BO03/025	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TENTH SET)	
BO03/026	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(ELEVENTH SET)	
BO03/027	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TWELFTH SET)	
BO03/028	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRTH'NTH SET)	
BO03/029	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTH'NTH SET)	
BO03/030	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTEENTH SET)	
BO03/031	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTEENTH SET)	
BO03/032	ONE SECOND	RISING	ONE SHOT		
BO03/033	ONE SECOND	FALLING	ONE SHOT		
BO03/034	TWO SECOND	RISING	ONE SHOT		
BO03/035	TWO SECOND	FALLING	ONE SHOT		
BO03/036	PROGRAM FILE	JUMP-TO-SUBR.	CONTROL RUNGS	COMMENT COIL	
BO03/037	MCP FILE #2	END OF PROGRAM	COMMENT COIL		
BO03/038	FAULT ROUTINE	FILE #3	END OF PROGRAM	COMMENT COIL	
BO03/039	PROGRAM	FILE #4 START	OF SUBROUTINE	COMMENT COIL	
BO03/040	PROGRAM	FILE #5 START	OF SUBROUTINE	COMMENT COIL	
BO03/041	PROGRAM	FILE #6 START	OF SUBROUTINE	COMMENT COIL	
BO03/042					
BO03/043					
BO03/044					
BO03/045					
BO03/046					
BO03/047					
BO03/048	ANALOG MODULE	INPUT CHANNEL	UNDER OR OVER	RANGE ALARMS	NOT ACTIVE
BO03/076	COMMUN. LOSS	WITH PCU-1	ONE SHOT		
BO03/077	COMMUN. LOSS	WITH PCU-1	ONE SHOT		
BO03/078	COMMUN. LOSS	WITH PCU-2	ONE SHOT		
BO03/079	COMMUN. LOSS	WITH PCU-2	ONE SHOT		
BO03/080	COMMUN. LOSS	WITH PCU-3	ONE SHOT		
BO03/081	COMMUN. LOSS	WITH PCU-3	ONE SHOT		
BO03/082	COMMUN. LOSS	WITH PCU-5	ONE SHOT		
BO03/083	COMMUN. LOSS	WITH PCU-5	ONE SHOT		
BO03/084	MOVE VALVE	MOV-843 TO	POS. 2 BIT		Y-71.2
BO03/085	MOVE VALVE	MOV-844 TO	POS. 1 BIT		Y-71.3
BO03/087	INTERNAL FIT	SCREEN BIT			
BO03/088	INTERNAL FIT	SCREEN BIT			
BO03/089	INTERNAL FIT	SCREEN BIT			
BO03/090	INTERNAL FIT	SCREEN BIT			
BO03/200	COMMUN. LOSS	WITH OCS	ONE SHOT		
BO03/201	COMMUN. LOSS	WITH OCS	ONE SHOT		
BO03/301	OPEN VALVE	MOV-845	BIT		
BO03/302	CLOSE VALVE	MOV-845	BIT		
BO03/303	OPEN VALVE	MOV-846	BIT		
BO03/304	CLOSE VALVE	MOV-846	BIT		
TO04:000	POWER-UP	SEQUENCING	DELAY		
TO04:000.ACC					
TO04:000.DN	POWER-UP	SEQUENCING	DELAY		
TO04:000.PRE					
TO04:000.TT					
TO04:001	HALF SECOND	FLASHER TIMER			
TO04:001.ACC					
TO04:001.DN	HALF SECOND	FLASHER TIMER			
TO04:001.PRE					
TO04:001.TT					
TO04:002	MOV-843	VALVE FAILED	TO POS. 2	DELAY	Y71
TO04:002.ACC					
TO04:002.DN	MOV-843	VALVE FAILED	TO POS. 2	DELAY COMPLETE	Y71
TO04:002.EN	MOV-843	VALVE FAILED	TO POS. 2		
TO04:002.PRE					
TO04:002.TT					
TO04:003	MOV-843	VALVE FAILED	TO POS. 1	DELAY	Y71
TO04:003.ACC					
TO04:003.DN	MOV-843	VALVE FAILED	TO POS. 1	DELAY COMPLETE	Y71
TO04:003.EN	MOV-843	VALVE FAILED	TO POS. 1	DELAY	Y71
TO04:003.PRE					
TO04:003.TT					
TO04:004	MOV-843	VALVE FAILED	TO POS. 3	DELAY	Y71
TO04:004.ACC					
TO04:004.DN	MOV-843	VALVE FAILED	TO POS. 3	DELAY COMPLETE	Y71
TO04:004.EN	MOV-843	VALVE FAILED	TO POS. 3		
TO04:004.PRE					
TO04:004.TT					
TO04:005	MOV-846	VALVE FAILED	TO CLOSE	DELAY	Y71
TO04:005.ACC					
TO04:005.DN	MOV-846	VALVE FAILED	TO CLOSE	DELAY COMPLETE	Y71
TO04:005.EN	MOV-846	VALVE FAILED	TO CLOSE	DELAY	Y71
TO04:005.PRE					

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00066

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

07:03:00 02/19/99

T004:005.TT					
T004:006	MOV-846	VALVE FAILED	TO OPEN	DELAY	Y71
T004:006.ACC	MOV-846	VALVE FAILED	TO OPEN	DELAY COMPLETE	Y71
T004:006.DN	MOV-846	VALVE FAILED	TO OPEN	DELAY	Y71
T004:006.EN					
T004:006.PRE					
T004:006.TT					
T004:007	MOV-846	VALVE POSITION	SWITCH FAILURE	DELAY	Y71
T004:007.ACC	MOV-846	VALVE FAILED	TO OPEN	DELAY COMPLETE	Y71
T004:007.DN					
T004:007.EN					
T004:007.PRE					
T004:007.TT					
T004:008	MOV-844	VALVE FAILED	TO POS.2	DELAY	Y71
T004:008.ACC	MOV-844	VALVE FAILED	TO POS.2	DELAY COMPLETE	Y71
T004:008.DN	MOV-844	VALVE FAILED	TO POS.2		
T004:008.EN					
T004:008.PRE					
T004:008.TT					
T004:009	MOV-844	VALVE FAILED	TO POS.1	DELAY	Y71
T004:009.ACC					
T004:009.DN	MOV-844	VALVE FAILED	TO POS.1	DELAY COMPLETE	Y71
T004:009.EN	MOV-844	VALVE FAILED	TO POS.1	DELAY	Y71
T004:009.PRE					
T004:009.TT					
T004:009DN					
T004:010	MOV-844	VALVE FAILED	TO POS.3	DELAY COMPLETE	Y71
T004:010.ACC					
T004:010.DN	MOV-844	VALVE FAILED	TO POS.3		
T004:010.EN					
T004:010.PRE					
T004:010.TT					
T004:011	MOV-845	VALVE FAILED	TO CLOSE	DELAY	Y71
T004:011.ACC	MOV-845	VALVE FAILED	TO CLOSE	DELAY COMPLETE	Y71
T004:011.DN					
T004:011.EN					
T004:011.PRE					
T004:011.TT					
T004:012	MOV-845	VALVE FAILED	TO OPEN	DELAY	Y71
T004:012.ACC					
T004:012.DN	MOV-845	VALVE FAILED	TO OPEN	DELAY COMPLETE	Y71
T004:012.EN					
T004:012.PRE					
T004:012.TT					
T004:013	MOV-845	VALVE POSITION	SWITCH FAILURE	DELAY	Y71
T004:013.ACC	MOV-845	VALVE POSITION	SWITCH FAILURE	DELAY COMPLETE	Y71
T004:013.DN					
T004:013.EN					
T004:013.PRE					
T004:013.TT					
T004:014	200-E TANK	FARM MASTER	SHUTDOWN	TIMER	Y-77.1
T004:014.ACC	200-E TANK	FARM MASTER	SHUTDOWN	TIMER	Y-77.1
T004:014.DN					
T004:014.EN					
T004:014.PRE					
T004:014.TT					
T004:015	COMMUN. LOSS	TIMER	WITH PCU-1		
T004:015.ACC	COMMUN. LOSS	TIMER	WITH PCU-1		
T004:015.DN					
T004:015.EN					
T004:015.PRE					
T004:015.TT					
T004:016	COMMUN. LOSS	TIMER	WITH PCU-2		
T004:016.ACC	COMMUN. LOSS	TIMER	WITH PCU-2		
T004:016.DN					
T004:016.EN					
T004:016.PRE					
T004:016.TT					
T004:017	COMMUN. LOSS	TIMER	WITH PCU-3		
T004:017.ACC					
T004:017.DN	COMMUN. LOSS	TIMER	WITH PCU-3		
T004:017.EN					
T004:017.PRE					
T004:017.TT					
T004:018	COMMUN. LOSS	TIMER	WITH PCU-5		
T004:018.ACC	COMMUN. LOSS	TIMER	WITH PCU-5		
T004:018.DN					
T004:018.EN					
T004:018.PRE					

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00067

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

07:03:01 02/19/99

TO04:018.TT					
TO04:019					
TO04:019.ACC		MOV-843	VALVE POSIT.	SWITCH FAIL.	DELAY
TO04:019.DN					Y-71.2
TO04:019.EN		MOV-843	VALVE POSIT.	SWITH FAIL.	DELAY COMPL.
TO04:019.PRE					
TO04:019.TT					
TO04:020		MOV-844	VALVE POSIT.	SWITH FAIL.	DELAY
TO04:020.ACC					Y-71.3
TO04:020.DN		MOV-844	VALVE POSIT.	SWITH FAIL.	DELAY COMPL.
TO04:020.EN					
TO04:020.PRE					
TO04:020.TT					
TO04:040					
RO06:000		COMM LOSS	TIMER	WITH OCS	
RO06:000.EN		TWO SCAN SUB-	DIVISIONS	CONTROL	REGISTER
RO06:000.UL		TWO SCAN SUB-	DIVISIONS	CONTROL	ENABLED
RO06:010		COMPARE	PCU-4 TO PCU-1	MSG FILE	UNLOAD
RO06:011		COMPARE	PCU-4 TO PCU-2	MSG FILE	WITH PREVIOUS
RO06:012		COMPARE	PCU-4 TO PCU-3	MSG FILE	WITH PREVIOUS
RO06:013		COMPARE	PCU-4 TO PCU-5	MSG FILE	WITH PREVIOUS
NO07:000		RADIATION	THRESHOLD	FROM 296-A-25	STACK MONITOR
NO07:001		FLOW	THRESHOLD	FROM 296-A-25	STACK MONITOR
NO07:002		SUPERNATE LINE	PRESSURE HIGH	THRESHOLD	
NO07:003					
NO07:004					
NO07:005					
NO07:006					
NO07:007					
NO07:008					
NO07:009					
NO10:000		REGISTER FOR	VERIFYING	FAULT ROUTINE	FILE OPERATION
NO10:007		Logical Rack	Fault Status	For Racks 0-7	And Racks 10-17
NO10:008		Last	program	scan time	ladder &
NO10:009		Maximum	program	scan time	ladder &
NO10:010/000		Battery	is bad or	missing	SFC
NO10:010/001		DH+ active	node table	changed	SFC
NO10:010/002		STI	overlap		
NO10:010/003		EEPROM	trans-	ferred	
NO10:010/004		Edits	prevent	SFC	continuing
NO10:010/005		Invalid	I/O status	file	
NO10:010/006		Memory	cartridge	battery	low
NO10:010/007		No more	command	blocks	exist
NO10:010/009		No MCP was	configured	to run	
NO10:010/010		MCP not	allowed		
NO10:010/011		Pil word	number	isn't in	local rack
NO10:010/012		User Pil	routine	overlap	
NO10:010/013		No command	block	exists to	get Pil
NO10:010/014		Arithmetic	overflow	occurred	
NO10:010/015		SFC	lingering	action	overlap
NO10:011/000		Bad	program	file	
NO10:011/001		Bad	address	in ladder	program
NO10:011/002		Programmer	error		
NO10:011/003		SFC Fault			
NO10:011/004		Program	assembly	error	
NO10:011/005		Powerup	protection	fault	
NO10:011/006		Error not	defined		
NO10:011/007		User	generated	fault	
NO10:011/008		Watchdog	timer	fault	
NO10:011/009		Bad system	config-	uration	
NO10:011/010		Hardware	Error		
NO10:011/011		MCP file	does not	exist or	is not
NO10:011/012		Pil file	does not	exist or	is not
NO10:011/013		STI file	does not	exist or	is not
NO10:011/014		Fault file	does not	exist or	is not
NO10:011/015		Non ladder	file		ladder
NO10:012		Fault Code			
NO10:013		Program	file where	fault	occurred
NO10:014		Rung	number	where	fault
NO10:016		I/O status	file		occurred
NO10:017		REGISTER FOR	VERIFYING	FAULT ROUTINE	FILE OPERATION
NO10:017/000		Queue full	between	local and	remote I/O
NO10:017/001		Queue full	servicing	channel 1A	
NO10:017/002		Queue full	servicing	channel 1B	
NO10:017/003		Queue full	servicing	channel 2A	
NO10:017/004		Queue full	servicing	channel 2B	
NO10:017/005		is modem	on serial	port	
NO10:017/006		Remote I/O	is greater	than image	size
NO10:017/008		ASCII	instruct-	ion error	

DB Form Report

Sorted By: Address

N010:017/009		Duplicate	node	address		
N010:018		Real time	clock YEAR			
N010:019		Real time	clock MONTH			
N010:020		Real time	clock DAY			
N010:021		Real time	clock HOUR			
N010:022		Real time	clock MINUTE			
N010:023		Real time	clock SECOND			
MG011:000		SEND MSG	FROM PCU-4	TO PCU-1		
MG011:001		SEND MSG	FROM PCU-4	TO PCU-2		
MG011:002		SEND MSG	FROM PCU-4	TO PCU-3		
MG011:003		SEND MSG	FROM PCU-4	TO PCU-5		
BT012:000						
BT012:001						
BT012:002						
BT012:003						
N013:000/000		ANALOG MODULE	POWERED UP BUT	NOT CONFIGURED		
N013:000/001		ONE OR MORE	CHANNELS ARE	UNDER OR OVER	RANGE	
N013:001		ANALOG MODULE	UNDERRANGE	BITS REGISTER		
N013:001/000		ANALOG MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:001/001		ANALOG MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:001/002		ANALOG MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:001/003		ANALOG MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:001/004		ANALOG MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:001/005		ANALOG MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:001/006		ANALOG MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:001/007		ANALOG MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:002		ANALOG MODULE	OVERRRANGE	BITS REGISTER		
N013:002/000		ANALOG MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:002/001		ANALOG MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:002/002		ANALOG MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:002/003		ANALOG MODULE	CHAN. 4 DATA	OVERRRANGE		
N013:002/004		ANALOG MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:002/005		ANALOG MODULE	CHAN. 6 DATA	OVERRRANGE		
N013:002/006		ANALOG MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:002/007		ANALOG MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:004	DY-850R	DENSITY	READING OF	244-A SUMP		
N013:005	LY-850R	244-A SUMP	LEVEL	READING		
N013:006	RY-851R	RADIATION	INDICATION	FROM 296-A-25	STACK MONITOR	
N013:007	FV-851R	FLOW	INDICATION	FROM 296-A-25	STACK MONITOR	
N013:008	DY-853R	DENSITY	READING FOR	244-A	CATCH TANK	
N013:009	LY-853R	244-A	CATCH TANK	LEVEL	READING	
N013:010	PT-841R	VALVE	MOV-843/846	FAILURE		
N013:011	PT-842R	VALVE	MOV-844/845	FAILURE		
N013:058/015		THERM. MODULE	POWERED UP BUT	NOT CONFIGURED		
N013:061/000		THERM. MODULE	CHAN. 1 DATA	UNDERRANGE		
N013:061/001		THERM. MODULE	CHAN. 1 DATA	OVERRRANGE		
N013:062	TI-841R	LINE	WT-SNL-3150	TEMP		
N013:063/000		THERM. MODULE	CHAN. 2 DATA	UNDERRANGE		
N013:063/001		THERM. MODULE	CHAN. 2 DATA	OVERRRANGE		
N013:064		SPARE	THERMOCOUPLE	INPUT		
N013:065/000		THERM. MODULE	CHAN. 3 DATA	UNDERRANGE		
N013:065/001		THERM. MODULE	CHAN. 3 DATA	OVERRRANGE		
N013:066	TI-842R	LINE	WT-SLL-3160	TEMP		
N013:067/000		THERM. MODULE	CHAN. 4 DATA	UNDERRANGE		
N013:067/001		THERM. MODULE	CHAN. 4 DATA	OVERRRANGE		
N013:068		SPARE	THERMOCOUPLE	INPUT		
N013:069/000		THERM. MODULE	CHAN. 5 DATA	UNDERRANGE		
N013:069/001		THERM. MODULE	CHAN. 5 DATA	OVERRRANGE		
N013:070		SPARE	THERMOCOUPLE	INPUT		
N013:071/000		THERM. MODULE	CHAN. 6 DATA	UNDERRANGE		
N013:071/001		THERM. MODULE	CHAN. 6 DATA	OVERRRANGE		
N013:072		SPARE	THERMOCOUPLE	INPUT		
N013:073/000		THERM. MODULE	CHAN. 7 DATA	UNDERRANGE		
N013:073/001		THERM. MODULE	CHAN. 7 DATA	OVERRRANGE		
N013:074		SPARE	THERMOCOUPLE	INPUT		
N013:075/000		THERM. MODULE	CHAN. 8 DATA	UNDERRANGE		
N013:075/001		THERM. MODULE	CHAN. 8 DATA	OVERRRANGE		
N013:076		SPARE	THERMOCOUPLE	INPUT		
N014:000						
N014:000/000	HB_PL4_OCS	HEARTBEAT	FROM PLC-4	TO OCS		
N014:000/001	COM-41	COMMUN. WITH	PCU-1	IGNORED		
N014:000/002	COM-42	COMMUN. WITH	PCU-2	IGNORED		
N014:000/003	COM-43	COMMUN. WITH	PCU-3	IGNORED		
N014:000/004	COM-4_OCS	COMMUN. WITH	OCS	IGNORED		
N014:000/005	COM-45	COMMUN. WITH	PCU-5	IGNORED		
N014:000/006	BATT_BAD_PL4	PLC-4 BATTERY	IS BAD OR	MISSING		
N014:000/007						
N014:000/008						
N014:000/009						

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

WL5 - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00069

07:03:01 02/19/99

DB Form Report

Sorted By: Address

N014:000/010						
N014:000/011						
N014:000/012	YL-058E	OVERRI DE OF	200-E MASTER	SHUTDOWN		Y-77.1
N014:000/013	RAH-851	STACK	296-A-25	HIGH RADIATION		
N014:000/014	FAL-851	STACK	296-A-25	LOW FLOW		
N014:000/015	PAH-842	SLURRY LINE	HIGH PRESSURE			
N014:001						
N014:001/000	ZA-843-1	VALVE FAILED	TO REACH	POS. 1		Y71.2
N014:001/001	ZA-843-2	VALVE FAILED	TO REACH	POS. 2		Y71.2
N014:001/002	ZA-843-3	VALVE FAILED	TO REACH	POS. 3		Y71.2
N014:001/003	ZA-843	VALVE	POSITION	SWITCH FAILURE		Y71.2
N014:001/004	ZA-844-1	VALVE FAILED	TO REACH	POS. 1		Y71.3
N014:001/005	ZA-844-2	VALVE FAILED	TO REACH	POS. 2		Y71.3
N014:001/006	ZA-844-3	VALVE FAILED	TO REACH	POS. 3		Y71.3
N014:001/007	ZA-844	VALVE	POSITION	SWITCH FAILURE		Y71.3
N014:001/008	ZA-845-1	VALVE	FAILED	TO OPEN		Y-71
N014:001/009	ZA-845-2	VALVE	FAILED	TO CLOSE		Y-71
N014:001/010	ZA-845	VALVE	POSITION	SWITCH FAILURE		Y-71
N014:001/011	ZA-846-1	VALVE	FAILED	TO OPEN		Y-71
N014:001/012	ZA-846-2	VALVE	FAILED	TO CLOSE		Y-71
N014:001/013	ZA-846	VALVE	POSITION	SWITCH FAILURE		Y-71
N014:001/014						
N014:001/015						
N014:011						
N014:011/000	DI-850 A	PCU-4 INPUT	ANALOG	RANGE STATUS	BITS TO 011	
N014:011/001	LI-850 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:011/002	RI-851 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:011/003	FI-851 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:011/004	DI-853 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:011/005	LI-853 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:011/008	PI-841 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:011/007	PI-842 A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:012/000	TE-841 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/009	PCU4-SP-TI-2_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/010	TE-842 A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/011	PCU4-SP-TI-4_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/012	PCU4-SP-TI-5_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/013	PCU4-SP-TI-6_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/014	PCU4-SP-TI-7_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:012/015	PCU4-SP-TI-8_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:026						
N014:026/000	ZLH-845	MOV-845	IS OPEN	REGISTER TO	OIT TERMINALS	Y71
N014:026/001	ZLL-845	MOV-845	IS CLOSED			Y71
N014:026/002	ZL-843-1	MOV-843 IS	IN POSITION 1	A >> B		Y71
N014:026/003	ZL-843-2	MOV-843 IS	IN POSITION 2	A >> C		Y71
N014:026/004	ZL-843-3	MOV-843 IS	IN POSITION 3	B >> C		Y71
N014:026/005	ZL-844-1	MOV-844 IS	IN POSITION 1	A >> B		Y71
N014:026/006	ZL-844-2	MOV-844 IS	IN POSITION 2	A >> C		Y71
N014:026/007	ZL-844-3	MOV-844 IS	IN POSITION 3	B >> C		Y71
N014:026/008	ZLH-846	MOV-846	IS OPEN			Y71
N014:026/009	ZLL-846	MOV-846	IS CLOSED			Y71
N014:026/010	YA-841	ENCASEMENT	RUPTURE DISK	ACTIVATED	TOFF = ALARM	Y78
N014:026/011	YA-842	ENCASEMENT	RUPTURE DISK	ACTIVATED	(OFF = ALARM)	Y78
N014:026/012	XA-056E	200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N014:026/013	RXA-852	SHAD EQPT	FAILURE FROM	296-A-25 STACK	MONITOR	(OFF=ALARM)
N014:026/014	LDA-841	244-A PUMP	PIT LEAK	DETECTION	(OFF=ALARM)	Y72
N014:026/015	YL-841	ON/OFF STATUS	FOR PUMP	P-841		(OCS)
N014:027						
N014:028						
N014:029						
N014:029/000	MOV-845-1	OPEN VALVE	MOV-845			Y71
N014:029/001	MOV-845-2	CLOSE VALVE	MOV-845			Y71
N014:029/002	MOV-843-1	MOVE VALVE 843	TO POSITION 1	A >> B		Y71
N014:029/003	MOV-843-2	MOVE VALVE 843	TO POSITION 2	A >> C		Y71
N014:029/004	MOV-843-3	MOVE VALVE 843	TO POSITION 3	B >> C		Y71
N014:029/005	MOV-846-1	OPEN VALVE	MOV-846			Y71
N014:029/006	MOV-846-2	CLOSE VALVE	MOV-846			Y71
N014:029/007	MOV-844-1	MOVE VALVE 844	TO POSITION 1	A >> B		Y71
N014:029/008	MOV-844-2	MOVE VALVE 843	TO POSITION 2	A >> C		Y71
N014:029/009	MOV-844-3	MOVE VALVE 844	TO POSITION 3	B >> C		Y71
N014:029/010	P-200E-SPM	START PERM	CONTACT FOR	200-E TRANSF.	PUMP	Y-44.1
N014:029/011	PCU4-SP-07-13	SPARE DIGITAL	OUTPUT			
N014:029/012	PCU4-SP-07-14	SPARE DIGITAL	OUTPUT			
N014:029/013	PCU4-SP-07-15	SPARE DIGITAL	OUTPUT			
N014:029/014	PCU4-SP-07-16	SPARE DIGITAL	OUTPUT			
N014:029/015	PCU4-SP-07-17	SPARE DIGITAL	OUTPUT			
N014:030	DI-850	DENSITY	READING OF	244-A SUMP		
N014:031	LI-850	244-A SUMP	LEVEL	READING		
N014:032	RI-851	RADIATION	INDICATION	FROM 296-A-25	STACK MONITOR	

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00070

07:03:02 02/19/99

DB Form Report

Sorted By: Address

N014:0033	FI-851	FLOW	INDICATION	FROM 296-A-25	STACK MONITOR	
N014:0034	DI-853	DENSITY	READING OF	244-A	CATCH TANK	
N014:0035	LI-853	244-A	CATCH TANK	LEVEL	READING	
N014:0036	PI-841	VALVE	MOV-843/848	FAILURE		
N014:0037	PI-842	VALVE	MOV-844/845	FAILURE		
N014:0038	TE-841	LINE	WT-SLL-3150	TEMPERATURE		
N014:0039	PCU4-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014:0040	TE-842	LINE	WT-SLL-3160	TEMPERATURE		
N014:0041	PCU4-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014:0042	PCU4-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014:0043	PCU4-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014:0044	PCU4-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		
N014:0045	PCU4-SP-TI-8	SPARE	THERMOCOUPLE	INPUT		
N014:0046						
N014:0047						
N014:0048						
N014:0049						
N014:090/000	H8 PLC4 OCS	HEARTBEAT	FROM PLC-4	TO OCS		
N014:090/001	COM-41	COMMUN. WITH	PCU-1	IGNORED		
N014:090/002	COM-42	COMMUN. WITH	PCU-2	IGNORED		
N014:090/003	COM-43	COMMUN. WITH	PCU-3	IGNORED		
N014:090/004	COM-4 OCS	COMMUN. WITH	PCS	IGNORED		
N014:090/005	COM-45	COMMUN. WITH	PCU-5	IGNORED		
N014:090/006	BATT_BAD_PL4	PLC-4 BATTERY	IS BAD OR	MISSING		
N014:090/007						
N014:090/008						
N014:090/009						
N014:090/010						
N014:090/011						
N014:090/012	YL-058E	OVERRIDE OF	200-E MASTER	SHUTDOWN		Y-77.1
N014:090/013	RAH-851	STACK	296-A-25	HIGH RADIATION		
N014:090/014	FAL-851	STACK	296-A-25	LOW FLOW		
N014:091/000	PAH-842	SUPERNATE LINE	HIGH PRESSURE			
N014:091/001	ZA-843-1	VALVE FAILED	TO REACH	POS. 1		Y71.2
N014:091/002	ZA-843-2	VALVE FAILED	TO REACH	POS. 2		Y71.2
N014:091/003	ZA-843-3	VALVE FAILED	TO REACH	POS. 3		Y71.2
N014:091/004	ZA-843	VALVE	POSITION	SWITCH FAILURE		Y71.2
N014:091/005	ZA-844-1	VALVE FAILED	TO REACH	POS. 1		Y71.3
N014:091/006	ZA-844-2	VALVE FAILED	TO REACH	POS. 2		Y71.3
N014:091/007	ZA-844-3	VALVE FAILED	TO REACH	POS. 3		Y71.3
N014:091/008	ZA-844	VALVE	POSITION	SWITCH FAILURE		Y71.3
N014:091/009	ZA-845-1	VALVE	FAILED	TO OPEN		Y-71
N014:091/010	ZA-845-2	VALVE	FAILED	TO CLOSE		Y-71
N014:091/011	ZA-845	VALVE	POSITION	SWITCH FAILURE		Y-71
N014:091/012	ZA-846-1	VALVE	FAILED	TO OPEN		Y-71
N014:091/013	ZA-846-2	VALVE	FAILED	TO CLOSE		Y-71
N014:091/014	ZA-846	VALVE	POSITION	SWITCH FAILURE		Y-71
N014:091/015						
N014:092/000	DI-850_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/001	LI-850_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/002	RI-851_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/003	FI-851_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/004	DI-853_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/005	LI-853_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/006	PI-841_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:092/007	PI-842_A	PCU-4 INPUT	ANALOG	OVER OR UNDER	RANGE ALARM	
N014:093/008	TE-841_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/009	PCU4-SP-TI-2_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/010	TE-842_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/011	PCU4-SP-TI-4_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/012	PCU4-SP-TI-5_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/013	PCU4-SP-TI-6_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/014	PCU4-SP-TI-7_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:093/015	PCU4-SP-TI-8_A	PCU-4 INPUT	THERMOCOUPLE	OVER OR UNDER	RANGE ALARM	
N014:094/000	ZLH-845	MOV-845	IS OPEN			Y71
N014:094/001	ZLL-845	MOV-845	IS CLOSED			Y71
N014:094/002	ZL-843-1	MOV-843 IS	IN POSITION 1	A >> B		Y71
N014:094/003	ZL-843-2	MOV-843 IS	IN POSITION 2	A >> C		Y71
N014:094/004	ZL-843-3	MOV-843 IS	IN POSITION 3	B >> C		Y71
N014:094/005	ZL-844-1	MOV-844 IS	IN POSITION 1	A >> B		Y71
N014:094/006	ZL-844-2	MOV-844 IS	IN POSITION 2	A >> C		Y71
N014:094/007	ZL-844-3	MOV-844 IS	IN POSITION 3	B >> C		Y71
N014:094/008	ZLH-846	MOV-846	IS OPEN			Y71
N014:094/009	ZLL-846	MOV-846	IS CLOSED			Y71
N014:094/010	YA-841	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	Y78
N014:094/011	YA-842	ENCASEMENT	RUPTURE DISK	ACTIVATED	[OFF = ALARM]	Y78
N014:094/012	XA-058E	200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N014:094/013	RXA-852	RAD EQPT	FAILURE FROM	296-A-25 STACK	MONITOR	(OFF=ALARM)

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
 WLS - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00071

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

07:03:02 02/19/99

N014:094/014	LDA-841	244-A PUMP	PIT LEAK	DETECTION	(OFF=ALARM)	Y72
N014:094/015	YL-841	ON/OFF STATUS	FOR PUMP	P-841		(OCS)
N014:095/000	MOV-845-1	OPEN VALVE	MOV-845			Y71
N014:095/001	MOV-845-2	CLOSE VALVE	MOV-845			Y71
N014:095/002	MOV-843-1	MOVE VALVE 843	TO POSITION 1	[A >> B]		Y71
N014:095/003	MOV-843-2	MOVE VALVE 843	TO POSITION 2	[A >> C]		Y71
N014:095/004	MOV-843-3	MOVE VALVE 843	TO POSITION 3	[B >> C]		Y71
N014:095/005	MOV-846-1	OPEN VALVE	MOV-846			Y71
N014:095/006	MOV-846-2	CLOSE VALVE	MOV-846			Y71
N014:095/007	MOV-844-1	MOVE VALVE 844	TO POSITION 1	[A >> B]		Y71
N014:095/008	MOV-844-2	MOVE VALVE 844	TO POSITION 2	[A >> C]		Y71
N014:095/009	MOV-844-3	MOVE VALVE 844	TO POSITION 3	[B >> C]		Y71
N014:095/010	P-200E-SPM	START PERM	CONTACT FOR	200-E TRANSF.	PUMP	Y-44.1
N014:095/011	PCU4-SP-07-13	SPARE DIGITAL	OUTPUT			
N014:095/012	PCU4-SP-07-14	SPARE DIGITAL	OUTPUT			
N014:095/013	PCU4-SP-07-15	SPARE DIGITAL	OUTPUT			
N014:095/014	PCU4-SP-07-16	SPARE DIGITAL	OUTPUT			
N014:095/015	PCU4-SP-07-17	SPARE DIGITAL	OUTPUT			
N014:096	DI-850	DENSITY	READING OF	244-A SUMP		
N014:097	LI-850	244-A SUMP	LEVEL	READING		
N014:098	RI-851	RADIATION	INDICATION	FROM 296-A-25	STACK MONITOR	
N014:099	FI-851	FLOW	INDICATION	FROM 296-A-25	STACK MONITOR	
N014:100	DI-853	DENSITY	READING OF	244-A	CATCH TANK	
N014:101	LI-853	244-A	CATCH TANK	LEVEL	READING	
N014:102	PI-841	VALVE	MOV-843/846	FAILURE		
N014:103	PI-842	VALVE	MOV-844/845	FAILURE		
N014:104	TE-841	LINE	WT-SLL-3150	TEMPERATURE		
N014:105	PCU4-SP-TI-2	SPARE	THERMOCOUPLE	INPUT		
N014:106	TE-842	LINE	WT-SLL-3160	TEMPERATURE		
N014:107	PCU4-SP-TI-4	SPARE	THERMOCOUPLE	INPUT		
N014:108	PCU4-SP-TI-5	SPARE	THERMOCOUPLE	INPUT		
N014:109	PCU4-SP-TI-6	SPARE	THERMOCOUPLE	INPUT		
N014:110	PCU4-SP-TI-7	SPARE	THERMOCOUPLE	INPUT		
N014:111	PCU4-SP-TI-8	SPARE	THERMOCOUPLE	INPUT		
N014:120						
N014:120/000	HB_OCS_PL4	HEARTBEAT	FROM OCS	TO PLC-4		
N014:120/001						
N014:120/002						
N014:120/003						
N014:120/004	HS-058E	OVERRIDE OF	200-E MASTER	SHUTDOWN		Y-77.1
N014:120/005						
N014:120/006	HS-843-1	OCS MOVE	VALVE MOV-843	TO POSITION 1		Y71
N014:120/007	HS-843-2	OCS MOVE	VALVE MOV-843	TO POSITION 2		Y71
N014:120/008	HS-843-3	OCS MOVE	VALVE MOV-843	TO POSITION 3		Y71
N014:120/009	HS-846-1	OCS OPEN	VALVE	MOV-846		Y71
N014:120/010	HS-846-2	OCS CLOSE	VALVE	MOV-846		Y71
N014:120/011	HS-844-1	OCS MOVE	VALVE MOV-844	TO POSITION 1		Y71
N014:120/012	HS-844-2	OCS MOVE	VALVE MOV-844	TO POSITION 2		Y71
N014:120/013	HS-844-3	OCS MOVE	VALVE MOV-844	TO POSITION 3		Y71
N014:120/014	HS-845-1	OCS OPEN	VALVE	MOV-845		Y71
N014:120/015						
N014:121/000	HS-845-2	OCS CLOSE	VALVE	MOV-845		Y71
N014:121/001						
N014:121/002						
N014:121/003						
N014:121/004						
N014:121/005						
N014:121/006						
N014:121/007						
N014:121/008						
N014:121/009						
N014:121/010						
N014:121/011						
N014:121/012						
N014:121/013						
N014:121/014						
N014:121/015						
N014:190/000	HB_OCS_PL4	HEARTBEAT	FROM OCS	TO PLC-4		
N014:190/001						
N014:190/002						
N014:190/003						
N014:190/004	HS-058E	OVERRIDE OF	200-E MASTER	SHUTDOWN		Y-77.1
N014:190/005						
N014:190/006	HS-843-1	OCS MOVE	VALVE MOV-843	TO POSITION 1		Y71
N014:190/007	HS-843-2	OCS MOVE	VALVE MOV-843	TO POSITION 2		Y71
N014:190/008	HS-843-3	OCS MOVE	VALVE MOV-843	TO POSITION 3		Y71
N014:190/009	HS-846-1	OCS OPEN	VALVE	MOV-846		Y71
N014:190/010	HS-846-2	OCS CLOSE	VALVE	MOV-846		Y71
N014:190/011	HS-844-1	OCS MOVE	VALVE MOV-844	TO POSITION 1		Y71

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)

HNF-2346, Rev. 1

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00072

07:03:03 02/19/99

DB Form Report

Sorted By: Address

N014:190/012	HS-844-2	OCS MOVE	VALVE MOV-844	TO POSITION 2		Y71
N014:190/013	HS-844-3	OCS MOVE	VALVE MOV-844	TO POSITION 3		Y71
N014:190/014	HS-845-1	OCS OPEN	VALVE MOV-845			Y71
N014:190/015	HS-845-2	OCS CLOSE	VALVE MOV-845			Y71
N019:001/000						
N019:001/001						
N019:001/002	HB-12	HEARTBEAT	FROM PCU-1	TO PCU-2		
N019:001/003	HB-13	HEARTBEAT	FROM PCU-1	TO PCU-3		
N019:001/004	HB-14	HEARTBEAT	FROM PCU-1	TO PCU-4		
N019:001/005	HB-15	HEARTBEAT	FROM PCU-1	TO PCU-5		
N019:001/006						
N019:001/007						
N019:001/008						
N019:001/009						
N019:001/010						
N019:001/011						
N019:001/012						
N019:001/013						
N019:001/014						
N019:001/015		200-W MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:002/000						
N019:002/001	HB-21	STOP BOOSTER	PUMP P-3125B &	TRANSFER PUMP	P-102-SY-02A	Y-74.2
N019:002/002		HEARTBEAT	FROM PCU-2	TO PCU-1		
N019:002/003		STOP BOOSTER	PUMP P-3125A &	TRANSFER PUMP	P-102-SY-02A	Y-74.1
N019:002/004	HB-23	HEARTBEAT	FROM PCU-2	TO PCU-3		
N019:002/005	HB-24	HEARTBEAT	FROM PCU-2	TO PCU-4		
N019:002/006	HB-25	HEARTBEAT	FROM PCU-2	TO PCU-5		
N019:002/007		LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
N019:002/008		LEAK DETECTED	IN LINE TO	DIVERSION	BOX 6241-A	Y-72.1
N019:002/009		SOV-3182A	VALVE	FAILURE		Y-71.1
N019:002/010		SOV-3182B	VALVE	FAILURE		Y-71.1
N019:002/011		SOV-3184	VALVE	FAILURE		Y-71.1
N019:002/012		SOV-3173A/B	VALVE	FAILURE		Y-73.1
N019:002/013		SOV-3183B	VALVE	FAILURE		Y-71.1
N019:002/014		SOV-3183A	VALVE	FAILURE		Y-71.1
N019:002/015		PUMP P-3125A	HIGH INLET	PRESSURE		Y-75.1
N019:003/000		PUMP P-3125B	HIGH INLET	PRESSURE		Y-75.1
N019:003/001		INPUT SIGNAL TO	200-W MASTER	SHUTDOWN	CIRCUIT	Y-72.1
N019:003/002	HB-31	HEARTBEAT	FROM PCU-3	TO PCU-1		
N019:003/003	HB-32	HEARTBEAT	FROM PCU-3	TO PCU-2		
N019:003/004						
N019:003/005	HB-34	HEARTBEAT	FROM PCU-3	TO PCU-4		
N019:003/006	HB-35	HEARTBEAT	FROM PCU-3	TO PCU-5		
N019:003/007						
N019:003/008		TRANSFER 2A	SHUTDOWN			Y-42.1
N019:003/009		TRANSFER 2B	SHUTDOWN			Y-43.1
N019:003/010						
N019:003/011		TRANSFER 1	INITIATED			Y-41.1
N019:003/012		TRANSFER 2A	INITIATED			Y-42.1
N019:003/013		TRANSFER 2B	INITIATED			Y-43.1
N019:003/014		TRANSFER 3	INITIATED			Y-44.1
N019:003/015						
N019:004/000		MASTER RESET				
N019:004/001	HB-41	HEARTBEAT	FROM PCU-4	TO PCU-1		
N019:004/002	HB-42	HEARTBEAT	FROM PCU-4	TO PCU-2		
N019:004/003	HB-43	HEARTBEAT	FROM PCU-4	TO PCU-3		
N019:004/004						
N019:004/005	HB-45	HEARTBEAT	FROM PCU-4	TO PCU-5		
N019:004/006		SLURRY LINE	HIGH PRESSURE	AT PCU-4		
N019:004/007		MOV-843	VALVE	FAILURE		Y71
N019:004/008						
N019:004/009		MOV-844	VALVE	FAILURE		Y71
N019:004/010		MOV-845	VALVE	FAILURE		Y71
N019:004/011		MOV-846	VALVE	FAILURE		Y71
N019:004/012		200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:004/013		RUPTURE	DISK FAILURE			Y-78.1
N019:004/014		LEAK DETECTED	AT 244-A LIFT	STATION	SUMP	Y-72.1
N019:004/015						
N019:005/000						
N019:005/001	HB-51	HEARTBEAT	FROM PCU-5	TO PCU-1		
N019:005/002						
N019:005/003	HB-52	HEARTBEAT	FROM PCU-5	TO PCU-2		
N019:005/004	HB-53	HEARTBEAT	FROM PCU-5	TO PCU-3		
N019:005/005	HB-54	HEARTBEAT	FROM PCU-5	TO PCU-4		
N019:005/006						
N019:005/007						
N019:005/008						
N019:005/009						
N019:005/010						

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00073

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

07:03:03 02/19/99

N019:005/011					
N019:005/012					
N019:005/013					
N019:005/014					
N019:005/015					
N020:000	DY-850	LEAK DETECTED	IN LINE TO	244-A LIFT	STATION
N020:001	LY-850	DENSITY	READING OF	244-A SUMP	Y72-1
N020:002	RY-850	244-A SUMP	LEVEL	READING	
N020:003	FY-851	RADIATION	INDICATION	FROM 296-A-25	STACK MONITOR
N020:004	DY-853	FLOW	INDICATION	FROM 296-A-25	STACK MONITOR
		DENSITY	READING FOR	244-A	CATCH TANK
N020:005	LY-853	244-A	CATCH TANK	LEVEL	READING
N020:006	PT-841	VALVE	MOV-843/846	FAILURE	
N020:007	PT-841	SLURRY LINE	PRESSURE		
N020:008	TI-841	LINE	WT-SLL-3150	TEMPERATURE	
N020:009		SPARE	THERMOCOUPLE	INPUT	
N020:010	TI-842	LINE	WT-SLL-3160	TEMPERATURE	
N020:011		SPARE	THERMOCOUPLE	INPUT	
N020:012		SPARE	THERMOCOUPLE	INPUT	
N020:013		SPARE	THERMOCOUPLE	INPUT	
N020:014		SPARE	THERMOCOUPLE	INPUT	
N020:015		SPARE	THERMOCOUPLE	INPUT	
N021:060		DH+ TRANSFER	FROM PCU-1	DATA REGISTERS	
N021:060/000					
N021:060/001					
N021:060/002					
N021:060/003					
N021:060/004					
N021:060/005					
N021:060/006					
N021:060/007					
N021:060/008					
N021:060/009					
N021:060/010					
N021:060/011					
N021:060/012					
N021:060/013					
N021:060/014					
N021:060/015					
N021:061					
N021:062					
N021:063					
N021:064					
N022:060		DH+ TRANSFER	FROM PCU-2	DATA REGISTERS	
N022:060/000					
N022:060/001					
N022:060/002					
N022:060/003					
N022:060/004					
N022:060/005					
N022:060/006					
N022:060/007					
N022:060/008					
N022:060/009					
N022:060/010					
N022:060/011					
N022:060/012					
N022:060/013					
N022:060/014					
N022:060/015					
N022:061					
N022:062					
N022:063					
N022:064					
N023:060		DH+ TRANSFER	FROM PCU-3	DATA REGISTERS	
N023:060/000					
N023:060/002					
N023:060/005					
N023:060/006					
N023:060/007					
N023:060/008					
N023:060/009					
N023:060/010					
N023:060/011					
N023:060/012					
N023:060/013					
N023:060/014					
N023:060/015					
N023:061					
N023:062					

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
WLS - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00074

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

07:03:04 02/19/99

N023:063					
N023:064					
N024:000	DH+ TRANSFER	TO PCU-1	DATA REGISTERS		
N024:000/000					
N024:000/001					
N024:000/002					
N024:000/003					
N024:000/004					
N024:000/005					
N024:000/006					
N024:000/007					
N024:000/008					
N024:000/009					
N024:000/010					
N024:000/011					
N024:000/012					
N024:000/013					
N024:000/014					
N024:000/015					
N024:001					
N024:002					
N024:003					
N024:004					
N024:020	DH+ TRANSFER	TO PCU-2	DATA REGISTERS		
N024:020/000					
N024:020/001					
N024:020/002					
N024:020/003					
N024:020/004					
N024:020/005					
N024:020/006					
N024:020/007					
N024:020/008					
N024:020/009					
N024:020/010					
N024:020/011					
N024:020/012					
N024:020/013					
N024:020/014					
N024:020/015					
N024:021					
N024:022					
N024:023					
N024:024					
N024:040	DH+ TRANSFER	TO PCU-3	DATA REGISTERS		
N024:040/000					
N024:040/001					
N024:040/002					
N024:040/003					
N024:040/004					
N024:040/005					
N024:040/006					
N024:040/007					
N024:040/008					
N024:040/009					
N024:040/010					
N024:040/011					
N024:040/012					
N024:040/013					
N024:040/014					
N024:040/015					
N024:041					
N024:042					
N024:043					
N024:044					
N024:080	DH+ TRANSFER	TO PCU-5	DATA REGISTERS		
N024:080/000					
N024:080/001					
N024:080/002					
N024:080/003					
N024:080/004					
N024:080/005					
N024:080/006					
N024:080/007					
N024:080/008					
N024:080/009					
N024:080/010					
N024:080/011					
N024:080/012					

DB Form Report

Sorted By: Address

07:03:04 02/19/99

NO24:080/013					
NO24:080/014					
NO24:080/015					
NO24:081					
NO24:082					
NO24:083					
NO24:084					
NO24:100	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
NO24:120	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
NO24:140	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
NO24:180	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
NO25:060	DH+ TRANSFER	FROM PCU-5	DATA REGISTERS	REGISTERS	
NO25:060/000					
NO25:060/001					
NO25:060/002					
NO25:060/003					
NO25:060/004					
NO25:060/005					
NO25:060/006					
NO25:060/007					
NO25:060/008					
NO25:060/009					
NO25:060/010					
NO25:060/011					
NO25:060/012					
NO25:060/013					
NO25:060/014					
NO25:060/015					
NO25:061					
NO25:062					
NO25:063					
NO25:064					
DFILE:000	OUTPUTS	Output Reg	isters And	Bits	
DFILE:001	INPUTS	Input Reg	isters And	Bits	
DFILE:002	SYSTEM	System Sta	tus Variab	les	
DFILE:003	BITS	General In	ternal Bit	Addresses	
DFILE:004	TIMERS	General Ti	mer Address	ses	
DFILE:005	COUNTERS	General Co	unter Addr	esses	
DFILE:006	CONTROL	General Co	ntrol Addr	esses	
DFILE:007	INTEGERS	General in	teger Addr	esses	
DFILE:008	FLOATING	General Fl	loating Poi	nt Address	es
DFILE:009	I/O STATUS	I/O Status	File (Use	d By The P	rocessor)
DFILE:010	PROC FLT	Stores Sys	tem Data 0	n A Proces	sor Fault
DFILE:011	GEN MSG	General	DH-Plus Me	ssage Cont	rol File
DFILE:012	GEN BT	General	Block Tran	sfer Contr	ol File
DFILE:013	ANA RAW	Analog Dat	a File		
DFILE:014	OIM DATA	OCS Commun	ication Fi	le	
DFILE:018	CONFIG1A	Channel 1A	Configura	tion Diag	File
DFILE:019	GLOBAL1A	Channel 1A	Config GI	obal Statu	s File
DFILE:020	ANA BUF	Analog I/O	Working F	ile	
DFILE:021	PLC1DATA	DATA FROM	PLC-1(DH+)		
DFILE:022	PLC2DATA	DATA FROM	PLC-2(DH+)		
DFILE:023	PLC3DATA	DATA FROM	PLC-3(DH+)		
DFILE:024	PLC4DATA	DATA FROM	PLC-4(DH+)		
DFILE:025	PLC5DATA	DATA FROM	PLC-5(DH+)		
PFIL:000	[SYSTEM DA	TA STORAGE	HEADER]		
PFIL:002	MAIN PROGR	AM FILE			
PFIL:003	PROCESSOR	FAULT ROUT	TNE		
PFIL:004	I/O HANDLI	NG FOR ANA	LOG AND OT	HER REGIST	ER INPUTS
PFIL:005	COMMUNICAT	ION			
PFIL:006	GENERAL F	ILE			
Q002:000	MAIN PROGRAM	FILE START-UP	JUMP TO JSR'S		
Q002:001	MAIN PROGRAM	FILE START-UP	JUMP TO END		
Q003:000	PROCESSOR	FAULT ROUTINE	JUMP TO END		
U:004	I/O HANDLTNG	FOR ANALOG OR	OTHER REG I70	SUBROUTINE	
U:005	DATA HIGHWAY +	CTRL & CHECK	COMMUNICATION	SUBROUTINE	
U:006	GENERAL FILE	SUBROUTINE			
V:004	I70 HANDLING	SUBROUTINE	OTHER REG IN	SUBROUTINE	
V:005	SUBROUTINE	FOR ANALOG OR			

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00076

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

07:03:05 02/19/99

Addr:B3/0
TITLE:GENERAL USE BITS AND TIMING FUNCTIONS
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF

Addr:B3/1
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON

Addr:B3/2
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY SECOND.

Addr:B3/3
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY TWO SECONDS.

Addr:B3/4
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/5
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/6
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/36
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING

Addr:B3/37
RUNG DESCRIPTION:
THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

Addr:B3/39
TITLE:ANALOG INPUTS BLOCK TRANSFER SEQUENCING

Addr:B3/40
TITLE:COMMUNICATION HANDLING SUBROUTINE

Addr:B3/48
TITLE:ANALOG INPUT OVER / UNDER RANGE ALARMS

Addr:B3/85
TITLE:SEQUENCING FOR TRANSFER VALVE MOV-844, Y-71.3

Addr:B3/301
TITLE:SEQUENCING FOR TRANSFER VALVE MOV-845, Y-71.1

Addr:B3/303
TITLE:SEQUENCING FOR TRANSFER VALVE MOV-846, Y-71.1

Addr:B3:1
RUNG DESCRIPTION:
THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE BITS CAN BE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN

APPENDIX D

Hanford Cross Site Transfer System (PCU-4)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00077

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

07:03:05 02/19/99

TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

Addr:N14:0/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND OCS

Addr:N14:190
TITLE:SEQUENCING TO HANDLE OIT DATA TO AND FROM PLC-1

Addr:N16:0/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-1

Addr:N16:20/1
TITLE:PCU-4 COMMUNICATIONS
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-2

Addr:N16:40/8
RUNG DESCRIPTION:
NEXT 3 RUNGS COMMUNICATION BETWEEN PCU-4 AND PCU-3

Addr:N16:60/0
TITLE:PCU-4 COMMUNICATIONS
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-1

Addr:N16:80/0
RUNG DESCRIPTION:
NEXT 3 RUNGS COMMUNICATION BETWEEN PCU-4 AND PCU-5

Addr:N19:4/1
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-1

Addr:N19:4/2
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-2

Addr:N19:4/3
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-3

Addr:N19:4/5
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-4 AND PCU-5

Addr:N19:4/12
TITLE:BOOSTER PUMP INTERLOCK, Y-78

Addr:N19:4/13
TITLE:LEAK DETECTION LOGIC, Y-72

Addr:0:007/02
TITLE:SEQUENCING FOR TRANSFER VALVE MOV-843, Y-71.2

Addr:Q2:1
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING

Addr:Q3:0
TITLE:PROCESSOR FAULT ROUTINE PROGRAM FILE.
RUNG DESCRIPTION:
THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL OCCURE ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN, A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE COPIED INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.

APPENDIX D

HNF-2346, Rev. 1

Hanford Cross Site Transfer System (PCU-4)

WLS - Data Base Form Report

Lockheed Martin Hanford Co.

Page:00078

DB Form Report Sorted By: Address

07:03:05 02/19/99

Addr:RUNG004-0007
TITLE:PCU-4 OIT FILE

Addr:RUNG006-0000
TITLE:SCHEME 3 241-A-B TO 241-SY-A LOGIC, Y-44.1

Addr:T4:0
TITLE:MAINLINE PROGRAM INITIALIZATION JUMP
RUNG DESCRIPTION:

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
P.O. Box 28970
Spokane, WA 99228-8970
(509) 466-2656

THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS BEEN UPDATED ON
POWERUP OR
ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS BEEN READ.
TIMER T4:0 IS
USED TO SET THIS TIME DELAY.

Addr:T4:1
RUNG DESCRIPTION:
THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

WINTelligent LOGIC 5 - Rockwell Software Inc.

Project Name : PLC5.X5

Time/Date : 15:54:15 02/18/99

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
WL5 - Table of Contents
Lockheed Martin Hanford Co.

HNF-2346, Rev. 1

15:54:03 02/18/99

Page	Rung	Description
1		<u>Ladder Report</u>
1	0	MAINLINE PROGRAM INITIALIZATION JUMP
2	2	GENERAL USE BITS AND TIMING FUNCTIONS
5	11	PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
7	0	PROCESSOR FAULT ROUTINE PROGRAM FILE
8	0	ANALOG INPUTS BLOCK TRANSFER SEQUENCING
9	0	COMMUNICATION HANDLING SUBROUTINE
19	26	SEQUENCING TO HANDLE THE OIT DATA TO AND FROM PLC-1
23	0	PCU-5 LEAK DETECTION CONTROL LOGIC (Y-72.1)
24		DT Form Report
24		DB Form Report Sorted By: Address

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 MAINLINE PROGRAM INITIALIZATION JUMP
 Lockheed Martin Hanford Co.
 Page:00001

HNF-2346, Rev. 1

15:54:15 02/18/99

File #2 Proj:PLCS

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
 P.O. Box 28970
 Spokane, WA 99228-8970
 (509) 466-2656

*THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
 *THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS
 *BEEN UPDATED ON POWERUP OR
 *ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS
 *BEEN READ. TIMER T4:0 IS
 *USED TO SET THIS TIME DELAY.

First scan
 of ladder
 or SFC
 step

POWER-UP
 SEQUENCING
 DELAY

2:0000 S:1/15

+--TOF--+
 Timer Off Delay (EN)
 Timer: T4:0
 Base (SEC): 0.01 (DN)
 Preset: 20
 Accum: 20
 +-----+

T4:0.DN - 0,1,14

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

2:0001 T4:0.DN

Q2:0
 [JMP]

Q2:0 - 1,11

File #2 Proj:PLC5

*THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF

ALWAYS OFF	ALWAYS OFF
OUTPUT	OUTPUT
ALWAYS OFF	ALWAYS OFF
B3 $\bar{O}$	B3 $\bar{O}$

ALWAYS OFF
OUTPUT
ALWAYS OFF
B3/0

2:0002

B3/0 - 2,2, /2,6, [5]3

*THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON

ALWAYS ON
OUTPUT
ALWAYS ON
B3/1
----- ( ) -----

2:0003

B3/1 - 3

*THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED *
ONCE EVERY SECOND.

REAL TIME	
CLOCK	ONE SECOND
SECOND	RISING
ONE'S BIT	ONE SHOT

ONE SECOND
SINGLE SCAN
PULSE
1_SEC PULSE
B372

2:0004

REAL TIME	
CLOCK	ONE SECOND
SECOND	FALLING
ONE'S BIT	ONE SHOT

S:23/0 B3/33
- - - | / | - - - - - [ONS]

B3/2 - 4, 7, [5], 5, 26

*THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE
*EXECUTED ONCE EVERY TWO
*SECONDS.

REAL TIME	
CLOCK	TWO SECOND
SECOND	RISING
TWO'S BIT	ONE SHOT

TWO SECOND
SINGLE SCAN
PULSE
2_SEC PULSE
B373

2:0005

REAL TIME	
CLOCK	TWO SECOND
SECOND	FALLING
TWO'S BIT	ONE SHOT

S:23/1 B3/35
---|/|-----[ONS]

B3/3 - 5.6.6

THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE BITS CAN BE USED TO DIVIDE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.

THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT DEVICES.

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
GENERAL USE BITS AND TIMING FUNCTIONS
Lockheed Martin Hanford Co.
Page:00004

HNF-2346, Rev. 1

15:54:15 02/18/99

File #2 Proj:PLC5

B3/4 - 8

*****
*THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT
*DEVICES.
*****

REAL TIME
CLOCK
SECOND
ONE'S BIT

ONE SECOND
FLASHER
1_SEC FLASH
B375

2:0009 S:23/0

B3/5 - 9

*****
*THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT
*DEVICES.
*****

REAL TIME
CLOCK
SECOND
TWO'S BIT

TWO SECOND
FLASHER
2_SEC FLASH
B376

2:0010 S:23/1

B3/6 - 10

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
 Lockheed Martin Hanford Co.
 Page:00005

HNF-2346, Rev. 1

15:54:16 02/18/99

File #2 Proj:PLC5

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING
 *****

MAIN PROGRAM
 FILE START-UP
 JUMP TO JSR'S

PROGRAM FILE
 JUMP-TO-SUBR.
 CONTROL RUNGS
 COMMENT COIL

2:0011 Q2:0
 -----[LBL]-----

B3/36
 -----( )-----

B3/36 - 11

I/O HANDLING
 FOR ANALOG OR
 OTHER REG I/O
 SUBROUTINE

2:0012 U:4
 ----- - 12,[4]0

+--JSR-----+
 |Jump To Subroutine|
 |File #: U:4|
 +-----+

DATA HIGHWAY+
 CTRL & CHECK
 COMMUNICATION
 SUBROUTINE

2:0013 U:5
 ----- - 13,[5]0

+--JSR-----+
 |Jump To Subroutine|
 |File #: U:5|
 +-----+

*****
 *THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING
 *****

POWER-UP
 SEQUENCING
 DELAY

MAIN PROGRAM
 FILE START-UP
 JUMP TO END

2:0014 T4:0.0N
 -----| |-----
 Q2:1 - 14,16

Q2:1
 -----[JMP]-----

GENERAL FILE
 SUBROUTINE

2:0015 U:6
 ----- - 15,[6]0

+--JSR-----+
 |Jump To Subroutine|
 |File #: U:6|
 +-----+

*****
 *THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE
 *****

MAIN PROGRAM
 FILE START-UP
 JUMP TO END

MCP FILE #2
 END OF PROGRAM
 COMMENT COIL

2:0016 Q2:1
 -----[LBL]-----

B3/37
 -----( )-----

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
Lockheed Martin Hanford Co.
Page:00006

HNF-2346, Rev. 1

15:54:16 02/18/99

File #2 Proj:PLC5

B3/37 - 16

2:0017

[End]

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 PROCESSOR FAULT ROUTINE PROGRAM FILE.
 Lockheed Martin Hanford Co.
 Page:00007

HNF-2346, Rev. 1

15:54:16 02/18/99

File #3 Proj:PLC5

*THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL OCCURE *
 *ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN, *
 *A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE *
 *COPIED *
 *INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO. *

First scan
 of ladder
 or SFC
 step

PROCESSOR
 FAULT ROUTINE
 JUMP TO END

3:0000 S:1/15
 |

Q3:0

[JMP]

Q3:0 - [3]0,2

Logical Rack
 Status Bits
 For Racks 0-7

3:0001

+--BTD-----+
 Bit Field Distributor
 Source: S:7
 0
 Source Bit: 0
 Dest: N10:7
 0
 Dest Bit: 0
 Length: 8
 +-----+

Last
 program
 scan time
 ladder &
 SFC

+--COP-----+
 Copy File
 Source: #S:8
 Dest: #N10:8
 Length: 16
 +-----+

S:7 - [3]1
 N10:7 - [3]1
 N10:7 - [3]wf1
 N10:7 - [3]wf1

PROCESSOR
 FAULT ROUTINE
 JUMP TO END

FAULT ROUTINE
 FILE #3
 END OF PROGRAM
 COMMENT COIL

3:0002 Q3:0
 [LBL]

B3/38

( )

B3/38 - [3]2

REGISTER FOR
 VERIFYING
 FAULT ROUTINE
 FILE OPERATION

3:0003

+--ADD-----+
 Add
 Source A: N10:0
 0
 Source B: 1
 1
 Dest: N10:0
 0
 +-----+

N10:0 - [3]3,3
 N10:0 - [3]3,3

3:0004

[End]

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
ANALOG INPUTS BLOCK TRANSFER SEQUENCING
Lockheed Martin Hanford Co.
Page:00008

HNF-2346, Rev. 1

15:54:16 02/18/99

File #4 Proj:PLC5

	I/O HANDLING FOR ANALOG OR OTHER REG I/O SUBROUTINE	PROGRAM FILE #4 START OF SUBROUTINE COMMENT COIL
4:0000	+--SBR-----+ Subroutine -----+ +-----+ B3/39 - [4]0	B3/39 - ( ) -
4:0001		I/O HANDLING FOR ANALOG OR OTHER REG IN SUBROUTINE
		+--RET-----+ Return ( ) -----+ +-----+
4:0002		[End]-

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00009

HNF-2346, Rev. 1

15:54:16 02/18/99

File #5 COMM_FILE Proj:PLC5

```

DATA HIGHWAY+
CTRL & CHECK
COMMUNICATION
SUBROUTINE

PROGRAM
FILE #5 START
OF SUBROUTINE
COMMENT COIL

5:0000 +---SBR-----+
|Subroutine|-----+ B3/40
+-----+
          ( )

B3/40      - [5]0

-----
*COMMUNICATION BETWEEN PCU-5 AND OCS
-----

HEARTBEAT
FROM OCS
TO PLC-5
HB_OCS_PLC5
N14:120/0

HEARTBEAT
FROM PLC-5
TO OCS
HB_PLC5_OCS
N14:070

5:0001 +-----+
|/|-----+
          ( )

N14:0/0      - [5]1,2,/2

HEARTBEAT
FROM PLC-5
TO OCS
HB_PLC5_OCS
N14:070

COMMUN LOSS
WITH OCS
ONE-SHOT
B3/200
[ONS]

COMM LOSS
TIMER
WITH OCS

5:0002 +---TOF-----+
|Timer Off Delay|-(EN)-
|Timer: T4:40|
|Base (SEC): 1.0|-(DN)
|Preset: 50|
|Accum: 50|
+-----+

HEARTBEAT
FROM PLC-5
TO OCS
HB_PLC5_OCS
N14:070

COMMUN LOSS
WITH OCS
ONE-SHOT
B3/201
[ONS]

T4:40.DN      - [5]2,/3

ALWAYS OFF
OUTPUT
ALWAYS OFF
B3/0

COMMUN. WITH
OCS
IGNORED
COB-5_OCS
N14:075

5:0003 +-----+
|/|-----+
          ( )

N14:0/5      - [5]3

Battery
is bad or
missing
S:10/0

PLC-5 BATTERY
IS BAD OR
MISSING
BATT_BAD_PLC5
N14:076

5:0004 +-----+
|/|-----+
          ( )

N14:0/6      - [5]4

ONE SECOND
SINGLE SCAN
PULSE
1_SEC_PULSE
B372

DIGITAL INPUT
REGISTER TO
OIT TERMINALS

5:0005 +---MOV-----+
|Move|
|Source: 1:000|
|Dest: N14:28|
|1|
|1|
+-----+

```

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00010

HNF-2346, Rev. 1

15:54:17 02/18/99

File #5 COMM_FILE Proj:PLCS

```

1:000/000 - [5]5,[6]/1
N14:28 - [5]5,30
*****
*COMMUNICATION BETWEEN PCU-5 AND PCU-1
*****

HEARTBEAT FROM PCU-1 TO PCU-5 HB-15 N19:1/5
HEARTBEAT FROM PCU-5 TO PCU-1 HB-51 N19:5/1
5:0006 -----

N19:5/1 - [5]6,7,/7

HEARTBEAT FROM PCU-5 TO PCU-1 HB-51 N19:5/1
COMMUN. LOSS WITH PCU-1 ONE-SHOT B3/76 [ONS]
5:0007 -----
+--TOF--+-
|Timer Off Delay|-(EN)-
|Timer: T4:2|
|Base (SEC): 1.0|-(DN)-
|Preset: 5|
|Accum: 0|
+-----+

HEARTBEAT FROM PCU-5 TO PCU-1 HB-51 N19:5/1
COMMUN. LOSS WITH PCU-1 ONE-SHOT B3/77 [ONS]
+-----+

T4:2.DN - [5]7,/8

COMMUN. LOSS TIMER WITH PCU-1
T4:2.DN
5:0008 -----

COMMUN. WITH PCU-1 IGNORED COM-51 N14:0/1
N14:0/1 - [5]8,/9,/26,/27,/29,/30,/31

```


APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00011

HNF-2346, Rev. 1

15:54:17 02/18/99

File #5 COMM_FILE Proj:PLCS

5:0009 COMMUN. WITH
 PCU-1
 IGNORED
 COM-51
 N14:0/1

R6:10.IN
 (U)

COMPARE
 PCU-5 TO PCU-1
 MSG FILE
 WITH PREVIOUS

MG11:0.EN

```

+--FSC-----+
+---|/|-----+ File Search/Compare -(EN)
+---|/|-----+ Control: R6:10 -(DN)
+---|/|-----+ Length: 20
+---|/|-----+ Position: 0
+---|/|-----+ Mode: ALL -(ER)
+---|/|-----+ Expression:
+---|/|-----+ #N25:0 <> #N25:100
  
```

R6:10.FD

```

+--COP-----+
+---|/|-----+ Copy File
+---|/|-----+ Source: #N25:0
+---|/|-----+ Dest: #N25:200
+---|/|-----+ Length: 20
  
```

SEND MSG
 FROM PCU-5
 TO PCU-1

```

+--MSG-----+
+---|/|-----+ Send/Receive Message -(EN)
+---|/|-----+ Control Block: MG11:0 -(DN)
+---|/|-----+ -(ER)
  
```

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:0.DN B3/160

```

+--COP-----+
+---|/|-----+ Copy File
+---|/|-----+ Source: #N25:200
+---|/|-----+ Dest: #N25:100
+---|/|-----+ Length: 20
  
```

```

R6:10.IN - [5]9,9,9,10,10,10,10
R6:10.IN - [5]9,9,9,10,10,10,10
R6:10.IN - [5]wf9,9
R6:10.IN - [5]wf9,9
R6:10.IN - [5]wf9,9
MG11:0.EN - [5]9,9,9
MG11:0.EN - [5]wf9,9
MG11:0.EN - [5]wf9
  
```

File #5 COMM_FILE Proj:PLC5

COMPARE
PCU-5 TO PCU-1
MSG FILE
WITH PREVIOUS

The diagram shows four digital signals over a 5.0010 second interval. The signals are:

- R6:10.DN**: A square wave that is high for approximately 1.5 seconds and then low.
- R6:10.FD**: A square wave that is low for approximately 1.5 seconds and then high.
- R8:10[RES]**: A square wave that is high for approximately 1.5 seconds and then low.
- R8:10.FD(U)**: A square wave that is low for approximately 1.5 seconds and then high.

The signals are shown as vertical lines with horizontal segments indicating the duration of each state. The time scale is marked as 5.0010.

R6:10.1N - [5]9,9,9,10,10,10,10
R6:10.1N - [5]9,9,9,10,10,10,10

*COMMUNICATION BETWEEN PCU-5 AND PCU-2

HEARTBEAT
FROM PCU-2
TO PCU-5
HB-25
N19:2/5

HEARTBEAT
FROM PCU-5
TO PCU-2
HB-52
N19:5/2

5:0011 | N19:2/5
N19:5/2 - [5]11,12,/12

HEARTBEAT FROM PCU-5 TO PCU-2 HB-52 N19:5/2	COMMUN. LOSS WITH PCU-2 ONE-SHOT B3/78

COMMUN. LOSS
TIMER WITH
PCU-2

5.0012	N19:5/2	[ONS]		Timer Off Delay	-(EN)
				Timer:	T4:3
				Base (SEC):	1.0
				Preset:	5
				Accum:	0
	HEARTBEAT COMMUN. LOSS				
	FROM PCU-5 WITH PCU-2				
	TO PCU-2 ONE-SHOT				
	HB-52				
	N19:5/2	B3/79			
	/ /	[ONS]			

T4:3.DN - [5]12, 13

COMMUN. LOSS
TIMER WITH
PCU-2

COMMUN. WITH
PCU-2
IGNORED
COM-52
N14:0/2
----- ( ) -----

5:0013 T4:3.DN N14:0/2
-----|/|-----
N14:0/2 - {5|13,/14

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00013

HNF-2346, Rev. 1

15:54:18 02/18/99

File #5 COMM_FILE Proj:PLC5

5:0014 COMMUN. WITH
 PCU-2
 IGNORED
 COM-52
 N14:0/2
 -|/|

R6:11.IN
 (U)

COMPARE
 PCU-5 TO PCU-2
 MSG FILE
 WITH PREVIOUS

MG11:1.EN

+--FSC-----+
 |File Search/Compare|-(EN)
 |Control: R6:11|
 |Length: 20|-(DN)
 |Position: 0|
 |Mode: ALL|-(ER)
 |Expression:|
 |#N25:20 <> #N25:120|

R6:11.FD

+--COP-----+
 |Copy File|
 |Source: #N25:20|
 |Dest: #N25:220|
 |Length: 20|

SEND MSG
 FROM PCU-5
 TO PCU-2

+--MSG-----+
 |Send/Receive Message|-(EN)--+
 |Control Block: MG11:1|-(DN)
 |-(ER)

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:1.DN B3/161

+--COP-----+
 |Copy File|
 |Source: #N25:220|
 |Dest: #N25:120|
 |Length: 20|

R6:11.IN - [5]14,14,14,15,15,15,15
 R6:11.IN - [5]14,14,14,15,15,15,15
 R6:11.IN - [5]w14,14
 R6:11.IN - [5]w14,14
 R6:11.IN - [5]w14,14
 R6:11.IN - [5]w14,14
 MG11:1.EN - [5]14,14,14
 MG11:1.EN - [5]w14,14
 MG11:1.EN - [5]w14

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00014

HNF-2346, Rev. 1
 15:54:18 02/18/99

File #5 COMM_FILE Proj:PLC5

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00015

HNF-2346, Rev. 1
 15:54:19 02/18/99

File #5 COMM_FILE Proj:PLC5

5:0019

COMMUN. WITH
 PCU-3
 IGNORED
 COM-53
 N14:0/3

R6:12.IN
 (U)

COMPARE
 PCU-5 TO PCU-3
 MSG FILE
 WITH PREVIOUS

MG11:2.EN
 -|/|

+--FSC-----+
 |File Search/Compare|-(EN)
 |Control: R6:12|
 |Length: 20|-(DN)
 |Position: 0|
 |Mode: ALL|-(ER)
 |Expression:
 |#N25:40 <> #N25:140|

R6:12.FD

+--COP-----+
 |Copy File|
 |Source: #N25:40|
 |Dest: #N25:240|
 |Length: 20|

SEND MSG
 FROM PCU-5
 TO PCU-3

+--MSG-----+
 |Send/Receive Message|-(EN)
 |Control Block: MG11:2|-(DN)
 |-(ER)

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:2.DN B3/162

+--COP-----+
 |Copy File|
 |Source: #N25:240|
 |Dest: #N25:140|
 |Length: 20|

R6:12.IN - [5]19,19,19,20,20,20,20
 R6:12.IN - [5]19,19,19,20,20,20,20
 R6:12.IN - [5]w19,19
 R6:12.IN - [5]w19,19
 R6:12.IN - [5]w19,19
 MG11:2.EN - [5]19,19,19
 MG11:2.EN - [5]w19,19
 MG11:2.EN - [5]w19

Hanford Cross Site Transfer System (PCU-5)
COMMUNICATION HANDLING SUBROUTINE
Lockheed Martin Hanford Co.
Page:00016

HNF-2346, Rev. 1
15:54:19 02/18/99

COMPARE
PCU-5 TO PCU-3
MSG FILE
WITH PREVIOUS

5:0020 R6:12.DN R6:12 [RES] R6:12.FD (U)

R6:12.IN - [5]19,19,19,20,20,20,20
R6:12.IN - [5]19,19,19,20,20,20,20

*****
*COMMUNICATION BETWEEN PCU-5 AND PCU-4
*****

HEARTBEAT FROM PCU-4 TO PCU-5 HB-45 N19:4/5

5:0021 HEARTBEAT FROM PCU-5 TO PCU-4 HB-54 N19:5/4 ( )

N19:5/4 - [5]21,22, /22

HEARTBEAT FROM PCU-5 TO PCU-4 HB-54 N19:5/4

5:0022 COMMUN. LOSS WITH PCU-4 ONE-SHOT [ONS] B3/82 [ONS]

COMMUN. LOSS TIMER WITH PCU-4

TOF
Timer Off Delay (EN)
Timer: T4:5
Base (SEC): 1.0 (DN)
Preset: 5
Accum: 0

HEARTBEAT FROM PCU-5 TO PCU-4 HB-54 N19:5/4

COMMUN. LOSS WITH PCU-4 ONE-SHOT [ONS] B3/83 [ONS]

T4:5.DN - [5]22, /23

COMMUN. LOSS TIMER WITH PCU-4

5:0023 T4:5.DN

COMMUN. WITH PCU-4 IGNORED COM-54 N14:0/4 ( )

N14:0/4 - [5]23, /24

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 COMMUNICATION HANDLING SUBROUTINE
 Lockheed Martin Hanford Co.
 Page:00017

HNF-2346, Rev. 1

15:54:19 02/18/99

File #5 COMM_FILE Proj:PLC5

5:0024 COMMUN. WITH
 PCU-4
 IGNORED
 COM-54
 N14:0/4
 -[/]

R6:13.IN
 (U)

COMPARE
 PCU-5 TO PCU-4
 MSG FILE
 WITH PREVIOUS

MG11:3.EN

File Search/Compare - (EN)
 Control: R6:13
 Length: 20 - (DN)
 Position: 0
 Mode: ALL - (ER)
 Expression:
 #N25:60 <> #N25:160

R6:13.FD

Copy File
 Source: #N25:60
 Dest: #N25:260
 Length: 20

SEND MSG
 FROM PCU-5
 TO PCU-4

Send/Receive Message - (EN)
 Control Block: MG11:3 - (DN)
 - (ER)

DH+ MESSAGE
 INSTRUCTION
 COMPARATIVE
 REGISTERS

MG11:3.DN B3/163

Copy File
 Source: #N25:260
 Dest: #N25:160
 Length: 20

R6:13.IN - [5]24,24,24,25,25,25,25
 R6:13.IN - [5]24,24,24,25,25,25,25
 R6:13.IN - [5]wf24,24
 R6:13.IN - [5]wf24,24
 R6:13.IN - [5]wf24,24
 MG11:3.EN - [5]24,24,24
 MG11:3.EN - [5]wf24,24
 MG11:3.EN - [5]wf24

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
COMMUNICATION HANDLING SUBROUTINE
Lockheed Martin Hanford Co.
Page:00018

HNF-2346, Rev. 1

15:54:20 02/18/99

File #5 COMM_FILE Proj:PLC5

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 SEQUENCING TO HANDLE THE OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.
 Page:00019

HNF-2346, Rev. 1

15:54:20 02/18/99

File #5 COMM_FILE Proj:PLC5

5:0026 COMMUN. WITH ONE SECOND
 PCU-1 SINGLE SCAN
 IGNORED PULSE
 COM-51 1_SEC_PULSE
 N14:0/1 B372

+-COP-+
 Copy File
 Source: #N14:120
 Dest: #N14:200
 Length: 1

f s - [5]wf26,29
 f s - [5]wf26,27,29

5:0027 COMMUN. WITH
 PCU-1
 IGNORED
 COM-51
 N14:0/1

R6:15.IN

(U)

MG11:5.EN

+-FSC-+
 File Search/Compare (EN)
 Control: R6:15
 Length: 1 (DN)
 Position: 0
 Mode: ALL (ER)
 Expression:
 #N14:200 <> #N21:0

R6:15.FD

+-COP-+
 Copy File
 Source: #N14:200
 Dest: #N21:20
 Length: 2

+-MSG-+
 Send/Receive Message (EN)
 Control Block: MG11:5 (DN)
 (ER)

MG11:5.DN B3/165

+-COP-+
 Copy File
 Source: #N21:20
 Dest: #N21:0
 Length: 2

R6:15.IN - [5]27,27,27,28,28,28,28
 R6:15.IN - [5]27,27,27,28,28,28,28
 R6:15.IN - [5]wf26,27,29
 R6:15.IN - [5]wf26,27,29
 R6:15.IN - [5]wf27,27
 MG11:5.EN - [5]27,27,127
 MG11:5.EN - [5]wf27,27
 MG11:5.EN - [5]wf27

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 SEQUENCING TO HANDLE THE OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.
 Page:00020

HNF-2346, Rev. 1

File #5 COMM_FILE Proj:PLC5

15:54:20 02/18/99

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 SEQUENCING TO HANDLE THE OIT DATA TO AND FROM PLC-1
 Lockheed Martin Hanford Co.
 Page:00021

HNF-2346, Rev. 1

15:54:21 02/18/99

File #5 COMM_FILE Proj:PLC5

5:0031 COMMUN. WITH
 PCU-1
 IGNORED
 COM-51
 N14:0/1
 -|/|

R6:14.IN
 (U)

MG11:6.EN

+--FSC-----+
 |File Search/Compare|-(EN)-+
 |Control: R6:14|
 |Length: 2|-(DN)
 |Position: 0|
 |Mode: ALL|-(ER)
 |Expression:|
 |#N14:320 <> #N21:100|

R6:14.FD

+--COP-----+
 |Copy File|
 |Source: #N14:320|
 |Dest: #N21:125|
 |Length: 2|

+--MSG-----+
 |Send/Receive Message|-(EN)-+
 |Control Block: MG11:6|-(DN)
 |-(ER)

MG11:6.DN 83/164

+--COP-----+
 |Copy File|
 |Source: #N21:125|
 |Dest: #N21:100|
 |Length: 2|

R6:14.IN - [5]31,31,31,32,32,32,32
 R6:14.IN - [5]31,31,31,32,32,32,32
 R6:14.IN - [5]wf31,31
 R6:14.IN - [5]wf31,31
 R6:14.IN - [5]wf31,31
 MG11:6.EN - [5]31,31,31
 MG11:6.EN - [5]wf31,31
 MG11:6.EN - [5]wf31

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
SEQUENCING TO HANDLE THE OIT DATA TO AND FROM PLC-1
Lockheed Martin Hanford Co.
Page:00022

HNF-2346, Rev. 1

15:54:21 02/18/99

File #5 COMM_FILE Proj:PLC5

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
PCU-5 LEAK DETECTION CONTROL LOGIC (Y-72.1)
Lockheed Martin Hanford Co.
Page:00023

HNF-2346, Rev. 1

File #6 Proj:PLC5

15:54:21 02/18/99

```

GENERAL FILE
SUBROUTINE
6:0000 +---SBR-----+
      |Subroutine|-----
      +---+

B3/41      - [6]0

244-A
ENCASEMENT
LEAK DETECTION
[OFF = ALARM]
Y-72
      LDK-3162
      I:000/00
      I:1771-IBD
6:0001 -----
      N19:5/15      - [6]1

6:0002 +---RET-----+
      |Return ()|-----
      +---+

6:0003 -----[End]-----
```

PROGRAM
FILE #6 START
OF SUBROUTINE
COMMENT COIL

B3/41

( )

LEAK DETECTED
IN LINE TO
244-A LIFT
STATION
Y72-1

N19:5/15

( )

+---RET-----+
|Return ()|-----
+---+

[End]

APPENDIX E

DB Form Report Sorted By: Address

I:000	DIGITAL INPUT	REGISTER	LEAK DETECTION	[OFF = ALARM]	Y-72
I:000/000	LDK-3162 244-A	ENCASEMENT			
I:000/001					
I:000/002					
I:000/003					
I:000/004					
I:000/005					
I:000/006					
I:000/007					
I:000/010					
I:000/011					
I:000/012					
I:000/013					
I:000/014					
I:000/015					
I:000/016					
I:000/017					
S:000/000	Processor	arithmetic	carry	flag	
S:000/001	Processor	arithmetic	overflow/	overflow	flag
S:000/002	Processor	arithmetic	zero	flag	
S:000/003	Processor	arithmetic	sign	flag	
S:001/000	Bad RAM	CHECKSUM	at power	up	
S:001/001	PLC-5 in	TEST mode			
S:001/002	PLC-5 in	PROG mode			
S:001/003	PLC-5 in	burning an	EEPROM	progress	
S:001/004	Download-	ing in			
S:001/005	Test edits	enabled			
S:001/006	Mode	switch	in REMOTE		
S:001/007	Forces	enabled			
S:001/008					
S:001/009	Forces	present		Burned	
S:001/010	EEPROM	success-	fully	ming	
S:001/011	Perform-	ing online	program-		
S:001/012	Processor	is in	DEBUG mode		
S:001/013	User	program	CHECKSUM	done	
S:001/014	Last scan	of ladder	or SFC	step	
S:001/015	First scan	of ladder	or SFC	step	
S:007/000	Logical Rack	Status Bits	For Racks 0-7		
S:007/001	Rack 0	Faulted			
S:007/001	Rack 1	Faulted			
S:007/002					
S:007/003	Rack 2	Faulted			
S:007/004	Rack 3	Faulted			
S:007/005	Rack 4	Faulted			
S:007/006	Rack 5	Faulted			
S:007/006	Rack 6	Faulted			
S:007/007	Rack 7	Faulted			
S:007/008	Block Xfer	queue to	rack 0 is	full	
S:007/009	Block Xfer	queue to	rack 1 is	full	
S:007/010	Block Xfer	queue to	rack 2 is	full	
S:007/011	Block Xfer	queue to	rack 3 is	full	
S:007/012					
S:007/013	Block Xfer	queue to	rack 4 is	full	
S:007/014	Block Xfer	queue to	rack 5 is	full	
S:007/015	Block Xfer	queue to	rack 6 is	full	
S:008	Last	program	scan time	ladder &	SFC
S:009	Maximum	program	scan time	ladder &	SFC
S:010/000	Battery	is bad or	missing		
S:010/001	DH+ active	node table	changed		
S:010/002	STI	overlap			
S:010/003	EEPROM	trans-	ferred		
S:010/004					
S:010/005	Edits	prevent	SFC	continuing	
S:010/006	Invalid	I/O status	file		
S:010/006	Memory	cartridge	battery	low	
S:010/007	No more	command	blocks	exist	
S:010/009	No MCP was	configured	to run		
S:010/010	MCP not	allowed			
S:010/011	PIL word	number	isn't in	local rack	
S:010/012	User PIL	routine	overlap	get PIL	
S:010/013	No command	block	exists to		
S:010/014	Arithmetic	overflow	occurred		
S:010/015					
S:011/000	SFC	lingering	action	overlap	
S:011/000	Bad	program	file		
S:011/001	Bad	address	in ladder	program	
S:011/002	Programmer	error			
S:011/003	SFC Fault				
S:011/004	Program	assembly	error		
S:011/005	Powerup	protection	fault		
S:011/006	Error not	defined			
S:011/007	User	generated	fault		
S:011/008	Watchdog	timer	fault		
S:011/009					
S:011/009	Bad system	config-	uration		

APPENDIX E

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

15:54:30 02/18/99

S:011/010	Hardware	Error			
S:011/011	WCP file	does not	exist or	is not	ladder
S:011/012	PII file	does not	exist or	is not	ladder
S:011/013	STI file	does not	exist or	is not	ladder
S:011/014	Fault file	does not	exist or	is not	ladder
S:011/015	Non ladder	file			
S:012	Fault Code				
S:013	Program	file where	fault	occurred	
S:014	Run	number	where	fault	occurred
S:016	I/O status	file			
S:017/000	Queue full	between	local and	remote I/O	
S:017/001	Queue full	servicing	channel 1A		
S:017/002	Queue full	servicing	channel 1B		
S:017/003	Queue full	servicing	channel 2A		
S:017/004	Queue full	servicing	channel 2B		
S:017/005	No modem	on serial	port		
S:017/006	Remote I/O	is greater	than image	size	
S:017/008	ASCII	instruct-	ion error		
S:017/009	Duplicate	node	address		
S:018	Real time	clock YEAR			
S:019	Real time	clock	MONTH		
S:020	Real time	clock DAY			
S:021	Real time	clock HOUR			
S:022	Real time	clock	MINUTE		
S:023	Real time	clock	SECOND		
S:023/000	REAL TIME	CLOCK	SECOND	ONE'S BIT	
S:023/001	REAL TIME	CLOCK	SECOND	TWO'S BIT	
S:024	Indexed	Addressing	Offset		
S:025	Adapter	Image	File		
S:026/000	SFC	Restart/	Continue		
S:026/001	Start-up	protect-	ion after	power loss	
S:026/002	Local rack	is 1 if	set or 0	if bit = 0	
S:026/003	Complementary	Rack	Mode		
S:027/000	Rack 0	Inhibit			
S:027/001	Rack 1	Inhibit			
S:027/002	Rack 2	Inhibit			
S:027/003	Rack 3	Inhibit			
S:027/004	Rack 4	Inhibit			
S:027/005	Rack 5	Inhibit			
S:027/006	Rack 6	Inhibit			
S:027/007	Rack 7	Inhibit			
S:027/008	Rack 0	Reset			
S:027/009	Rack 1	Reset			
S:027/010	Rack 2	Reset			
S:027/011	Rack 3	Reset			
S:027/012	Rack 4	Reset			
S:027/013	Rack 5	Reset			
S:027/014	Rack 6	Reset			
S:027/015	Rack 7	Reset			
S:028	Watchdog	Timer	Setpoint		
S:029	Fault	routine	file	number	
S:030	STI	setpoint	(interval)		
S:031	STI	file	number		
S:032	Logical Rack	Status Bits	For Racks 10-17		
S:032/000	Rack 10	Faulted			
S:032/001	Rack 11	Faulted			
S:032/002	Rack 12	Faulted			
S:032/003	Rack 13	Faulted			
S:032/004	Rack 14	Faulted			
S:032/005	Rack 15	Faulted			
S:032/006	Rack 16	Faulted			
S:032/007	Rack 17	Faulted			
S:032/008	Block Xfer	queue to	rack 10 is	full	
S:032/009	Block Xfer	queue to	rack 11 is	full	
S:032/010	Block Xfer	queue to	rack 12 is	full	
S:032/011	Block Xfer	queue to	rack 13 is	full	
S:032/012	Block Xfer	queue to	rack 14 is	full	
S:032/013	Block Xfer	queue to	rack 15 is	full	
S:032/014	Block Xfer	queue to	rack 16 is	full	
S:032/015	Block Xfer	queue to	rack 17 is	full	
S:033/000	Rack 10	Inhibit			
S:033/001	Rack 11	Inhibit			
S:033/002	Rack 12	Inhibit			
S:033/003	Rack 13	Inhibit			
S:033/004	Rack 14	Inhibit			
S:033/005	Rack 15	Inhibit			
S:033/006	Rack 16	Inhibit			
S:033/007	Rack 17	Inhibit			
S:033/008	Rack 10	Reset			
S:033/009	Rack 11	Reset			
S:033/010	Rack 12	Reset			

APPENDIX E

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

15:54:30 02/18/99

S: 093/011	Rack 13	Reset			
S: 093/012	Rack 14	Reset			
S: 093/013	Rack 15	Reset			
S: 093/014	Rack 16	Reset			
S: 093/015	Rack 17	Reset			
S: 034/000	Rack 20	Faulted			
S: 034/001	Rack 21	Faulted			
S: 034/002	Rack 22	Faulted			
S: 034/003	Rack 23	Faulted			
S: 034/004	Rack 24	Faulted			
S: 034/005	Rack 25	Faulted			
S: 034/006	Rack 26	Faulted			
S: 034/007	Rack 27	Faulted			
S: 034/008	Block Xfer	queue to	rack 20 is	full	
S: 034/009	Block Xfer	queue to	rack 21 is	full	
S: 034/010	Block Xfer	queue to	rack 22 is	full	
S: 034/011	Block Xfer	queue to	rack 23 is	full	
S: 034/012	Block Xfer	queue to	rack 24 is	full	
S: 034/013	Block Xfer	queue to	rack 25 is	full	
S: 034/014	Block Xfer	queue to	rack 26 is	full	
S: 034/015	Block Xfer	queue to	rack 27 is	full	
S: 035/000	Rack 20	Inhibit			
S: 035/001	Rack 21	Inhibit			
S: 035/002	Rack 22	Inhibit			
S: 035/003	Rack 23	Inhibit			
S: 035/004	Rack 24	Inhibit			
S: 035/005	Rack 25	Inhibit			
S: 035/006	Rack 26	Inhibit			
S: 035/007	Rack 27	Inhibit			
S: 035/008	Rack 20	Reset			
S: 035/009	Rack 21	Reset			
S: 035/010	Rack 22	Reset			
S: 035/011	Rack 23	Reset			
S: 035/012	Rack 24	Reset			
S: 035/013	Rack 25	Reset			
S: 035/014	Rack 26	Reset			
S: 035/015	Rack 27	Reset			
S: 048	P11	file	number		
S: 047	P11	module	group to	examine	
S: 048	P11	bit	mask		
S: 048/000	P11 Module	Bit	1=Monitor	0=Ignore	
S: 049	P11	compare	value		
S: 049/000	P11 Bit	1=false to	TRUE	0=	true to
S: 050	P11 down	count			
S: 051	P11 return	mask			
S: 052	P11 accum-	ulator			
S: 053	STI last	scan time			
S: 054	STI max	scan time			
S: 055	P11 last	scan time			
S: 056	P11 max	scan time			
S: 079/000	Main	control	program A	disable	bit
S: 079/001	Main	control	program B	disable	bit
S: 079/002	Main	control	program C	disable	bit
S: 079/003	Main	control	program D	disable	bit
S: 079/004	Main	control	program E	disable	bit
S: 079/005	Main	control	program F	disable	bit
S: 079/006	Main	control	program G	disable	bit
S: 079/007	Main	control	program H	disable	bit
S: 079/008	Main	control	program I	disable	bit
S: 079/009	Main	control	program J	disable	bit
S: 079/010	Main	control	program K	disable	bit
S: 079/011	Main	control	program L	disable	bit
S: 079/012	Main	control	program M	disable	bit
S: 079/013	Main	control	program N	disable	bit
S: 079/014	Main	control	program O	disable	bit
S: 079/015	Main	control	program P	disable	bit
S: 080	Main	control	program A	file	number
S: 081	Program A	scan time			
S: 082	Program A	maximum	scan time		
S: 083	Main	control	program B	file	number
S: 084	Program B	scan time			
S: 085	Program B	maximum	scan time		
S: 086	Main	control	program C	file	number
S: 087	Program C	scan time			
S: 088	Program C	maximum	scan time		
S: 089	Main	control	program D	file	number
S: 090	Program D	scan time			
S: 091	Program D	maximum	scan time		
S: 092	Main	control	program E	file	number
S: 093	Program E	scan time			
S: 094	Program E	maximum	scan time		

APPENDIX E

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

15:54:31 02/18/99

S:095	Main	control	program F	file	number
S:096	Program F	scan time			
S:097	Program F	maximum	scan time		
S:098	Main	control	program G	file	number
S:099	Program G	scan time			
S:100	Program G	maximum	scan time		
S:101	Main	control	program H	file	number
S:102	Program H	scan time			
S:103	Program H	maximum	scan time		
S:104	Main	control	program I	file	number
S:105	Program I	scan time			
S:106	Program I	maximum	scan time		
S:107	Main	control	program J	file	number
S:108	Program J	scan time			
S:109	Program J	maximum	scan time		
S:110	Main	control	program K	file	number
S:111	Program K	scan time			
S:112	Program K	maximum	scan time		
S:113	Main	control	program L	file	number
S:114	Program L	scan time			
S:115	Program L	maximum	scan time		
S:116	Main	control	program M	file	number
S:117	Program M	scan time			
S:118	Program M	maximum	scan time		
S:119	Main	control	program N	file	number
S:120	Program N	scan time			
S:121	Program N	maximum	scan time		
S:122	Main	control	program O	file	number
S:123	Program O	scan time			
S:124	Program O	maximum	scan time		
S:125	Main	control	program P	file	number
S:126	Program P	scan time			
S:127	Program P	maximum	scan time		
BO03/000	ALWAYS OFF	ALWAYS OFF	OUTPUT		
BO03/001	ALWAYS ON	ALWAYS ON	OUTPUT		
BO03/002	1 SEC PULSE	ONE SECOND	SINGLE SCAN	PULSE	
BO03/003	2 SEC PULSE	TWO SECOND	SINGLE SCAN	PULSE	
BO03/004	HALF SEC FLASH	HALF SECOND	FLASHER		
BO03/005	1 SEC FLASH	ONE SECOND	FLASHER		
BO03/006	2 SEC FLASH	TWO SECOND	FLASHER		
BO03/007					
BO03/008					
BO03/009					
BO03/010					
BO03/011					
BO03/012					
BO03/013					
BO03/014					
BO03/015					
BO03/001	TWO SCAN SUB-	DIVISIONS	REGISTER		
BO03/016	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIRST SET)	
BO03/017	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SECOND SET)	
BO03/018	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRD SET)	
BO03/019	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTH SET)	
BO03/020	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTH SET)	
BO03/021	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTH SET)	
BO03/022	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SEVENTH SET)	
BO03/023	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(EIGHTH SET)	
BO03/024	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(NINTH SET)	
BO03/025	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TENTH SET)	
BO03/026	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(ELEVENTH SET)	
BO03/027	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(TWELFTH SET)	
BO03/028	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(THIRTEENTH SET)	
BO03/029	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FOURTEENTH SET)	
BO03/030	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(FIFTEENTH SET)	
BO03/031	TWO SCAN SUB-	DIVISIONS TWO	SECONDS APART	(SIXTEENTH SET)	
BO03/032	ONE SECOND	RISING	ONE SHOT		
BO03/033	ONE SECOND	FALLING	ONE SHOT		
BO03/034	TWO SECOND	RISING	ONE SHOT		
BO03/035	TWO SECOND	FALLING	ONE SHOT		
BO03/036	PROGRAM FILE	JUMP-TO-SUBR.	CONTROL RUNGS	COMMENT COIL	
BO03/037	MCP FILE #2	END OF PROGRAM	COMMENT COIL		
BO03/038	FAULT ROUTINE	FILE #3	END OF PROGRAM	COMMENT COIL	
BO03/039	PROGRAM	FILE #4 START	OF SUBROUTINE	COMMENT COIL	
BO03/040	PROGRAM	FILE #5 START	OF SUBROUTINE	COMMENT COIL	
BO03/041	PROGRAM	FILE #6 START	OF SUBROUTINE	COMMENT COIL	
BO03/042					
BO03/043					
BO03/044					
BO03/046					
BO03/047					

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00028

HNF-2346, Rev. 1

15:54:31 02/18/99

DB Form Report Sorted By: Address

8003/076	COMMUN. LOSS	WITH PCU-1	ONE-SHOT		
8003/077	COMMUN. LOSS	WITH PCU-1	ONE-SHOT		
8003/078	COMMUN. LOSS	WITH PCU-2	ONE-SHOT		
8003/079	COMMUN. LOSS	WITH PCU-2	ONE-SHOT		
8003/080	COMMUN. LOSS	WITH PCU-3	ONE-SHOT		
8003/081	COMMUN. LOSS	WITH PCU-3	ONE-SHOT		
8003/082	COMMUN. LOSS	WITH PCU-4	ONE-SHOT		
8003/083	COMMUN. LOSS	WITH PCU-4	ONE-SHOT		
8003/200	COMMUN LOSS	WITH OCS	ONE-SHOT		
8003/201	COMMUN LOSS	WITH OCS	ONE-SHOT		
T004:000	POWER-UP	SEQUENCING	DELAY		
T004:000.ACC	POWER-UP	SEQUENCING	DELAY		
T004:000.DN					
T004:000.PRE					
T004:000.TT					
T004:001	HALF SECOND	FLASHER TIMER			
T004:001.ACC	HALF SECOND	FLASHER TIMER			
T004:001.DN					
T004:001.PRE					
T004:001.TT					
T004:002	COMMUN. LOSS	TIMER WITH	PCU-1		
T004:002.ACC	COMMUN. LOSS	TIMER WITH	PCU-1		
T004:002.DN					
T004:002.PRE					
T004:002.TT					
T004:003	COMMUN. LOSS	TIMER WITH	PCU-2		
T004:003.ACC	COMMUN. LOSS	TIMER WITH	PCU-2		
T004:003.DN					
T004:003.PRE					
T004:003.TT					
T004:004	COMMUN. LOSS	TIMER WITH	PCU-3		
T004:004.ACC	COMMUN. LOSS	TIMER WITH	PCU-3		
T004:004.DN					
T004:004.PRE					
T004:004.TT					
T004:005	COMMUN. LOSS	TIMER WITH	PCU-4		
T004:005.ACC	COMMUN. LOSS	TIMER WITH	PCU-4		
T004:005.DN					
T004:005.PRE					
T004:005.TT					
T004:040	COMM LOSS	TIMER	WITH OCS		
R006:000	TWO SCAN SUB-	DIVISIONS	CONTROL	REGISTER	
R006:000.EN	TWO SCAN SUB-	DIVISIONS	CONTROL	ENABLED	
R006:000.UL	TWO SCAN SUB-	DIVISIONS	CONTROL	UNLOAD	
R006:010	COMPARE	PCU-5 TO PCU-1	MSG FILE	WITH PREVIOUS	
R006:011	COMPARE	PCU-5 TO PCU-2	MSG FILE	WITH PREVIOUS	
R006:012	COMPARE	PCU-5 TO PCU-3	MSG FILE	WITH PREVIOUS	
R006:013	COMPARE	PCU-5 TO PCU-4	MSG FILE	WITH PREVIOUS	
N007:000					
N007:001					
N007:002					
N007:003					
N007:004					
N007:005					
N007:006					
N007:007					
N007:008					
N007:009					
N010:000	REGISTER FOR	VERIFYING	FAULTY ROUTINE	FILE OPERATION	
N010:007	Logical Rack	Fault Status	For Racks 0-7	And Racks 10-17	
N010:008	Last	program	scan time	ladder &	SFC
N010:009	Maximum	program	scan time	ladder &	SFC
N010:010/000	Battery	is bad or	missing		
N010:010/001	DH+ active	node table	changed		
N010:010/002	STI	overlap			
N010:010/003	EEPROM	trans-	ferred		
N010:010/004	Edits	prevent		continuing	
N010:010/005	Invalid	I/O status	file		
N010:010/006	Memory	cartridge	battery	low	
N010:010/007	No more	command	blocks	exist	
N010:010/009	No MCP was	configured	to run		
N010:010/010	MCP not	allowed			
N010:010/011	Pil word	number	isn't in	local rack	
N010:010/012	User Pil	routine	overlap		
N010:010/013	No command	block	exists to	get Pil	
N010:010/014	Arithmetic	overflow	occurred		
N010:010/015	SFC	lingering	action	overlap	
N010:011/000	Bad	program	file		
N010:011/001	Bad	address	in ladder	program	
N010:011/002	Programmer	error			
N010:011/003	SFC Fault				

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00029

HNF-2346, Rev. 1

15:54:00 02/18/99

DB Form Report Sorted By: Address

N010:011/004	Program	assembly	error		
N010:011/005	Powerup	protection	fault		
N010:011/006	Error not	defined	fault		
N010:011/007	User	generated	fault		
N010:011/008	Watchdog	timer	fault		
N010:011/009	Bad system	config-	uration		
N010:011/010	Hardware	Error			
N010:011/011	MCP file	does not	exist or	is not	ladder
N010:011/012	PLI file	does not	exist or	is not	ladder
N010:011/013	STI file	does not	exist or	is not	ladder
N010:011/014	Fault file	does not	exist or	is not	ladder
N010:011/015	Non ladder	file			
N010:012	Fault Code				
N010:013	Program	file where	fault	occurred	
N010:014	Rung	number	where	fault	occurred
N010:016	I/O status	file			
N010:017	REGISTER FOR	VERIFYING	FAULT ROUTINE	FILE OPERATION	
N010:017/000	Queue full	between	local and	remote I/O	
N010:017/001	Queue full	servicing	channel 1A		
N010:017/002	Queue full	servicing	channel 1B		
N010:017/003	Queue full	servicing	channel 2A		
N010:017/004	Queue full	servicing	channel 2B		
N010:017/005	No modem	on serial	port		
N010:017/006	Remote I/O	is greater	than image	size	
N010:017/008	ASCII	instruct-	ion error		
N010:017/009	Duplicate	node	address		
N010:018	Real time	clock YEAR			
N010:019	Real time	clock	MONTH		
N010:020	Real time	clock DAY			
N010:021	Real time	clock HOUR			
N010:022	Real time	clock	MINUTE		
N010:023	Real time	clock	SECOND		
MG011:000	SEND MSG	FROM PCU-5	TO PCU-1		
MG011:001	SEND MSG	FROM PCU-5	TO PCU-2		
MG011:002	SEND MSG	FROM PCU-5	TO PCU-3		
MG011:003	SEND MSG	FROM PCU-5	TO PCU-4		
N014:000					
N014:000/000	HB PLC5_OCS	HEARTBEAT	FROM PLC-5	TO OCS	
N014:000/001	COM-51	COMMUN. WITH	PCU-1	IGNORED	
N014:000/002	COM-52	COMMUN. WITH	PCU-2	IGNORED	
N014:000/003	COM-53	COMMUN. WITH	PCU-3	IGNORED	
N014:000/004	COM-54	COMMUN. WITH	PCU-4	IGNORED	
N014:000/005	COM-5_OCS	COMMUN. WITH	OCS	IGNORED	
N014:000/006	BATT_BAD_PLCS	PLC-5 BATTERY	IS BAD OR	MISSING	
N014:000/007					
N014:000/008					
N014:000/009					
N014:000/010					
N014:000/011					
N014:000/012					
N014:000/013					
N014:000/014					
N014:000/015					
N014:028					
N014:028/000	LDA-3162	244-A	REGISTER TO	OTI TERMINALS	
N014:028/001	PCU5-SP-10-01	SPARE DIGITAL	ENCASEMENT	LEAK DETECTION	[OFF = ALARM] Y-72
N014:028/002	PCU5-SP-10-02	SPARE DIGITAL	INPUT		
N014:028/003	PCU5-SP-10-03	SPARE DIGITAL	INPUT		
N014:028/004	PCU5-SP-10-04	SPARE DIGITAL	INPUT		
N014:028/005	PCU5-SP-10-05	SPARE DIGITAL	INPUT		
N014:028/006	PCU5-SP-10-06	SPARE DIGITAL	INPUT		
N014:028/007	PCU5-SP-10-07	SPARE DIGITAL	INPUT		
N014:028/008	PCU5-SP-10-10	SPARE DIGITAL	INPUT		
N014:028/009	PCU5-SP-10-11	SPARE DIGITAL	INPUT		
N014:028/010	PCU5-SP-10-12	SPARE DIGITAL	INPUT		
N014:028/011	PCU5-SP-10-13	SPARE DIGITAL	INPUT		
N014:028/012	PCU5-SP-10-14	SPARE DIGITAL	INPUT		
N014:028/013	PCU5-SP-10-15	SPARE DIGITAL	INPUT		
N014:028/014	PCU5-SP-10-16	SPARE DIGITAL	INPUT		
N014:028/015	PCU5-SP-10-17	SPARE DIGITAL	INPUT		
N014:029					
N014:030					
N014:031					
N014:032					
N014:033					
N014:034					
N014:120					
N014:120/000	HB_OCS_PLCS	HEARTBEAT	FROM OCS	TO PLC-5	
N014:120/001					
N014:120/002					
N014:120/003					

APPENDIX E

DB Form Report

Sorted By: Address

N014:120/004					
N014:120/005					
N014:120/006					
N014:120/007					
N014:120/008					
N014:120/009					
N014:120/010					
N014:120/011					
N014:120/012					
N014:120/013					
N014:120/014					
N014:120/015					
N014:150					
N014:151					
N014:152					
N014:153					
N014:154					
N014:200/000	HB_OCS_PLC5	HEARTBEAT	FROM OCS	TO PLC-5	
N014:200/001					
N014:200/002					
N014:200/003					
N014:200/004					
N014:200/005					
N014:200/006					
N014:200/007					
N014:200/008					
N014:200/009					
N014:200/010					
N014:200/011					
N014:200/012					
N014:200/013					
N014:200/014					
N014:200/015					
N014:320/000	HB_PLC5_OCS	HEARTBEAT	FROM PLC-5	TO OCS	
N014:320/001	COM-51	COMMUN. WITH	PCU-1	IGNORED	
N014:320/002	COM-52	COMMUN. WITH	PCU-2	IGNORED	
N014:320/003	COM-53	COMMUN. WITH	PCU-3	IGNORED	
N014:320/004	COM-54	COMMUN. WITH	PCU-4	IGNORED	
N014:320/005	COM-5_OCS	COMMUN. WITH	OCS	IGNORED	
N014:320/006	BATT_BAD_PLC5	PLC-5 BATTERY	IS BAD OR	MISSING	
N014:320/007					
N014:320/008					
N014:320/009					
N014:320/010					
N014:320/011					
N014:320/012					
N014:320/013					
N014:320/014					
N014:320/015					
N014:321/000	LDA-3162	244-A	ENCASEMENT	LEAK DETECTION	[OFF = ALARM] Y-72
N014:321/001	PCU5-SP-10-01	SPARE DIGITAL	INPUT		
N014:321/002	PCU5-SP-10-02	SPARE DIGITAL	INPUT		
N014:321/003	PCU5-SP-10-03	SPARE DIGITAL	INPUT		
N014:321/004	PCU5-SP-10-04	SPARE DIGITAL	INPUT		
N014:321/005	PCU5-SP-10-05	SPARE DIGITAL	INPUT		
N014:321/006	PCU5-SP-10-06	SPARE DIGITAL	INPUT		
N014:321/007	PCU5-SP-10-07	SPARE DIGITAL	INPUT		
N014:321/008	PCU5-SP-10-10	SPARE DIGITAL	INPUT		
N014:321/009	PCU5-SP-10-11	SPARE DIGITAL	INPUT		
N014:321/010	PCU5-SP-10-12	SPARE DIGITAL	INPUT		
N014:321/011	PCU5-SP-10-13	SPARE DIGITAL	INPUT		
N014:321/012	PCU5-SP-10-14	SPARE DIGITAL	INPUT		
N014:321/013	PCU5-SP-10-15	SPARE DIGITAL	INPUT		
N014:321/014	PCU5-SP-10-16	SPARE DIGITAL	INPUT		
N014:321/015	PCU5-SP-10-17	SPARE DIGITAL	INPUT		
N019:001/000					
N019:001/001					
N019:001/002	HB-12	HEARTBEAT	FROM PCU-1	TO PCU-2	
N019:001/003	HB-13	HEARTBEAT	FROM PCU-1	TO PCU-3	
N019:001/004	HB-14	HEARTBEAT	FROM PCU-1	TO PCU-4	
N019:001/005	HB-15	HEARTBEAT	FROM PCU-1	TO PCU-5	
N019:001/006					
N019:001/007					
N019:001/008					
N019:001/009					
N019:001/010					
N019:001/011					
N019:001/012					
N019:001/013					
N019:001/014					
N019:001/015					
N019:001/016					
N019:001/017					
N019:001/018					
N019:001/019					
N019:001/020					
N019:001/021					
N019:001/022					
N019:001/023					
N019:001/024					
N019:001/025					
N019:001/026					
N019:001/027					
N019:001/028					
N019:001/029					
N019:001/030					
N019:001/031					
N019:001/032					
N019:001/033					
N019:001/034					
N019:001/035					
N019:001/036					
N019:001/037					
N019:001/038					
N019:001/039					
N019:001/040					
N019:001/041					
N019:001/042					
N019:001/043					
N019:001/044					
N019:001/045					
N019:001/046					
N019:001/047					
N019:001/048					
N019:001/049					
N019:001/050					
N019:001/051					
N019:001/052					
N019:001/053					
N019:001/054					
N019:001/055					
N019:001/056					
N019:001/057					
N019:001/058					
N019:001/059					
N019:001/060					
N019:001/061					
N019:001/062					
N019:001/063					
N019:001/064					
N019:001/065					
N019:001/066					
N019:001/067					
N019:001/068					
N019:001/069					
N019:001/070					
N019:001/071					
N019:001/072					
N019:001/073					
N019:001/074					
N019:001/075					
N019:001/076					
N019:001/077					
N019:001/078					
N019:001/079					
N019:001/080					
N019:001/081					
N019:001/082					
N019:001/083					
N019:001/084					
N019:001/085					
N019:001/086					
N019:001/087					
N019:001/088					
N019:001/089					
N019:001/090					
N019:001/091					
N019:001/092					
N019:001/093					
N019:001/094					
N019:001/095					
N019:001/096					
N019:001/097					
N019:001/098					
N019:001/099					
N019:001/100					
N019:001/101					
N019:001/102					
N019:001/103					
N019:001/104					
N019:001/105					
N019:001/106					
N019:001/107					
N019:001/108					
N019:001/109					
N019:001/110					
N019:001/111					
N019:001/112					
N019:001/113					
N019:001/114					
N019:001/115					
N019:001/116					
N019:001/117					
N019:001/118					
N019:001/119					
N019:001/120					
N019:001/121					
N019:001/122					
N019:001/123					
N019:001/124					
N019:001/125					
N019:001/126					
N019:001/127					
N019:001/128					
N019:001/129					
N019:001/130					
N019:001/131					
N019:001/132					
N019:001/133					
N019:001/134					
N019:001/135					
N019:001/136					
N019:001/137					
N019:001/138					
N019:001/139					
N019:001/140					
N019:001/141					
N019:001/142					
N019:001/143					
N019:001/144					
N019:001/145					
N019:001/146					
N019:001/147					
N019:001/148					
N019:001/149					
N019:001/150					
N019:001/151					
N019:001/152					
N019:001/153					
N019:001/154					
N019:001/155					
N019:001/156					
N019:001/157					
N019:001/158					
N019:001/159					
N019:001/160					
N019:001/161					
N019:001/162					
N019:001/163					
N019:001/164					
N019:001/165					
N019:001/166					
N019:001/167					
N019:001/168					
N019:001/169					
N019:001/170					
N019:001/171					
N019:001/172					
N019:001/173					
N019:001/174					
N019:001/175					
N019:001/176					
N019:001/177					
N019:001/178					
N019:001/179					
N019:001/180					
N019:001/181					
N019:001/182					
N019:001/183					
N019:001/184					
N019:001/185					
N019:001/186					
N019:001/187					
N019:001/188					
N019:001/189					
N019:001/190					
N019:001/191					
N019:001/192					
N019:001/193					
N019:001/194					
N019:001/195					
N019:001/196					
N019:001/197					
N019:001/198					
N019:001/199					
N019:001/200					
N019:001/201					
N019:001/202					
N019:001/203					
N019:001/204					

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00031

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

15:54:01 02/18/99

N019:002/000		STOP BOOSTER	PUMP P-3125B &	TRANSFER PUMP	P-102-SY-02A	Y-74.2
N019:002/001	HB-21	HEARTBEAT	FROM PCU-2	TO PCU-1		
N019:002/002		STOP BOOSTER	PUMP P-3125A &	TRANSFER PUMP	P-102-SY-02A	Y-74.1
N019:002/003	HB-23	HEARTBEAT	FROM PCU-2	TO PCU-3		
N019:002/004	HB-24	HEARTBEAT	FROM PCU-2	TO PCU-4		
N019:002/005	HB-25	HEARTBEAT	FROM PCU-2	TO PCU-5		
N019:002/006		LEAK DETECTED	AT DIVERSION	BOX 6241-A	SUMP	Y-72.1
N019:002/007		LEAK DETECTED	IN LINE TO	DIVERSION	BOX 6241-A	Y-72.1
N019:002/008		SOV-3182A	VALVE	FAILURE		Y-71.1
N019:002/009		SOV-3182B	VALVE	FAILURE		Y-71.1
N019:002/010		SOV-3184	VALVE	FAILURE		Y-71.1
N019:002/011		SOV-3173A/B	VALVE	FAILURE		Y-73.1
N019:002/012		SOV-3183B	VALVE	FAILURE		Y-71.1
N019:002/013		SOV-3183A	VALVE	FAILURE		Y-71.1
N019:002/014		PUMP P-3125A	HIGH INLET	PRESSURE		Y-75.1
N019:002/015		PUMP P-3125B	HIGH INLET	PRESSURE		Y-75.1
N019:003/000		INPUT SIGNAL TO	200-W MASTER	SHUTDOWN	CIRCUIT	Y-72.1
N019:003/001	HB-31	HEARTBEAT	FROM PCU-3	TO PCU-1		
N019:003/002	HB-32	HEARTBEAT	FROM PCU-3	TO PCU-2		
N019:003/003						
N019:003/004	HB-34	HEARTBEAT	FROM PCU-3	TO PCU-4		
N019:003/005	HB-35	HEARTBEAT	FROM PCU-3	TO PCU-5		
N019:003/006						
N019:003/007		TRANSFER 2A	SHUTDOWN			Y-42.1
N019:003/008		TRANSFER 2B	SHUTDOWN			Y-43.1
N019:003/009						
N019:003/010		TRANSFER 1	INITIATED			Y-41.1
N019:003/011		TRANSFER 2A	INITIATED			Y-42.1
N019:003/012		TRANSFER 2B	INITIATED			Y-43.1
N019:003/013		TRANSFER 3	INITIATED			Y-44.1
N019:003/014						
N019:003/015		MASTER RESET				
N019:004/000						
N019:004/001	HB-41	HEARTBEAT	FROM PCU-4	TO PCU-1		
N019:004/002	HB-42	HEARTBEAT	FROM PCU-4	TO PCU-2		
N019:004/003	HB-43	HEARTBEAT	FROM PCU-4	TO PCU-3		
N019:004/004						
N019:004/005	HB-45	HEARTBEAT	FROM PCU-4	TO PCU-5		
N019:004/006						
N019:004/007		MOV-843	VALVE	FAILURE		Y71
N019:004/008		MOV-844	VALVE	FAILURE		Y71
N019:004/009		MOV-845	VALVE	FAILURE		Y71
N019:004/010		MOV-846	VALVE	FAILURE		Y71
N019:004/011		200-E MASTER	SHUTDOWN	CIRCUIT	ACTIVATED	Y-77.1
N019:004/012		RUPTURE	DISK FAILURE			Y-78.1
N019:004/013		LEAK DETECTED	AT 244-A LIFT	STATION	SUMP	Y-72.1
N019:004/014						
N019:004/015						
N019:005/000						
N019:005/001	HB-51	HEARTBEAT	FROM PCU-5	TO PCU-1		
N019:005/002						
N019:005/003	HB-52	HEARTBEAT	FROM PCU-5	TO PCU-2		
N019:005/004	HB-53	HEARTBEAT	FROM PCU-5	TO PCU-3		
N019:005/005	HB-54	HEARTBEAT	FROM PCU-5	TO PCU-4		
N019:005/006						
N019:005/007						
N019:005/008						
N019:005/009						
N019:005/010						
N019:005/011						
N019:005/012						
N019:005/013						
N019:005/014						
N019:005/015						
N021:080/000		LEAK DETECTED	IN LINE TO	244-A LIFT	STATION	Y72-1
N021:080/001		DH+ TRANSFER	FROM PCU-1	DATA REGISTERS		
N021:080/002						
N021:080/003						
N021:080/004						
N021:080/005						
N021:080/006						
N021:080/007						
N021:080/008						
N021:080/009						
N021:080/010						
N021:080/011						
N021:080/012						
N021:080/013						
N021:080/014						
N021:080/015						

APPENDIX E

DB Form Report Sorted By: Address

N021:081					
N021:082					
N021:083					
N021:084					
N022:080	DH+ TRANSFER	FROM PCU-2	DATA REGISTERS		
N022:080/000					
N022:080/001					
N022:080/002					
N022:080/003					
N022:080/004					
N022:080/005					
N022:080/006					
N022:080/007					
N022:080/008					
N022:080/009					
N022:080/010					
N022:080/011					
N022:080/012					
N022:080/013					
N022:080/014					
N022:080/015					
N022:081					
N022:082					
N022:083					
N022:084					
N023:080	DH+ TRANSFER	FROM PCU-3	DATA REGISTERS		
N023:080/000					
N023:080/001					
N023:080/002					
N023:080/003					
N023:080/004					
N023:080/005					
N023:080/006					
N023:080/007					
N023:080/008					
N023:080/009					
N023:080/010					
N023:080/011					
N023:080/012					
N023:080/013					
N023:080/014					
N023:080/015					
N023:081					
N023:082					
N023:083					
N023:084					
N024:080	DH+ TRANSFER	FROM PCU-4	DATA REGISTERS		
N024:080/000					
N024:080/001					
N024:080/002					
N024:080/003					
N024:080/004					
N024:080/005					
N024:080/006					
N024:080/007					
N024:080/008					
N024:080/009					
N024:080/010					
N024:080/011					
N024:080/012					
N024:080/013					
N024:080/014					
N024:080/015					
N024:081					
N024:082					
N024:083					
N024:084					
N025:000	DH+ TRANSFER	TO PCU-1	DATA REGISTERS		
N025:000/000					
N025:000/001					
N025:000/002					
N025:000/003					
N025:000/004					
N025:000/005					
N025:000/006					
N025:000/007					
N025:000/008					
N025:000/009					
N025:000/010					
N025:000/011					
N025:000/012					

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)

WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00033

HNF-2346, Rev. 1

15:54:02 02/18/99

DB Form Report Sorted By: Address

N025:000/013					
N025:000/014					
N025:000/015					
N025:001					
N025:002					
N025:003					
N025:004					
N025:020					
N025:020/000	DH+ TRANSFER	TO PCU-2	DATA REGISTERS		
N025:020/001					
N025:020/002					
N025:020/003					
N025:020/004					
N025:020/005					
N025:020/006					
N025:020/007					
N025:020/008					
N025:020/009					
N025:020/010					
N025:020/011					
N025:020/012					
N025:020/013					
N025:020/014					
N025:020/015					
N025:021					
N025:022					
N025:023					
N025:024					
N025:040	DH+ TRANSFER	TO PCU-3	DATA REGISTERS		
N025:040/000					
N025:040/001					
N025:040/002					
N025:040/003					
N025:040/004					
N025:040/005					
N025:040/006					
N025:040/007					
N025:040/008					
N025:040/009					
N025:040/010					
N025:040/011					
N025:040/012					
N025:040/013					
N025:040/014					
N025:040/015					
N025:041					
N025:042					
N025:043					
N025:044					
N025:060	DH+ TRANSFER	TO PCU-4	DATA REGISTERS		
N025:060/000					
N025:060/001					
N025:060/002					
N025:060/003					
N025:060/004					
N025:060/005					
N025:060/006					
N025:060/007					
N025:060/008					
N025:060/009					
N025:060/010					
N025:060/011					
N025:060/012					
N025:060/013					
N025:060/014					
N025:060/015					
N025:061					
N025:062					
N025:063					
N025:064					
N025:100	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N025:120	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N025:140	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
N025:160	DH+ MESSAGE	INSTRUCTION	COMPARATIVE	REGISTERS	
DFILE:000	OUTPUTS	Output Reg	isters And	Bits	
DFILE:001	INPUTS	Input Reg	siers And	Bits	
DFILE:002	SYSTEM	System Sta	tus Variab	les	
DFILE:003	.BITS	General In	ternal Bit	Addreses	
DFILE:004	TIMERS	General Ti	mer Addres	ses	
DFILE:005	COUNTERS	General Co	unter Addr	esses	
DFILE:006	CONTROL	General Co	ntrol Addr	esses	

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
 WL5 - Data Base Form Report
 Lockheed Martin Hanford Co.
 Page:00034

HNF-2346, Rev. 1

DB Form Report

Sorted By: Address

15:54:03 02/18/99

DFILE:007	INTEGERS	General In	Integer Addr	esses	
DFILE:008	FLOATING	General Fl	loating Poi	nt Address	es
DFILE:009	I/O STATUS	I/O Status	File (Use	d By The P	rocessor)
DFILE:010	PROC FLT	Stores Sys	tem Data 0	n A Proces	sor Fault
DFILE:011	GEN MSG	General	DH-Plus Me	ssage Cont	rol File
DFILE:012	GEN_BT	General	Block Tran	sfer Contr	ol File
DFILE:013	ANA_RAW	Analog Dat	a File		
DFILE:014	OIM DATA	OCS Commun	ication Fi	le	
DFILE:018	CONFIG1A	Channel 1A	Configura	tion Diag	File
DFILE:019	GLOBAL1A	Channel 1A	Config GI	obal Statu	s File
DFILE:020	ANA BUF	Analog I/O	Working F	ile	
DFILE:021	PLC1DATA	DATA FROM	PLC-1(DH+)		
DFILE:022	PLC2DATA	DATA FROM	PLC-2(DH+)		
DFILE:023	PLC3DATA	DATA FROM	PLC-3(DH+)		
DFILE:024	PLC4DATA	DATA FROM	PLC-4(DH+)		
DFILE:025	PLC5DATA	DATA FROM	PLC-5(DH+)		
PFILE:000	[SYSTEM DA	TA STORAGE	HEADER]		
PFILE:002	MAIN Progr	AM FILE			
PFILE:003	PROCESSOR	FAULT ROUT	TNE		
PFILE:004	I/O HANDLI	NG FOR ANA	LOG AND OT	HER REGIST	ER INPUTS
PFILE:005	COMMUNICAT	ION			
PFILE:006	GENERAL FI	LE			
0002:000	MAIN PROGRAM	FILE START-UP	JUMP TO JSR'S		
0003:001	MAIN PROGRAM	FILE START-UP	JUMP TO END		
0003:000	PROCESSOR	FAULT ROUTINE	JUMP TO END		
U:004	I/O HANDLING	FOR ANALOG OR	OTHER REG I/O	SUBROUTINE	
U:005	DATA HIGHWAY+	CTRL & CHECK	COMMUNICATION	SUBROUTINE	
U:006	GENERAL FILE	SUBROUTINE			
V:004	I/O HANDLING	FOR ANALOG OR	OTHER REG IN	SUBROUTINE	
V:005	DATA HIGHWAY+	CTRL & CHECK	COMMUNICATION	SUBROUTINE	
V:006	GENERAL FILE	SUBROUTINE			

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00035

HNF-2346, Rev. 1

DB Form Report Sorted By: Address

15:54:03 02/18/99

Addr:B3/0
TITLE:GENERAL USE BITS AND TIMING FUNCTIONS
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE OFF

Addr:B3/1
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG WILL ALWAYS BE ON

Addr:B3/2
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY SECOND. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY SECOND.

Addr:B3/3
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS TRUE ONE SCAN EVERY TWO SECONDS. IT IS USED TO ACTIVATE LOGIC THAT IS TO BE EXECUTED ONCE EVERY TWO SECONDS.

Addr:B3/4
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A HALF SECOND FLASHER. IT MAY BE USED FOR A FAST FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/5
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A ONE SECOND FLASHER. IT MAY BE USED FOR A NORMAL FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/6
RUNG DESCRIPTION:
THE OUTPUT OF THIS RUNG IS A TWO SECOND FLASHER. IT MAY BE USED FOR A SLOW FLASHER ON OPERATOR OUTPUT DEVICES.

Addr:B3/36
TITLE:PROGRAM FILE JUMP-TO-SUBROUTINE CONTROL RUNGS
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SCANNED DURING THE POWER-UP SEQUENCING

Addr:B3/37
RUNG DESCRIPTION:
THIS IS THE END OF THE MAIN PROGRAM CONTROL FILE

Addr:B3/39
TITLE:ANALOG INPUTS BLOCK TRANSFER SEQUENCING

Addr:B3/40
TITLE:COMMUNICATION HANDLING SUBROUTINE

Addr:B3/41
TITLE:PCU-5 LEAK DETECTION CONTROL LOGIC (Y-72.1)

Addr:B3:1
RUNG DESCRIPTION:
THIS RUNG PROVIDES UP TO SIXTEEN SUBDIVISIONS EVERY TWO SECONDS FOR TRIGGERING SUBROUTINES. THE BITS FROM B3/16 TO B3/31 WILL BE SET ON DIFFERENT SCANS BASED ON THE BIT PATTERN LOADED INTO B3:1. EACH BIT WILL BE SET FOR TWO SCANS. IF A ONE IS LOADED INTO B3:1, THE BIT SETTING WILL START WITH B3/16 ON THE SAME SCAN AS THE TWO SECOND SINGLE SCAN PULSE. THESE BITS CAN BE USED TO DIVIDE PORTIONS OF THE SEQUENCING WHICH ONLY NEED TO HAPPEN ONCE EVERY OTHER SECOND OR SO AMONG MULTIPLE SCANS. THE PLC PROGRAM SCAN TIME MUST BE LESS THAN SIXTY MILLI-SECONDS IF ALL SIXTEEN DIVISIONS ARE GOING TO BE USED.

Addr:N14:0/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND OCS

Addr:N14:200
TITLE:SEQUENCING TO HANDLE THE OIT DATA TO AND FROM PLC-1

Addr:N16:0/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-1

APPENDIX E

Hanford Cross Site Transfer System (PCU-5)
WL5 - Data Base Form Report
Lockheed Martin Hanford Co.
Page:00036

HNF-2346, Rev. 1

15:54:03 02/18/99

DB Form Report Sorted By: Address

Addr:N16:20/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-2

Addr:N16:40/1
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-3

Addr:N16:60/0
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-4

Addr:N19:5/1
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-1

Addr:N19:5/2
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-2

Addr:N19:5/3
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-3

Addr:N19:5/4
RUNG DESCRIPTION:
COMMUNICATION BETWEEN PCU-5 AND PCU-4

Addr:02:1
RUNG DESCRIPTION:
THE JSR'S FOLLOWING THIS RUNG WILL BE SKIPPED DURING THE POWER-UP SEQUENCING

Addr:03:0
TITLE:PROCESSOR FAULT ROUTINE PROGRAM FILE.
RUNG DESCRIPTION:
THE FAULT ROUTINE RUNS AUTOMATICALLY ON THE FIRST AND LAST SCAN OF THE PROCESSOR. FIRST SCAN WILL OCCURE ON POWER UP AND WHEN THE PROCESSOR IS SWITCHED INTO RUN MODE. LAST SCAN WILL OCCURE ON POWER DOWN, A PROCESSOR FAULT, AND WHEN THE PROCESSOR IS SWITCHED INTO PROGRAM MODE. THE STATUS DATA WILL ONLY BE COPIED INTO THE INTEGER FILE ON A LAST SCAN, DUE TO THE FIRST SCAN JUMP PROGRAMMED IN RUNG ZERO.

Addr:T4:0
TITLE:MAINLINE PROGRAM INITIALIZATION JUMP
RUNG DESCRIPTION:

THIS PROGRAM WAS WRITTEN BY: Programmable Control Services, Inc.
P.O. Box 28970
Spokane, WA 99228-8970
(509) 466-2656

THE MAINLINE PROGRAM CONTROLS GENERAL FUNCTIONS AND PROGRAM SEQUENCING.
THE FIRST THREE RUNGS IN THE PROGRAM ENSURE THAT THE PROGRAM SEQUENCING IS NOT SCANNED UNTIL THE I/O HAS BEEN UPDATED ON POWERUP OR
ENTERING RUN MODE. THE MAIN PROGRAM LOGIC IS NOT EXECUTED UNTIL ANY REMOTE OR BLOCK TRANSFERED I/O HAS BEEN READ.
TIMER T4:0 IS
USED TO SET THIS TIME DELAY.

Addr:T4:1
RUNG DESCRIPTION:
THE OUTPUT OF THIS TIMER IS USED TO ACTIVATE A 1/2 SECOND FLASHER.