ENGINEERING CHANGE NOTICE

Page 1 of

1. ECN 657667

Proj.
ECN

2. ECN Category (mark one) Supplemental ☐ Direct Revision ☒ Change ECN ☐ Temporary ☐ Standby ☐ Supersedure ☐ Cancel/Void ☐		3. Originator's Name, Organization, MSIN, and Telephone No. N. E. Wilkins, N1B10000, T5-55, 373-3685		4. USQ Required? ☒ Yes ☐ No		5. Date 3/16/00			
		6. Project Title/No./Work Order No. Thermal Stabilization/110893		7. Bldg./Sys./Fac. No. 234-5Z/PFP		8. Approval Designator S			
		9. Document Numbers Changed by this ECN (includes sheet no. and rev.) WHC-SD-CP-OCD-040, Rev. 2D		10. Related ECN No(s). N/A		11. Related PO No. N/A			
12a. Modification Work ☐ Yes (fill out Blk. 12b) ☒ No (NA Blks. 12b, 12c, 12d)		12b. Work Package No. N/A		12c. Modification Work Completed N/A Design Authority/Cog. Engineer Signature & Date		12d. Restored to Original Condition (Temp. or Standby ECNs only) N/A Design Authority/Cog. Engineer Signature & Date			
13a. Description of Change Add section 3.7, "Heating Cycle for Pu Metal". Add Attachment F "Burning Plutonium Metal Buttons Using an Igniter". Delete section titled "Fire Suppression System Activation Temperature" (formerly Section 6.1). <i>USQ WHC-SD-CP-OCD-040 Rev. 3 attached. - NEW 3/30/00</i>								13b. Design Baseline Document? ☒ Yes ☐ No	
14a. Justification (mark one) Criteria Change ☐ Design Improvement ☒ Environmental ☐ Facility Deactivation ☐ As-Found ☐ Facilitate Const. ☐ Const. Error/Omission ☐ Design Error/Omission ☐		14b. Justification Details Pu Metal will be processed through the HC-21C furnaces. A technical justification of the heating cycle (Section 3.7) and previous experimental results from heating Pu Metal in a furnace (Attachment F) are being added to the document. The section concerning the fire suppression system activation temperature is being deleted because the responsibility for maintaining this system lies with the Hanford Fire Department, not Thermal Stabilization.							
15. Distribution (include name, MSIN, and no. of copies) N E Wilkins: T5-55 H R Risenmay T5-55 A M Stubbs T5-55 K A Larkin T5-55 S E Nunn T5-11 R A Burk T4-20						RELEASE STAMP APR 03 2000 DATE: STA: 4 ID: HANFORD RELEASE			

ENGINEERING CHANGE NOTICE

Page 2 of 25

1. ECN (use no. from pg. 1)

657667

16. Design Verification Required

☐ Yes

☒ No

17. Cost Impact

ENGINEERING

Additional ☐ \$ N/A

Savings ☐ \$ N/A

CONSTRUCTION

Additional ☐ \$ N/A

Savings ☐ \$ N/A

18. Schedule Impact (days)

Improvement ☐ N/A

Delay ☐ N/A

19. Change Impact Review: Indicate the related documents (other than the engineering documents identified on Side 1) that will be affected by the change described in Block 13. Enter the affected document number in Block 20.

SDD/DD	☐	Seismic/Stress Analysis	☐	Tank Calibration Manual	☐
Functional Design Criteria	☐	Stress/Design Report	☐	Health Physics Procedure	☐
Operating Specification	☒	Interface Control Drawing	☐	Spares Multiple Unit Listing	☐
Criticality Specification	☐	Calibration Procedure	☐	Test Procedures/Specification	☐
Conceptual Design Report	☐	Installation Procedure	☐	Component Index	☐
Equipment Spec.	☐	Maintenance Procedure	☐	ASME Coded Item	☐
Const. Spec.	☐	Engineering Procedure	☐	Human Factor Consideration	☐
Procurement Spec.	☐	Operating Instruction	☐	Computer Software	☐
Vendor Information	☐	Operating Procedure	☐	Electric Circuit Schedule	☐
OM Manual	☐	Operational Safety Requirement	☐	ICRS Procedure	☐
FSAR/SAR	☐	IEFD Drawing	☐	Process Control Manual/Plan	☐
Safety Equipment List	☐	Cell Arrangement Drawing	☐	Process Flow Chart	☐
Radiation Work Permit	☐	Essential Material Specification	☐	Purchase Requisition	☐
Environmental Impact Statement	☐	Fac. Proc. Samp. Schedule	☐	Tickler File	☐
Environmental Report	☐	Inspection Plan	☐		☐
Environmental Permit	☐	Inventory Adjustment Request	☐		☐

20. Other Affected Documents: (NOTE: Documents listed below will not be revised by this ECN.) Signatures below indicate that the signing organization has been notified of other affected documents listed below.

Document Number/Revision

Document Number/Revision

Document Number/Revision

OSD-Z-184-00006/D-6

21. Approvals

Signature

Date

Design Authority H. Rees Reisinger 3-23-2000

Cog. Eng. R.A. Burk 3/30/00

Cog. Mgr. OR Smith 3-30-00

QA S.E. Nunn 3-29-00

Safety S.E. Nunn 3-29-00

Environ. _____

Other _____

Signature

Date

Design Agent Mary E. Williams 3/16/00

PE _____

QA _____

Safety _____

Design _____

Environ. _____

Other _____

This Document is UNCLASSIFIED.
Work Performed under this requirement is
☒ UNCLASSIFIED
☐ CONFIDENTIAL
☐ SECRET
W. J. R. 04/03/00
Signature Date
AUTHORIZED CLASSIFIER

DEPARTMENT OF ENERGY

Signature or a Control Number that tracks the Approval Signature

ADDITIONAL

**UNREVIEWED SAFETY QUESTION (USQ)
SCREENING AND EVALUATION**

ECN 657667

Page 1 of 3

3/5 11/1/00

1. Identification Number: ZO-160-038 A-0
ZO-160-039 A-0, OSD-Z-184-00006 D-7
WHC-SD-CP-OCD-040 Rev 3

USQ SCREENING

2. Title: Add Plutonium Metal Processing to Thermal Stabilization Procedures

DESCRIPTION

Sections are being added to the OSD and OCD for thermal stabilization to describe the heating cycle for plutonium metal. Section 6.6.1 of the OSD, "Fire Suppression System Activation Temperature", will be deleted. New procedures are being written for furnace charge preparation for plutonium metal and oxidizing the plutonium metal in Glovebox HC-21C.

INTRODUCTION

Vault personnel have begun a program of radiographing plutonium metal cans. Metal that appears to be corroded will be processed through the furnaces in Glovebox HC-21C. The fire suppression system activation temperature will be deleted because it is not maintained by PFP Stabilization.

AFFECTED SSC

HC-21C glovebox and furnaces, HC-21A glovebox

AUTHORIZATION BASIS

The authorization basis documents considered for review included those listed in FSP-PFP-5-8, Section 2.23, Appendix A. Those applicable are:

HNF-SD-CP-SAR-021, Rev. 1

Letter FDH-9954877 R1, which includes HNF-4823, Rev. 0, "Hazards Evaluation of Plutonium Metal Opening and Stabilization" and USQ Evaluation PFP 99-017, "Pu Metal Reaction Upon Opening Item with Paneled Inner Container" (Approved by DOE Letter 99-TPD-326)

HNF-4823 and Pu metal as a feed stream into the HC-21C furnaces is scheduled to be incorporated into the next update of the FSAR (DOE Letter 99-TPD-326).

CONCLUSION

These changes will not affect the plant's safety envelope in any way.

REFERENCES

HNF-SD-CP-SDD-010, "Definition and Means of Maintaining the Fire Protection System Portion of the PFP Safety

ECN 657667

UNREVIEWED SAFETY QUESTION (USQ) SCREENING AND EVALUATION

1. Identification Number: ZO-160-038 A-0
ZO-160-039 A-0, OSD-Z-184-00006 D-7
WHC-SD-CP-OCD-040 Rev 3

USQ SCREENING

Page 2 of 3
4 5 4/3/00

2. Title: Add Plutonium Metal Processing to Thermal Stabilization Procedures

QUESTIONS

1. Does the proposed change or occurrence represent a change to the facility or procedures as described in the Authorization Basis?

☐ N/A ☒ No ☐ Yes/Maybe

BASIS: A hazard analysis was done of the activities involved with stabilizing Pu metal in the HC-21C furnaces (HNF-4823) which was included in the Authorization Basis for PFP. The procedures for Pu metal include only the activities evaluated (as listed on pages 2 and 3 of HNF-4823). USQ 99-017 has an evaluation of the various accidents that can be associated with stabilizing plutonium metal in the HC-21C furnaces, and it concluded that thermal stabilization of plutonium metal was not outside the Authorization Basis, as long as certain operating restrictions were lifted. DOE Letter 99-TPD-326 lifted the operating restrictions. These procedures do not represent a change to thermal stabilization activities as described in the Authorization Basis.

In SDD-010, Section 5.2.1, it states that the Hanford Fire Department is responsible for testing, maintenance, and inspection of the dry chemical and Halon fire suppression systems. Thermal stabilization personnel are not responsible for the correct operation of the fire suppression system, and this section is being removed from the OSD.

2. Does the proposed change or occurrence represent conditions that have not been analyzed in the Authorization Basis?

☐ N/A ☒ No ☐ Yes/Maybe

BASIS: See answer to question 1. These procedures do not represent conditions that have not been analyzed in the Authorization Basis.

3. Does the proposed change represent a test or experiment NOT described in the Authorization Basis that may affect the safe operation of the facility?

☒ N/A ☐ No ☐ Yes/Maybe

BASIS: This is not a test or experiment.

4. Does the proposed change or occurrence represent a change to the Technical Safety Requirements or a reduction in the margin of safety defined in the Technical Safety Requirements?

☐ N/A ☒ No ☐ Yes/Maybe

BASIS: These changes do not propose a change to any technical safety requirements, and PFP has no safety limits in OSR-010. Therefore, no margin of safety is applicable.

UNREVIEWED SAFETY QUESTION (USQ) SCREENING AND EVALUATION

1. Identification Number: ZO-160-038 A-0
ZO-160-039 A-0, OSD-Z-184-00006 D-7
WHC-SD-CP-OCD-040 Rev 3

USQ SCREENING

Page 3 of 8
55 4/3/00

2. Title: Add Plutonium Metal Processing to Thermal Stabilization Procedures

USQE #1

Nancy E. Wilkins
(Print Name)

USQE #2

J.P. King
(Print Name)

Nancy E. Wilkins
Signature

Date: 3/14/00

J.P. King
Signature

Date: 3/14/00

If there is a YES/MAYBE response to questions 1, 2, 3, or 4, then a USQ Evaluation must be completed.

The following guidance should be considered when completing this screening. This guidance should not be considered all-inclusive; additional factors may need to be considered depending on the nature of the proposed change.

Does the proposed change:

- 1) Modify, add, or delete a safety class function of a structure, system or component stated in the authorization basis?
- 2) Alter the design of a structure, system or component as described in the authorization basis?
- 3) Modify, add, or delete the description of operation, operating environment, or analyses of any system or component described in the authorization basis?
- 4) Modify, add, delete or conflict with any of the design bases stated in the authorization basis?
- 5) Conflict with the principle or general design criteria stated in the authorization basis?
- 6) Modify, add, or delete any plant design features described in the authorization basis?
- 7) Modify, add, or delete a flow diagram or facility drawing provided in the authorization basis?
- 8) Create the potential for new system or component interactions (e.g., seismic, electrical breaker coordination)?

Basis Document for Sludge Stabilization

ECN-657667

Prepared for the U.S. Department of Energy
Assistant Secretary for Environmental Management

Project Hanford Management Contractor for the
U.S. Department of Energy under Contract DE-AC06-96RL13200

Fluor Hanford
P.O. Box 1000
Richland, Washington

Basis Document for Sludge Stabilization

Date Published
April 2000

Prepared for the U.S. Department of Energy
Assistant Secretary for Environmental Management

Project Hanford Management Contractor for the
U.S. Department of Energy under Contract DE-AC06-96RL13200

Fluor Hanford

P.O. Box 1000

Richland, Washington

Release Approval Date 4/3/00

Release Stamp

TRADEMARK DISCLAIMER

Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

This report has been reproduced from the best available copy.

Printed in the United States of America

Total Pages:

75 74
XOF 4/13/0

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

TABLE OF CONTENTS

1.	INTRODUCTION	4
2.	Feed Specifications	4
	2.1. Feeds Permitted.....	4
	2.2. Feeds NOT Permitted.....	5
	2.3. Charge Size.....	5
3.	Controller Specifications	6
	3.1. Furnace Ramp Rate Settings.....	6
	3.2. Furnace Temperature Deviation Band Settings.....	7
	3.3. Heating Cycle PRF Sludge Settings.....	7
	3.4. Heating Cycle Pu Oxalate (Oxycarbonate) Settings.....	8
	3.5. Heating Cycle Pu Oxide Setting.....	9
	3.6. Heating Cycle Reactive Incinerator Ash Setting.....	9
	3.7. Heating Cycle for Pu Metal	9
	3.8. High Furnace Temperature Setting	10
	3.9. Glovebox High Temperature Alarm Setting	10
4.	OFF-GAS SYSTEM	10
	4.1. Off-gas Flow Rate.....	10
	4.2. Filter Differential Pressure.....	11
5.	PURGE SYSTEM	12
	5.1. Purge Flow Rate.....	12
6.	FIRE SAFETY	12
	6.1. Combustible Material.....	12
7.	Product Specifications	13
	7.1. Particle Size.....	13

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

TABLE OF CONTENTS (continued)

ATTACHMENT A:	SLUDGE STABILIZATION STUDIES	14
ATTACHMENT B	TEST PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES 1994	26
ATTACHMENT C	INTERNAL MEMO (15530-94-DMB-070) "D. M. BERSHAW TO W. S. LEWIS, "PRESSURE DROP ANALYSIS FOR FILTER ON 26 IN VACUUM LINE IN GLOVE BOX HC-21C"	35
ATTACHMENT D	MASS BALANCE	41
ATTACHMENT E	REACTIVE INCINERATOR ASH OFF GAS FLOW RATE CALCULATIONS	49
ATTACHMENT F	BURNING PLUTONIUM METAL BUTTONS USING AN IGNITER	55

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

1. **INTRODUCTION**

The HC-21C and HA-21I gloveboxes will be used to stabilize plutonium bearing material. This will be accomplished by heating PRF and other organic (tributyl phosphate) bearing sludges, plutonium oxide, reactive incinerator ash, plutonium metal, and plutonium oxalate conversion product (oxycarbonate). Heating to a temperature of 1000°C in an air stream will drive off residual volatile components and convert residual plutonium-organic materials to PuO_2 .

This technical basis covers the Operation Specification Document (OSD-Z-184-00006) and explains the limits necessary for criticality prevention, protection of personnel and environmental safety, minimizing equipment damage, and attempting to maximize process efficiency.

The following equipment, along with associated instrumentation, interlocks, piping, etc., is covered.

Equipment

Furnace
Temperature Controller
Temperature Alarm Switches
Off-gas Filter
Sieve

2. **Feed Specifications**

2.1. **Feeds Permitted**

Limit: PRF sludge and sludges from other wet process gloveboxes, plutonium oxide, plutonium oxalate (oxycarbonate), plutonium metal and incinerator ash. Glovebox HA-21I cannot be used to process plutonium metal or any material that may have organic content, i.e., PRF sludge and sludges from other wet process gloveboxes that may contain tributyl phosphate (TBP).

Basis: Processing has been limited to the above feeds because analysis has shown the off-gases produced will not be a safety hazard. Glovebox HA-21I is not equipped with a CO_2 purge system, and therefore, it cannot be used to process any item that may contain organic material (TBP). The Authorization Basis does not allow plutonium metal to be processed in Glovebox HA-21I.

Over time the Pu Oxalate will degrade to $\text{PuOCO}_3 \cdot 2\text{H}_2\text{O}$ (plutonium oxycarbonate) with a reaction half-life of 64 days. Considering the length of time the oxalate has been in storage (in excess of 4 years), this results in essentially all of the oxalate having degraded to the carbonate form. (Reference: The Chemistry of Plutonium, J. M. Cleveland, pages 407-408)

Incinerator ash is primarily made of material from the Rocky Flats incinerator. A small portion of the material is from the 232-Z incinerator. The ash contained an average of 22% carbon and therefore was reburned in glovebox HA-40F to remove the carbon. A

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

portion of the material was not processed in HA-40F and this material will be stabilized in the muffle furnaces.

The material that came from Rocky Flats is broken into three categories, Old, Middle and Current. The Old material typically has the high carbon content (up to 42%) and the lowest plutonium content. The Current material typically has the lowest carbon content and the highest plutonium content.

A potential concern with the incinerator ash from Rocky Flats is the presence of lead in the form of lead nitrate which can react violently with graphite. TGA/DTA testing performed with lead nitrate in the presence of graphite indicated that only a small exothermic reaction occurred between 340°C and 420°C (Appendix H). The material was heated to over 450°C prior to being shipped to Hanford, therefore the presence of lead nitrate is not expected.

Any other feeds will be evaluated by PFP Stabilization engineers on a case by case basis.

2.2. Feeds NOT Permitted

Limit: Plutonium bearing materials (PBM) with greater than 10 grams maximum organic in each charge.

Basis: Feed items that originated in PRF have a potential to contain tributyl phosphate (TBP). One of the decomposition products of TBP is butene. Butene, in certain concentrations, can be flammable. Controlling the organic content to ≤ 10 grams is one of the barriers which prevents butene generation from reaching flammable levels. (See Attachment A, Table 1 and Figures 1 and 2.)

The 10 gram organic limit is specified in the Addendum to WHC-SD-CP-SAR-021, Revision 0-K, "Plutonium Finishing Plant Final Safety Analysis Report", 1999, Section 5.2.2.

2.3. Charge Size

Limit: Shall not exceed a mass of 2400 g of Pu for feed material except organic bearing sludge and reactive incinerator ash, 1½ inches depth in the boat and a maximum amount of 10 grams organic in the charge

Basis: Charge size (depth) was determined to allow for oxidation of the material in the boat and to allow for safe operation of the process. Safety calculations have been done using 20 grams TBP. If the charge size is limited to 10 grams organic, then the amount of butene gas generated during processing will be within safe limits (below flammability limits).

Laboratory tests showed that charges containing oxalate (oxycarbonate) liquefied and foamed. The charge must fit into the boat, which has been designed to fit inside the furnace without interference with thermocouples or purge and vent lines. The boat allows generous free board to avoid boil over. CSER 94-007 and 94-008 assess

BASIS DOCUMENT FOR SLUDGE STABILIZATION

the boat size for criticality and allows material to fully load the boat.

Feed material charges other than organic bearing sludges and reactive incinerator ash are limited to 2725g total weight with a restriction of 2400g Pu. The criticality limit for glovebox HC-21C is 5000g Pu when processing feed material with a H/X < 20. Reducing the boat charge size to 2400g from the CPS allowed 2500g allows 200g for the glovebox holdup. Typical glovebox holdup is around 50g Pu.

To eliminate the necessity of doing calculations to determine the allowable charge that meets the 2400g Pu limit that can be placed in a furnace boat during charge preparation, the maximum charge size will be based on a product quality oxide that contains about 88% Pu. This results in a maximum charge size of 2725g of material in each boat for stabilization.

3. Controller Specifications

3.1. Furnace Ramp Rate Settings

Limit:	Maximum Furnace Ramp Rate		
Temperature Range °	Ramp Rate (C/hr)	SCR Output (Amps)	
25 - 500	300	13	
500 - 700	200	13	
700 - 900	125	13	
900 - 1000	75	13	

Basis: The furnace is ramped up slowly to avoid damaging the furnace heating coils. The manufacturer recommends that the furnace should not be operated at full power (17 amps) for extended periods of time (over 4 hours). Process tests indicate that complying with the specified ramp rates will prevent overloading the heating coils. (See Attachment C), "Scrap Stabilization Furnace Test Results", WHC-SD-CP-TRP-059, J. A. Compton, April 5, 1994)

Consideration was also given to optimize process time within the safety envelope and to protect the furnace heating coils from overheating causing failure and short lifetime.

These ramp rates are a safety feature and are programmed into the controller. The specified ramp rates ensure that gases will be exhausted as they are generated so combustible mixtures will not be accumulated. (See Attachment A, Table 1 and Figures 1 and 2)

The ramp rates cited are maximum rates. Ramp rates can be adjusted to avoid overshooting the soak temperatures.

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

3.2. Furnace Temperature Deviation Band Settings

Deviation Limit: $\pm 20^{\circ}\text{C}$

Basis: Low deviation alarm can detect a removed thermocouple, burnt out heater element, poorly tuned controller, etc. High deviation alarm will detect too high a ramp rate by activating when temperature exceeds the expected ramping temperature. Exceeding the ramp rate could generate excess butene gas when processing an organic charge or overheat the heating coils causing failure and short lifetime.

The deviation band alarm will also detect soak temperatures either above or below the set point. The butene curves in Figures 2 and 6 of Attachment A show the effect of exceeding the soak temperature set point of 175°C by 20 degrees.

3.3. Heating Cycle PRF Sludge Settings

Limit: 1st Soak - $1\frac{1}{2}$ hr at 175°C
2nd Soak - 2 hr at 1000°C

Basis: The ramp rate and temperature limit for the first soak time was selected because this parameter keeps the rate of butene generation outside of the flammable range. The one and a half hour soak time was determined by calculating the amount of time it would take to thermally decompose 20 grams of TBP to butene. Twenty grams is double the amount of TBP allowed in a batch. (See Attachment A, Table 1 and Figures 1 and 2).

Laboratory test results were used to determine the temperature limit and one hour soak time for the second soak. The tests showed that by heating material at 1000°C for one hour, essentially all of the volatiles will be removed, thus meeting the vault storage specification. In addition, the higher temperature reduces the absorptivity of the processed sludge making it more stable. (See Attachment B)

These soak rates are specified in the Addendum to WHC-SD-CP-SAR-021, Revision 0-K, "Plutonium Finishing Plant Final Safety Analysis Report", 1999, Section 5.2.2.

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

3.4. Heating Cycle Pu Oxalate (Oxycarbonate) Settings

Limit: 1st Soak - 1 hr at 110°C
2nd Soak - 1/2 hr at 175°C
3rd Soak - Minimum - 2 hrs at 1000°C

Basis: 1st Soak - Before start of operation, laboratory tests with oxalate (oxycarbonate) showed that it became liquid above 100°C. A soak at this temperature removes the water of hydration and allows the evaporation of the free liquid portion of the charge to evaporate without foaming over the edge of the boat. Operating experience has shown that boil-over was not avoided at the previous soak setpoint of 175°C. Upon further research it was found that the dehydration temperatures start at 90°C (Reference: J.M. Cleveland, The Chemistry of Plutonium, 1979, p. 403, 404). In order to evaporate water, the soak temperature must exceed the boiling point of water. To avoid boil-over and still evaporate water, a new setpoint of 110°C was selected for the first soak. Even with the lower soak time, some of the material may boil over. This is not a major concern in that the material can be easily scraped and brushed out of the furnace. The material is then placed in a can with the rest of the charge material in HC-18M.

2nd Soak - Laboratory test results were used to determine the temperature limits for the second and third soaks. The second soak separates the remaining water of hydration from the oxycarbonate (oxalate) and continues evaporation of free liquids.

3rd Soak - The DOE Standard 3013-96, Long Term Storage Criteria for >50% Pu oxides, requires that materials be heated to 950°C or higher for 2 hours and meet a <0.5% LOI @ 1000°C. Tests showed that by heating material at 1000°C for one hour, essentially all of the volatiles will be removed, thus meeting the vault storage specification of <0.5% LOI for material less than 50% Pu. In addition, the higher temperature reduces the absorptivity of the processed sludge making it more stable. (See Attachment B)

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

3.5. Heating Cycle Pu Oxide Setting

Limit: Soak - Minimum 2 hrs at 1000°C

Basis: Laboratory test results were used to determine the temperature limit and soak time. The DOE Standard 3013-96, Long Term Storage Criteria for >50% Pu oxides, requires that materials be heated to 950°C or higher for 2 hours and meet a <0.5% LOI @ 1000°C. Tests showed that by heating material at 1000°C for one hour, essentially all of the volatiles will be removed, thus meeting the vault storage specifications of <0.5% LOI for material less than 50% Pu. In addition, the higher temperature reduces the absorptivity of the processed sludge making it more stable. (See Attachment B)

3.6. Heating Cycle Incinerator Ash Setting

Limit: Reactive Ash Soak - 4 hr at 1000°C
Nonreactive Ash - Minimum 2 hrs at 1000°C

Basis: Process testing indicates that a 4 hour soak time at 1000°C along with a one and one half inch depth in the boat will allow oxidation of sufficient carbon to meet vault specifications. (Reference: WHC-SD-CP-TP-087 Rocky Flat Ash Test Procedure (Sludge Stabilization), 9/14/95).

The 2 hrs at 1000°C heating cycle is to be used with nonreactive incinerator ash that has been processed through HA-40F or the stabilization furnaces. Because the material was previously processed to 600°C, 2 hours at 1000°C is sufficient to meet the Long Term Storage Criteria.

3.7 Heating Cycle for Pu Metal

Limit: 1st Soak - 550°C for 6 hours
2nd Soak - 1000°C for 2 hours

Basis: A laboratory experiment heated a metal button to 550°C in a crucible furnace. Oxidation of the button was completed in 6 hours. (Reference: SD-CP-PTR-008, Burning Plutonium Metal Buttons Using an Igniter, 10/23/85) The second soak is identical to the soak performed on other plutonium oxide items.

The soak temperature of 550°C was selected for the first soak because it is below the melting point of plutonium metal. If the metal melts, it will form an alloy with the Hastelloy boat and ruin the boat.

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

3.8. High Furnace Temperature Setting

Limit: 1050°C

Basis: The high furnace temperature alarm system provides an independent backup to prevent over-heating the furnace if the Controller fails. The maximum furnace temperature recommended by the manufacturer is 1093°C. Operating the furnace at the full output of power required to maintain this temperature for an extended period of time (>4 hours) can shorten the lifetime of the furnace element and cause failure.

Specification limit is set to allow for over-shooting during ramp time. The set point changed from 1025°C to 1050°C in September, 1995 because the lower temperature was found to be more conservative than required and caused unnecessary process cycle shut-downs. There were no safety reasons for the lower limit of 1025°C and the new setpoint of 1050°C is still well below the manufacturers recommended guidelines.

3.9. Glovebox High Temperature Alarm Setting

Limit: 70°C (158°F)

Basis: This alarm is in place to provide sufficient warning of off-standard conditions which could cause the glovebox to heat up and reach the Fire Suppression System activation temperature of 93°C (200°F).

Glovebox HC-21C has a Halon fire suppression system, and Glovebox HA-21I has a dry chemical suppression system. It is desirable that activation of the Halon system in Glovebox HC-21C be avoided unless there is an uncontrolled fire in the glovebox, because once the Halon has been released, there will be no fire suppression system for the glovebox. Halon is a regulated material and may be difficult to replace. (Reference drawing H-2-97481, sheets 26, 27, 28, 29.)

4. OFF-GAS SYSTEM

4.1. Off-gas Flow Rate

Limit: 120 to 180 std. ft³/hr. for Sludge/oxalate
60 to 90 std. ft³/hr. for Oxide/MOX/Pu Metal

A flow rate of 60 - 90 std. ft³/hr shall be used when processing reactive incinerator ash.

Exception:

Off-gas flow was specified for sludge charges because of the possibility of butene which could be generated when PRF Sludge containing tributyl phosphate (TBP) is

BASIS DOCUMENT FOR SLUDGE STABILIZATION

processed. Its purpose is to dilute and remove flammable off-gases during the period butene can be generated. This period is ended before the furnace reaches a temperature of 250°C. The same flow rate was specified for oxalate charges to aid the evaporation of free liquids.

Basis: In glovebox HC-21C, off-gases are vented to the 26" Hg vacuum system. In glovebox HA-21I, off-gases are vented to the 5" Hg vacuum system. A flow rate of 120 - 180 std. ft³/hr will provide enough circulation to dilute the flammable gases generated when processing PRF Sludge to within safe concentrations. It will also provide greater air circulation through the furnace to aid oxidation and remove volatiles from the charges. (See Attachment A, Figures 3, 4, 5, and 6 and associated tables.)

During stabilization of reactive incinerator ash, carbon will oxidize to both CO and CO₂. CO is flammable (though not explosive) in concentrations greater than 12%. Calculations were performed which indicated that CO concentrations will remain below 12% as long as sufficient oxygen is present (0.6 scfm is sufficient to convert almost all carbon to CO₂) (Attachment E).

The incinerator ash is very flighty and therefore is susceptible to being pulled into the off gas line and plugging the filter. The off gas flow rate will be reduced to 60 - 90 scfh while processing this material.

The sludge/oxalate and oxide/MOX off-gas flow rates are specified in the Addendum to WHC-SD-CP-SAR-021, Revision O-K, "Plutonium Finishing Plant Final Safety Analysis Report", 1999, Section 5.2.2.

4.2. Filter Differential Pressure

Limit: ≤ 10 psi for Glovebox HC-21C
≤ 50 in.-H₂O for Glovebox HA-21I

Exception

PFP Stabilization engineers can allow continued operation of a cycle with greater dP as long as the required exhaust flow is maintained.

A filter is installed in the exhaust line after it leaves the furnace. The filter's function is to remove airborne particulate matter in the off-gas.

Basis: Any particulate matter remaining in the filter can absorb moisture at the beginning of the cycle. Once the particulate matter absorbs moisture, it hardens into a solid piece. This reduces the permeability of the filter which decreases the air flow rate through the furnace. Low air flow increases the possibility of combustible gas build-up. (See Attachment C, Internal Memo 15530-94-DMB-070, D. M. Bershaw to W. S. Lewis, "Pressure Drop Analysis for Filter on 26 Inch Vacuum Line in Glove Box HC-21C", Westinghouse Hanford Company,

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

Richland, Washington, June 1, 1994). The limit for Glovebox HC-21C is also specified in the Addendum to WHC-SD-CP-SAR-021, Revision 0-K, "Plutonium Finishing Plant Final Safety Analysis Report", 1999, Section 5.2.2.

5. **PURGE SYSTEM**

5.1. **Purge Flow Rate**

Limit: ≥ 45 std. ft³/hr CO₂

The carbon dioxide purge flow will be used only for charges originating in PRF or other wet process gloveboxes with a potential for containing TBP. The CO₂ purge is only available in Glovebox HC-21C.

Basis: Carbon dioxide was chosen because it was found to be more effective on a molar basis. Minimum purge flow with carbon dioxide during the ramp and soak times (about 2½ hours) for PRF sludge charges, assures flammable gas concentration in the furnace remains below minimum safe limit. (See Attachment A, Figures 3, 4, 5, and 6 and associated tables).

The 45 scfh CO₂ flow rate is specified in the Addendum to WHC-SD-CP-SAR-021, Revision 0-K, "Plutonium Finishing Plant Final Safety Analysis Report", 1999, Section 5.2.2.

6. **FIRE SAFETY**

6.1. **Combustible Material**

Limit: Glovebox gloves near furnace fixed in position with bungi cord during processing cycle.

Minimal non-engineered combustible materials such as plastic bags, polyjars, or rags in Gloveboxes HC-21C and HA-21I during the heating cycle.

Basis: This limit is set both to prevent contacting of combustible materials with hot surfaces and accumulating of significant quantities of combustibles. Surface temperatures of the lines exiting the furnace can exceed 400°C during the heating cycle. The exhaust line which carries the hot gasses is insulated to the offgas filter which is a significant heat sink. The CO₂ line is not insulated and portions of the line near the furnace could reach temperatures over 400°C. Radiant heat transfer should reduce the line temperature to below 200°C by the time the line exits the glovebox. Combustible materials contacting these surfaces may ignite and the resulting fire may breach glovebox containment if these materials are present in sufficient quantity.

These requirements are specified in the Addendum to WHC-SD-CP-SAR-021, Revision 0-K, "Plutonium Finishing Plant Final Safety Analysis Report", 1999, Section 5.2.2.

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

7. **Product Specifications**

7.1. **Particle Size**

Limit: Particles must go through 4 mesh sieve

Exception: PFP Stabilization engineers can allow larger chunks of material to be canned with the concurrence of the Product Handling and Storage Cognizant Engineer.

Basis: A fairly uniform particle size is required to assure that samples taken for LOI are representative. Larger chunks also may not be completely dried. If no large chunks of material are present in product, sieving will not be required.

HNF-SD-CP-QCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT A: SLUDGE STABILIZATION STUDIES

BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT A

PAGE A-1 of A-11

SLUDGE STABILIZATION STUDIES

This series of figures was developed from data obtained from laboratory tests performed with uranyl nitrate-tributyl phosphate adduct ("Behavior of Tributyl Phosphate in A-Line Processes", DP-1418, August 1976, H.D. Harmon, et al). The physical and chemical properties were studied to define optimum, safe operating conditions for denitration of uranyl nitrate solutions containing low concentrations of adduct. A conservative kinetic factor (KF) of 3 was used when the data was applied to plutonium bearing material, which will be used in the sludge stabilization process, to account for the fact that plutonium nitrate has two times as much nitrate as uranyl nitrate.

Figures 1 and 2 show the expected results calculated if the process is operated at conditions defined in the Operating Specification Document. Figure 1 shows the relationship of the decomposition curve of 20 grams of TBP and the butene generation curve to the temperature cycle. Figure 2 shows the flammability curves. The butene concentration is well below the lower flammability limit.

Changes in inputs for Table 2 and reflected in Figures 3 and 4 are: (1) a hold temperature of 155 °C, which is 20 °C less than setpoint temperature but still within the OSD limits; (2) furnace purge flow rates at 5% less than OSD limits; and (3) the off-gas flow rate of 90 scfh, which is 25% less than OSD limits. Figure 3 shows a part of the butene is generated at a temperature of about 150 °C and dissipated slowly during the hold time. The remainder is generated at the time of the second ramp up. However, as can be seen in Figure 4 the concentration level of the highest peak is much less than the lower flammability limit. These results indicate that the carbon dioxide purge flow needs to continue for at least 140 minutes to compensate for this deviation.

Figures 5 and 6 reflect the input changes as follows: (1) the hold temperature of 195 °C, which is 20 °C greater than setpoint temperature, but still within the OSD limits; (2) the furnace purge rate at 5% less than OSD limits; and (3) the off-gas flow rate of 90 scfh, which is 25% less than OSD limits. The butene peak for these conditions reaches its highest concentration at the set point (See Figure 5). This is the point most likely to have an overshoot so the upper deviation limit should not exceed this temperature. The highest butene concentration (as shown in Figure 6) is about 75% of the flammable limit. This concentration is acceptable due to the four other conservative inputs used in the calculations.

Temperature over-shoots of 3 to 13 degrees were observed in the initial furnace tests. Therefore, a hold temperature of 20 °C less than the upper deviation band will be set to allow for overshoot without activating the furnace shutdown interlock.

HNF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

BASIS DOCUMENT FOR SLUDGE STABILIZATION
ATTACHMENT A
Page A-2 of A-11

Calculations to show the lower flammability limit for butene compared to normal operating conditions.

Butene is generated at 0.648 mol/hr (Table #1, Row 9, Columns 1 and 2)

Offgas flow rate is 139.006 mol/hr (Table #1, Last Row, Columns 1 and 2)

$$\frac{0.648 \text{ mol/hr butene}}{139.006 \text{ mol/hr offgas}} = 0.0046 \times 100 = 0.46\% \frac{\text{butene}}{\text{total offgas}}$$

For conservatism, calculations were made for a double batch, with the amount of TBP (20 grams) See Table #1, Row 1, Columns 3 and 4.

Normal operations will process a charge of 500 grams with a maximum of 2% TBP which equals 10 grams TBP. The percent butene is divided by 2.

$$\frac{0.46}{2} = 0.23\%$$

The lower flammability limit at 25°C as shown in Figure 2 is from Figure 68 on page 54 of Bureau of Mines Bulletin 627, "Flammability Characteristics of Combustible Gases and Vapors", M. G. Zabetakis, 1965.

The lower flammability limit at 250°C is calculated by using the temperature correction equation on page C-67 of AIChE Today Series, "Fundamentals of Fire and Explosion Hazards Evaluation", C. Grelecki, 1976.

$$L_t / L_{25} = 1 - 0.000721 (t - 25)$$

where

L_t = lower limit of gas mixture at temperature of interest
 L_{25} = lower limit of gas mixture at 25°C
 t = temperature of interest

$$L_{25} = 1 - 0.000721 (250 - 25) (2)$$

$$L_{25} = 1.675$$

The percent of butene which could be generated at normal conditions as compared to the lower flammability limit at 250°C is as follows:

$$\frac{0.23}{1.675} = 0.1373 \times 100 = 13.73\%$$

TABLE #1

Initial Ramp Rate	5 (C/min)	Initial TBP wt.	20 (gm TBP)
Time Interval	1.5 (min)	Initial TBP mols	0.075098 (mol TBP)
Temp @ Time 0	30 (C)	TBP Conv factor	3 (mol C4/mol TBP)
Time/new Ramp Rate	120 (min)	Inert Rtn Gen fact	1 (mol inert/mol C4)
New Ramp Rate	3.33333 (C/min)	Kin factor Input	3
Frn Hold Temp	175 (C)	Kin factor Min	1
Frn Min Temp	25 (C)	Kin factor Used	3
Frn Max Temp	400 (C)		
Max C4 Gen Rate	0.648 (mol C4/hr)		
Max Inert Rate	0.648 (mol inert/hr)		
Max Tot Flow	36.047 (mol (C4+inert+purge)/hr)		
Min Frn OG Req'd	31.118 (cfh @ 200 & 1 atm)		
TIME AT FRN PURGE CHANGE	400 (min)		
Furn Purge Rate	30 (scfh)		
O2 in Furn Purge	0.1% (% O2)		
Inert in Frn Prg	99.9% (% N2)		
Mol Frn Prg Rate	34.751 (mol purge/hr)		
	0.035 (mol O2 purge/hr)		
	34.717 (mol Inert Purge/h)		
TIME WHEN OG RATE CHANGES	400 (min)		
Furn OG Rate	120 (scfh)		
Mol Frn OG Rate	139.006 (mol tot OG/hr)		

Unreacted TBP, C4H8 Rate, & Temperature OSD Nominal Conditions, KF = 3.0

FIGURE 1

FIGURE 2
 Furnace Off-gas Flammability
 OSD Nominal Conditions, $KF = 3.0$

TABLE #2

Initial Ramp Rate	5 (C/min)	Initial TBP wt.	20 (gm TBP)
Time Interval	1.5 (min)	Initial TBP mols	0.075098 (mol TBP)
Temp @ Time 0	30 (C)	TBP Conv Factor	3 (mol C4/mol TBP)
Time/new Ramp Rate	120 (min)	Inert Rtn Gen fact	1 (mol inert/mol C4)
New Ramp Rate	3.33333 (C/min)	Min Factor Input	3
Frn Hold Temp	155 (C)	Min Factor Min	1
Frn Min Temp	25 (C)	Min Factor Used	3
Frn Max Temp	400 (C)		
Max C4 Gen Rate	0.234 (mol C4/hr)		
Max Inert Rate	0.234 (mol inert/hr)		
Max Tot Flow	33.682 (mol (C4+inert+purge)/hr)		
Min frn OG Req'd	28.904 (cfh @ 298 & 1 atm)		
TIME AT FRN PURGE CHARGE	400 (min)		
Furn Purge Rate	28.5 (scfh)		
O2 in Furn Purge	0.1% (% O2)		
Inert in frn prg	99.9% (% H2)		
Mol frn prg Rate	33.014 (mol purge/hr) 0.033 (mol O2 purge/hr) 32.981 (mol Inert Purge/hr)		
TIME WHEN OG RATE CHANGES	400 (min)		
Furn OG Rate	90 (scfh)		
Mol frn OG Rate	104.254 (mol Tot OG/hr)		

FIGURE 3

Unreacted TBP, C4H8 Rate, & Temperature OSD Error Conditions, KF = 3.0

Furnace Off-gas Flammability OSD Error Conditions, $KF = 3.0$

FIGURE 4

TABLE #3

Initial Ramp Rate	5 (C/min)	Initial TBP wt.	20 (gm TBP)
Time Interval	1.5 (min)	Initial TBP mols	0.075098 (mol TBP)
Temp @ Time 0	30 (C)	TBP Conv Factor	3 (mol C ₄ /mol TBP)
Time/new Ramp Rate	120 (min)	Inert Rxn Gen Fact	1 (mol inert/mol C ₄)
New Ramp Rate	3.333333 (C/min)	Kin factor Inert	3
Frn Hold Temp	195 (C)	Kin factor Min	1
Frn Min Temp	25 (C)	Kin factor Used	3
Frn Max Temp	400 (C)		
Max C ₄ Gen Rate	1.387 (mol C ₄ /hr)		
Max Inert Rate	1.387 (mol inert/hr)		
Max Tot flow	35.788 (mol (C ₄ +inert+Purge)/hr)		
Min Frn OG Req'd	30.895 (cft @ 298 & 1 atm)		
TIME AT FRN PURGE CHANGE	400 (min)		
Furn Purge Rate	28.5 (scfh)		
O ₂ in furn Purge	0.1% (% O ₂)		
Inert in frn Prg	99.9% (% N ₂)		
Hol Frn Prg Rate	33.014 (mol purge/hr) 0.033 (mol O ₂ purge/hr) 32.981 (mol Inert Purge/h)		
TIME WHEN OG RATE CHANGES	400 (min)		
Furn OG Rate	90 (scfh)		
Hol Frn OG Rate	104.254 (mol tot OG/hr)		

FIGURE 5

Unreacted TBP, C4H8 Rate, & Temperature OSD Error Conditions, KF = 3.0

FIGURE 6
 Furnace Off-gas Flammability
 OSD Error Conditions, $KF = 3.0$

ANP-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT B TEST PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES
1994

TESTS PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES - 1994									
	ITEM ID	BOHE DRY NET WEIGHT	WT. ITEM + CAN W/LID	WT. GAIN	% WT. GAIN	T	T-T ₀	$\sqrt{T-T_0}$	
760°C FIXED	PPSL-213A	45.94g	131.23g	0.0	0.0	0738 4/14	0 hrs	0 hrs %	
			131.26	0.03	0.0653	0810 4/14	0.534	0.731	
			131.29	0.04	0.131	0842 4/14	1.067	1.033	
			131.33	0.10	0.218	1030 4/14	2.867	1.693	
			131.33	0.10	0.218	1120 4/14	3.697	1.923	
			131.26	0.13	0.293	1604 4/14	8.434	2.904	
			132.39	1.03	2.24	0730 4/20	102.275	10.118	
			133.97	2.74	5.96	1045 4/27	315.037	17.74	
1000°C FIXED	PPSL-213B	74.32	159.78	0.0	0.0	0740 4/20	0	0	
			159.81	0.03	0.040	0810 4/10	0.500	0.707	
			159.82	0.04	0.054	0849 4/20	1.150	1.072	
			159.95	0.07	0.094	0900 4/20	1.333	1.154	
			159.87	0.09	0.121	0920 4/20	1.333	1.154	
			159.88	0.100	0.135	0940 4/20	2.000	1.414	
			159.89	0.110	0.148	0955 4/20	2.250	1.500	
			159.97	0.140	0.186	1030 4/20	2.833	1.683	
			159.94	0.160	0.215	1100 4/20	3.333	1.876	
			159.96	0.180	0.242	1155 4/20	4.250	2.061	
			159.97	0.190	0.256	1220 4/20	4.644	2.160	
			160.00	0.220	0.296	1315 4/20	5.503	2.363	
			160.03	0.250	0.336	1510 4/20	7.500	2.739	
			160.34	0.560	0.753	0635 4/21	22.913	4.786	

TEST PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES - 1994								
ITEM ID	BONE DRY NET WEIGHT	WT. ITEM + CAN W/LID	WT. GAIN	% WT. GAIN	T	T-T ₀	$\sqrt{T-T_0}$	
		160.37	0.590	0.794	0730 4/21	23.83	4.880	
		160.55	0.770	1.036	1430 4/21	30.83	5.553	
		161.07	1.290	1.736	1045 4/27	171.00	13.08	

BASIC DOCUMENT FOR SLUDGE STABILIZATION

HNF-SD-P-000-040

Rev. 3

70

60

50

40

30

20

10

0

1.0

① P132-2/3A Centrifuge Sludge 7000 RPM for 1 hour
② P132-2/3B Centrifuge Sludge 10000 RPM for 1 hour

UNREPRODUCIBLE COPY

UNREPRODUCIBLE COPY

0.0

1.0

2.0

3.0

4.0

5.0

6.0

7.0

8.0

9.0

10.0

11.0

12.0

13.0

14.0

15.0

16.0

17.0

18.0

19.0

20.0

21.0

22.0

23.0

24.0

25.0

26.0

27.0

28.0

29.0

30.0

31.0

32.0

33.0

34.0

35.0

36.0

37.0

38.0

39.0

40.0

41.0

42.0

43.0

44.0

45.0

46.0

47.0

48.0

49.0

50.0

51.0

52.0

53.0

54.0

55.0

56.0

57.0

58.0

59.0

60.0

61.0

62.0

63.0

64.0

65.0

66.0

67.0

68.0

69.0

70.0

71.0

72.0

73.0

74.0

75.0

76.0

77.0

78.0

79.0

80.0

81.0

82.0

83.0

84.0

85.0

86.0

87.0

88.0

89.0

90.0

91.0

92.0

93.0

94.0

95.0

96.0

97.0

98.0

99.0

100.0

101.0

102.0

103.0

104.0

105.0

106.0

107.0

108.0

109.0

110.0

111.0

112.0

113.0

114.0

115.0

116.0

117.0

118.0

119.0

120.0

121.0

122.0

123.0

124.0

125.0

126.0

127.0

128.0

129.0

130.0

131.0

132.0

133.0

134.0

135.0

136.0

137.0

138.0

139.0

140.0

141.0

142.0

143.0

144.0

145.0

146.0

147.0

148.0

149.0

150.0

151.0

152.0

153.0

154.0

155.0

156.0

157.0

158.0

159.0

160.0

161.0

162.0

163.0

164.0

165.0

166.0

167.0

168.0

169.0

170.0

171.0

172.0

173.0

174.0

175.0

176.0

177.0

178.0

179.0

180.0

181.0

182.0

183.0

184.0

185.0

186.0

187.0

188.0

189.0

190.0

191.0

192.0

193.0

194.0

195.0

196.0

197.0

198.0

199.0

200.0

201.0

202.0

203.0

204.0

205.0

206.0

207.0

208.0

209.0

210.0

211.0

212.0

213.0

214.0

215.0

216.0

217.0

218.0

219.0

220.0

221.0

222.0

223.0

224.0

225.0

226.0

227.0

228.0

229.0

230.0

231.0

232.0

233.0

234.0

235.0

236.0

237.0

238.0

239.0

240.0

241.0

242.0

243.0

244.0

245.0

246.0

247.0

248.0

249.0

250.0

251.0

252.0

253.0

254.0

255.0

256.0

257.0

258.0

259.0

260.0

261.0

262.0

263.0

264.0

265.0

266.0

267.0

268.0

269.0

270.0

271.0

272.0

273.0

274.0

275.0

276.0

277.0

278.0

279.0

280.0

281.0

282.0

283.0

284.0

285.0

286.0

287.0

288.0

289.0

290.0

291.0

292.0

293.0

294.0

295.0

296.0

297.0

298.0

299.0

300.0

301.0

302.0

303.0

304.0

305.0

306.0

307.0

308.0

309.0

310.0

311.0

312.0

313.0

314.0

315.0

316.0

317.0

318.0

319.0

320.0

321.0

322.0

323.0

324.0

325.0

<

TESTS PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES - 1994									
	ITEM ID	BONE DRY NET WEIGHT	WT. ITEM + CAN W/LID	WT. GAIN	% WT. GAIN	T	T-T ₀	$\sqrt{T-T_0}$	
760°C FIXED	PSSL-213B	105.11g	155.85g	0.0	0.0	0800 4/5	0 hrs		0 hrs %
			155.86	0.110	0.00951	0910 4/5	1.167		1.080
			155.90	0.150	0.0476	1005 4/5	2.083		1.443
			155.91	0.150	0.0571	1020 4/5	2.333		1.527
			155.96	0.150	0.104	1220 4/5	4.333		2.082
			155.98	0.150	0.124	1340 4/5	5.667		2.380
			155.99	0.150	0.133	1440 4/5	6.667		2.582
			166.17	0.180	0.457	1210 4/5	29.167		5.481
			156.64	0.590	0.561	0755 4/7	47.917		6.922
			157.62	1.170	1.684	0630 4/12	166.50		12.904
1000°C FIXED			162.76	6.910	6.574	1045 4/27	534.67		23.55
	PSSL-214A	109.67	193.60g	0.0	0.0	1020 4/27	0		0
			193.63	0.030	0.0274	1235 4/27	2.250		1.500
			193.63	0.030	0.0274	1300 4/27	2.667		1.633
			193.66	0.040	0.0547	1445 4/27	4.334		2.082
			193.91	0.210	0.1915	0650 4/28	20.500		4.528
			193.82	0.220	0.2006	0850 4/28	22.500		4.743
			193.84	0.240	0.2189	1000 4/28	23.667		4.865
			193.86	0.260	0.237	1120 4/28	25.000		5.000
			193.91	0.310	0.283	0900 4/29	45.667		6.757
			194.13	0.530	0.483	0630 5/2	140.167		11.839

BASIS DOCUMENT FOR SLUDGE STABILIZATION

HW-50-CP-OCD-040
REV. 3

TESTS PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES - 1994									
	ITEM ID	BOHE DRY NET WEIGHT	WT. ITEM + CAN W/LID	WT. GAIN	% WT. GAIN	T	T-T ₀	$\sqrt{T-T_0}$	
760°C FIXED	PPSL-215A	71.08g	145.99g	0	0	1320 4/6	0	0	
			146.02	0.030	0.0422	1350 4/6	0.500	0.707	
			146.87	0.880	1.238	0630 4/12	137.17	11.712	
			148.00	2.010	2.828	0740 4/20	330.33	18.175	
			148.45	2.460	3.46	1045 4/21	357.337	18.900	
1000°C FIXED	PPSL-215B	74.55g	149.44	0	0	0600 4/21	0		
			159.64	0.040	0.0537	0810 4/21	0.167	0.409	
			159.66	0.060	0.0805	0820 4/21	0.333	0.577	
			159.69	0.090	0.1207	0830 4/21	0.500	0.707	
			159.72	0.120	0.1610	0840 4/21	0.667	0.817	
			159.74	0.140	0.1878	0850 4/21	0.833	0.913	
			159.76	0.160	0.2146	0900 4/21	1.000	1.000	
			159.77	0.170	0.2280	0910 4/21	1.167	1.080	
			159.78	0.190	0.2415	0920 4/21	1.333	1.155	
			159.81	0.210	0.2817	0940 4/21	1.667	1.291	
			159.82	0.220	0.2961	1000 4/21	2.000	1.414	
			159.83	0.230	0.3085	1010 4/21	2.167	1.472	
			159.84	0.240	0.3219	1030 4/21	2.500	1.581	
			159.84	0.240	0.3219	1050 4/21	2.833	1.683	

TEST PERFORMED BY PLUTONIUM PROCESS SUPPORT LABORATORIES - 1994									
ITEM ID	BONE DRY NET WEIGHT	WT. ITEM + CAN W/LID	WT. GAIN	% WT. GAIN	T	T-T ₀	$\sqrt{T-T_0}$		
		159.85	0.250	0.3353	1100 4/21	3.000	1.732		
		159.86	0.260	0.3488	1130 4/21	3.500	1.871		
		159.87	0.270	0.3622	1250 4/21	4.833	2.198		
		159.88	0.280	0.3756	1430 4/21	6.500	2.550		
		160.38	0.780	1.046	1020 4/27	146.33	12.097		
		160.36	0.760	1.019	1045 4/27	146.75	12.116		

7.0

6.0

5.0

4.0

3.4

3.0

2.0

1.0

0.5

△ PPSL-2167, Canyon Floor Solids, 74000 for 116000
 ○ PPSL-2153, Canyon Floor Solids, 10000 for 116000

BEST AVAILABLE COPY

~~HW~~ -SD-CP-OCD-040
REV. 3

BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT C INTERNAL MEMO (15530-94-DMB-070) "D. M. BERSHAW TO W. S.
LEWIS, "PRESSURE DROP ANALYSIS FOR FILTER ON 26 IN VACUUM
LINE IN GLOVE BOX HC-21C"

Westinghouse
Hanford Company

ATTACHMENT C
PAGE 2-1 of 2-5
HNF-SO-CF-000-040 REV. 3

Internal
Memo

BASIS DOCUMENT FOR SLUDGE STABILIZATION REV. 0
From: PFP Process Engineering 15530-94-DMB-070
Phone: 373-5092 TS-55
Date: June 1, 1994
Subject: PRESSURE DROP ANALYSIS FOR FILTER ON 26 INCH VACUUM LINE IN GLOVE BOX HC-21C

To: W. S. Lewis TS-55
cc: L. Dayley TS-55
M. W. Gibson *mws* TS-55
DMB File/LB

- (1) CRANE Co. Flow of Fluids Through Valves, Fittings, and Pipe. Technical Paper No. 410. Crane Co. King of Prussia, PA. 1988.
- (2) Rockwell Hanford Operations. Plutonium Finishing Plant Safety Analysis Report (SO-HS-SAR-007). Pages 5-21 through 5-26. 1987.

This memo documents an analysis of the 26" vacuum line and filter in glove box HC-21C. A minimum flow rate of 2 cfm through the vacuum line during sludge stabilization is necessary to ensure the glove box is properly vented. A differential pressure gauge has been installed across the 26" vacuum line filter. The normal operating pressure drop across this ceramic filter is 1 psi. It is expected that with use the pressure drop across the filter will increase, thus reducing flow through the line. By approximating how much vacuum is necessary to sustain the minimum flow rate, a guideline may be established to determine when the filter should be changed out.

Analysis of this system indicates the vacuum required for a 2 cfm flow through the vacuum line is 0.12 psi (0.25 in. Hg). However, this analysis does not take into account the pressure drop for all the piping from the glove box to the 26" vacuum pumps located in building 291-Z. Therefore a safe operating limit for the pressure drop across the filter would be in the 8-10 psi (16-20 in. Hg) range.

In order to calculate the pressure drop a flow rate of 2 cfm (120 cfh), observed 5 ft. from the end of a 1/2" s.s. pipe, was plugged into a version of the Bernoulli equation for compressible fluid flow in pipe. The ideal gas law and a temperature of 70°F were used to determine the density of air under a 26" vacuum. Correction factors for the compressibility of air were

W. S. Lewis
Page 2
June 1, 1994

found in the Crane Manual. These factors were approximated to solve the flow equation and then were refined after several iterations.

Any questions concerning this analysis may be addressed to Dwayne Bershaw at 373-5092 (TS-55).

D. M. Bershaw, Engineer
PFP Process Engineering

Concurrence:

L. Day, PFP Process Engineer
PFP Process Engineering

CSE

Attachments 3

W. S. Lewis
Page 1 of 1
June 1, 1994

15530-94-DMB-070

Attachment 1

Determination Reynold's Number:

$$Re = \frac{DVP}{\mu}$$

$$D = 0.5 \text{ inches}$$

$$\rho = \frac{PM}{RT} = \frac{100 \text{ mmHg mol K}}{62.36 \text{ L mmHg 294 K}} \cdot \frac{28.85 \text{ g}}{1000 \text{ g}} \cdot \frac{\text{kg}}{\text{m}^3} \cdot \frac{2.205 \text{ lbm}}{1000 \text{ L}} \cdot \frac{\text{m}^3}{35.313 \text{ ft}^3} = 9.83 \cdot 10^{-3} \frac{\text{lb}}{\text{ft}^3}$$

$$v = \frac{q}{A} = \frac{\frac{2 \text{ ft}^3}{\text{min}}}{\left(\frac{0.25 \text{ ft}}{12} \right)^2 \pi} \cdot \frac{\text{min}}{60 \text{ s}} = 24.4 \frac{\text{ft}}{\text{s}}$$

$$\mu = 0.018 \text{ cP (air at } 70^\circ \text{F, 1 atm) Crane Manual pg. A-5}$$

$$\mu = 0.018 \text{ cP} \cdot \frac{\text{P}}{100 \text{ cP}} \cdot \frac{\text{N s}}{10 \text{ P m}^2 \text{ N s}^2} \cdot \frac{\text{kg m}}{2.205 \text{ lbm}} \cdot \frac{\text{m}}{\text{kg}} \cdot \frac{3.2808 \text{ ft}}{1} = 1.21 \cdot 10^{-5} \frac{\text{lb}}{\text{ft s}}$$

$$Re = \frac{DVP}{\mu} = \frac{0.5 \text{ inch}}{12 \text{ inch}} \cdot \frac{\text{ft}}{\text{s}} \cdot \frac{24.4 \text{ ft}}{1} \cdot \frac{9.83 \cdot 10^{-3} \text{ lb}}{\text{ft}^3} \cdot \frac{\text{ft s}}{1.21 \cdot 10^{-5} \text{ lb}} = 825$$

Attachment 2

Flow Equation for Compressible Fluid through pipe:
(Crane Manual, Equation 3-20, pg. 3-4)

$$Q'_m = 678 Y d^2 \sqrt{\frac{\Delta P P'_1}{K T_1 S_g}}$$

$$Q'_m = 2 \frac{ft^3}{min} \quad T_1 = 530R (70^\circ F) \quad S_g = 1.0$$

$$P'_1 = -1.1 \text{ inches } H_2O \text{ gauge} = 0.997 \text{ atm} = 14.7 \text{ psi} \quad (\text{Ref. 2})$$

$$\text{For Laminar Flow (Re < 2300) friction factor } f = \frac{64}{Re} = \frac{64}{825} = 0.0776$$

$$K_{\text{pipe}} = f \frac{L}{D} = 0.0776 \frac{5ft}{0.5inch} \frac{12inch}{1ft} = 9.31 \quad K_{\text{expansion}} = 1.0 \quad K_{\text{tot}} = 10.3$$

$$d^2 = (0.5inch)^2 = 0.25 \quad Y = 0.99(1)$$

(1) found in Crane Manual pg. A-22 and solved for after several iterations

$$\Delta P = \frac{K T_1 S_g}{P'_1} \left(\frac{Q'_m}{678 Y d^2} \right)^2 = \frac{10.3 (530) (1)}{14.7 \text{ psi}} \left(\frac{2}{6 (0.99) (0.25)} \right)^2 = 0.0528 \text{ psi}$$

W S Lewis
Page 1 of 1
June 1, 1994

15530-94-DHB 070

Attachment 3

Total Possible Pressure Drop Across 26" Vacuum Line

$$\Delta P = (26 \text{ inch Hg} - 0.081 \text{ inch Hg}) \frac{1000 \text{ mmHg}}{39.37 \text{ inch Hg}} \frac{14.7 \text{ psi}}{760 \text{ mmHg}} = 12.7 \text{ psi}$$

Pressure needed to maintain 2 cfm flow rate

$$\Delta P = 0.0528 \text{ psi} = 0.107 \text{ inches Hg}$$

Acceptable Pressure Drop Across Filter

$$\Delta P = 8-10 \text{ psi} = 16-20 \text{ inches Hg}$$

Normal operating pressure drop for the ceramic filter = 1 psi

For Glovebox HA-21I

Total Possible Pressure Drop Across 5" Hg Vacuum Line

$$\Delta P = (5 \text{ inch Hg} - 0.081 \text{ inch Hg}) \frac{1000 \text{ mmHg}}{39.37 \text{ inch Hg}} \frac{14.7 \text{ psi}}{760 \text{ mmHg}} = 2.4 \text{ psi}$$

Pressure needed to maintain 2 cfm flow rate is 0.0528 psi

Acceptable Pressure Drop Across Filter

$$\Delta P = 15-19 \text{ psi} = 41.5-52.6 \text{ in-H}_2\text{O} \approx 50 \text{ in-H}_2\text{O}$$

M E Williams

checked by David Williams

HN -SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT D MASS BALANCE

HC-21C

Material Balance

ATTACHMENT **D**
 PAGE **D-2** of **D-7**
 BASIS DOCUMENT FOR SLUDGE STABILIZATION
 HNF-SD-CP-0CD-040 REV. 3

Feed 1 (Pu Oxalate)

95% HNO₃ driven off as acid

5% Reacts as follows:

Charge Size (grams) 500

	Grams				
	1	2	3	4	5
PuCO ₃ * H ₂ O	472.5				
HNO ₃	5.5			5.23	
O ₂			624.4	624.4688	
CO ₂				59.4	
PuO ₂					365.85
NO				0.0645	
NO ₂				0.0989	
H ₂ O	22			70.779	
N ₂			2497.6	2497.6

95% HNO₃ driven off as acid

5% Reacts as follows:

Charge Size (grams) 500

Grams					
	1	2	3	4	5
Pu(NO ₃) ₄	130				
HNO ₃	165			258.495	
O ₂			624.4	645.616	
CO ₂		4658		4658	
PuO ₂	35				105.46
NO				19.89	
NO ₂				30.5	
H ₂ O				2.457	
N ₂			2497.6	2497.6	
Fe(NO ₃) ₃	165				
(C ₄ H ₉ O) ₃ PO	5				
P ₂ O ₅				1.35	
C ₄ H ₈				2.96	
Fe ₂ O ₃					46.95

Feed 1

Feed 2

Off gas flow rate
Based on 1 hr @ 20°C 260 mm Hg BDA Density 1.225 g/m³

$$\frac{90 \text{ ft}^3}{\text{hr}} \cdot \frac{0.02832 \text{ m}^3}{\text{ft}^3} \cdot \frac{1.225 \text{ kg}}{\text{m}^3} = 3,122 \text{ g of BDA}$$

assume air is 20% O₂ + 80% N₂

$$\begin{aligned} \text{O}_2 &= 624.4 \text{ g} \\ \text{N}_2 &= 2497.6 \text{ g} \end{aligned}$$

CO₂ Cured only with PRF sludge for 3 hrs of the ramp up time
specific volume = 8.76 ft³/lb

$$\frac{30 \text{ ft}^3}{\text{hr}} \cdot \frac{\text{ft}^3}{8.76 \text{ lb}} \cdot \frac{3 \text{ hrs}}{\text{cycle}} \cdot \frac{1 \text{ lb}}{20\% \text{ O}_2} = 4.6575 \text{ kg} = 4658 \text{ g/cycle}$$

27 6/14/94

Feed

$$\begin{array}{rcl}
 P_u & = & 239 = 239(1) \\
 O & = & 16 = 16(1) \\
 C & = & 12 = 12(1) \\
 H & = & 1 = 2 \\
 & & \hline
 & & 349
 \end{array}$$

$$\frac{472.5 \text{ g}}{349 \text{ g/mole}} = 1.35 \text{ g-moles } P_u O C O_3 \cdot 2H_2O$$

$$472.5 \text{ g } P_u O C O_3$$

$$\frac{1.35 \text{ moles } P_u O C O_3 \cdot 2H_2O}{1 \text{ mole } P_u O C O_3 \cdot 2H_2O} \left| \frac{2 \text{ mole } H_2O}{1 \text{ mole } H_2O} \right| = 2.71 \text{ m } H_2O \left| \frac{18 \text{ g}}{1 \text{ mole } H_2O} \right| = 48.8 \text{ g } H_2O$$

$$\frac{1.35 \text{ moles } P_u O C O_3 \cdot 2H_2O}{1 \text{ mole } P_u O C O_3 \cdot 2H_2O} \left| \frac{1 \text{ mole } CO_2}{1 \text{ mole } CO_2} \right| \left| \frac{44 \text{ g } CO_2}{1 \text{ mole } CO_2} \right| = 59.4 \text{ g } CO_2$$

O = 16

N = 14

H = 1

$$\frac{.27 \text{ g } HNO_3}{63 \text{ g/mole}} = .0043 \text{ m } HNO_3$$

$$\frac{.0043 \text{ m } HNO_3}{1 \text{ mole } HNO_3} \left| \frac{1 \text{ mole } H_2O}{2 \text{ mole } HNO_3} \right| \left| \frac{18 \text{ g}}{1 \text{ mole } H_2O} \right| = .039 \text{ g } H_2O$$

$$\frac{.0043 \text{ m } HNO_3}{1 \text{ mole } HNO_3} \left| \frac{1 \text{ mole } NO}{2 \text{ mole } HNO_3} \right| \left| \frac{30 \text{ g}}{1 \text{ mole } NO} \right| = .0645 \text{ g } NO$$

$$\frac{.0043 \text{ m } HNO_3}{1 \text{ mole } HNO_3} \left| \frac{1 \text{ mole } NO_2}{2 \text{ mole } HNO_3} \right| \left| \frac{46 \text{ g}}{1 \text{ mole } NO_2} \right| = .0989 \text{ g } NO_2$$

$$\frac{.0043 \text{ m } HNO_3}{1 \text{ mole } HNO_3} \left| \frac{1 \text{ mole } O_2}{2 \text{ mole } HNO_3} \right| \left| \frac{32 \text{ g}}{1 \text{ mole } O_2} \right| = .0688 \text{ g } O_2$$

$$\frac{1.35 \text{ moles } P_u O C O_3 \cdot 2H_2O}{1 \text{ mole } P_u O C O_3 \cdot 2H_2O} \left| \frac{1 \text{ mole } P_u C_2}{1 \text{ mole } P_u O C O_3 \cdot 2H_2O} \right| \left| \frac{271 \text{ g } P_u C_2}{1 \text{ mole } P_u C_2} \right| = 365.55$$

BEST AVAILABLE COPY

47 6/14/94 Feed 2

Fe

3
12

Fe: 55.85

.26

H = 1

mols $Pu(NO_3)_4 = \frac{55.85}{239} = .234$ m $Pu(NO_3)_4$

C = 12

mols $HNO_3 = \frac{163}{63} = 2.62$ m HNO_3

O = 16

mols $Fe(NO_3)_3 = \frac{163}{242} = .674$ m HNO_3

P = 30.97

mols $(C_4H_9O)_3PO = \frac{5}{265.4} = .019$ m $(C_4H_9O)_3PO$

$Pu = 239$

mols $H_4P_2O_7 =$

N = 14

$NO_2 = 46$, $H_4P_2O_7 = 4 + 2(16) + 7(14) = 177.94$

$Pu(NO_3)_4 = 239 + 4(14 + 16(3)) = 487$ 505

$HNO_3 = 63$

$Fe(NO_3)_3 = 55.85 + 3(14 + 16(3)) = 242.45$ 277.85

$(C_4H_9O)_3PO = (4(12) + 9 + 16(3)) + 30.97 + 16 = 265.97$

$NO = 30$, $P_2O_5 = 142$

.26	27 m $Pu(NO_3)_4$	2 m HNO_3	63 g	32.76
	1 m $Pu(NO_3)_4$	1 mols HNO_3		32.76 g HNO_3

.26	27 m $Pu(NO_3)_4$	1 m NO	30 g	9.8
	1 m $Pu(NO_3)_4$	1 mols NO		9.8 g NO

.26	27 m $Pu(NO_3)_4$	1 m NO_2	46 g	11.96
	1 m $Pu(NO_3)_4$	1 m NO_2		11.96 g NO_2

.26	27 m $Pu(NO_3)_4$	1 m P_2O_5	142 g	37.46
	1 m $Pu(NO_3)_4$	1 mols P_2O_5		37.46 g P_2O_5

.26	27 m $Pu(NO_3)_4$	1 mols O_2	32 g	9.32
	1 m $Pu(NO_3)_4$	1 mols O_2		9.32 g O_2

.019	0.19 m $(C_4H_9O)_3PO$	3 m C_4H_8	52 g	2.96 g C_4H_8
	1 m $(C_4H_9O)_3PO$	1 mols C_4H_8		

.019	0.19 m $(C_4H_9O)_3PO$	.5 m $H_4P_2O_7$	2 m H_2O	36 g
	1 m $(C_4H_9O)_3PO$	1 m $H_4P_2O_7$	1 m H_2O	18 g

.019	0.19 m $(C_4H_9O)_3PO$	.5 m $H_4P_2O_7$	1 m P_2O_5	142 g
	1 m $(C_4H_9O)_3PO$	1 m $H_4P_2O_7$	1 m P_2O_5	142 g

.019	0.19 m $(C_4H_9O)_3PO$	.5 m H_2O	9 g	1.71 g H_2O
	1 m $(C_4H_9O)_3PO$	1 m H_2O		

.59	59 mols $Fe(NO_3)_3$	1 Fe_2O_3	159.7 g	47.11 g Fe_2O_3
	2 m $Fe(NO_3)_3$	1 m Fe_2O_3		

.59	59 mols $Fe(NO_3)_3$	4 m HNO_3	63 g	74.34 g HNO_3
	2 m $Fe(NO_3)_3$	1 mols HNO_3		

.59	59 mols $Fe(NO_3)_3$	1 m NO	30 g	9.85 g NO
	2 m $Fe(NO_3)_3$	1 m NO		

.59	59 mols $Fe(NO_3)_3$	1 m NO_2	46 g	13.57 g NO_2
	2 m $Fe(NO_3)_3$	1 m NO_2		

.59	59 mols $Fe(NO_3)_3$	1 m O_2	32 g	9.44 g O_2
	2 m $Fe(NO_3)_3$	1 m O_2		

ATTACHMENT D
PAGE B-6 of B-7
BASIS DOCUMENT FOR SLUDGE STABILIZATION
HNF-SD-CR-CCD-040 REV. 3

BEST AVAILABLE COPY

13.605 g = .216 moles
63 g

7 6/14/94

13.61 - 13.605
.005 g

NOT AVAILABLE COPY

ATTACHMENT B
PAGE D-7 of D-7
BASIS DOCUMENT FOR SLUDGE STABILIZATION
HMF-SO-CF-000-040 REV. 3

HVF-SD-CP-OCD-040
REV. 3
BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT E REACTIVE INCINERATOR ASH OFF GAS FLOW RATE CALCULATIONS

Westinghouse
Hanford Company

HNF-SD-CA-OCD-040 Rev 3

Internal
Memo

From: PFP Process Engineering 15530-95-LTC-039
Phone: 373-3685 T5-55
Date: May 10, 1995
Subject: AIR FLOW REQUIREMENTS FOR STABILIZATION OF ROCKY FLATS ASH

To: W.S. Lewis T5-55
cc: M.W. Gibson T5-55

The purpose of this memo is to present the results of calculations for determining the air flow required through the HC-21C muffle furnaces when stabilizing Rocky Flats Ash. The air flow must be great enough to provide sufficient oxygen to oxidize the carbon in the ash.

Observations from a TGA done by the PPSL with granular activated carbon indicate that a minimum reaction time of 1.9 hours is required to oxidize a carbon charge. This time was used to perform the remaining calculations.

As seen in Attachment 1, calculations show that an air flow of 0.679 scfm is required to oxidize a charge of 500 grams with 37% carbon to carbon dioxide (CO₂).

Formation of carbon monoxide (CO) due to deficient supply of oxygen is undesirable since CO concentrations of 12.5% to 74.2% are flammable. Evaluation of the PPSL analysis does not show formation of CO with an air flow of 20 cc/min. This is equivalent to an air flow of 1 scfm through the muffle furnaces in HC-21C using the carbon mass to air ratio used for the TGA analysis.

Even if the carbon in a charge were to form exclusively CO, the air flow can be set to ensure the CO concentration is below the lower flammability limit of 12.5%. An air flow of 0.86 scfm was found to maintain the CO level below the LFL.

Therefore, an air flow of 1 scfm is sufficient for charges of Rocky Flats Ash. This flow rate is adequate to oxidize the carbon to CO₂ and also ensures that CO concentrations will remain below the LFL for CO of 12.5%.

L. T. Cunningham
PFP Process Engineer

att

Carbon Monoxide Generation Calculations

- Assumptions:
- Charge weight is 500 grams bulk weight
 - Maximum carbon content is 37% (average is 22%)
 - Carbon homogenously mixed throughout charge
 - Oxygen diffusion into charge is sufficient to maintain carbon oxidation at maximum rate
 - Efficiency of oxygen utilization is 75%
 - Standard Temperature and Pressure

1. Calculate the rate at which carbon will oxidize.

=> Used the TGA run of granular activated carbon (GAC) done in the PPSC laboratory. TGA run done with 130.8 mg GAC and from 20°C to 1000°C at 5°C/min.

* Find the greatest slope of the TG curve.

Data points: 10% weight loss at 590°C and 24% weight loss at 670°C

$$\frac{dT}{d(\text{Weight Loss})} * \left[\frac{100\%}{5^\circ\text{C/min}} \right] = \frac{80^\circ\text{C}}{14\% \text{ weight loss}} * \left[\frac{100\%}{5^\circ\text{C/min}} \right] = 114 \text{ min}$$

2. Calculate the amount of carbon in a charge.

=> The maximum carbon content in the Rocky Flats Ash is 37%. The average carbon content is 22%. Charge size is currently limited to 500 grams.

Maximum carbon in charge:

$$500 \text{ g} * 0.37 \text{ g C/g material} = 185 \text{ g carbon or } 15.417 \text{ g-moles}$$

Average carbon in charge:

$$500 \text{ g} * 0.22 \text{ g C/g material} = 110 \text{ g carbon or } 9.167 \text{ g-moles}$$

3. Calculate the flow rate of air needed to oxidize carbon completely to carbon dioxide.

=> Reaction: $\text{C} + \text{O}_2 \rightarrow \text{CO}_2$

=> Assume efficiency of O_2 use as 75%

=> O_2 used produces an equal volume of CO_2

Oxygen needed:

$$\frac{15.417 \text{ g-moles C}}{1 \text{ g-mole C}} * \frac{1 \text{ g-mole O}_2}{1 \text{ g-mole C}} * \frac{1}{0.75} = 20.556 \text{ g-moles O}_2$$

Air needed:

$$\frac{20.556 \text{ g-moles O}_2}{28.316 \text{ g/g-mole O}_2} * \frac{22.4 \text{ l/g-mole air}}{21 \text{ g-moles O}_2} = 77.43 \text{ ft}^3 \text{ air}$$

$$\frac{77.43 \text{ ft}^3 \text{ air}}{1.9 \text{ hours}} = 40.76 \text{ ft}^3/\text{hr} = 0.679 \text{ scfm}$$

Carbon Monoxide Generation Calculations

4. Calculate the air flow rate to maintain the CO level below the LFL if only CO is produced.

=> Reaction: $2C + O_2 \rightarrow 2CO$

=> LFL of CO is 12.5%

=> O_2 used produces twice the volume of CO

Oxygen needed to make CO:

$$\frac{15.417 \text{ g-moles C}}{1} \times \frac{1 \text{ g-mole } O_2}{2 \text{ g-mole C}} = 10.278 \text{ g-moles } O_2$$

Air needed to produce CO:

$$\frac{10.278 \text{ g-moles } O_2}{1} \times \frac{22.4 \text{ l/g-mole air}}{28.316 \text{ l/ft}^3} \times \frac{100 \text{ g-moles air}}{21 \text{ g-moles } O_2} = 38.72 \text{ ft}^3 \text{ air}$$

$$\frac{38.72 \text{ ft}^3 \text{ air}}{1.9 \text{ hours}} = 20.38 \text{ ft}^3/\text{hr} = 0.340 \text{ scfm}$$

Carbon Monoxide produced:

$$\frac{15.417 \text{ g-moles C}}{1.9 \text{ hours}} \times \frac{1 \text{ g-mole CO}}{1 \text{ g-mole C}} \times \frac{22.4 \text{ l/g-mole air}}{28.316 \text{ l/ft}^3} = 6.42 \text{ ft}^3/\text{hr CO}$$

Air flow rate needed to maintain CO concentration below 12.5%:

$$\frac{6.42 \text{ ft}^3/\text{hr CO}}{12.5\%} = 51.35 \text{ ft}^3/\text{hr} = 0.86 \text{ scfm}$$

If the CO is
produced before
the flow is
then required -

-SD-CP-OCD-040

REV. 3

BASIS DOCUMENT FOR SLUDGE STABILIZATION

ATTACHMENT F PROCESS TEST REPORT: BURNING PLUTONIUM METAL
 BUTTONS USING AN IGNITER

ORIGINAL

Rockwell Hanford Operations

SUPPORTING DOCUMENT		Number	Rev. Ltr./ Chg. No.	Page A of Total Pages																																																			
PROGRAM: CHEMICAL PROCESSING		SD-CP-PTR-008	0	17																																																			
Document Title: PROCESS TEST REPORT: Burning Plutonium Metal Buttons Using An Igniter		Baseline Document ☐ Yes ☒ No																																																					
Key Words: Plutonium metal, Glovebox HC-21-C and Glovebox HA-21-I, oxidation, igniters, Hoskins furnace		WBS No. or Work Package No. K6H3A																																																					
THIS DOCUMENT IS FOR USE IN PERFORMANCE OF WORK UNDER CONTRACTS WITH THE U.S. DEPARTMENT OF ENERGY BY PERSONS OR FOR PURPOSES WITHIN THE SCOPE OF THESE CONTRACTS. DISSEMINATION OF ITS CONTENTS FOR ANY OTHER USE OR PURPOSE IS EXPRESSLY FORBIDDEN.		Prepared by (Name and Dept. No.) <i>Lisa D. Weissbach</i> Lisa D. Weissbach/65930 See reverse side for additional approvals																																																					
Abstract		<table border="1"> <thead> <tr> <th>* Distribution</th> <th>Name</th> <th>Mail Address</th> </tr> </thead> <tbody> <tr><td>*</td><td>E. T. Abramowski</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>R. R. Bevins</td><td>MO-032/2W</td></tr> <tr><td>*</td><td>R. J. Brown</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>S. R. Davis</td><td>2736-28/2W</td></tr> <tr><td>*</td><td>A. L. Ehlert</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>G. A. Glover</td><td>231-Z/2W</td></tr> <tr><td>*</td><td>K. O. Goodey</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>J. L. Johnson</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>G. L. Kunkle</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>R. R. Lehrschall</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>K. E. Nelson</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>J. J. Roemer</td><td>2751-E/2E</td></tr> <tr><td>*</td><td>R. M. Storm</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>C. R. Stroup</td><td>234-5Z/2W</td></tr> <tr><td>*</td><td>R. J. Thomas</td><td>MO-031/2W</td></tr> <tr><td>*</td><td>J. F. Washburn</td><td>234-5Z/2W</td></tr> </tbody> </table>			* Distribution	Name	Mail Address	*	E. T. Abramowski	234-5Z/2W	*	R. R. Bevins	MO-032/2W	*	R. J. Brown	234-5Z/2W	*	S. R. Davis	2736-28/2W	*	A. L. Ehlert	234-5Z/2W	*	G. A. Glover	231-Z/2W	*	K. O. Goodey	234-5Z/2W	*	J. L. Johnson	234-5Z/2W	*	G. L. Kunkle	234-5Z/2W	*	R. R. Lehrschall	234-5Z/2W	*	K. E. Nelson	234-5Z/2W	*	J. J. Roemer	2751-E/2E	*	R. M. Storm	234-5Z/2W	*	C. R. Stroup	234-5Z/2W	*	R. J. Thomas	MO-031/2W	*	J. F. Washburn	234-5Z/2W
* Distribution	Name	Mail Address																																																					
*	E. T. Abramowski	234-5Z/2W																																																					
*	R. R. Bevins	MO-032/2W																																																					
*	R. J. Brown	234-5Z/2W																																																					
*	S. R. Davis	2736-28/2W																																																					
*	A. L. Ehlert	234-5Z/2W																																																					
*	G. A. Glover	231-Z/2W																																																					
*	K. O. Goodey	234-5Z/2W																																																					
*	J. L. Johnson	234-5Z/2W																																																					
*	G. L. Kunkle	234-5Z/2W																																																					
*	R. R. Lehrschall	234-5Z/2W																																																					
*	K. E. Nelson	234-5Z/2W																																																					
*	J. J. Roemer	2751-E/2E																																																					
*	R. M. Storm	234-5Z/2W																																																					
*	C. R. Stroup	234-5Z/2W																																																					
*	R. J. Thomas	MO-031/2W																																																					
*	J. F. Washburn	234-5Z/2W																																																					
<p>Four (4) process tests were performed in Glovebox HA-21-I to determine the safest and most effective method of oxidizing plutonium metal. The final process, which used the button igniter as a heat source, was performed on 08-21-85 and was the most successful in terms of safety, processing time, and ease of operation.</p> <p>Plutonium metal oxidation is accomplished by contacting a heat source with the button to raise the surface temperature of the button to approximately 550°C. At this temperature, ignition occurs and the plutonium metal burns to form a plutonium oxide powder.</p> <p>The first three process tests involved ignition in a Hoskins crucible furnace. Because of poor air supply to the burning oxide and the awkward handling of hot crucibles using tongs, improvements in safety and operating time were needed. An alternative processing method, a button igniter, was fabricated for the fourth process test. The igniter was designed to sit on the button surface and supply sufficient heat to initiate oxidation. Besides reducing processing time from approximately 9 hours to approximately 2 hours, no transferring of hot material was necessary.</p> <p>The procedure and equipment outlined in the fourth process test, PTP-Z-995-0004, "Oxidation Process", will be used as a basis for future plutonium oxidation processing in Glovebox HC-21-C.</p>																																																							
Release Stamp																																																							
<p>94 2 11 02 100 9361</p> <p>OFFICIALLY RELEASED</p> <p>56</p>		<p>(Continued on reverse side)</p> <p>*COMPLETE DOCUMENT (No asterisk, title page/summary or revision page only)</p>																																																					

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number	Rev. Ltr./Chg. No.	Page
	SD- CP-PTR-008	0	1

TABLE OF CONTENTS

	<u>PAGE</u>
1.0 INTRODUCTION	2
2.0 DESCRIPTION OF TEST	3
3.0 TEST METHOD AND TEST EQUIPMENT	5
4.0 TEST RESULTS	6
5.0 RECOMMENDATIONS/CONCLUSIONS	9
6.0 REFERENCES	10
7.0 APPENDIX A	11
7.1 Data Sheets	12 - 15

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number	Rev. Ltr./Chg. No.	Page
	SD- CP-PTR-008	0	2

1.0 INTRODUCTION

Four (4) process tests were performed to determine the safest and most efficient method of oxidizing plutonium metal. The third process test was also run to verify Pu button calorimetry results for Nuclear Material Inventory Control (NMIC). The tests were established by Z-U-T-S Process Engineering and performed by Plutonium Operations in Glovebox HA-21-I. The process tests PTP-Z-995-0004, Rev. 0 - 2, were performed on July 7, 1985, July 18, 1985, July 19, 1985 and August 27, 1985 on buttons 02B-45-06-384, -426, -425, and -401, respectively.

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD- CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 3
---------------------	--------------------------	-------------------------	-----------

2.0 DESCRIPTION OF TEST

Plutonium (Pu) metal oxidation is accomplished by contacting a heat source to the metal, which raises the surface temperature of the button to approximately 550°C. At this temperature, ignition occurs and initiates the oxidation of Pu metal to Pu oxide.

A series of four (4) tests, total, were performed to evaluate processing time and ease of operation. The processing details for each test are described below.

2.1 First Test

The first test examined button ignition and oxidation of Pu metal in a crucible furnace. Besides successful oxidation of the plutonium metal in a crucible furnace, the processing time, ignition temperature, and cooling times, associated with this apparatus was a question answered by this process test.

2.2 Second Test

The second test was an attempt to ignite the plutonium metal button using a soldering iron as an alternative heat source to the crucible furnace. The button was placed in a 6" x 6" x 1" burning pan and the soldering iron held on the button surface. When the soldering iron failed to ignite the plutonium metal, the button was placed in the crucible furnace, heated to ignition, and transferred to the burning pan to complete conversion to the oxide form.

2.3 Third Test

Verification of NMIC calorimetry results and increasing the air supply to the burning plutonium metal were the object of this process test. The button ignition was accomplished in the crucible furnace and then transferred to the 6" x 6" x 1" burning pan to oxidize. After about 30 minutes the burning metal was transferred to an 11" x 11" x 1-1/2" pan which was being tested to see if processing time could be reduced. When sufficient time was allowed to complete cooling of the oxide product, it was transferred to packaging cans.

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD - CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 4
---------------------	---------------------------	-------------------------	-----------

2.4 Fourth Test

An additional heat source, an igniter designed and fabricated for this process test, initiated oxidation of the plutonium button without the use of a Hoskin furnace. The button was placed in an 11" x 11" x 1-1/2" burning pan and the igniter rested on the button surface supplying enough heat through a circular shaped element to initiate oxidation. The plutonium oxide product, once formed in the pan, was allowed to cool and then packaged. As with the other tests, criteria such as total processing time and ease of operation were considered.

In addition, heat dissipation from the burning button was measured using heat crayons. The results of these observations will be discussed in the "test results" section of this document.

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number	Rev. Ltr./Chg. No.	Page
	SD- CP-PTR-008	0	5

3.0 TEST METHOD AND TEST EQUIPMENT

All four (4) process tests involved plutonium metal oxidation in Glovebox HA-21-I. The following summarizes equipment used in each test.

<u>Test 1</u>	<u>Test 2</u>	<u>Test 3</u>	<u>Test 4</u>
Furnace (Hoskins model FD-104	Furnace (Hoskins model FD-104	Furnace (Hoskins model FD-104	Igniter (H-2-95860)
Crucible	Crucible	Crucible	S.S. stirrer
S.S. sheathed chrom-alumel	S.S. sheathed chrom-alumel	S.S. sheathed chrom-alumel	Electronic balance S.S. 11"x11"x1-1/2" pan
Electronic balance	Electronic balance	Electronic balance	Leather gloves Heat crayons
Leather gloves	Soldering iron S.S. 6"x6"x1" pan Leather gloves	S.S. 11"x11"x1-1/2" pan Leather gloves	

*S.S. = Stainless steel

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD- CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 6
---------------------	--------------------------	-------------------------	-----------

4.0 TEST RESULTS

Processing time and operator safety were major criteria for choosing the most desirable processing method. The results for processing time in terms of ignition, burning, and cooling times are summarized in Figure 1. A significant decrease in processing time between the first and fourth run is illustrated by the drop from 8.75 hours to 2.25 hours. This is a decrease of 74%, which translates to a 200% - 300% increase in processing capability. For Runs 1, 2, and 3, the use of the furnace increased ignition time because of poor air supply to the metal. In Run 1, since the conversion of Pu metal to oxide was performed completely in the crucible furnace, the air supply problem was even more evident by the drastic increase in reaction time. For tests 2 and 3, transferring Pu metal and oxide in a hot crucible was awkward and ignition time took longer because of air supply problems. For these reasons, Process Tests 2 and 3 took longer than the fourth process test.

In terms of safety and ease of operation, Process Test 4 was the best processing alternative. The results are presented in tabular form on Table 1. In summary, Run 4 was the safest and easiest process test to perform because the igniter, instead of the crucible, was the heat source. There was no transferring of thermally hot material, no awkward and heavy crucible handling and no air circulation problems around the burning Pu metal. The first test was the next best alternative, since all transfers were made while the plutonium was cool. The worst alternatives were Runs 2 and 3. Because of operating difficulties and transference of hot plutonium metal, these two operating schemes were considered poor choices.

Using the heat crayons during Process Test 4 revealed no heat dissipation problems around or above the burning pan. Temperatures close to normal were observed because of good air circulation. However, the area of contact below the pan, which sat directly on the glovebox floor, became quite hot, reaching approximately 400°C. Because of this finding, a change in the burning pan design was incorporated which added 1" legs. The introduction of an insulating layer of air between the pan and glovebox should prevent future hot spots on the glovebox.

TIMED BUTTON IGNITION

PROCESS TEST RESULTS

TABLE I

OBSERVATIONS ON SAFETY AND EASE OF OPERATION

Run	ACTIVITY	EASE OF OPERATION			SAFETY	OVERALL RATING
		Simple	Simple	Difficult; crucible with button oxide is heavy, hard to hold with tongs		
Run 1	Placed button in crucible furnace Ignition, oxidation, & cooling Removal of crucible from furnace after run completion for weighing & packaging	Simple	Simple	Difficult; crucible with button oxide is heavy, hard to hold with tongs	No problems Furnace is hot; caution around heat source May be problem if crucible breaks, glove rips or loss of Pu oxide inventory	Good
Run 2	Placed button in pan Attempted use of soldering iron Placed button in crucible furnace After ignition transferred button from crucible to burning pan	Simple Simple Simple	Simple	Difficult; crucible with button is heavy (approx. 5 lbs.), very hot (550°C), could burn gloves or organics	No problems Caution around heat source No problems Dangerous if button should fall out or if crucible dropped & broke, possibility of uncontrolled Pu metal fire, burning of gloves	Poor
Run 3	Placed button in crucible furnace After ignition transferred button from crucible to burning pan	Simple	Difficult; crucible with button is heavy (approx. 5 lbs.), very hot (550°C), could burn gloves or organics	No problems Dangerous if button should fall out or if crucible dropped & broke, possibility of uncontrolled Pu metal fire, burning of gloves	No problems	Poor
Run 4	Placed button in burning pan Ignited with igniter Removal from pan after cooling	Simple Simple Simple	No problems Caution around heat source, potential to burn gloves No problems	Excellent		

HNF-SD-CP-OCD-040 Rev 3

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD- CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 9
---------------------	--------------------------	-------------------------	-----------

5.0 RECOMMENDATIONS/CONCLUSIONS

In terms of safety, ease of operation, and processing time, using the igniter to initiate burning was the optimum alternative. The crucible furnace made transfers of plutonium metal, or oxide, a problem and lengthened processing time. This was due to the awkward handling of the crucible with tongs and to the poor air supply available to the burning metal in the crucible. Using the furnace alone, as in the first process test, the operation was both safe and easy to perform, but the processing time was too long and therefore unacceptable.

The second and third process tests were acceptable in terms of processing time, but were considered neither safe nor easy to perform.

Since the fourth process test, which evaluated the igniter, met all the criteria deemed essential for button burning, the process test procedure PTP-Z-995-0004, "Oxidation Process" will be the basis for future plutonium oxidation processing in Glovebox HC-21-C. The operating procedure which will provide instructions for processing is: ZO-160-033, Rev 3.

As for heat dissipation, continued monitoring of the operation is planned. Initial operation will involve two (2) buttons burning simultaneously in HC-21-C. With the availability of additional heat sources and increased operator familiarity with the button burning process, Z-Plant Process Engineering can approve simultaneous ignition of up to four (4) buttons.

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD-CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 10
---------------------	-------------------------	-------------------------	------------

6.0 REFERENCES

Process Test Plans

PTP-Z-995-0004, Rev. 0 - Rev. 2, "Oxidation Process"

Operating Procedure

ZO-160-033, Rev. A-0, "Oxide Pu Metal in Glovebox HC-21-C"

Process Specification

OSD-A-184-00005, "Miscellaneous Treatment"

Drawings

H-2-95860, Button Igniter Assembly

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD-CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 11
---------------------	-------------------------	-------------------------	------------

APPENDIX A

DATA SHEETS

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD-CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 12
---------------------	-------------------------	-------------------------	------------

OXIDATION PROCESS TEST DATA SHEETS

DZA-45-06-384 (07-09-85)

1. Weight of button/% 240: content: 2064.3
2. Time of starting furnace: 10:50 am
3. Time oxidation begins: 11:25 am
4. Temperature oxidation begins: 550°C
5. Time oxidation is complete: 5:45 pm
6. Time furnace is cooled to 500°C: 6:45 pm
7. Tare weight of slip lid can(s): 87.7 - 94.0 grams
8. Gross weight of can(s): 1432.4 - 1172.0 grams
9. Net weight (8-7): 1344.7 - 1078.0 grams wt. gain: 359.4 grams
10. Estimated plutonium value to can(s): (0.88 x net wt. (9.)) 2132 grams
11. Measured Pu value (calorimeter/NDAIA)

- NOTES:
- o Once oxidation started, the metal burned slow due to lack of oxygen.
 - o Material stuck to the sides of pot crucible; operators had to reheat crucible to clean out remaining metal
 - o Metal would arc when temperature reached 2200°C

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number	Rev. Ltr./Chg. No.	Page
	SD- CP-PTR-008	0	13

OXIDATION PROCESS TEST DATA SHEET

DZA-45-06-426 (07-18-85)

1. Weight of button/%240 content: 2054 grams
2. Time soldering iron turned on: 10:00 am
3. Time oxidation begins: 10:43 am
4. Temperature oxidation begins: 575°C
5. Time oxidation complete: 1:30 pm
6. Tare weight of slip lid can(s): 88.2 g/91.3 g
7. Gross weight of can(s): 1331.1 g/1260.2 g
8. Net weight (8-7): 1242.9 g/1168.9 g
9. Estimated plutonium value to can(s): 1093.8 g/1028.6 g
(0.88 x net weight (9.)) Total: 2122.4 g
10. Measured Pu value (calorimeter/NDAIA)

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD-- CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 14
---------------------	---------------------------	-------------------------	------------

OXIDATION PROCESS TEST DATA SHEET

DZA-45-06-425 (07-19-85)

1. Weight of button/% 240 content: 2068.8 grams
2. Time soldering iron turned on: furnace time: 10:15 am
3. Time oxidation begins: 10:55 am
4. Temperature oxidation begins: 550°C
5. Time oxidation is complete: 12:45 pm
6. Tare weight of slip lid can(s): 128.0 g
7. Gross weight of can(s): 2475.3 g
8. Net weight (8-7): 2347.3 g
9. Estimated plutonium value to can(s): 2065.6 g
(0.88 x net weight (9.))
10. Measured Pu value (calorimeter/NDAIA)

Rockwell Hanford Operations

SUPPORTING DOCUMENT	Number SD- CP-PTR-008	Rev. Ltr./Chg. No. 0	Page 15
---------------------	--------------------------	-------------------------	------------

OXIDATION PROCESS TEST DATA SHEET

DZA-45-06-401 (08-27-85)

1. Weight of button/% 240 content: 2037 grams
2. Time ring heater turned on: 11:30 am
3. Time oxidation begins: 12:00 pm
4. Temperature oxidation begins: 550°C
5. Time oxidation is complete: 12:55 pm
6. Tare weight of slip lid can(s): 124.5 g
7. Gross weight of can(s): 2461.0 g
8. Net weight (8-7): 2336.5 g
9. Estimated plutonium value to can(s): 2056.12 g

(0.88 x net weight (9.))

10. Measured Pu value (calorimeter/NDAIA)

11.	<u>Heat Crayon Types</u>	<u>Melt? (y/n)</u>	<u>Time</u>	<u>Location</u>
	52°C	N	12:30	1' from pan inside glovebox
	150°C	Y	12:30	Under glovebox, under pan
	260°C	Y	12:35	Under glovebox, under pan
	371°C	Y	12:40	Under glovebox, under pan
	427°C	N	12:45	Under glovebox, under pan