**Cover Sheet for a Hanford
Historical Document
Released for Public Availability**

Released 1995

**Prepared for the U.S. Department of Energy
under Contract DE-AC06-76RLO 1830**

**Pacific Northwest Laboratory
Operated for the U.S. Department of Energy
by Battelle Memorial Institute**

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, make any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

HW-33007

DECLASSIFIED RECORD CENTER FILE

GENERAL ELECTRIC
COMPANY

HW-33007

- 2 -

Classification Cancelled and Changed To
DECLASSIFIED

By Authority of CG-PR-2
CH Henager 12-3-91
By JH Wells 12-1-94
Verified By Jessi Mally
12-22-94

NOT UCN

E. G. Fiorick, Head
Process Engineering Unit
Superations Section

1. E. G. Fiorick
2. W. H. Mahley-LI Brooks
3. E. G. Hall-AM HANST
4. W. G. Genger
5. G. F. Hill
6. G. H. Genger
7. A. E. Smith-AM HANST
8. J. H. Wells
9. J. H. Wells

September 7, 1954

RECEIVED

JUL 6 1954

300 AREA
CLASSIFIED FILES

RE: HANDLING OF PLUTONIUM METAL

In answer to your letter of August 2, 1954, requesting technical information as to the handling of plutonium metal in various forms, we have the following comments and recommendations to make:

1. Exp-Chemistry and Reduction. Laboratory work has shown that the addition of water to the reduction bath causes the formation of a highly reactive coating (composition unknown) on the bottom on the side next to the crucible. Presumably water in any form could cause such an effect. Consequently, precautions should be taken to ensure complete dryness of the reduction bath and all its contents. In considering the results of laboratory work upon the reduction of low temperature fluorides, it appears that plutonium tetrafluoride, which has been hydrofluorinated at a maximum temperature as low as 450 C may contain small quantities of water. Since this possibility exists and since better fluorides may be found at higher hydrofluorination temperatures, the current that II, temperature-time cycle studies should be of interest from this viewpoint.
2. Handling of Metal in Miscellaneous Forms. Metal should never be stored in contact with a flammable material. However metal (except buttons for ship-mat) is to be removed from the line and/or stored for any length of time, it should be placed in a dry, air-tight metal container (such as the one used formerly in use in the 20 Line), evacuated, and the air replaced with dried air of dewpoint less than -40 F. Any cans used for such a

REPRODUCED FROM BEST

AVAILABLE COPY

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DECLASSIFIED

E. G. Pirrick

- 2 -

September 7, 1954

purpose should contain as little excess volume as possible, to reduce to a minimum the amount of oxygen which is present and free to react with the metal.

3. Turnings. In general, turnings should not be removed from the line and should be handled as little as possible. They should be brigotted as soon as possible after machining and should be weighed or stored as briquettes. Besides reducing any hazard associated with the handling of turnings, this procedure should give a reduction in the size of the shells resulting from casting briquettes.
4. Shipment of Buttons. The present procedure preparing buttons for shipment is probably satisfactory, provided the following precautions are taken: only good, smooth buttons with no evidence of unusual sensitivity should be shipped; and the buttons should be sealed into the can immediately after sealing into the plastic bag. However, to give an added safety factor and to comply with the recommendation that the metal never be left in contact with a flammable material, it appears wise to wrap the button in aluminum foil before placing it in the plastic bag.
5. Sampling. Present, approved Process Specification 5.05 reads as follows: "Samples of plutonium are cut from clean metal surfaces (polar and planar) and packaged immediately in clean dry containers flushed with inert gas." This is adequate.

We believe that compliance with the above suggestions will assure the safe handling of plutonium metal in its various forms in the operating line.

Original signed by
O. F. Hill

Head, Plant Processes Unit
Technical Section

OF Hill/mab

RECEIVED

SEP 8 1954

ADRA WOODS
CLASSIFIED FILES

DECLASSIFIED