SURVEILLANCE OF 18 Hz AND 60 Hz COMPONENTS OF GROUND MOTION AT THE APS SITE

by

ANL/APS/IN/VIB--90/1

J. A. Jendrzeczyk, M. W. Wambsganss, and R. K. Smith

DE92 012173

Materials and Components Technology Division
Argonne National Laboratory

Background

Successful operation of the APS Facility requires stability of the positron closed orbit. Any vibration transmitted to the magnets, through paths such as the magnet support structure, will cause orbit distortion leading to emittance growth for high frequencies; low frequency (<10 Hz), distortions can be interpreted as positron and photon beam steering and corrected with feedback systems using steering magnets. For frequencies greater than 10 Hz, the vibration criteria require that peak vibration amplitudes of the quadrupole magnets be limited to $0.34\text{ }\mu\text{m}$ and $0.12\text{ }\mu\text{m}$ in the horizontal and vertical directions respectively.

Far field vibration sources, those which are generated external to the facility, have been measured and reported [1]. From this study it can be concluded that the amplitude of site ground motion is very low, less than 0.05 micron rms, with the exception of a few relatively high level transients and large amplitude motion at discrete frequencies of 18 Hz and 60 Hz. The latter, which is of an intermittent nature and present only at measurement locations 3 and 4, is shown in Fig. 1; frequency content is presented in Fig. 2. The numbers on the plot in Fig. 2 correspond to time in minutes from the beginning of the measurement sequence.

The levels of the 18 and 60 Hz motion exceed the allowable vibration amplitude. Further, the frequencies are above the upper limit for correction with the feedback system and steering magnets. As a consequence, these motions are of concern and it was deemed necessary to investigate this motion relative to its source and occurrence.

Objective

The objectives of this study are to determine the location and source of the 18- and 60-Hz vibration and to eliminate or reduce its amplitude. To accomplish this it is necessary to know the time of occurrence and then, to utilize triangulation methods to identify the location of the source. If its time sequence is

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

known, it may be possible to correlate it with the operation of some equipment at or near the site. Therefore, a major effort was made to obtain the time sequence and is the basis of this note.

Location and Time

Vibration measurements began on July 28, 1988, and ended on January 30, 1990, and were continuous within that period. Other data, such as, groundwater level, water level in the AARR hole, and soil temperature was accumulated whenever possible. Location 3 (51,602 North-31,562 East), Fig. 3, was used for vibration measurements using the same accelerometer mounting method described in Ref. 1. The monitoring instruments were located in a room of Building 383. It was necessary to cross a gravel road, this was accomplished by elevating the instrumentation cable was elevated above the gravel road with a telephone pole.

Data Acquisition System

The data acquisition system, Fig. 4, consisted of a PCB #393C Accelerometer, a PCB #180A10 Integrating Amplifier, and a PCB 180D06 Amplifier, the output of which was coupled to a 60 Hz bandpass Filter. After additional amplification and detection the signal was monitored on the strip chart recorder. Since one objective of this study was to determine the time sequence of the 18 Hz and 60 Hz vibrations, and not normal site noise such as vehicle traffic, construction activities, and other random sources, a 60 Hz bandpass filter was employed. The filter response characteristic is shown in Fig. 5. The detection and filter circuits eliminated the printout of vibration amplitude levels of less than 0.057 micron rms which made data reduction considerably easier, as only the high levels would be shown. Response of the recorder-detector system to input voltage is shown in Fig. 6, with the recorder scale of 0-1 equal to a displacement measurement range of 0.057 - 0.149 micron, rms. Figure 7 is a copy of the chart record produced on July 28, 1988. It is the only positive response that was obtained during the duration of the monitoring program.

Related Site Measurements

A pump, possibly used for dewatering, was considered a possible source of the vibration. To investigate this possibility, site water level was monitored to determine any possible correlation with the measured vibration. Water level at

borehole APS-28 is shown in Fig. 8. Data from May 1988 to February 1989 were provided by the Illinois State Geological Survey; we made our own measurements from June 1989 to December 1989.

Water level in the AARR hole was monitored from the beginning of January 1989 to the end of January 1989, when it was pumped out. No appreciable water level changes were observed during the four weeks of monitoring.

Precipitation data (measured at the ANL Weather Station) was obtained but apparently there was no correlation with the vibration.

A related vibration study, funded by the ANL Engineering Division [2], involved floor and structure vibration measurements in Building 360, on June 15, 1989. A low amplitude vibration with a large 18 Hz and 60 Hz frequency content was measured on the large caisson which supports the accelerator and is anchored in bedrock; see the frequency response plot of Fig. 9. This result was an indication that the vibration may have been conducted through the bedrock. To verify the conduction path, several more measurements were made; at the caisson and also at a USGS water level monitoring well located approximately 75 ft Northeast of the intersection of Bluff and Kearney roads. This well was chosen because it appeared to be a private property well in time past with the possibility that the casing was driven into bedrock, and could thus act as a waveguide. These measurements were made on October 6, 1989: at 9:30 AM in Building 360 and at 10:30 AM on the well casing. The frequency spectrum of the octant vibration is shown in Fig. 10; frequencies of 18 Hz and 60 Hz are still present, along with a large 30 Hz component which may have originated within the IPNS Facility. There is an absence of both frequencies (30 Hz and 60 Hz) from the frequency spectrum of the vibration measured on the well casing (Fig. 11).

Discussion

Although the monitoring continued to January 30, 1990, only one positive response was recorded, that being on July 28, 1988. Many small events occurred over the measurement period but none could be positively identified. Some were related to site construction, others to measurement equipment operation (e.g., weak batteries), and to mechanical damage to cabling and transducer resulting from exposure to the weather.

From Fig. 8, it can be assumed that the water level at APS-28 was at its highest level in the Spring of 1988, and was lower for the remainder of the surveillance period. If the 18 Hz and 60 Hz vibration is related to a water

pumping activity, it may not occur again unless the groundwater is above a certain level.

References

1. J. A. Jendrzeczyk, Z. Nagy, and R. K. Smith, "Ambient Ground Motion at the 7-GeV APS Site at Argonne National Laboratory over Extended Time Periods," LS-136, December 1988.
2. J. A. Jendrzeczyk, Z. Nagy, and R. K. Smith, "Vibration Measurements at the WAFFOG Area of ANL NPB Test Area B," ANL-MCT/MV1424, July 1988.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Total Displacement "Wideband" (4-100Hz)

Figure 1. Total displacement at Locations 3 and 4

Figure 2. Spectral content of displacement measured at Location 3

Figure 3. Measurement locations

Figure 4. Data acquisition system

Figure 5. Bandpass filter response

Figure 6. Detector- Recorder sensitivity

Figure 7. Actual 60 Hz measurement on July 28, 88

Figure 8. Water level at APS-28, with reference to top of casing
(755 ft., Ground level = 753 ft.)

Figure 9. Frequency content of vibration measured on octant at Building 360 on June 15, 89

Figure 10. Frequency content of vibration measured on octant at Building 360 on Oct. 6, 88 at 9:30 AM

Figure 11. Frequency content of vibration measured on USGS well on Oct. 6, 88 at 10:30 AM

END

**DATE
FILMED**

6 10 8 192