THE FEASIBILITY OF WELDING OF IRRADIATED MATERIALS

H. T. Lin* and B. A. Chin
Materials Engineering, Auburn University, AL 36849

Abstract

Helium was implanted into solution-annealed (SA) 316 stainless steel, 20% cold-worked (CW) 316 stainless steel and titanium-modified Primary Candidate Alloy (PCA) through tritium decay to levels ranging from 0.18 to 256 appm. Full penetration welds were then made on helium-doped materials using gas tungsten arc welding (GTAW) under fully constrained conditions. Intergranular heat-affected zone (HAZ) cracking was observed in all of the materials containing greater than 1 appm He. Electron microscopy showed that the HAZ cracking originated from the growth and coalescence of grain boundary (GB) helium bubbles. Bubble growth kinetics in the HAZ is explained by stress-enhanced diffusive cavity growth. Results suggest that the propensity for HAZ cracking can be reduced by the preexisting cold-worked structure and by finely-distributed MC precipitates that refine the distribution of helium bubbles and minimize the flow of vacancies in grain boundaries.

Key words: tritium trick, helium-doped material, gas tungsten arc welding, heat-affected zone cracking, fusion zone cracking, stress-enhanced diffusive cavity growth, helium embrittlement.

*Present Address: Metals and Ceramics Division, Oak Ridge National Laboratory, Oak Ridge, TN 37831-6068.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

1. Introduction

Degradation of structural materials due to physical damage induced by neutron bombardment (14 MeV) and associated transmutation reactions plays a decisive role in determining the operational life of fusion reactors [1,2]. To achieve economical operation of the fusion reactors, it is reasonable to assume that repair and replacement of irradiation-degraded and damaged components, particularly the first wall, by conventional welding techniques will be required.

The major effect that will be encountered during the welding of irradiated first wall materials is the entrapped helium which is generated by (n,α) reactions and tritium decay in the material [3,4]. It is well known that the presence of GB helium bubbles can cause substantial loss of ductility of irradiated materials at elevated temperatures [3,5]. The helium bubbles grow rapidly under the influences of high temperature and tensile stress. As these bubbles grow and coalesce along the grain boundaries, intergranular fracture can occur prematurely. Since welding processes always produce high temperatures and high thermal stresses, the growth of GB helium bubbles is anticipated to be enhanced during welding.

To date little work has been performed on the welding of irradiated materials, particularly none that is applicable to fusion conditions, i.e. high helium concentrations (≥ 100 appm). The purpose of this study was to elucidate the principal effect of helium on the weldability and post weld properties of materials. The effects of fabrication processes and material composition on weld cracking tendency induced by helium were also evaluated.

2. Experimental procedures

In this study, SA 316 stainless steel was investigated as a primary alloy and 20% CW 316 stainless steel and SA PCA (Ti-modified alloys) were secondary alloys. These alloys have been investigated extensively in the U.S. Fusion Materials Program [6]. The chemical compositions for 316 stainless steel and PCA can be found in ref. 6. Type 316 stainless steel was annealed at 1050°C for 1 h in an inert gas atmosphere. The cold-worked specimens were obtained from sheet by 20% rolling; prior to final cold work, the material was annealed at 1050°C for 1 h. The PCA specimens were annealed at 1100°C for 45 minutes. The purpose of 20% CW 316 stainless steel and PCA studies was to understand how fabrication process and chemical composition affect the weld cracking tendency induced by helium.

To avoid radioactive hazards and remote hot cell operations that would be involved in working with neutron-irradiated materials, the helium was implanted into test materials through tritium decay (tritium trick technique) [7]. In this technique tritium gas was diffused into the materials at elevated temperatures and at high pressures. The entrapped tritium was then allowed to decay to form helium by the reaction ${}^3\text{H} \rightarrow \beta^- + {}^3\text{He}$ with a half life of 12.3 years. All materials were charged at 300°C and at tritium pressures from 0.07 to 125 MPa for 30 days. The helium levels generated under these charging conditions ranged from 0.18 to 256 appm. At the end of this charging period, the exposed materials were removed from the high pressure charging vessel and degassed at 400°C in a vacuum of 10^{-3} Pa to remove the residual tritium and therefore to stop the further generation of helium. The detailed charging conditions for each material with variable helium levels can be found in ref. 8. To demonstrate that weld cracking which occurred during welding

arose only from the presence of helium rather than tritium, specimens of 316 stainless steel were charged with hydrogen under the same charging conditions as the highest helium content materials.

Bead-on-plate GTA welds were then made on control, hydrogen-charged and helium-doped materials. Full penetration welds were produced in the 0.76 mm-thick plates at 10 V-dc, 24 A at a travel speed of 3.6 mm/s under argon atmosphere enclosed by a plastic chamber. The plates were fully constrained to simulate the structural restraint expected to be experienced by actual irradiated components during weld repair.

Following welding, all of the welds were examined in detail using a scanning electron microscopy (SEM). The weld microstructures were also examined by preparing metallographic sections transverse to the welding direction. The sections were electrolytically etched in a solution of 40% HNO_3 - 60% H_2O . The helium bubble distribution morphology in the HAZ was examined using transmission electron microscopy (TEM).

3. Results and discussion

3.1 SA 316 stainless steel

Results of metallography and SEM examinations showed that control, hydrogen-charged and 0.18 appm He content plates were sound and free of any weld defects. However, materials containing greater than 1 appm He all revealed a severe degradation of weldability. Figure 1 shows the typical features for the welds with 2.5 appm helium level. Severe, continuous HAZ cracking was consistently observed in all of the welds with helium levels greater than 2.5 appm. In addition to HAZ cracking, center line fusion zone cracking was also observed in the materials with helium concentrations greater than 100 appm. Generally, the HAZ cracking occurred one to three grain

diameters from the fusion boundary, and was fully intergranular in nature. At higher magnification, the grain facets were observed to be decorated with a uniform distribution of dimples attributed to helium bubbles. The dimple spacing was approximately $1\text{ }\mu\text{m}$. Additionally, the shear ligaments separating the dimples were found to have been rounded by surface diffusion, indicating that cracking occurred at high temperature. The measured thermal cycle in the HAZ confirmed that fracture occurred at about 1150°C [8]. The SEM examinations of fusion zone cracking indicated that brittle fracture proceeded along the dendritic interfaces during weld pool solidification. Spherical pores resulting from the growth of helium bubbles trapped in the melt were also observed on the fracture surface.

Since the control and hydrogen-charged materials were uncracked, it is clear that the degradation of weldability is entirely related to the entrapped helium, not to tritium or hydrogen. In addition, the cracking location, one to three grain diameters from the fusion boundary, suggests that high temperature alone is not sufficient to induce brittle HAZ fracture. Rather, a critical combination of high temperatures and tensile thermal stresses is a key factor in controlling the helium bubble growth and crack formation. Since no external loads were applied prior to welding, the HAZ cracking arose from the generation of tensile thermal stresses as the material contracted upon cooling of the constrained plates.

The GB helium bubbles ($\approx 1.8\text{ nm}$) which formed during helium doping grew during the weld thermal cycle until the reduced contact area could no longer bear the shrinkage thermal stress, leading to final brittle fracture. A model which has been proposed to describe the cracking indicates that the growth kinetics of GB helium bubbles leading to intergranular HAZ cracking is

dictated by the stress-induced diffusion of vacancies into bubbles [8]. The growth of GB bubbles is governed by the absorption of vacancies into bubbles. The initial driving force for this mechanism is the helium gas overpressure in the bubbles. Such growth occurs even in the absence of applied tensile stress. Subsequent growth of bubbles is controlled by the shrinkage-imposed tensile stresses developed during cooling. The model predicts that the GB helium bubbles should reach about $0.85\text{ }\mu\text{m}$ in diameter one second after the passing of the torch. The prediction compares favorably with the experimentally measured dimple spacing ($1\text{ }\mu\text{m}$) and the time observed for the onset of cracking.

3.2. 20% CW 316 stainless steel

GTA welds of 20% CW 316 stainless steel (Fig. 2) were made to investigate the effect of mechanical treatment during fabrication on the HAZ cracking tendency of helium containing materials. Results showed that no cracking was observed for the control materials, while cracking occurred in the HAZ (Fig. 2b) during cooling of the welds on material containing 1.9 appm He (3 out of 3). As in the case of SA 316 stainless steel, cracking in the HAZ was fully intergranular in nature and the grain facets were covered with a uniform distribution of dimples (Fig. 2c). Again, the HAZ cracking was approximately three grain diameters from the fusion boundary. The length of the cracking was 8% of the total length of the weld bead which was much less than that of SA type 316 stainless steel (80%). This latter result suggests that mechanical pretreatment may be used to reduce the HAZ cracking tendency of helium-containing materials. This tendency is attributed to two possible mechanisms: dislocation structures which act as a sink for helium atoms and vacancies, and recovery processes of cold-worked grains which consume many of

the vacancies reducing available vacancies for bubble growth. However, further study is needed to provide insight into the microscopic control mechanisms.

3.3. Primary candidate alloy

Figure 3 shows the as-welded features of Ti-modified austenitic stainless steel (PCA) containing 1.6 appm He. The postweld SEM examinations indicated that only one of the three welded plates revealed HAZ cracking. The HAZ cracking was limited to the beginning region of the weld. Again, the HAZ fractured intergranularly and was one to three grain diameters from the fusion boundary. Results also showed that the degree of HAZ cracking (length of cracks) was significantly reduced from 80% down to 0.6% with respect to that observed in SA 316 stainless steel (Fig. 1a). This suggests that PCA exhibits much better resistance to high temperature weld helium embrittlement than SA 316 stainless steel. The addition of Ti into austenitic stainless steels leads to the formation of MC precipitation [9-12]. It is hypothesized that these precipitates act as trapping sites for helium, thereby reducing the amount of helium on the grain boundaries. Experimentally, it has been found that formation of these carbides can substantially increase the resistance to helium embrittlement following irradiation [13,14]. Creep-rupture results of German Ti-stabilized austenitic stainless steel (DIN 1.4970) further supports this hypothesis [15,16]. It was suggested that carbide formation such as MC within the grain boundaries traps helium and refines the bubble distribution at particle interfaces and affects the grain boundary resistance to migration and its behavior as a sink for helium [11,15]. Additionally, the presence of MC precipitates at grain boundaries will inhibit grain boundary sliding which reduces the stress-induced flow of vacancies along the grain boundaries,

further reducing the bubble growth. Accordingly, helium accumulation and bubble growth rates on the grain boundaries are retarded, and the occurrence of HAZ cracking induced by helium is reduced.

4. Conclusions

This study of the welding of austenitic stainless steels containing helium has led to the following conclusions:

- Severe intergranular HAZ cracking occurred during cooling of the GTA welded SA 316 stainless steel, 20% CW 316 stainless steel and PCA plates containing helium levels ≥ 1 appm.
- Intergranular HAZ cracking originates from the growth and coalescence of GB helium bubbles. Brittle fracture in the fusion zone of SA 316 stainless steel containing greater than 100 appm He arises from the precipitation of helium bubbles at dendrite boundaries.
- High peak temperature is not the main driving force for HAZ cracking. A critical combination of high temperature and stress is necessary.
- PCA, Ti-modified 316 stainless steel containing helium, exhibits less weld cracking than SA 316 stainless steel under similar welding conditions.
- Retained cold-worked structure can reduce the HAZ cracking tendency observed in helium containing austenitic steels.

Acknowledgements

The authors thank Drs. K. Farrell and S. J. Zinkle for reviewing the manuscript. This research was sponsored by the Office of Fusion Energy, U.S. Department of Energy under Contract DE-AC05-84OR21400 with Martin Marietta Energy Systems, Inc., and Grant DEFG0585ER52139C with Auburn University.

References

- [1] H. S. Rosenbaum, Treatise on Materials Science and Technology, vol. 7 (Academic Press, Inc., New York, 1975).
- [2] J. O. Stiegler and L. K. Mansur, Ann. Rev. Mater. Sci. 9 (1979) 405.
- [3] R. S. Barnes, Nature 206 (1965) 1307.
- [4] D. R. Harries, J. Nucl. Mater. 82 (1979) 2.
- [5] H. Ullmaier, Nucl. Fusion 24 (1984) 1039.
- [6] R. E. Gold, E. E. Bloom, F. W. Clinard, D. L. Smith, R. D. Stevenson and W. G. Wolfer Nucl. Tech/Fusion 1 (1981) 169.
- [7] Annual Books and ASTM Standards, Standard Guide for Simulation of Helium Effects in Irradiated Materials, Vol.12.02, E492-83, p. 808.
- [8] H. T. Lin, Ph.D. Dissertation, Auburn University, 1989.
- [9] W. R. Martin and J. R. Weir, in Effects of Radiation on Structural Metals, ASTM STP-426 (1967) 440.
- [10] A. F. Rowcliffe, G. J. C. Carpenter, H. F. Merrick and R. B. Nicholson, in Effects of Radiation on Structural Metals, ASTM STP-426 (1967) 161.
- [11] D. R. Harries and A. G. Roberts, in Effects of Radiation on Structural Metals, ASTM STP-426 (1967) 21.
- [12] P. J. Maziasz, in MiCon 86: Optimization of Processing, Properties, and Service Performance Through Microstructural Control, ASTM STP-979 (1988) 116.
- [13] P. J. Maziasz and E. E. Bloom, Trans. ANS 27 (1977) 268.
- [14] P. J. Maziasz and D. N. Braski, J. Nucl. Mater. 122&123 (1984) 305.
- [15] W. Kesternich and J. Rothaut, J. Nucl. Mater. 103&104 (1985) 153.
- [16] W. Kesternich, J. Nucl. Mater. 127 (1985) 153.

Figure Captions:

Figure 1. Structures of as-welded SA 316 stainless steels containing 2.5 appm He. (a) SEM micrograph showing HAZ intergranular fracture, (b) SEM micrographs showing details of intergranular fracture, (c) SEM micrograph of grain facets decorated with a uniform distribution of dimples.

Figure 2. Structures of as-welded 20% CW 316 stainless steel containing 1.9 appm He. (a) SEM micrograph showing intergranular HAZ fracture, (b) SEM micrographs showing details of intergranular fracture.

Figure 3. Structures of as-welded Ti-modified Primary Candidate Alloy containing 1.6 appm He. (a) SEM micrograph showing intergranular HAZ cracking limited to the beginning region of the weld, (b) SEM micrograph showing details of intergranular fracture.

SA 316 SS

20% CW 316 SS

SA PCA