WHC-SD-WM-EV-098, REV, 0

INVENTORY OF TANK FARM EQUIPMENT STORED
OR ABANDONED ABOVEGROUND

October 5, 1994

Prepared by
Tank Farms Environmental Engineering

S. C. Hines
M. E. Lakes

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

TABLE OF CONTENTS

<u>Section</u>	<u>Description</u>	<u>Page</u>
1.0	SUMMARY.....	3
2.0	INTRODUCTION.....	3
3.0	PURPOSE.....	4
4.0	SCOPE AND OBJECTIVE.....	4
4.1	SCOPE.....	4
4.2	OBJECTIVE.....	5
5.0	REGULATORY DISCUSSION.....	5
6.0	ACCESSIBLE EQUIPMENT INVENTORY.....	5
7.0	EQUIPMENT INVENTORY DESCRIPTION.....	6
7.1	EAST AREA	
7.1.1	EAST AREA TANK FARMS.....	6
7.1.2	EAST AREA CONEX BOXES.....	6
7.2	WEST AREA	
7.2.1	WEST AREA TANK FARMS.....	7
7.2.2	WEST AREA CONEX BOXES.....	7
7.2.3	WEST AREA EVAPORATORS.....	8
7.3	MISCELLANEOUS AREAS.....	8
8.0	RECOMMENDATIONS.....	9
9.0	REFERENCES.....	10
10.0	APPENDICES.....	10
	APPENDIX A "TANK FARM AREAS INVENTORIED".....	A-0
	APPENDIX B "IDENTIFICATION OF DATABASE FIELDS"....	B-0
	APPENDIX C "EQUIPMENT DATABASE AND PHOTOGRAPHS"..	C-0
	APPENDIX D "AERIAL PHOTOGRAPHS OF TANK FARMS"....	D-0

1.0 SUMMARY

Early in FY94, an Engineering Work plan was developed detailing the need and extent of this equipment inventory (5). This inventory was conducted as a first step toward ensuring environmental compliance with dangerous waste regulations concerning the storage and disposal of equipment and/or debris that has contacted dangerous waste.

The Tank Farm contaminated equipment inventory consists of two phases. The first phase includes conducting an inventory of accessible above ground contaminated equipment that may no longer be needed. The second phase will include inventorying equipment contained within Tank Farm ancillary units such as diversion boxes, valve pits, process pits, etc. The inventories are being developed for use as a tool for identifying whether the equipment is reusable, recyclable, amenable to decontamination, or if it is waste, and to help in decisions regarding retrieval, storage, characterization, remediation and disposal. The first phase of the equipment inventory has been completed. This report details the aboveground portion of the equipment inventory.

This document identifies the Tank Farm areas inventoried and provides photographs of potentially contaminated equipment found to exist in Tank Farms. Appendix A includes a listing of all areas inventoried for this report. Appendix B identifies each of the fields in the database. Appendix C of this report includes photographs taken of potentially contaminated equipment stored in Tank Farms and facilities maintained by Tank Farms. Also, information was gathered in an effort to provide additional information related to the equipment. This information has been incorporated into the database, a printout of which is included with the equipment pictures in Appendix C. Appendix D includes aerial photographs of Tank Farm.

2.0 INTRODUCTION

The inventory was the first step required to help make an accurate assessment of the quantities and types of contaminated equipment residing in Tank Farms. This report identifies contaminated equipment residing in Tank farms that may no longer be needed. The information will provide a framework for a determination regarding the storage, decontamination, or disposal of any contaminated equipment. Only equipment that is likely or known to have been in contact with tank waste from process knowledge was included in the inventory.

This report provides some of the information that will be used by other organizations in making decisions on whether equipment is contaminated, reusable, whether it is needed, should be recycled, used at other locations, or classified as waste. This report will also aid in the characterization of any contaminated equipment destined for disposal.

3.0 PURPOSE

This report provides a detailed description of the inventory of above ground contaminated equipment in Tank Farms. Several potential regulatory issues exist concerning the storage of contaminated equipment. This report is the first step in determining what is to be done with the equipment and to help ensure that WHC is in compliance with State and Federal waste handling regulations.

4.0 SCOPE AND OBJECTIVE

4.1 SCOPE

This report includes an inventory of accessible above ground contaminated equipment within Tank Farms facilities. This inventory is focused on equipment that has potentially been in contact with tank waste and will not necessarily be reused.

This report does not include an inventory of all areas that were initially intended for the accessible portion of the inventory. Some areas, originally intended for this inventory were not adequately accessible, such as the 242-S evaporator building. Safety concerns posed problems for inventory of some of the areas. The following areas will be inventoried to the extent possible or have their inventories updated during Fiscal Year 1995:

1. 242-T Evaporator
2. 242-S Evaporator
3. Miscellaneous Buildings in C-Farm
4. Update of the Conex box inventories
5. Any other areas identified as belonging to Tank Farms requiring an inventory for stored/abandoned equipment
6. Shield plug areas in each Single-Shell Tank Farm

4.2 OBJECTIVE

The objective of this report is to provide a listing of potentially contaminated equipment in Tank Farms with accompanying photographs, a statement of location, and background information. This report was written in response to regulatory concerns posed in the engineering work plan WHC-SC-WD-WP-270(5).

5.0 REGULATORY DISCUSSION

The existence of contaminated equipment within Tank Farms poses several compliance issues. In early 1993, it was recognized by TWRS Plant management that potential issues regarding proper dangerous waste management exist. The issues include topics concerning proper management and storage of contaminated equipment, housekeeping, safety, soil contamination, and fugitive emissions. A proposed site policy for contaminated equipment has been drafted by the Environmental Protection Agency (EPA). Under the proposed policy, equipment or material contaminated with Tank Waste (including condensate) would become hazardous waste if that equipment or material is not reusable. Consequently, equipment contaminated with hazardous waste must be managed as dangerous waste unless or until it no longer contains the waste, is adequately decontaminated or is delisted. Options for management of contaminated equipment include, but may not be limited to: management in a compliant generator accumulation area; management in a compliant Treatment, Storage or Disposal (TSD) unit; or management in accordance with a regulatory agency approved RCRA or CERCLA decision document. Storing radioactive contaminated equipment or material may also be contributing to "fugitive emissions" under the radioactive air emission authority of the Washington State Department of Health.

6.0 ACCESSIBLE EQUIPMENT INVENTORY

The aboveground inventory encompassed both Tank Farms and Tank Farm facilities. Only equipment that was likely or known to have been in contact with tank waste from process knowledge was included in the inventory. Photographs were taken of potentially contaminated equipment stored in Tank Farms and facilities maintained by Tank Farms, as well as equipment outside the farms likely to have been in contact with tank waste. Information was also gathered from different sources in an effort to provide additional data related to the equipment. The database will be maintained and updated as additional information is known about the equipment. Appendix B defines each of the fields identified in the database.

7.0 EQUIPMENT INVENTORY DESCRIPTION

7.1 200 EAST AREA

7.1.1 EAST AREA TANK FARMS

The East Area Tank Farms contain the majority of the Tank Farm contaminated equipment. The A, BX, BY, and C Tank Farms contain large quantities of equipment that are potentially contaminated and may not be reusable. The BX and BY Tank Farms contain a large number of contaminated jumpers and lead shielding.

A-Farm contains two old exhausters that have been in contact with tank waste. These exhausters have been in this complex for years, and are greatly deteriorated due to weathering. It is noted that a number of small animals, especially birds, have built their nests inside the stacks and other exposed areas of these exhausters and other equipment. Resident animals spread contamination not only within Tank Farms but throughout the site.

C-Tank Farm contains equipment that is most likely to be contaminated and not reusable. Many items are wrapped in plastic for storage and for the prevention of contamination spread to the soil. Much of the plastic has deteriorated and may result in contamination of the surrounding soil if corrective action is not instituted in a timely manner.

The C-Farm inventoried equipment also includes one large crane, an exhauster, valve handles and some unidentified equipment probably used in conjunction with 244-CR vault.

7.1.2 EAST AREA CONEX BOXES

Three Tank Farms in the East Area each contain a Conex box housing potentially contaminated equipment. All three Conex boxes were inventoried.

The AW Conex box, located within the fence line of AW Tank Farm, contains a large quantity of waste contacted equipment. Most of this equipment is wrapped in plastic (for contamination control) precluding a complete inventory. Items identified include flexible and fixed jumpers, valve handles and other tank farm equipment. Equipment in the Conex box is piled one on top of another. The potential for cross-contamination is very high because of the storage configuration. Equipment such as lighting that would never

come into contact with tank waste within normal use has thus been potentially exposed to tank waste.

The C-Farm Conex box is located Northeast of C-Tank Farm. A large quantity of equipment is stored on the ground around the Conex box. Most of the equipment that cannot be used again can be recycled, especially the stainless steel and other metals. This equipment may exhibit low levels of radiological contamination. It is unlikely that this equipment has been in contact with tank waste. An unmarked barrel was found along with several piles of lumber.

The B-Farm Conex box contains eight contaminated valve handles, some of which are wrapped in plastic. Some do not have any plastic shielding or other protection and are stored on top of otherwise uncontaminated equipment. This method of storage has the potential to contaminate equipment that is otherwise clean.

One storage building in B-Tank Farm houses several flexible jumpers and other contaminated equipment. Lead shielding covering the equipment made it difficult to inventory this area.

7.2 200 WEST AREA

7.2.1 WEST AREA TANK FARMS

The S-Complex contains a variety of potentially contaminated equipment including exhausters, valve handles, shield plugs and contaminated jumpers. The S-Complex has one central storage area near the east fence line in S-Tank Farm which contains a large volume of contaminated equipment. The other West area Tank Farms contain small quantities of contaminated equipment.

7.2.2 WEST AREA CONEX BOXES

Four Conex boxes located in the S-Complex contain a variety of contaminated equipment. Most of the contaminated equipment, such as valve handles are properly stored and intended for reuse. The one 40-ft Conex box in the S-complex near the West fence area contains two spider jumpers highly contaminated with tank waste. These were removed from SX-A and SX-B valve pits.

7.2.3 WEST AREA EVAPORATOR BUILDINGS

The two West Area evaporators (242-S and 242-T) will be inventoried as part of the inaccessible equipment inventory, which is phase II of the inventory. These evaporators are no longer in service. The 242-T facility poses a difficult access problem due to high contamination.

There are no plans to restart either the 242-S or 242-T evaporator. Any equipment left in the facility that has contacted tank waste will be considered contaminated equipment. The S Evaporator has several "hot cells." Only one storage area in the facility contains contaminated equipment. The storage area contains rigid jumpers that have all been in contact with tank waste. Some of the jumpers contain lead counterweights.

Photographs obtained from outside the "hot cells" were not of sufficient quality to reveal the drawing numbers of the jumpers. An entrance into this area will be done as part of the inaccessible equipment inventory.

7.3 MISCELLANEOUS AREAS

Tank Farms manages several areas outside of the official boundaries of the Tank Farms. There are five major areas outside of Tank Farms that were inventoried for the presence of contaminated equipment that may no longer be reusable. These areas include the 204-AR Railcar Unloading Facility, the 2727-WA Sodium Storage Building, the West area coverblock storage area, the S-Complex Boneyard, and the West area railcar area.

The 204-AR Unloading Facility and the 2727-WA "Sodium Storage Building" do not contain any contaminated equipment that is included in this report. The West Area railcar area contains three railcars that contain various types of equipment, most of which is uncontaminated and reusable. Some of the equipment is slightly contaminated but may be reusable.

The West Area coverblock storage area contains a wide assortment of potentially contaminated equipment. This area contains equipment originating from Tank Farms and from other plants on the Hanford Site, such as U-Plant. A number of these coverblocks may have been exposed to tank waste and

longer be usable. Many of these cover blocks do not belong to Tank Farms. Items include two large wooden burial boxes with unknown contents, two empty barrels with no labeling, assorted shield plugs, one riser plug, unknown piping, and a large pile of wood.

The S-Complex "Boneyard" contains items of note that are contaminated such as air lances and other equipment.

8.0 RECOMMENDATIONS

The aboveground portion of the contaminated equipment inventory is complete. The next phase to be completed is the inventory of contaminated equipment stored within Tank Farm ancillary units including diversion boxes, valve pits, process pits, etc. Once both inventories are complete, the inventoried equipment will require categorization as reusable or not reusable. TWRS Plant will develop a plan for categorization and characterization of the equipment. Following the characterization of the equipment and possible designation as dangerous waste, plans will be developed for disposal or proper storage of the equipment. Removal of equipment will be prioritized and plans to recycle, dispose or decontaminate the equipment prepared. It is recommended that TWRS Plant develop a multi functional team dedicated to characterization, remediation, decontamination, and /or disposal of used contaminated equipment in Tank Farm facilities.

9.0 REFERENCES

1. Dangerous Waste Regulations, Chapter 173-303-070
"Designation of Dangerous Waste," amended 1993.
2. Dangerous Waste Regulations," Chapter 173-303-660
"Waste Piles," amended 1993.
3. The RCRA Hazardous Wastes Handbook, Chapter 6.5 "Waste
Piles," 10th Edition, 1993.
4. Dangerous Waste Regulations, Chapter 173-303-200
"Accumulating Dangerous Waste On-Site," amended 1993.
5. WHC-SD-WM-WP-270, REV. 0. "Engineering Work Plan For
The Inventory Of Stored Or Abandoned Equipment In Tank
Farms," April 15, 1994.

10.0 APPENDICES

APPENDIX A
TANK FARM AREAS INVENTORIED
(ACCESSIBLE INVENTORY)

1. West Area

WHC-SD-WM-EV-098, REV. 0

A. Tank Farms

1. 241-S Tank Farm
2. 241-SX Tank Farm
3. 241-SY Tank Farm
4. 241-T Tank Farm
5. 241-TX Tank Farm
6. 241-TY Tank Farm
7. 241-U Tank Farm

B. Conex Boxes

1. 241-S Farm Conex Boxes
2. 241-SX Farm Conex Boxes
3. 241-SY Farm Conex Boxes
4. 241-TX Farm Conex Box

C. Evaporators

1. 242-S
2. 242-TX

2. East Area

A. Tank Farms

1. 241-A Tank Farm
2. 214-AN Tank Farm
3. 241-AP Tank Farm
4. 241-AW Tank Farm
5. 241-AX Tank Farm
6. 241-AY Tank Farm
7. 241-AZ Tank Farm
8. 241-B Tank Farm
9. 241-BX Tank Farm
10. 241-BY Tank Farm
11. 241-C Tank Farm

B. Conex Boxes

1. 241-AW Conex Box
2. 241-B Conex Box
3. 241-C Conex Box

3. Misc. Areas

A. Tank Farm Facilities

1. 204-AR Unloading Facility
2. 2727-WA Sodium Storage

B. Other Areas Containing Tank Farm Equipment

1. Coverblock Storage Area
2. S-Complex Boneyard
3. West Area Railcar Area

APPENDIX B
IDENTIFICATION OF DATABASE FIELDS

Identification of Database Fields

1. Area: Indicate 200 East and 200 West
2. Tank Farm: Specific Tank Farm
3. General Area: General location of equipment
4. Drawing: Engineering documentation, if applicable
5. Position: Identify location (i.e. on ground, etc.)
6. Building: Equipment located in or near a structure
7. General Condition: Visual description
8. Physical Description: Specific name of equipment
9. Equipment Age: Approximate age of equipment
10. Radiation Contamination: Contamination (process knowledge)
11. Labeling: Marking or identification
12. Reusable: Reusability of equipment
13. In Place: Equipment intended usage
14. Last Used: Last time the equipment performed the intended function
15. Future Use: Equipment that could be used again
16. Use: Specific function of equipment
17. History: Any additional information about equipment
18. Active: Still in use
19. Fluids: Any known liquid that has contacted equipment
20. Parts: Part number identified on equipment
21. Flushed: Has been rinsed/flushed

APPENDIX C
TANK FARM EQUIPMENT DATABASE AND PHOTOGRAPHS

Area: East
Tank_farm: 241-A
Gen_area: E OF 702 VENT BLDG
Drawing: H-2-64771
Position: IN PLACE ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: RADIATION ELEMENT (PIG AND SAMPLE ASSEMBLY)
Equip_age: 30 YEARS
Rad_contam: UNKNOWN
Labeling: RE-1
Reusable: NO
In_place: YES
Last_used: 1985
Future_use: NO
Use: MONITORING RADIATION LEVELS
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-A
Gen_area: E OF 702 VENT BLDG
Drawing: H-2-64770, H-2-64771
Position: IN PLACE ON GROUND
Building: N/A
Gen_cond: AGING
Phys_desc: PIPING ATTACHED TO ION. COLUMN
Equip_age: 30 YEARS
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: YES
Last_used: 1985
Future_use: NO
Use: MONITOR CONDENSATE FILTRATION PROCESS
History:
Active: NO
Fluids: CONDENSATE, WATER
Parts: N/A
Flushed: NO

Area: East
 Tank_farm: 241-A
 Gen_area: E OF 702-A BUILDING
 Drawing: H-2-64771
 Position: IN PLACE ON GROUND
 Building: N/A
 Gen_cond: RUSTED/CORRODED
 Phys_desc: CONDENSATE FILTER ASSEMBLY
 Equip_age: 30 YEARS
 Rad_contam: UNKNOWN
 Labeling: NONE
 Reusable: NO
 In_place: YES
 Last_used: 1985
 Future_use: NO
 Use: CONDENSATE FILTRATION
 History:
 Active: NO
 Fluids: CONDENSATE, WATER
 Parts: N/A
 Flushed: UNKNOWN/COULD BE FLUSHED

Area: East
 Tank_farm: 241-A
 Gen_area: EAST AREA FENCE LINE
 Drawing: N/A
 Position: ON GROUND
 Building: N/A
 Gen_cond: IN TACT
 Phys_desc: P.E. TRACK TO SUPPORT PE
 Equip_age: UNKNOWN
 Rad_contam: UNKNOWN
 Labeling: NONE
 Reusable: NO
 In_place: YES
 Last_used: CURRENT
 Future_use: NO
 Use: SUPPORT PE
 History:
 Active: NO
 Fluids: N/A
 Parts: N/A
 Flushed: NO

Area: East
Tank_farm: 241-A
Gen_area: EAST AREA FENCE LINE
Drawing: N/A
Position: ON PIT/GROUND
Building: N/A
Gen_cond: USED/WATERLOGGED
Phys_desc: LARGE PLYWOOD PILE
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN/PIT COVERS
History:
Active: NO
Fluids: UNKNOWN/POTENTIAL CONT FROM PE
Parts: N/A
Flushed: NO

C-6

WHC-SD-WM-EV-098, REV.0

Area: East
Tank_farm: 241-A
Gen_area: EAST FENCE AREA
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: OLD BOXES
Phys_desc: (3) EQUIPMENT BOXES
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: YES
In_place: YES
Last_used: UNKNOWN
Future_use: NO
Use: STORE TF EQUIPMENT
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

C-8

Area: East
Tank_farm: 241-A
Gen_area: EAST OF 702 WEST BUILDING
Drawing: H-2-64770, H-2-64771
Position: IN PLACE
Building: N/A
Gen_cond: DEGRADED
Phys_desc: ION EXCHANGE COLUMN
Equip_age: 30 YEARS
Rad_contam: POSSIBLE
Labeling: NONE
Reusable: NO
In_place: YES
Last_used: 1984-1985
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: WATER
Parts: N/A
Flushed: NO

C-10

Area: East
Tank_farm: 241-A
Gen_area: NEAR EAST AREA FENCE
Drawing: N/A
Position: ON PIT
Building: UNKNOWN PIT
Gen_cond: DETERIORATED
Phys_desc: (2) BARRELS/OVERPACK COVERS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NON-TRU
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: YES
Use: EQUIPMENT STORAGE
History:
Active: YES
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

C-12

Area: East
 Tank_farm: 241-A
 Gen_area: NEAR EAST FENCE LINE
 Drawing: H-2-75150
 Position: ON EXHAUSTER TRAILER
 Building: N/A
 Gen_cond: COMPLETELY CORRODED
 Phys_desc: PORTABLE EXHAUSTER
 Equip_age: UNKNOWN
 Rad_contam: YES-RADIATION STICKER
 Labeling: YES
 Reusable: NO
 In_place: NO
 Last_used: UNKNOWN
 Future_use: NO
 Use: TANK VENTILATION
 History:
 Active: NO
 Fluids: LIKELY MIXED WASTE INSIDE
 Parts: N/A
 Flushed: NO

Area: East
 Tank_farm: 241-A
 Gen_area: NEAR EAST FENCE LINE
 Drawing: N/A
 Position: ON GROUND
 Building: N/A
 Gen_cond: OLD WOOD
 Phys_desc: WOOD PILE
 Equip_age: UNKNOWN
 Rad_contam: UNKNOWN
 Labeling: NONE
 Reusable: NO
 In_place: NO
 Last_used: UNKNOWN
 Future_use: NO
 Use: PROBABLY USED WITH PORTABLE EXHAUSTER
 History:
 Active: NO
 Fluids: POT. RAD/CREOSOTE FROM WOOD
 Parts: N/A
 Flushed: NO

Area: East
 Tank_farm: 241-A
 Gen_area: NEAR EAST FENCE LINE
 Drawing: N/A
 Position: ON GROUND SUPPORTING P.E.
 Building: N/A
 Gen_cond: OLD/RUSTED
 Phys_desc: PORTABLE EXHAUSTER TRUCK
 Equip_age: UNKNOWN
 Rad_contam: LIKELY
 Labeling: NONE
 Reusable: NO
 In_place: NO
 Last_used: UNKNOWN
 Future_use: NO
 Use: MOVE P.E. BETWEEN TANKS
 History:
 Active: NO
 Fluids: POTENTIAL RAD CONTAMINATION
 Parts: N/A
 Flushed: NO

Area: East
 Tank_farm: 241-A
 Gen_area: NEAR EAST FENCE LINE
 Drawing: N/A
 Position: ON P.E. TRACK
 Building: N/A
 Gen_cond: COMPLETELY RUSTED
 Phys_desc: PORTABLE EXHAUSTER
 Equip_age: OLD
 Rad_contam: YES-RADIATION STICKER
 Labeling: NONE
 Reusable: NO
 In_place: NO
 Last_used: UNKNOWN
 Future_use: NO
 Use: TANK EXHAUST
 History:
 Active: NO
 Fluids: LIKELY MIXED WASTE IN LINE
 Parts: N/A
 Flushed: NO

Area: East
Tank_farm: 241-A
Gen_area: ABOVE 241-A-105
Drawing: H-2-74857
Position: ON P.E. TRUCK
Building: N/A
Gen_cond: COMPLETELY RUSTED
Phys_desc: PORTALBE EXHAUSTER
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: 1991
Future_use: NO
Use: TANK VENTILATION
History:
Active: NO
Fluids: LIKELY MIXED WASTE IN EXHAUSTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-A
Gen_area: NEAR EAST FENCE LINE
Drawing: N/A
Position: PIPING ON GROUND
Building: N/A
Gen_cond: COMPLETELY RUSTED
Phys_desc: 1" PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN/PLASTIC INDICATES RAD
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

C-19

Area: East
Tank_farm: 241-AN
Gen_area: NEAR 241-AN CHANGEOUT ROOM
Drawing: N/A
Position: ON GROUND
Building: CHANGEROOM
Gen_cond: EMPTY/UNKNOWN
Phys_desc: 55-GAL BARREL/ITEM IN PLASTIC
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: N/A
History:
Active: NO
Fluids: UNKNOWN LIQUID PCS. IN BARREL
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AN
Gen_area: NEAR 241-AN CHANGECUT ROOM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: "BAD PIG"
Phys_desc: SAMPLE PIG
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: TE-4 "BAD PIG"
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: USED TO COLLECT AND STORE TANK SAMPLES
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: UNKNOWN
Phys_desc: MISC. EQUIPMENT
Equip_age: UNKNOWN
Rad_contam: ITEMS IN PLASTIC ARE CONT.
Labeling: NONE
Reusable: UNKNOWN
In_place: N/A
Last_used: UNKNOWN
Future_use: UNKNOWN
Use: VARIOUS
History:
Active: NO
Fluids: ?
Parts: N/A
Flushed: NO

LISTING OF MISC. ITEMS IN AW CONEX BOX

1. 3 ITEMS IN PLASTIC BAGS
2. MISC. PIPING
3. CARD BOARD BOXES
4. MISC. HOSES
5. METAL BUCKET
6. WOODEN PALLET
7. STANDIONS
8. PLASTIC
9. UNKNOWN ITEMS UNDER THE JUMPERS
10. PLASTIC BUCKET
11. PLASTIC BOTTLES
12. MISC. WOOD ITEMS
13. RAD ROPE (4+ BUNDLES)

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BOX
Drawing: NONE
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: GOOD CONDITION
Phys_desc: 3 METAL VENT PIT LADDERS
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: YES
Use: USED IN VENT PITS
History:
Active: NO
Fluids: NONE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BOX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: POTENTIALLY REUSABLE
Phys_desc: 12" SHIELD PLUG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: YES
Use: RISER COVER/REDUCE SHINE
History:
Active: NO
Fluids: NONE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BCX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: GOOD CONDITION
Phys_desc: 3 WOODEN LADDERS
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: UNKNOWN
Use: USED IN TANK FARMS
History:
Active: NO
Fluids: NONE
Parts: NONE
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BOX
Drawing: N/A
Position: IN AW CONEX BOX
Building: CONEX BOX
Gen_cond: DETERIORATED
Phys_desc: 3 RED HOSES RUBBER/PLASTIC
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TRANSPORT WATER IN TANK FARMS
History:
Active: NO
Fluids: NONE KNOWN
Parts: NONE
Flushed:

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-70434
Position: ON CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 3 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN JUMPER
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-76942
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 3 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN JUMPER
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-76942
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 2 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-76944
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 2 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE CONTAM.
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-76945
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 2 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-76946
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 3 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-76948
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 3 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-77112
Position: ON AW CONEX BOX FLOOR
Building: CONEX BOX
Gen_cond: USED
Phys_desc: 2 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-77114
Position: ON AW CONEX BOX FLOOR
Building: COB
Gen_cond: USED
Phys_desc: 3 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: H-2-90830
Position: ON AW CONEX BOX FLOOR
Building: COB
Gen_cond: USED
Phys_desc: 2 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL INTERNAL CONTAMINATION
Parts: N/A
Flushed: YES

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: ?
Position: IN PLASTIC ON CCB FLOOR
Building: COB
Gen_cond: USED
Phys_desc: 2 HEAD RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BCX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: UNKNOWN
Phys_desc: 2 VALVE HANDLES
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: UNKNOWN
Use: USED IN PITS
History:
Active: NO
Fluids: NONE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BOX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: UNKNOWN
Phys_desc: 4 STANDIONS
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use:
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: AW CONEX BOX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: UNKNOWN
Phys_desc: PIKE POLES
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: USED TO BUILD GREENHOUSES
History:
Active: NO
Fluids: NONE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: N/A
Position: ON CLEANOUT BOX FLOOR
Building: COB
Gen_cond: RUSTED
Phys_desc: 12" RISER FLANGE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: RISER COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: N/A
Position: ON CLEANOUT BOX FLOOR
Building: COB
Gen_cond: SOME IS CRACKED/OLD
Phys_desc: 2 SHEETS OF PLYWOOD
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN USE IN PITS
History:
Active: NO
Fluids: NONE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: N/A
Position: ON CLEANOUT BOX FLOOR
Building: COB
Gen_cond: WORN OUT
Phys_desc: WOODEN STRAIGHT LADDER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: LADDER FOR PITS
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: IN AW CONEX BOX
Drawing: N/A
Position: IN CONEX BOX
Building: CONEX BOX
Gen_cond: UNKNOWN
Phys_desc: 1 ELECTRIC CORD LANTERN
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: YES
Use: LIGHTING
History:
Active: NO
Fluids: ?
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AW
Gen_area: NEAR AW CHANGE ROOM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: USABLE/NOT NEEDED
Phys_desc: MANOMETER
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: MEASURE FLOW RATES
History:
Active: NO
Fluids: MERCURY
Parts: N/A
Flushed: NO

C-61

Area: East
Tank_farm: 241-AX
Gen_area: SE VALVE HANDLE STORAGE AREA
Drawing: N/A
Position: IN BUILDING
Building: VALVE HANDLE STORAGE AREA
Gen_cond: USED
Phys_desc: VALVE HANDLES (7+), NON-TRU BARREL, MISC.
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: SOME MAY BE REUSABLE
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: TURN VALVES IN PITS
History:
Active: NO
Fluids: POTENTIAL CONTACT WITH MIXED WASTE
Parts: N/A
Flushed: NO

WHC-SD-WM-EV-098, REV. 0

Area: East
Tank_farm: 241-AX
Gen_area: 241-AX-A/B VALVE PIT
Drawing: H-2-73754
Position: ON GROUND
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: VAVLE HANDLE IN BAG
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: USED TO TURN VALVES IN PITS
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-66

Area: East
Tank_farm: C41-AX
Gen_area: AT 104-AX FIC
Drawing: N/A
Position: ON SURFACE
Building: N/A
Gen_cond: NOT USED
Phys_desc: FIC
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: YES
Last_used: UNKNOWN
Future_use: NO
Use: LIQUID LEVEL MEASURE 104-AX
History:
Active: NO
Fluids: TANK WASTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AX
Gen_area: AX-A/AX-B
Drawing: N/A
Position: ON GROUND IN BAG
Building: N/A
Gen_cond: USED
Phys_desc: 4" RISER/4" FLANGE FLUSH PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-70

Area: East
Tank_farm: 241-AX
Gen_area: NEAR 241-AX-A/B VP
Drawing: N/A
Position: ON GORUND
Building: N/A
Gen_cond: USED
Phys_desc: MISC. PIPING (2) SECTIONS
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AX
Gen_area: NEAR AX-A/B VALVE PIT
Drawing: N/A
Position: ON GROUND ON PLASTIC BAG
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: BLACK HOSE
Equip_age: UNKNOWN
Rad_contam: N/A
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-74

Area: East
Tank_farm: 241-AX
Gen_area: NEAR CENTER OF TF
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: USED
Phys_desc: PLUG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: SHIELD COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
 Tank_farm: 241-AY
 Gen_area: E OF CHANGE TRAILER
 Drawing: N/A
 Position: ON GROUND
 Building: N/A
 Gen_cond: BARREL TOP IS RUSTED
 Phys_desc: 55 GALLON BARREL OF 5W-30 OIL
 Equip_age: UNKNOWN
 Rad_contam: UNLIKELY
 Labeling: MOBIL 1 FORMULA
 Reusable: NO
 In_place: YES
 Last_used: UNKNOWN
 Future_use: YES
 Use: USED FOR GENERATORS
 History:
 Active: NO
 Fluids: 5W-30 OIL
 Parts: N/A
 Flushed: NO

Area: East
Tank_farm: 241-AY
Gen_area: N EXHAUSTER HEPA FIL.
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: DELAPITATED/RUSTED
Phys_desc: 3 VALVE HANDLES/MISC. PIPING
Equip_age: UNKNOWN
Rad_contam: YES ON VH
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PIPING (UNKNOWN) /WASTE ROUTING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

08-C

Area: East
Tank_farm: 241-AY
Gen_area: NEAR CHANGE ROOM
Drawing: N/A
Position: AGAINST CHANGE ROOM/GROUND
Building: AY CHANGER
Gen_cond: USED/RUSTED
Phys_desc: CONTAMINATED POLE
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AZ
Gen_area: NCR CF AZ-101 CPP
Drawing: N/A
Position: ON GROUND UNDER RUBBER
Building: 241-AZ-271
Gen_cond: UNKNOWN
Phys_desc: RISER/SHIELD PLUG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: SHIELD FOR RISER PLUG HOLE
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-AZ
Gen_area: NEAR EAST FENCE AREA
Drawing: N/A
Position: ON GROUND
Building: 241-AZ-101 CENTRAL PUMP PIT
Gen_cond: DETERIORATED
Phys_desc: RISER PLUG IN TAPE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PLUG RISER HOLE
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-86

C-86

Area: East
Tank_farm: 241-BX
Gen_area: E. OF 111 BREATHER F
Drawing: N/A
Position: ON GROUND IN PLASTIC BAG
Building: 111 BR FIL
Gen_cond: USED
Phys_desc: 2 VALVE HANDLES/?/WOOD IN BAG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: POSITION VALVES
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-88

Area: East
Tank_farm: 241-BX
Gen_area: NEAR ?? FENCE LINE
Drawing: N/A
Position: ON CEMENT PAD
Building: H3PO4 TANK
Gen_cond: GOOD
Phys_desc: 14' H3PO4 TANK
Equip_age: UNKNOWN
Rad_contam: UNLIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: H3PO4 STORAGE FOR SALTWELL
History:
Active: NO
Fluids: LIKELY TO HAVE H3PO4 RESIDUE
Parts: N/A
Flushed: NO

C-90

Area: East
Tank_farm: 241-BX
Gen_area: NEAR BX CHANGE ROOM
Drawing: N/A
Position: ON GROUND (IN BAG)
Building: BX CHANGE
Gen_cond: USED
Phys_desc: GARBAGE LID / UNKNOWN IN BAG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: GARBAGE LID/???
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: WEST OF 244-BX DCRT
Drawing: N/A
Position: ON EDGE OF PIT
Building: 244-BX
Gen_cond: UNKNOWN
Phys_desc: SMALL ITEM 3' WRAPPED IN BAG
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON 4X8" BLOCKS
Building: N/A
Gen_cond: RUSTED
Phys_desc: DIESEL GENERATOR
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: GENERATOR
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: GENERATOR
History:
Active: NO
Fluids: POTENTIAL FLUIDS IN GENERATOR
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: IN PLASTIC BAG ON GROUND
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: EXHAUSTER FILTER IN BAG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: RAD STICKER
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: FILTRATION
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN FILTER
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: * NEAR WEST FENCE
Drawing: N/A
Position: ON CEMENT FOUNDATION
Building: N/A
Gen_cond: GOOD CONDITION
Phys_desc: 3 VALVE HANDLES
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: ?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON CEMENT BLOCK
Building: N/A
Gen_cond: USED
Phys_desc: (9) METAL COVERS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: ?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-101

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON WOOD BLOCK
Building: N/A
Gen_cond: RUSTED/USED
Phys_desc: RIGID JUMPER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: DRAWING
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: WASTE TRANSFERS
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: ?

C-103

WHC-SD-MM-EV-098, REV. 0

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON WOODEN PALLET
Building: N/A
Gen_cond: RUSTED OUT
Phys_desc: (2) ELECTRIC MOTORS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: LABEL ON MOTOR
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: POTENTIAL OILS IN MOTOR
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED OUT
Phys_desc: LARGE SALTWELL ITEM
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: ?
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: (2) METAL POLES
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: ?
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WRAPPED IN PLASTIC
Phys_desc: METAL PART OF EXHAUSTER?
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: ?
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON GROUND IN PLASTIC
Building: N/A
Gen_cond: USED
Phys_desc: EXHAUSTER/EXHAUSTER PART/DIESEL GENERATOR
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TANK EXHAUSTER/TANK EXHAUSTER POWER SUPPLY
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON CEMENT FOUNDATION
Building: N/A
Gen_cond: CORRODED/USED
Phys_desc: ? SAMPLE PIG HOLDER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: SAMPLING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: ?

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: LONG EQUIPMENT/SALTWELL ITEM
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-116

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: IN STORAGE BUILDING
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: LARGE ITEM UNDER PB SHIELDING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON CEMENT FOUNDATION
Building: N/A
Gen_cond: USED
Phys_desc: EXHAUSTER FILTER
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PART OF EXHAUSTER/EXHAUST FILTRATION
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: SW CORNER OF FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: LARGE METAL SUPPORTS (EXHAUSTER)
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: SUPPORT
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: SW CORNER OF FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: UNKNOWN ITEM
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-124

Area: East
Tank_farm: 241-BX
Gen_area: SW CORNER OF TANK FARM ON PIT
Drawing: N/A
Position: ON EDGE OF PIT
Building: N/A
Gen_cond: DETERIORATED
Phys_desc: LARGE ITEM IN CANVAS
Equip_age: UNKNOWN
Rad_contam: ?
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BX
Gen_area: BX/BY CONEX BOX
Drawing: N/A
Position: IN CONEX BOX
Building: N/A
Gen_cond: USED
Phys_desc: (3) FECN BARRELS/VALVE HANDLES
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: FECN SAMPLING FLANGE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: EQUIPMENT STORAGE
History:
Active: NO
Fluids: ? IN BARRELS
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BY
Gen_area: NEAR 102-BY CPP
Drawing: N/A
Position: ON GROUND IN BAG
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: LOOKS LIKE WOOD IN BAG
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN ITEM IN BAG
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BY
Gen_area: NEAR EAST FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: LOOKS NEW
Phys_desc: WRENCH
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: LABEL CRAFTSMAN
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WRENCH
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BY
Gen_area: NEAR EAST FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WORN
Phys_desc: GREENHOUSE COUPLINGS
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: USED TO BUILD GREENHOUSES
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BY
Gen_area: NEAR N FENCE LINE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: OLD
Phys_desc: INTAKE EXHAUSTER
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use:
Use: INTAKE EXHAUSTER
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BY
Gen_area: NEAR TANK 102-BY WEST SIDE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WORN
Phys_desc: (4) PB SHIELDING PLATES 2X3'
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: YES
In_place: YES
Last_used: ? IN USE?
Future_use: NO
Use: PB SHIELDING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-137

Area: East
Tank_farm: 241-BY
Gen_area: ON 106-BY CPP
Drawing: N/A
Position: ON PIT
Building: 106-BY CPP
Gen_cond: UNKNOWN BAG/BENT
Phys_desc: ?WOOD IN BAG/.5X2' PB SHIELDING
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN/PB FOR SHIELDING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-139

Area: East
Tank_farm: 241-BY
Gen_area: ON 109-BY CPP
Drawing: N/A
Position: ON PIT
Building: 109-BY CPP
Gen_cond: RUSTED/WORN
Phys_desc: STEEL PLATE/.5*2' PB SHIELDING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN/SHIELDING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-BY
Gen_area: ON TANK 101-BY S CPP
Drawing: N/A
Position: ON PLYWOOD ON GROUND
Building: N/A
Gen_cond: REMOVED
Phys_desc: SERVICE OR STEAM PIT REMOVED
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: SERVICE OR STEAM PIT
History:
Active: NO
Fluids: UNKNOWN POTENTIAL CONTAMINATIO
Parts: N/A
Flushed: NO

C-143

Area: East
Tank_farm: 241-BY
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: IN STORAGE BUILDING
Building: RAD STORAG
Gen_cond: USED
Phys_desc: FLEXIBLE JUMPER IN PLASTIC
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: ?

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: 2 SALTWELL PIT COVERS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: "SAVE"
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: AGING WASTE SAMPLER PLATFORM
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: SAMPLE BARREL WITH LID/SUPPORT
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: UNKNOWN FLUID IN LINE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: SALTWELL PUMP PIT COVERS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: 241-AZ-01A
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: PIT COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: LIMIT ACCESS COVER
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: LLW-A
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: LIMITED ACCESS PORT COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WORN
Phys_desc: SALTWELL PUMP PIT COVER
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: 241-A-1A
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: PUMP PIT COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON PUMP PIT COVER
Building: N/A
Gen_cond: WEATHERED
Phys_desc: TWO RED HOSES
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: HOSES
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON PUMP PIT COVER
Building: N/A
Gen_cond: WEATHERED
Phys_desc: (4) 24" TWINSEAL PIPING 80 PSI
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: 24" IIPE 80PSI
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: POSSIBLE RISER COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WEATHERED
Phys_desc: SALTWELL PUMP PIT COVER
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: SALTWELL P. PIT
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WEATHERED
Phys_desc: (2) BARREL COVERS/PIPE REDUCER
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: 24" TO 12" CONVERTER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WEATHERED
Phys_desc: (4) 1" PIPES 20 FT IN LENGTH
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: RAD STRIPES
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED AND BENT
Phys_desc: FENCE POSTS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: FENCING
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: H-2-90833
Position: ON GROUND
Building: N/A
Gen_cond: USED
Phys_desc: PIPING/DUMMY PUMP HEAD/PB CWT
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: DRAWING #
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: PIPING
History:
Active: NO
Fluids: UNKNOWN FLUID IN LINE
Parts: N/A
Flushed: ?

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: USED AND RUSTED
Phys_desc: TURBINE PUMP
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: 118P 10
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PUMP WASTE FROM PIT
History:
Active: NO
Fluids: UNKNOWN FLUID IN LINE
Parts: N/A
Flushed: ?

Area: East
Tank_farm: 241-C CONEX BOX AREA
Gen_area: EAST SIDE OF C-FARM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: USED AND RUSTED
Phys_desc: MISC. PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: UNKNOWN FLUID IN LINE
Parts: N/A
Flushed: ?

Area: East
Tank_farm: 241-C
Gen_area: S RIDGE OF C TF
Drawing: N/A
Position: ON GROUND IN BAG
Building: N/A
Gen_cond: RUSTED
Phys_desc: WATER LANCE
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TANK LANCING
History:
Active: NO
Fluids: POTENTIAL TANK WASTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: NEAR CHANGE OUT ROOM
Drawing: N/A
Position: AGAINST CHANGE ROOM STEPS
Building: CHANGEROOM
Gen_cond: UNKNOWN
Phys_desc: PIPE IN BAG
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: POTENTIAL TANK WASTE IN PIPE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: N OF 244-C CONTRLBLD
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: DETERIORATED
Phys_desc: VALVE HANDLE IN HOLDER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable:
In_place: NO
Last_used: UNKNOWN
Future_use:
Use: USED IN WASTE ROUTING IN PITS
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: N OF 244-CR CTRLROOM
Drawing: N/A
Position: ON GROUND IN PLASTIC BAG
Building: N/A
Gen_cond: LOOKS NEW
Phys_desc: 1" PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: UNKNOWN FLUID IN LINE
Parts: N/A
Flushed: NO

C-175

Area: East
Tank_farm: 241-C
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON 296-P-29 EXHAUST. CART
Building: N/A
Gen_cond: USED
Phys_desc: 296-P-27 EXHAUSTER
Equip_age: UNKNOWN
Rad_contam: YES REGULA
Labeling: YES
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TANK VENTILATION
History:
Active: NO
Fluids: TANK WASTE IN FILTER
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: NEAR WEST FENCE
Drawing: N/A
Position: ON TWO RAILS IN TANK FARM
Building: N/A
Gen_cond: INOPERABLE
Phys_desc: GANTRY CRAIN
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: YES
Last_used: UNKNOWN
Future_use: NO
Use: MOVE JUMPERS/COVER BLOCK?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: NORTH OF 109-C
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: COMPLETELY WORN
Phys_desc: 1.5*2' PB SHIELDING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: SHIELDING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: S END OF CR VAULT PI
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: (4) VALVES AND JUMPER ASSEMBLIES
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: JETTING OPERATION
History:
Active: NO
Fluids: POTENTIAL TANK WASTE IN LINES
Parts: N/A
Flushed:

C-183

Area: East
Tank_farm: 241-C
Gen_area: S OF 106-C EXHAUSTER
Drawing: N/A
Position: ON GROUND IN PLASTIC BAG
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: UNKNOWN
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: S END OF CR-VAULT PI
Drawing: N/A
Position: ON GROUND
Building: CR-VAULT
Gen_cond: RUSTED
Phys_desc: PUMP
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PUMP FOR ?
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: SW CORNER CR-V BLDG
Drawing: N/A
Position: ON GROUND
Building: 244-CR BLG
Gen_cond: WORN OUT
Phys_desc: WOOD/BARREL/MISC. PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-189

Area: East
Tank_farm: 241-C
Gen_area: SW OF 104 CPP
Drawing: N/A
Position: ON GROUND AGAINST PIT
Building: 104 CPP
Gen_cond: WRAPPED IN PLASTIC
Phys_desc: RISER FLANGE
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: RISER COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: W OF CR-VAULT BLDG
Drawing: N/A
Position: ON GROUND
Building: CR-VAULT
Gen_cond: RUSTED
Phys_desc: PUMP STATION
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: OPERATE/CONTROL PUMPING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: W SIDE CR-VAULT BLDG
Drawing: N/A
Position: ON GROUND/LAYING ON BLDG
Building: CR-VAULT B
Gen_cond: RUSTED
Phys_desc: ?
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: ?
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: W. OF CR-VAULT BLDG
Drawing: N/A
Position: LAYING AGAINST BUILDING
Building: CR-VAULT B
Gen_cond: DETERIORATED
Phys_desc: WATER PIPE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: FLUSHING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: NEAR CHANGE ROOM
Drawing: N/A
Position: IN PLASTIC RAD BAG
Building: N/A
Gen_cond: USED IN GOOD SHAPE
Phys_desc: PB SHIELDING IN CANVAS ENCLOSURE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: UNKNOWN
Future_use:
Use: PB SHIELDING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: NEAR CHANGE ROOM
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: MISC. EQUIPMENT PILE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable:
In_place: NO
Last_used: UNKNOWN
Future_use:
Use: VARIOUS
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: WEST FENCE/S OF CRAI
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: USED
Phys_desc: 10'x15' SHEET OF TIN
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: East
Tank_farm: 241-C
Gen_area: CR VAULT BUILDING
Drawing: N/A
Position: ON GROUND IN PLASTIC TUBE
Building: N/A
Gen_cond: DETERIORATED
Phys_desc: METAL PIPING?
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: ?????
Drawing: N/A
Position: ON GROUND/STACKED
Building: UNKNOWN
Gen_cond: USED
Phys_desc: MISC./COVER BLKS/PIPNG/TIN/ETC
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PIT COVER/UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: EAST AREA FENCE/CON
Drawing: N/A
Position: ON TARP ON GROUND
Building: N/A
Gen_cond: DETERIORATED
Phys_desc: EXHAUSTER
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: REDUCE TANK PRESSURE
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: EAST PART OF T.F.
Drawing: N/A
Position: AGAINST BUILDING
Building: ?
Gen_cond: ALL USED/WORN OUT
Phys_desc: VAL.HANDLE/4X8WOOD/PAINT TROFF
Equip_age: UNKNOWN
Rad_contam: VALVE HAND
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: POSSIBLE PAINT USE
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: EAST S FENCE LINE
Drawing: N/A
Position: ON PALLET
Building: N/A
Gen_cond: USED/RUSTED BARRELS
Phys_desc: 3 BARRELS/2 EMPTY
Equip_age: UNKNOWN
Rad_contam: ?
Labeling: NON-???
Reusable:
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: STORAGE BARRELS ???
History:
Active: NO
Fluids: ??/RESIDUE
Parts: N/A
Flushed: NO

C-215

Area: West
Tank_farm: 241-S
Gen_area: N OF 241-A VALVE PIT
Drawing: N/A
Position: ON GROUND IN BAG
Building: N/A
Gen_cond: RUSTED
Phys_desc: 5 FOOT PIPE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: N OF 241-S-C/D V.F.
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WRAPPED IN PLASTIC
Phys_desc: HEAT TRACE CABINET
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: YES
Last_used: UNKNOWN
Future_use: NO
Use: HEAT TRACE FOR PIPING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: N. OF TANK S-104 CPP
Drawing: N/A
Position: ON GROUND IN PLASTIC
Building: N/A
Gen_cond: USED
Phys_desc: 5 VALVE HANDLES IN BAG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: USED IN PITS TO TURN VALVES
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-221

Area: West
Tank_farm: 241-S
Gen_area: NEAR EAST FENCE AREA
Drawing: N/A
Position: ON EXHAUSTER CART
Building: N/A
Gen_cond: VERY OLD/RUSTED
Phys_desc: OLD EXHAUSTER ON CART
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TANK VENTILATION
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

C-223

Area: West
Tank_farm: 241-S
Gen_area: NEAR EAST FENCE/COB
Drawing: N/A
Position: ON EXHAUSTER TRAILER
Building: N/A
Gen_cond: COMPLETELY RUSTED
Phys_desc: (2) EXHAUSTERS
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TANK VENTILATION/NEG. PRESSURE
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-225

Area: West
Tank_farm: 241-S
Gen_area: NEAR ORANGE CONEXBOX
Drawing: N/A
Position: BARREL ON COVER BLOCKS
Building: N/A
Gen_cond: GOOD
Phys_desc: 1 BARREL/4 LARGE COVER BLOCKS
Equip_age: UNKNOWN
Rad_contam: ?
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PIT COVER-BARREL UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: S OF 105-S CPP
Drawing: N/A
Position: ON GROUND/END IN PLASTIC
Building: N/A
Gen_cond: GOOD
Phys_desc: PRESSURE TEST ASSEMBLY
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PRESSURE TEST LINES
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-230

Area: West
 Tank_farm: 241-S
 Gen_area: S OF RED CONEX BOX
 Drawing: N/A
 Position: ON GROUND
 Building: CONEX BOX
 Gen_cond: USED/BARREL LOOKS AC
 Phys_desc: ONE SILVER BARREL/ONE USED A/C
 Equip_age: UNKNOWN
 Rad_contam: UNLIKELY
 Labeling: NONE
 Reusable: NO
 In_place: NO
 Last_used: UNKNOWN
 Future_use: NO
 Use: ?
 History:
 Active: NO
 Fluids: POTENTIAL CFC'S IN AC/BAR???
 Parts: N/A
 Flushed: NO

C-232

Area: West
Tank_farm: 241-S
Gen_area: S OF RED CONEX BOX
Drawing: N/A
Position: ON GROUND
Building: RED CONEX
Gen_cond: USED
Phys_desc: MISC. PIPING/WOOD/(2) 4" RIS. PLG
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: ?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-234

Area: West
Tank_farm: 241-S
Gen_area: NEAR EAST FENCE AREA
Drawing: N/A
Position: ON GROUND IN TARP
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: LARGE UNKNOWN ITEM IN CANVAS BAG
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: ?
History:
Active: NO
Fluids: ?
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: S OF RED CONEX BOX
Drawing: N/A
Position: ON GROUND/RACKED
Building: CONEX BOX
Gen_cond: ALL USED
Phys_desc: FLUSH HANDLE/VLVE HANS/PIPING
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: ?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S/SX
Gen_area: EXHAUSTER PIPING
Drawing: MANY
Position: COVERS S AND SX TANK FARM
Building: N/A
Gen_cond: RUSTED/HOLES/DETERIO
Phys_desc: EXHAUSTER PIPING
Equip_age:
Rad_contam: YES/HIGH
Labeling: RADIATION STICKERS
Reusable: NO
In_place: YES
Last_used:
Future_use: NO
Use: EXHAUSTER PIPING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: NO

C-240

Area: West
Tank_farm: 241-S
Gen_area: WEST OF 241-S-A V.P.
Drawing: N/A
Position: ON GROUND IN BAG
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: CRAIN RIGGING
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: USED TO LIFT COVER BLOCKS
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S
Gen_area: 241-S-112 WEIGHT F E
Drawing: N/A
Position: IN PLACE
Building: 241-S-112
Gen_cond: CONTAMINATED FUNCT1?
Phys_desc: WEIGHT FACTOR ENCLOSURE
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICKER
Labeling: WFE
Reusable: NO
In_place: YES
Last_used: UNKNOWN
Future_use: NO
Use: WEIGHT FACTOR
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-S CONEX BOX
Gen_area: 40' CONEX BOX
Drawing: N/A
Position: LAYING ON CONEX BOX FLOOR
Building: 40' CONEX BOX
Gen_cond: LEAKING
Phys_desc: (2) LEAKING SPIDER JUMPERS
Equip_age: APPROX. 30 YEARS
Rad_contam: YES
Labeling: SX-A AND SX-B VALVE PIT
Reusable: NEEDS TO BE REPAIRED/DECON.
In_place: NO
Last_used: ~~130~~ YEARS
Future_use: NO
Use: WASTE ROUTING
History:
Active: NO
Fluids: POTENTIAL MIXED WASTE IN LINE
Parts: N/A
Flushed: YES

Area: West
Tank_farm: 241-S CONEX BOX
Gen_area: 40' CONEX BOX
Drawing: N/A
Position: LAYING IN BACK OF CONEX BOX
Building: 40' CONEX BOX
Gen_cond: UNKNOWN
Phys_desc: UNKNOWN
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: UNKNOWN
History:
Active: NO
Fluids: ?
Parts: N/A
Flushed: NO

WMC-SD-EM-EV-098, REV. 0

C-247

Area: West
Tank_farm: 241-S/SX
Gen_area: NE END OF 241 SX TF
Drawing:
Position: ON TRACK ON GROUND
Building: N/A
Gen_cond: CONTAMINATED
Phys_desc: GANTRY CRANE
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: YES
Last_used: EARLY 80'S
Future_use: NO
Use: USED TO REMOVE COVER BLOCKS
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-SX
Gen_area: SW CORNER FENCE AREA
Drawing: NONE
Position: IN PLASTIC CN GROUND
Building: N/A
Gen_cond: CONTAMINATED
Phys_desc: RISER PLUG IN BAG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-SX
Gen_area: NEAR CRANE
Drawing: NONE
Position: ON PLYWOOD ON PLASTIC
Building: N/A
Gen_cond: USED
Phys_desc: 42" SHIELD PLUG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: ?
In_place: NO
Last_used: UNKNOWN
Future_use: ?
Use: SHIELD PLUG
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-251

Area: West
Tank_farm: 241-SY
Gen_area: 101SY-11B RISER
Drawing: N/A
Position: ON GROUND IN RUBBER COVER
Building: N/A
Gen_cond: RUSTED IN RAD COVER
Phys_desc: 42" SHIELD PLUG
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: PLUG
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-253

Area: West
Tank_farm: 241-SY
Gen_area: BY EVAPORATOR FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: DETERIORATED
Phys_desc: ENCLOSURES
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: ENCLOSURES
History:
Active: NO
Fluids: UNKNOWN
Parts: N/A
Flushed: NO

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: ANNULUS PUMP AND PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable:
In_place: NO
Last_used: UNKNOWN
Future_use:
Use: ANNULUS PUMP
History:
Active: NO
Fluids: UNKNOWN RESIDUE IN LINES
Parts: N/A
Flushed:

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CCNEX
Drawing: N/A
Position: ON STORAGE SHELF
Building: N/A
Gen_cond: RUSTED
Phys_desc: 1" PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use:
Use: UNKNOWN
History:
Active: NO
Fluids: UNKNOWN RESIDUE IN LINES
Parts: N/A
Flushed: NO

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: N/A
Position: ON PALLET
Building: N/A
Gen_cond: WEATHERED
Phys_desc: SALTWELL PUMP, DIP TUBES
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: N
Use: WASTE PUMPING, LEVEL MEASUREMENT
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: N/A
Position: IN WOODEN STORAGE BOX
Building: N/A
Gen_cond: RUSTED
Phys_desc: CABLES/GEARS/ELECTRIC MOTOR/ET
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: MISC.
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: west
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: N/A
Position: ON PALLET ON GROUND
Building: N/A
Gen_cond: WORN/USED HOSES
Phys_desc: OLD HOSES ON PALLET
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: N
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: OLD VALVE
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: N
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-264

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: N/A
Position: IN WOODEN BOX
Building: N/A
Gen_cond: WORN/RUSTED
Phys_desc: BOX OF VAPOR SEALS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: OUTSIDE S/SX
Gen_area: NEAR 204256AP CONEX
Drawing: H-2-90175
Position: CN PALLET
Building: N/A
Gen_cond: RUSTED
Phys_desc: THREE JUMPER (PARTS)
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-T
Gen_area: NEAR 105-FIC
Drawing: N/A
Position: ON GROUND UNDER PLASTIC
Building: N/A
Gen_cond: UNKNOWN
Phys_desc: PB BRICKS/SHEETS
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: YES
In_place: NO
Last_used: N/A
Future_use: NO
Use: SHIELDING
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-269

Area: West
Tank_farm: 241-T
Gen_area: UNKNOWN
Drawing: N/A
Position: ON GROUND IN BAG
Building: N/A
Gen_cond: USED
Phys_desc: PIPING
Equip_age: UNKNOWN
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: ?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 241-U-151
Gen_area: ON GROUND NEAR U-151
Drawing: IS9610
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED (WELL USED)
Phys_desc: COUNTERWEIGHT WITH PB
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: BOX NO. WC33001
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: COUNTERWEIGHT FOR CRANE
History:
Active: NO
Fluids: MAY CONTAIN PB
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 244-U
Gen_area: BETWEEN 241-U-C/D VP
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: PARTIALLY RUSTED
Phys_desc: CABLE/BULL HOOK
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: REMOVE COVER BLOCKS
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 244-U
Gen_area: N PART U TF INST.BLD
Drawing: N/A
Position: ON GROUND/PART IN PLASTIC
Building: INST. BLDG
Gen_cond: CONTAMINATED
Phys_desc: PLYWOOD IN PLASTIC BAGS
Equip_age: UNKNOWN
Rad_contam: YES-RADIATION STICER
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: WOOD USED TO COVER PITS?
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-277

Area: West
Tank_farm: 244-U
Gen_area: NEXT TO NORTH FENCE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: OLD PLASTIC DETERIORATED
Phys_desc: OLD HOSES 2"
Equip_age: UNKNOWN
Rad_contam: POSSIBLE
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-279

Area: West
Tank_farm: 244-U
Gen_area: ON EDGE OF PIT
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: USED
Phys_desc: HOSE IN BAG/WOOD/LADDER
Equip_age: UNKNOWN
Rad_contam: HOSE?
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: MAY HAVE BEEN USED IN THE PIT
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 244-U
Gen_area: NEAR SE FENCE LINE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: RUSTED PIPING 2"
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm: 244-U
Gen_area: NEAR SE FENCE LINE
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WEATHERED
Phys_desc: 2X4'S AND 4x8'S PILE
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

C-285

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED/CUT OPEN
Phys_desc: 55 GALLON DRUM CUT OPEN
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: BARREL
History:
Active: NO
Fluids: UNKNOWN RESIDUE FROM BARREL
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON METAL PLATFORM ON GROU
Building: N/A
Gen_cond: WORN OUT WOOD
Phys_desc: 2 BURIAL BOXES
Equip_age: >30 YEARS
Rad_contam: YES
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: STORAGE OF WASTE
History:
Active: NO
Fluids: UNKNOWN CONTENTS
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: IN PILE ON GROUND
Building: N/A
Gen_cond: WEATHERED
Phys_desc: (21) 4" x 8" WOOD
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN (COVERBLOCK STORAGE)
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WEATHERED
Phys_desc: CABLE SPOOL/COVER BLOCK
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: COVER BLOCK/CABLE SPOOL
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: CN GROUND
Building: N/A
Gen_cond: RUSTED TOPS
Phys_desc: (8) 42" SHIELD PLUGS
Equip_age: UNKNOWN
Rad_contam: LIKELY
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: TANK ACCESS HOLE COVER
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: CN GROUND
Building: N/A
Gen_cond: WEATHERED PIPES
Phys_desc: 4" PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN PIPING
History:
Active: NO
Fluids: UNKNOWN RESIDUE IN PIPE
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: WEATHERED PIPE
Phys_desc: 4" PIPE
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN PIPING
History:
Active: NO
Fluids: UNKNOWN RESIDUE IN PIPE
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED TOP
Phys_desc: 6" RISER PLUG
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: COVERS ACCESS PORT
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON PALLET ON GROUND
Building: N/A
Gen_cond: IN PLASTIC BAGS
Phys_desc: UNKNOWN ITEMS (1 RISER PLUG)
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN ITEM
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON METAL PLATE ON GROUND
Building: N/A
Gen_cond: ONE END IN PLASTIC
Phys_desc: 1" PIPING
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON GROUND (CEMENT PAD)
Building: N/A
Gen_cond: RUSTED
Phys_desc: LARGE METAL SUPPORT
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: ON GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: METAL STORAGE PLATE
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

Area: West
Tank_farm:
Gen_area: NEAR 2727-WA BLDG
Drawing: N/A
Position: CN GROUND
Building: N/A
Gen_cond: RUSTED
Phys_desc: LARGE METAL SUPPORT
Equip_age: UNKNOWN
Rad_contam: UNKNOWN
Labeling: NONE
Reusable: NO
In_place: NO
Last_used: UNKNOWN
Future_use: NO
Use: UNKNOWN
History:
Active: NO
Fluids: N/A
Parts: N/A
Flushed: NO

APPENDIX D
AERIAL PHOTOGRAPHS OF TANK FARMS