SARPM
SEVERE ACCIDENT PROGRAM

WSRC-RP-91-0952

WSRC-RP--91-0952

DE92 040819

**SCOPING TESTS ON THE POTENTIAL FOR LITHIUM/ALUMINUM STEAM
EXPLOSIONS IN AN SRS SEPTIFOIL (U)**

by

D.H. Cho, J.D. Gabor, R.T. Purviance, & J.C. Cassulo

**Argonne National Laboratory
Argonne, Illinois**

Reviewed by

**P.G. Ellison & M.L. Hyder
Westinghouse Savannah River Company
Aiken, South Carolina**

September 1991

**Westinghouse Savannah River Company
Savannah River Site
Aiken, SC 29808**

PREPARED FOR THE US DEPARTMENT OF ENERGY UNDER CONTRACT NO. DE-AC09-89SR18035

MASTER

JP

PROJECT: Steam Explosions/ Aluminum-Lithium Alloys

DOCUMENT: WSRC-RP-91-0952

TITLE: SCOPING TESTS ON THE POTENTIAL FOR LITHIUM/ ALUMINUM STEAM
EXPLOSIONS IN AN SRS SEPTIFOIL (U)

TASK: Severe Accident Program Documentation

APPROVALS

Phillip G. Ellison
Derivative Classifier

Phillip G. Ellison

Date: 9-24-91

Phillip G. Ellison
Technical Review

Phillip G. Ellison

Date: 9-24-91

M.L. Hyder
Technical Review

M.L. Hyder

Date: 9/30/91

L.A. Wooten, Manager
Safety Analysis Group

L.A. Wooten

Date: 10/1/91

M.J. Hitchler, Manager
Reactor Safety Research

M.J. Hitchler

Date: 10/1/91

1. INTRODUCTION

In May 1991, WSRC/SRL requested that ANL conduct five scoping tests in order to investigate the potential for self-triggered lithium/aluminum steam explosion in an SRS Septifoil. This work was to support the ongoing SAR Chapter 15 analysis for the K-reactor restart at SRS. The five tests were successfully completed over a two-month period between June and August 1991.

The conditions for the five tests were specified by the WSRC designated technical manager, Dr. Phillip G. Ellison. While the tests were carried out in an existing facility at ANL, WSRC/SRL provided the test sections which consisted of a three-foot long SRS Septifoil section including webbing, bottom endfitting, and eleven-inch long control rod segments. In addition, WSRC/SRL supplied the lithium/aluminum alloy required for the tests.

2. TEST APPARATUS AND PROCEDURE

The tests were conducted in a facility consisting of a main Interaction Assembly, power supplies, instrumentation and controls, and services. The Interaction Assembly was located in a cell with three-foot thick concrete walls and fourteen-inch thick steel doors. The Interaction Assembly consisted of the Interaction Vessel, Alloy Melting Furnace/Injector and Steam Accumulator (see Figs. 1 and 2').

The Alloy Melting Furnace/Injector was 3.75 in. (95 mm) in ID and eight inches (203 mm) high. The furnace was wrapped with 1/16-in. coaxial heater wire sufficient for 2 KW. Injection was achieved by having a cutter actuated by a pneumatic piston cut through a vitreous aluminosilicate fiber crucible containing the melt inside the furnace.

The nine-inch (0.23 m) diameter Interaction Vessel was filled with water up to three inches from the top flange, and nearly the entire test section (i.e., the SRS Septifoil) was submerged in the water. Figures 1 and 2 show the test section configuration for Test C1 and that for Tests C2 and C5, respectively. The septifoil was mounted on a one-inch diameter aluminum rod to locate its top two inches above the water level and one inch below the bottom of the injector tube.

¹ All tables and figures are attached at end of report.

Two stainless steel rings with threaded positioning rods were used to locate the septifoil laterally under the injector tube opening. During the tests, the plenum space above the water was purged with argon. For each of the tests (except C4), two gas samples were withdrawn from the plenum above the water at ten and fifteen seconds after the melt injection.

The steam accumulator was a plastic container partially filled with water and vented. The steam line to the accumulator was a one-inch copper tube that was heated and insulated. The end of the copper tube was capped, and the steam flow was emitted through sixty-four 1/4-in. (6.4 mm) holes below the water level. The water for condensing the steam was initially at room temperature. A 1-gal. plastic container was used for the first three experiments, and a 2.5-gal. plastic container was used in the final two experiments. At zero time (start of melt injection), the steam line to the accumulator was opened by a pneumatic valve, and the vent from the Interaction Vessel was closed.

Thermocouple and pressure transducer mountings in the Interaction Vessel are shown in Figs. 1 and 2. The thermocouples were chromel-alumel enclosed in a 1/16-in. (1.6 mm) diameter stainless steel sheath. A 0-1000-psia pressure transducer was mounted near the bottom of the Interaction Vessel. A 0-2000-psia pressure transducer was located near the center of the vessel, and a 0-100-psia pressure transducer indicated the plenum pressure above the water. The thermocouple readings were recorded by a Digitrend Model 210 during the heatup phase. A Honeywell 1858 Visicorder and a Honeywell 101 magnetic tape unit were used to record temperature and pressure data. The heat flows to the furnace and the Interaction Vessel were regulated by 0-1000 C Weather Measure Model PTC-1 temperature controllers.

3. RESULTS AND DISCUSSION

The thermal conditions were identical for all five tests. The melt temperature was in the range of 680-700° ensuring that the lithium/aluminum alloy loaded in the furnace was fully molten with minimal superheat. The water temperature was kept constant at 85°C.

Table 1 summarizes the test conditions. Test C1 employed a single melt jet injection in one of the six peripheral channels of the Septifoil, simulating a one-rod configuration (i.e., one eleven-

inch control rod segment was inserted into the channel where the melt injection took place). Tests C2 through C5 employed a multiple melt jet injection with one jet being in each of five peripheral channels, simulating a five-rod configuration (i.e., five eleven-inch control rod segments were inserted into the five channels where the melt injection took place). Test conditions for C3 and C4 were identical to those for C2 and C5 except for the water depth in the Septifoil. In Tests C2 and C5, the water depth was twenty-four inches from the bottom of the Septifoil (or thirteen inches from the top of the control rod segments submerged in the water). In tests C3 and C4, the water depth was sixteen inches from the bottom of the Septifoil (or five inches from the top of the control rod segments).

Following a description of overall observations, some noteworthy features of the results will be discussed.

Overall Observations

In any of the five tests conducted, no explosive events occurred. No significant pressure pulses were detected by the two pressure transducers mounted in the water tank (Interaction Vessel) outside the Septifoil. These transducers had a range of 0-1000 psi and of 0-2000 psi, respectively. Some pressurization of the plenum space (i.e., the space above the water in the tank) was noticed in all tests, as will be discussed later.

Posttest examinations revealed that the Septifoil housing structure remained intact in all five tests. The inside and outside surfaces of the housing tube were covered with slimy, whitish scum, indicating that the Septifoil water containing impurities had splashed over the surfaces and dried out. In addition, in each of the five tests, it was noticed that the water level in the Septifoil had dropped from the level prior to the test. Evidently, substantial amounts of water were lost from the Septifoil during the test. The observed water losses are summarized in Table 2. This table also shows estimates of maximum water loss due to vaporization based on the melt thermal energy. It is seen that the estimated vaporization losses represent only a small fraction of the observed water losses. If there had been a significant chemical reaction between the Li/Al alloy and water, the thermal energy available for water vaporization would have been much greater than the melt stored energy. However, it seems highly unlikely that the observed water

losses could be accounted for by vaporization alone. Rather, it would appear that a transient pressurization in the Septifoil caused expulsion of some of the water in a burping manner.

The X-ray radiographs of the test sections showed that the lower portions of the Septifoil channels were filled with debris, which was later found to consist of particles of various sizes and fine white powder. Figure 3 compares two X-ray radiographs of the C1 test section, one before the test and the other after the test. The melt injection was made in one of the peripheral channels containing a control rod segment. It is seen that the debris accumulated in all seven channels including the initially empty channels. Clearly, the injected melt found its paths through the webbings and relocated to all available channels. Figure 4 shows a similar X-ray radiograph of the C2 test section after the test. (The bottom three inches of the test section are not shown.) Again, it is seen that the available channels were filled with debris. Figure 5 shows an X-ray radiograph of the lower portion of the C3 test section. It is interesting to note that a small amount of debris collected in the bottom endfitting region, indicating that some melt relocated through the inlet flow orifices. Figure 6 shows a photograph of the C3 test section with half of the housing tube removed. This photograph clearly shows the Septifoil channels fully packed with debris. These observations suggest that the injected melt was readily quenched and frozen in the available channels of the Septifoil.

Pressurization in Plenum Space

As indicated earlier, a pressure transducer was mounted in the top flange of the water tank (see Figs. 1 and 2). This pressure transducer, which had a range of 0-100 psi, measured pressure variations in the plenum space above the water level. In each of the five tests, there was some pressurization of the plenum space. The pressure traces for the five tests are shown in Figs. 7-11. Zero time in these figures corresponds to the start of melt injection. (The melt injection was completed in 1-2 seconds.) It is seen that the pressurization took place over a period of about ten seconds. The extent of pressurization was about 0.02 and 0.03 MPa for tests C1 and C2, respectively, while it was in the range of 0.15 MPa for Tests C3 to C5. Evidently, the extent of pressurization increased with increasing mass of melt delivered (see Table 1). The observed pressurizations were not shock pressures, but represented a static pressure buildup in a confined space (i.e., the plenum). Clearly, these pressurizations are related to the expulsion

of water from the Septifoil discussed above. It appears that there was rapid production of gas (steam and hydrogen, presumably) upon contact of the injected melt with water and that the gas production caused the expulsion of water from the Septifoil as well as the pressurization of the plenum space.

Plenum Gas Samples

As described earlier, for each of the tests (except for C4), two samples of the plenum atmosphere above the tank water were taken at ten and fifteen seconds after the melt injection. These samples were analyzed using a mass spectrometer and the results are presented in Table 3. This table shows the contents of the various gases in volume per cent. At the time when the samples were taken, the sampling bottles probably contained a substantial amount of steam. The contents of this steam, however, are not known. The sampling system as well as the analysis method employed was not designed to determine the steam content at the time of sampling. It is not possible to determine the relative contributions of steam and hydrogen to the observed plenum pressurizations, although Table 3 seems to suggest that the hydrogen contribution might have been significant. The potential contribution of steam to the pressurization will be discussed later.

Temperature Transients in Injector Channels and Melt Crucible

As described earlier, the melt injector for Tests C2 to C5 had five channels. Thermocouples were mounted in three of the five injector channels in order to monitor the temperatures of the melt as it flowed through the channels. Observations made with these thermocouples will be illustrated using a thermocouple trace for Test C3, which is shown in Fig. 12. Upon injection of the melt (i.e., zero time), the trace correctly indicates the melt temperature. One or two seconds later, the temperature is seen to decrease to about 100°C. This temperature decrease seems to coincide with the plenum pressurization shown in Fig. 9. It would appear that saturated steam was flowing up through the channel. Then, interestingly enough, the temperature increases well above the initial melt temperature. At this point, there was no external heat source available in the injector. A plausible explanation for this temperature increase is that a chemical reaction between steam and residual Li/Al melt adhering to the channel walls released energy, heating up the channel atmosphere.

Similar temperature increases were also noticed in the melt crucible. Figure 13 shows a crucible thermocouple trace for Test C4. The melt temperature at injection was in the range of 690-700°C. Figure 13 shows that the crucible atmosphere temperature steadily increases after the melt injection. Some heat flow from the steel furnace to the crucible was expected, since the furnace was at a higher temperature than the melt prior to the injection. However, the heat stored in the furnace is not considered to be sufficient to account for the temperature increases shown in Fig. 13. Again, a chemical reaction between steam and Li/Al melt remaining in the crucible appears to be responsible for the observed temperature increases.

Septifoil Water Samples

After each test, a sample of the Septifoil water was collected and titrated with a standard HCl solution. The water was found to be highly alkaline, the pH being in the range of 10-12. The lithium (Li) content was estimated, assuming that Li exists in the water in the form of lithium hydroxide (LiOH). The Li content per 1000 ml of water was found to be 0.084 g for Test C1, 0.043 g for Test C2, and 0.041 g for Test C5. For Test C1, the Li content corresponded to about 2% of the amount of Li in the delivered melt, while for Tests C2 and C5, it corresponded to about 0.5% of the amount of Li in the delivered melt.

Debris

Overall, the debris collected after the tests consisted of particles of various sizes and small amounts of fine white powder. The sizes of most of the particles were in the range of one to ten millimeters. Figure 14 shows debris samples from Test C1.

A sample of the fine white powder collected after Test C1 was analyzed by the Analytical Laboratory at WSRC/SRL (P. G. Ellison, WSRC/SRL, Private Communication to D. H. Cho, ANL, June 25, 1991). The analysis identified Lithium Aluminum Carbonate Hydroxide Hydrate, $\text{Li}_2\text{Al}_4(\text{CO}_3)_3(\text{OH})_{12}\cdot 3\text{H}_2\text{O}$, as the major component and Aluminum Hydroxide, $\text{Al}(\text{OH})_3$, as a minor component. It appears that the fine white powder mostly consists of the reaction products of water (or steam) with the Li/Al alloy melt.

Further Discussion

Based on the foregoing observations, it appears that the injected melt rapidly quenched as it penetrated the water in the Septifoil. Evidently, during the quenching process, steam and hydrogen were produced, leading to the expulsion of water from the Septifoil and pressurizing the plenum space over a period of ten seconds. Now, it might be useful to examine further some of the available data.

Consider, for example, Test C4. Figure 12 shows an overpressurization of 0.15 MPa in the plenum space above the tank water. Assuming an ideal gas at the boiling point of water, this overpressurization would require an addition of 0.28 g-mole of gas (steam, hydrogen, or both) to the plenum space. This would be the minimum amount required, since during the pressurization, some of the gas would have escaped through the melt injector channels as well as through the vent tube leading to the steam accumulator.

This required amount of gas for the plenum pressurization for Test C4 may be compared with the amount of steam that could have been produced based on the thermal energy of the injected melt. The melt thermal energy above the boiling point of water is 0.72 MJ. As already indicated in Table 2, the maximum amount of steam that could have been produced by this thermal energy is 309 g or 17 g-moles. If it is assumed that the melt was uniformly mixed with all the available water (~1500 g), a somewhat smaller amount of steam (15 g-moles) would have been produced. In any case, the amount of steam that would have been produced is about fifty times greater than the minimum amount required for the plenum pressurization. Clearly, the thermal energy of the melt was far greater than needed to produce steam for the observed plenum pressurization. Any chemical reaction between the melt and water would, of course, have added to the energy available for steam production.

Information on the amount of steam produced, albeit somewhat qualitative, may be obtained by examining the thermocouple records of the steam accumulator. The bulk of steam produced during the tests was collected and condensed in the steam accumulator. For Test C4, the initial water mass and temperature of the steam accumulator were 8870 g and 25°C, respectively. During the test, the water mass and temperature increased to 9442 g and 50°C, respectively.

Assuming that a steam/water two-phase mixture at 100°C flowed into the accumulator during the test, an estimate of the amount of steam condensed in the accumulator was made based on an energy balance. It indicates that the steam condensed was about 360 g or 20 g-moles, which is slightly larger than the maximum amount of vaporization based on the melt thermal energy (see Table 2). It might be possible to account for the difference by considering the chemical energy contribution of a Li/Al melt-water reaction. While the steam accumulator data is rather qualitative, it seems clear that the steam production alone would have been more than sufficient to cause the observed pressurizations of the plenum space.

4. SUMMARY AND CONCLUSIONS

Five scoping tests on Li/Al melt-water interaction were conducted in order to investigate the potential for a self-triggered steam explosion in an SRS Septifoil. In all five tests, no explosive events took place, and the Septifoil housing structure remained intact. Other significant findings are summarized below.

- Overpressurizations of the order of 0.1 MPa over a period of ten seconds were measured in the plenum space above the water of the Interaction Vessel (which contained the Test Section, i.e., the Septifoil). It is believed that these pressurizations were caused by the production of steam and hydrogen upon quenching of the injected melt in the Septifoil water.
- It is not possible to determine the relative contributions of steam and hydrogen to the plenum pressurizations. However, an energy consideration suggests that the production of steam alone would have been more than sufficient to account for the pressurizations.
- Analyses of the gas samples withdrawn from the plenum space during the tests seem to indicate that the contribution of hydrogen to the plenum pressurizations might have been significant.

- Thermocouple records for the injector channels and melt crucible suggest the possibility of the residual Li/Al melt (after the melt delivery) reacting with steam and producing heat.
- Posttest analyses of the Septifoil water samples show that the water was highly alkaline, the pH being in the range of 10-12, due presumably to lithium hydroxide dissolved in the water.
- The debris collected after the tests consisted of particles of various sizes (mostly in the range of one to ten millimeters) and small amounts of fine white powder. An analysis of the white powder indicates that it consists of the reaction products of water (or steam) with the Li/Al alloy melt.

Table 1. Test Conditions

Test No.	C1	C2	C3	C4	C5
Water Depth, In.	24	24	16	16	24
Water Height above Top of Control Rods, In.	13	13	5	5	13
Water Temperature, °C	85	85	85	85	85
No. of Control Rods (11-in. long)	1	5	5	5	5
Melt Delivery Mode	Single jet into one channel	Multiple jets (one jet in each of five channels)			
Melt Jet Diameter, cm.	1.4	1.2	1.2	1.2	1.2
Melt Delivery Rate (nominal), kg/s	0.3	0.9	0.9	0.9	0.9
Total Melt Mass, kg	0.5	1.0	1.0	1.0	1.0
Melt Mass Delivered, kg	-0.4	-0.5	-0.8	-0.8	-0.8
Melt Temperature, °C	680-685	680-685	685-690	690-700	685-690

Table 2. Water Loss from Septifoil

Test	C1	C2	C3	C4	C5
Water volume before test (cc)	2940	2400	1525	1500	2400
Water volume after test (cc)	2110	1100	--	--	370
Water volume loss (cc)	830	1300	1525	1500	2030
Maximum water volume loss due to vaporization based on melt thermal energy (cc)	154	193	309	309	309

Table 3. Results of Plenum Gas Sample Analysis (Volume %)

Sample 1 (Sample taken 10 sec. after melt injection)				
Test No.	C1	C2	C3	C5
H ₂	91.0	27.5	55.1	59.7
H ₂ O	0.22	*	*	*
N ₂	4.04	55.3	35.3	31.9
O ₂	0.85	16.2	8.6	7.5
Ar	3.90	0.9	0.8	0.7
CO ₂	0.02	0.1	0.2	0.2
Sample 2 (Sample taken 15 sec. after melt injection)				
Test No.	C1	C2	C3	C5
H ₂	58.4	33.2	40.6	55.8
H ₂ O	1.4	*	*	*
N ₂	32.6	42.2	44.9	36.4
O ₂	7.1	14.7	13.7	6.2
Ar	0.52	9.8	0.7	1.3
CO ₂	<0.01	0.1	0.1	0.3

* Not determined

Fig. 1. Test Section Configuration for CI

Fig. 2. Test Section Configuration for C2 to C5

Before Test

After Test

Fig. 3. X-ray Radiograph of C1 Test Section

Fig. 4. X-ray Radiograph of C2 Test Section

Fig. 5. X-ray Radiograph of C3 Test Section

Fig. 6. C3 Test Section with Half of the
Septifoil Housing Tube Removed

Fig. 7. Plenum Overpressurization for CI

Fig. 8. Plenum Overpressurization for C2

Fig. 9. Plenum Overpressurization for C3

Fig. 10. Plenum Overpressurization for C4

Fig. 11. Plenum Overpressurization for C5

Fig. 12. Injector Channel Temperature Transient for C3

Fig. 13. Melt Crucible Temperature Transient for C4

Fig. 14. Debris Samples from CI

K:\TOWNSHIP\ELSON.DXC

END

**DATE
FILMED**

12 / 9 / 92