TECHNICAL REPORT

December 1, 1991 through February 29, 1992

Project Title: HIGH TEMPERATURE CORROSION DURING USE OF CHLORINE CONTAINING COAL

Principal Investigator: Michael McNallan, University of Illinois at Chicago

Other Investigators: Steven Danyluk, J.E. Indacochea, University of Illinois at Chicago

Project Monitor: Dr. Dan Banerjee, CRSC

ABSTRACT

The goal of this project is to characterize the role of chlorine in coal on the high temperature corrosion processes which can occur in coal combustion and conversion processes. The experiments include laboratory tests performed in well-controlled high temperature environments and field tests in industrial coal fired boilers. Evaluation of samples of boiler tubes which have been recovered from boilers which used both high and low chlorine coals does not indicate that the higher chlorine levels are associated with accelerated corrosion of either water wall tubes or superheater tubes in pulverized coal boilers. Laboratory testing of metal coupons in combustion gas environments produced from low sulfur, high chlorine coal IBC-109 and high sulfur-low chlorine coal IBC-101 has been performed at 700 and 800°C. Initial results indicate that more corrosion is produced in the high sulfur environment than in the high chlorine environment. Further testing at other temperatures and gas compositions is in progress.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

MASTER

This project is funded by the U. S. Department of Energy (METC) and by the Illinois Department of Energy and Natural Resources as part of their cost-shared program.

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

EXECUTIVE SUMMARY

Illinois basin coals have the highest chlorine contents of any coals mined in North America in addition to high sulfur contents. The perception that chlorine in coal contributes to boiler corrosion is a hindrance to the marketing of Illinois coal. Although this perception is widespread, it is not supported by any definitive data. The goal of this program is to investigate the corrosion of several important high temperature structural materials in environments produced by the combustion of coals, and to clarify the role of chlorine in these processes.

The research includes laboratory exposure tests as well as field tests in industrial boilers. Corrosion tests are performed on metal specimens in environments generated by combusting high sulfur, low chlorine coal (IBC-101) and low sulfur, high chlorine coal (IBC-109) at controlled fuel to air ratios and temperatures. Coal specimens have been ground to less than 200 mesh and combusted under conditions which simulate pulverized coal combustion. Test coupons of low carbon steel, 2 1/4Cr-1Mo steel, AISI 310 stainless steel, and alloy 800 have been exposed to combustion gases produced from the coals at 700 and 800°C. The low carbon steel and the 2 1/4 Cr-1Mo steel oxidized much more than the stainless steel or alloy 800 on the basis of weight change and external scale formation. The combustion gases from the IBC-109 coal produced less corrosion than the combustion gases from the IBC-101 coal for 24 hour exposures at both temperatures. Examination of the corrosion products by X-ray diffraction analysis and energy dispersive X-ray microanalysis in a scanning electron microscope indicated that the corrosion products in the environment produced by combusting IBC-101 coal contained sulfides as well as oxides. Further microstructural examination of the corrosion products from the IBC-109 combustion gas are in progress.

Additional tests are under way in a second laboratory furnace in corrosive gases produced by mixing reagent quality gases. In these experiments, the effects of chlorine contamination on the corrosion of high alloy steels in a CO₂ containing environment at 800°C are investigated. HCl is much less aggressive than Cl₂ in these environments. Further tests to evaluate the effects of sulfur additions will be performed in the coming quarter.

Evaluation of test coupons which have been exposed to combustion gases from coal in working boilers is addressed in a second phase of the program. Tubes have been collected and evaluated from several pulverized coal boilers which burned Illinois coals. The results do not indicate that there is any correlation between chlorine content of coal and fire-side corrosion in pulverized coal boilers. Test coupons of low carbon steel, 1 1/4Cr-1/2Mo steel, 2 1/4Cr-1Mo steel, and AISI 304 stainless steel were placed in the low temperature superheater of a boiler last year. These coupons will be recovered next quarter for evaluation. Discussions are underway with another company regarding placement of test coupons in a fluidized bed combustion boiler.

OBJECTIVES

The goal of this project is to characterize the conditions under which corrosion in coal fired boilers and coal conversion systems can be produced by chlorine in coal and to investigate the mechanisms of this corrosion. The program focusses on high temperature fireside corrosion and includes laboratory scale tests under well controlled conditions in the laboratory as well as coupon tests in utility boilers using high and low sulfur coal. In order to meet these objectives, a laboratory furnace is used to expose coupons of important structural materials to combustion gases under well characterized conditions. The apparatus permits control of the temperature, feed rate of well characterized coal, and composition and feed rate of the other combustion gases. Exposure tests are performed over a range of fuel to air ratios, temperatures, and other relevant parameters and the response of the materials is characterized using weight change and microstructural examination. The laboratory work is supplemented by coupon testing in industrial boilers to verify that the corrosion mechanisms identified in the laboratory correspond to the corrosion observed in practice.

INTRODUCTION AND BACKGROUND

In addition to their high sulfur contents, Illinois basin coals have the highest chlorine contents of any coals mined in North America. The perception on the part of many coal users that chlorine in coal contributes to boiler corrosion problems is a hindrance to the marketing of Illinois coal. Although this perception is widespread, it is not well documented, and chlorine containing coals have been used in many applications without

serious problems. The materials degradation processes which occur in many coal combustion and conversion systems are complex and there is presently no clear knowledge of whether chlorine in coal can accelerate corrosion in combustion or in gasifiers or other coal conversion systems.

This research program addresses the influence of chlorine in coal on corrosion problems experienced by important structural materials in atmospheres produced by combustion of coal. The research is performed in two sections: (1) Laboratory studies and (2) in plant coupon tests. In the laboratory studies, care is taken to insure that the materials are exposed only to the gaseous atmosphere produced by combustion of the coal so that damage by erosion or other degradation processes is avoided. The mechanisms and rates of corrosion will be characterized as a function of the material, temperature and composition of the atmosphere. The results will provide definitive information on the effects of chlorine on corrosion in atmospheres typical of coal combustion and conversion systems, so that the significance of chlorine to high temperature corrosion problems can be assessed. The plant tests provide verification of the laboratory generated data, as well as documenting data on the actual effects of varying chlorine levels in coal on corrosion problems experienced by coal users.

EXPERIMENTAL PROCEDURES

The laboratory experiments consist of exposures of well characterized materials to gas environments produced by combustion of coals under well characterized conditions. They are performed in a specially designed furnace in which the composition of the corrosive environment can be

accurately controlled. Considerable effort has gone into the design and construction of this unit, and improvements in the performance of the furnace have continued as we have gained experience in its operation. It is clear that the combustion of coal in a small scale continuous furnace operation under sufficiently well controlled conditions that reproducible high temperature corrosive gas mixtures are produced is much more difficult than the preparation of gas mixtures of similar composition from reagent gases. The effort is worthwhile, however, because this provides the only means to evaluate the corrosiveness of combustion gases produced when specific coals are burned at specified fuel to air ratios. The following modifications in the furnace have been made during the past quarter:

1. The vibratory type coal feeder used on the top of the furnace has been replaced by an AccuRate Model 106 screw type coal feeder. This unit permits pulverized coal to be fed into the furnace at much more accurate and reproducible rates than with the vibratory type feeder. The accuracy of the coal feeder permits the fuel to air ratios in the furnace to be controlled more accurately and provides the precision necessary to investigate the effects of fuel to air ratio on the corrosion. During the first month of the quarter, the coal feeder was calibrated and mounted on the test furnace.

2. In the initial experiments using the screw type coal feeder, some plugging problems were encountered at the top of the furnace where the coal air mixture enters the sealed reaction tube through a water cooled brass plate. These problems were overcome by fabricating a teflon insert to connect the coal feeder with the reaction tube. The water cooling

from the brass plate is sufficient to keep the teflon from melting and the low friction teflon surface prevents the coal from forming blockages as it flows into the test furnace.

3. The kinetics of the combustion of the coal continues to be a concern. Combustion is performed in the upper zone of the furnace which is maintained at a temperature of 800°C , and the combustion gases are fed to the lower zone of the furnace where metal test coupons are exposed to the gases at temperatures between 400 and 800°C . We are interested in simulating the exposure conditions of tubes in a pulverized coal boiler where the coal has been essentially all combusted before the gases reach the superheater tubes. However, the temperatures in the combustion zone of the test furnace are still much lower than those in the fireball of coal boiler where they may approach the adiabatic flame temperature of the coal. The thermal history of the combustion gases before they come in contact with the metals would not be expected to affect the corrosion rates, but it is important that the coal be fully combusted. The formation of small tar deposits in the exit line from the test furnace indicates that at least some hydrocarbons pass entirely through the furnace without being fully combusted. It may not be practical to increase the temperature of the combustion furnace above 850 to 900°C , because at higher temperatures, the iron oxides in the coal ash could begin to form liquid reaction products with the fused silica reaction tube, and this could lead to rapid failure of the tube. Higher temperatures could be possible with a more expensive mullite reaction tube, but there are other disadvantages to this ceramic. At this time we are considering the feasibility of placing catalysts in the lower part of the combustion zone to insure that the combustion reactions proceed to completion.

In addition to the coal combustion furnace, an additional test furnace has been committed to the program in which supplementary tests are performed in simulated combustion gases produced by mixing reagent gases. These tests can be performed more rapidly, and have the advantage that the composition of the gas is not dependent on the efficiency of the combustion process. They are being performed to supplement the results obtained in the coal combustion furnace and to verify the effects of the corrosive species found in the coal combustion tests.

RESULTS AND DISCUSSION

1. Laboratory Corrosion Tests

A. Coal Combustion Furnace

Tests have been performed for 24 hour periods in the laboratory coal combustion furnace at 700 and 800°C feeding both low chlorine IBC-101 coal and high chlorine IBC-109 coal. Coupons of four test alloys (1010 carbon steel, F-22 2 1/4 Cr - 1 Mo steel, AISI 310 stainless steel, and alloy 800) have been exposed. Table 1 summarizes the changes in mass measured on the specimens after each test. The corrosion occurred in the form of growth of oxide scales on the specimens as expected based on the thermodynamic calculations performed for the high excess air combustion gas mixture. The differences in amount of corrosion among the different alloys are consistent with the known corrosion resistances of the four materials in high temperature oxidizing environments.

TABLE 1
CHANGE IN MASS OF TEST COUPONS AFTER EXPOSURE
IN COMBUSTION LABORATORY FURNACE (mg/cm²)

	C1010	F-22	310	800
1. IBC-101 T = 800 C	+25.4	-9.7	+1.1	+1.59
(After scale removal)	-64.1	-148.5		
2. IBC-109	+36.3	+34.9	+0.43	+0.48
3. IBC-101 T = 700 C	+38.2	+10.3	+0.48	+0.44
(After scale removal)	-74.3	-31.4		
4. IBC-109 T = 700 C	+24.9	+18.7	+0.34	+0.61

The overall amounts of attack of the materials are consistent with the expected behavior of the alloys and the results of earlier tests performed using the vibratory coal feeder. The 1010 steel and F-22 low alloy steel were severely attacked leading to large increases in weight. The scales formed on these alloys in the atmosphere produced from the IBC-101 coal spalled easily after the exposure, so the weight losses after scale removal were also measured. The ratio between the weight loss after scale removal and the weight gain during oxidation is an indication of the ratio of the mass of metal and oxide species in the oxidation product. This ratio was lower than would be expected for iron oxide formation, but higher than would be expected for iron sulfide formation, indicating that both oxides and sulfides were formed in this mixed oxida-

tion process. This was confirmed by examination of the oxidation products using X-ray diffraction analysis and microanalysis using energy dispersive X-ray spectroscopy in a scanning electron microscope, both of which indicated that both iron oxide and iron sulfide were present in the scale. Formation of such multicomponent scales are expected in atmospheres which are high in SO_2 with the sulfides concentrating near the scale-metal interface. There was some spallation of the corrosion products from the F-22 specimen exposed to the IBC-101 coal gas at 800°C , which caused the mass of the sample to decrease after exposure.

The mass changes for the samples exposed to the combustion gases from IBC-109 coal were smaller than for those exposed to combustion gases from IBC-101 coal. This may indicate that the higher sulfur content of the IBC-101 coal has a greater effect on the corrosion of the metals at these temperatures than the higher chlorine content of the IBC-109 coals. The scales formed on the C1010 and F-22 steels in the IBC-109 coal combustion gas were more adherent to the metals than those formed in the IBC-101 coal combustion gas. Microchemical and X-ray diffraction analyses of the scales formed in the IBC-109 coal are in progress.

Scanning electron microscopy performed on the oxidation products and metal from the samples exposed in these tests produced micrographs which were similar to those that we published in the last quarterly report.

The more highly alloyed materials showed little net change in mass as expected. The scales formed on these specimens were primarily chromium rich oxides as determined by scanning electron microscopy and energy X-ray microanalysis. These scales are very protective in environments

which contain sufficient oxygen and are the primary reason for the oxidation resistance of these materials. They may be subject to internal corrosion on grain boundaries, and metallographic analysis of the coupons is in progress to determine the extent of this form of attack.

B. Reagent Gas Mixture Furnace.

In addition to the test furnace where coal combustion gases are generated, tests have also been performed in a separate furnace where reagent gases can be mixed to prepare gas mixtures of accurately controlled compositions. The tests performed in this furnace to date have focussed on the corrosion of the high alloy steels 310 and 800 at 800°C where they have good resistance to corrosion in the coal combustion furnace. Our interest is identifying the level of chlorine contamination necessary to produce attack in these alloys and identifying characteristic corrosion product morphologies which can be used to identify chlorine induced corrosion in these materials. Table 2 indicates the environments tested during the past quarter and the weight loss produced in each test.

TABLE 2
CHANGE IN MASS OF TEST COUPONS AFTER 24 HOUR
EXPOSURE AT 800 C (mg/cm²)

ALLOY	ENVIRONMENT				
	A	B	C	D	E
310 STAINLESS STEEL	+2.5	-33.7	-20.8	-0.03	+0.03
ALLOY 800	+2.5	-13.3	-21.1	-1.06	+1.08

Environments:

A = Ar + 20%CO₂

B = Ar + 20%CO₂ + 0.25%Cl₂

C = Ar + 20%CO₂ + 0.25%Cl₂ + 2%H₂O

D = Ar + 20%CO₂ + 0.5%HCl

E = Ar + 20%CO₂ + 0.5%HCl + 2%H₂O

The test environments all contain a high concentration of CO₂, since this is a major combustion product from coal, and oxidation of these alloys in CO₂ is known to differ from that in pure oxygen. The effects of additions of chlorine and hydrogen (as water vapor or HCl) on the corrosion rates are investigated. The alloys experience a small weight gain after exposure to the environment containing only CO₂ as expected. The addition of 0.25%Cl₂ to the gas mixture causes a large weight loss due to formation of volatile chloride corrosion products. Cl₂ is more aggressive to the metals than the HCl which would be expected to be present in the coal combustion environments because of the hydrogen contents of the coals. Replacing the Cl₂ with HCl reduces the amount of weight loss sub-

stantially as shown for environment D. However, adding sufficient hydrogen to the environment as water vapor to convert all of the Cl_2 to HCl does not substantially reduce the rate of attack as shown for environment C. Adding water to the HCl containing environment changes the weight loss to a weight gain as shown for environment E. Thermodynamic calculations performed to support these experiments are consistent with the experimental results in that the chlorine potential in the HCl containing environment is approximately three orders of magnitude lower than that in the Cl_2 containing environment, so that much less corrosion would be expected. However, the calculations predict that the addition of water vapor to the environment should have a similar effect, since the Cl_2 would be expected to react to form HCl . The discrepancy indicates that the kinetics of the gas phase reactions also influence the corrosion kinetics.

These alloys are also known to be susceptible to internal corrosion in chlorine containing environments, and metallographic evaluation of the specimens is in progress to evaluate the effects of these changes on the extent and morphology of the internal corrosion. These results will be reported in the next progress report. This furnace will also be used to investigate the effects of additional oxygen and sulfur on the attack of these alloys by adding additional O_2 and SO_2 to the gas mixtures. The results will then be compared with those obtained in the coal combustion furnace and to the coupons recovered from operating boilers to aid in the interpretation of these results.

2. Evaluation of Test Coupons from Operating Plants

Negotiations are still ongoing with several companies regarding placement of test coupons and/or recovery of tubing which had seen long term, well documented service. We are still seeking to place coupons in a fluidized bed combustion unit. In addition, several test coupons which were placed in a pulverized coal combustion unit last spring will be recovered during the spring outage of that power plant during the coming quarter.

CONCLUSION AND RECOMMENDATION

Examination of exposed tubes recovered from boilers burning coals with chlorine contents ranging from 0.07% to 0.5% Cl have not indicated that the higher chlorine coals cause more severe corrosion of either superheater tubes or water wall tubes.

Laboratory furnace tests of four common boiler materials are in progress. Initial tests in combustion gases from IBC-101 and IBC109 coals burned with at 700 and 800°C indicate less corrosion with the higher chlorine IBC-109 coal than with the higher sulfur IBC-101 coal over 24 hours. Tests performed in reagent Ar-CO₂ gas mixtures containing Cl₂ or HCl indicate that the HCl is much less aggressive than the Cl₂ to the high alloyed steels at 800°C. Evaluation of internal attack produced in these environments is still under way. Further testing at lower temperatures and in more complex environments will be performed in the next quarter.

PROJECT MANAGEMENT REPORT
December 1, 1991 through February 29, 1992

Project Title: HIGH TEMPERATURE CORROSION DURING USE OF CHLORINE
CONTAINING COAL

Principal Investigator: Michael McNallan, University of Illinois at Chi-
cago

Other Investigators: Steven Danyluk, J.E. Indacochea, University of
Illinois at Chicago

Project Monitor: Dr. Dan Banerjee, CRSC

COMMENTS

The expenditures are proceeding approximately on schedule. It has been necessary to estimate some of the charges because the formal contract was received at the University of Illinois in January, 1992, and the accounting process is still catching up with the charges which were incurred while the contract was being negotiated.

This project is funded by the U. S. Department of Energy (METC) and by the Illinois Department of Energy and Natural Resources as part of their cost-shared program.

Projected and Estimated Expenditures by Quarter

Quarter*	Types of Cost	Direct Labor	Materials & Supplies	Travel	Major Equipment	Other Direct Costs	Indirect Cost	Total
Sept. 1, 1991 to Nov. 30, 1991	Projected	6600	2000			1000	960	10560
	Estimated	6000	500			200	670	7370
Sept. 1, 1991 to Feb. 29, 1992	Projected	13200	4000	400		2000	1960	21560
	Estimated	13200	2000	400		500	1610	17710
Sept. 1, 1991 to May 31, 1992	Projected							
	Estimated							
Sept. 1, 1991 to Aug. 31, 1992	Projected							
	Estimated							

*Cumulative by quarter

COSTS BY QUARTER - EXHIBIT C

(Example)

HIGH TEMPERATURE CORROSION DURING USE OF CHLORING CONTAINING COAL

Months and Quarters

○ = Projected Expenditures -----

△ = Actual Expenditures _____

Total CRSC Award \$ 80226

- A. Research assistant employed
- B. Apparatus assembled and constructed
- C. Laboratory corrosion testing
- D. Evaluation of coupons from laboratory tests
- E. Install coupons in service sites
- F. Recover coupons from service sites
- G. Evaluation of coupons from service sites
- H. Technical and Project Management reports prepared and submitted.

END

**DATE
FILMED**

9/02/92