AIM

Association for Information and Image Management

1100 Wayne Avenue, Suite 1100
Silver Spring, Maryland 20910
301/587-8202

Centimeter

Inches

MANUFACTURED TO AIM STANDARDS
BY APPLIED IMAGE, INC.

1 of 2

WSRC-TR-93-007
TASK 89-023-1

EMT

EQUIPMENT AND
MATERIALS TECHNOLOGY

Keywords: Process Water System
IGSCC
Stainless Steel
Fracture
PTERM
CAMEL

Retention - Permanent

**REACTOR MATERIALS PROGRAM -
Weldment Component Toughness of SRS PWS Piping Materials (U)
Task Number: 89-023-1**

By

R. L. Sindelar
R. L. Sindelar

Issued: February 1993

Authorized Derivative Classifier

W. L. Daugherty
W. L. Daugherty

4 Mar 93
Date

SRTC

SAVANNAH RIVER TECHNOLOGY CENTER, AIKEN, SC 29808
Westinghouse Savannah River Company
Prepared for the U. S. Department of Energy under Contract DE-AC09-89SR18035

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Project: REACTOR MATERIALS PROGRAM
Document: WSRC-TR-93-007
Title: REACTOR MATERIALS PROGRAM - Weldment
Component Toughness of SRS PWS Piping Materials (U)
Task: 89-023-A-1
Task Title: Measure Mechanical Properties of Moderator Piping

Approvals

D. M. Barnes, Technical Reviewer
SRTC - Materials Technology
Date: 3/3/93

G. R. Caskey Jr., Technical Reviewer
SRTC - Materials Technology
Date: 3/4/93

N. G. Awadalla, Manager
SRTC - Materials Technology
Date: 3/8/93

T. L. Capeletti, Manager
SRTC - Materials Technology
Date: 3/8/93

EXECUTIVE SUMMARY

Weld Fusion Line Fracture Toughness

The mechanical properties of austenitic stainless steel materials from the reactor systems in the unirradiated (baseline) and the irradiated conditions have been developed previously for structural and fracture analyses of the pressure boundary of the SRS reactor Process Water System (PWS) components.¹ Individual mechanical specimen test results were compiled into three separate weldment components or regions, namely, the base, weld, and weld heat-affected-zone (HAZ), for two orientations (L-C and C-L)² with respect to the pipe axis of the source materials and for two test temperatures of 25 and 125°C. Twelve separate categories were thus defined to assess the effect of test conditions on the mechanical properties and to facilitate selection of properties for structural and fracture analyses. The testing results show high fracture toughness of the materials and support the demonstration of PWS pressure boundary structural integrity under all conditions of reactor operation.

The fracture toughness of a fourth weldment component, namely, the weld fusion line region, has been measured to evaluate the potential for a region of low toughness in the interface between the Type 308 stainless steel weld metal and the Type 304 stainless steel pipe. The testing details and results of the weld fusion line toughness are contained in this report.

¹ The mechanical properties were developed from testing of archival SRS reactor piping system materials and are summarized in technical reports WSRC-TR-91-10, providing properties for the PWS piping and components (unirradiated material condition), and WSRC-TR-91-11, providing properties for the reactor tank (irradiated material condition). The piping and tank were constructed from Type 304 stainless steel with Type 308 stainless steel weld filler; replacement PWS piping material is Type 304L stainless steel with Type 308L stainless steel weld filler. The mechanical testing results in report WSRC-TR-91-10 also included a heat of Type 304L stainless steel plate material (non-archival) along with Type 304 and 308 stainless steel from archival piping materials. In addition, the fracture toughness of CF-8 castings were compiled from literature results for analysis of the PWS cast piping (included in WSRC-TR-92-10), valve bodies (WSRC-TR-92-440), pump casings (WSRC-TR-92-12), Andale strainers (WSRC-TR-92-539), and plenum inlet nozzles (WSRC-TR-92-441).

² designation from American Society for Testing and Materials (ASTM) - Standard E399-90.

The elastic-plastic fracture toughness of the base, weld, HAZ, and weld fusion line regions of the archival PWS piping was measured by testing 0.4T planform compact tension C(T) specimens and performing J-R curve analyses (for both J_{deformation} and J_{modified} J-integral methods). Crack extension was evaluated by single-specimen unloading compliance methods. The J-R curves of the four weldment components are compared showing high initiation toughness for ductile tearing and high resistance to crack extension for all the components. The fracture toughness parameters J_{Ic}, the J-integral value at the onset of stable crack extension by ductile tearing, and T, the average tearing modulus, calculated from the J-R curve data³ are summarized in the table below for the four weldment components in the L-C orientation at 25°C, and show no low toughness in the weld fusion line region compared to the other components.

Elastic-Plastic Toughness - 20% Side-Grooved 0.4T C(T) Specimens, L-C Orientation (from J _{deformation} -R curve analysis with a power law fit to the exclusion line data)		
Weldment Component	J _{Ic} : in-lb/in ² (kJ/m ²)	Average Tearing Modulus
Base - Archival PWS piping Ring 6, Side A (Ave. of three specimens)	3990 (699)	234
Weld - Archival PWS piping Rings 2, 5, & 8 (Ave. of six specimens)	2380 (417)	244
HAZ - Archival PWS piping Ring 6, Side A (Ave. of two specimens)	2920 (511)	165
Weld Fusion Line - Archival PWS piping Ring 6, Side A (Specimen 6HAOR5)	3440 (602)	256

Microstructural examination of the archival materials by optical metallography did not show any evidence for a reduced material fracture toughness at the weld metal/base metal interface which is consistent with the mechanical testing results.

Orientation Dependency of the Mechanical Properties

The anisotropy in the toughness of the Type 304 stainless steel in the PWS pressure boundary has been characterized in this report. A strong dependency of the Charpy V-notch absorbed energy and fracture toughness on the orientation of the fracture plane with respect to the axis of the pipe (i.e., the rolling direction of the original plate) is observed in the results from both the baseline and irradiated materials. The C-L orientation yields lower toughness than the L-C orientation; the tensile properties (strength and ductility), however, do not show an orientation dependency. Irradiation hardened the materials and lowered the toughness but did not alter the orientation dependency pattern. The material microstructure and the fracture surfaces of several C(T) specimens were characterized to investigate the cause of the orientation dependency of toughness. The toughness is most likely influenced by minor modulations of the major alloying components that arise from the original dendritic structure and are not completely eliminated during subsequent thermo-mechanical processing of the plate. The orientation dependency of fracture toughness with a corresponding microchemical modulation are not unique to the archival SRS materials but were observed in a recent heat of Type 316LN stainless steel.

³ the analysis of the weld fusion line region was per ASTM Standards E1152-87 and E813-89; the analyses of the base, weld, and HAZ regions was performed to previous editions of these standards (see WSRC-TR-91-10).

TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY.....	i
TABLE OF CONTENTS.....	iii
LIST OF TABLES	iv
LIST OF FIGURES	v
 1.0 INTRODUCTION.....	 1
1.1. Weld Fusion Line Fracture Toughness	1
1.2. Orientation Dependency of Fracture Toughness.....	1
 2.0 WELD FUSION LINE COMPONENT - MECHANICAL TEST RESULTS.....	 2
2.1 Process Water System Materials and Baseline Mechanical Testing Overview.....	2
2.2 Weld Fusion Line Component Compact Tension (C(T)) Specimen Testing.....	3
2.2.1 C(T) Specimen Design and Placement of the Weld Fusion Line C(T) Specimens with Respect to the Circumferential Pipe Weldment.....	3
2.2.2 Weld Fusion Line Fracture Toughness Results.....	4
2.3 Elastic-Plastic Fracture Toughness - Comparison of Weldment Components.....	4
2.3.1 Comparison of Base, Weld, HAZ, and Weld Fusion Line Regions.....	4
2.3.2 Comparison Weldment Components' Microstructure.....	6
 3.0 ORIENTATION DEPENDENCY OF MECHANICAL PROPERTIES.....	 6
3.1. Summary of Results of Tensile, CVN, and C(T) Testing.....	6
3.2. Microstructural Characterization of Ring 7, Side A Material.....	11
3.3. Fracture Surface Examination of Ring 7, Side A C(T) Specimens.....	17
3.4. Discussion on Orientation Dependency of Fracture Toughness.....	17
3.5. Application of Elastic-Plastic Fracture Toughness Properties in PWS Fracture Analyses - Recommendations.....	17
 4.0 ACKNOWLEDGMENTS.....	 20
 5.0 REFERENCES.....	 21
 ATTACHMENT 1	

LIST OF TABLES

Table	Page
1 Elastic-plastic fracture toughness parameters reported by ORNL in the weld fusion line testing	4
2 Comparison of elastic-plastic toughness of the base, weld, HAZ, and weld fusion line regions of ring 6, side A archival piping materials.....	6
3 Unirradiated tensile specimen test results.....	8
4 Irradiated tensile specimen test results.....	8
5 Unirradiated Charpy V-notch results.....	9
6 Irradiated Charpy V-notch results.....	9
7 Unirradiated fracture toughness results.....	10
8 Irradiated fracture toughness results.....	10

LIST OF FIGURES

Figure	Page
1 Comparison of J-R curves of base, weld, HAZ and weld fusion line regions of ring 6, side A archival piping materials.....	5
2 Low Magnification Ring 7, Side A material showing the ring 7 weld and the weld fusion line, HAZ, and base metal.....	12
3 High magnification in the HAZ of Ring 7, side A showing a delta ferrite stringer and intergranular carbide precipitation.....	12
4 High magnification montage of the ring 7, side A material showing the weld, weld fusion line, HAZ, and base metal regions.....	13
5 a) Optical micrograph of ring 7, side A base material plane of fracture for the C-L orientation; b) Optical micrograph of ring 7, side A base material plane of fracture for the L-C orientation.....	16
6 Fractographs of broken C(T) specimens cut from SRS archival piping ring 7, base and HAZ components: a) 7HA12; b) 7HA4; c) 7BA15S; and d) 7BA18S.....	18
7 Optical micrograph of Type 316LN stainless steel (reference heat #18474) illustrating flow lines on the planes perpendicular to the plate surface: a) in the longitudinal direction, parallel to the rolling direction of the plate; and b) in the transverse direction, perpendicular to the rolling direction of the plate.....	19

1.0 INTRODUCTION

1.1 Weld Fusion Line Fracture Toughness

The mechanical properties of the materials of the pressure boundary of the reactor Process Water System (PWS) and their application to fracture analysis of the piping and reactor tank were reviewed in 1990 by the Department of Energy - Independent Review Committee (DIRC) on System Integrity [1]. The committee concluded the materials' fracture toughness in both the unirradiated and irradiated condition is high and does not pose a concern to the structural integrity of the pressure boundary.

Based on data generated for the Nuclear Regulatory Commission in the Degraded Piping Program [2], an issue was raised by the DIRC [1] that there may be a potential for lower toughness at the region between the weld metal and base metal interface than the that at the base, weld, and weld heat-affected-zone (HAZ) regions of the PWS piping measured in the Savannah River Technology Center (SRTC) Reactor Materials Program. The mechanical testing of a single-edge notch tension (SE(T)) specimen for weldment regions of Type 304 stainless steel joined with a shielded-metal arc weld (SMAW) and tested at 288°C showed crack propagation from the heat-affected zone to the weld fusion line [2]. The crack mouth opening with the crack at the fusion line was less than companion specimens with the cracks in the weld metal region the base metal region indicating the fusion line toughness was less than the toughness in those regions. A plan to address the DIRC issues following reactor restart was prepared by the Reactor Restart Division [3]; subsequently, a task activity to evaluate the weld fusion line fracture toughness was planned under the SRTC Reactor Materials Program [4]. This report provides the evaluation of the fracture toughness of the weld fusion line region and includes the results of fracture toughness testing and microstructural analysis to complete this task activity.

The elastic-plastic fracture toughness for the weld fusion line regions was measured by testing 0.4T planform compact tension C(T) specimens with the machine notch plane positioned as close to the weld metal/base metal interface as practicable. The testing of the weld fusion line fracture toughness with 0.4 C(T) specimens allows direct comparison to previous fracture toughness results from the baseline testing of base, weld, and HAZ regions [5] where elastic-plastic crack growth resistance or J-R curve analysis was performed for both $J_{\text{deformation}}$ and J_{modified} J-integral methods. The initiation toughness, J_{Ic} , and the tearing modulus, T, parameters are also computed in the analysis of the J-R curve data.

The weld fusion line region testing was performed as part of the SRTC Reactor Materials Program Task 89-023-1 [4] under RMP Specification SRP-SL-1111, Rev. 2 [6]. Attachment 1 is the letter report from the Fracture Mechanics Group of the Metals & Ceramics Division at Oak Ridge National Laboratory which contains the full details and results of the C(T) specimen preparation and testing to provide the fracture toughness of the weld fusion line region. Section 2 of this report contains a brief description of the mechanical testing of the archival piping materials and the details of the weld fusion line testing summarized from Attachment 1. Section 2 also contains the comparison of the weld fusion line results to the base, weld, and HAZ region results from the previous baseline testing.

1.2 Orientation Dependency of Fracture Toughness

Design safety review requirements for the coolant systems of commercial nuclear reactors address pressure boundary materials and system integrity [7]. In addition to pressure boundary material requirements specified by the ASME Boiler and Pressure Vessel Code Sections II and III [8], and, Title 10 of the Code of Federal Regulations - Part 50 [9], the Standard Review Plan [7] requires acceptability of the materials to be based on standard practice and engineering judgment including

consideration of nonisotropic characteristics. The mechanical properties of the SRS reactor pressure boundary materials show a strong dependency of fracture toughness on orientation in both the unirradiated and irradiated conditions [5, 10]. Section 3 of this report contains a summary of the mechanical testing results of the materials in the unirradiated and irradiated conditions. Section 3 also contains the results of a recent microstructural investigation of the archival materials providing insight as to the cause of the anisotropy in the mechanical properties. The anisotropy in properties is considered in the fracture analyses of the PWS piping and reactor tank.

2.0 WELD FUSION LINE COMPONENT - MECHANICAL TEST RESULTS

2.1 Process Water System Materials and Baseline Mechanical Testing Overview

The materials of construction of the pressure boundary of the reactor primary coolant system (Process Water System) including the reactor tank is American Iron and Steel Institute (AISI) Type 304 stainless steel joined by inert-gas-shielded metal arc (GMA) welding with Type 308 stainless steel filler wire [11]. Replacement piping in the PWS is Type 304L stainless steel with Type 308L filler [11]. The Y and T castings at the heat exchanger inlet and outlet piping, respectively, the pump casings, the valve bodies, and the plenum inlet nozzles are constructed of cast CF-8 stainless steel. Databases for the reactor Process Water System (PWS) pressure boundary materials [5] have been developed from archival piping materials [12] and also from the archival materials following neutron irradiation at temperature and displacement damage conditions of the reactor tank sidewalls [10, 13] for structural and fracture analyses of the pressure boundaries of the PWS components[†] [14-19].

The machining and testing of the archival piping materials in the unirradiated or baseline condition were performed by Materials Engineering Associates (MEA) in Lanham, Maryland under the direction of the RMP [20, 21]. The mechanical test specimen types were tensile (T), Charpy V-notch (CVN), and compact tension (C(T)) specimens machined from the three different weldment components: base material; weld material; and weld heat-affected-zone (HAZ) material [22]. The mechanical specimens from the archival piping were machined in the ASTM C-L and L-C orientations to allow comparison of the mechanical response for the cases of postulated flaws oriented parallel and perpendicular, respectively, to the pipe axis or rolling direction of the original plate.

The complete details of placement of the mechanical specimens with respect to the circumferential pipe weldment to measure properties in the "base," "weld," and "HAZ" regions are provided in reference 22. The weld fusion line specimen tests are compared to the base, weld, and HAZ regions with the C(T) specimens in the L-C orientation in Section 2.3 of this report. The placement of the L-C orientation C(T) specimens in the base, weld, and HAZ regions was such that the machine notch plane, the fatigue pre-crack, and the crack extension in the testing were completely contained in the respective regions. The placement of the L-C orientation C(T) specimens to measure the fracture toughness of the HAZ region was such that the notch plane, the fatigue pre-crack, and the crack extension in the testing were at a nominal distance of 5/16" from the weld fusion line at the inside diameter of the piping [figure 3.18 of ref. 22]. In contrast, the weld fusion line specimens were placed such that the notch plane bisected the weld fusion line of the V-shaped weld deposit (see section 2.2.1).

[†]The PWS heat exchanger tubing provides an interface pressure boundary between the PWS and the Cooling Water System. The material of construction of the tubing of the heat exchangers presently installed in K-reactor is either Type 316L stainless steel or Sea Cure®, a trade name for a commercial ferritic stainless steel product. An evaluation of the structural margins of the heat exchanger tubing are contained in report WSRC-TR-92-72.

2.2 Weld Fusion Line Component Compact Tension (C(T)) Specimen Testing

Fracture toughness measurements of a fourth weldment component, namely, the weld fusion line region, between the Type 308 stainless steel weld deposit and the Type 304 stainless steel pipe material, have been performed. Attachment 1 contains the full details of specimen design, cutting, mechanical testing, and data processing to perform J-R curve analysis and measure the fracture toughness of the weld fusion line region. The discussion below summarizes the results of the weld fusion line testing for comparison to the previous test results for the base, weld, and HAZ regions.

Sections of piping for C(T) specimens for the weld fusion line testing were obtained from the archival pipe materials [12] and transmitted to ORNL for specimen preparation and mechanical testing. Three specimens for weld fusion line testing were machined from excess material of ring 6: 6HAOR5; 6HAOR6; and 6HAOR7 (see Appendix D of Attachment 1).

Prior to the fusion line testing, checkout testing of the software used by the Fracture Mechanics group of the Metals & Ceramics Division of ORNL was performed on load vs. displacement data from the testing of C(T) specimens by MEA. Specifically, data from specimen 8BB15 (L-C) was processed by ORNL (see Appendices B and C of Attachment 1) for comparison to the MEA results (Appendix A of Attachment 1 and reference 22). The value derived by ORNL for J_{IC} for with a power law fit to the $J_{modified}$ (or Ernst method) resistance curve data from the 8BB15 specimen is 921 kJ/m² and is 5% greater than the value of 878 kJ/m² reported by MEA in reference 22 using both loading and unloading compliance data to determine crack growth. The difference is not significant and is attributed to operator judgment in data processing. In addition, the checkout testing also included machining and data analysis of two other specimens of 8BB material, namely, specimen 8BBOR3 (L-C orientation) and specimen 8BBOR4 (C-L orientation). The results for J_{IC} from these tests (Appendix G of Attachment 1) are consistent with the results in the baseline testing [5, 22].

The following paragraphs briefly describe the design, machining, and testing results of the weld fusion line C(T) specimens by ORNL.

2.2.1 *C(T) Specimen Design and Placement of the Weld Fusion Line C(T) Specimens with Respect to the Circumferential Pipe Weldment*

The design of the 0.4T C(T) weld fusion line specimens (Appendix F to Attachment 1) is identical to the E399 SR 0.4T C(T) design [22] used in the Reactor Materials Program mechanical properties testing [5, 10]. The weld fusion line specimens were machined from the archival pipe material from ring 6, side A [12] such that the line defined by the root of the machine notch of the L-C orientation specimens bisected the line defined by the intersection of the weld and base metal of the circumferential weld. This was the only placement available to test the toughness of the weld fusion line region given the 0.4T C(T) planform specimen design and the V-shape of the weld metal deposit in the piping. The design is also appropriate to determine the fracture toughness of the piping material for the postulated case whereby an intergranular crack initiates in the weld heat-affected-zone (offset from the fusion line) and propagates into the weld fusion line region.

Sidegrooving promotes an even, parallel crack front to facilitate the determination of the crack extension in the C(T) testing [22]. This design with 20% sidegrooves was used for the testing of specimen 6HAOR5. Specimen 6HAOR6 did not contain sidegrooves providing less constraint which would allow crack extension to more readily follow the fusion line if the fusion line were a low toughness region. Appendix E of Attachment 1 contains a photographic record of the 6HAOR5, 6HAOR6, and 6HAOR7 specimens prior to testing which are etched to highlight the placement of the C(T) notch plane with respect to the weld fusion line. (Non-side-grooved specimen 6HAOR7 was not tested in this study and is reserved for checkout of the mechanical

testing facilities in the ORNL Metals & Ceramics Division hot cells prior to the testing of the HFIR 12M irradiated mechanical specimens).

2.2.2 Weld Fusion Line Fracture Toughness Results

The fracture toughness results in Table 1 below are the ORNL results (see Appendix G of Attachment 1) from the testing of the weld fusion line specimens from ring 6, side A material with 20% sidegrooving and no sidegrooving. The parameters were obtained from $J_{\text{deformation}}$ -R curve analysis with a power law fit to the exclusion line data per ASTM standard E813-89. The non-side-grooved specimen has higher toughness than the side-grooved specimen as measured by J_{IC} . These results show that the fusion line region has high toughness; the effect of lower toughness with sidegrooving is consistent with results observed in the baseline testing program [5, 22].

Table 1 - Elastic-plastic fracture toughness parameters reported by ORNL in the weld fusion line testing (from Appendix G of Attachment 1).

Specimen Number	J_{IC} (kJ/m ²)	Tearing Modulus	ASTM Orientation	Side grooving (%)
6HAOR5	602	256	L-C	20
6HAOR6	868	227	L-C	0

2.3 Elastic-Plastic Fracture Toughness - Comparison of Weldment Components

2.3.1 Comparison of Base, Weld, HAZ, and Weld Fusion Line Regions

The mechanical properties from individual test specimens in the baseline and irradiated condition from the archival piping were previously reported in references 5, 10 and 13. Section 3 contains the average mechanical properties of the unirradiated and irradiated specimens from the archival piping materials.

A comparison of weld fusion line fracture toughness to the previous toughness results is made by comparing the $J_{\text{deformation}}$ -R curve analysis results of the 20% side-grooved C(T) specimens of the ring 6, side A material in the L-C orientation tested at 25°C. Specifically, the results from weld fusion line specimen 6HAOR5 are compared to specimens from the HAZ region (specimens 6HA18 and 6HA20 [5]) and the base region (specimens 6BA26, 6BA30, and 6BA34 [5]). Weld material from ring 6 was not measured in the baseline program [5]; instead, the average results from the weld material from rings 2, 5, and 8 (specimens 2W127, 2W131, 5W18, 5W21, 8W12, and 8W13 [5]) are used in the comparison. The J-R curves are shown in Figure 1. Table 2 gives the average elastic-plastic fracture toughness results from the J-R curve analysis of these specimens.

Figure 1 - Comparison of J-R curves of base, weld, HAZ and weld fusion line regions of ring 6, side A archival piping materials

Table 2 - Comparison of elastic-plastic toughness of base, weld, HAZ, and weld fusion line regions

Elastic-Plastic Toughness - 20% Side-Grooved 0.4T C(T) Specimens, L-C Orientation. (from J_{def} -R curve analysis with a power law fit to the exclusion line data)		
Weldment Component	J_{IC} : in-lb/in ² (kJ/m ²)	Average Tearing Modulus
Base (Ring 6, Side A) Ave. of three specimens	3990 (699)	234
Weld (Rings 2, 5, & 8) Ave. of six specimens	2380 (417)	244
HAZ (Ring 6, Side A) Ave. of two specimens	2920 (511)	165
Weld Fusion Line (Ring 6, Side A) Specimen 6HAOR5	3440 (602)	256

2.3.2 Comparison of Weldment Components' Microstructure

A microstructural characterization of several of the archival materials was previously performed from the remnants of the broken C(T) specimens from the baseline testing [23]. No evidence of local precipitation that could cause a local brittle zone at the interface was observed. Microstructural characterization of piping recently removed from K reactor was also performed and no evidence was observed for a low toughness region at the weld fusion line [24].

Additional microstructural characterization of the material from broken C(T) 7HA12 was performed in this present study; the results are summarized in Section 3.2. There is no second phase precipitation or inclusions at the fusion line and therefore no evidence for low toughness at weld fusion line region.

3.0 ORIENTATION DEPENDENCY OF MECHANICAL PROPERTIES

3.1 Summary of Results of Tensile, CVN, and C(T) Testing

The mechanical property testing of the unirradiated [5] and irradiated [10, 13] archival piping materials involved several experimentation variables including irradiation conditions (temperature, exposure level, exposure rate, and neutron energy spectrum), weldment component (base, weld, or HAZ), chemical composition, orientation, and test conditions (temperature, and testing apparatus). From the test parameters of temperature (25 and 125°C), orientation (L-C and C-L), and weldment component (base, weld, and HAZ), twelve different categories of properties are defined in the evaluation of the mechanical response of the archival piping materials in both the unirradiated and irradiated conditions to assess the effect of test conditions on the mechanical property results and to facilitate selection of properties for structural and fracture analyses. The results from the unirradiated mechanical property testing [5] show no significant effect of chemical composition on the strength or toughness response; similarly, the irradiated property testing [10, 13] shows no significant effect of composition on the response of the material to the low temperature neutron irradiation conditions.

The irradiated mechanical property results of the archival piping materials, along with the mechanical results of archival reactor vessel and thermal shield materials, are shown as a function of exposure level in references 10 and 13. A slight decrease in toughness was observed with displacement damage levels from 0.065 to 2.1 displacements per atom (dpa_{NRT}). The change in mechanical properties with displacement damage level for the archival piping specimens irradiated

in the UBR (0.065 dpa) and the HFIR (1.0 to 2.1 dpa) are secondary to the orientation effects on the mechanical response and are not addressed in this report.

The average tensile, impact, and elastic-plastic fracture toughness results for the twelve categories defined by weldment component, test temperature, and specimen orientation for the specimen testing are contained in Tables 2 through 7. The unirradiated and irradiated properties in these tables were obtained by averaging the combined set of individual specimen results from the unirradiated testing [5] and the UBR and HFIR 4M irradiated specimen testing [10, 13], respectively. The following discussion was also reported in reference 25.

Tensile Results. Tables 3 and 4 contain the average unirradiated and irradiated results from the testing of T specimens from the archival piping. A total of one to seventeen specimens were tested in each category of the unirradiated property results and a statistical analysis of the uncertainty in the sample mean is provided.

The unirradiated and irradiated strengths at the higher test temperature (125°C) were slightly lower than the corresponding strengths at the lower temperature (25°C). Ductility as measured by either total elongation or reduction in area showed little temperature dependence. No significant orientation effect on strength or ductility was observed for the L-C and C-L test directions in the unirradiated condition. The strength and ductility results from the irradiated weld component show slightly higher strength and lower ductility in the C-L orientation although there is insufficient data to evaluate the significance of the difference. Hardening due to irradiation is evident in all of the test data except for the strength of the weld metal at 125°C; the data in the weld material categories is solely from the low-exposure UBR irradiation.

Charpy V-Notch Results. Tables 5 and 6 contain the average unirradiated and irradiated results from the testing of CVN specimens from the archival piping. Irradiation reduced the energy absorption under impact loading, for all test temperatures, orientations, and weld components. The average energy absorption exceeded 50 ft-lbs showing a high toughness for all test conditions. All three material types (base, weld, and HAZ) show a temperature dependence with the lower impact energies at 25°C.

The unirradiated impact test results show a difference of 25 to 60% between the absorbed energies for the C-L and L-C for the base and HAZ components. No significant difference between the C-L and L-C results is shown for the weld component. Irradiation did not change the orientation dependency pattern. The irradiated test results also show the C-L orientation to yield lower absorbed energies than the L-C orientation for the base and HAZ components with differences of 27 to 39%.

Compact Tension Results. Tables 7 and 8 contain the average unirradiated and irradiated results from the testing of C(T) specimens from the archival piping. The average reductions in fracture toughness due to irradiation depended on the weldment component. The largest reductions in toughness occurred for the HAZ specimens. The average unirradiated toughness results for the companion specimens (2W132 and 2W164) of the irradiated weld C(T) specimen (2W2, results listed in Table 8) are a J_{IC} of 1880 in-lb/in² with a tearing modulus of 249.

The unirradiated test results show a difference of 33 to 84% between the J_{IC} values for the C-L and L-C orientations for the base and HAZ components. No significant difference between the C-L and L-C results is shown for the weld component. Irradiation did not change the orientation dependency pattern. The irradiated test results also show the C-L orientation to yield lower J_{IC} values than the L-C orientation for the base and HAZ components with differences of 59 to 79%.

Table 3 - Unirradiated Tensile Specimen Test Results (from refs. 5, 25)

Material	Test Temperature (°C)	Sample ASTM Orientation	Engineering Yield Strength (ksi)	Engineering Tensile Strength (ksi)	Total Elongation* (%)	Reduction in Area (%)
Base	25	L-C	38 (±2)**	91 (±3)	88 (±6)	73 (±6)
		C-L	38 (±2)	92 (±3)	85 (±8)	71 (±5)
Base	125	L-C	29 (±2)	70 (±2)	61 (±3)	77 (±1)
		C-L	29 (±2)	71 (±1)	62 (±3)	73 (±1)
HAZ	25	L-C	-	-	-	-
		C-L	51 (±2)	95 (±3)	86 (±2)	71 (±2)
HAZ	125	L-C	-	-	-	-
		C-L	43 (***)	74 (***)	60 (***)	67 (***)
Weld	25	L-C	55 (±6)	90 (±5)	48 (±10)	64 (±8)
		C-L	57 (±8)	90 (±2)	58 (±30)	57 (±22)
Weld	125	L-C	46 (±2)	72 (±2)	37 (±5)	68 (±12)
		C-L	-	-	-	-

*: Gage length = 0.80 inch

** : Number in parentheses is the 95% confidence interval for sample mean

***: High standard deviation of the sample mean due to small sample size

Table 4 - Irradiated Tensile Specimen Test Results (from refs. 10, 13, 25)

Material	Test Temperature (°C)	Sample ASTM Orientation	Engineering Yield (0.2%) Strength (ksi)	Engineering Tensile Strength (ksi)	Total Elongation* (%)	Reduction in Area (%)
Base	25	L-C	-	-	-	-
		C-L	-	-	-	-
Base	125	L-C	72.9 (2)**	85.0	52.6	68.5
		C-L	74.5 (2)	86.4	37.2	73.5
HAZ	25	L-C	-	-	-	-
		C-L	-	-	-	-
HAZ	125	L-C	81.2 (1)	88.6	NR	NR
		C-L	-	-	-	-
Weld	25	L-C	84.8 (4)	104.3	41.0	60.9
		C-L	93.6 (4)	107.2	32.2	52.8
Weld	125	L-C	55.9 (2)	64.6	36.0	72.6
		C-L	60.2 (2)	65.2	32.0	59.3

*: Gage length = 0.8 inch

** : The number in parentheses is the number of specimens in the sample

NR = Not Reported

Notes: 1) Twelve Weld T specimens in the L-C and C-L orientations were irradiated in the UBR and tested at 25 or 125°C [6]. Four Base specimens and one HAZ specimen were irradiated in the HFIR and tested at 125°C.

2) The range of Young's Modulus for the HFIR 4M specimens is 27.3 to 36.1 x 10⁶ psi [6].

Table 5 - Unirradiated Charpy V-Notch Test Results (from refs. 5, 25)

Material	Test Temperature (°C)	Sample ASTM Orientation	Energy Absorption (ft-lbs)	Lateral Expansion (mils)
Base	25	L-C	149 (±7)*	80 (±4)
		C-L	116 (±5)	83 (±5)
Base	125	L-C	229 (±14)	87 (±2)
		C-L	128 (±11)	77 (±2)
HAZ	25	L-C	136 (±8)	80 (±2)
		C-L	95 (±13)	73 (±6)
HAZ	125	L-C	188 (±33)	85 (±3)
		C-L	101 (±12)	81 (±2)
Weld	25	L-C	113 (±7)	84 (±7)
		C-L	118 (±27)	85 (±3)
Weld	125	L-C	158 (±39)	79 (±6)
		C-L	175 (±16)	83 (±2)

*: Number in parentheses is the 95% confidence interval for the sample mean

Table 6 - Irradiated Charpy V-Notch Results (from refs. 10, 13, 25)

Material	Test Temperature (°C)	Sample ASTM Orientation	Energy Absorption (ft-lbs)	Lateral Expansion (mils)
Base	25	L-C	83 (3)*	67
		C-L	63 (3)	50
Base	125	L-C	94 (4)	80
		C-L	71 (4)	66
HAZ	25	L-C	80 (34)	59
		C-L	54 (3)	43
HAZ	125	L-C	84 (4)	66
		C-L	63 (3)	56
Weld	25	L-C	64 (21)	50
		C-L	-	-
Weld	125	L-C	87 (4)	77
		C-L	78 (3)	65

* The number in parentheses is the number of specimens in the sample. The results for the **Base**, **HAZ**, and **Weld**, L-C and C-L orientations are the average of the properties of eighty-one UBR and five HFIR 4M data. The 25°C results are from UBR data only. Of the five HFIR data at 125°C, one datum each is in the **Base** L-C and C-L and the **Weld** L-C categories; two data are in the **HAZ** L-C category.

Table 7 - Unirradiated Fracture Toughness Results (from refs. 5, 25)

Material	Test Temperature (°C)	Sample ASTM Orientation	J _{IC} - Deformation J Power Law Fit (in-lb/in ²)	Tearing Modulus (T)
Base	25	L-C	3380 (±450)*	218 (±23)
		C-L	2420 (±170)	186 (±21)
Base	125	L-C	3310 (±310)	254 (±21)
		C-L	1930 (±190)	218 (±17)
HAZ	25	L-C	2840 (±450)	178 (±27)
		C-L	1790 (±300)	151 (±35)
HAZ	125	L-C	3060 (**)	190 (±21)
		C-L	1250 (**)	155 (**)
Weld	25	L-C	2380 (±420)	244 (±48)
		C-L	2280 (**)	181 (**)
Weld	125	L-C	2780 (**)	300 (±70)
		C-L	3070 (**)	253 (±97)

*: Number in parenthesis is the 95% confidence interval of the mean

**: High standard deviation of the sample mean due to small sample size

Table 8 - Irradiated Fracture Toughness Results (from refs. 10, 13, 25)

Material	Test Temperature (°C)	Sample ASTM Orientation	J _{IC} - Deformation J Power Law Fit (in-lb/in ²)	Tearing Modulus (T)
Base	25	L-C	-	-
		C-L	-	-
Base	125	L-C	1730 (3)*	127
		C-L	942 (2)	70
HAZ	25	L-C	-	-
		C-L	-	-
HAZ	125	L-C	982 (2)	76
		C-L	428 (2)	18
Weld	25	L-C	-	-
		C-L	-	-
Weld	125	L-C	805 (1)	77
		C-L	-	-

* The number in parentheses is the number of specimens in the sample.
The results are the average of the properties of the HFIR 4M data

3.2 Microstructural Characterization of Ring 7, Side A Material

A detailed investigation of the influence of the second phase particle distribution in causing the orientation effects on the toughness of the archival piping materials was performed in reference 23. It was concluded that there was no correlation between the distribution of the particles and the fracture toughness of the material.

A further investigation of the microstructure was pursued to determine the origin of the orientation dependency. Compact Tension specimen 7HA12 (C-L, 125°C test) had the lowest fracture toughness of the unirradiated materials with a J_{IC} of 875 in-lb/in² and a tearing modulus of 121 ($J_{deformation}$, power law fit to J-R curve data). The average fracture toughness results from specimens 7HA3 and 7HA4, the corresponding 7HA L-C specimens, are a J_{IC} of 3660 in-lb/in² and a tearing modulus of 200. This difference in fracture toughness results was the largest among the unirradiated materials. The broken C(T) remnants from ring 7, side A materials were therefore selected for additional optical metallography and fractography examination.

Optical metallography was performed on the C(T) half remnant of specimen 7HA12. The specimen was polished down to 0.3 μ m diamond paste and successively etched with Vilella's Reagent and Glyceregia followed by repetition of the polish and etch sequence as needed to highlight the grain boundaries and second phase particles. Figure 2 shows a low magnification optical micrograph of the plane of fracture of the C(T) specimen of 7HA material with a C-L orientation. The microstructure shows stringers of second phase particles with the long axis parallel to the pipe axis or rolling direction of the original plate. In addition, "flow lines" parallel to the rolling direction are observed in the low magnification micrograph. Figure 3 is a high magnification optical micrograph of the HAZ region at the mid-point region of the piping wall thickness and shows a delta ferrite stringer and intergranular chromium carbide precipitation. Figure 4 shows a high magnification optical montage from the weld region through the weld interface region, HAZ, and base metal regions at the mid-point region of the piping wall thickness. Intergranular precipitation is observed at distances from approximately 0.1 to 0.2 inches from the weld fusion line.

Figure 2 - Low Magnification Ring 7, Side A material showing the ring 7 weld and the weld fusion line, HAZ, and base metal.

Figure 3 - High magnification in the HAZ of Ring 7, side A showing a delta ferrite stringer and intergranular carbide precipitation.

Figure 4 - High magnification montage of the ring 7, side A material showing the weld, weld fusion line, HAZ, and base metal regions.

Figure 4 (cont'd)

Characterization of the microstructure of the ring 7, side A material was performed [26] per ASTM E1268-88 [27]. The C-L plane of fracture has an oriented microstructure with high-aspect ratio delta ferrite stringers and elongated, aligned discrete particles. The average number of feature interceptions for test lines perpendicular to the pipe axis or rolling direction is 1.88 ± 0.464 features/mm; the average number of feature interceptions for test lines parallel to the rolling direction is 0.500 ± 0.206 . The degree of orientation is 0.64. The average spacing or perpendicular distance between the elongated features is $1/1.88$ mm or $530 \mu\text{m}$. The L-C plane of fracture for the ring 7, side A material does not have an oriented microstructure with respect to the second phase particles.

Characterization of the flow line features in the plane of fracture for the 7HA12 specimen was also performed. The flow line features in the microstructure were highlighted with a nitric and hydrochloric acid etch. Figures 5a and 5b show the planes for fracture in the base material region for the C-L and L-C orientations, respectively. The average spacing of the flow lines, calculated by the inverse of the number of interceptions of the flow lines per length of test line on the C-L plane for fracture, is approximately $40 \mu\text{m}$. It is noted that the images of the flow line features are diffuse and that some flow line features are more pronounced than others; therefore, quantification of the spacing is only approximate. It is also noted that the flow lines on the C-L plane are several times longer than the those on the L-C plane which is consistent with the interpretation that a residual dendritic structure is aligned with the rolling direction of the plate used in the fabrication of the piping.

Figure 5a - Optical micrograph of ring 7, side A base material plane of fracture for the C-L orientation.

Figure 5b - Optical micrograph of ring 7, side A base material plane of fracture for the L-C orientation.

3.3 Fracture Surface Examination of Ring 7, Side A C(T) Specimens

Fractographs of the broken C(T) specimens from the base and HAZ components of the ring 7, side A material for the L-C and C-L orientations are shown in Figures 6a-d. Both the HAZ and base component specimens show a "channel" morphology to the ductile rupture surface for the C-L orientation whereas the L-C orientation exhibits an equiaxed ductile rupture. The channels in the HAZ C-L specimen are slightly more pronounced than the base L-C specimen. The average ridge-to-ridge spacing of the channels in both the base and HAZ C-L specimen fracture surfaces (Figures 6a and 6c) is approximately 90 μm .

3.4 Discussion on Orientation Dependency of Fracture Toughness

The strong dependency of fracture toughness on the orientation with respect to the rolling direction of the austenitic stainless steel plate was also observed in a recent heat of Type 316LN stainless steel. Mechanical testing of C(T) specimens identical in design to the E399 SR design were cut from Type 316LN piping materials and tested at Oak Ridge National Laboratory as part of the pipe test program [28]. The fracture toughness test results for companion specimens of base component specimens, in the L-C and C-L orientations, tested at 110°C, were a J_{IC} of 3040 in-lb/in² with a tearing modulus of 163 (L-C orientation) and a J_{IC} of 988 in-lb/in² with a tearing modulus of 95 (C-L orientation) [28], respectively. Figures 7a and 7b show flow lines from a plate of Type 316LN stainless steel which was also part of the test program.

Flow lines have also been observed in 21Cr-6Ni-9Mn, 19Ni-18Cr, and Type 304L stainless steels and have been shown to correspond to modulation in microchemistry [29 and 30]. The location of flow lines observed in both a hot rolled bar and a high energy rate forging of Type 304L stainless steel were shown to correlate to areas enriched in chromium and iron and depleted in nickel by approximately 1 wt.% for each of the respective constituents [30]. It is interesting to note that flow lines were not observed in a hot cross rolled plate of Type 304L stainless steel [30].

Figure 6 - Fractographs of broken C(T) specimens cut from SRS archival piping ring 7, base and HAZ components: a) 7HA12; b) 7HA4; c) 7BA15S; and d) 7BA18S. Note the channel morphology of the ductile rupture surface for the C-L orientation for both the base and HAZ specimens.

Figure 7 - Optical micrographs of Type 316LN stainless steel (reference heat #18474) illustrating flow lines on the planes perpendicular to the plate surface: a) in the longitudinal direction, parallel to the rolling direction of the plate; and b) in the transverse direction, perpendicular to the rolling direction of the plate.

The patterns observed in the optical micrographs and on the fracture surfaces of the base and HAZ component specimens of the ring 7, side A material suggest that the weakest fracture path in the microstructure was established during solidification. The normal dendritic solidification process for a stainless steel of 9.35 % Ni and 18.65 % Cr will tend to develop ferrite and modulations in the Ni/Cr ratio [31]. The extent of these effects will depend on the specific details of the casting process and the location of the material within the ingot - top, bottom, outer surface or interior. As expected, ferrite stringers and flow lines were not prevalent in every specimen tested in this study, although all specimens were of similar composition. Ordinarily, the times and temperatures encountered in thermomechanical processing are not sufficient to homogenize the microstructures formed during solidification. Consequently, the thermomechanical processing of the steel to form the pipe leads to an oriented pattern of ferrite stringers and flow lines such as those seen in the micrographs. These features are reflected in the elongated "channel-like" dimples observed on the fracture surfaces.

Fracture properties are markedly more sensitive to orientation and segregation effects than either tensile or impact properties. The data presented herein and that reported by Haggag [28] for Type 316LN stainless steel shows a pronounced orientation dependence for fracture properties with no corresponding orientation dependence of the tensile properties. Irradiation of the Type 304 specimens, up to 2.1 dpa at 155 °C, did not alter the effect of orientation on the fracture toughness response. This is expected as the irradiation conditions of time, temperature, and dpa do not cause long range rearrangement of the microchemical and microstructural features in Type 304 stainless steel.

3.5 Application of Elastic-Plastic Fracture Toughness Properties in PWS Fracture Analyses - Recommendations

The application of fracture toughness properties to the elastic-plastic fracture mechanics analysis of the reactor tank in the development of the acceptance criteria [32] is conservative as noted by the DIRC [1]. The lower bound toughness results from the irradiated C(T) specimens in the low toughness orientation (C-L) were applied in the analyses without regard for orientation of postulated flaws [32]. It is recommended that the orientation of flaw with respect to the rolling direction of the plates used to construct the tank be considered in applying fracture toughness properties [10] in flaw-specific analyses [32] to allow a more accurate evaluation of the safety margins. Flaws oriented parallel to the rolling direction of the plate corresponds to the C-L specimen orientation.

The fracture analysis methodology applied to circumferential flaws in the development of the acceptance criteria [14] for the PWS piping involves a plastic collapse criterion modified by a pipe size multiplier based on elastic-plastic fracture mechanics analysis. An extension of an engineering approach for strictly elastic-plastic fracture analysis of the large-diameter, thin-walled PWS piping has been recently completed [33]. It is recommended that elastic-plastic fracture analyses of the PWS piping consider the orientation of the flaw with respect to the pipe axis or rolling direction of the plate material in the application of toughness properties from the databases [5].

4.0 ACKNOWLEDGMENTS

The work of F. E. Odom, J. R. Durden, and C. N. Foreman in performing the optical and scanning electron microscopy for this report is gratefully acknowledged.

5.0 REFERENCES

1. "Savannah River Reactors - Primary System Integrity - Peer Review," by committee: P. G. Shewmon (chairman), S. Doctor, G. M. Wilcowski, and A. Zahoor, July 26, 1990, enclosure to letter: THE U. S. DEPARTMENT OF ENERGY (DOE) INDEPENDENT REVIEW COMMITTEE (DIRC) FOR SYSTEM INTEGRITY, Frank R. McCoy, III, Acting Director SR Restart Special Projects Office to James L. Gallagher, Vice President and General Manager - Reactor Restart, WSRC, August 21, 1990.
2. **NUREG/CR-4082**, "Degraded Piping Program -- Phase II," prepared by G. M. Wilcowski, et. al., Battelle Columbus Division, for Office of Nuclear Regulatory Research, U. S. Nuclear Regulatory Commission, published March 1989.
3. "WSRC Plan for Implementation of Recommendations of the DOE Independent Review Committee for System Integrity," September 20, 1990, enclosure to letter: DOE INDEPENDENT REVIEW COMMITTEE (DIRC) FOR SYSTEM INTEGRITY (U), J. L. Gallagher to Frank R. McCoy, III, OPS-RRD-900111, September 20, 1990.
4. **Task Technical Plan # 89-023-1**, "Reactor Materials Program Action Plan," SRTC - Nuclear Reactor Technology and Scientific Computations Department, December 1990.
5. **WSRC-TR-91-10**, "Reactor Materials Program - Baseline Material Property Handbook-Mechanical Properties of 1950's Vintage Stainless Steel Weldment Components (U)," K. J. Stoner, R. L. Sindelar, and G. R. Caskey Jr., Savannah River Laboratory, April 1991.
6. Reactor Materials Program Specification No. **SRP-SL-1111**, "Specification for Shipping, Testing, and Analysis of Irradiated Stainless Steel Mechanical and Corrosion Specimens," Rev. 2 October 31, 1991 (in Task 89-023-1 Files).
7. **NUREG 0800**, *Standard Review Plan (SRP) for the Review of Safety Analysis Reports for Nuclear Power Plants, Chapter 5, Reactor Coolant System and Connected Systems*, Office of Standards Development, U. S. Nuclear Regulatory Commission, Washington, D. C., June 1987.
8. American Society of Mechanical Engineers Boiler and Pressure Vessel Code, Sections II Section III, 1992 Edition, July 1, 1992.
9. Code of Federal Regulations: Energy - 10, The Office of the Federal Register National Archives and Records Administration, Revised as of January 1, U. S. Government Printing Office, Washington, D. C. (1993).
10. **WSRC-TR-91-11**, "Reactor Materials Program -- Mechanical Properties of Irradiated Types 304 and 304L Stainless Steel Weldment Components (U)," R. L. Sindelar and G. R. Caskey Jr., Savannah River Laboratory, December 1991.
11. PWS Piping: per Du Pont Specification SW 304M (Grade 304) in site piping specification 3018, P39.010 and P39.020, issued November 11, 1951 with latest revision January 24, 1957; site piping specification 4482, "Process and Service Piping P-Code P45 and P46;" and the current site piping specification: Engineering Requirement 15060-01-R, "Process and Service Piping," P-Codes P45 and P46." Tank Construction Records: 1) M & E Activities at New York Ship, "Part VII, Section IV - R, P, & L Main Tank," May 28, 1954 (SRP File Box M-898, formerly box 394); 2) M & E Activities at New York Ship, "Part VII Section III - R, P, L Bottom Tube Sheet Assemblies," April 28, 1954 (SRP File Box M898, formerly box 394); 3)

- M & E Activities at New York Ship "Part VIII "K" Unit Plenum Chamber, Top Tube Sheet and Tank Assembly," June 3, 1954 (SRP File Box M898, formerly Box 394); 4) NYX Fabrication Manual, "L" Unit B.T.S. and Tank" (SRP File Box 6493 Formerly Box 393); 5) NYX Fabrication Manual, "C" Unit (SRP File Box 6493, Formerly Box 393); 6) NYX Fabrication Manual, "General Information," (SRP File Box 6818, Formerly Box 392).
12. **DPST-88-1010**, "Reactor Materials Program - Materials Source History for Type 304 Stainless Steel Testing Program," K. J. Stoner, Savannah River Laboratory, December 1988.
 13. "Mechanical Properties of 1950's Vintage Type 304 Stainless Steel Weldment Components After Low Temperature Neutron Irradiation," R. L. Sindelar, G. R. Caskey Jr., J. K. Thomas, J. R. Hawthorne, A. L. Hiser, R. G. Lott, J. A. Begley, and R. P. Shogan, in *Effects of Radiation on Materials: 16th International Symposium, ASTM STP 1175*, A. S. Kumar, D. S. Gelles, R. K. Nanstad, and E. A. Little, Editors, American Society for Testing and Materials, Philadelphia, 1993.
 14. **WSRC-TR-92-10**, "PWS Piping Acceptance Criteria (U)," D. M. Barnes and R. L. Sindelar, Savannah River Technology Center, September 1992.
 15. **WSRC-TR-92-12**, "Structural Integrity Evaluation of Process Water System Bingham Pumps (U)," N. K. Gupta, Savannah River Technology Center, October 1992.
 16. **WSRC-TR-92-440**, "Process Water System Valve Acceptance Criteria (U)," R. F. Miller and R. L. Sindelar, Savannah River Technology Center, December 1992.
 17. **WSRC-TR-92-441**, "Plenum Inlet Nozzle Acceptance Criteria (U)," R. F. Miller and R. L. Sindelar, Savannah River Technology Center, February 1993.
 18. **WSRC-TR-92-539**, "Structural Integrity Evaluation of Process Water System Andale Strainers (U)," N. K. Gupta, Savannah River Technology Center, January 1993
 19. **WSRC-RP-89-208, Rev.2**, "Reactor Tank UT Acceptance Criteria, (U)," W. L. Daugherty, et. al., Savannah River Laboratory, January 1990.
 20. Reactor Materials Program, "Specification for Sample Preparation, Irradiation and Testing," **SRP-SL-1101**, 1984 (in Task 89-023-1 Files).
 21. Reactor Materials Program, "Revision to Specification for Sample Preparation, Irradiation and Testing," **SRP-SL-1108**, 1989 (in Task 89-023-1 Files).
 22. J. R. Hawthorne, et. al., "Sample Preparation, Irradiation, and Testing of 304 Stainless Steel Specimens," Materials Engineering Associates, Report **MEA-2221**, August 1987.
 23. **WSRC-TR-91-496**, "Reactor Materials Program - Material Characterization of Archival Type 304 Stainless Steel Piping (U)," K. W. Murphy and K. J. Stoner, Savannah River Laboratory, September 1991.
 24. **WSRC-TR-90-504**, "Metallurgical Examination of a K Reactor Process Water Pipe Weld (U)," S. L. West, M. R. Louthan Jr., and D. Z. Nelson, Savannah River Laboratory, December 1990.
 25. R. L. Sindelar and G. R. Caskey Jr., "Orientation Dependency of 1950's Vintage Type 304 Stainless Steel Weldment Components Before and After Low Temperature Neutron

Irradiation," presented at the 1st International Symposium on Microstructures and Mechanical Properties of Aging Materials, TMS Fall Meeting, Chicago, IL, November 2-5, 1992, to be published in the proceedings.

26. Laboratory Notebook, **DPSTN-4321**, Copy Series E37276.
27. ASTM E1268-88, *Standard Practice for Assessing the Degree of Banding or Orientation of Microstructures*.
28. F. M. Haggag, test results presented at Piping Integrity Review Group meeting at Y-12, August 18, 1992, Oak Ridge National Laboratory, Metals and Ceramics Division (copy of results retained in Task 89-023-1 files).
29. M. R. Dietrich, G. R. Caskey Jr., and J. A. Donovan, "J-controlled Crack Growth as an Indicator of Hydrogen-Stainless Steel Compatibility," in *Hydrogen Effects in Metals*, I. M. Bernstein and Anthony W. Thompson, eds., 1981, pp. 637-643.
30. W. C. Mosely Jr., "Flow Lines and Microscopic Elemental Inhomogeneities in Austenitic Stainless Steels," in *Microbeam Analysis-1982*, K. F. J. Heinrich, ed., San Francisco Press, 1982, pp. 415-421.
31. "The Cr-Fe-Ni System," in *Bulletin of Alloy Phase Diagrams* 2 (1), (1981) pp. 89-99.
32. **WSRC-RP-89-208, Rev. 2**, "Reactor Tank UT Acceptance Criteria (U)," W. L. Daugherty, Savannah River Laboratory, January 1990.
33. "J-Integral of Circumferential Crack in Large Diameter Pipes," J. Wei, Y. J. Chao, M. A. Sutton, P. S. Lam, and G. E. Mertz, to be presented at the 2nd ASME/JSME International Conference on Nuclear Engineering, March 21-24, 1993, San Francisco, and to be published in the proceedings.

ATTACHMENT 1 TO WSRC-TR-93-007

0916-23-92

OAK RIDGE NATIONAL LABORATORY
MANAGED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE U.S. DEPARTMENT OF ENERGY

POST OFFICE BOX 2008
OAK RIDGE, TENNESSEE 37831

4500S, MS-6151
PHONE 615-574-7007
FAX 615-574-5118

September 16, 1992

Mr. Robert L. Sindelar
Westinghouse Savannah River Company
Savannah River Technology Center
Building 773-41A
Aiken, South Carolina 29808

Dear Bob:

I am enclosing a copy of my letter report, "**Fracture Toughness of Type 304 Stainless Steel Pipe Materials.**" If you have any questions or need further information, please contact me.

Sincerely yours,

Fahmy M. Haggag
Fracture Mechanics Group
Metals and Ceramics Division

FMH:jljb

Enclosure

cc/enc: R. K. Nanstad
R. L. Senn
R. L. Swain
F. M. Haggag - RC

Fracture Toughness of Type 304 Stainless Steel Pipe Materials

(Letter report submitted to Westinghouse Savannah River Company)

September 16, 1992

Fahmy M. Haggag
Fracture Mechanics Group
Metals and Ceramics Division
Oak Ridge National Laboratory

ABSTRACT

Several unirradiated 0.4T C(T) fracture toughness specimens (machined from type 304 stainless steel pipe materials) were tested successfully at room temperature. The test results indicate excellent functionality of the hardware (particularly the outboard clip gage) and the unloading compliance software. The initiation J-integral values ranged from 602 to 888 kJ/m² and the tearing modulus ranged from 163 to 256 for all specimens. All initiation fracture toughness values were invalid per ASTM standard E 813 due to insufficient specimen thickness. This work completes the shakedown testing at Oak Ridge National Laboratory (ORNL), in preparation for irradiated specimen testing from the High Flux Isotope Reactor (HFIR) capsule 12M. Testing of eight irradiated fracture toughness, three Charpy V-notch and five tensile specimens will start following capsule disassembly and transferring the specimens to the hot cell of Building 3025.

Test Procedures

This letter report presents the test results from unirradiated type 304 stainless steel pipe materials. Prior to testing at ORNL, a floppy disk was received from Savannah River Technology Center (SRTC) containing test data of unirradiated specimen No. 8BB-15. This specimen was tested by Materials Engineering Associates (MEA) and the raw data was in the format of personal computer files. We have converted the files into Hewlett Packard computer files and analyzed the data in two different ways. The specimen load-line compliance was determined by performing a linear regression on: (1) both the unload and reload data for the partial unload similar to the approach by MEA, and (2) using the unload data only as used in all our tests at ORNL and as described in ASTM standards E 813 and E 1152. The results of MEA and ORNL on specimen 8BB-15 are shown in Appendices A (MEA results), and B & C (ORNL results). These results show reasonable agreement between the two laboratories.

Seven 0.4T C(T) fracture toughness specimens were machined from type 304 stainless steel pipe material. Six of these specimens were tested at room temperature according to ASTM standards E 813 and E 1152. The seventh specimen will be tested later in the hot cell prior to testing the irradiated specimens from capsule 12M for equipment verification. The seven specimens were machined from three remnant pipe pieces received from SRTC designated (marked) as 8B4 (0.5" thick x 1.25" x 1.375"), 8BB (0.5"

thick x 1.00" x 4.25"), and Excess Ring 6 (0.5" thick x 2.625" x 3.375"). The specimen machining plans (specimen layout) and orientation are given in Appendix D (drawings FMGSRLO8B4, Rev. 1, FMGSRLO8BB, Rev. 1, and FMGSRLO6A, Rev. 1). The specimen layout and testing was performed according to the instructions requested in the letter from K. J. Stoner to R. L. Sindeler (SRL-EDG-900380, Task #: 89-023-A,C-1) dated February 13, 1991. A photograph of specimens 6HAOR5, 6HAOR6, and 6HAOR7 is given in Appendix E to show that the specimen notch plane bisects the weld fusion-line. The specimen geometry is given in Appendix F. An outboard clip gage of maximum span of 0.25 inch (6.35 mm) was used for testing these 0.4T C(T) specimens.

RESULTS

Four specimens (two from base metal and two from weld fusion material with the crack bisecting the weld) were analyzed successfully. The test data acquired on the computer hard disk from one specimen (No. 8BB8B4) was accidentally erased. Specimen No. 8BBOR2 was tested successfully but was stopped while the data were climbing the blunting line at a J-Integral value of 600 kJ/m^2 (indicating that the J_{lc} value from this specimen is expected to be higher than 600 kJ/m^2). The results from this specimen are consistent with those from No. 8BBOR3. The J_{lc} and tearing modulus values are summarized in Table 1. (The initiation J-integral toughness values are not valid for all these specimens because of their small thickness.) An intact weld fusion specimen No. 6HAOR7, which is not side grooved, remains as contingency for testing in the hot cell for equipment verification prior to testing the irradiated specimens from the HFIR capsule 12M. The detailed results of five specimens including the load-displacement and J-R plots are given in Appendix G. It was noticed that the final crack front was irregular for both specimens 6HAOR5 (20% side-grooved) and 6HAOR6 (0% side-grooved) with crack front tunneling (thumb nail shape) in the none side-grooved specimen. The amount of slow stable crack growth was less in the weld metal as compared to the remainder of the crack plane where the crack notch plane bisected the weld fusion-line. This observation is in agreement with the higher tearing modulus values of the weld fusion specimens as compared to the base metal specimens (Table 1). The test results indicate excellent functionality of the hardware (particularly the outboard clip gage) and the unloading compliance J-R software. These results also completes the shakedown work at ORNL. Testing of the irradiated fracture toughness specimens will start when the specimens become available and transferred to the hot cell of Building 3025.

Table 1
SUMMARY OF STATIC FRACTURE TOUGHNESS TEST
RESULTS OF 0.4TC(T) TYPE 304 STAINLESS STEEL

Specimen number	J_{Ic}^a (kJ/m ²)	K_{Jc} (MPa√m)	Tearing modulus	ASTM orientation	Material source	Side grooving (%)
8BBOR3	888	399	181	L-C	Base metal	20
8BBOR4	688	351	163	C-L	Base metal	20
6HAOR5	602	329	256	L-C	Weld fusion	20
6HAOR6	868	394	227	L-C	Weld fusion	0

^a All initiation fracture toughness values were invalid per ASTM standard E 813 because of insufficient specimen thickness.

Appendix A

Fracture Toughness Test Results of Specimen 8BB-15 Obtained by Materials Engineering Associates

Attachment 2 1 of 7

TEST SPECIMEN DATA

Material Type	= BASE	
Test Temperature	= 25 C	
Percent Side Groove	= 20 %	
Specimen Thickness	= 10.000 mm	
Initial Crack Length	= 10.55 mm	Init a/W = .527
Final Crack Length	= 14.3 mm	Final a/W = .714
Flow Stress	= 447 MPa	
Youngs Modulus	= 205700 MPa	(Estimated Value)

POWER LAW DATA $J = C (\Delta a)^n$

J _{ic}	= 736.3 kJ/m ²
K _{Jc}	= 389.2 MPa √m
J (0J/Y=9.8)	= 1191.3 kJ/m ²
Exponent n	= .4705
Coefficient C	= 744.6 kJ/m ²
T (average)	= 260

LEAST SQUARE LINEAR LINE (ASTM) $J = M (\Delta a) + B$

J _{ic}	= 781.2 kJ/m ²
K _{Jc}	= 400.9 MPa √m
Slope M	= 215693.9 kJ/m ³
Intercept B	= 592.5 kJ/m ²
T (ASTM)	= 222
Validity (J _{ic})	= INVALID--d, e
Validity (R-curve)	= INVALID--2, 3 (.4 vs .14)
J maximum allowed	= 176.0 kJ/m ² (J _{max} =B _{net} *Flow stress/20)
Delta a max. allowed	= .95 mm (Delta a max = 0.1*b ₀)
Final Delta a	= 3.35 mm
Poisson's Ratio (ν)	= 0
Points Left	= 2

Points Right = 0

Data for
J_{modified} (Ernst)
formulation is
contained in MEA-2221

JUN-13-1991 08:46 FROM

TO

86245118 P.11

AA 2 7 of 7

TOTAL P.11

Appendix B

Fracture Toughness Test Results of Specimen 8BB-15 Obtained by

Oak Ridge National Laboratory

(Both the unload and reload data of each partial unload are used in the load-line compliance determination.)

SPECIMEN

IDENTIFICATION: 8BB-15

MATERIAL

CODE: STEEL

YOUNG'S MODULUS: 199.95 (GPA), 29000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 262 (MPA), 38 (KSI)

ULTIMATE: 627.42 (MPA), 91 (KSI)

ORIENTATION: L-C

GEOMETRY: C(T)

WIDTH: 20.015 (MM), 0.788 (IN)

THICKNESS: 10.008 (MM), 0.394 (IN)

SIDE GROOVE: 20 (PERCENT)

LOAD PIN CENTER SPAN: 9.804 (MM), 0.386 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 4.448 (KN), 1000 (LB)

FREQUENCY: 25 (HZ)

MEASURED CRACK LENGTHS

INITIAL: 10.541 (MM), 0.415 (IN)

FINAL: 14.3 (MM), 0.563 (IN)

TEST

ROUTINE REVISION: FOREIGN

TYPE: UCJR

ENGINEER: UNKNOWN

TECHNICIAN: UNKNOWN

TEST DATE: UNKNOWN

ATMOSPHERE: UNKNOWN

TEMPERATURE: 25 (DEG C), 77 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90

UNLOADING COMPLIANCE RESULTS

CRACK LENGTH PINS

INITIAL

TEST CYCLE FOR EFFECTIVE MODULUS DETERMINATION: 0

EFFECTIVE MODULUS: 193.18 (GPA), 28018 (KSI)

EFFECTIVE MODULUS SHIFT: -3.4 (PERCENT)

FINAL

PIN NOT APPLIED

UNLOAD DATA EXCLUSIONS

UPPER: 10

LOWER: 10

MEASURED FINAL CRACK EXTENSION: 3.759 (MM), 0.148 (IN)

FINAL CRACK EXTENSION: 4.049 (MM), 0.1594 (IN)

FINAL CRACK EXTENSION ERROR: 7.7 (PERCENT)

PQ: 3.818 (KN), 858 (LB)

KQ: 29.52 (MPA-SQRT(M)), 26.86 (KSI-SQRT(IN))

KIC: NO VALID KIC FOR TEST

PMX: 7.989 (KN), 1796 (LB)

KMX: 61.77 (MPA-SQRT(M)), 56.21 (KSI-SQRT(IN))

ERNST RESULTS

PMX J-INTEGRAL: 685.64 (KJ/M^2), 3915.1 (IN-LB/IN^2)

FINAL J-INTEGRAL: 1083.9 (KJ/M^2), 6189.1 (IN-LB/IN^2)

FINAL KJ: 465.53 (MPA-SQRT(M)), 423.65 (KSI-SQRT(IN))

POWER LAW MODEL

J-INTEGRAL (KJ/M^2) = 856.25 * ((CRACK EXTENSION (MM))^0.34741)

*all unloading
data used*

used { // } used

J-INTEGRAL (IN-LB/IN^2)=15042*((CRACK EXTENSION (IN))^0.34741)
RESULTS EXCLUDED FROM MODEL: CYCLES 1,2,3,4,5,6,7,8,9,10,11,12,13,14,
15,16,17,26 AND 27
JIC: 921.08 (KJ/M^2),5259.5 (IN-LB/IN^2)
KJIC: 429.15 (MPA-SQRT(M)),390.55 (KSI-SQRT(IN))
TEARING MODULUS: 194

SPECIMEN

IDENTIFICATION: 8BB-15

MATERIAL CODE: STEEL

ORIENTATION: L-C

GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE

INITIAL CRACK LENGTH: 10.541 (MM)

TEST

ATMOSPHERE: UNKNOWN

TEMPERATURE: 25 (DEG C)

ANALYSIS

CRACK LENGTH PINS: INITIAL

CRACK EXTENSION METHOD: UNLOADING COMPLIANCE

J-INTEGRAL METHOD: ERNST

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	4.249	0.139	0.383	0.041	11.19	47.3
2	4.905	0.242	0.889	0.022	26.22	72.4
3	5.413	0.495	2.308	0.075	67.6	116.26
4	5.921	0.75	3.868	0.092	114.09	151.04
5	6.174	1.004	5.504	0.124	162.19	180.08
6	6.424	1.233	7.041	0.144	207.69	203.78
7	6.66	1.513	8.989	0.165	265.4	230.36
8	6.865	1.766	10.807	0.237	316.74	251.66
9	6.946	2.02	12.675	0.294	370.25	272.08
10	7.169	2.274	14.582	0.339	425.41	291.65
11	7.258	2.527	16.518	0.385	481.43	310.26
12	7.426	2.833	18.899	0.51	544.38	329.92
13	7.5	3.137	21.295	0.582	612.35	349.91
14	7.594	3.444	23.733	0.671	679.45	368.59
15	7.506	3.748	26.151	0.826	738.03	384.14
16	7.451	4.052	28.558	0.999	793.84	398.41
17	7.468	4.357	30.957	1.107	857.53	414.08
18	7.386	4.662	33.334	1.239	916.98	428.19
19	7.325	4.967	35.682	1.436	964.63	439.18
20	7.101	5.272	37.989	1.605	1014.84	450.46
21	6.944	5.576	40.226	1.8	1058.27	460
22	6.657	5.958	42.953	2.056	1106.2	470.3
23	6.319	6.339	45.542	2.324	1145.62	478.61
24	6.007	6.719	48.001	2.575	1185	486.76
25	5.812	7.1	50.371	2.808	1223.88	494.68
26	5.457	7.481	52.604	3.091	1244.79	498.89
27	5.188	7.862	54.722	4.049	1083.87	465.53

SPECIMEN

IDENTIFICATION: 8BB-15

MATERIAL CODE: STEEL

ORIENTATION: L-C

GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE

INITIAL CRACK LENGTH: 0.415 (IN)

TEST

ATMOSPHERE: UNKNOWN

TEMPERATURE: 77 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL

CRACK EXTENSION METHOD: UNLOADING COMPLIANCE

J-INTEGRAL METHOD: ERNST

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN ²)	KJ (KSI-SQRT(IN))
1	955	0.0055	3.39	0.0016	63.9	43.05
2	1103	0.0095	7.87	0.0009	149.7	65.89
3	1217	0.0195	20.43	0.003	386	105.81
4	1331	0.0295	34.24	0.0036	651.5	137.45
5	1388	0.0395	48.71	0.0049	926.1	163.88
6	1444	0.0485	62.32	0.0057	1186	185.45
7	1497	0.0595	79.56	0.0065	1515.5	209.64
8	1543	0.0695	95.65	0.0093	1808.7	229.02
9	1562	0.0795	112.18	0.0116	2114.2	247.61
10	1612	0.0895	129.06	0.0133	2429.2	265.42
11	1632	0.0995	146.19	0.0152	2749	282.35
12	1669	0.1115	167.27	0.0201	3108.5	300.24
13	1686	0.1235	188.48	0.0229	3496.6	318.44
14	1707	0.1356	210.05	0.0264	3879.8	335.43
15	1688	0.1476	231.46	0.0325	4214.3	349.59
16	1675	0.1595	252.76	0.0393	4532.9	362.57
17	1679	0.1716	273.99	0.0436	4896.6	376.83
18	1660	0.1836	295.03	0.0488	5236.1	389.67
19	1647	0.1956	315.81	0.0565	5508.2	399.67
20	1596	0.2076	336.23	0.0632	5794.9	409.94
21	1561	0.2195	356.03	0.0709	6042.9	418.62
22	1497	0.2346	380.17	0.0809	6316.6	428
23	1420	0.2496	403.08	0.0915	6541.7	435.56
24	1350	0.2645	424.84	0.1014	6766.6	442.98
25	1307	0.2795	445.82	0.1106	6988.5	450.19
26	1227	0.2945	465.59	0.1217	7107.9	454.02
27	1166	0.3095	484.33	0.1594	6189.1	423.65

Appendix C

Fracture Toughness Test Results of Specimen 8BB-15 Obtained by

Oak Ridge National Laboratory

**(Only the unload data of each partial unload are used in the load-line
compliance determination.)**

SPECIMEN

IDENTIFICATION: 8BB-15

MATERIAL

CODE: STEEL

YOUNG'S MODULUS: 199.95 (GPA), 29000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 262 (MPA), 38 (KSI)

ULTIMATE: 627.42 (MPA), 91 (KSI)

ORIENTATION: L-C

GEOMETRY: C(T)

WIDTH: 20.015 (MM), 0.788 (IN)

THICKNESS: 10.008 (MM), 0.394 (IN)

SIDE GROOVE: 20 (PERCENT)

LOAD PIN CENTER SPAN: 9.804 (MM), 0.386 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 8.896 (KN), 2000 (LB)

FREQUENCY: 25 (HZ)

MEASURED CRACK LENGTHS

INITIAL: 10.541 (MM), 0.415 (IN)

FINAL: 14.3 (MM), 0.563 (IN)

TEST

ROUTINE REVISION:

TYPE: UCJR

ENGINEER: UNKNOWN

TECHNICIAN: UNKNOWN

TEST DATE: UNKNOWN

ATMOSPHERE: UNKNOWN

TEMPERATURE: 25 (DEG C), 77 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90

UNLOADING COMPLIANCE RESULTS**CRACK LENGTH PINS****INITIAL**

TEST CYCLE FOR EFFECTIVE MODULUS DETERMINATION: 0

EFFECTIVE MODULUS: 190.17 (GPA), 27582 (KSI)

EFFECTIVE MODULUS SHIFT: -4.9 (PERCENT)

FINAL

PIN NOT APPLIED

UNLOAD DATA EXCLUSIONS

UPPER: 10

LOWER: 10

MEASURED FINAL CRACK EXTENSION: 3.759 (MM), 0.148 (IN)

FINAL CRACK EXTENSION: 3.895 (MM), 0.1534 (IN)

FINAL CRACK EXTENSION ERROR: 3.6 (PERCENT)

PQ: 3.818 (KN), 858 (LB)

KQ: 29.52 (MPA-SQRT(M)), 26.86 (KSI-SQRT(IN))

KIC: NO VALID KIC FOR TEST

PMX: 7.989 (KN), 1796 (LB)

KMX: 61.77 (MPA-SQRT(M)), 56.21 (KSI-SQRT(IN))

ERNST RESULTS

PMX J-INTEGRAL: 679.1 (KJ/M^2), 3877.8 (IN-LB/IN^2)

FINAL J-INTEGRAL: 1112.1 (KJ/M^2), 6350.2 (IN-LB/IN^2)

FINAL KJ: 471.55 (MPA-SQRT(M)), 429.13 (KSI-SQRT(IN))

POWER LAW MODEL $J\text{-INTEGRAL (KJ/M}^2\text{)} = 867.55 * ((\text{CRACK EXTENSION (MM)})^{0.32843})$

used / not used

J-INTEGRAL (IN-LB/IN^2)=14333*((CRACK EXTENSION (IN))^0.32843)
RESULTS EXCLUDED FROM MODEL: CYCLES 1,2,3,4,5,6,7,8,9,10,11,12,13,14,
15,16,17,26 AND 27
JIC: 933.32 (KJ/M^2),5329.4 (IN-LB/IN^2)
KJIC: 431.99 (MPA-SQRT(M)),393.13 (KSI-SQRT(IN))
TEARING MODULUS: 183

SPECIMEN

IDENTIFICATION: 8BB-15

MATERIAL CODE: STEEL

ORIENTATION: L-C

GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE

INITIAL CRACK LENGTH: 10.541 (MM)

TEST

ATMOSPHERE: UNKNOWN

TEMPERATURE: 25 (DEG C)

ANALYSIS

CRACK LENGTH PINS: INITIAL

CRACK EXTENSION METHOD: UNLOADING COMPLIANCE

J-INTEGRAL METHOD: ERNST

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	4.249	0.139	0.383	-0.044	11.33	47.59
2	4.905	0.242	0.889	-0.054	26.2	72.38
3	5.413	0.495	2.308	-0.078	68.44	116.98
4	5.921	0.75	3.868	0.063	111.87	149.56
5	6.174	1.004	5.504	0.102	159.66	178.67
6	6.424	1.233	7.041	0.112	205.37	202.64
7	6.66	1.513	8.989	0.15	262.27	229
8	6.865	1.766	10.807	0.193	314.88	250.92
9	6.946	2.02	12.675	0.288	366.13	270.57
10	7.169	2.274	14.582	0.284	424.31	291.27
11	7.258	2.527	16.518	0.326	480.39	309.92
12	7.426	2.833	18.899	0.477	540.81	328.84
13	7.5	3.137	21.295	0.493	613.76	350.32
14	7.594	3.444	23.733	0.656	672.63	366.73
15	7.506	3.748	26.151	0.785	734.24	383.16
16	7.451	4.052	28.558	0.923	794.27	398.51
17	7.468	4.357	30.957	1.097	848.49	411.89
18	7.386	4.662	33.334	1.196	912.73	427.2
19	7.325	4.967	35.682	1.404	958.58	437.8
20	7.101	5.272	37.989	1.519	1018.42	451.25
21	6.944	5.576	40.226	1.791	1047.09	457.56
22	6.657	5.958	42.953	2.012	1102.05	469.42
23	6.319	6.339	45.542	2.319	1133.74	476.12
24	6.007	6.719	48.001	2.564	1174.64	484.63
25	5.812	7.1	50.371	2.776	1218.85	493.67
26	5.457	7.481	52.604	3.065	1238.41	497.61
27	5.188	7.862	54.722	3.895	1112.09	471.55

SPECIMEN

IDENTIFICATION: 8BB-15

MATERIAL CODE: STEEL

ORIENTATION: L-C

GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE

INITIAL CRACK LENGTH: 0.415 (IN)

TEST

ATMOSPHERE: UNKNOWN

TEMPERATURE: 77 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL

CRACK EXTENSION METHOD: UNLOADING COMPLIANCE

J-INTEGRAL METHOD: ERNST

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN ²)	KJ (KSI-SQRT(IN))
1	955	0.0055	3.39	-0.0017	64.7	43.31
2	1103	0.0095	7.87	-0.0021	149.6	65.87
3	1217	0.0195	20.43	-0.0031	390.8	106.46
4	1331	0.0295	34.24	0.0025	638.8	136.1
5	1388	0.0395	48.71	0.004	911.7	162.6
6	1444	0.0485	62.32	0.0044	1172.7	184.41
7	1497	0.0595	79.56	0.0059	1497.6	208.4
8	1543	0.0695	95.65	0.0076	1798	228.35
9	1562	0.0795	112.18	0.0113	2090.7	246.23
10	1612	0.0895	129.06	0.0112	2422.8	265.07
11	1632	0.0995	146.19	0.0128	2743.1	282.05
12	1669	0.1115	167.27	0.0188	3088.1	299.26
13	1686	0.1235	188.48	0.0194	3504.7	318.8
14	1707	0.1356	210.05	0.0258	3840.8	333.74
15	1688	0.1476	231.46	0.0309	4192.6	348.69
16	1675	0.1595	252.76	0.0363	4535.4	362.67
17	1679	0.1716	273.99	0.0432	4845	374.84
18	1660	0.1836	295.03	0.0471	5211.8	388.77
19	1647	0.1956	315.81	0.0553	5473.7	398.42
20	1596	0.2076	336.23	0.0598	5815.3	410.66
21	1561	0.2195	356.03	0.0705	5979.1	416.4
22	1497	0.2346	380.17	0.0792	6292.9	427.19
23	1420	0.2496	403.08	0.0913	6473.8	433.29
24	1350	0.2645	424.84	0.1009	6707.4	441.04
25	1307	0.2795	445.82	0.1093	6959.8	449.26
26	1227	0.2945	465.59	0.1207	7071.5	452.85
27	1166	0.3095	484.33	0.1534	6350.2	429.13

Appendix D

Specimen Machining Plans (Specimen Layout Drawings)

**(Piece "8B4": one base metal specimen, L-C orientation,
Piece "RING 8 PC B": three base metal specimens, 2 L-C, and 1 C-L orientations,
Piece "Excess RING 6": three weld fusion specimens, L-C orientation)**

(The specimen numbers are 8BB8B4, 8BBOR2, 8BBOR3, 8BBOR4, 6HAOR5, 6HAOR6, and 6HAOR7), Specimen 8BB8B4 replaces the number 8BBOR1 given by K. V. Stoner in his letter of 13 February, 1991 to R. L. Sindelar.

All specimens except 6HAOR6 and 6HAOR7 were 20% side-grooved.

A4J44

ORIENTATION OF SPECIMEN IS CRITICAL!
SPECIMEN IS LAID OUT ON SAMPLE BLOCK AS SHOWN.
NOTCH IS TO BE PARALLEL TO THE LAYOUT LINE PUNCHED DOWN THE
CENTER OF THE BLOCK.

MACHINE INNER SURFACE FLAT AND TRANSFER SPECIMEN AND ID
ONTO IT.
USE COOLANT WHEN NECESSARY. HEATING THE SURFACE TO
STRAW COLOR WILL CHANGE THE RESULTS OF ANY TESTING.
CONTACT JOHN HENRY 574-4473 OR FAHMY HAGGAG 574-7007 TO
CONFIRM PROPER ORIENTATION BEFORE PROCEEDING.
AFTER CONFIRMATION MACHINE THE SPECIMEN AS PER DRAWING
NO. FMG026 R. 1
PROVIDED BY THE TFRACUTURE MECHANICS GROUP.

SPECIMEN ID.
SPEC. CODE (8BB)
SPEC. NO. OR1

MATERIAL: 304 STAINLESS STEEL BASE METAL

DRAWING NUMBER: FMGSRLO8B4		REV. 1
Oak Ridge National Laboratory MANAGED BY		
MARTIN MARIETTA ENERGY SYSTEMS, INC. OAK RIDGE, TENNESSEE		
FRACTURE MECHANICS GROUP	BLDg No. 4500S D55	
SAVANNAH RIVER 394 CT MACHINING PLAN MATERIAL 8B4		
SUBMITTED	ACCEPTED	APPROVED
John Henry 5/19/19 Fahmy 5/19/19 [Signature]		
		5/17/19

A4J44

ORIENTATION OF SPECIMEN IS CRITICAL!
SAW MATERIAL INTO THREE SECTIONS. HEATING THE
SURFACE TO STRAW COLOR WILL CHANGE THE RESULTS OF
ANY TESTING. USE COOLANT ON ALL MACHINING WHICH
MIGHT HEAT SPECIMEN.
OUTER SURFACE OF PIPE SPECIMEN HAS A ROUGH DRAWING
OF SPECIMENS AND ID. NO. AS SHOWN.
NOTCH IS TO BE PARALLEL TO THE PIPE CIRCUMFERENCE
ON OR2 & OR3 AND PERPENDICULAR ON OR4

MACHINE INNER SURFACES FLAT AND TRANSFER SPECIMENS
AND ID. NOS. ONTO THEM WITH SCRIBE OR PERMANENT
MARKER.
CONTACT JOHN HENRY 574-4473 OR FAHMY HAGGAG 574-7007
TO CONFIRM PROPER ORIENTATION BEFORE PROCEEDING.
AFTER CONFIRMATION, MACHINE THE SPECIMENS AS PER
DRAWING NO. FMG026 REV. 1 PROVIDED BY THE FRACTURE
MECHANICS GROUP. PRESERVE ID AND NOTCH DIRECTIONS
MARKINGS AT ALL TIMES DURING THE MACHINING PROCESS

MATERIAL: 304 STAINLESS STEEL BASE METAL

SPECIMEN NUMBERS:
SPEC CODE (8BB)
SPEC NOS OR2, OR3, & OR4 AS SHOWN

DRAWING NUMBER: FMGSRLO8BB		REV. 1
Oak Ridge National Laboratory MANAGED BY		
MARTIN MARIETTA ENERGY SYSTEMS, INC. OAK RIDGE, TENNESSEE		
FRACTURE MECHANICS GROUP ^{BL 96} 4500S D55 SAVANNAH RIVER 394 CT MACHINING PLAN MATERIAL 8BB		
SUBMITTED	ACCEPTED	APPROVED
John F. Haggar 5/1/91	Fahmy H. Haggag 5/1/91	5/1/91

84JY4

SPECIMEN NUMBERS:
SPEC CODE (6HA)
SPEC NOs OR5, OR6, &
OR7 AS SHOWN

Heating the surface to straw color will change the results of any testing. Use coolant on all machining which might heat specimen.

- 1 Remove the tang sticking out to the left and cut material into three equal sections as shown by bold dashed lines on drawing. There is only .068" total excess material over the finished specimen dimensions as measured from the inner circumference after removal of tang. Cuts must be straight and parallel. EDM must be used to assure enough material for machining. Use extreme care, this material cannot be replaced.
- 2 Machine inner circumference of each section flat and right edge perpendicular to this. Orientations of specimens are CRITICAL! Transfer IDs to former inner circumference surface in such a way as to preserve specimen orientation. Contact John Henry 574-4473 or Fahmy Haggag 574-7007 to come verify transfer before proceeding to the next step.
- 3 Machine outer circumference flat and parallel to inner surface but not less than .394" between surfaces. Transfer IDs to the outer surface. If specimens are still greater than .394" remove material from the inner surface, because the block is wider toward the top this will allow more room for specimen positioning. Return slices to ORNL. Fracture mechanics group will acid etch and layout specimens then return to shop for final cutting. Contact John Henry 574-4473 or Fahmy Haggag 574-7007 to come and observe initial setup before proceeding. Machine the specimens as per drawing no. FMG026 Rev. 1 provided by the fracture mechanics group.

Specimens must be machined so that weld angle exactly crosses the center of notch of the side with the straightest weld. Leave the 2.63" dimension uncut so that specimens can be shifted as needed.

DRAWING NUMBER: FMGSRLO6A	REV. 1
Oak Ridge National Laboratory MANAGED BY	
MARTIN MARIETTA ENERGY SYSTEMS, INC. OAK RIDGE, TENNESSEE	
FRACTURE MECHANICS GROUP	BL 96 4500S D55
SAVANNAH RIVER 394 CT MACHINING PLAN MATERIAL EXCESS RING 6	
SUBMITTED	ACCEPTED
APPROVED	

John I. Henry 5/10/91 Fahmy H. Haggag 5/13/91 [Signature] 5/13/91

Appendix E

Photograph of three weld fusion specimens prior to their testing

(The crack notch plane bisects the weld fusion-line)

Appendix F

Geometry of the 0.394T C(T) Compact Fracture Toughness Specimen

A7J44

STAMP SPECIMEN
CODE NO. (XXX) AND
SPECIMEN
CONSECUTIVE NO.
(YYY) 2 PLACES AS
SHOWN.

Attachment 1
Page 26 of 66

Notes:
1. E=F to within 0.002.
2. 60° included angle groove .020 deep with less than .002 root radius (TYP).

Tolerances
Unless otherwise specified-
X.XXX = ± 0.003
All surfaces should be parallel and perpendicular as appropriate within 0.002". All dimensions in inches. Surface finishes $\sqrt{.197}$ or better.

DRAWING NUMBER: FMG026	REV. 1
Oak Ridge National Laboratory MANAGED BY MARTIN MARIETTA ENERGY SYSTEMS, INC. OAK RIDGE, TENNESSEE	
FRACTURE MECHANICS GROUP	ALB. 4500S D55
.394" T Compact Specimen	
SUBMITTED	ACCEPTED
APPROVED	APPROVED
Rev. Henry 8/1/91 F.M.H. 9/91	Rev. 5/8/91

May 9-91

Appendix G

Test Results of Five Fracture Toughness Specimens (8BBOR3, 8BBOR4, 6HAOR5, 6HAOR6, and 8BBOR2)

SPECIMEN

IDENTIFICATION: 8BBOR3

MATERIAL

CODE: 304SS

YOUNG'S MODULUS: 206.84 (GPA), 30000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 244.76 (MPA), 35.5 (KSI)

ULTIMATE: 693.61 (MPA), 100.6 (KSI)

ORIENTATION: L-C

GEOMETRY: C(T)

WIDTH: 20.03 (MM), 0.7886 (IN)

THICKNESS: 10.033 (MM), 0.395 (IN)

SIDE GROOVE: 20 (PERCENT)

LOAD PIN CENTER SPAN: 9.906 (MM), 0.39 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 1.779 (KN), 400 (LB)

FREQUENCY: 30 (HZ)

FRONT SURFACE TO LOAD LINE DISTANCE: 5.004 (MM), 0.197 (IN)

FRONT SURFACE TO INITIAL CRACK FRONT DISTANCES

DISTANCE 1: 15.464 (MM), 0.6088 (IN)

DISTANCE 2: 15.631 (MM), 0.6154 (IN)

DISTANCE 3: 15.834 (MM), 0.6234 (IN)

DISTANCE 4: 15.86 (MM), 0.6244 (IN)

DISTANCE 5: 15.86 (MM), 0.6244 (IN)

DISTANCE 6: 15.88 (MM), 0.6252 (IN)

DISTANCE 7: 15.806 (MM), 0.6223 (IN)

DISTANCE 8: 15.695 (MM), 0.6179 (IN)

DISTANCE 9: 15.575 (MM), 0.6132 (IN)

FRONT SURFACE TO FINAL CRACK FRONT DISTANCES

DISTANCE 1: 17.968 (MM), 0.7074 (IN)

DISTANCE 2: 17.683 (MM), 0.6962 (IN)

DISTANCE 3: 17.889 (MM), 0.7043 (IN)

DISTANCE 4: 17.838 (MM), 0.7023 (IN)

DISTANCE 5: 17.94 (MM), 0.7063 (IN)

DISTANCE 6: 18.039 (MM), 0.7102 (IN)

DISTANCE 7: 17.871 (MM), 0.7036 (IN)

DISTANCE 8: 17.734 (MM), 0.6982 (IN)

DISTANCE 9: 17.976 (MM), 0.7077 (IN)

MEASURED CRACK LENGTHS

INITIAL: 10.757 (MM), 0.4235 (IN)

FINAL: 12.867 (MM), 0.5066 (IN)

TEST

ROUTINE REVISION: 1.02/07-JUL-88

TYPE: UCJR

ENGINEER: FMH

TECHNICIAN: RLS

TEST DATE: 18-FEB-92

ATMOSPHERE: AIR

TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

FILE NAME: 8BBOR3

DRIVE SPECIFIER: :, 700, 1

EXISTING UCJR TEST FILE PURGED

Attachment 1

Page 28 of 66

8BB0R3
ANALYZE

PAGE 2
19-FEB-92

UCJR TEST FILE CREATED
TEST SET SAVED
ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90
CRACK LENGTH PINS

UC

INITIAL

DETERMINATION TEST CYCLE: 1
EFFECTIVE MODULUS: 189.96 (GPA), 27552 (KSI)
YOUNG'S MODULUS-EFFECTIVE MODULUS: 8.2 (PERCENT)

FINAL

PIN NOT APPLIED

UC RESULTS

MEASURED FINAL CRACK EXTENSION: 2.11 (MM), 0.0831 (IN)
FINAL CRACK EXTENSION: 1.871 (MM), 0.0737 (IN)
FINAL CRACK EXTENSION ERROR: -11.3 (PERCENT)
PQ: 2.728 (KN), 613 (LB)
KQ: 21.77 (MPA-SQRT(M)), 19807 (KSI-SQRT(IN))
KIC: NO VALID KIC FOR TEST
PMX: 8.011 (KN), 1801 (LB)
KMX: 63.91 (MPA-SQRT(M)), 58.16 (KSI-SQRT(IN))

E1152 J-INTEGRAL

PMX J-INTEGRAL: 748.6 (KJ/M²), 4274.6 (IN-LB/IN²)
FINAL J-INTEGRAL: 1052.5 (KJ/M²), 6009.8 (IN-LB/IN²)
FINAL KJ: 466.58 (MPA-SQRT(M)), 424.61 (KSI-SQRT(IN))
JIC: 887.72 (KJ/M²), 5069 (IN-LB/IN²)
KJIC: 428.51 (MPA-SQRT(M)), 389.96 (KSI-SQRT(IN))
TEARING MODULUS: 181

SPECIMEN

IDENTIFICATION: 8BB0R3
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.4TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 10.757 (MM), 0.4235 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	2.858	0.076	0.119	0.001	3.39	26.47
2	3.645	0.114	0.251	0.04	7.03	38.12
3	4.065	0.152	0.405	0.023	11.47	48.71
4	4.369	0.19	0.579	0.059	16.28	58.03
5	4.58	0.228	0.758	0.031	21.47	66.63
6	4.7	0.265	0.941	0.063	26.56	74.12
7	4.886	0.322	1.235	0.032	35.03	85.12
8	4.979	0.377	1.527	0.066	43.19	94.52
9	5.152	0.435	1.838	0.102	51.59	103.3
10	5.259	0.51	2.256	0.098	63.59	114.69
11	5.435	0.586	2.693	0.1	75.84	125.25
12	5.475	0.661	3.128	0.118	88.28	135.13
13	5.704	0.775	3.806	0.104	107.49	149.11
14	5.818	0.888	4.493	0.189	125.7	161.24
15	5.886	1	5.192	0.188	145.97	173.76
16	5.977	1.111	5.901	0.193	166.28	185.46
17	6.069	1.242	6.748	0.191	190.85	198.68
18	6.23	1.374	7.616	0.218	214.79	210.78
19	6.404	1.524	8.629	0.255	242.59	224.01
20	6.521	1.674	9.656	0.283	271.27	236.88
21	6.648	1.825	10.705	0.282	301.89	249.89
22	6.762	1.975	11.767	0.317	331.12	261.71
23	6.859	2.125	12.847	0.336	361.78	273.55
24	6.939	2.274	13.936	0.38	391.2	284.46
25	7.023	2.425	15.053	0.401	422.58	295.65
26	7.107	2.573	16.16	0.424	453.95	306.42
27	7.17	2.723	17.293	0.452	485.61	316.93
28	7.258	2.874	18.439	0.464	518.72	327.56
29	7.324	3.023	19.586	0.529	547.65	336.57
30	7.4	3.173	20.752	0.564	579.51	346.22
31	7.445	3.322	21.922	0.529	618	357.53
32	7.476	3.472	23.102	0.611	645.42	365.38
33	7.507	3.622	24.293	0.669	675.57	373.81
34	7.517	3.771	25.476	0.694	708.99	382.95
35	7.513	3.92	26.66	0.777	735.89	390.15
36	7.529	4.07	27.856	0.806	769.39	398.93
37	7.528	4.22	29.049	0.852	800.54	406.92
38	7.544	4.37	30.245	0.957	824.17	412.89
39	7.484	4.519	31.428	1.016	853.66	420.21
40	7.464	4.67	32.614	1.097	879.57	426.54

8BB0R3
ANALYZE

PAGE 4
19-FEB-92

41	7.43	4.821	33.79	1.21	900.62	431.61
42	7.34	4.971	34.951	1.313	922.88	436.91
43	7.256	5.121	36.096	1.362	952.93	443.97
44	7.126	5.27	37.224	1.506	967.02	447.24
45	6.978	5.419	38.322	1.607	987.43	451.93
46	6.996	5.57	39.432	1.653	1017.01	458.65
47	6.904	5.72	40.522	1.782	1031.49	461.9
48	6.762	5.87	41.594	1.871	1052.47	466.58

SPECIMEN

IDENTIFICATION: 8BB0R3
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.4TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 10.757 (MM), 0.4235 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN ²)	KJ (KSI-SQRT(IN))
1	643	0.003	1.05	0	19.3	24.09
2	820	0.0045	2.23	0.0016	40.1	34.69
3	914	0.006	3.58	0.0009	65.5	44.33
4	982	0.0075	5.13	0.0023	93	52.81
5	1030	0.009	6.71	0.0012	122.6	60.64
6	1057	0.0104	8.33	0.0025	151.7	67.45
7	1098	0.0127	10.93	0.0013	200	77.46
8	1119	0.0149	13.52	0.0026	246.6	86.02
9	1158	0.0171	16.26	0.004	294.6	94.01
10	1182	0.0201	19.96	0.0039	363.1	104.37
11	1222	0.0231	23.83	0.0039	433	113.98
12	1231	0.026	27.69	0.0046	504.1	122.97
13	1282	0.0305	33.69	0.0041	613.8	135.7
14	1308	0.0349	39.77	0.0074	717.7	146.74
15	1323	0.0394	45.95	0.0074	833.5	158.13
16	1344	0.0437	52.23	0.0076	949.5	168.77
17	1364	0.0489	59.73	0.0075	1089.8	180.81
18	1401	0.0541	67.4	0.0086	1226.5	191.82
19	1440	0.06	76.37	0.01	1385.2	203.86
20	1466	0.0659	85.46	0.0111	1549	215.57
21	1495	0.0718	94.75	0.0111	1723.8	227.41
22	1520	0.0777	104.14	0.0125	1890.7	238.16
23	1542	0.0836	113.7	0.0132	2065.8	248.95
24	1560	0.0895	123.34	0.015	2233.8	258.87
25	1579	0.0955	133.23	0.0158	2413	269.05
26	1598	0.1013	143.03	0.0167	2592.1	278.86
27	1612	0.1072	153.06	0.0178	2772.9	288.42
28	1632	0.1131	163.2	0.0183	2962	298.09
29	1647	0.119	173.35	0.0208	3127.2	306.29
30	1664	0.1249	183.67	0.0222	3309.1	315.08
31	1674	0.1308	194.03	0.0208	3528.9	325.37
32	1681	0.1367	204.47	0.0241	3685.5	332.51
33	1688	0.1426	215.01	0.0263	3857.6	340.19
34	1690	0.1485	225.48	0.0273	4048.4	348.5
35	1689	0.1543	235.96	0.0306	4202.1	355.05
36	1693	0.1602	246.55	0.0317	4393.4	363.04
37	1692	0.1661	257.11	0.0336	4571.2	370.32
38	1696	0.172	267.69	0.0377	4706.2	375.75
39	1683	0.1779	278.16	0.04	4874.5	382.41
40	1678	0.1839	288.56	0.0432	5022.5	388.17

8BB0R3
ANALYZE

PAGE 6
19-FEB-92

41	1670	0.1898	299.07	0.0477	5142.7	392.79
42	1650	0.1957	309.34	0.0517	5269.8	397.61
43	1631	0.2016	319.48	0.0536	5441.4	404.03
44	1602	0.2075	329.46	0.0593	5521.9	407.01
45	1569	0.2133	339.18	0.0633	5638.4	411.28
46	1573	0.2193	349	0.0651	5807.3	417.39
47	1552	0.2252	358.65	0.0701	5890	420.36
48	1520	0.2311	368.14	0.0737	6009.8	424.61

COMMAND: ANALYZE
SPECIMEN IDENTIFICATION: 8BB0R3

PAGE 7
15-SEP-92

SPECIMEN

IDENTIFICATION: 8BBOR4

MATERIAL

CODE: 304SS

YOUNG'S MODULUS: 206.84 (GPA), 30000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 244.76 (MPA), 35.5 (KSI)

ULTIMATE: 693.61 (MPA), 100.6 (KSI)

ORIENTATION: C-L

GEOMETRY: C(T)

WIDTH: 20.03 (MM), 0.7886 (IN)

THICKNESS: 10.033 (MM), 0.395 (IN)

SIDE GROOVE: 20 (PERCENT)

LOAD PIN CENTER SPAN: 9.906 (MM), 0.39 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 1.779 (KN), 400 (LB)

FREQUENCY: 30 (HZ)

FRONT SURFACE TO LOAD LINE DISTANCE: 4.983 (MM), 0.1962 (IN)

FRONT SURFACE TO INITIAL CRACK FRONT DISTANCES

DISTANCE 1: 15.601 (MM), 0.6142 (IN)

DISTANCE 2: 15.789 (MM), 0.6216 (IN)

DISTANCE 3: 15.926 (MM), 0.627 (IN)

DISTANCE 4: 16.04 (MM), 0.6315 (IN)

DISTANCE 5: 16.05 (MM), 0.6319 (IN)

DISTANCE 6: 16.096 (MM), 0.6337 (IN)

DISTANCE 7: 15.946 (MM), 0.6278 (IN)

DISTANCE 8: 15.71 (MM), 0.6185 (IN)

DISTANCE 9: 15.606 (MM), 0.6144 (IN)

FRONT SURFACE TO FINAL CRACK FRONT DISTANCES

DISTANCE 1: 18.476 (MM), 0.7274 (IN)

DISTANCE 2: 18.346 (MM), 0.7223 (IN)

DISTANCE 3: 18.435 (MM), 0.7258 (IN)

DISTANCE 4: 18.636 (MM), 0.7337 (IN)

DISTANCE 5: 18.773 (MM), 0.7391 (IN)

DISTANCE 6: 18.75 (MM), 0.7382 (IN)

DISTANCE 7: 18.39 (MM), 0.724 (IN)

DISTANCE 8: 18.339 (MM), 0.722 (IN)

DISTANCE 9: 18.425 (MM), 0.7254 (IN)

MEASURED CRACK LENGTHS

INITIAL: 10.912 (MM), 0.4296 (IN)

FINAL: 13.532 (MM), 0.5327 (IN)

TEST

ROUTINE REVISION: 1.02/07-JUL-88

TYPE: UCJR

ENGINEER: FMH

TECHNICIAN: RLS

TEST DATE: 18-FEB-92

ATMOSPHERE: AIR

TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

FILE NAME: 8BBOR4

DRIVE SPECIFIER: :, 700, 1

EXISTING UCJR TEST FILE PURGED

Attachment 1

Page 36 of 66

8BBOR4
ANALYZE

PAGE 2
19-FEB-92

UCJR TEST FILE CREATED
TEST SET SAVED
ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90
CRACK LENGTH PINS

UC

INITIAL

DETERMINATION TEST CYCLE: 1
EFFECTIVE MODULUS: 184.07 (GPA), 26698 (KSI)
YOUNG'S MODULUS-EFFECTIVE MODULUS: 11 (PERCENT)

FINAL

PIN NOT APPLIED

UC RESULTS

MEASURED FINAL CRACK EXTENSION: 2.62 (MM), 0.1032 (IN)
FINAL CRACK EXTENSION: 2.282 (MM), 0.0899 (IN)
FINAL CRACK EXTENSION ERROR: -12.9 (PERCENT)
PQ: 2.809 (KN), 632 (LB)
KQ: 23.01 (MPA-SQRT(M)), 20936 (KSI-SQRT(IN))
KIC: NO VALID KIC FOR TEST
PMX: 7.224 (KN), 1624 (LB)
KMX: 59.15 (MPA-SQRT(M)), 53.83 (KSI-SQRT(IN))

E1152 J-INTEGRAL

PMX J-INTEGRAL: 547.62 (KJ/M²), 3127 (IN-LB/IN²)
FINAL J-INTEGRAL: 921.12 (KJ/M²), 5259.7 (IN-LB/IN²)
FINAL KJ: 436.49 (MPA-SQRT(M)), 397.23 (KSI-SQRT(IN))
JIC: 688.1 (KJ/M²), 3929.2 (IN-LB/IN²)
KJIC: 377.26 (MPA-SQRT(M)), 343.33 (KSI-SQRT(IN))
TEARING MODULUS: 163

SPECIMEN

IDENTIFICATION: 8BB0R4
MATERIAL CODE: 304SS
ORIENTATION: C-L
GEOMETRY: 0.4TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 10.912 (MM), 0.4296 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	2.702	0.08	0.119	0	3.44	26.66
2	3.457	0.121	0.252	0.019	7.11	38.35
3	3.852	0.162	0.409	-0.019	11.75	49.29
4	4.274	0.241	0.756	0.034	21.45	66.61
5	4.605	0.324	1.147	-0.013	32.62	82.14
6	4.724	0.402	1.536	0.011	43.74	95.12
7	4.933	0.484	1.959	0.03	55.44	107.09
8	5.153	0.605	2.606	0.048	73.75	123.51
9	5.22	0.723	3.257	0.039	92.88	138.61
10	5.384	0.846	3.951	0.057	112.47	152.52
11	5.461	0.965	4.644	0.065	132.46	165.53
12	5.589	1.085	5.36	0.08	152.66	177.7
13	5.758	1.246	6.337	0.132	179.54	192.71
14	5.903	1.408	7.348	0.151	208.2	207.52
15	6.073	1.57	8.376	0.167	237.39	221.59
16	6.134	1.729	9.407	0.19	266.83	234.93
17	6.245	1.891	10.475	0.217	296.91	247.82
18	6.35	2.053	11.563	0.282	325.76	259.58
19	6.475	2.214	12.659	0.269	358.71	272.39
20	6.551	2.375	13.763	0.35	386.81	282.86
21	6.572	2.534	14.872	0.382	418.08	294.07
22	6.693	2.695	16.009	0.419	449.42	304.89
23	6.72	2.855	17.146	0.483	479.17	314.82
24	6.773	3.016	18.298	0.515	511.53	325.28
25	6.791	3.176	19.445	0.569	542.14	334.87
26	6.798	3.337	20.6	0.654	570	343.37
27	6.781	3.497	21.748	0.714	600.24	352.36
28	6.735	3.657	22.897	0.784	629.22	360.76
29	6.811	3.822	24.076	0.878	655.95	368.34
30	6.781	3.982	25.219	0.953	684.08	376.16
31	6.692	4.142	26.346	1.014	713.57	384.18
32	6.594	4.302	27.467	1.125	736.52	390.31
33	6.524	4.462	28.574	1.218	761.23	396.81
34	6.486	4.624	29.68	1.311	785.5	403.08
35	6.381	4.785	30.766	1.439	804.39	407.9
36	6.18	4.944	31.817	1.572	821.57	412.23
37	6.045	5.104	32.845	1.704	838.1	416.36
38	5.962	5.266	33.86	1.8	859.41	421.62
39	5.906	5.427	34.862	1.901	879.23	426.45
40	5.764	5.586	35.837	2.016	896.06	430.52

8BBOR4
ANALYZE

PAGE 4
19-FEB-92

41	5.629	5.747	36.8	2.146	909.68	433.77
42	5.509	5.909	37.743	2.282	921.12	436.49

SPECIMEN

IDENTIFICATION: 8BBOR4
MATERIAL CODE: 304SS
ORIENTATION: C-L
GEOMETRY: 0.4TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 10.912 (MM), 0.4296 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN^2)	KJ (KSI-SQRT(IN))
1	608	0.0031	1.05	0	19.6	24.26
2	777	0.0048	2.23	0.0007	40.6	34.9
3	866	0.0064	3.62	-0.0007	67.1	44.86
4	961	0.0095	6.69	0.0013	122.5	60.62
5	1035	0.0127	10.15	-0.0005	186.2	74.75
6	1062	0.0158	13.6	0.0005	249.8	86.56
7	1109	0.0191	17.34	0.0012	316.6	97.45
8	1158	0.0238	23.07	0.0019	421.1	112.4
9	1173	0.0285	28.83	0.0015	530.4	126.14
10	1210	0.0333	34.97	0.0022	642.2	138.8
11	1228	0.038	41.1	0.0026	756.4	150.64
12	1256	0.0427	47.44	0.0031	871.7	161.71
13	1295	0.0491	56.09	0.0052	1025.2	175.37
14	1327	0.0554	65.04	0.0059	1188.9	188.85
15	1365	0.0618	74.13	0.0066	1355.5	201.66
16	1379	0.0681	83.26	0.0075	1523.6	213.8
17	1404	0.0744	92.71	0.0086	1695.4	225.53
18	1428	0.0808	102.34	0.0111	1860.1	236.23
19	1456	0.0872	112.04	0.0106	2048.3	247.89
20	1473	0.0935	121.82	0.0138	2208.7	257.41
21	1478	0.0998	131.63	0.015	2387.3	267.62
22	1505	0.1061	141.69	0.0165	2566.3	277.47
23	1511	0.1124	151.76	0.019	2736.1	286.5
24	1523	0.1188	161.95	0.0203	2920.9	296.02
25	1527	0.125	172.1	0.0224	3095.7	304.75
26	1528	0.1314	182.33	0.0258	3254.8	312.48
27	1525	0.1377	192.49	0.0281	3427.5	320.66
28	1514	0.144	202.65	0.0309	3592.9	328.31
29	1531	0.1505	213.09	0.0346	3745.6	335.21
30	1525	0.1568	223.2	0.0375	3906.2	342.32
31	1504	0.1631	233.18	0.0399	4074.6	349.62
32	1482	0.1694	243.1	0.0443	4205.6	355.2
33	1467	0.1757	252.91	0.0479	4346.8	361.11
34	1458	0.182	262.69	0.0516	4485.3	366.82
35	1435	0.1884	272.3	0.0567	4593.2	371.21
36	1389	0.1947	281.6	0.0619	4691.3	375.15
37	1359	0.201	290.7	0.0671	4785.7	378.91
38	1340	0.2073	299.68	0.0709	4907.4	383.69
39	1328	0.2137	308.56	0.0749	5020.5	388.09
40	1296	0.2199	317.1	0.0754	5116.6	391.79

8BBOR4
ANALYZE

PAGE 6
19-FEB-92

41	1266	0.2263	325.71	0.0845	5194.4	394.76
42	1238	0.2326	334.06	0.0899	5259.7	397.23

COMMAND: ANALYZE
SPECIMEN IDENTIFICATION: 8BB0R4

PAGE 17
15-SEP-92

SPECIMEN

IDENTIFICATION: 6HA0R5

MATERIAL

CODE: 304SS

YOUNG'S MODULUS: 206.84 (GPA), 30000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 244.76 (MPA), 35.5 (KSI)

ULTIMATE: 693.61 (MPA), 100.6 (KSI)

ORIENTATION: L-C

GEOMETRY: C(T)

WIDTH: 20.051 (MM), 0.7894 (IN)

THICKNESS: 10.023 (MM), 0.3946 (IN)

SIDE GROOVE: 20 (PERCENT)

LOAD PIN CENTER SPAN: 9.906 (MM), 0.39 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 1.779 (KN), 400 (LB)

FREQUENCY: 30 (HZ)

FRONT SURFACE TO LOAD LINE DISTANCE: 4.95 (MM), 0.1949 (IN)

FRONT SURFACE TO INITIAL CRACK FRONT DISTANCES

DISTANCE 1: 15.26 (MM), 0.6008 (IN)

DISTANCE 2: 15.281 (MM), 0.6016 (IN)

DISTANCE 3: 15.509 (MM), 0.6106 (IN)

DISTANCE 4: 15.799 (MM), 0.622 (IN)

DISTANCE 5: 15.923 (MM), 0.6269 (IN)

DISTANCE 6: 16.017 (MM), 0.6306 (IN)

DISTANCE 7: 15.908 (MM), 0.6263 (IN)

DISTANCE 8: 15.639 (MM), 0.6157 (IN)

DISTANCE 9: 15.464 (MM), 0.6088 (IN)

FRONT SURFACE TO FINAL CRACK FRONT DISTANCES

DISTANCE 1: 18.136 (MM), 0.714 (IN)

DISTANCE 2: 17.925 (MM), 0.7057 (IN)

DISTANCE 3: 17.874 (MM), 0.7037 (IN)

DISTANCE 4: 18.341 (MM), 0.7221 (IN)

DISTANCE 5: 18.974 (MM), 0.747 (IN)

DISTANCE 6: 19.355 (MM), 0.762 (IN)

DISTANCE 7: 19.802 (MM), 0.7796 (IN)

DISTANCE 8: 19.51 (MM), 0.7681 (IN)

DISTANCE 9: 19.355 (MM), 0.762 (IN)

MEASURED CRACK LENGTHS

INITIAL: 10.729 (MM), 0.4224 (IN)

FINAL: 13.865 (MM), 0.5459 (IN)

TEST

ROUTINE REVISION: 1.02/07-JUL-88

TYPE: UCJR

ENGINEER: FMH

TECHNICIAN: RLS

TEST DATE: 19-FEB-92

ATMOSPHERE: AIR

TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

FILE NAME: 6HA0R5

DRIVE SPECIFIER: :, 700, 1

EXISTING UCJR TEST FILE PURGED

Attachment 1

Page 44 of 66

6HA0R5
ANALYZE

PAGE 2
19-FEB-92

UCJR TEST FILE CREATED
TEST SET SAVED
ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90
CRACK LENGTH PINS

UC

INITIAL

DETERMINATION TEST CYCLE: 1

EFFECTIVE MODULUS: 178.69 (GPA), 25917 (KSI)

YOUNG'S MODULUS-EFFECTIVE MODULUS: 13.6 (PERCENT)

FINAL

PIN NOT APPLIED

UC RESULTS

MEASURED FINAL CRACK EXTENSION: 3.136 (MM), 0.1235 (IN)

FINAL CRACK EXTENSION: 2.715 (MM), 0.1069 (IN)

FINAL CRACK EXTENSION ERROR: -13.4 (PERCENT)

PQ: 3.375 (KN), 759 (LB)

KQ: 26.77 (MPA-SQRT(M)), 24363 (KSI-SQRT(IN))

KIC: NO VALID KIC FOR TEST

PMX: 8.323 (KN), 1871 (LB)

KMX: 66.01 (MPA-SQRT(M)), 60.07 (KSI-SQRT(IN))

E1152 J-INTEGRAL

PMX J-INTEGRAL: 504.37 (KJ/M²), 2880 (IN-LB/IN²)

FINAL J-INTEGRAL: 1056 (KJ/M²), 6030.1 (IN-LB/IN²)

FINAL KJ: 467.37 (MPA-SQRT(M)), 425.33 (KSI-SQRT(IN))

JIC: 601.82 (KJ/M²), 3436.5 (IN-LB/IN²)

KJIC: 352.82 (MPA-SQRT(M)), 321.08 (KSI-SQRT(IN))

TEARING MODULUS: 256

SPECIMEN

IDENTIFICATION: 6HA0R5
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 10.729 (MM), 0.4224 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	3.582	0.102	0.197	0.001	5.58	33.98
2	4.209	0.127	0.296	-0.02	8.52	41.98
3	4.765	0.153	0.416	-0.037	12.02	49.86
4	5.221	0.179	0.551	-0.006	15.72	57.03
5	5.585	0.206	0.699	-0.005	19.92	64.19
6	5.811	0.231	0.848	-0.011	24.26	70.83
7	6.028	0.257	1.008	-0.004	28.79	77.17
8	6.206	0.283	1.176	-0.003	33.52	83.27
9	6.434	0.325	1.447	0.008	41.06	92.16
10	6.553	0.365	1.718	-0.007	49.08	100.75
11	6.691	0.408	2.015	0.027	57.12	108.69
12	6.829	0.468	2.442	0.042	69.15	119.6
13	6.88	0.527	2.867	0.037	81.79	130.07
14	7.027	0.604	3.427	0.051	97.59	142.07
15	7.108	0.679	3.992	0.08	113.33	153.11
16	7.288	0.758	4.587	0.069	130.32	164.18
17	7.357	0.858	5.356	0.095	152.07	177.36
18	7.441	0.959	6.143	0.08	175.21	190.37
19	7.554	1.061	6.951	0.137	196.75	201.73
20	7.673	1.189	7.97	0.151	225.79	216.11
21	7.67	1.315	8.991	0.183	254.57	229.47
22	7.76	1.441	10.023	0.235	282	241.52
23	7.771	1.596	11.284	0.32	315.01	255.26
24	7.807	1.748	12.535	0.409	347.19	267.98
25	7.878	1.901	13.793	0.489	379.99	280.35
26	7.9	2.054	15.053	0.516	416.23	293.42
27	7.889	2.206	16.307	0.592	448.99	304.75
28	7.913	2.358	17.57	0.63	484.6	316.6
29	7.897	2.509	18.824	0.687	518.46	327.48
30	7.875	2.689	20.309	0.785	555.56	338.99
31	7.801	2.865	21.759	0.877	592.49	350.07
32	7.83	3.045	23.225	0.95	630.82	361.22
33	7.767	3.222	24.67	1.045	666.49	371.29
34	7.696	3.399	26.095	1.119	704.06	381.61
35	7.628	3.601	27.724	1.2	746.89	393.05
36	7.528	3.804	29.337	1.318	784.32	402.78
37	7.388	4.008	30.926	1.452	818.54	411.47
38	7.222	4.211	32.471	1.585	851.69	419.72
39	7.091	4.414	33.988	1.704	885.44	427.96
40	6.845	4.617	35.483	1.865	911.51	434.21

6HA0R5
ANALYZE

PAGE 4
19-FEB-92

41	6.791	4.82	36.936	1.99	942.41	441.51
42	6.692	5.023	38.369	2.111	972.73	448.56
43	6.465	5.226	39.76	2.246	999.19	454.62
44	6.309	5.428	41.112	2.37	1026.2	460.72
45	6.179	5.632	42.444	2.507	1049.4	465.9
46	5.872	5.837	43.732	2.715	1056.03	467.37

SPECIMEN

IDENTIFICATION: 6HAOR5
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 10.729 (MM), 0.4224 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN^2)	KJ (KSI-SQRT(IN))
1	805	0.004	1.74	0	31.9	30.93
2	946	0.005	2.62	-0.0008	48.7	38.2
3	1071	0.006	3.68	-0.0015	68.6	45.38
4	1174	0.0071	4.88	-0.0002	89.8	51.9
5	1255	0.0081	6.18	-0.0002	113.8	58.42
6	1306	0.0091	7.51	-0.0005	138.5	64.46
7	1355	0.0101	8.92	-0.0001	164.4	70.23
8	1395	0.0112	10.41	-0.0001	191.4	75.78
9	1446	0.0128	12.81	0.0003	234.5	83.87
10	1473	0.0144	15.2	-0.0003	280.2	91.69
11	1504	0.0161	17.83	0.0011	326.1	98.92
12	1535	0.0184	21.61	0.0017	394.9	108.84
13	1547	0.0208	25.37	0.0015	467	118.37
14	1580	0.0238	30.34	0.002	557.2	129.29
15	1598	0.0267	35.33	0.0032	647.1	139.33
16	1638	0.0298	40.6	0.0027	744.1	149.41
17	1654	0.0338	47.4	0.0037	868.4	161.4
18	1673	0.0378	54.37	0.0031	1000.5	173.25
19	1698	0.0418	61.52	0.0054	1123.5	183.59
20	1725	0.0468	70.54	0.006	1289.3	196.67
21	1724	0.0518	79.58	0.0072	1453.6	208.83
22	1744	0.0567	88.71	0.0093	1610.3	219.79
23	1747	0.0628	99.88	0.0126	1798.7	232.3
24	1755	0.0688	110.95	0.0161	1982.5	243.87
25	1771	0.0749	122.08	0.0193	2169.8	255.13
26	1776	0.0809	133.23	0.0203	2376.7	267.02
27	1773	0.0868	144.33	0.0233	2563.8	277.33
28	1779	0.0928	155.51	0.0248	2767.1	288.12
29	1775	0.0988	166.61	0.0271	2960.5	298.02
30	1770	0.1059	179.75	0.0309	3172.4	308.5
31	1754	0.1128	192.59	0.0345	3383.2	318.58
32	1760	0.1199	205.55	0.0374	3602.1	328.73
33	1746	0.1269	218.35	0.0412	3805.8	337.89
34	1730	0.1338	230.96	0.0441	4020.3	347.29
35	1715	0.1418	245.38	0.0472	4264.9	357.69
36	1692	0.1498	259.66	0.0519	4478.6	366.55
37	1661	0.1578	273.71	0.0572	4674	374.46
38	1624	0.1658	287.4	0.0624	4863.3	381.97
39	1594	0.1738	300.82	0.0671	5056	389.46
40	1566	0.1818	314.05	0.0734	5204.9	395.15

6HA0R5
ANALYZE

PAGE 6
19-FEB-92

41	1527	0.1898	326.91	0.0783	5381.3	401.8
42	1504	0.1978	339.6	0.0831	5554.5	408.21
43	1453	0.2057	351.91	0.0884	5705.5	413.72
44	1418	0.2137	363.87	0.0933	5859.7	419.28
45	1389	0.2217	375.66	0.0987	5992.2	423.99
46	1320	0.2298	387.06	0.1069	6030.1	425.33

SPECIMEN

IDENTIFICATION: 6HA0R6

MATERIAL

CODE: 304SS

YOUNG'S MODULUS: 206.84 (GPA), 30000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 244.76 (MPA), 35.5 (KSI)

ULTIMATE: 693.61 (MPA), 100.6 (KSI)

ORIENTATION: L-C

GEOMETRY: C(T)

WIDTH: 20 (MM), 0.7874 (IN)

THICKNESS: 10.018 (MM), 0.3944 (IN)

SIDE GROOVE: 0 (PERCENT)

LOAD PIN CENTER SPAN: 9.906 (MM), 0.39 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 1.779 (KN), 400 (LB)

FREQUENCY: 30 (HZ)

FRONT SURFACE TO LOAD LINE DISTANCE: 4.999 (MM), 0.1968 (IN)

FRONT SURFACE TO INITIAL CRACK FRONT DISTANCES

DISTANCE 1: 14.818 (MM), 0.5834 (IN)

DISTANCE 2: 15.194 (MM), 0.5982 (IN)

DISTANCE 3: 15.479 (MM), 0.6094 (IN)

DISTANCE 4: 15.593 (MM), 0.6139 (IN)

DISTANCE 5: 15.845 (MM), 0.6238 (IN)

DISTANCE 6: 16.012 (MM), 0.6304 (IN)

DISTANCE 7: 15.911 (MM), 0.6264 (IN)

DISTANCE 8: 15.641 (MM), 0.6158 (IN)

DISTANCE 9: 15.088 (MM), 0.594 (IN)

FRONT SURFACE TO FINAL CRACK FRONT DISTANCES

DISTANCE 1: 16.32 (MM), 0.6425 (IN)

DISTANCE 2: 16.393 (MM), 0.6454 (IN)

DISTANCE 3: 17.008 (MM), 0.6696 (IN)

DISTANCE 4: 17.678 (MM), 0.696 (IN)

DISTANCE 5: 18.557 (MM), 0.7306 (IN)

DISTANCE 6: 19.098 (MM), 0.7519 (IN)

DISTANCE 7: 18.74 (MM), 0.7378 (IN)

DISTANCE 8: 17.785 (MM), 0.7002 (IN)

DISTANCE 9: 17.412 (MM), 0.6855 (IN)

MEASURED CRACK LENGTHS

INITIAL: 10.58 (MM), 0.4165 (IN)

FINAL: 12.767 (MM), 0.5026 (IN)

TEST

ROUTINE REVISION: 1.02/07-JJL-88

TYPE: UCJR

ENGINEER: FMH

TECHNICIAN: RLS

TEST DATE: 19-FEB-92

ATMOSPHERE: AIR

TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

FILE NAME: 6HA0R6

DRIVE SPECIFIER: :, 700, 1

EXISTING UCJR TEST FILE PURGED

6HA0R6
ANALYZE

PAGE 2
19-FEB-92

UCJR TEST FILE CREATED
TEST SET SAVED
ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90
CRACK LENGTH PINS

UC

INITIAL

DETERMINATION TEST CYCLE: 1
EFFECTIVE MODULUS: 182.25 (GPA), 26433 (KSI)
YOUNG'S MODULUS-EFFECTIVE MODULUS: 11.9 (PERCENT)

FINAL

PIN NOT APPLIED

UC RESULTS

MEASURED FINAL CRACK EXTENSION: 2.187 (MM), 0.0861 (IN)
FINAL CRACK EXTENSION: 1.837 (MM), 0.0723 (IN)
FINAL CRACK EXTENSION ERROR: -16 (PERCENT)
PQ: 3.586 (KN), 806 (LB)
KQ: 26.8 (MPA-SQRT(M)), 24392 (KSI-SQRT(IN))
KIC: NO VALID KIC FOR TEST
PMX: 9.886 (KN), 2223 (LB)
KMX: 73.9 (MPA-SQRT(M)), 67.25 (KSI-SQRT(IN))

E1152 J-INTEGRAL

PMX J-INTEGRAL: 615.25 (KJ/M²), 3513.1 (IN-LB/IN²)
FINAL J-INTEGRAL: 1068 (KJ/M²), 6098.4 (IN-LB/IN²)
FINAL KJ: 470.01 (MPA-SQRT(M)), 427.73 (KSI-SQRT(IN))
JIC: 868.13 (KJ/M²), 4957.1 (IN-LB/IN²)
KJIC: 423.75 (MPA-SQRT(M)), 385.63 (KSI-SQRT(IN))
TEARING MODULUS: 227

SPECIMEN

IDENTIFICATION: 6HAOR6
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.39TC(T) NO SIDE GROOVE
INITIAL CRACK LENGTH: 10.58 (MM), 0.4165 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	4.024	0.103	0.222	0.001	5.03	32.25
2	5.248	0.153	0.459	0.017	10.68	47.01
3	6.115	0.206	0.776	0.021	17.83	60.72
4	6.585	0.258	1.116	0.034	25.64	72.83
5	7.06	0.36	1.858	0.032	42.59	93.86
6	7.369	0.464	2.651	0.031	60.51	111.88
7	7.689	0.621	3.897	0.074	88.15	135.03
8	7.847	0.775	5.167	0.1	116.77	155.41
9	8.042	0.929	6.467	0.1	146.37	174
10	8.242	1.087	7.829	0.154	176.08	190.84
11	8.445	1.296	9.665	0.167	217.8	212.25
12	8.635	1.503	11.529	0.207	259.17	231.53
13	8.798	1.71	13.431	0.245	301.5	249.73
14	8.928	1.916	15.357	0.299	343.55	266.57
15	9.034	2.123	17.314	0.291	389.67	283.9
16	9.14	2.331	19.31	0.382	430.67	298.46
17	9.282	2.54	21.325	0.394	477	314.11
18	9.347	2.747	23.336	0.449	520.28	328.05
19	9.39	2.954	25.367	0.534	561.51	340.8
20	9.402	3.16	27.393	0.564	607.43	354.46
21	9.361	3.367	29.427	0.643	648.59	366.27
22	9.339	3.574	31.454	0.706	691.33	378.15
23	9.278	3.781	33.471	0.815	728.61	388.21
24	9.209	3.987	35.47	0.858	772.83	399.82
25	9.121	4.194	37.455	1.008	803.43	407.66
26	9.08	4.401	39.428	1.068	845.31	418.15
27	9.124	4.61	41.417	1.13	886.77	428.28
28	8.977	4.817	43.368	1.251	919	435.99
29	8.833	5.024	45.289	1.366	951.22	443.57
30	8.638	5.23	47.163	1.468	984.34	451.22
31	8.518	5.438	49.023	1.639	1004.66	455.86
32	8.3	5.643	50.823	1.738	1037.02	463.14
33	8.217	5.852	52.627	1.837	1068	470.01

SPECIMEN

IDENTIFICATION: 6HA0R6
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.39TC(T) NO SIDE GROOVE
INITIAL CRACK LENGTH: 10.58 (MM), 0.4165 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN^2)	KJ (KSI-SQRT(IN))
1	905	0.0041	1.97	0	28.7	29.35
2	1180	0.006	4.06	0.0007	61	42.78
3	1375	0.0081	6.86	0.0008	101.8	55.26
4	1480	0.0101	9.88	0.0013	146.4	66.28
5	1587	0.0142	16.44	0.0012	243.2	85.42
6	1657	0.0183	23.47	0.0012	345.5	101.82
7	1729	0.0244	34.49	0.0029	503.4	122.88
8	1764	0.0305	45.73	0.0039	666.8	141.43
9	1808	0.0366	57.24	0.0039	835.8	158.35
10	1853	0.0428	69.29	0.006	1005.5	173.68
11	1899	0.051	85.55	0.0066	1243.7	193.16
12	1941	0.0592	102.04	0.0082	1479.9	210.71
13	1978	0.0673	118.88	0.0097	1721.6	227.26
14	2007	0.0754	135.92	0.0118	1961.7	242.6
15	2031	0.0836	153.24	0.0115	2225.1	258.36
16	2055	0.0918	170.91	0.0151	2459.2	271.62
17	2087	0.1	188.75	0.0155	2723.7	285.85
18	2101	0.1081	206.54	0.0177	2970.9	298.54
19	2111	0.1163	224.52	0.021	3206.3	310.14
20	2114	0.1244	242.45	0.0222	3468.5	322.58
21	2104	0.1326	260.45	0.0253	3703.6	333.33
22	2100	0.1407	278.39	0.0278	3947.6	344.13
23	2086	0.1489	296.25	0.0321	4160.5	353.29
24	2070	0.157	313.93	0.0338	4413	363.85
25	2050	0.1651	331.51	0.0397	4587.7	370.99
26	2041	0.1733	348.97	0.042	4826.8	380.53
27	2051	0.1815	366.57	0.0445	5063.6	389.75
28	2018	0.1896	383.84	0.0492	5247.6	396.77
29	1986	0.1978	400.84	0.0538	5431.6	403.67
30	1942	0.2059	417.43	0.0578	5620.7	410.64
31	1915	0.2141	433.89	0.0645	5736.8	414.85
32	1866	0.2222	449.83	0.0684	5921.5	421.48
33	1847	0.2304	465.79	0.0723	6098.4	427.73

SPECIMEN

IDENTIFICATION: 8BBOR2

MATERIAL

CODE: 304SS

YOUNG'S MODULUS: 206.84 (GPA), 30000 (KSI)

POISSON'S RATIO: 0.3

STRENGTHS

YIELD: 244.76 (MPA), 35.5 (KSI)

ULTIMATE: 693.61 (MPA), 100.6 (KSI)

ORIENTATION: L-C

GEOMETRY: C(T)

WIDTH: 20.056 (MM), 0.7896 (IN)

THICKNESS: 10.023 (MM), 0.3946 (IN)

SIDE GROOVE: 20 (PERCENT)

LOAD PIN CENTER SPAN: 9.906 (MM), 0.39 (IN)

EXTENSOMETER LOCATION: 0 (MM), 0 (IN)

PRECRACK CONDITIONS

MAXIMUM LOAD: 1.779 (KN), 400 (LB)

FREQUENCY: 30 (HZ)

FRONT SURFACE TO LOAD LINE DISTANCE: 4.966 (MM), 0.1955 (IN)

FRONT SURFACE TO INITIAL CRACK FRONT DISTANCES

DISTANCE 1: 15.471 (MM), 0.6091 (IN)

DISTANCE 2: 15.53 (MM), 0.6114 (IN)

DISTANCE 3: 16.048 (MM), 0.6318 (IN)

DISTANCE 4: 16.18 (MM), 0.637 (IN)

DISTANCE 5: 16.281 (MM), 0.641 (IN)

DISTANCE 6: 16.243 (MM), 0.6395 (IN)

DISTANCE 7: 16.175 (MM), 0.6368 (IN)

DISTANCE 8: 15.784 (MM), 0.6214 (IN)

DISTANCE 9: 15.71 (MM), 0.6185 (IN)

FRONT SURFACE TO FINAL CRACK FRONT DISTANCES

DISTANCE 1: 16.454 (MM), 0.6478 (IN)

DISTANCE 2: 16.396 (MM), 0.6455 (IN)

DISTANCE 3: 16.52 (MM), 0.6504 (IN)

DISTANCE 4: 16.767 (MM), 0.6601 (IN)

DISTANCE 5: 16.817 (MM), 0.6621 (IN)

DISTANCE 6: 16.726 (MM), 0.6585 (IN)

DISTANCE 7: 16.662 (MM), 0.656 (IN)

DISTANCE 8: 16.363 (MM), 0.6442 (IN)

DISTANCE 9: 16.37 (MM), 0.6445 (IN)

MEASURED CRACK LENGTHS

INITIAL: 11.013 (MM), 0.4336 (IN)

FINAL: 11.617 (MM), 0.4574 (IN)

TEST

ROUTINE REVISION: 1.02/07-JUL-88

TYPE: UCJR

ENGINEER: FMH

TECHNICIAN: RLS

TEST DATE: 14-FEB-92

ATMOSPHERE: AIR

TEMPERATURE: 21.1 (DEG C), 70 (DEG F)

REMARK: NONE

DID SPECIMEN CLEAVE? NO

FILE NAME: 8BBOR2

DRIVE SPECIFIER: :, 700, 1

OVERWRITE EXISTING 8BBOR2: , 700, 1 FILE? YES

EXISTING FILE PURGED
UCJR TEST FILE CREATED
TEST SET SAVED
ANALYSIS

ROUTINE REVISION: 1.10/06-MAR-90

CRACK LENGTH PINS

UC

INITIAL

DETERMINATION TEST CYCLE: 1

EFFECTIVE MODULUS: 186.85 (GPA), 27101 (KSI)

YOUNG'S MODULUS-EFFECTIVE MODULUS: 9.7 (PERCENT)

FINAL

PIN NOT APPLIED

UC RESULTS

MEASURED FINAL CRACK EXTENSION: 0.604 (MM), 0.0238 (IN)

FINAL CRACK EXTENSION: 0.564 (MM), 0.0222 (IN)

#FINAL CRACK EXTENSION ERROR: -6.6 (PERCENT)

PQ: 3.099 (KN), 697 (LB)

KQ: 25.76 (MPA-SQRT(M)), 23446 (KSI-SQRT(IN))

KIC: NO VALID KIC FOR TEST

PMX: 7.501 (KN), 1686 (LB)

KMX: 62.37 (MPA-SQRT(M)), 56.76 (KSI-SQRT(IN))

E1152 J-INTEGRAL

PMX J-INTEGRAL: 596.76 (KJ/M²), 3407.6 (IN-LB/IN²)

#FINAL J-INTEGRAL: 601.17 (KJ/M²), 3432.7 (IN-LB/IN²)

#FINAL KJ: 352.63 (MPA-SQRT(M)), 320.91 (KSI-SQRT(IN))

JIC: NO POWER-LAW MODEL AVAILABLE

KJIC: NO POWER-LAW MODEL AVAILABLE

TEARING MODULUS: NO POWER-LAW MODEL AVAILABLE

#ESTIMATED FINAL CRACK LENGTH

SPECIMEN

IDENTIFICATION: 8BB0R2
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 11.013 (MM)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 21.1 (DEG C)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (KN)	DISPL (MM)	ENERGY (J)	CRACK EXTN (MM)	J-INTEGRAL (KJ/M^2)	KJ (MPA-SQRT(M))
1	3.096	0.093	0.157	0	4.41	30.22
2	3.39	0.107	0.204	-0.002	5.77	34.54
3	3.582	0.121	0.251	-0.027	7.3	38.86
4	3.907	0.145	0.344	-0.018	9.86	45.15
5	4.062	0.166	0.434	-0.002	12.63	51.11
6	4.236	0.189	0.536	-0.046	15.71	57.01
7	4.439	0.215	0.651	-0.017	18.78	62.33
8	4.536	0.238	0.76	0.003	21.89	67.28
9	4.679	0.272	0.924	0.013	26.56	74.12
10	4.713	0.302	1.076	0.009	31.27	80.42
11	4.833	0.336	1.246	0.01	36.09	86.4
12	4.974	0.383	1.492	0.008	43.11	94.42
13	5.057	0.429	1.734	0.009	50.1	101.8
14	5.134	0.477	1.988	0.02	57.44	109
15	5.203	0.523	2.244	0.039	64.7	115.69
16	5.305	0.585	2.584	0.036	74.58	124.2
17	5.384	0.645	2.927	0.035	84.58	132.27
18	5.367	0.704	3.263	0.067	94.3	139.66
19	5.545	0.781	3.708	0.057	107.04	148.8
20	5.621	0.854	4.142	0.07	119.46	157.19
21	5.72	0.947	4.697	0.079	135.48	167.4
22	5.788	1.038	5.256	0.109	151.18	176.83
23	5.899	1.154	5.973	0.141	171.4	188.29
24	5.992	1.27	6.701	0.168	192.07	199.32
25	6.084	1.385	7.44	0.182	213.41	210.1
26	6.205	1.501	8.196	0.179	235.72	220.81
27	6.26	1.617	8.956	0.224	256.59	230.38
28	6.346	1.733	9.729	0.208	280.19	240.74
29	6.442	1.872	10.674	0.238	306.87	251.94
30	6.52	2.012	11.632	0.257	334.49	263.03
31	6.602	2.151	12.6	0.312	360.45	273.05
32	6.678	2.291	13.58	0.296	390.75	284.3
33	6.761	2.43	14.572	0.372	415.77	293.25
34	6.811	2.57	15.57	0.365	446.48	303.89
35	6.876	2.709	16.58	0.424	472.71	312.69
36	6.905	2.848	17.592	0.466	500.45	321.74
37	6.973	2.988	18.616	0.511	528.1	330.51
38	7.009	3.127	19.641	0.522	558.74	339.96
39	7.058	3.266	20.675	0.552	587.86	348.7
#40	7.497	3.325	21.119	0.564	601.17	352.63

#ESTIMATED FINAL CRACK LENGTH

SPECIMEN

IDENTIFICATION: 8BBOR2
MATERIAL CODE: 304SS
ORIENTATION: L-C
GEOMETRY: 0.39TC(T) 20 PERCENT SIDE GROOVE
INITIAL CRACK LENGTH: 0.4336 (IN)

TEST

ATMOSPHERE: AIR
TEMPERATURE: 70 (DEG F)

ANALYSIS

CRACK LENGTH PINS: INITIAL
CRACK EXTENSION METHOD: UNLOADING COMPLIANCE
J-INTEGRAL METHOD: E1152

CYCLE	LOAD (LB)	DISPL (IN)	ENERGY (FT-LB)	CRACK EXTN (IN)	J-INTEGRAL (IN-LB/IN ²)	KJ (KSI-SQRT(IN))
1	696	0.0037	1.39	0	25.2	27.5
2	762	0.0042	1.81	-0.0001	32.9	31.43
3	805	0.0047	2.22	-0.0011	41.7	35.37
4	878	0.0057	3.05	-0.0007	56.3	41.09
5	913	0.0065	3.84	-0.0001	72.1	46.51
6	952	0.0075	4.75	-0.0018	89.7	51.88
7	998	0.0084	5.76	-0.0007	107.2	56.72
8	1020	0.0094	6.73	0.0001	125	61.23
9	1052	0.0107	8.18	0.0005	151.7	67.45
10	1060	0.0119	9.53	0.0004	178.6	73.19
11	1086	0.0132	11.03	0.0004	206.1	78.63
12	1118	0.0151	13.2	0.0003	246.1	85.93
13	1137	0.0169	15.34	0.0004	286.1	92.64
14	1154	0.0188	17.59	0.0008	328	99.2
15	1170	0.0206	19.86	0.0015	369.5	105.28
16	1193	0.023	22.87	0.0014	425.9	113.03
17	1210	0.0254	25.9	0.0014	483	120.37
18	1207	0.0277	28.88	0.0026	538.5	127.1
19	1247	0.0307	32.82	0.0022	611.2	135.41
20	1264	0.0336	36.66	0.0027	682.1	143.05
21	1286	0.0373	41.57	0.0031	773.6	152.34
22	1301	0.0409	46.52	0.0043	863.2	160.93
23	1326	0.0454	52.87	0.0056	978.7	171.35
24	1347	0.05	59.31	0.0066	1096.8	181.39
25	1368	0.0545	65.85	0.0072	1218.6	191.2
26	1395	0.0591	72.54	0.0071	1346	200.95
27	1407	0.0636	79.26	0.0088	1465.2	209.66
28	1427	0.0682	86.11	0.0082	1599.9	219.08
29	1448	0.0737	94.47	0.0094	1752.3	229.28
30	1466	0.0792	102.95	0.0101	1910	239.37
31	1484	0.0847	111.52	0.0123	2058.2	248.49
32	1501	0.0902	120.19	0.0117	2231.3	258.72
33	1520	0.0957	128.97	0.0146	2374.1	266.88
34	1531	0.1012	137.8	0.0144	2549.4	276.56
35	1546	0.1067	146.74	0.0167	2699.2	284.57
36	1552	0.1121	155.7	0.0183	2857.7	292.8
37	1568	0.1176	164.76	0.0201	3015.5	300.78
38	1576	0.1231	173.84	0.0206	3190.5	309.38
39	1587	0.1286	182.99	0.0217	3356.8	317.34
#40	1685	0.1309	186.92	0.0222	3432.7	320.91

#ESTIMATED FINAL CRACK LENGTH

AIM

Association for Information and Image Management

1100 Wayne Avenue, Suite 1100
Silver Spring, Maryland 20910
301/587-8202

Centimeter

Inches

MANUFACTURED TO AIM STANDARDS
BY APPLIED IMAGE, INC.

2 of 2

**DATE
FILMED**

9 / 9 / 93

END