Nevada
Environmental
Restoration
Project

DOE/NV-11718-168
UC-702

RECEIVED
NOV 27 1998
OSTI

Closure Report
for Housekeeping Category
Corrective Action Unit 353
Nevada Test Site

UNCONTROLLED COPY

Controlled Copy No. _____

Revision: 0

January 1998

Environmental Restoration
Division

U.S. Department of Energy
Nevada Operations Office

**CLOSURE REPORT FOR HOUSEKEEPING CATEGORY
CORRECTIVE ACTION UNIT 353
NEVADA TEST SITE**

**Prepared for
U.S. Department of Energy
Nevada Operations Office
Under Contract No. DE-AC08-96NV11718**

UNCONTROLLED COPY

Controlled Copy No.: _____

Revision: 0

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

**Prepared by
Bechtel Nevada
Environmental Restoration**

MASTER

January 1998

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

FFACO HOUSEKEEPING CATEGORY CORRECTIVE ACTION UNIT 353

CAS NUMBER	DESCRIPTION OF CAS	STATUS
22-22-01	(7) Buckets	The items were retrieved along with other debris and disposed. No further action required.
22-99-02	Water Fill	The inactive water shed was filled with native soil and the metal cover was disposed. No further action required.
22-99-03	Ammunition Storage Area	Used by Camp Desert Rock soldiers, only metal debris and fencing materials remained for disposal. Additional materials cleaned from the area, consisting of vehicle parts and debris, included 22-19-02, 22-99-04, and 22-99-05. No further action required.

**FFACO CORRECTIVE ACTION SITE
HOUSEKEEPING CLOSURE VERIFICATION FORM**

Closure Verification Date: 09-AUG-97

CAS Number: 22-22-01

CAU Number: 353

General Location: Weather Station

Elevation:

Latitude:

Northing: 682,657.144

Longitude:

Easting: 691,164.332

Coordinate/Elevation Data Obtained from Garmin 40 Global Position System: Accuracy is within 300 ft Horizontal - Vertical Varies with Locality

Site Access Route: Mercury Hwy south through Gate 100, proceeding to Desert Rock Airstrip Rd. Turn right (west) and proceed 0.5 mi to access road, turn left (south) and go approx. 0.1 mi to end of pavement. The CAS is 50 feet south of end of pavement (approx. 250 yds east of Air Resources Laboratory [Weather Station]).

Waste Item(s) Originally at Site	Apparent Waste Type*
Buckets (7)	Ordinary

* Ordinary, Scrap Metal, Asbestos, PCB, Salvageable, Hazardous, Radioactive, Mixed, Unknown, Other

CAS Prior to Cleanup

CAS After Cleanup

Current Site Description/Observations: Originally identified on 24-JAN-91, NTS personnel retrieved seven empty 5-gal. metal buckets and steel cable segments on 09-AUG-97. This location is formerly known as a petroleum oil and lubricants dump and was active during the Camp Desert Rock encampment period (circa 1950s). No hydrocarbon-type staining was observed in the area. All solid waste was disposed at the Area 9 U10c Landfill.

☒ **No Further Action Required at Corrective Action Site**

C. Carlos Gonzales

C. Carlos Gonzales

1-6-98

Corrective Action Coordinator/Designee

(Signature)

Date

**FFACO CORRECTIVE ACTION SITE
HOUSEKEEPING CLOSURE VERIFICATION FORM**

Closure Verification Date: 05-SEP-97

CAS Number: 22-99-02

CAU Number: 353

General Location: Gate 100 (Power Pole #44)

Elevation:

Latitude:

Northing: 686,420.327

Longitude:

Easting: 694,065.769

Coordinate/Elevation Data Obtained from Garmin 40 Global Position System: Accuracy is within 300 ft Horizontal - Vertical Varies with Locality

Site Access Route: Mercury Hwy south through Gate 100, proceeding approximately 0.85 mi to power pole #44. CAS is on right (west) side of Mercury Hwy, approx. 104 feet from road, due west of power pole.

Waste Item(s) Originally at Site	Apparent Waste Type*
Water Fill	Ordinary

* Ordinary, Scrap Metal, Asbestos, PCB, Salvageable, Hazardous, Radioactive, Mixed, Unknown, Other

CAS Prior to Cleanup

CAS After Cleanup

Current Site Description/Observations: Originally identified on 24-JAN-91, NTS field crews verified its location on 05-AUG-93. Per conversations with the NTS Water Department, this water shed was used in the early 1950s, but has been inactive ever since. NTS personnel removed the sheet metal cover for disposal at the A-23 Landfill and filled the cement trough with native desert soil. A marker at the northeast corner of the trough identifies the CAS.

☒ **No Further Action Required at Corrective Action Site**

C. Carlos Gonzales

Corrective Action Coordinator/Designee

C. Carlos Gonzales

(Signature)

1-6-98

Date

FFACO CORRECTIVE ACTION SITE HOUSEKEEPING CLOSURE VERIFICATION FORM

Closure Verification Date: 05-SEP-97

CAS Number: 22-99-03

CAU Number: 353

General Location: ARL/Camp Desert Rock

Elevation:

Latitude:

Northing:

Longitude:

Easting:

Coordinate/Elevation Data Obtained from Garmin 40 Global Position System: Accuracy is within 300 ft Horizontal - Vertical Varies with Locality

Site Access Route: Mercury Hwy south through Gate 100, proceeding to Desert Rock Airstrip Rd. Turn right (west) and proceed to Air Resources Lab (Weather Station) on left (south) side of road. The CAS is located approx. 600 feet south of the weather station.

Waste Item(s) Originally at Site	Apparent Waste Type*
Ammunition Storage Area (empty)	Ordinary

* Ordinary, Scrap Metal, Asbestos, PCB, Salvageable, Hazardous, Radioactive, Mixed, Unknown, Other

CAS Prior to Cleanup

CAS After Cleanup

Current Site Description/Observations: Originally identified on 24-JAN-91, field crews verified its location on 26-SEP-95. Used by the military in the 1950s, only metal debris and fencing remained and were retrieved for disposal by NTS personnel. Three CASs which were in close vicinity were also cleaned: 22-99-04, consisting of metal debris and fencing; 22-99-05, military vehicle parts and metal debris; and 22-19-02, consisting of military vehicle parts and metal debris. An area surrounding AEC Well #6 (10/9/51), SE of 22-99-03, was also cleaned of metal and glass debris. Markers identify each of the FFACO CASs.

☒ No Further Action Required at Corrective Action Site

C. Carlos Gonzales

C. Carlos Gonzales

1-6-98

Corrective Action Coordinator/Designee

(Signature)

Date

DISTRIBUTION LIST

	Copies
U. S. Department of Energy, Nevada Operations Office P. O. Box 98518 Las Vegas, NV 89193-8518	
J. L. Appenzeller-Wing	1
Public Reading Room	2
Technical Information Resource Center	1
U. S. Department of Energy, Office of Scientific and Technical Information 175 Oak Ridge Turnpike P. O. Box 62 Oak Ridge, TN 37831	2
Bechtel Nevada P. O. Box 98521 Las Vegas, NV 89193-8521	
D. K. Cowser	1
J. R. Kannard	1
C. C. Gonzales	1
IT Corporation 4330 South Valley View, Suite 114 Las Vegas, NV 89103-4047	
R. C. Silver	4