Nevada
Environmental
Restoration
Project

RECEIVED
NOV 27 1998
OST

DOE/NV-11718-215
UC-702

Closure Report for
Corrective Action Unit 211
Area 15 EPA Farm Waste Sites
Nevada Test Site, Nevada

Controlled Copy No.:

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Revision: 0

April 1998

MASTER

Approved for public release; further distribution is authorized

Environmental Restoration
Division

U.S. Department of Energy
Nevada Operations Office

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

**CLOSURE REPORT FOR
CORRECTIVE ACTION UNIT 211
AREA 15 EPA FARM WASTE SITES,
NEVADA TEST SITE, NEVADA**

**Prepared for
U. S. Department of Energy
Nevada Operations Office
Under Contract No. DE-AC08-96NV11718**

Controlled Copy No.: _____

Revision: 0

**Prepared by
Bechtel Nevada
Environmental Restoration**

April 1998

**CLOSURE REPORT FOR
CORRECTIVE ACTION UNIT 211
AREA 15 EPA FARM WASTE SITES
NEVADA TEST SITE, NEVADA**

Approved by:

Janet Appenzeller-Wing

Janet L. Appenzeller-Wing, Project Manager
Industrial Sites Subproject

Date:

4/14/98

Approved by:

Robert M. Bangert Jr.

for Runore C. Wycoff, Project Manager
Nevada Environmental Restoration Project

Date:

4/14/98

SUMMARY OF CORRECTIVE ACTIONS FOR CAU 211

Corrective Action Site	Waste Description	Corrective Action
15-01-02	Scrap Metal	Removed from site on October 1, 1997 and transported to salvage.
15-01-06	Ordinary Debris	Removed from site on September 6, 1997 and transported to landfill.
15-19-01	Ordinary Debris	Removed from site on September 25, 1991 for disposal.
15-22-31	Oil	The material was determined to be a non-hazardous petroleum hydrocarbon. It was removed from site on September 2, 1997. Solidification and disposal was completed on February 11, 1998.

**FFACO Corrective Action Site
Housekeeping Closure Verification Form
Closure Report for CAU 211: CAS 15-01-02**

Closure Verification Date: 24-OCT-97

CAS Number: 15-01-02

CAU Number: 211

General Location: Area 15 EPA Farm

Elevation: 4586 feet

Latitude:

Northing: 895,709

Longitude:

Easting: 682,084

Coordinate/Elevation data from Nevada Test Site Drilling & Mining Summary, (prepared by Raytheon Services Nevada, 1991) based on water well UE15d located onsite.

Site Access Route: From Mercury take Mercury Highway north to Rainier Mesa Road, proceeding northwest, turn north onto 2-05 Road. Continue on 2-05 Road for 4.5 miles and go north at "y" onto Circle Road and continue for 5 miles. Turn north onto 10-02 Road and continue for 1.5 miles. Turn east and go to end of paved road. The EPA Farm complex is on the south.

Waste Item(s) Originally at Site	Apparent Waste Type
Aboveground Storage Tanks	Scrap metal

CAS Status Prior To Cleanup

CAS Status After Cleanup

Current Site Description/Observations: Bechtel Nevada Environmental Restoration personnel determined through historical research, radiological survey, and visual inspection that the tanks were used for the storage of propane gas and water for use with the associated greenhouse. The tanks were removed from the site on October 1, 1997 and transported to the Area 23 Excess Yard to be salvaged as scrap metal.

☒ **No Further Action Required at Corrective Action Site**

Angela L. Olson

Corrective Action Coordinator/Designee

[Signature]

(Signature)

FOR ALO

4/13/98

Date

**FFACO Corrective Action Site
Housekeeping Closure Verification Form
Closure Report for CAU 211: CAS 15-01-06**

Closure Verification Date: 24-OCT-97

CAS Number: 15-01-06

CAU Number: 211

General Location: Area 15 EPA Farm

Elevation: 4586 feet

Latitude:

Northing: 895,709

Longitude:

Easting: 682,084

Coordinate/Elevation data from Nevada Test Site Drilling & Mining Summary, (prepared by Raytheon Services Nevada, 1991) based on water well UE15d located onsite.

Site Access Route: From Mercury take Mercury Highway north to Rainier Mesa Road, proceeding northwest, turn north onto 2-05 Road. Continue on 2-05 Road for 4.5 miles and go north at "y" onto Circle Road and continue for 5 miles. Turn north onto 10-02 Road and continue for 1.5 miles. Turn east and go to end of paved road. The EPA Farm complex is on the south.

Waste Item(s) Originally at Site	Apparent Waste Type
Aboveground Storage Tank	Ordinary Debris

CAS Status Prior To Cleanup

CAS Status After Cleanup

CURRENT Site Description/Observations: Bechtel Nevada Environmental Restoration personnel determined through historical research, radiological survey, and visual inspection that the tank was part of the original water chlorination system used at the farm and had not been used for the storage of hazardous substances. The tank was removed from the site on September 6, 1997 and transported to the Area 9 10c Sanitary Landfill as ordinary debris.

☒ **No Further Action Required at Corrective Action Site**

Angela L. Olson

Corrective Action Coordinator/Designee

(Signature)

For ALO

4/13/98

Date

**FFACO Corrective Action Site
Housekeeping Closure Verification Form
Closure Report for CAU 211: CAS 15-19-01**

Closure Verification Date: 26-FEB-98

CAS Number: 15-19-01

General Location: EPA Farm/Climax Mine

Latitude: 37.231270

Longitude: -116.056026

CAU Number: 211

Elevation: 5219 feet

Northing:

Easting:

Coordinate/Elevation Data Obtained from Garmin 40 Global Position System: Accuracy is within 300 ft Horizontal - Vertical Varies with Locality

Site Access Route: North on "D" Road approximately 2 miles from the Area 15 former EPA Farm site, to old miner's shack. Go west approx. 0.2 miles to dump on right, turning right (north) toward drill pad and shaft. The CAS lies along the west side of the dirt road.

Waste Item(s) Originally at Site	Apparent Waste Type*
Empty Chemical Containers, Trash	Ordinary

* Ordinary, Scrap Metal, Asbestos, PCB, Salvageable, Hazardous, Radioactive, Mixed, Unknown, Other

CAS Status Prior to Cleanup

CAS Status After Cleanup

Current Site Description/Observations: The waste originally identified at this CAS was retrieved for disposal on 25-SEP-91. There is wood debris and ancillary waste remaining at this location which will be re-visited for retrieval under a separate program, outside of FFACO corrective actions. All metal containers retrieved from this site were empty and no soil staining was observed.

☒ No Further Action Required at Corrective Action Site

C. Carlos Gonzales
Corrective Action Coordinator/Designee

C. Carlos Gonzales
(Signature)

2-26-98
Date

**FFACO Corrective Action Site
Housekeeping Closure Verification Form
Closure Report for CAU 211: CAS 15-22-31**

Closure Verification Date: 24-OCT-97

CAS Number: 15-22-31

CAU Number: 211

General Location: Area 15 EPA Farm

Elevation: 4586 feet

Latitude:

Northing: 895,709

Longitude:

Easting: 682,084

Coordinate/Elevation data from Nevada Test Site Drilling & Mining Summary, (prepared by Raytheon Services Nevada, 1991) based on water well UE15d located onsite.

Site Access Route: From Mercury take Mercury Highway north to Rainier Mesa Road, proceeding northwest, turn north onto 2-05 Road. Continue on 2-05 Road for 4.5 miles and go north at "y" onto Circle Road and continue for 5 miles. Turn north onto 10-02 Road and continue for 1.5 miles. Turn east and go to end of paved road. The EPA Farm complex is on the south.

Waste Item(s) Originally at Site	Apparent Waste Type
Fuel oil can	Oil

CAS Status Prior To Cleanup

CAS Status After Cleanup

Current Site Description/Observations: Bechtel Nevada Nonradioactive Waste Management Project personnel sampled the contents of the can on September 2, 1997. Analytical results indicated that the contents were nonhazardous petroleum hydrocarbons. The contents were solidified with clean soil and disposed of in the Area 9 10c Sanitary Landfill on February 11, 1998.

☒ **No Further Action Required at Corrective Action Site**

Angela L. Olson

Corrective Action Coordinator/Designee

FOR ALD

(Signature)

4/13/98

Date

DISTRIBUTION LIST

Copies

Controlled

Bureau of Federal Facilities
Division of Environmental Protection
333 W. Nye Lane, Room 13B
Carson City, NV 89706-0866

P. J. Liebendorfer
D. A. Garrepy

2
1

U.S. Department of Energy, Nevada Operations Office
P. O. Box 98518, 505
Las Vegas, NV 89193-8518

S. D. Bonnell

1

Uncontrolled Copies

U.S. Department of Energy, Nevada Operations Office
P. O. Box 98518, 505
Las Vegas, NV 89193-8518

Janet L. Appenzeller-Wing
C. W. Barrow

1
1

Public Reading Room
Technical Information Resource Center

1
1

U. S. Department of Energy,
Office of Scientific and Technical Information
P. O. Box 62
Oak Ridge, TN 37831

2

DISTRIBUTION LIST (continued)

Uncontrolled Copies

Bechtel Nevada

P. O. Box 98521, M/S NLV008
Las Vegas, NV 89193-8521

Correspondence Control

D. K. Cowser

D. D. Madsen

S. J. Nacht

A. L. Olson

K. A. Quintana

1

1

1

1

1

1