Lawrence Berkeley Laboratory

UNIVERSITY OF CALIFORNIA

Materials & Molecular Research Division

Submitted to Applied Physics Letters

ON THE COMPARISON OF TRANSMISSION ELECTRON MICROSCOPY
AND CHANNELLED RUTHERFORD BACK SCATTERING TECHNIQUES TO
EVALUATE THE MULTI-LAYER SUB-SURFACE DAMAGE STRUCTURES

D. K. Sadana, M. Strathman, J. Washburn and G. R. Booker

April 1980

RECEIVED
LAWRENCE
BERKELEY LABORATORY

JUN 20 1980

LIBRARY AND
DOCUMENTS SECTION

TWO-WEEK LOAN COPY

*This is a Library Circulating Copy
which may be borrowed for two weeks.
For a personal retention copy, call
Tech. Info. Division, Ext. 6782.*

LBL-10725 Rev. c.2

DISCLAIMER

This document was prepared as an account of work sponsored by the United States Government. While this document is believed to contain correct information, neither the United States Government nor any agency thereof, nor the Regents of the University of California, nor any of their employees, makes any warranty, express or implied, or assumes any legal responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by its trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof, or the Regents of the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof or the Regents of the University of California.

ON THE COMPARISON OF TRANSMISSION ELECTRON MICROSCOPY
AND CHANNELLED RUTHERFORD BACK SCATTERING TECHNIQUES
TO EVALUATE THE MULTI-LAYER SUB-SURFACE DAMAGE STRUCTURES

D. K. Sadana, M. Strathman, J. Washburn
Lawrence Berkeley Laboratory
University of California, Berkeley, CA 94720

G. R. Booker
Department of Metallurgy
University of Oxford, OX1 3PH (England)

ABSTRACT

Cross-sectional transmission electron microscopy (TEM) and MeV He⁺ channelling methods have been used to examine different damage structures present under the colour bands visible at the surface of a high dose rate P⁺ implanted (111) Si wafer implanted to a dose of 7.5×10^{15} ions/cm². TEM and channelling results obtained from individual coloured regions showed a good qualitative correlation in that discrete damage layers observed in the 'cross-sectional TEM' micrographs appeared as discrete peaks in the channelled spectra. The mean depths of the damage layers obtained from these two methods were in agreement. However, the widths of the deeper lying damage layers calculated from the channelling measurements were always greater than the widths observed by TEM. An empirical method based on subtraction of dechannelling background in the channelling spectra gave damage layer widths that were in close agreement with the TEM results.

******This manuscript has been printed from copy provided by the author.

Rutherford backscattering (RBS) using a channelling orientation has been used extensively to detect lattice disorder and its depth distribution. However, the method used alone is incapable of giving detailed information concerning the nature of the disorder such as can be obtained by transmission electron microscopy (TEM). Also when more than one buried damage layer exists, quantitative interpretation becomes difficult. The present work was aimed at improving the interpretation of channelled RBS results when more than one damage layer is present. Such damaged structures were found to be present in a high dose rate P^+ implanted Si wafer that showed colour bands at the implanted surface.¹ The colour bands appear because of optical interference between light reflected from the surface and from a variable depth of the sub-surface interface at which refractive index changes occur. A model for the appearance of colour bands has been reported elsewhere.²⁻⁴

Phosphorus was implanted into a (111) Si wafer at a dose rate of 0.7 mA/cm^2 to a total dose of $7.5 \times 10^{15}/\text{cm}^2$ at 120 KeV in a manner described elsewhere.⁵ '90° cross-sectional TEM' microscopy specimens were prepared⁶ to obtain damage-depth distribution for each coloured region. The nature of the damage was further revealed by 'plan' view specimens. A 1.7 MeV He^+ beam channelled along a $\langle 111 \rangle$ direction was also used to detect the disorder in the same coloured regions that were used for the TEM examinations.

The damage distribution beneath each particular colour band was found to be entirely different from that present beneath the adjacent band. Figure 1a shows a 'cross-sectional TEM' micrograph from the region showing 'green' band at the implanted surface. The micrograph

showed two discrete buried damage layers D_1 and D_2 . Regions F_1 and F_2 , above and below layer D_1 , were free of the 'visible damage' (data, Table 1). The term 'visible damage' refers to the damage visible by TEM. Transmission electron diffraction (TED) pattern from plan view micrographs showed that the surface region was heavily damaged. The channelling measurements from the same specimen showed three peaks, G_1 , G_2 and G_3 (Fig. 1b). Peak G_1 corresponded to surface peak 's' in the channelled spectrum for the 'virgin' crystal, indicating that the surface region was single crystal in nature. However, increase in the peak height of G_1 (scattering yield) as compared to that of 'virgin' crystal indicated that the surface region was heavily damaged. Peaks G_2 and G_3 showed that two distinct damage regions separated by a relatively less damaged region were present under the damaged surface region. The magnitude of the scattering yield values for these peaks indicated that the damage in the first layer was very dense, and the second layer contained less dense and lightly damaged regions. The mean depths of these layers were calculated from the energy loss calibration and the widths were determined by taking half width at half maximum and multiplying by 2.⁷ These values are included in Table 1.

Figure 2a shows a 'cross-sectioned TEM' micrograph from the region showing 'violet' band at the implanted surface. The micrograph again showed two discrete layers of damage, L_1 and L_2 respectively; however, the damage widths sequence was now in the reverse order as compared to that in the 'green' band specimen. The first damage layer L_1 was narrow and consisted of damage clusters and coarse damage; but the

second deeper lying damage layer L_2 was wider and contained dense structure (data, Table 1). Regions T_1 and T_2 , above and below layer L_1 , were free of 'visible damage'. TED patterns from the plan view specimen showed that the surface was heavily damaged. The channelling measurements also showed three distinct peaks, B_1 , B_2 and B_3 (Fig. 2b). Peak B_1 indicated that the surface region was single crystal but damaged, although the amount of disorder was less as compared to that in the surface region of the 'green' band specimen. Peaks B_2 and B_3 indicated the presence of two distinct damage layers separated by a relatively less damaged region. However, the first damage layer was much narrower as compared to the second damage layer (data, Table 1). The scattering yield values showed that in contrast to the results obtained for the 'green' band specimen, the first narrow damage layer contained less disorder as compared to second wider damage layer.

It is clear from above that there is a good qualitative correlation between the results obtained by TEM and channelling methods. The discrete damage layers as observed by TEM appeared as discrete damage peaks in the channelling spectra. However, further comparison of the data showed that although the mean depths obtained from the two methods were in agreement, the widths of the damage layers as calculated from the channelling measurements were consistently greater. The discrepancy increased for the deeper lying damage layers in double buried damage layers type structures.

It was observed that the dechannelling of the beam due to the interaction with the disorder nearer the surface gave a 'background' at lower energies that was superimposed on the spectra due to deeper

damage. The dechannelling associated with the surface peak had a 'background' on the lower energy side which was frequently approximately half the amplitude of the surface peak. Spectra containing single buried damage layers were also found to have this 'background' on the lower energy side of the peak also of the order of half the magnitude of the peak height.⁸ Therefore, for the calculations of the widths of a second or third peak, the 'background' due to each scattering peak was assumed to be independent of that from the others and to have a magnitude of half the height of the peak at all lower energies. Then, for peaks due to buried layers of damage, the width at half-maximum was taken at a scattering yield half way between the 'background' resulting from all higher energy peaks and the top of the peak in question. Fig. 3 shows a schematic representation of the empirical approach used. The damage layer widths calculated after this 'background' subtraction were then in close agreement with the TEM results (data, Table 1). The damage width data obtained by 'cross-sectional TEM' and channeling measurements respectively for several other types of damage structures such as, the discrete layers of dislocation loops or damage clusters present both in Si and GeAs⁹ was also found to be in close agreement after following the above empirical approach even though the minimum yield on the low energy side in some cases did not fall to a magnitude of half the peak height.

The results can be summarized as follows:

1. The discrete damage layers seen in the TEM cross-section specimens appeared as discrete damage peaks in the channelled RBS spectra.

2. The damage layers widths as obtained from the channelled RBS spectra using the ordinary surface approximation method consistently gave higher values as compared to the values obtained from TEM cross-section micrographs.
3. An empirical method based on subtraction of the dechannelling background gave damage layer widths that were in close agreement with the TEM result.

ACKNOWLEDGEMENTS

The authors would like to thank Jim Hodges and Steve Klingeler who designed and fabricated the specimen stage for the channelling measurements; Scott Hubbard and Dan Meier for their help in improving the performance of the equipment at various stages of the work and Jim Stephens and D. Chivers of AERE Harewell (England) for implanting the Si wafers. The authors are grateful to Marc-A. Nicolet, Jim Mayer and I. Golecki of the California Institute of Technology and to George Gabor of this Laboratory for the useful discussions and comments on the paper. Finally, we would like to acknowledge the financial support of the Department of Energy through the Material and Molecular Research Division and the Department of Instrument Techniques of Lawrence Berkeley Laboratory. This work was supported by the U. S. Department of Energy under Contract W-7405-ENG-48.

REFERENCES

1. J.H. Freeman, D.J. Chivers, G.A. Gard, G.W. Hinder, B.J. Smith and J. Stephen, Ion Implantation in Semiconductors, Ed. S. Namba (Plenum Press: New York, 1975). pp 555-569.
2. L. Csepregi, E.F. Kennedy, S.S. Lau, J.W. Mayer and T.W. Sigmon, App. Phys. Lett., 29, 645 (1976).
3. T.E. Seidel, G.A. Pasteur and J.C. Tsai, App. Phys. Lett., 29, 648 (1976).
4. D.G. Beanland, Rad. Eff., 33, 219 (1977).
5. J.H. Freeman, L.R. Caldecourt, K.C.W. Done and J. Francis, Proc. Conf. on Ion Implantation, Reading (Peter Peregrinus, Stevenage) 1970 and AERE Report R 6496 (1970).
6. H.R. Pettit and G.R. Booker, IOP London Conf Series, 10, 290 (1971).
7. W.K. Chu, J.W. Mayer and M-A Nicolet, Backscattering Spectrometry (Academic Press, 1978), Chapt. 4, pp. 89-122.
8. D.K. Sadana, M. Strathman, J. Washburn and G.R. Booker, Proc. Laser and Electron Beam Processing of Materials, AIP Conference, Boston, Nov. 1979 (to be published).
9. D.K. Sadana, J. Washburn, C.W. Magee, M. Maenpaa, M. Strathman and G.R. Booker (unpublished).
10. J.M. Harris and M-A. Nicolet, Phys. Rev., 11, 1013 (1975).

TABLE I

(All measurement units are in Å)

Colour of the Band	TEM				Channelling			
	Upper Damage Layer		Lower Damage Layer		Upper Damage Layer		Lower Damage Layer	
	Mean Depth	Width	Mean Depth	Width	Mean Depth	Width	Mean Depth	Width
Green	D_1 800	870	D_2 1560	550	800	$920^a, 900^b, \underline{840^c}$	1600	$1040^a, 1000^b, \underline{500^c}$
Violet	L_1 800	350	L_2 1500	870	800	$960^a, 940^b, \underline{350^c}$	1470	$1520^a, 1500^b, \underline{850^c}$

^aUsing surface approximation only.^bUsing surface approximation with energy straggling factor incorporated.⁹^cUsing surface approximation and subtracting the "background" (our empirical method).The values were found to differ by $\pm 5\%$, due to human error in calculating widths by the method described in the text.

FIGURE CAPTIONS

- Fig. 1 Comparison of cross-sectional TEM and channelling spectrum for the 'green band' specimen.
- Fig. 2 Comparison of cross-sectional TEM and channelling spectrum for the 'violet band' specimen.
- Fig. 3 A schematic representation of the empirical method used to subtract the dechannelling 'background'.

Fig. 1

XBB790-13570

Fig. 2

XBB790-13567A

Fig. 3

XBL 7910-12209