APPENDIX C

WASTE DISPOSITION DOCUMENTATION*

* Appendix C, Waste Disposition Documentation, will be available in the M&OC project files at Mercury, Nevada, after the low-level waste has been disposed of after September 2007.

THIS PAGE INTENTIONALLY LEFT BLANK

APPENDIX D

SITE CLOSURE PHOTOGRAPHS

THIS PAGE INTENTIONALLY LEFT BLANK

PHOTOGRAPH LOG

CAS	PHOTO NUMBER	DATE	PERSPECTIVE	DESCRIPTION
TA-52-001-TANL TA-52-006-TAPL TA-52-004-TAAL RG-52-007-TAML	1	5/7/2007		Typical excavation for small, DU hand-excavated areas on NEDS and Antelope Lakes
	2	6/7/2007		Cleanup verification using Kiwi on Antelope Lake
	3	5/29/2007		Hot spot cleanup verification on Antelope Lake, using handheld survey instruments and Kiwi
RG-52-007-TAML	4	6/23/2007		Mt. Helen excavation for Davis Gun projectile
	5	7/23/2007	View to the southwest	Antelope Lake DU location CA-1 excavation upon completion
	6	7/23/2007	View to the east	Antelope Lake DU location CA-1 excavation, Kiwi screening to verify clean closure
TA-52-005-TAAL	7	11/7/2006		JTA DU ring at location NA-2
	8	11/7/2006		JTA DU ring at location NA-3
	9	11/7/2006		JTA DU ring at location SA-10, south Antelope Lake
TA-54-001-TANL	10	9/24/2006	View to the southeast	Structures at north end of NEDS Lake, before removal
	11	9/13/2006	View to the east	Structures at north end of NEDS Lake, before removal
	12	6/28/2007		Location at north end of NEDS Lake, after structures were removed.

THIS PAGE INTENTIONALLY LEFT BLANK

Photograph 1: Typical Small Excavation to Remove Depleted Uranium (DU) from NEDS or Antelope Lake, 5/7/2007

Photograph 2: Cleanup Verification Using Kiwi on Antelope Lake, 6/7/2007

Photograph 3: Hot Spot Cleanup Verification on Antelope Lake using Handheld Survey Instruments and Kiwi, 5/29/2007

Photograph 4: Mt. Helen Excavation for Davis Gun Projectile, 6/23/2007

Photograph 5: Antelope Lake DU Location CA-1 Excavation upon Completion, Confirmed Clean, 7/23/2007

Photograph 6: Antelope Lake DU Location CA-1 Excavation, Kiwi Screening to Verify Clean Closure, 7/23/2007

Photograph 7: Joint Test Assembly (JTA) DU Ring at Location NA-2, 11/7/2006

Photograph 8: JTA DU Ring at Location NA-3, 11/7/2006

Photograph 9: JTA DU Ring at Location SA-10, 11/7/2006

Photograph 10: Structures at North End of NEDS Lake, Before Removal, 9/24/2006

Photograph 11: Structures at North End of NEDS Lake, Before Removal, 9/13/2006

Photograph 12: Location at North End of NEDS Lake, After Structure Removal, 6/28/2007

APPENDIX E

POSITION PAPER

**End State Meeting for Depleted Uranium and Davis Gun Targets,
Tonopah Test Range, Nye County, Nevada, January 2007**

Includes NDEP Approval Letter

THIS PAGE INTENTIONALLY LEFT BLANK

STATE OF NEVADA

Department of Conservation & Natural Resources

DIVISION OF ENVIRONMENTAL PROTECTION

Jim Gibbons, Governor

Allen Biaggi, Director

Leo M. Drozdoff, P.E., Administrator

ERD.070416.0002

April 5, 2007

Kevin J. Cabble, Acting Federal Project Director
Nevada Nuclear Security Administration
Nevada Site Office (NNSA/NSO)
P. O. Box 98518
Las Vegas, NV 89193-8518

RE: Review of White Paper on Corrective Action Unit (CAU) 484, Surface Debris, Waste Sites, and Burn Area, Tonopah Test Range, Nevada Federal Facility Agreement and Consent Order

The Nevada Division of Environmental Protection, Bureau of Federal Facilities (NDEP) staff reviewed the NNSA/NSO transmittal letter dated March 27, 2007 and the White Paper titled "CAU 484: Surface Debris, Waste Sites, and Burn Area (TTR), End State Meeting for Depleted Uranium And Davis Gun Targets, Tonopah Test Range, Nye County, Nevada, January 2007". NDEP concurs with the approach presented.

Address any questions regarding this matter to either Ted Zaferatos at (702) 486-2850, ext. 234, or me at (702) 486-2850, ext. 229.

Sincerely,

Don Elle
Supervisor
Bureau of Federal Facilities

TZ

cc: John B. Jones, Acting Federal Director, NNSA/NSO
Frank Di Sanza, WMD, NNSA/ NSO
D.C. Loewer, DTRA/CXT1, M/S 645, Mercury, NV
Tiffany Lantow, DTRA/CXT1, M/S 645, Mercury, NV
Wayne Griffin, SNJV/DTRA, M/S 645, Mercury, NV
FFACO Group, PSG, NNSA/ NSO
J.L. Smith, NSTec, Las Vegas
R.F. Boehlecke, SNJV, Las Vegas, NV
K.A. Hoar, AD/AMSP, NNSA/NSO

1771 E. Flamingo Road Suite 121-A • Las Vegas, Nevada 8911

Printed on recyc

ACTION
INFO
NSO/MGR
AMEM
AMNS
AMSO
AMSP
AMSS

ERP WMP PSG AMSP
✓
✓

**CAU 484: SURFACE DEBRIS, WASTE SITES,
AND BURN AREA (TTR)**

**END STATE MEETING FOR DEPLETED
URANIUM AND DAVIS GUN TARGETS**

**TONOPAH TEST RANGE, NYE COUNTY,
NEVADA**

JANUARY 2007

SUMMARY AND PURPOSE

Closure requirements specified in the CAU 484 SAFER Plan have been implemented and the results have been presented to NNSA for review. The purpose of this paper is to confirm agreement of project end state with NDEP, and to determine if any additional fieldwork is needed to fulfill the SAFER Plan requirements.

Aerial and ground investigations of several dry lake beds and half of Antelope Lake were conducted for CAU 484 at TTR in 2004 and 2005. The investigation used three integrated survey methods which included multispectral aerial imagery, time domain electromagnetic, and gamma ray spectroscopic radiological surveys. In 2006 surveys using similar geophysical and radiological surveys were performed on the Southern half of Antelope Lake and nearby volcanic tuff sites to identify radiological and geophysical anomalies fitting the Conceptual Site Models (CSMs) outlined in the CAU 484 SAFER Plan. The purpose of these investigations was to map the spatial distribution of surficial and buried metal debris, to locate materials potentially associated with CAU 484 and fitting the Conceptual Site Models outlined in the SAFER plan.

In addition to these initial surveys, investigations of each of the sites were performed with hand held geophysical and radiological instruments. Only those areas that closely matched the conditions of the CSMs documented in the SAFER Plan were reinvestigated. These included areas that showed a geophysical anomaly or radiological signature similar to a Davis Gun Projectile, Depleted Uranium (DU) ring, or pieces of DU. All identified DU pieces on Antelope Lake and NEDS Lake have been removed and packaged, including the three DU rings (CAS TA-52-005-TAAL).

Based on the results of investigation activities, the following findings and recommendations are presented for CAU 484.

SAFER PLAN

The following three CSMs are presented in the SAFER Plan:

Surface-Shallow Subsurface Debris

This CSM includes all sites where DU may be present in the shallow subsurface (defined as a maximum depth of 10 feet below ground surface or shallower). CASs included in this CSM include Joint Test Assembly DU Sites (TA-52-005-TAAL) and nine Davis Gun Penetrator Test locations (RG-52-007-TAML).

Surface Detonation Debris

This CSM includes sites where detonations involving DU have occurred and contamination may be present on the ground surface. CASs included in this CSM include the NEDS Detonation Area (TA-52-001-TANL); the Metal Particle Dispersion Test (TA-52-004-TAAL); and the (COLIMBO) Depleted Uranium Site (TA-52-006-TAPL).

Non-Impacted Surface Debris

This CSM includes one site, the Containment Tank and Steel Structure (TA-54-001-TANL).

The primary assumptions regarding contaminants of potential concern (COPC) for the CSMs and closure are if DU is present it will be in discrete pieces or fragments; sites will be clean closed if it is technically feasible; and that closure will be verified using hand-held survey instruments. Additionally, beryllium is identified as a COPC for the Surface Detonation Debris sites.

The SAFER Plan also establishes Hold Points to be implemented during the investigation and closure process to review data for the selection of potential site locations for further investigation and review of verification data. The following hold points pertain to the current investigation:

- Review the results of geophysical and radiological surveys. If multiple potential targets are identified, a decision will be made concerning which targets are to be investigated and the nature of additional data collection requirements.
- Review the results of soil sampling and laboratory analysis for beryllium and DU screening/analytical data with NNSA to confirm the cleanup and/or closure approach.

DAVIS GUN SITE BACKGROUND INFORMATION

The Davis Gun was a recoilless rifle used by Sandia National Laboratories to fire artillery projectiles into soil, rock, and concrete targets. According to interviews and Sandia documentation, the penetrators used at TTR were usually inert with the occasional use of DU as ballast and that test articles penetrated the ground to a depth between 10 to 100 feet below ground surface, depending on the test objective. Davis Gun and similar penetrator tests were conducted at TTR from the 1960s until the 1990s. Sandia reports indicate that tests conducted in the 1960s and 1970s were often not recovered unless they contained a data recording package or the penetrator casing was needed for further analysis. Documents also confirm that some penetrators were damaged and broke up during recovery. Due to the management and practices involving DU during this timeframe, it cannot be assumed that DU cleanup was a concern, and documentation from tests during this timeframe does not discuss cleanup or management of DU. Many tests from this timeframe were also shallow and are the primary subject of the current investigation. However, tests conducted in the 1980s and 1990s contain details on tests involving DU and recovery/cleanup operations.

Test locations where Davis Gun Penetrator tests were conducted during the 1960's through the 1990's include Antelope Tuff Target 1, Antelope Tuff Target 2, Myers Ridge, Sidewinder Tuff Target, Antelope Lake, Main Lake, Pedro Lake, Brownes Lake, and Mt. Helen.

Personnel involved in the testing during the 1980s and 1990s stated that the purpose of the Davis Gun tests was to evaluate delivery system packages and a primary goal of the experiments was to recover the test components; therefore it is highly unlikely that test components were left at the sites where the experiments were conducted. In addition, Davis Gun tests during this timeframe were considerably deeper than earlier tests. Therefore, due to the depth of any penetrators not

recovered, there is minimal risk to encountering the penetrators and exposure to potential contaminants.

DAVIS GUN SITE INVESTIGATION PROPOSAL

Information indicates that soil berms were usually constructed around the test areas on the playa to keep water from entering the test area. Therefore, the most logical places to excavate and locate any lost Davis Gun Projectiles are at geophysical anomalies located within circular bermed areas on Antelope Lake or Pedro Lake. Davis Gun test locations on Antelope Lake from the 1960s to 1970s have been largely erased by water and wave action, however maps in reports from this timeframe indicate general locations on the playa surface. Based on available information, Davis Gun test locations are located on the northern half of Antelope Lake and all of Pedro Lake.

Geophysical seed objects closely matching the size and material of the Davis Gun Projectiles were buried in both the playa and volcanic tuffs to identify a geophysical signature prior to performing the second set of geophysical surveys. A steel object buried between 6-9 feet below the surface in a vertical position indicated a geophysical signature approximately 5 meters in diameter and in excess of 50 mill-volts, as shown on attached Figures 1 & 2. The objects were buried at this depth due to the limitations of the geophysical mapping process, which will only see large objects to approximately 10 feet below ground surface. There were several reasons for investigating the shallow sub-surface. The first was to determine if any of the older and shallower projectiles could be identified, mainly located at the tuff sites. Secondly this was done to detect fragments or broken pieces of the projectiles that were not initially recovered. Lastly, the shallow sub-surface was investigated to locate a penetrator described in the SAFER Plan that was lost down a fissure and was never recovered. Geophysical signatures similar to those from the test seeds in the areas mentioned previously were identified for excavation. After performing this comparison, a total of 32 geophysical targets, 22 on Antelope Lake and 14 on Pedro Lake, were identified on the dry lake beds at TTR that meet the Davis Gun criteria, and 46 geophysical targets have been identified at the off-lake tuff locations.

Dry Lake Bed Davis Gun Sites

Following the outlined activities in the SAFER Plan, a total of 9 anomalies on Antelope Lake and 5 on Pedro Lake were investigated with a backhoe to a maximum depth of 10 feet below ground surface. Of the 14 anomalies excavated five items were identified as potentially explosive ordinance. There has been no confirmation whether or not the uncovered items are explosive or not. Weston, a part of Stoller-Navarro Joint Venture will work under a secondary REOP to investigate the ordinance to remove any explosive hazards associated with these objects. Other inert items uncovered included a metal stake, a metal plate, concrete slabs, and scrap metal. No further excavation activities will be performed by NSTec on the dry lake beds based on the high risk this activity poses to site personnel in addition to the process knowledge information stated above regarding depth of penetration and the current success rate with no projectiles uncovered from 14 excavations. Due diligence has been performed to show that the

probability of locating a buried Davis Gun projectile within the first 10-feet of the playa is unlikely.

Volcanic Tuff Davis Gun Sites

Geophysical data collected over each of the volcanic tuff sites identified a large number of subsurface metal anomalies at each of the test locations. Radiological surveys performed in the area do not show any signs of DU contamination at or around the test holes at each site. No subsurface investigations have been performed at any of the volcanic tuff Davis Gun Sites. In order to determine if additional excavation efforts are required, two of the most likely locations for a buried projectile will be uncovered. Since each tuff site has several high potential candidates of large geophysical anomalies deep (3-10' bgs) inside of possible test holes, two from the Mt. Helen site will be excavated since it was the first test area used, and therefore, has the best chance to find a shallow projectile. Geophysical anomalies PH01_001 and PH01_002 identified on Figure 3 will be excavated.

DEPLETED URANIUM SITES

Initial radiological surveys completed using the Kiwi sodium iodide detector system identified 75 DU targets within the CAU 484 and 408 boundaries. These targets were located and removed and hand-held survey instruments were used to verify closure. One of the CSM assumptions of the SAFER Plan was that DU would be in discrete fragments, however after removing all impacted media (DU and impacted soil); eight B-25 boxes of LLW were generated indicating a significantly larger volume of soil was impacted than assumed. No residual radionuclides greater than two times the background determined by hand held field screening remains at the remediation sites. Verification samples from a number of the DU sites were collected in accordance with a separate white paper to verify that site closure goals were reached. Data will be used to verify closure and will be provided to Sandia to assist with their deposing activities for their CAs or soil contamination areas within the CAU 484 boundaries.

CONCLUSION AND RECOMMENDATIONS

NSTec has excavated 14 anomaly locations on the dry lake beds without finding any Davis Gun projectiles; therefore, NSTec proposes to discontinue excavation activities on the dry lake beds. The lack of any evidence of Davis Gun test items (intact or fragmented) and the high risk to site personnel, due to potential for buried UXO hazards, supports no additional excavation at the Davis Gun lake bed sites. Two geophysical anomalies at the Mt. Helen tuff site will be investigated to determine if they are related to past Davis Gun activities. If the anomalies are not related, NSTec proposes to discontinue investigation activities at the tuff locations. A summary of the findings and rationale for target investigation and completion of investigation tasks will be included in the closure report.

Weston will perform an investigation of the exposed potential explosive ordinance on Antelope Lake and Pedro Lake to remove any explosive hazards associated with these objects.

All DU identified at surface and shallow subsurface sites using the Kiwi surveys has been removed, verified by field survey methods, and verification samples have been collected at specific locations. Closure of the surface and shallow subsurface DU sites is dependant upon the results of the verification samples. If no uranium is detected above action levels identified in Section 5.2 of Appendix A of the SAFER Plan at any of the DU sites, these areas will be considered clean closed.

CAU 484 and 408 Depleted Uranium Soil Sampling Criteria and Strategy Plan

Soil sampling will be conducted at CAU 484 sites to confirm cleanup standards established in the SAFER Plan. The initial approach was to verify clean closure using hand-held survey instruments, assuming only depleted uranium (DU) fragments and minor impacted soil were present. During closure activities, some areas contained volumes in excess of one cubic foot of impacted soil and DU debris. Based on discussions at the CAU 484 end point meeting, it was decided that soil samples would be collected to confirm clean closure since the conceptual site model assumption was no longer valid.

The following approach establishes criteria for when to collect samples and the number of samples to collect. The sampling criteria are based on a graded approach to maximize use of available resources and provide the most useful information for the project.

During the Kiwi surveys of CAU 484/408 lakebed locations 109 DU targets were identified. Of these, 49 DU targets were located in the field, DU and associated impacted soil were removed, and survey instrumentation was used to verify cleanup to within two times the site specific background. The amounts of impacted soil removed during cleanup activities ranged from a minor amount from the area surrounding the DU fragment to over one cubic yard. Because little residual contamination is anticipated at areas where small DU fragments were removed, only locations where greater than one cubic foot of soil was removed will be sampled. This approach results in collecting samples at 15 locations: four locations where the excavation was approximately one cubic foot; four locations where the excavation was approximately one cubic yard, and seven locations where the excavation was greater than one cubic yard. The sampling locations are biased towards areas with the highest residual activities within each excavation, and therefore confirmation sampling is expected to provide the data to confirm using the screening method approach as a guide to closure of the sites.

A table showing all of the DU targets and evaluation using these selection criteria is available to support the sampling rationale.

The following criteria are proposed for confirmation sampling locations and quantities. Impacted soil and DU have been removed to screening levels within two times background (using an Electra instrument). Each DU location will be verified using the documented site coordinates. Samples will be collected to verify cleanup effectiveness. Using a conservative approach, excavations will be screened by an RCT at the time of sample collection and the soil sample will be collected from the area within each excavation yielding the highest reading.

The soil sample will be collected from the bottom of the excavation if the Electra screening results do not vary appreciably, for single sample excavations of approximately 1 cubic foot. For excavations where 3 or 5 samples will be collected, samples will be collected from the areas of the excavation that yield the highest screening levels, per RCT direction. If there are no appreciable differences in readings, one sample will be collected from two

sides of the excavation and one from the bottom (for excavations of approximately 1 cubic yard); one sample from each of four sides of the excavation and one from the bottom (for excavations of 1 cubic yard or greater); and for sites with multiple small excavations, one soil sample will be collected from the five areas of highest readings (one per excavation) as directed by the RCT, or from the five largest excavations if no variation in screening levels is observed by the RCT (See table below). Radiological surveys conducted to determine sample location selection and details concerning sample collection will be documented in field notes and will be available to support preparation of the closure report.

Debris/Soil Removed	Number of Samples/Location
DU fragment/minor soil volume (<1 cubic foot)	0
Excavations of approximately 1 cubic foot	1
Excavations of approximately 1 cubic yard	3
Excavations exceeding 1 cubic yard or combined areas	5

Using this approach, a total of 51 soil samples will be collected (plus associated QA samples) and will be analyzed according to the same DQO standard established for characterization sampling (Isotopic U - DOE HASL 300, and Chemical U - SW-846 6010b). The described methodologies and sampling/analytical specifications are also consistent with the requirements of the SAFER Plan. Sandia previously posted some areas as Soil Contamination Areas. The sampling data will be provided to Sandia to support deposing of these Soil Contamination Areas.

Sampling 15 of the 49 areas of DU which were located in the field is approximately 30% of the population, and provides a level of statistical significance to confirm cleanup of these sites. The statistical significance will be determined by the analytical results.

mV

Explanation

- Seeded Deep Target
- Picked Target

Scale 1:300

metres

WGS 84 / UTM zone 11N

Tonopah

Browns Lake Test Plot
060706_MTADS_GPO_Profile
Large Projectiles

mV

Scale 1:200

metres

WGS 84 / UTM zone 11N

Explanation

✕ Seeded Deep Target

✕ Picked Target

Tonopah

Antelope Tuft Test Plot
TP_MTADS_081006DH
Deep Projectile

Explanation

— Known Boundary

○ Selected Target

H01_001 Target ID

Tonopah

Mt. Helens Site 1 - Penetrators
MTADS Data

APPENDIX F

POSITION PAPER

**Initial Multi-Spectral, Electromagnetic, and Radiometric Survey
Results, Tonopah Test Range, Nye County, Nevada
January 2006**

THIS PAGE INTENTIONALLY LEFT BLANK

INITIAL MULTI-SPECTRAL, ELECTROMAGNETIC, AND RADIOMETRIC SURVEY RESULTS

**CAU 484: SURFACE DEBRIS, WASTE SITES,
AND BURN AREA (TTR)**

**TONOPAH TEST RANGE, NYE COUNTY,
NEVADA**

JANUARY 2006

EXECUTIVE SUMMARY

Aerial and ground investigations were conducted for CAU 484 at TTR in 2004 and 2005. The investigation used three integrated survey methods which included multispectral aerial imagery, time domain electromagnetic, and gamma ray spectroscopic radiological surveys. The purpose of these investigations was to map the spatial distribution of surficial and buried metal debris, in order to locate materials potentially associated with CAU 484 and fitting the Conceptual Site Models outlined in the SAFER plan. The data and selected targets presented in this report will allow for efficient investigation during the resumption of geophysical and radiological surveys on Antelope Lake in 2006. This Executive Summary presents the findings outlined in this detailed report. Based on the results of the investigation the following findings were identified for the four lakes where the surveys were conducted:

Browne's Lake

- No clear indication of a Davis Gun site with associated depleted uranium (DU) or buried projectiles was identified.
- A possible subsurface waste disposal site was identified in proximity to several circular disturbed earth features. However, investigation of waste burial sites is not included in the approved SAFER plan.
- Four potential DU fragments were identified, but were not identified or located during ground-truthing.

Pedro Lake

- One circular topographic feature identified from the aerial imagery corresponds to the description of a Davis Gun test location. A walkdown of this feature and potential Electromagnetic (EM) ground truthing will determine if the buried metal detected there meets the criteria for Davis Gun projectiles.
 - Twelve circular topographic features were identified from the aerial imagery resembling the physical characteristics of a Davis Gun site as well exhibiting EM responses. While several of these features may be bomb craters unrelated to the Davis Gun tests, a site walkdown is recommended to determine the nature of these features. EM ground truthing may be necessary if they cannot be ruled out as Davis Gun sites.
 - One potential Davis Gun site was identified from the EM data. While there is no indication of surface disturbance in the immediate area evident from the aerial imagery, a visual inspection of this site is recommended. If there is indication of potential Davis Gun operations, EM ground truthing will determine if the buried metal meets the criteria for Davis Gun projectiles.
 - No potential DU fragments were detected on Pedro Lake.
-

NEDS Lake

- There is no evidence in the geophysical or multispectral data that would indicate the presence of a Davis Gun site.
- Instrumentation cables or conduit leading from the white containment tank (CAS TA-54-001-TANL) to the presumed NEDS test area support evidence that the white tank was used as a command bunker for test personnel and not as a propellant burn site.
- Two targets were identified from the EM data in areas corresponding with surface DU. Detailed EM ground truthing in support of DU cleanup will determine if these targets are associated with the surface DU.
- Two potential debris burial sites were identified from the EM data. However, investigation of waste burial sites is not included in the approved SAFER plan.
- Twenty potential DU fragments were identified from the radiological data.

Antelope Lake

- Nine buried metal objects fitting the criteria for Davis Gun sites were identified from the EM data. Ten topographic features fitting the criteria for potential Davis Gun sites were identified from the aerial imagery. In addition, a survey monument labeled “Davis Gun CP” is located near middle of five of these topographic features. A site visit is recommended to determine if any of these objects are candidates for EM ground truthing.
- No targets fit the ideal conceptual model for the JTA buried DU rings. However, follow up site visits and EM ground truth (if needed) on 10 selected targets is recommended during DU fragment removal to confirm or deny the presence of the JTA rings due to the close proximity of potential surface DU fragments and subsurface EM targets.
- Due to wind and water movement of metallic debris, the distribution of metallic debris in the MPDT is concentrated in the southwest corner and the upper central portion of the soil contamination area (SCA) with a pronounced southwesterly trend. Soil sampling is recommended in these areas per the SAFER Plan.
- Thirty-five potential DU fragments were identified in the SCA, while an additional 16 potential DU fragments were identified in the remainder of the surveyed areas of Antelope Lake.

Upon resuming the survey activities at TTR in 2006 with UXO subcontractor support, the data included in this report will allow potential sites to be inspected either through site visits and/or additional localized EM surveys. Ground truthing of these potential sites will facilitate analysis of the remaining 550 acres on Antelope Lake based on the improved target profiles.

INTRODUCTION

Corrective Action Unit (CAU) 484 consists of six Corrective Action Sites (CASs) located at the Tonopah Test Range (TTR), Nevada. CAU 484 consists of the following six CASs:

- CAS RG-52-007-TAML, Davis Gun Penetrator Test
- CAS TA-52-001-TANL, NEDS Detonation Area
- CAS TA-52-004-TAAL, Metal Particle Dispersion Test
- CAS TA-52-005-TAAL, Joint Test Assembly DU Sites
- CAS TA-52-006-TAPL, Depleted Uranium Site
- CAS TA-54-001-TANL, Containment Tank and Steel Structure

Of these six CASs, five CASs were selected for geophysical and radiological investigation under the Streamlined Approach for Environmental Restoration (SAFER) plan.

CAS TA-54-001-TANL consists of large surface debris that did not require any action under this phase of the SAFER investigation.

CAS RG-52-007-TAML consists of Davis Gun test locations where the Davis Gun was used to test high-velocity earth penetrators that used depleted uranium (DU) ballast weights for stabilization. The Davis Gun tests used a 10.7-meter (m) (35-foot [ft]) recoilless rifle to fire a 145.5 to 327-kilogram (320 to 720-pound) penetrator directly into the lakebed. The penetrators were constructed of various types of steel alloy, titanium, aluminum, and classified metallic materials. They ranged in size from 20.3 to 30.5 centimeters (cm) (8 to 12 inches [in.]) in diameter and from 1.2 to 1.8 m (4 to 6 ft) in length. The rounds were recovered by excavation. In some cases, circular berms were constructed around the test area to protect them from surface water run-on from precipitation on the lakebeds. It was reported that one penetrator was lost on Antelope Lake in the mid-1970s (*Preliminary Assessment [PA] Site Reference Summary for CAU 484: Surface Debris, Waste Sites, and Burn Area [TTR]*, IT Corporation, January 22, 2003). The penetrator may have been lost in a lakebed fracture.

Used in a series of experiments associated with the Nonviolent Explosive Destruct System (NEDS), the NEDS detonation area (CAS TA-52-001-TANL) was located on the north end of NEDS Lake. This series of experiments were designed to test a containment system that would contain shrapnel and gaseous products produced by the single-point detonation of the high explosives in a nuclear weapon. Mock nuclear weapons containing DU and beryllium were used for the testing. Some tests resulted in release of DU and beryllium.

CAS TA-52-006-TAPL on NEDS Lake was also the site of a cruise missile detonation (Colimbo) containing a mock nuclear warhead. The point directly under the detonation is marked with a survey point labeled "Colimbo." The mock warhead contained beryllium, DU, and two valves, each containing a 1-millicurie Co-60 source. One valve was recovered after the test and one remained missing.

CAS TA-52-004-TALL, Metal Particle Dispersion Test (MPDT) consists of a Soil Contamination Area (SCA) located on the northwest end of Antelope Lake where a dummy

W-82 artillery projectile was detonated at ground surface to monitor particulate dispersion of DU and Beryllium. This SCA is approximately 610 x 915 m (2,000 x 3,000 ft) in size and is controlled as a Radioactive Material Management Area.

CAS TA-52-005-TAAL, Joint Test Assembly (JTA) DU sites consist of the northern portion of Antelope Lake where a series of JTA tests were conducted in which four W-33 units were launched from Area 9. The PA indicated there was a possibility that three DU rings, with a total estimated weight of 59 kg (132 lbs), were not recovered and may be buried at the northern end of Antelope Lake approximately 0.6 – 1.2m (2 - 4 ft) below the surface.

INVESTIGATION METHODOLOGY

The investigation used three integrated survey methods which included multispectral aerial imagery, time domain electromagnetic, and gamma ray spectroscopic radiological surveys. The purpose of these investigations was to map the spatial distribution of surfacial and buried metal debris, in order to locate materials potentially associated with CAU 484.

An aerial survey was flown in September 2003 by the Bechtel Nevada Remote Sensing Laboratory at a height of 290 m (950 ft) above ground level using a Daedalus 1268 multispectral scanner with a ground resolution of 0.8 m (2.6 ft). The first principal component of all visible and reflected infrared bands (which displays the maximum portion of the variance within the band) was used as a base image. This image was then treated with a harsh spatial 2x2 convolution filter to enhance any linear trends and disturbed earth. The electromagnetic (EM) and radiological data are overlain on this image to correlate the geophysical data with disturbed earth excavations and circular features that may be related to the Davis Gun sites or other CASs in CAU 484.

The radiological survey used the Bechtel Nevada Remote Sensing Laboratory Aerial Measurements Service's Kiwi system, which consisted of a truck-mounted multi-channel gamma ray spectrometer and eight 5x10x41 cm (2x4x16 in.) sodium iodide detectors. The system was optimized to look for DU and was operated with a 1-second detector integration time. A satellite differential-corrected GPS receiver was located over the detector array.

The DU hit ranking is based on the spectral quality of the net spectrum extracted at hot spot locations. The presence of DU signature with photo peaks is considered higher in ranking.

- Ranking A: All three photo peaks at 93 keV, 767 keV and 1001 keV are present.
 - Ranking B: Only the two photo peaks at 93 keV and 1001 keV are present.
 - Ranking C: There is reasonable amount of net spectral counts from 40 keV to 1000 keV, but DU photo peaks are not well defined.
 - Ranking D: Man-made count level is greater than 3 sigma over background levels. No spectral consideration.
-

The EM survey was run using a synchronous array of three Geonics EM61 Mark II high power time domain metal detectors recording four time gates of EM data interleaved with global positioning satellite (GPS) data. The system did not use the high power option. Data were collected in the differential mode, using both the bottom and top coil for target selection and depth interpretation. The EM 61 MKII HP system used three 1 m x 0.5m (3.28 ft x 1.64 ft) coils arranged to cover a 3m wide swath recording at a maximum speed of seven miles per hour. Line spacing was 3m and used a satellite-corrected differential GPS system with the antenna positioned over the center coil. The EM61 ElectroMagnetic Unit (EMU) was towed 3.3 m (11 ft) directly behind the Kiwi system, with both systems collecting data simultaneously along a 3-m (10 ft) wide swath. GPS data were collected independently for each system.

The data set was leveled to remove the geologic background and electronic drift. The effects of surface noise were suppressed using the top and bottom coil difference. Data were reduced and modeled using the GeoSoft® UXO Detect® program.

This survey was designed to identify potential targets fitting the assumed profiles of test-related materials as outlined in the SAFER Plan. Follow up investigations would consist of a site visit to determine if there are surface indications corresponding to the anomalies and to determine if a more detailed local geophysical or radiological survey would be required.

The surveys were conducted between November 2003 and December 2003, and resumed after weather allowed entry onto lakes (May 2004 through June 2004). Surveys were temporarily suspended in June 2005 due to discovery of UXO. Approximately 550 acres on the southern portion of Antelope Lake remain to be surveyed. Therefore, the interpretation of these survey results is limited to the lower resolution reconnaissance data without the benefit of ground truth follow-up or a more detailed survey. As a result, the reported depths can be expected to have a higher degree of error than future follow-up surveys will provide.

SURVEY RESULTS

Browne's Lake

Browne's Lake is located north of Antelope Lake and immediately south of Pedro Lake on the Tonopah Test Range, Nye County, Nevada. This site consists of flat lakebed sediments with little vegetation. The imagery data (see attached map) for Browne's Lake show the Browne's Lake road extending across the upper portion of the lakebed and a set of square multispectral calibration panels running north-south in the center of the image.

The EM survey identified one north-south trending area of disturbed earth located at approximately 473651N, 527880E, which contains several surface and shallow EM anomalies (labeled EM1) within the disturbed boundary. The designator "EM" in the target ID indicates that this target was identified using the EM data. The coincidence of these features would indicate a trench-like burial site with some entrained metallic debris. However, investigation of waste burial sites is not included in the approved SAFER plan. Just north of the disturbed area

are several circular disturbed earth features approximately 30 meters (m) in diameter that do not contain significant surficial metal debris and no evidence of a deep target. The exception is the northeastern circle, which shows a single large surface piece of metal centered within the circular feature. Another circular disturbed earth feature approximately 7m in diameter can be seen at 473702 N, 527898 E which does not contain any metal. The only deep EM targets noted on the lake are ID 254 and 633 located west of the suspect trench and circular features. They indicate a depth of 150-200 cm. Based on this information, these EM targets do not fit the profile of any of the CAU 484 CASs.

The Kiwi radiological survey identified four potential DU fragments with a ranking of “D,” indicating a non-spectral response but with a man-made count rate of 3-sigma over background. None of the Kiwi targets were associated with EMU responses. Target 4 was located on the southern edge of the lakebed just east of what appears to be an area of disturbed soil or erosion. Radiological ground-truthing of these D-ranked Potential DU fragments was conducted in the fall of 2005. Detailed radiological investigation of these potential targets did not identify any DU fragments, indicating contamination levels were too low to distinguish from background concentrations.

A summary of the survey findings from Browne’s Lake are as follows:

- No clear indication of a Davis Gun site with associated DU or buried projectiles was identified.
- A possible subsurface waste disposal site at EM1 was identified in proximity to several circular disturbed earth features. However, investigation of waste burial sites is not included in the approved SAFER plan.
- Four potential DU fragments were identified, but were discounted during DU during ground-truthing.

Pedro Lake

Pedro Lake was surveyed by the Kiwi and EMU systems to locate possible Davis Gun sites. Pedro Lake, located immediately north of Browne's Lake, is characterized by the Pedro Lake bombing target in the center of the lakebed (see attached map). The multispectral imagery shows four large circular features on the northern portion of the lake, and six smaller, less distinct circular features in the central and southwestern portion of the lake north of the road.

The EM survey identified numerous pieces of metallic debris scattered over the lake surface and buried at shallow to moderate depth 10 -75 cm (4 – 30 in). A weak large-object deep response (EM 1711) occurs on the west edge of the lake with a depth of 500 cm (200 in) but does not appear to be associated with any surface disturbances. The designator "EM" in the target ID indicates that this target was identified using the EM data.

The density of metallic debris increases in the center of the Pedro Lake Target and within the two circular topographic features located north of the Pedro Lake Target at 417458.6 N, 527473.2E and 417458.5 N, 527473.2 E. The multispectral imagery indicates the western most circular feature (IM-1) contains a rectangular area approximately 55 m x 40 m (180 x 130 ft) of disturbed earth and/or plant growth. The PA document indicated a large pit 30 x 61 m (100ft x 200 ft) was excavated on Pedro Lake and filled with granite boulders and used for Davis Gun tests. This feature matches that size and shape and may be the granite test site. There is some buried metal associated with these features as well as pieces of granite scattered on the lake bed surface. In addition, a large pile of granite boulders was located to the northwest just off the lake bed. Due to the evidence supporting this feature as a former Davis Gun test site, a detailed ground truthing EM survey would confirm or deny the presence of significant EM targets fitting the Davis Gun site profile.

Multispectral images indicate changes in soil reflectance in seven small circular disturbed earth features located at IM 2 – IM 8. The designator "IM" in the Target ID indicates a target identified from examination of the aerial imagery with no corresponding EM occurrence. This change in reflectance is interpreted as subsurface materials brought to the surface by excavation, penetrator testing, aerial bombardment, or vegetative growth. There are some shallow buried metal coincident with these areas and the bomb impact craters that are located across the lake may account for this reflectance change and associated metal fragments. However, a visual examination of these sites is recommended to determine if any of them are potential Davis Gun sites. Other small circular features occur but without the change in reflectance. They are located at IM 9 – 13 and each has some metallic debris associated with them, particularly IM 11. As noted above, these features could be aerial impact craters and investigation of these is not included in the approved SAFER plan.

The locations of these targets are summarized in Table 1. The imagery-derived targets are presented for informational purposes. A visual inspection of these targets would determine if they are bomb craters or potential Davis Gun locations. Any locations not ruled out during the site visit would be candidates for additional EM ground truthing to verify if the buried metal fits the Davis Gun site profile.

TABLE 1. PEDRO LAKE POTENTIAL DAVIS GUN SITES

NORTHING	EASTING	TARGET ID	COMMENTS
4174586	527473.2	IM* 1	Probable granite block Davis Gun Site with associated buried metal
4174656	527442.5	IM 2	Possible disturbed earth location
4174683	527534.6	IM 3	Possible disturbed earth location
4174221	527574.5	IM 4	Possible disturbed earth location
4174323	527398.9	IM 5	Possible disturbed earth location
4174352	527357.2	IM 6	Possible disturbed earth location
4174054	527987.1	IM 7	Possible disturbed earth location
4173745	527582.2	IM 8	Possible disturbed earth location
4174034	527769.8	IM 9	Possible disturbed earth location
4174046	527724	IM 10	Possible disturbed earth location
4174166	527620.6	IM 11	Possible disturbed earth location
4174150	527513.2	IM 12	Possible disturbed earth location
4174159	527477.8	IM 13	Possible disturbed earth location
4174587	527289.7	EM** 1711	EM target moderate size deep object

Targets shown in **bold** indicate the most likely candidates for potential Davis Gun sites. Remaining targets may be ruled out by field observations.

* Denotes target identified using aerial imagery

** Denotes target identified using EM data.

The linear features seen on the imagery base map that lead into both the Pedro Lake target and the northern circular feature IM1 are due to plant growth along a road or berm. The north-south trending linear feature seen in the imagery data running through the Pedro Lake target is a set of subsurface buried cables. However, this continuous metallic conductor created a negative EM response and therefore was removed during data processing and is not presented in the EM data set to facilitate examination of the data for presentation purposes.

The radiological survey did not identify any potential DU fragments on Pedro Lake.

A summary of the survey findings from Pedro Lake are as follows:

- Imagery target IM 1 is probably the granite block Davis Gun test area described in the PA. A walkdown of this target and potential EM ground truthing will determine if the buried metal located there meets the criteria for Davis Gun projectiles.
- Imagery targets IM 2 - IM 8 appear to be small circular excavations with subsurface soils brought to the surface by excavation, penetrator testing, aerial bombardment, or vegetative growth. Due to interference from surficial metal, a site walkdown is

recommended to determine the nature of these features. EM ground truthing may be necessary if they cannot be ruled out as Davis Gun sites.

- IM 9 – IM13 are small circular features with associated metal debris. Due to interference from surficial metal, a site walkdown is recommended to determine the nature of these features. EM ground truthing may be necessary if they cannot be ruled out as Davis Gun sites.
- One EM target (EM 1711) presents as a weak, deep, moderate-sized object, but there is no indication of surface disturbance in the immediate area. A visual inspection of this site is recommended. If there is indication of potential Davis Gun operations EM ground truthing will determine if the buried metal meets the criteria for a Davis Gun projectile.
- No potential DU targets were detected on Pedro Lake.

NEDS Lake

NEDS Lake is located north of Pedro Lake on the Tonopah Test Range, Nye County, Nevada, and consists of lakebed sediments with little vegetation. The NEDS detonation area (CAS TA-52-001-TANL) was located on the north end of NEDS Lake. NEDS Lake was also the site of the Colimbo test. No Davis Gun sites have been reported on NEDS Lake.

Multispectral imagery (see attached map) of the lakebed shows no circular features or disturbed earth that might be associated with a Davis Gun site. The prominent feature extending from the northwest to the southwest is a former roadway ending at mound of earth with angled concrete slabs. While the PA identified the NEDS test location on the northern portion of the lake, this mounded feature may be related to the NEDS test.

The EM data indicates a buried cable or metal conduit east of the berm/former roadway extending from the white containment tank (CAS TA-54-001-TANL) to the presumed NEDS test area. The depth is approximately 80 to 150 cm (32 to 60 in.). The PA documents indicated the white tank might have been used to burn propellant or have been used as a bunker for test personnel. The use of the tank as a command bunker is consistent with the EM data showing instrumentation cables and/or conduit leading from it to the test area as well as visual observations of the interior of the tank.

The area designated EM1 has a higher density of metallic debris than the surrounding area. This debris is predominantly on the surface with some of the buried material indicating a depth of approximately 100 – 300 cm (40 – 118 in.). The radiological survey also shows numerous responses from DU in this area.

Northwest of the Colimbo marker, the density of surface metallic debris (EM 2) increases significantly with the majority being on the surface with some of the buried material indicating depths to approximately 30 cm (12 in.). The area of EM 2 corresponds with the location of the NEDS test as identified in the PA. Some DU is also found in this area and immediately south of

it. The distribution of DU appears to be dispersed on a trend N25°W from the area designated EM1 or N70°W of the Colimbo monument.

A group of relatively deep metallic responses (EM 3) are noted just west of the berm and along the eastern lake margin at EM 4. There is no indication of disturbed earth at EM 4 while the buried target at EM 3 has some indications of either disturbed earth or plant growth in the immediate area. The concentration of shallow (surface to 65 cm [26 in.]) buried targets may indicate a small burial site at EM 3.

Radiological surveys indicate 20 Potential DU fragments identified varying from confirmed spectral identification (Rank A) to a non-spectral suspected DU target (Rank D). The general trend in the distribution of DU was northwesterly from the mounded area. No Co-60 responses were seen in the data and the missing valve with the Co-60 source was not located. The locations of potential DU fragments are summarized in Table 2.

TABLE 2. NEDS LAKE POTENTIAL DU FRAGMENTS

TARGET ID	RANK	NET CPS	LONGITUDE	LATITUDE
1	A1	1629	-116.695795	37.758638
2	A2	1331	-116.695048	37.758367
3	A3	1507	-116.693240	37.756034
4	A4	2298	-116.692048	37.759317
5	A5	1743	-116.694482	37.756965
6	A6	1155	-116.693297	37.756660
7	A7	2388	-116.693022	37.756189
8	B1	1028	-116.693360	37.756630
9	B2	321	-116.594725	37.757536
10	B3	447	-116.693042	37.756635
11	B4	415	-116.694183	37.757730
12	C1	505	-116.692169	37.756965
13	C2	320	-116.693220	37.756661
14	C3	365	-116.693128	37.755771
15	C4	235	-116.694439	37.755813
16	D1	869	-116.694980	37.758668
17	D2	357	-116.694107	37.757869
18	D3	594	-116.694882	37.757838
19	D4	684	-116.693893	37.757071
20	D5	368	-117.694903	37.756765

A summary of the survey findings from NEDS Lake are as follows:

- There is no evidence in the geophysical or multispectral data that would indicate a Davis Gun site. In addition, no Davis Gun test locations were reported in the PA for NEDS Lake.
- Instrumentation cables or conduit leading from the white tank to the presumed NEDS test area support evidence that the white tank was used as a command bunker for test personnel and not as a propellant burn site.
- Two EM targets (EM 1 and EM 2) were detected in areas corresponding with surface DU. Detailed EM ground truthing is recommended in this area to support the cleanup of the DU and to determine if the buried metal is associated with the DU fragments.
- Two potential debris burial sites (EM 3 and EM 4) were identified from the EM data. However, investigation of waste burial sites is not included in the approved SAFER plan.
- Twenty potential DU fragments were identified from the radiological data. Radiological ground-truthing of these targets could be performed in a during DU cleanup activities.

Antelope Lake

Antelope Lake was the site of numerous Davis Gun tests and also contains CAS TA-52-004-TALL, Metal Particle Dispersion Test (MPDT) and CAS TA-52-005-TAAL, Joint Test Assembly (JTA) DU sites.

During the surveys on Antelope Lake, a loss of the GPS data stream being acquired resulted in the loss of 12 lines of data north of IM 8. These lines will be re-run on a future survey.

One possible subsurface waste disposal site at EM1 was identified from the EM data. However, investigation of waste burial sites is not included in the approved SAFER plan and the target does not fit the criteria of the three CASs on Antelope Lake.

The findings on Antelope Lake and described below and grouped according to the three CASs.

CAS RG-52-007-TAML, Davis Gun Penetrator Test

Multispectral imagery indicates ten circular features, IM 1 – IM 10, located in the survey area (see attached map). In addition, a survey monument labeled “Davis Gun CP” is located near the middle of the five circular features labeled IM 1 – IM 5. These features are approximately 90 m (295 ft) in diameter and are likely locations of the Davis Gun tests.

IM 5, IM 4, IM 2 may have some small discrete areas of disturbed earth, while IM 1 appears to have had the entire central portion disturbed. IM 3 is relatively undisturbed but shows a circular boundary. IM 4 appears to have had some disturbed areas on the east side. IM 6 and IM 7 are located east of a suspected Davis Gun site and are also approximately 90 m (295 ft) in diameter. IM 6 had an elevated berm around it and was not entered prior to the survey termination. Three

other circular features, IM 8, IM 9, and IM 10 are found southeast along the terminus of the survey coverage. Due to the interruption of survey work, no EM or radiological data were obtained in IM 6, IM 9, and IM 10. The circular features at IM 6, IM 7, and IM 10 may be related to aerial bombing targets and not the Davis Gun tests. This could likely be determined during a site visit to further examine the area for bomb impact-related features. DU was detected between IM 2 and IM 5 (42) and on the west side of IM 4 (40). An additional DU target (45) is identified approximately 40m southwest of IM 2.

Five EM targets were identified for ground truth in the potential Davis Gun site located at IM 2 and represent a selection of deeper relatively moderate-sized targets. The locations of potential Davis Gun sites based on imagery and/or EM data are summarized in Table 3.

TABLE 3. POTENTIAL DAVIS GUN-RELATED EM AND IMAGERY TARGETS

NORTHING	EASTING	TARGET ID	COMMENTS
4172162.0	528259.6	EM 1	Potential Burial Site
4171660.5	528243.1	ID 2456	EM Target Associated with IM 2
4171682.9	528255.0	ID 2636	EM Target Associated with IM 2
4171680.0	528229.8	ID 2614	EM Target Associated with IM 2
4171685.7	528278.0	ID 2657	EM Target Associated with IM 2
4171660.5	528287.2	ID 2457	EM Target Associated with IM 2
4171927.2	529252.0	ID 11476	EM Target
4171442.0	528325.0	ID 1088	EM Target
417168.1	528379.7	ID 2615	EM Target
4171227.9	529020.8	ID 279	EM Target
4171671.6	528159.0	IM 1	Davis Gun site
4171671.6	528261.8	IM 2	Davis Gun site with 5 associated EM targets
4171671.4	528070.2	IM 3	Davis Gun site
4171672.0	528121.0	IM 4	Davis Gun site
4171672.3	528232.0	IM 5	Davis Gun site
417165.2	528518.7	IM 6	Potential Aerial Target or Davis Gun site
417162.6	528577.8	IM 7	Likely Aerial Target
417162.5	528580.0	IM 8	Potential Davis Gun site
4171674.2	528806.2	IM 9	Potential Davis Gun site
4171674.0	528871.3	IM 10	Potential Aerial Target or Davis Gun site

Targets shown in **bold** indicate the most likely candidates for potential Davis Gun sites. Remaining targets may be ruled out by field observations.

CAS TA-52-005-TAAL, Joint Test Assembly DU Sites

Target selection for potential JTA sites assumes that the DU rings would be buried approximately 60 to 120 cm (2- 4 ft) in depth and due to the amount of DU and oxidizing conditions, some mobilization of DU oxide to the surface could be expected. Target selection was based on apparent subsurface EM targets that corresponded to radiological targets.

Potential DU hits coincident or close to an apparent subsurface EM anomaly in the northern portion of Antelope Lake are 8, 10, 18, 20, 27, 31, 36, and 38. None of these targets fit the ideal model assumed for a JTA ring. Locations 38 (5,998 net counts per second [cps]) and 36 (2,382 cps) are the highest count rates while the count rate for 8, 20, and 18 and 31 are relatively equivalent. Target 10 occurs in an area with considerable metallic debris and with moderate depth. Target 27 occurs in close proximity to two deeper-EM responses. Additional EM ground-truthing will confirm or deny if any of these targets are good candidates for excavation. Targets identified as potential JTA rings based on the radiological survey are summarized in Table 4.

TABLE 4. POTENTIAL JTA DU RINGS

TARGET ID	RANKING	EASTING	NORTHING	NET_MM_CPS*
8	D	527907.5	4172769.9	1717
10	D	527884.6	4172663.4	1641
18	D	528142.7	4172614.1	1705
20	D	528018.8	4172522.9	1743
27	D	527787.7	4172302.5	2074
31	D	527813.9	4172165.8	1666
36	B	528471.9	4172676.6	2382
38	A	528285.5	4172289.5	5998

Targets shown in **bold** indicate the most likely candidates for JTA rings based on radiological data. Remaining targets may be ruled out by field observations.

*Background corrected, man-made counts per second

Target selection by EM for the JTA assumed a moderate depth of burial of approximately 60-120 cm (2-4 ft) with a moderate target size. Targets identified with the EM data are summarized in Table 5.

TABLE 5. POTENTIAL JTA EM TARGETS

TARGET ID	NORTHING	EASTING	ID
1	4172924.7	528152.8	JT 11412
2	4171981.8	528855.0	JT 4724
3	4172164.5	527924.0	JT 6247
4	4172226.1	528077.2	JT 6667
5	4172373.1	528432.0	JT 8053
6	4172372.0	528593.8	JT 8031
7	4172751.1	528360.7	JT 10879
8	4172844.9	528160.5	JT 11264
9	4172675.5	528181.5	JT 10305
10	4172887.6	528165.4	JT 11366

CAS TA-52-004-TAAL, Metal Particle Dispersion Test

The MPDT can be seen on the imagery as the rectangular area in the upper northwest portion of Antelope Lake. Thirty-five potential DU fragments are located within this boundary.

Distribution of metallic debris is concentrated in the southwest corner and the upper central portion of the soil contamination area (SCA) with a pronounced southwesterly trend. The southwest trend of metallic debris seen on the lake is due to transport from water entering the lakebed on the northwestern corner. In addition, water and wind movement caused linear features to be formed when the metal was trapped along the lakebed fractures.

Soil sampling is recommended in depositional areas of mobilized metal, areas of high metal concentration and in the vicinity of the detonation as specified in the SAFER plan. Potential DU fragments detected in the SCA are summarized in Table 6. Additional potential DU fragments detected elsewhere on Antelope Lake are summarized in Table 7.

TABLE 6. POTENTIAL DU FRAGMENTS IN THE SCA

Target ID	Ranking	Easting	Northing	Net_MM_CPS*
1	D	528111.5	4172919.6	1721
2	D	527790.6	4172885.0	1798
3	D	527982.5	4172861.3	1648
4	D	527963.1	4172821.9	1614
5	D	527974.5	4172825.0	1699
6	D	528050.8	4172825.3	1788
7	D	528114.0	4172788.6	1735
8	D	527907.5	4172769.9	1717
9	D	528067.5	4172757.7	1662
10	D	527884.6	4172663.4	1641
11	D	527975.6	4172654.3	1860
12	D	527701.9	4172650.2	1815
13	D	527812.7	4172642.0	1756
14	D	527947.3	4172648.2	1610
15	D	527807.5	4172613.9	1724
16	D	527693.6	4172607.6	1705
17	D	527859.0	4172605.0	1689
18	D	528142.7	4172614.1	1705
19	D	528087.9	4172590.5	1865
20	D	528018.8	4172522.9	1743
21	D	527897.0	4172509.8	1604
22	D	527968.9	4172470.8	1713
23	D	528060.3	4172467.5	1935
24	D	527712.8	4172394.1	1743
25	D	527797.3	4172388.3	1660
26	D	527734.0	4172314.4	1761
27	D	527787.7	4172302.5	2074
28	D	527840.5	4172302.8	1698
29	D	527919.3	4172282.2	1679
30	D	527745.4	4172177.5	1859
31	D	527813.9	4172165.8	1666
32	D	528123.6	4172092.6	1932
33	A	527902.8	4172074.9	4201
34	D	527949.8	4172005.4	2042
35	D	527905.2	4171964.8	1617

*Background corrected, man-made counts per second

TABLE 7. ADDITIONAL ANTELOPE LAKE POTENTIAL DU FRAGMENTS

LOCATION	RANKING	EASTING	NORTHING	NET_MM_CPS*
36	B	528471.9	4172676.6	2382
37	A	528601.9	4172396.9	7204
38	A	528285.5	4172289.5	5998
39	C	527696.7	4171903.0	2333
40	D	528096.4	4171755.4	2211
41	C	527750.5	4171717.7	2147
42	D	528250.3	4171721.9	2175
43	D	527774.3	4171592.7	2406
44	D	527798.2	4171589.8	2171
45	D	528297.5	4171591.5	2240
46	D	527888.6	4171587.3	2122
47	D	528466.0	4171582.8	2160
48	C	528656.2	4171288.7	2239
49	A	528649.5	4171285.1	14150
50	B	528657.8	4171281.9	3963
51	D	527938.2	4171178.8	2174

*Background corrected, man-made counts per second

A summary of the survey findings from Antelope Lake are as follows:

- A survey monument labeled “Davis Gun CP” is located near middle of five circular features (IM 1 – IM 5). These features are approximately 90 m (295 ft) in diameter and are the most likely sites of the Davis Gun tests.
- Nine targets fitting the criteria for Davis Gun were identified from the EM data, five of which are located within a single Davis Gun location. A site visit is recommended to determine if any of these targets are candidates for EM ground truthing.
- Ten targets fitting the criteria for potential Davis Gun sites were identified from the aerial imagery. However, three of these circular features may be related to aerial bombing rather than the Davis Gun tests. A site visit is recommended to determine if any of these targets are candidates for EM ground truthing.
- No targets fit the ideal conceptual model for the JTA buried DU rings. However, follow up site visits and EM ground truth (if needed) on 10 selected targets is recommended during DU removal.
- Due to wind and water movement of metallic debris the distribution of metallic debris in the MPDT is concentrated in the southwest corner and the upper central portion of the soil contamination area (SCA) with a pronounced southwesterly trend. Soil sampling is recommended in these areas per the SAFER Plan.

- Thirty-five potential DU fragments were identified in the SCA, while an additional 16 potential DU fragments were identified in the remainder of the surveyed areas of Antelope Lake.

CONCLUSION

Upon resuming the survey activities at TTR in 2006 with UXO subcontractor support, the data included in this report will allow potential target sites to be inspected either through site visits and/or additional localized EM surveys. Ground truthing of these potential sites will facilitate analysis of the remaining 550 acres on Antelope Lake based on the improved target profiles. Based on the results of the investigation, the following findings were noted:

Browne's Lake

- No clear indication of a Davis Gun site with associated DU or buried projectiles was identified.
- A possible subsurface waste disposal site was identified in proximity to several circular disturbed earth features. However, investigation of waste burial sites is not included in the approved SAFER plan.
- Four potential DU fragments were identified, but were not identified or located during ground-truthing.

Pedro Lake

- One circular topographic feature identified from the aerial imagery corresponds to the description of a Davis Gun test location. A walkdown of this feature and potential Electromagnetic (EM) ground truthing will determine if the buried metal detected there meets the criteria for Davis Gun projectiles.
- Twelve circular topographic features were identified from the aerial imagery resembling the physical characteristics of a Davis Gun site as well exhibiting EM responses. While several of these features may be bomb craters unrelated to the Davis Gun tests, a site walkdown is recommended to determine the nature of these features. EM ground truthing may be necessary if they cannot be ruled out as Davis Gun sites.
- One potential Davis Gun site was identified from the EM data. While there is no indication of surface disturbance in the immediate area evident from the aerial imagery, a visual inspection of this site is recommended. If there is indication of potential Davis Gun operations, EM ground truthing will determine if the buried metal meets the criteria for Davis Gun projectiles.
- No potential DU fragments were detected on Pedro Lake.

NEDS Lake

- There is no evidence in the geophysical or multispectral data that would indicate the presence of a Davis Gun site.
- Instrumentation cables or conduit leading from the white containment tank (CAS TA-54-001-TANL) to the presumed NEDS test area support evidence that the white tank was used as a command bunker for test personnel and not as a propellant burn site.
- Two targets were identified from the EM data in areas corresponding with surface DU. Detailed EM ground truthing in support of DU cleanup will determine if these targets are associated with the surface DU.
- Two potential debris burial sites were identified from the EM data. However, investigation of waste burial sites is not included in the approved SAFER plan.
- Twenty potential DU fragments were identified from the radiological data.

Antelope Lake

- Nine buried metal objects fitting the criteria for Davis Gun sites were identified from the EM data. Ten topographic features fitting the criteria for potential Davis Gun sites were identified from the aerial imagery. In addition, a survey monument labeled “Davis Gun CP” is located near middle of five of these topographic features. A site visit is recommended to determine if any of these objects are candidates for EM ground truthing.
- No targets fit the ideal conceptual model for the JTA buried DU rings. However, follow up site visits and EM ground truth (if needed) on 10 selected targets is recommended during DU fragment removal to confirm or deny the presence of the JTA rings due to the close proximity of potential surface DU fragments and subsurface EM targets.
- Due to wind and water movement of metallic debris, the distribution of metallic debris in the MPDT is concentrated in the southwest corner and the upper central portion of the soil contamination area (SCA) with a pronounced southwesterly trend. Soil sampling is recommended in these areas per the SAFER Plan.
- Thirty-five potential DU fragments were identified in the SCA, while an additional 16 potential DU fragments were identified in the remainder of the surveyed areas of Antelope Lake.

THIS PAGE INTENTIONALLY LEFT BLANK

APPENDIX G

POSITION PAPER

**Depleted Uranium Closure In Place
Tonopah Test Range, Nye County, Nevada
August 2007**

THIS PAGE INTENTIONALLY LEFT BLANK

**CAU 484: SURFACE DEBRIS, WASTE SITES,
AND BURN AREA (TTR)**

DEPLETED URANIUM CLOSURE IN PLACE

**TONOPAH TEST RANGE, NYE COUNTY,
NEVADA**

AUGUST 2007

CAU 484 DEPLETED URANIUM CLOSURE IN PLACE

The Streamlined Approach for Environmental Restoration (SAFER) Plan for Corrective Action Unit (CAU) 484 calls for the identification and remediation of surface hot spot depleted uranium (DU) with some excavation to determine the vertical extent of contamination. During the CAU 484 SAFER investigation, approximately 50 locations containing DU were identified on Antelope Lake, and approximately 30 locations containing DU were identified on NEDS Lake.

Remediation activities have resulted in the removal of all detectable DU on NEDS Lake. All but four locations have been remediated on Antelope Lake. A total of 275 cubic yards of DU-impacted soil have been removed from Antelope Lake. Approximately 246 of the 275 cubic yards were removed from four remaining sites. These four sites have reached a hold point condition as described in Section 1.3, Hold/Decision Points, of the SAFER Plan.

At three of the four sites, the volume of DU-impacted soil greatly exceeds the SAFER conceptual site model assumption of a small volume hot spot; two have been excavated to depths of 3.5 to 7 feet (ft) below ground surface (bgs), and a third, with a footprint of 30 ft by 60 ft, has been excavated to a depth of 0.5 ft bgs. At the fourth site, unexploded ordnance (UXO) and other debris have been discovered that present a greater hazard than the DU; this location has been excavated to a depth of 2 ft bgs.

Recently completed Kiwi surveys using four sodium iodide detectors and post processing algorithms for isolating the radiological response from DU have confirmed that residual DU is present in the four remaining excavations and that some minor contamination is present along the surface margins of three of the sites. The goal of the CAU 484 closure is to minimize the potential for exposure to DU by eliminating the presence of DU on the lake bed surface. Keeping this goal in mind, closure in place with subsurface use restrictions for the remaining four locations is proposed. The following closure approach would be taken for the four remaining sites on Antelope Lake.

CA-1

An area measuring approximately 15 ft by 20 ft was excavated to a depth of 7 ft. Kiwi surveys have identified areas of elevated readings indicating possible surface and/or subsurface DU contamination from the southeast edge of the excavation extending out approximately 20 ft. Consistent with the remediation and field verification methods used to date, the surface areas identified by the Kiwi will be marked for remediation. Areas marked for surface contamination will be remediated by scraping and/or excavating the area to a depth of 0.5 ft bgs. Contaminated material will be placed into the larger excavation. The entire excavation will then be backfilled with clean fill and compacted to surface grade. The surface area will be confirmed clean by a final Kiwi drive over survey. The area containing subsurface DU contamination will be land surveyed and posted with use restriction warning signs, and a use restriction will be implemented.

SA-5-9

An area measuring approximately 30 ft by 35 ft was excavated to a depth of 3.5 ft. Residual DU contamination was detected only within the excavation. The excavation will be backfilled with clean fill and compacted to surface grade. The area containing subsurface DU contamination will be land surveyed and posted with use restriction warning signs, and a use restriction will be implemented.

SA-12-15

An area measuring approximately 30 ft by 60 ft was excavated to a depth of 0.5 ft. Kiwi surveys have identified a subsurface area within the excavation and two isolated locations on the edge of the excavation with elevated readings indicating possible surface and/or subsurface DU contamination. Consistent with the remediation and field verification methods used to date, the surface areas outside the current excavation identified by the Kiwi will be marked for remediation. Areas marked for surface contamination will be remediated by scraping and/or excavating the area to a depth of 0.5 ft bgs. Contaminated material will be placed in the CA-1 excavation. The entire excavation will be backfilled with clean fill and compacted to surface grade. The surface area will be confirmed clean by a final Kiwi drive over survey. The area containing subsurface DU contamination will be land surveyed and posted with use restriction warning signs, and a use restriction will be implemented.

SA-4

Remediation/excavation activities were halted in this area due to the discovery of UXO and other debris not in the scope of CAU 484. The current excavation is approximately 15 ft by 5 ft and approximately 2 ft deep. Kiwi surveys have identified areas of elevated readings indicating possible surface and/or subsurface DU contamination at the north, east, and south edges of the current excavation. Consistent with the remediation and field verification methods used to date, the surface areas identified by the Kiwi will be scanned for UXO and, if clear, marked for remediation. Areas marked for surface contamination will be remediated by scraping and/or excavating the area to a depth of 0.5 ft bgs. If the areas cannot be cleared for UXO, they will be marked and included in the posted use restriction area. Contaminated material will be placed into the larger excavation. The entire excavation will be backfilled with clean fill and compacted to surface grade. The surface area will be confirmed clean by a final Kiwi drive over survey. The area containing subsurface DU contamination will be land surveyed and posted with use restriction warning signs, and a use restriction will be implemented.

CONCLUSION

After this work is completed, all locations identified as containing DU during the SAFER investigation will have been clean closed or closed in place with only residual subsurface contamination remaining. The areas with remaining subsurface contamination will be posted, and use restrictions will be implemented. Fill material applied to each location may be slightly mounded to prevent standing water.

THIS PAGE INTENTIONALLY LEFT BLANK

APPENDIX H

UXO REPORT

UXO Removal and Destruction at CAU 484 Tonopah Test Range, Nevada

THIS PAGE INTENTIONALLY LEFT BLANK

**UXO Removal and Destruction
at CAU 484
Tonopah Test Range, Nevada**

Final

Stoller-Navarro Joint Venture
Las Vegas, Nevada 89129

June 2007

Table of Contents

List of Figures	ii
List of Tables	iv
Acronyms and Abbreviations	v
1.0 Introduction.....	1
2.0 Site Description.....	2
3.0 Initial Scope of Work.....	3
4.0 Pre-Investigation Activities	4
5.0 UXO Removal Activities.....	5
6.0 UXO Destruction Activities.....	7
7.0 Conclusion	8

Attachment A - Photos

Attachment B - NDEP Temporary Emergency Permit for Treatment of UXO

Attachment C - Certification Log

Attachment D - NNSA/NSO to NDEP Permit Closeout Letter

List of Figures

<i>Number</i>	<i>Title</i>	<i>Page</i>
1	Overview of Pedro Lake Showing Locations of Pits P1 through P4.....	A-1
2	Overview of Antelope Lake Showing Locations of Pits A1 and A2.....	A-2
3	Pits P3 (foreground) and P4 at Pedro Lake (pre-removal, Feb. 21, 2007)	A-3
4	Pits P1 (background) and P2 at Pedro Lake (pre-removal, Feb. 21, 2007)	A-3
5	Pre-removal View of P1 at Pedro Lake (Feb. 21, 2007).....	A-4
6	Post-removal View of P1 at Pedro Lake (Feb. 21, 2007)	A-4
7	Pre-removal View of P2 at Pedro Lake (Feb. 21, 2007).....	A-5
8	Post-removal View of P2 at Pedro Lake (Feb. 21, 2007)	A-5
9	Pre-removal View of P4 at Pedro Lake (Feb. 21, 2007).....	A-6
10	Post-removal View of P4 at Pedro Lake (Feb. 21, 2007)	A-6
11	Pre-removal View of P3 at Pedro Lake (Feb. 21, 2007).....	A-7
12	Post-removal View of P3 at Pedro Lake (Feb. 21, 2007)	A-7
13	Pre-removal View of A1 Excavation (MK-82) at Antelope Lake (Feb. 21, 2007)	A-8
14	Pre-removal View of A2 Excavation (155 mm) at Antelope Lake (Feb. 21, 2007)	A-9
15	Representative View of Surface UXO (BLU 63) Identified at South End of Antelope Lake (Feb. 21, 2007)	A-10
16	Recovered UXO from Pits P1 through P4 at Pedro Lake (Feb. 21, 2007)	A-11
17	Front View of Six Recovered UXO Items before Destruction at Pedro Lake (Feb. 21, 2007).....	A-12
18	Back View of Same Six Recovered UXO Items before Destruction (Feb. 21, 2007).....	A-12
19	Post-destruction Overview of Five of the Six UXO at Pedro Lake (Feb. 22, 2007).....	A-13

List of Figures (Continued)

<i>Number</i>	<i>Title</i>	<i>Page</i>
20 and 21	Post-destruction Photos of M117s at Pedro Lake (recovered from P2 and P3) (Feb. 22, 2007)	A-14
22 and 23	Post-destruction View of MK-82s at Pedro Lake (recovered from P1 and P4) (Feb. 22, 2007)	A-15
24	Post-destruction View of MK-82 at Pedro Lake (recovered from A1) (Feb. 22, 2007).....	A-16

List of Tables

<i>Number</i>	<i>Title</i>	<i>Page</i>
6.0	Recovered UXO from Pedro and Antelope Lakes	7

Acronyms and Abbreviations

bgs	Below ground surface
CAU	Corrective Action Unit
ft	Foot
MEC	Munitions and explosives of concern
NDEP	Nevada Division of Environmental Protection
NNSA/NSO	U.S. Department of Energy, National Nuclear Security Administration Nevada Operations Office
NSTec	National Security Technologies, LLC
POD	Plan of the Day
REOP	Real Estate/Operations Permit
SAFER	Streamlined Approach for Environmental Restoration
SNL	Sandia National Laboratories
TTR	Tonopah Test Range
UXO	Unexploded ordnance

1.0 Introduction

The Tonopah Test Range (TTR) unexploded ordnance (UXO) removal scope of work activities were conducted to assist National Security Technologies, LLC (NSTec) in the destruction of UXO items identified during the NSTec investigation activities performed under the Corrective Action Unit (CAU) 484 Streamlined Approach for Environmental Restoration (SAFER) Plan.

The UXO removal activities included the following:

- Uncovered each suspect UXO item within the open excavations using a combination of hand tools and/or heavy equipment.
- Determined that UXO recovered in excavations could be safely moved before destruction, and surface UXO could be left in place for destruction.
- Performed radiological field screening on soil and debris.
- Performed geophysical surveys using Schonstedts to confirm that no additional metallic items (potential UXO) were present within each excavation.
- Maintained a certification log of the various types of debris identified (including number and types of live UXO destroyed).
- Vented (destroyed) all suspect UXO items to confirm they were inert.
- Staged scrap metal resulting from the destruction of UXO items for proper disposition. Scrap metal waste is being managed by NSTec as non-hazardous waste.
- Delivered, transported, and used all high explosives on the same day. The onsite transport and management of explosives was performed by appropriately trained personnel from Sandia National Laboratories (SNL), with oversight by Stoller-Navarro Joint Venture (SNJV) and Weston UXO personnel.

All work at the TTR site was conducted under the primary Real Estate/Operations Permit (REOP) BN-0243-02. The Plan of the Day (POD) program was implemented by the Site Supervisor during this investigation, and included using daily POD briefings and Tailgate Safety Briefings.

2.0 Site Description

Six open and roped-off excavation pits were investigated under this scope of work for the TTR UXO removal. The six excavations were located within the footprint of CAU 484 and CAS RG-52-007-TAML. Four excavations were located on the southern end of Pedro Lake, and two excavations were located at the northern end of Antelope Lake at the TTR. [Attachment A \(Photos 1 and 2\)](#) of this report includes two aerial photographs showing the general area of the excavations with the respective coordinates of each excavation provided. In addition, a portion of southern Antelope Lake was investigated as the location of up to 15 UXO tentatively identified as 40 mm grenades on the ground surface.

3.0 Initial Scope of Work

During investigation activities in October and November 2006, NSTec excavated several anomalies identified during a geophysical survey. These anomalies turned out to be UXO items of various types. Upon discovery of the UXO items, NSTec had suspended work and left the excavations open. Each ordnance item had been partially exposed at the bottom of each excavation (6 to 8 feet [ft] below ground surface [bgs]) with tentative identification of UXO items that included MK-82s, MK-84s, and one potential ordnance item of unknown type but that resembled a 155 mm round. In addition to the excavation pits, 15 (40 mm) grenades had been tentatively identified for destruction on the ground surface in the southern portion of Antelope Lake.

The specific activities included, but were not limited to, the following for TTR UXO removal:

- Excavation to fully uncover and identify the type and condition of UXO
- Removal of UXO if necessary to accommodate destruction
- Destruction of all UXO items to detonate or confirm inert
- Survey excavations to confirm no additional UXO/munitions and explosives of concern (MEC) present

4.0 Pre-Investigation Activities

Pre investigation activities included the procurement of an Emergency Treatment permit from the Nevada Division of Environmental Protection (NDEP) and public notices in a local newspaper. The U.S. Department of Energy, National Nuclear Security Administration Nevada Site Office (NNSA/NSO) received a Nevada Bureau of Federal Facilities temporary emergency permit for CAU 484 on the TTR. Public Notices were published on February 6 and 13, 2007. The Temporary Emergency Permit authorizes the permitted entity to treat by means of open detonation the UXO recently found during excavations and geophysical surveys pertaining to remediation of CAU 484 on the TTR. A copy of the Temporary Emergency permit is included in [Attachment B](#). The NNSA/NSO and U.S. Air Force coordinated an airspace clearance schedule to provide an adequate safety perimeter during UXO destruction activities.

5.0 UXO Removal Activities

All investigation and removal activities were performed by SNJV and Weston personnel in accordance with subject areas and procedures in the SNJV SBMS, Weston MEC Clearance Work Plan, and the SNJV Field Work Permit.

On February 21, 2007, SNJV, Weston, and NSTec personnel inspected and confirmed locations of previously identified UXO items at Pedro and Antelope Lakes. Three open excavations were originally reported at Pedro Lake; however, four open excavations were discovered upon inspection of the Pedro Lake area. After establishing the safety perimeters and exclusion zones, Weston UXO personnel used heavy equipment to fully expose each UXO item at Pedro Lake within excavations that reached depths up to 10 to 12 ft bgs. All four UXO items found at Pedro Lake were deemed safe to remove and were placed on the ground surface for destruction.

With the aid of SNL and NSTec personnel, 8 of the 15 potential 40 mm grenades on the ground surface at the south end of Antelope Lake were re-identified and marked for destruction. The remaining seven were unaccounted for. The two open excavations at Antelope Lake were shallow enough to allow Weston personnel to fully expose and identify the UXO by hand digging. The two UXO items found at Antelope Lake during the excavations were deemed safe to move to Pedro Lake for destruction. No excavation was necessary for the surface UXO (potential 40 mm grenades) found at Antelope Lake, and none of these items were moved before destruction.

Photos showing each of the identified UXO from the Pedro and Antelope Lake excavations are included in [Attachment A](#). The aerial photos provided in [Attachment A \(Photos 1 and 2\)](#) also show the number designation given to each excavated pit. The type of each UXO identified at the four excavations at Pedro Lake and the two locations at the northern end of Antelope Lake are listed as follows:

- P1 – MK-82 (see [Photo 16](#) in [Attachment A](#))
- P2 – M117 bomb (see [Photo 16](#) in [Attachment A](#))
- P3 – M117 bomb (see [Photo 16](#) in [Attachment A](#))
- P4 – MK-82 (see [Photo 16](#) in [Attachment A](#))
- A1 – MK-82 (see [Photo 13](#) in [Attachment A](#))
- A2 – 155 mm projectile (see [Photo 14](#) in [Attachment A](#))

Radiological field screening was performed by SNJV personnel on soil and debris during all field activities. Radioactivity was not identified on any debris or surrounding soil. After each UXO item was removed within each excavation, Weston personnel performed geophysical

surveys using Schonstedts and confirmed that no additional metallic items (potential UXO) were present within each excavation. All open excavations at Pedro and Antelope Lakes were backfilled to original grade upon confirmation that no additional metallic anomalies were present.

6.0 UXO Destruction Activities

Upon completion of additional excavation at Pedro and Antelope Lakes to uncover, identify, and recover UXO, Weston personnel treated all of the recovered UXO in accordance with the NDEP Temporary Emergency permit. Onsite transportation and management of the explosives used in the detonation events was performed by appropriately trained SNL personnel. A log (DD Form 1348) certifying that the MK-82 and M117 items (5 total) were rendered inert and are considered scrap metal at Pedro Lake was completed by Weston personnel and is included as [Attachment C](#). This log is required for waste disposal purposes.

A total of three detonations were conducted, all on February 22, 2007. Before each detonation, airspace clearance was obtained from the U.S. Air Force. [Table 6.0](#) provides details regarding the type, quantity, and location of UXO rendered inert on February 22, 2007. The table provides the types of explosives used in the destruction of the UXO.

Table 6.0
Recovered UXO from Pedro and Antelope Lakes

Quantity/Types of UXO	Detonation Location	Donor Charge Expended
Detonation 1 – 10 AM		
3 - MK-82 bombs (inert) 2 - M117 bombs (inert) 1 - 155 mm HE projectile	Pedro Lake	10-pound C-4 50 each 32-gram perforators 10 each electric blasting caps
Detonation 2 – 10:30 AM		
2 - 40 mm grenades 2 - BLU 63 submunitions	Antelope Lake	3-pound C-4 6 each electric blasting caps
Detonation 3 – 10:45 AM		
2 - 40 mm grenades 1 - BLU 63 submunition 1 - Aircraft flare	Antelope Lake	3-pound C-4 9 each electric blasting caps

Each detonation site was visually inspected after treatments occurred, and no residual contamination was found. All UXO items were rendered inert, and the scrap metal resulting from the destruction at Pedro Lake (i.e., MK-82, 155 mm, and M117 bombs) was staged for waste disposal by NSTec personnel. All high explosives were used in the destruction of the UXO, leaving no hazardous waste. Destruction of the 40 mm grenades and BLU 63s left no scrap metal for disposal. All treatments were conducted safely, efficiently, and in a manner protective to human health and the environment.

7.0 Conclusion

All of these munitions items have been around for many years, and it is difficult to determine exactly when they were used on the TTR Site. The M117 bombs are of a late 1950s vintage and are still being used until the complete stockpile within the U.S. arsenal is depleted. The MK-80 Series bombs have been around from the mid-1960s and are still heavily used in any military air-dropped bombing campaign. Based on the condition of the air-dropped bombs excavated at TTR during this operation, the MK-80s have been in the ground approximately 20 years.

There are no additional activities required under this scope of work, and all identified UXO were rendered inert. The reporting requirements of the NDEP Temporary Emergency Permit have been met, and the permit has since been terminated in accordance with a letter from NNSA/NSO to NDEP dated April 10, 2007. A copy of this letter is included as [Attachment D](#). Additional documentation is available in the SNJV project files.

Attachment A

Photos

Photo 1: Overview of Pedro Lake Showing Locations of Pits P1 through P4
The location of Pit P4 is approximated because no GPS coordinates were collected.

Photo 2: Overview of Antelope Lake Showing Locations of Pits A1 and A2

Photo 3: Pits P3 (foreground) and P4 at Pedro Lake (pre-removal, Feb. 21, 2007)

Photo 4: Pits P1 (background) and P2 at Pedro Lake (pre-removal, Feb. 21, 2007)

Photo 5: Pre-removal View of P1 at Pedro Lake (Feb. 21, 2007)

Photo 6: Post-removal View of P1 at Pedro Lake (Feb. 21, 2007)

Photo 7: Pre-removal View of P2 at Pedro Lake (Feb. 21, 2007)

Photo 8: Post-removal View of P2 at Pedro Lake (Feb. 21, 2007)

Photo 9: Pre-removal View of P4 at Pedro Lake (Feb. 21, 2007)

Photo 10: Post-removal View of P4 at Pedro Lake (Feb. 21, 2007)

Photo 11: Pre-removal View of P3 at Pedro Lake (Feb. 21, 2007)

Photo 12: Post-removal View of P3 at Pedro Lake (Feb. 21, 2007)

Photo 13: Pre-removal View of A1 Excavation (MK-82)
at Antelope Lake (Feb. 21, 2007)

Photo 14: Pre-removal View of A2 Excavation (155 mm)
at Antelope Lake (Feb. 21, 2007)

Photo 15: Representative View of Surface UXO (BLU 63) Identified at South End of Antelope Lake (Feb. 21, 2007)

Photo 16: Recovered UXO from Pits P1 through P4 at Pedro Lake (Feb. 21, 2007)
From left to right: M117 (P3); MK-82 (P1); M117 (P2); MK-82 (P4).

Photo 17: Front View of Six Recovered UXO Items
before Destruction at Pedro Lake (Feb. 21, 2007)

Photo 18: Back View of Same Six Recovered UXO Items
before Destruction (Feb. 21, 2007)

Photo 19: Post-destruction Overview of Five of the Six UXO
at Pedro Lake (Feb. 22, 2007)

Note the backfilled excavations of P3 and P4 in background.

Photos 20 and 21: Post-destruction Photos of M117s at Pedro Lake
(recovered from P2 and P3) (Feb. 22, 2007)

Photos 22 and 23: Post-destruction View of MK-82s at Pedro Lake
(recovered from P1 and P4) (Feb. 22, 2007)

Photo 24: Post-destruction View of MK-82 at Pedro Lake
(recovered from A1) (Feb. 22, 2007)

Attachment B

NDEP Temporary Emergency Permit for Treatment of UXO

(3 Pages)

STATE OF NEVADA

Department of Conservation & Natural Resources

DIVISION OF ENVIRONMENTAL PROTECTION

Jim Gibbons, Governor

Allen Biaggi, Director

Leo M. Drozdoff, P.E., Administrator

January 29, 2007

Mr. Ken Small, RCRA Program Manager
Waste Management Project
National Nuclear Security Administration
Nevada Site Office
P.O. Box 98518
Las Vegas, NV 89193-8518

Re: Temporary Emergency Permit for Treatment of Unexploded Ordnance (UXO) Found
During Remediation Activities for Corrective Action Unit (CAU) 484 on the Tonopah Test
Range (TTR)

Dear Mr. Small:

The Nevada Division of Environmental Protection staff (NDEP) received the subject request dated January 24, 2007. The request pertains to UXO discovered during excavation and during geophysical surveys associated with CAU 484 at the TTR. The request states that approximately twenty (20) pieces of ordnance have been found with a possibility that additional ordnance may be found during the excavation, repositioning and treatment of the UXO discovered to date. Three excavations on Pedro Lake have thus far uncovered three bombs. Two excavations on Antelope Lake have thus far uncovered a bomb and a 155 mm round. Approximately fifteen 40 mm grenades have been discovered on the ground surface on Antelope Lake.

NDEP has reviewed the information provided and attaches a 90-Day Emergency Permit to be effective on February 12, 2007 and to remain in effect until May 13, 2007.

RCRA regulation 40 CFR 270.61 is the correct reference for items that pose an "imminent and substantial endangerment to human health or the environment".

Address any questions regarding this matter to either Ted Zaferatos at (702) 486-2850, ext. 234, Don Elle at (702) 486-2850, ext. 229, or myself at (702) 486-2850, ext. 231.

Sincerely,

T.H. Murphy
Chief
Bureau of Federal Facilities

1771 E. Flamingo Road Suite 121-A • Las Vegas, Nevada 89119 • p: 702.486.2850 • f: 702.486.2863 • www.ndep.nv.gov

Printed on recycled paper

Uncontrolled When Printed

Mr. Ken Small, RCRA Program Manager

Page 2

January 29, 2007

DRE/TZ

Enclosure

cc: E. F. Di Sanza, WMP, NNSA/NSO
Janet Appenzeller-Wing, AD/AMEM, NNSA/NSO
Kevin Cabbie, ERP, NNSA/NSO
Pete Sanders, ERP, NNSA/NSO
W.R. Wilborn, A/ERP, NNSA/NSO
P. Hall, PSG, NNSA/NSO
K.K. Snyder, PSG, NNSA/NSO
K.A. Hoar, AD/AMSP, NNSA/NSO
Lt. Col. B.C. Kieffer, 98RANW/XPD, Nellis AFB
Eloise Hopper, Nellis AFB
98 RANW/CC, 3770 Duffer Drive, Las Vegas, NV 89191
98 RANW/XPL, 3770 Duffer Drive, Las Vegas, NV 89191
Vern Gabbard, SNL/TTR
J. Elliston, Westinghouse, TTR
T.A. Thiele, NSTec, Mercury, NV
J.L. Smith, NSTec, NSTec, Mercury, NV
John Fowler, SNJV, Las Vegas, NV
R.F. Boehlecke, SNJV
S.K. Krenzien, NREI, Las Vegas, NV
D.C. Loewer, DTRA/CXT1, M/S 645 Mercury, NV
T.A. Lantow, DTRA/CXT1, M/S 645 Mercury, NV
W.R. Griffin, SNJV/DTRA, M/S 645 Mercury, NV
M.A. DeBurle, NDEP-CC

Temporary Emergency Permit

The Nevada Division of Environmental Protection hereby issues this Temporary Emergency Permit to The United States Department of Energy National Nuclear Security Administration, Nevada Site Office (NNSA/NSO), PO Box 98518, Las Vegas, Nevada 89193 (Permittee) pursuant to the provisions of 40 CFR 270.61 under the authority of Nevada Revised Statutes (NRS) 459.520 and Nevada Administrative Code (NAC) 444.8632.

This Temporary Emergency Permit authorizes the Permittee to treat by means of open detonation the Unexploded Ordnance (UXO) recently found during excavations and geophysical surveys pertaining to remediation of Corrective Action Unit (CAU) 484 on the Tonopah Test Range (TTR). Excavations on Pedro Lake have uncovered one (1) Mark 82 bomb and two (2) Mark 84 bombs. Excavations on Antelope Lake have uncovered one (1) Mark 82 bomb and one (1) 155 mm round. Geophysical surveys on the south end of Antelope Lake have led to the discovery of approximately fifteen (15) 40 mm grenades on the ground surface. It is possible other discoveries will be made during further excavation, repositioning or treatment. It is unknown whether or not the ordnance is reactive. It is planned to detonate the ordnance in place.

This permit is effective as of February 12, 2007 and shall remain in effect for 90 days until May 13, 2007. The treatment locations shall be evaluated to insure any residual contamination is below action levels. NNSA/NSO must document the approximate amounts of UXO and donor charge, date and time for each treatment event.

The effect of this permit notwithstanding, it may be terminated at any time without process if it is determined that termination is appropriate to protect human health and the environment. Treatment shall be conducted in a manner protective of human health and the environment and shall adhere to established protocols as determined by the Item Manager.

Any treatment of hazardous waste not authorized by this permit is prohibited. Issuance of this permit does not convey property rights of any sort or any exclusive privilege; nor does it authorize any injury to persons or property, any invasion of other private rights, or any infringement of State or local laws or regulations.

In accordance with 40 CFR 270.61(b)(5), the Permittee shall public notice this action.

1/29/2007
Date

T.H. Murphy
Chief
Bureau of Federal Facilities

Attachment C
Certification Log
(1 Page)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27																																																																																																																							
DOC NO		R FROM		M		QUANTITY		SUPPLY		DIS		PRO		R		P		R		A		D		O		C																																																																																																																							
454647484950515253545556575859606162636465666768697071727374757677787980		2 2		3 4 5 6 7 8 9		10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000		454647484950515253545556575859606162636465666768697071727374757677787980		1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27																																																																																			
 																																																																																																											

Attachment D

NNSA/NSO to NDEP Permit Closeout Letter

(2 Pages)

Department of Energy
National Nuclear Security Administration
Nevada Site Office
P.O. Box 98518
Las Vegas, NV 89193-8518

April 10, 2007

Tim Murphy, Chief
Bureau of Federal Facilities
Division of Environmental Protection
1771 E. Flamingo Road, Suite 121-A
Las Vegas, NV 89119

**TEMPORARY EMERGENCY PERMIT FOR TREATMENT OF UNEXPLODED
ORDNANCE (UXO) FOUND DURING REMEDIATION ACTIVITIES FOR CORRECTIVE
ACTION UNIT (CAU) 484, SURFACE DEBRIS, WASTE SITES AND BURN AREA, ON
THE TONOPAH TEST RANGE (TTR)**

REFERENCE: Letter from Tim Murphy, NDEP, to Ken Small, NNSA, dtd. January 29, 2007

This letter report is being submitted to the Nevada Division of Environmental Protection to serve as documentation of actions carried out in accordance with the subject permit. Public Notices were published on February 6, 2007 and on February 13, 2007 in a local newspaper. A total of three detonations were conducted, all on February 22, 2007. A summary of the NNSA/NSO treatment activities are listed below:

<u>Quantity/Types of UXO</u>	<u>Location</u>	<u>Donor Charge Expended</u>
<u>Detonation 1 – 10 AM</u>		
3 -MK-82 Bombs (Inert)	Pedro Lake	10 Lbs. C-4
2-M117 Bombs (Inert)	Pedro Lake	50 Ea 32 gm. Perforators
1-155MM HE Projectiles	Pedro Lake	10 Ea Electric Blasting Caps
<u>Detonation 2 – 10:30 AM</u>		
2- 40 MM Grenades	Antelope Lake	3 Lbs C-4
2-BLU 63 Submunition	Antelope Lake	6 ea Electric Blasting Caps
<u>Detonation 3 – 10:45 AM</u>		
2- 40 MM Grenades	Antelope Lake	3 Lbs C-4
1-BLU 63 Submunition	Antelope Lake	9 ea Electric Blasting Caps
1-Aircraft Flare	Antelope Lake	

Each detonation site was inspected after treatments occurred, and no residual contamination was found. All treatments were conducted safely, efficiently, and in a manner protective to human health and the environment.

Uncontrolled When Printed

All of these munitions items have been around for many years and it is difficult to determine the exact time frame that they were utilized on the TTR Site. The two locations which were originally thought to be MK-84 bombs, after additional excavation, were determined to be M-117 bombs. The M-117 bombs are of a late 1950's vintage and are still being utilized until the complete stockpile within the U.S. arsenal are depleted. The MK-80 Series bombs have been around from the mid 1960's and are still heavily utilized in any military air dropped bombing campaign. Based on the condition of the Air Dropped bombs excavated at TTR during this operation, they appear to have been in the ground approximately 20 years.

If you have any questions or need any additional information, please contact Peter A. Sanders at (702) 295-1037 or myself at (702) 295-1933.

WMP:2986.KMS

Kenneth M. Small
RCRA Program Manager
Waste Management Project

cc via e-mail:

D. R. Elle, NDEP, Las Vegas
Ted Zaferatos, NDEP, Las Vegas
M. A. DeBurle, NDEP, Carson City, NV
V. G. Gabbard, SNL/TTR, Tonopah, NV
Lt Col B. C. Kieffer, 98RANW/XPD,
 Nellis AFB, Las Vegas, NV
J. Elliston, Westinghouse, Tonopah, NV
T. A. Thiele, NSTec, Mercury, NV
J. L. Smith, NSTec, Mercury, NV
T. D. Taylor, SNJV Las Vegas, NV
R. F. Boehlecke, SNJV Las Vegas, NV
J. M. Fowler, SNJV Las Vegas, NV
K. A. Hoar, AD/AMSP, NNSA/NSO,
 Las Vegas, NV
J. B. Jones, A/ERP, NNSA/NSO,
 Las Vegas, NV
K. J. Cabbie, ERP, NNSA/NSO,
 Las Vegas, NV
P. A. Sanders, ERP, NNSA/NSO,
 Las Vegas, NV
E. F. Di Sanza, WMP, NNSA/NSO,
 Las Vegas, NV

APPENDIX I

MULTISPECTRAL SURVEY REPORT

THIS PAGE INTENTIONALLY LEFT BLANK

**Multispectral Imagery Acquisition, Processing,
and Interpretation for Selected Areas on
the Tonopah Test Range, Nevada**

**Alan Klawitter
Remote Sensing Laboratory
Las Vegas, Nevada**

**Report Produced:
July 2007**

THIS PAGE INTENTIONALLY LEFT BLANK

Introduction

This report briefly documents work accomplished by the U.S. Department of Energy's Remote Sensing Laboratory (RSL) for MultiSpectral Scanner (MSS) imagery acquisitions that occurred at the Tonopah Test Range (TTR), Nevada, in September 2003, April 2006, and July 2006. The purpose of the MSS portion of this project was to acquire, process, and interpret imagery products in order to: 1) help locate surficially disturbed areas potentially caused by projectiles, burial pits, etc., and 2) map suspected surficial fracture zones on portions of the TTR. To this end, RSL acquired high spatial resolution natural color stereo air photos and digital Daedalus 1268 MSS imagery over selected areas of the Tonopah Test Range on September 21, 2003. These areas included: Antelope, NEDS, Brownes, and Pedro dry lake beds, and a location called "Mellan" (Note: Mellan was originally identified as a location of Davis Gun tests. It was later identified as a misnomer for Mt. Helen). In 2006, Daedalus 1268 MSS and digital aerial camera imagery were collected over a larger portion of the TTR that included Main, Antelope, Pedro, NEDS, and Brownes dry lake beds, as well as rangeland areas that included regions north and east of Antelope Lake, Clean Slate, Middle Target, SAC Target (Corrective Action Unit [CAU] 408), Mount (Mt.) Helen, Antelope Tuff #1, Antelope Tuff #2, Sidewinder, Double Tracks, and Myers Ridge.

A Daedalus 1268 MSS is a digital line scanning airborne sensor that records data within 11 discrete wavelength bandwidths. This sensor records data in the visible, short-wave reflected infrared, and the thermal infrared regions of the electromagnetic spectrum. A fundamental physical characteristic of any material is its spectral reflectance curve, which is the amount of energy reflected by the material at a given wavelength. Since a MSS measures the spectral reflectance of materials in multiple wavelength bandwidths, material-specific spectral reflectance curves can be constructed. This allows differentiation of surficial materials. Band designations and bandwidths of the Daedalus 1268 are listed at the back of this report.

Data Acquisition

Imagery was collected in 2003, with a high sun angle, between 11:24 a.m. and 1:08 p.m. local time. Aerial photography was obtained with an RC-30 aerial mapping camera from a flight altitude of 1,000 feet above ground level (agl), resulting in a contact print scale of 1:2,000. MSS data were also obtained from this altitude, resulting in a ground spatial resolution of 0.8 meters. On April 29, 2006, imagery was collected at two flight altitudes between the hours of 9 a.m. and 3 p.m. local time. The southern portion of Antelope Lake, Middle Target, and the SAC Target (CAU 408) areas were acquired from 1,000 feet agl, resulting in a ground spatial resolution of 0.8 meters. Imagery for the remaining areas was collected at 4,000 feet agl, which translates to a ground spatial resolution of

3.5 meters for MSS data. An additional flight on July 15, 2006, was conducted during the late morning hours to obtain data for the Double Tracks area, which had been obscured by cloud shadows on April 29, 2006. Flight altitude on July 15th was 1,000 feet agl. MSS imagery was acquired during this re-flight, but the data have not been processed at the present time since the area surveyed is CAU 408. Flight logs for all MSS imagery acquisitions appear at the end of this report.

Product Generation

Because of aircraft attitude changes and illumination irregularities caused by sun angle variations throughout the collection periods, radiometric and geometric corrections were applied to all data prior to data processing. Flight strips were corrected for cross-track illumination differences. Geodetic corrections were accomplished using aircraft navigation information supplied by an on-board GPS [global positioning system] receiver and an Inertial Measurement Unit (IMU). No ground control points were used for geometric rectification of the data. Data were geometrically rectified to a UTM (Universal Transverse Mercator) Zone 11 projection using a World Geodetic System 1984 (WGS84) ellipsoid. Locational accuracy of geometrically rectified multispectral scanner data is estimated to be within 8 meters of true ground location for imagery acquired at 1,000 feet agl, and within 18 meters for imagery acquired at 4,000 feet agl.

After rectification, 2003 imagery flight strips were mosaicked to form contiguous coverage of three regions: Mellan, NEDS Lake, and the greater Antelope Lake area. The greater Antelope Lake area encompassed Antelope, Pedro, and Brownes dry lakes. Subsequently, Brownes and Pedro Lake areas were subset from the greater Antelope Lake area mosaic. The 2006 imagery flight strips were mosaicked to encompass the following regions: the southern portion of Antelope Lake, Big Boxes, Little Boxes, Clean Slate, Main Lake, Middle Target, SAC Target (CAU 408), and Mt. Helen. The Little Boxes mosaic was subset to create Antelope Tuff #1, Antelope Tuff #2, Sidewinder, and Myers Ridge.

Geometrically and radiometrically rectified hard and softcopy imagery products were created for interpretation, field use, and documentation from data collected in 2003 and April 2006. Hardcopy products in the form of film contact prints were created for aerial photographs, and scaled photographic prints were produced for all processed digital multispectral imagery. Softcopy deliverables were produced as GEO-TIFF format files for raster graphics and DXF format and ESRI shape files for vector-based imagery interpretations. Processed MSS imagery in the form of GEO-TIFF format files were converted to Adobe PDF format files for inclusion as a DVD (see the CAU 484 Closure Report, Appendix N). (Note: The DVD containing all imagery produced from CAU 484 data collection activities is included as Appendix N to the CAU 484 Closure Report.)

For each area of interest defined for the 2003 and 2006 data collections (e.g., Main Lake), five images were created. These were: (1) a false color composite, (2) a false color principal component composite, (3) a directionally-filtered image with a northeast-trending feature bias, (4) a directionally-filtered image with a northwest-trending feature bias, and (5) either a color ratio composite or a color density sliced thermal image. An example of each type of image is briefly discussed in the following paragraphs. All images produced for this project are included on the DVD in PDF format (see the CAU 484 Closure Report, Appendix N).

False color composite images for all areas were produced using bands 9 or 10, band 7, and band 2 in red, green, and blue, respectively. Composites built with these band combinations usually display most of the spectral variability present in the data set. These MSS bands are normally the least correlated; therefore, they minimize the duplication of spectral information. Areas expressing different hues than adjacent regions usually indicate that changes in chemical composition have occurred; whereas, areas displaying similar hues probably mean the chemical compositions are similar. Image hues of specific objects presented on false color composites rarely represent the hues that humans are used to seeing (e.g., red rocks will appear in yellow hues).

Figure 1 is a false color composite mosaic of the greater Antelope Lake area using bands 9, 7, and 2 in red, green, and blue, respectively. Differences in the hues on this composite show that, although the playa surface may seem homogeneous to the human eye, the surface composition of the playa changes both from north to south and from east to west. This false color composite was contrast-stretched to improve interpretability, and only statistics from the playa were used to contrast-stretch the image. This process resulted in saturation of the rangeland regions surrounding the playa so that spectral details on the playa are now more apparent. All examples have been spatially degraded to fit on 8½-by 11-inch pages.

Linear, large-scale, northwest-southeast and northeast-southwest trending expansion cracks are evident. These features are aligned with, and transverse to, the axis of the playa and indicate the orientations of the local stress fields. Culturally-disturbed areas can be observed throughout the image (e.g., the road paralleling the western shoreline of the playa, the retention dam in the north portion of the lake, and the circular targets in the central portion of the playa). Detailed inspection of the full-scale image shows areas on the playa that have characteristics of surficial disturbance.

Figure 2 is a false-color, principal-component, composite mosaic of the same area presented on Figure 1. Principal components are linear combinations of the original MSS input bands in which the spectral information has been re-arranged to minimize correlation between the output bands. Interpretation of principle

Figure 1: False Color Composite Mosaic of Antelope Lake

Figure 2: Principal Component Composite Mosaic of Antelope Lake

component composites can be more difficult than interpreting band composites; however, imagery spectral features that are statistically anomalous are quickly identified. This is due to the manner in which principle component images are created. Input bands are mathematically transformed into output bands according to the statistical variability within all input bands. The first principle component image describes most of the spectral variation; the second component image describes the most of the remaining variation, and so on. Statistical anomalies, such as disturbed soil in relatively undisturbed areas, will be prominent in the higher component images.

Principal components 1, 2, and 5 are presented in red, green, and blue, respectively, in Figure 2. Statistics used for the mathematical transform were derived only from playa regions. Figure 2 again demonstrates that the composition of the playa surface is heterogeneous. Surficial compositional changes around the circular targets on the playa are evident. Effects of the expansion fractures on the composition of the adjacent areas are also apparent.

Black and white, directionally-filtered images were created to assist in interpreting linear features that might be surficial indications of fracturing, or sharp spectral boundaries that might indicate disturbance. Directionally-filtered images were produced to enhance features trending along either northwest-southeast or northeast-southwest geographic orientations. These orientations correspond to the orientations of the regional stress fields in the western United States. The majority of faulting in this region of Nevada is oriented north-south, northwest-southeast, or northeast-southwest. Orientation of playas is usually related to the direction of local faulting. Because the orientation of the playas in this project was northwest-southeast and northeast-southwest (conjugate fault orientation), filtered images were created for these directions.

Spatial convolution filtering is a local mathematical operation that alters the pixel value of an image by comparing it to the values of its surrounding pixels. Directional filters only compare a pixel value to its neighbors that are oriented in a particular direction. Filtered image maps were created in the following manner. After the imagery was geodetically rectified, the first principle component of all visible and reflected infrared bands was created for use as the base image. This image was then subjected to harsh spatial convolution filtering. To accentuate linear features trending in a northwest-southeast orientation, a 2 X 2 convolution filter with the following weightings was used:

$$\begin{array}{cc} 0 & -1 \\ 1 & 0 \end{array}$$

Linear features which are orthogonal to the weighting of the filter are enhanced.

Figure 3 is an example of a directionally-filtered image of the Antelope Lake area. The insert in the upper right portion of the image shows detail within a portion of

Figure 3: NW Directionally Filtered Mosaic Image of Antelope Lake

the larger image around some circular targets. Small-scale cultural disturbances such as vehicle tire tracks are enhanced. Features that trend northwest-southeast are preferentially enhanced compared to features that trend northeast-southwest.

Linear features trending in a northeast-southwest orientation were accentuated by the application of a 2 X 2 convolution filter with the following weightings:

$$\begin{matrix} -1 & 0 \\ 0 & 1 \end{matrix}$$

The resulting grey scale images are stripped of spectral content but show linear trends in the data that are not always apparent when viewing individual bands or color composites. Figure 4 has been directionally filtered to accentuate features trending northeast-southwest. Comparison of the inserts in Figures 3 and 4 show the effects of using differently-oriented differential spatial filters.

Ratio composite images are simply false color composites that include one or more ratio images. Ratio images are constructed by dividing one band by another. Materials of interest can be enhanced by ratioing. For example, rocks rich in iron can oxidize to a red color. By ratioing an image acquired in visible red wavelengths by an image acquired in visible green wavelengths, red objects will be enhanced. In ratio composites created for this project, the ratios used were 5/2 and 9/10. The 5/2 ratio will enhance objects containing the ferric ion and red iron oxides. The 9/10 ratio will enhance clay rich surfaces. A 9/10 ratio will also enhance vegetated areas. Again, care must be exercised when drawing inferences from ratio images because, in addition to enhancing materials that were chosen to be enhanced, other materials will also be enhanced (e.g., the 5/2 ratio will enhance red rocks, red vegetation, and any material that absorbs more green light than red light).

Figure 5 presents a color ratio composite image of the Antelope Lake area. Again, gross compositional differences between the north and south, as well as east and west, sides of the lake are apparent. Disturbed areas on the north and west sides of the playa appear in brown and purple hues, and dark gravel dune-like deposits on the southern and southeastern sections of the playa are bright red.

Color density sliced thermal images were generated for Main Lake, Myers Ridge, Southern Antelope Lake, and Sidewinder areas. Within these areas, band 11 possessed some unique features that were best expressed in thermal wavelengths. Color density sliced images were created by increasing the contrast of the thermal channel and assigning colors to discreet portions of the radiometric range of the data. The radiometric range of the thermal channel represents the range of apparent surficial object temperatures. To convert apparent temperatures to kinetic temperatures, the emissivity of the surficial objects must be known. Reflective objects, such as polished metals, have low

Figure 4: NE Directionally Filtered Mosaic Image of Antelope Lake

Figure 5: False Color Ratio Composite Mosaic Image of Antelope Lake

apparent temperatures even though they may be hot to the touch. Dark colors were assigned to low apparent temperatures and warm colors were assigned to relatively hot apparent temperatures.

A color density sliced thermal image of Main Lake is provided as Figure 6. A northwest-southeast striking thermal discontinuity separates the northeast quadrant of the playa from the remaining portions. A similar, but smaller, discontinuity separates the southwestern portion of the playa from the main body of the playa. These trends may indicate a change in the composition of the surface materials, or they could be due to structural changes beneath the playa. Very often, thermal signatures are produced by faulting caused by percolation of fluids along a fault zone.

A suite of five enhanced MSS images were generated for each of the areas of interest that were determined by NSTec Environmental Restoration. These images were selected to provide a broad picture of the spectral diversity and possible structural components of the area of interest, specifically to assist with interpreting disturbed soils and locating fracture zones.

Figure 6: Color Density Sliced Thermal Image of Main Lake

Image Interpretation

Areas on the TTR were interpreted by image analysts at RSL. Interpreted areas are denoted by the presence of DXF or ESRI shape format files accompanying the imagery on the DVD (see the CAU 484 Closure Report, Appendix N). These vector format files can be digitally overlaid onto the imagery using GIS or imagery processing software such as ARCGIS, ENVI, ERDAS, or PCI. Areas that were interpreted for spectral or structural anomalies were NEDS Lake, Antelope Lake, and Mellan. Computer-assisted spectral anomaly detection algorithms, Los Alamos National Laboratories (LANL) GENIE, and ENVI RXD algorithms were used to interpret Brownes Lake. The results reside in the Brownes directory on the DVD (see the CAU 484 Closure Report, Appendix N). Interpretations, either manual or computer generated, were provided in graphic and electronic format for field verification.

Manual interpretation of NEDS Lake, Antelope Lake, and Mellan used standard photogrammetric methods based upon differences in color, tone, and texture. Hardcopy multispectral false color, principle component, and ratio composites, as well as the black and white filtered images, were inspected for anomalous regions that could possibly be associated with disturbed soils. Suspected areas were marked on a mylar overlay. A separate overlay was then prepared for interpreted fractures, and the process was repeated for all three regions of interest.

Interpretations were converted into digital vector files in the following manner. Geodetic registration marks were recorded on the mylar overlays. The overlays were converted into raster graphics files by digital scanning of the overlays. This digital raster graphics file was imported into image processing software and geometrically rectified using the geodetic registration marks. Digital locations of suspected disturbed soil were obtained by placing a cursor on top of the interpreted feature and electronically recording the location in UTM Zone 11 coordinates. Locations of interpreted disturbed soils were recorded as points.

Interpretation of suspected fractures was converted into digital vector files using the above procedure except that instead of point locations, line segments were recorded electronically. Points and line segments were then converted to vector DXF file formats.

September 2003 MSS data was used for computer-assisted spectral anomaly analysis of Brownes Lake. The two algorithms used were the ENVI RXD anomaly detection and the LANL GENIE genetic software.

Figure 7, RXD_BROWNES.JPG on the DVD (see the CAU 484 Closure Report, Appendix N), is the result of the ENVI RXD classification. RXD is an unsupervised anomaly detection algorithm that detects the spectral differences

between a region to be tested and its neighboring pixels. This algorithm extracts unknown targets that are spectrally distinct from the image background. Spectral anomalies should occur where an object penetrates the playa surface, exposing materials that have not been in direct contact with the atmosphere and therefore having a slightly different chemical composition than other surficial materials. In this image, bright pixels are spectrally different than their surroundings. The brighter the pixel, the more spectrally dissimilar it is to its neighbors.

Figure 7: RXD Spectral Anomaly Interpretation, Brownes Lake

Figures 8 and 9 resulted from the GENIE processing. GENIE is a software program for rapidly evolving feature extraction algorithms for image analysis. GENIE uses a genetic programming approach to produce automatic feature extraction tools for broad-area features in multispectral, hyperspectral, panchromatic, and multi-instrument imagery. Both spectral and spatial signatures of features are identified and exploited. It is an evolutionary computation software system, which uses a genetic algorithm to assemble image-processing tools from a collection of low-level image operators (e.g., edge detectors, texture measures, spectral operations, or various morphological filters).

Areas within the red polygons on Figure 8, BROWNES_GENIE1.JPG on the DVD, have been identified by GENIE as being spatially and spectrally anomalous, according to training sets derived from a disturbed area north of the large circular feature centered near UTM coordinates 527500 E – 4174400 N. Some of the areas within the red polygons are known to contain disturbed soils. Figure 9, BROWNES_GENIE2.JPG on the DVD, is a separate classification based on training sets obtained from areas south of the large circular feature centered near UTM coordinates 527500 E – 4174400 N. Areas considered anomalous are contained within blue polygons.

Results of computer-derived spectral anomaly classifications were compared to each other and then to the false color composite, principal component composite, and composite ratio images that were originally generated to enhance disturbed soil. The RXD spectral anomaly classification (Figure 7) behaved predictably. Whenever the spectral properties of a pixel differed significantly from its neighbors, the pixel was flagged as anomalous. Obvious spectral differences (e.g., the circular feature on the playa) were assigned the brightest pixel values. An image interpreter would have identified items without the help of the algorithm. Areas with known surficial disturbances, such as the region 250 meters north of the circle, appear in relatively bright and mid-grey tones, indicating that surficial disturbances on the playa are spectrally subtle. This suggests that preferentially contrast stretching the mid-grey tones on this image prior to classification should enhance areas of possible disturbance.

The two graphics created with the GENIE algorithm, Figures 8 and 9, produced similar results in key regions such as the area 250 meters north of the circle; however, there are some significant differences. Red polygons (in Figure 8) cover less area than the blue polygons (in Figure 9); therefore, use of the red polygons was more discriminating. Approximately 25 percent of the playa is contained within the red polygons. Visually, it appears that more than 80 percent of the area encompassed by the red polygons is contained within the blue polygons. This suggests that both applications of GENIE were mapping similar spectral/spatial features. Fair to good correlations exist between areas flagged as anomalous by the RXD classification and the areas identified by GENIE as anomalous.

Figure 8: GENIE Spectral Anomaly Classification of Brownes and Pedro Lakes

Figure 9: GENIE Spectral Anomaly Classification of Brownes and Pedro Lakes

Red polygons on Figure 8 correlated well with distinct hues present on the false color ratio composite and the false color principal component composite. Because strong correlations exist between polygon locations and areas with known surficial disturbances, this image should be used as a predictive tool to locate additional surficially disturbed areas. Results presented on both Figures 7 and 8 should be field-checked to determine the accuracy of the computer-assisted spectral anomaly classifications.

Conclusions and Recommendations

MSS imagery was acquired for various areas of interest on the TTR in September 2003, April 2006, and July 2006. Imagery was geometrically rectified to a UTM Zone 11 projection using a WGS84 spheroid. Radiometric rectifications that were applied to imagery included cross-track illumination corrections and conversion of thermal data to apparent temperatures. Where necessary, flight strips of MSS imagery were radiometrically balanced and mosaicked to form contiguous imagery coverage encompassing large areas of interest, such as Antelope Lake. Imagery was then digitally processed to enhance areas that exhibited spectral characteristics of surficial disturbance, and spatially filtered to enhance subtle geologic structures. A collection of five hard and softcopy images were generated for each area of interest.

Structural and spectral MSS image interpretations were conducted for Antelope, NEDS, Brownes, and Pedro Lakes, and for the Mellan area. Interpretation image overlays in the form of vector-based DXF format files were created. Additional computer-assisted anomaly interpretations were accomplished for Brownes Lake using ENVI RXD and LANL GENIE classification algorithms. Results from these image interpretations have not been, and should be, field-checked to assess the accuracy of the interpretations. Initial comparison of the interpretations to known areas of disturbed soil and locations of structures with surficial expressions have shown that the results of the interpretations are plausible.

Hardcopy MSS images for presentation and field use were generated for the majority of the data and are located on the accompanying DVD (see the CAU 484 Closure Report, Appendix N). Because the personnel that created the MSS enhanced imagery were not intimately familiar with the TTR, processed images were designed, in part, for use by TTR field scientists who are not especially familiar with imagery, but who could use the imagery as a resource to assist in locating disturbed areas and unmapped structures. When disturbed areas or structures were located on the ground by TTR field personnel, they could then use analogous signatures on the imagery to locate additional areas for field inspection.

MSS MISSION FLIGHT LOGS

11:15

MULTISPECTRAL SCANNER FLIGHT LOG *Bechtel Nevada*

Spectral Image Acquisition

PROJECT: <i>TTB</i>		AIRCRAFT: <i>135XP</i>		FILE CHANNELS VS SPECTRAL CHANNELS									
DATE: <i>9/21/03</i>	FLIGHT#: <i>1</i>	GROUND ELEVATION:		SPEC1	<i>1</i>	SPEC6	<i>6</i>	ATM	☒				
OPS BASE: <i>Tobago</i>		SCANNER SYSTEM: <i>1268</i>		SPEC2	<i>2</i>	SPEC7	<i>7</i>	CZCS	☐				
FLIGHT CREW: <i>Sue / Don / Marc / Steve</i>		DETECTOR: Spectrometer ☐ 1.6 ☐ 2.2 ☐ 3-5 ☐ 8-12 ☐		SPEC3	<i>3</i>	SPEC8	<i>8</i>						
RC30: ☐	Hasselblad: ☐	Linhoff: ☐	IR: ☐	FILTER INSB:		FILTER MCT:		SPEC4	<i>4</i>	SPEC9	<i>9</i>	MCT	☐
Video: ☐	WEATHER:		GYRO#:	IMU:	NAV: <i>ASCOT</i> ☐	SPEC5	<i>5</i>	SPC10	<i>10</i>	INSB	☐		

TIME	DISK#	FILE#	TARGET	HEAD	GND SPD	ALT AGL	BB-1	BB-2	SCAN SPD	FIX GAIN	CH #11 GN/OFF	FIX GAIN	CH #12 GN/OFF	COMMENTS
1133	6	1	Line 10 Panel Run	180	135	1000	19.8	45.3	100	.5		1		
1137		2	Panel Run	360	130									
1143		3	Line 10	180	135									
1148		4	Line 12	360	127									
1151		5	Line 7	180	135									
1156		6	Line 11	360	129									
1200		7	Line 6	180	140									
1203		8	Line 9	360	127									
1208		9	Line 5	180	135									
1212		10	Line 8	360	129									
1217		11	Line 4	180	135									
1221		12	Line 2	360	133									
1225		13	Line 3	180	135									

Signature: _____

Page 2

MULTISPECTRAL SCANNER FLIGHT LOG

Bechtel Nevada

Spectral Image Acquisition

PROJECT: <u>TTA</u>		AIRCRAFT:		FILE CHANNELS VS SPECTRAL CHANNELS									
DATE: <u>9/21/03</u>	FLIGHT#: <u>1</u>	GROUND ELEVATION:		SPEC1	1	SPEC6	6	ATM	☒				
OPS BASE: <u>Tonopah</u>		SCANNER SYSTEM: <u>1288</u>		SPEC2	2	SPEC7	7	CZCS	☐				
FLIGHT CREW:		DETECTOR: <u>Spectrometer</u> ☐ 1.6 ☐ 2.2 ☐ 3-5 ☐ 8-12 ☐		SPEC3	3	SPEC8	8						
RC30: ☐	Hasselblad: ☐	Linhoff: ☐	IR: ☐	FILTER INSB:		FILTER MCT:		SPEC4	4	SPEC9	9	MCT	☐
Video: ☐	WEATHER:		GYRO#:	IMU:	NAV: <u>ASCOT</u> ☐	SPEC5	5	SPC10	10	INSB	☐		

TIME	DISK#	FILE#	TARGET	HEAD	GND SPD	ALT AGL	BB-1	BB-2	SCAN SPD	FIX GAIN	CH #11 GN/OFF	FIX GAIN	CH #12 GN/OFF	COMMENTS
1230	6	14	Line 1	360	129	1000	19.8	45.3	100	.5		1		
1235		15	ned Line 2	360	127									
1239		16	ned Line 4	180	135									
1243		17	melon Line 4	360	131									
1248		18	Line 7	180	133									
1252		19	Line 3	360	127									
1256		20	Line 6	180	138									
1300		21	Line 2	360	133									
1303		22	Line 5	180	137									
1307		23	Line 1	360	133									
1312		24	Panel Run	180	131									
		25												
		26												

Signature: _____

MULTISPECTRAL SCANNER FLIGHT LOG

Bechtel Nevada

Spectral Image Acquisition

PROJECT: Tonopah Test Range - Environmental Restoration				AIRCRAFT: N7232R				FILE CHANNELS VS SPECTRAL CHANNELS					
DATE: 29-Apr-2006		FLIGHT#: 1		GROUND ELEVATION:				SPEC1	1	SPEC6	6	ATM	☒
OPS BASE: TPH - Tonopah Municipal Airport				SCANNER SYSTEM: Daedalus 1268				SPEC2	2	SPEC7	7	CZCS	☐
FLIGHT CREW: D. Wrigley, G. Butler, M. Rivera, H. Gledhill				DETECTOR: Spectrometer ☐ 1.6 ☒ 2.2 ☒ 3-5 ☐ 8-12 ☒				SPEC3	3	SPEC8	8		
RC30: ☒	Hasselblad: ☐	Linhoff: ☐	IR: ☐	FILTER INSB:		FILTER MCT:		SPEC4	4	SPEC9	9	MCT	☒
Video: ☐	WEATHER:			GYRO#:	IMU: LN200	NAV: ASCOT ☒		SPEC5	5	SPC10	10	INSB	☐

TIME	DISK#	FILE#	TARGET	HEAD	GND SPD	ALT AGL	BB-1	BB-2	SCAN SPD	FIX GAIN	CH #11 GN/OFF	FIX GAIN	CH #12 GN/OFF	COMMENTS
0834	4	00 ☒	Ground check	--	00	0	20.4	20.4	100	0.5	--	1	--	Got events
0856	4	01	Panels	180	138	1000	9.9	34.2	100	0.5	228/654	1	222/556	Panels off center
0906	4	02	Panels	180	--	1000	--	--	100	0.5	228/654	1	222/556	Good
0910	4	03	Antelope Line 1	360	129	1000	9.9	34.2	100	0.5	228/654	1	222/556	Westernmost line
0915	4	04	Antelope Line 2	180	--	1000	9.9	34.2	100	0.5	228/654	1	222/556	Saturated in visible on lake bed
0919	4	05	Antelope Line 3	360	129	1000	9.9	34.2	100	0.5	228/654	1	222/556	Lowered gains in visible
0923	4	06	Antelope Line 2	180	--	1000	9.9	34.2	100	0.5	228/654	1	222/556	Repeat for gain change
0927	4	07	Antelope Line 4	360	133	1000	9.9	34.2	100	0.5	228/654	1	222/556	
0931	4	08	Antelope Line 5	180	129	1000	9.9	34.2	100	0.5	228/654	1	222/556	
0935	4	09	Antelope Line 6	360	129	1000	9.9	34.2	100	0.5	228/654	1	222/556	
0939	4	10	Antelope Line 7	180	127	1000	9.9	34.2	100	0.5	228/654	1	222/556	Saturated in Ch. 12
0943	4	11	Antelope Line 8	360	130	1000	9.9	34.2	100	0.5	228/654	1	184/550	Lowered gain/offset for Ch. 12
0948	4	12	Antelope Line 9	180	130	1000	9.8	34.2	100	0.5	228/654	1	184/550	
0952	4	13	Antelope Line 10	360	129	1000	9.8	34.2	100	0.5	228/654	1	184/550	Saturated in Ch. 12 - OK in Ch. 11
0956	4	14	Antelope Line 11	180	137	1000	9.8	34.2	100	0.5	228/654	1	184/550	
1000	4	15	Panels	360	--	1000	--	--	100	0.5	228/654	1	092/518	Gains set for lake bed
1005	4	16 ☒	Main Lake Line 1	360	160	4000	10.0	35.6	50	0.5	216/654	1	092/518	
1008	4	17 ☒	Main Lake Line 2	180	170	4000	10.0	35.6	50	0.5	216/654	1	092/518	
1012	4	18 ☒	Main Lake Line 3	360	169	4000	10.0	35.6	50	0.5	216/654	1	092/518	
1018	4	19	Panels	180	129	1000	10.0	35.4	100	0.5	216/654	1	092/518	Used lake bed gains
1027	4	20	Mid Targ. Line 1	180	137	1000	10.0	35.4	100	0.5	216/654	1	198/518	Used lake bed gains
----	4	21	N/A	--	--	--	--	--	--	--	--	--	--	No imagery data recorded
1031	4	22	Mid Targ. Line 2	360	129	1000	10.1	35.4	100	0.5	165/655	1	088/522	
1035	4	23	Mid Targ. Line 3	180	134	1000	10.1	35.5	100	0.5	165/655	1	088/522	

Signature: _____

MULTISPECTRAL SCANNER FLIGHT LOG

Bechtel Nevada

Spectral Image Acquisition

PROJECT: Tonopah Test Range - Environmental Restoration				AIRCRAFT: N7232R				FILE CHANNELS VS SPECTRAL CHANNELS					
DATE: 29-Apr-2006		FLIGHT#: 1		GROUND ELEVATION:				SPEC1	1	SPEC6	6	ATM	☒
OPS BASE: TPH - Tonopah Municipal Airport				SCANNER SYSTEM: Daedalus 1268				SPEC2	2	SPEC7	7	CZCS	☐
FLIGHT CREW: D. Wrigley, G. Butler, M. Rivera, H. Gledhill				DETECTOR: Spectrometer ☐ 1.6 ☒ 2.2 ☒ 3-5 ☐ 8-12 ☒				SPEC3	3	SPEC8	8		
RC30: ☒	Hasselblad: ☐	Linhoff: ☐	IR: ☐	FILTER INSB:				SPEC4	4	SPEC9	9	MCT	☒
Video: ☐	WEATHER: ☐			GYRO#:	IMU: LN200	NAV: ASCOT ☒		SPEC5	5	SPEC10	10	INSB	

[illegible]

Signature: _____

PROJECT: Tonopah Test Range - Environmental Restoration				AIRCRAFT: N7232R				FILE CHANNELS VS SPECTRAL CHANNELS					
DATE: 29-Apr-2006		FLIGHT#: 2		GROUND ELEVATION:				SPEC1	1	SPEC6	6	ATM	☒
OPS BASE: TPH - Tonopah Municipal Airport				SCANNER SYSTEM: Daedalus 1268				SPEC2	2	SPEC7	7	CZCS	☐
FLIGHT CREW: G. Butler, D. Wrigley, M. Rivera, H. Gledhill				DETECTOR: Spectrometer ☐ 1.6 ☒ 2.2 ☒ 3-5 ☐ 8-12 ☒				SPEC3	3	SPEC8	8		☐
RC30: ☒	Hasselblad: ☐	Linhoff: ☐	IR: ☐	FILTER INSB:		FILTER MCT:		SPEC4	4	SPEC9	9	MCT	☒
Video: ☐	WEATHER: High cirrus to patchy cumulus			GYRO#:		NAV: ASCOT ☐		SPEC5	5	SPEC10	10	INSB	☐
				IMU: LN200									

Signature: _____

MULTISPECTRAL SCANNER FLIGHT LOG

Bechtel Nevada

Spectral Image Acquisition

Init Start 0847-0855
 Deinit Start 1206

PROJECT: TTR	FLIGHT#: 1	AIRCRAFT: N185XP	FILE CHANNELS VS SPECTRAL CHANNELS			
DATE: 7-15-2006		GROUND ELEVATION:	SPEC1	1	SPEC6	6
OPS BASE: Tonopah Municipal Airport		SCANNER SYSTEM: 1268	SPEC2	2	SPEC7	7
FLIGHT CREW: Smith, Roberts, Rivera, Gledhill		DETECTOR: Spectrometer	SPEC3	3	SPEC8	8
RC30: ☒ Hasselblad: ☐ Linhoff: ☐ IR: ☐		FILTER INSB:	SPEC4	4	SPEC9	9
Video: ☐ WEATHER: High cirrus forming		GYRO#: IMU: NAV: ASCOT	SPEC5	5	SPC10	10
					INSB	☐

TIME	DISK#	FILE#	TARGET	HEAD	GND SPD	ALT AGL	BB-1	BB-2	SCAN SPD	FIX GAIN	CH #11 GN/OFF	FIX GAIN	CH #12 GN/OFF	COMMENTS
0852	14	00	Ground check	-	0	0	24.6	24.6	100	0.5		1		OK
0913	14	01	Panels				13.2	55.6	100	.5		1		Panels off center
0918	14	02	Panels											Changed gains on-line
0923	14	03	Panels	180	130	1K	25.4	44.5	100	.5		1		Good
0928	14	04	Blue Box	360	140	1K	25.4	44.5	100	.5	175/632	1	192/538	
0933	14	05	Green Box	180	-	1K	25.3	53.9	100	.5	140/672	1	148/562	Cropped BB1-ch.?
0938	14	06	Red Box	-	-	1K	25.3	53.8	100	.5	140/672	1	148/562	
0943	14	07	Green Box	180	129	1K	25.3	53.9	100	.5	140/672	1	148/562	Repeat for 1268-gain
0947	14	08	Panels	360	-	1K	25.5	53.9	100	.5	"	1	"	Good
0954	14	09	Mid-Line 1	180	127	1K	25.3	53.9	100	.5	"	1	"	Used Lake Bed gains
0959	14	10	Mid-Line 2	360	142	1K	"	"	100	.5	"	1	"	Little fast
1004	14	11	Mid-Line 3	180	133	1K	"	"	100	.5	"	1	"	
1009	14	12	Mid-Line 4	360	137	1K	"	"	100	.5	"	1	"	Little fast
1014	14	13	Mid-Line 5	180	125	1K	"	"	100	.5	"	1	"	
1023	14	14	Dbl-Line 1	180	172	4K	25.4	54.4	50	.5	"	1	"	
1030	14	15	Dbl-Line 2	360	200	4K	25.0	54.5	50	.5	"	1	"	
1039	14	16	Panels	180	126	1K	25.5	53.9	100	.5	"	1	"	
1046	14	17	ASL Ph-Line 10	345	195	2K	"	54.1	100	.5	"	1	"	Fast line - used Lake Bed gains

Signature: _____

Lake Bed Panels
 1-1 7-1
 2-1 8-2
 3-5 9-1
 4-5 10-1
 5-5 11-5
 6-5 12-5

Other
 1-2 7-1
 2-2 8-2
 3-1 9-1
 4-1 10-2
 5-1 11-5
 6-1 12-1

Spectral Image Acquisition

[illegible]

I-27

Bechtel Nevada

Init. Start 1319-1324

[illegible]

Variable gain or level adjustments seem backwards again.

DAEDALUS 1268 SPECTRAL BANDS

Number	Wavelength Range (microns)	Centroid (wavelength)
1	0.420-0.450	0.435
2	0.450-0.520	0.485
3	0.520-0.600	0.560
4	0.605-0.625	0.615
5	0.630-0.690	0.660
6	0.695-0.750	0.723
7	0.760-0.900	0.830
8	0.910-1.050	0.980
9	1.550-1.750	1.650
10	2.080-2.350	2.215
11	8.5-13.0	10.75

THIS PAGE INTENTIONALLY LEFT BLANK

APPENDIX J

STATISTICS REPORTS

APPENDIX J-1

Statistical Modeling & Analysis of Site Verification and Background Data

APPENDIX J-2

Davis Gun Penetrator Geophysical Target Statistical Analysis

APPENDIX J-1

STATISTICS REPORT

Statistical Modeling & Analysis of Site Verification and Background Data

*Alpine Analytics*TM

PO Box 830
Durango, CO 81302
Tel: 970-884-9490
AlpineAnalytics.com

*Sound ethical decisions based on data!*SM

E-mail: Root@AlpineAnalytics.com

Fax: 970-884-9141

July 27, 2007

**Tonopah Test Range
NSTec Environmental Restoration
*Corrective Action Unit 484***

**Task 1: Statistical Modeling & Analysis of
Site Verification and Background Data**

Root Routledge, PhD
Alpine Analytics

Project Subcontract No. 4140-02
Release Order No. 007
Peer Consultants, Inc.
Peer Client: Teledyne Brown Engineering

Alpine Analytics™

PO Box 830
Durango, CO 81302
Tel: 970-884-9490
AlpineAnalytics.com

Sound ethical decisions based on data! SM

E-mail: Root@AlpineAnalytics.com
Fax: 970-884-9141

Project Scope of Work for Statistical Modeling & Analysis

Objective & Background

Complete a statistical evaluation of quantitative and qualitative data collected during the closure of CAU 484 located at the Tonopah Test Range. Data consists of surface and subsurface samples collected from three detonation sites.

Analytical methods used shall be technically defensible, and data output and analysis shall be presented in both numerical and graphical formats.

Task 1 (this report)

Analytical data from Geoprobe® sampling shall be evaluated using an accepted statistical methodology to determine if there is a significant difference or trend within each of the following three data sets (data to be provided by NSTec):

- A. Surface and subsurface concentrations for each site
- B. Site-specific concentrations and background conditions
- C. Site-specific concentrations and action levels

In addition, the probability/confidence that any locations within the study area will exceed action levels or background conditions based on site-specific concentrations is also to be determined as part of this task.

Data Provided

Laboratory analytical data from the field samples was provided in Excel format. Local geometric X-Y “geo-coordinates” were provided for each site and sample location, which facilitates cleaner analysis and allows translation back and forth to UTM (Universal Transverse Mercator) or other coordinate systems.

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Executive Summary

There are four Sites under study for CAU 484: PDRO (Pedro Lake); DUS (Depleted Uranium Site); MPDT (Metal Particle Dispersion Test); and NEDS (Nonviolent Explosive Destruct System). The three types of comparisons specified in the Task 1 Scope for the four CAS sites (PDRO, DUS, MPDT, and NEDS) and the nine analytes of concern are summarized in the following two tables which are also in the report body as *Table 4: Summary of Depth Differences* and *Table 6: Summary of Verification v Background Conclusions* in the main report. They identify the statistically based scientific conclusions described in detail in the technical report. Note: The Depth-Factor levels are as follows, using the NSTec identifier letters: **A** = Surface (0-6" below ground surface, or "bgs"); and, **B** = Subsurface (1.5-2 feet bgs).¹

The tables below show the results of the statistical comparisons of interest: Depth Level **A** vs Depth Level **B** for each analyte at each site; and, Verification Site **V** (DUS, MPDT, and NEDS) vs the Background Site **B** (PDRO). Equating the factor symbols (e.g. **A = B** and **V = B**) in the two tables *means* there *is no statistically significant difference* in the response variable that identifies the row (e.g. analyte concentration) *due to* differences in the factor level (Depth class or Site) as performed by the proper statistical analysis, which varies depending on specific conditions. An inequality symbol, ">" or "<", *means* there *is a statistically significant difference* in the concentrations of the analyte and identifies which factor level had the higher value.

Summary of Depth Differences (Table 4)

Analyte	CAS			
	PDRO	DUS	MPDT	NEDS
U	A = B	A = B	A = B	A = B
U234	A > B	A = B	A = B	A = B
U235	A = B	A = B	A = B	A = B
U238	A = B	A = B	A = B	A = B
Be	A = B	A > B	A > B	A < B
Li	A > B	A = B	None	
Hg	A = B	A = B		
Nb	A = B	A = B		
Tl	A = B	A = B		

Summary of Comparisons (Table 6)

Analyte	Verification CAS (V) (B = PDRO)		
	DUS	MPDT	NEDS
U	V = B	V = B	V > B
U234	V > B	V > B	V > B
U235	V > B	V > B	V > B
U238	V = B	V > B	V > B
Be	V < B	V > B	V = B
Li	V < B	None	
Hg	V = B		
Nb	V = B		
Tl	V = B		

¹ Per CAU 484 Surface Debris, Waste Sites Sampling Plan, NSTec, pg 1. Note: It is common statistical language to refer to "factor differences" in any given measured response variable, Y (say), by simply referring to "Machine differences" or "Catalyst differences" (say, if different machines or catalysts were under study), which means the difference in Y *due to* a difference in the Machine or Catalyst factor. Hence the use of the phrase "*Depth Differences*" in discussion and table and graphical summaries throughout this report refers to the difference in any of the multiple response variables ("analytes") *due to* the difference in Depth levels (**A** and **B**) of the samples. It is quite clear from the context of the study that "Depth Differences" should not be interpreted as the simple difference between the actual and consistent depth level classes of the Depth-Factor (0-6") and (1.5-2 feet) from which the samples were drawn.

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Statistically significant differences are either defined by the “p-value” or “confidence interval” associated with the specific test; and these are identified in the detailed tables of the report. Industry standard values of 0.05 (5%) and 0.95 (95%) are used to determine statistical significance and as the specified confidence level. A difference is statistically significant if $p < 0.05$, which means that the probability of finding the computed difference in response (analyte concentrations) *due to pure random chance* is less than 5%.

Finally, all analytes for each site were compared to their specific Action Levels (AL) using proper statistical methodology for the conditions of the data. Significant results as compared to AL are identified in **red shading** of the table cell.

Only one site exceeded an Action Level, which was a hotspot in the center of the NEDS site for Uranium at 325 mg/kg versus an AL = 200 mg/kg. All other site locations for all contaminants were well below the AL. The red-shaded cell in the Depth comparison table indicates that, although there was no statistically significant difference overall between the two Depths ($A = B$), there was a hot spot at Depth B (325 mg/kg) that was much higher than the concentration at that same location in Depth A (27.1 mg/kg) as well as the site maximum at Depth A, occurring at the adjacent point (48.7 mg/kg). To highlight that a difference in extremes exists the cell is shaded red.

Depth differences were minimal for most analytes and sites, with Beryllium showing the most differences (see CAS sites DUS, MPDT and NEDS). PDRO had two significant depth differences, one each for U234 and Lithium. *Table 3: Statistical Comparisons of Surface (Depth A) and Subsurface (Depth B) Concentrations* identifies the magnitude for these differences, which although statistically significant ($p < .05$) were not very large relative to overall concentrations.

Comparisons of Verification (V) sites DUS, MPDT and NEDS to the Background (B) site PDRO identified most differences in the Isotopic Uranium analytes, U234, U235 and U238, along with Beryllium for one site, MPDT. These differences, where estimable due to the percent of Nondetects (%ND) were statistically significant, although not very large. The appropriate statistical comparison of the NEDS site for Uranium overall had a p-value of 0.127 (>0.05), however due to its hotspot the difference is noted as significantly higher than the background site. These comparisons are summarized and described in detail in *Table 5: Statistical Comparisons of Verification Sites and Background Site*.

Variance component analysis of the QA data did not identify any levels of measurement variation that would have affected the conclusions in any of the statistical comparisons. *Table 7: Variance Component Analysis* summarizes these results for those analytes that could be analyzed due to their ND censoring levels.

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Characterization of the Sites

Sites, Sample Sizes and Analytes Measured:

There are four sites, identified as: PDRO (Pedro Lake); DUS (Depleted Uranium Site); MPDT (Metal Particle Dispersion Test); and NEDS (Nonviolent Explosive Destruct System); with PDRO being the background site, denoted **B** in the analysis, and the remaining three being verification sites, denoted **V** in the analysis. There are nine analytes of interest, but they are not measured for all samples from all four sites. Table 1 summarizes the basic structure of the data, showing the sample size (**n**) for each combination of site and analyte.

Table 1: CAU 484 Analytical Data Structure

Analyte	Symbol	Units	Action Level	Measurement Sample Locations (n)			
				PDRO	DUS	MPDT	NEDS
Uranium	U	mg/kg	200	20	36	36	36
Isotopic Uranium-234	U234	pCi/g	85.8				
Isotopic Uranium-235	U235	pCi/g	10.56				
Isotopic Uranium-238	U238	pCi/g	63				
Beryllium	Be	mg/kg	2000			None	None
Lithium	Li	mg/kg	20000				
Mercury	Hg	mg/kg	310				
Niobium	Nb	mg/kg	NA				
Thallium	Tl	mg/kg	67				

Note: Each sampling location contains two samples from each of two depths (A & B depths)

Background CAS: PDRO

Verification CAS: DUS, MPDT, NEDS

Physical Location Comparison of Concentrations: A and B Depths

The following set of figures gives a visual representation of spatial distributions of the data on the ground, showing the relative concentrations of the analytes by “bubble size” located at their respective geographical locations. The analyte concentrations for the A and B depths are shown in respective graphs top-and-bottom for the same analyte-site combination².

For these graphs, any “nondetect” (ND) measurement (that is, below its respective detection limit, <DL) is replaced with the DL for a worst-case potentially highest concentration for the measurement. Later, when doing statistical comparisons, the nondetects are treated in a more statistically sophisticated manner. The “concentration” legend identifies by color which points are

² Note: For ease of graphical presentation, the aspect ratio of the X and Y location scales on the graphs is not 1:1; unlike GIS software, statistical software is not designed to hold a visual 1:1 aspect ration, which would make all graphs different sizes in order to accommodate different ground distances, in its extreme for example, a tall skinny graph might result. Thus, for example, points laid out on the ground in a square grid will appear as a rectangle. However, the distance in meters from the local (0,0) point for each CAS is correct for their respective axes.

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

below their respective DL and which points are “detects” (D), both plotted in a relative scale size proportional to its actual lab value, with a magnitude-annotated scale bubble at the (0,0) location that identifies relative size and units of measure to help in visually judging and comparing relative sizes. Although occasionally making some points very small, for cross-site visual comparisons the scale is intentionally kept the same for all site graphs for the same analyte. Selected larger graphs can be viewed in the Appendix for very small point sizes. Further, when there are few very high values, such as NEDS, the scale necessarily reduces the size of all other points.

Figure 1: Uranium (U mg/kg)

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Figure 2: Isotopic Uranium-234 (U234 pCi/g)

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Figure 3: Isotopic Uranium-235 (U235 pCi/g)

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Figure 4: Isotopic Uranium-238 (U238 pCi/g)

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Figure 5: Beryllium (Be mg/kg)

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Figure 6: Lithium (Li mg/kg)

Figure 7: Mercury (Hg mg/kg)

Task 1 Report

NSTec Environmental Restoration
CAU 484 Statistical Analysis

Figure 8: Niobium (Nb mg/kg)

Figure 9: Thallium (Tl mg/kg)

Numerical Summary Statistics

Table 2 presents summary statistics for Nondetect (using the DLs) and Detect measurements.

Task 1 Report
NTS Environmental Restoration
CAU 484 Statistical Analysis

Table 2: Numerical Summary of CAU 484 Analytical Data

Analyte	Statistic	Summary Statistics																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
		PDRO												DUS												MPDT												NEDS																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
		A				B				Site (A & B)				A				B				Site (A & B)				A				B				Site (A & B)				A				B				Site (A & B)																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A	D	ND	B	D	ND	A

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Comparison of Depths

Table 3 summarizes the statistical comparison of surface (Depth A) with subsurface (Depth B) concentrations. These are paired observations, since each X-Y sample location has two measurements associated with it, one each for Depths A and B.

Table 3: Statistical Comparisons of Surface (Depth A) and Subsurface (Depth B) Concentrations

		CAS																			
Analyte	Depth	PDRO				DUS				MPDT				NEDS							
		A		B		A		B		A		B		A		B					
Uranium (U mg/kg) AL = 200 mg/kg	<=HDL	20	1.000	20	1.000	36	1.000	36	1.000	35	0.972	36	1.000	34	0.944	34	0.944				
	>HDL	0	0.000	0	0.000	0	0.000	0	0.000	1	0.028	0	0.000	2	0.056	2	0.056				
	n	20	(100%ND)	20	(100%ND)	36	(100%ND)	36	(100%ND)	36	(97%ND)	36	(100%ND)	36	(94%ND)	36	(94%ND)				
	HDL	0.99				2.4				2.5				2.4							
	Median	<HDL		<HDL		<HDL		<HDL		<HDL		<HDL		<HDL		<HDL					
	Significance	p = 1.0				p = 1.0				p = 0.312				p = 1.0							
	Conclusion	A = B				A = B				A = B				A = B							
	Uniqueness																				
Isotopic Uranium-234 (U234 pCi/g) AL = 85.8 pCi/g	Method	Comp of Props > HDL				Comp of Props > HDL				Comp of Props > HDL				Comp of Props > HDL							
	n (& %ND)	20 (0% ND)		20 (0% ND)		36 (39% ND)		36 (28% ND)		36 (0% ND)		36 (0% ND)		36 (19% ND)		36 (28% ND)					
	A-B Median	0.134				2.208 (KM)		2.939 (KM)		-0.225				2.430 (KM)		2.386 (KM)					
	Significance	p = 0.024				p = 0.213				p = 0.144				p = 0.798							
	Conclusion	A > B				A = B				A = B				A = B							
	Method	WSR (paired data)				GWT				WSR (paired data)				GWT							
Isotopic Uranium-235 (U235 pCi/g) AL = 10.56 pCi/g	<=HDL					33	0.917	29	0.806	30	0.833	31	0.861	33	0.917	33	0.917				
	>HDL					3	0.083	7	0.194	6	0.167	5	0.139	3	0.083	3	0.083				
	n (& %ND)	20 (0% ND)		20 (0% ND)		36 (92%ND)		36 (81%ND)		36 (83%ND)		36 (86%ND)		36 (92%ND)		36 (92%ND)					
	HDL					2.26				0.477				2.36							
	A-B Median	0.0031				<HDL		<HDL		<HDL		<HDL		<HDL		<HDL					
	Significance	p = 0.422				p = 0.173				p = 0.741				p = 1.0							
	Conclusion	A = B				A = B				A = B				A = B							
	Method	WSR (paired data)				Comp of Props > HDL				Comp of Props > HDL				Comp of Props > HDL							
Isotopic Uranium-238 (U238 pCi/g) AL = 63 pCi/g	n (& %ND)	20 (0% ND)		20 (0% ND)		36 (61% ND)		36 (67% ND)		36 (0% ND)		36 (0% ND)		36 (28% ND)		36 (42% ND)					
	A-B Median	0.0535				1.131 (KM ave)		1.239 (KM ave)		-0.064				1.798 (KM)		1.837 (KM)					
	Significance	p = 0.287				p = 0.726				p = 0.999				p = 0.931							
	Conclusion	A = B				A = B				A = B				A = B							
	Method	WSR (paired data)				GWT				WSR (paired data)				GWT							
	n (& %ND)	20 (0% ND)		20 (0% ND)		36 (0% ND)		36 (0% ND)		36 (0% ND)		36 (0% ND)		36 (0% ND)		36 (0% ND)					
Beryllium (Be mg/kg) AL = 2,000 mg/kg	A-B Median	0.15				0.225				0.1				-0.2							
	Significance	p = 0.629				p = 0.001				p < 0.001				p < 0.001							
	Conclusion	A = B				A > B				A > B				A < B							
	Method	WSR (paired data)				WSR (paired data)				WSR (paired data)				WSR (paired data)							
	n (& %ND)	20 (0% ND)		20 (0% ND)		36 (0% ND)		36 (0% ND)													
Lithium (Li mg/kg) AL = 20,000 mg/kg	A-B Median	4.3				-1.7				None				None							
	Significance	p = 0.003				p = 0.730															
	Conclusion	A > B				A = B															
	Method	WSR (paired data)				WSR (paired data)															
	n (& %ND)	20 (0% ND)		20 (0% ND)		36 (0% ND)		36 (0% ND)													
Mercury (Hg mg/kg) AL = 310 mg/kg	<=HDL	17	0.850	19	0.950	33	0.917	35	0.972	None		None									
	>HDL	3	0.150	1	0.050	3	0.083	1	0.028												
	n	20	(85%ND)	20	(95%ND)	36	(92%ND)	36	(97%ND)												
	HDL	0.02				0.02															
	A-B Median	<HDL		<HDL		<HDL		<HDL													
	Significance	p = 0.292				p = 0.308															
	Conclusion	A = B				A = B															
	Method	Comp of Props > HDL				Comp of Props > HDL															
Niobium (Nb mg/kg) AL = NA	<=HDL	20	1.000	20	1.000	35	0.972	36	1.000	None		None									
	>HDL	0	0.000	0	0.000	1	0.028	0	0.000												
	n	20	(100%ND)	20	(100%ND)	36	(97%ND)	36	(100%ND)												
	HDL	3.1				3															
	A-B Median	<HDL		<HDL		<HDL		<HDL													
	Significance	p = 1.0				p = 0.312															
	Conclusion	A = B				A = B															
	Method	Comp of Props > HDL				Comp of Props > HDL															
Thallium (Tl mg/kg) AL = 67 mg/kg	<=HDL	18	0.900	19	0.950	28	0.778	33	0.917	None		None									
	>HDL	2	0.100	1	0.050	8	0.222	3	0.083												
	n	20	(90%ND)	20	(95%ND)	36	(78%ND)	36	(92%ND)												
	HDL	0.79				0.6															
	A-B Median	<HDL		<HDL		<HDL		<HDL													
	Significance	p = 0.548				p = 0.101															
	Conclusion	A = B				A = B															
	Method	Comp of Props > HDL				Comp of Props > HDL															

Test Methods: Comp of Props > HDL
WSR (paired data)
GWT

Comparison of proportions greater than Highest Detection Limit
Wilcoxon Signed Rank Test for Paired Data
Generalized Wilcoxon Test

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

There are several different types of statistical comparisons identified in the “Method” lines in the table (see the Statistical Methods section for descriptions of the annotations and when they are used); therefore, not all analyte-site combinations display exactly the same types of information. Taking the table row labeled U235 for example, the statistical method for high levels of censoring (percent nondetects > 80%) requires comparisons in terms of proportion of observations above the Highest Detection Level (HDL), thus the cells for the sites DUS, MPDT and NEDS have information related to that. By contrast, the appropriate comparison for 0% ND is the Wilcoxon Signed Rank test on the median of the paired-difference data, thus the cell for PDRO contains information relevant to that situation. And, for U238 DUS site data, as well as the NEDS site, the available test for these levels of censoring/nondetects is the Generalized Wilcoxon Test (GWT), with relevant information related to that, including the Kaplan Meier (KM) Maximum Likelihood estimates for median or average.³

For the decision maker, the most relevant information in the table are the “Conclusion” lines and their respective values of “Significance” (p-values). Recall that p-values less than 0.05 (or 5%) are statistically significant, greater than 0.05 not significantly different. The results of these statistical comparisons are indicated by the comparisons in the Conclusion lines, with **A = B** meaning no significant difference and **A > B** meaning that the Depth A concentration level for the analyte is significantly higher than the Depth B concentration level overall (e.g. median or average difference).

Summary of Depth Comparison Results

Table 3 identifies (in red letters, e.g. **A > B**) five statistically significant median depth level differences in U234, Beryllium, and Lithium at various CAS sites; all other analyte-site combinations show no statistically discernable differences. All but one of the five show a surface level contamination (Depth A) greater than subsurface contamination (Depth B). Table 4 summarizes the conclusions from these median concentration differences. The red background square (U-NEDS) indicates this site has a hotspot (> AL) for Uranium.

Table 4: Summary of Depth Differences

Analyte	CAS			
	PDRO	DUS	MPDT	NEDS
U	A = B	A = B	A = B	A = B
U234	A > B	A = B	A = B	A = B
U235	A = B	A = B	A = B	A = B
U238	A = B	A = B	A = B	A = B
Be	A = B	A > B	A > B	A < B
Li	A > B	A = B	None	
Hg	A = B	A = B		
Nb	A = B	A = B		
Tl	A = B	A = B		

³ These various methods employ advanced statistical procedures due to the complexity of the data; it is not the intent of this report to be a primer in environmental statistical methodology, but to document the method used and its results. The interested reader is referred to the cited references in the Statistical Methods section. These tables merely summarize results of statistical significance based on the correct method for the circumstances of the data.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis**Graphs of Selected Paired Comparisons (A – B for 0% ND)**

The following box-plot graphs in Figure 10 illustrate the distribution of the paired depth-difference data, A – B, in the units of their respective analytes (mg/kg for all but isotopic Uranium in pCi/g) when the data contain no censored “less-than” values (0% ND),⁴ the results of which have been summarized statistically, along with other combinations that do contain nondetects, in *Table 3: Statistical Comparisons of Surface (Depth A) and Subsurface (Depth B) Concentrations*. See Table 4 to determine what graphs illustrate statistically significant differences. See Table 3 for the specific tests and p-values. These box-plots simply show the spread of the data (minimum to maximum) and the central tendency statistics: median (line in the box) and mean (red “+” sign). The width of the box represents the middle 50% of the observations; extremes annotated.

Figure 10: Surface (A) - Subsurface (B) Concentration with 0% ND

⁴ As mentioned above with the geo-coordinate graphs, and below in the Statistical Methods section, plotting and comparing multiply censored data is problematic in dealing with indeterminate differences and plotting positions. The ability to do various types of plotting for multiply censored data is not yet available in commercial statistical packages.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Comparison of Verification Sites to Background Site

Table 5 summarizes the statistical comparisons of the three verification sites (DUS, MPDT, and NEDS) with the background site (PDRO). Significant differences are in red, e.g. **V > B**.

Table 5: Statistical Comparisons of Verification Sites and Background Site

Analyte		Background CAS		Verification CAS vs Background CAS (PDRO)			
		PDRO		DUS		MPDT	
Uranium (U mg/kg) AL = 200 mg/kg	<=HDL	40	1.000	72	1.000	71	0.986
	>HDL	0	0.000	0	0.000	1	0.014
	n	40	(100% ND)	72	(100% ND)	72	(99% ND)
	HDL	0.99		2.4		2.5	
	Median	<HDL		<HDL		<HDL	
	Significance			p = 1.0		p = 0.452	
	Conclusion			V = B		V = B	
	Uniqueness						
Isotopic Uranium-234 (U234 pCi/g) AL = 85.8 pCi/g	Method			Comp of Props > HDL		Comp of Props > HDL	
	n (& %ND)	40 (0% ND)		72 (33% ND)		72 (0% ND)	
	Median	1.318		2.770 (KM)		2.044	
	Significance			p < 0.001		p < 0.001	
	Conclusion			V > B		V > B	
	Method			GWT		WRS	
	n (& %ND)	40 (0% ND)		72 (86% ND)		72 (85% ND)	
	HDL			2.26		0.477	
Isotopic Uranium-235 (U235 pCi/g) AL = 10.56 pCi/g	Median	0.0723		<HDL (0.14 KM ave)		<HDL (0.20 KM ave)	
	Significance			p = 0.001		p = 0.007	
	Conclusion			V > B		V > B	
	Method			GWT		GWT	
	n (& %ND)	40 (0% ND)		72 (64% ND)		72 (0% ND)	
	Median	1.235		<HDL (1.10 KM ave)		1.757	
	Significance			p = 0.180		p < 0.001	
	Conclusion			V = B		V > B	
Isotopic Uranium-238 (U238 pCi/g) AL = 63 pCi/g	Method			GWT		WRS	
	n (& %ND)	40 (0% ND)		72 (0% ND)		72 (0% ND)	
	Median	1.2		0.99		1.6	
	Significance			p = 0.001		p < 0.001	
	Conclusion			V < B		V > B	
	Method			WRS		WRS	
	n (& %ND)	40 (0% ND)		72 (0% ND)		72 (0% ND)	
	Median	25.05		20.85			
Beryllium (Be mg/kg) AL = 2,000 mg/kg	Significance			p = 0.009			
	Conclusion			V < B			
	Method			WRS			
	n (& %ND)	40 (0% ND)		72 (0% ND)		72 (0% ND)	
	Median	1.2		0.99		1.6	
	Significance			p = 0.001		p < 0.001	
	Conclusion			V < B		V > B	
	Method			WRS		WRS	
Lithium (Li mg/kg) AL = 20,000 mg/kg	n (& %ND)	40 (0% ND)		72 (0% ND)			
	Median	25.05		20.85			
	Significance			p = 0.009			
	Conclusion			V < B			
	Method			WRS			
	n (& %ND)	40 (0% ND)		72 (0% ND)			
	Median	25.05		20.85			
	Significance			p = 0.009			
Mercury (Hg mg/kg) AL = 310 mg/kg	Conclusion			V < B			
	Method			WRS			
	n (& %ND)	40 (90% ND)		72 (94% ND)			
	HDL	0.02		0.02			
	Median	<HDL		<HDL			
	Significance			p = 0.387			
	Conclusion			V = B			
	Method			Comp of Props > HDL			
Niobium (Nb mg/kg) AL = NA	<=HDL	40	1.000	71	0.986		
	>HDL	0	0.000	1	0.014		
	n	40	(100% ND)	72	(99% ND)		
	HDL	3.1		3			
	Median	<HDL		<HDL			
	Significance			p = 0.452			
	Conclusion			V = B			
	Method			Comp of Props > HDL			
Thallium (Tl mg/kg) AL = 67 mg/kg	<=HDL	37	0.925	61	0.847		
	>HDL	3	0.075	11	0.153		
	n	40	(93% ND)	72	(85% ND)		
	HDL	0.79		0.6			
	Median	<HDL		<HDL			
	Significance			p = 0.232			
	Conclusion			V = B			
	Method			Comp of Props > HDL			

Test Methods: Comp of Props > HDL
WRS
GWT

Comparison of proportions greater than Highest Detection Limit
Wilcoxon Rank Sum Test
Generalized Wilcoxon Test

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

For explanation and examples of various different items in Table 5, see the previous section. All comments there are relevant to this table as well; although the previous table, Table 3, dealt with “paired data” for Depths A and B at the same location, whereas Table 5 and this section deal with the comparison of independent samples from each site overall: Verification (**V**) sites to the Background (**B**) site, as identified in Table 6 below. For a more detailed breakout of statistics for Depths A and B individually, see Table 2.

Summary of Verification to Background Results

Table 5 identifies (in red letters, e.g. **V > B**) 10 statistically significant differences where the verification site is higher than the background site for the respective analyte. There were two DUS site analytes (Be and Li) for which the verification site was actually significantly lower than the background site. All other analyte-site combinations show no statistically discernable differences. See Table 5 for actual median concentrations (where computable).

Table 6 summarizes the conclusions from these median concentration differences. The red background square (U-NEDS) indicates this site has a hotspot (> AL) for Uranium.

Table 6: Summary of Verification v Background Conclusions

Analyte	Verification CAS (V) (B = PDRO)		
	DUS	MPDT	NEDS
U	V = B	V = B	V > B
U234	V > B	V > B	V > B
U235	V > B	V > B	V > B
U238	V = B	V > B	V > B
Be	V < B	V > B	V = B
Li	V < B	None	
Hg	V = B		
Nb	V = B		
Tl	V = B		

Graphs of Selected Comparisons (Verification v Background 0% ND)

The following graphs illustrate the distribution of verification data as compared to the background data (PDRO) when the data contain no censored “less-than” values, the results of which have been summarized statistically, along with all combinations containing nondetects, in *Table 5: Statistical Comparisons of Verification Sites and Background Site*.

See Table 6 to determine what graphs illustrate statistically significant differences. See Table 5 for the specific tests and p-values.

Task 1 Report
NTS Environmental Restoration
CAU 484 Statistical Analysis

Figure 11: Verification v Background Comparisons for 0% ND

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Comparison of Sites to Action Levels (AL)

An examination of the maximum values reported in *Table 2: Numerical Summary of CAU 484 Analytical Data* show that the concentrations for all analyte-site combinations are so far below their respective Action Levels (AL) that the probability of any random point at the site exceeding the AL is exceptionally low, near zero (e.g. < 0.000001). There is one exception: Uranium at the NEDS site, which is analyzed further here since a hotspot had concentration greater than the AL.

The AL for Uranium is 200 mg/kg, and the maximum concentration of Uranium at the NEDS site is 325 (B Depth) and next highest is 48.7 (A Depth). There are 3 relatively high “detect” values at this site and one relatively small detected value: 27.1, 48.7 (A), and 325.0 (B), with the smallest detected value being 3.4 (B). The remaining 68 values are all nondetects below the highest detection limit (HDL = 2.4). Thus there is an identified “hot spot” at this site for Uranium that does exceed the AL, but the rest of the values are well below the AL.

Figure 1: Uranium (U mg/kg) illustrates that these higher values occur near the center of the site, with the 325 and 27.1 values at the same X-Y point exactly at the geometric center, with the 48.7 value right next to that point. If these locations are cleaned, and only random variation remains in the relative range of the rest of the values, as is the assumption with all these sites, there is a low probability (e.g. < 0.000001) of the site “average” exceeding the AL, after the hotspot is cleaned.

Based on the assumption that concentrations are randomly distributed in the relative range of the magnitudes observed from these systematic random samples, there is no evidence that indicates any reasonable probability (i.e. > 0.001) of a simple randomly selected location exceeding the respective AL.

Parametric probability models might be used for 0% ND or low levels of censoring in order to estimate high-end tail probabilities of the concentration of a randomly selected sample location from the area exceeding the respective AL; however, such tail estimates would be extremely unreliable other than to demonstrate that, regardless of the model fit, the tail probabilities (of exceeding the AL) would be extremely low (e.g. < 0.000001).

For example, for U234-PDRO, which has no nondetects and a maximum of 1.974 pCi/g (U234 + U234 Error, the 2-sigma error term being added as earlier in all these model analyses), the models in order of best fit are: Lognormal, Gamma, Largest Extreme Value, Normal and Weibull distributions, as shown below in Figure 12. All of these models predict less than 0.0001 probability of a randomly selected sample value of U234 exceeding **3** (three) pCi/g (best fit Lognormal predicts 0.000001) and immeasurable probability (< 0.000001) of exceeding **5** (five) pCi/g; whereas, the AL = 85.8 pCi/g. (Note: probabilities are numbers between 0 and 1)

For U234-MPDT, also with 0% ND but a maximum of 2.95 pCi/g, Figure 13, the probability of exceeding 5 is at best 0.00003 (Largest Extreme Value model, which along with Weibull are the poorest fits) or 0.00000002 (Lognormal model, best fit). All models predict essentially a 0 probability of U234 exceeding 7 pCi/g; again, for sites with the same AL = 85.8 pCi/g.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Figure 12: Distribution Models for U234 - PDRO Site (0% ND)

Figure 13: Distribution Models for U234 - MPDT Site (0% ND)

Similarly, when doing an MLE-fit (Maximum Likelihood) of the partially censored data of U234-DUS (33% ND, Figure 14) with a maximum of 7.15 pCi/g and U234-NEDS (24% ND, Figure 15) with a single extreme-value (only point beyond 7) maximum of 21.13 pCi/g, we find that for the worst case (NEDS) the probability of exceeding 20 pCi/g is at most 0.00003

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

(Lognormal being best fit), and not discernibly different from 0 for exceeding 25 pCi/g; for an AL = 85.8 pCi/g.

Figure 14: Maximum Likelihood Fit of Distribution Models for Partially Censored (33% ND) U234 – DUS

Figure 15: Maximum Likelihood Fit of Distribution Models for Partially Censored (24% ND) U234 – NEDS

NSTec has indicated that the primary contaminants of concern are U238 (Depleted Uranium or DU) with AL = 63 pCi/g and Beryllium (Be) with AL = 2,000 mg/kg. The maximum values of each across all four sites are 11.76 pCi/g and 3.4 mg/kg respectively, both on the NEDS site and located in the center of the site where the one hotspot for elemental Uranium is located. For Be,

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

there is essentially a zero probability (e.g. < 0.000001) of a randomly selected sample exceeding the AL of 2,000 mg/kg, several orders of magnitude higher than the maximum sample value.

For U238, the maximum concentration among the three other sites (non-NEDS) is 4.44 pCi/g, well below the AL of 63 pCi/g, resulting in essentially zero probability (e.g. < 0.000001) of a randomly selected sample exceeding the AL. Since the NEDS site has the highest value, still well below the AL (11.76 vs 63), it is modeled parametrically with Maximum Likelihood fit for partially censored data to illustrate that there is still an extremely low probability of a randomly selected sample exceeding its AL. The most conservative probability distribution model (Lognormal distribution fit) predicts that the probability of a randomly selected sample exceeding 30 mg/kg (less than half the AL) is 0.000004 and the probability of exceeding the AL of 63 pCi/g is less than 10^{-8} . These are extrapolations in the far ends of the distribution tail and are therefore not to be taken as precise values; simply to illustrate that the chance of U238 exceeding its AL on the worst site, NEDS, is essentially zero (e.g. < 0.000001). The model for U-238 is shown below in Figure 16.

Figure 16: Maximum Likelihood Fit of Distribution Models for Partially Censored (35% ND) U238 — NEDS

The same analysis holds for all other analyte-site combinations, with the same conclusion: that there is essentially a zero probability (e.g. < 0.000001) of a randomly selected sample will exceed its Action Level for the respective analyte. In general, when the critical value (AL) is so far above any of the data values, there is essentially no area under the tail of the distribution beyond that value.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Statistical Methods

The most respected authority on nondetect data analysis, U.S. Geological Survey senior scientist Dr Dennis Helsel, notes in his recent book, titled, *Nondetects And Data Analysis: Statistics for Censored Environmental Data*,⁵ that the development of proper statistical methodologies regarding left-censored nondetect (“less-than” detection limit) data is an active area of research, but even existing methods “have not found their way into common use within any of the environmental sciences.” The most common, arbitrary and inappropriate method in environmental studies for dealing with nondetect data is to substitute one-half the detection limit, which “is not a reasonable method for interpreting censored data.” In the analysis of CAU 484 data, a reasonable effort is made to follow the methodologies and guidelines identified by Dr Helsel.

Further, Helsel and Hirsch⁶ and all other environmental statisticians highly recommend the use of nonparametric statistical procedures for environmental data, since standard statistical distribution assumptions rarely hold true due to the typical attributes of environmental data, which include high levels of right skewing and extreme values that heavily impact the mean, along with the extendibility of these nonparametric methods for left-censored data, which is consistent with the CAU 484 data. Nonparametric methods work with the medians, order statistics and empirical distribution functions, rather than the means and assumed parametric distributional forms. These are the methods used in this study.⁷

Different methods are recommended for different levels of censoring and whether or not the censoring is based on multiple detection limits, which is the case throughout this CAU 484 study. Further, another level of complexity in paired data derives from the often indeterminate comparison of the compared numbers due to each having different detection levels. Thus, the standard paired comparison method of taking the paired differences and then doing a simple statistical test to see if the median of the differences is significantly different from zero cannot always be applied. In such cases, the analyte concentrations for the two Depths are treated as two different samples for the site and compared using appropriate methods with respect to the level of censoring. When there is no censoring, standard nonparametric statistical methods are employed.

⁵ Dennis R. Helsel. 2005. *Nondetects And Data Analysis: Statistics for Censored Environmental Data*. Wiley, New York.

⁶ Dennis Helsel and R.M. Hirsch. 2002. *Statistical Methods in Water Resources*. Available on-line from U.S. Geological Survey (originally published with Elsevier, NY).

⁷ Where more than 50% of the data is less than the highest detection level (HDL), the median cannot be determined other than “<HDL”. For example, in Table 3, the median NEDS-Uranium can only be indicated as “< HDL” since 94% of the measurements were Nondetects.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

For comparing each verification site (DUS, MPDT, and NEDS) to the background site (PDRO), all data is used (both A and B depths). Again, appropriate methods are used, depending on the level of censoring. Unique site characteristics, such as hot spots, are identified as such.

The Isotopic Uranium measurements (U234, U235, and U238) have “2-sigma measurement errors” associated with them from the lab reports. To treat the measurements of contaminants conservatively, these 2-sigma measurement error terms have been added to the mean measurement results for an approximate 95% upper bound estimate on the measurements (for both nondetect measurements and detect measurements) before using any of these numbers in statistical analyses.

Censoring: Censoring, in this case “left-censored” data, mean that the actual value is only known to be “less than” some analytical lab “detection limit” due to the technological limits of the equipment in resolution and sensitivity at concentrations less than the DL. That is, any analyte “signal” is not statistically different from the signal the analyst might get from a blank.

Different levels of censoring require different approaches to the analysis of the data and statistical comparisons. For example, if the censoring (% ND) is greater than 50%, the median is indeterminate other than as a “less than” some detection level. When the censoring is greater than 80% the analysis based on ranks becomes unreliable due to the indeterminate nature of most of the data; thus, statistical differences are determined by comparing proportions above the highest detection limit (HDL). The following are the methods used in this analysis and identified with the abbreviations used in the tables⁸:

0% ND (no censoring)	WSR (Wilcoxon Signed Rank) for paired comparisons (A vs B) WRS (Wilcoxon Rank Sum) for two-sample comparisons (V vs B)
< 50% ND (0 – 50%)	KM MLE (Kaplan Meier Maximum Likelihood) median estimates GWT (Generalized Wilcoxon Test) for comparisons
< 80% ND (50 – 80%)	KM ave (averages) for central tendency (median indeterminate) GWT for comparisons
> 80% ND	Comp of Props > HDL (Comparison of Proportions > HDL)

⁸ See Helsel, cited earlier, for technical details of these methods and when to use them.

Task 1 Report
NTS Environmental Restoration
CAU 484 Statistical Analysis

Quality Assurance Analysis

Blind duplicate samples were taken from each of the four sites in order to get an estimate of laboratory measurement variation (Lab Reps) relative to Sampling Unit variation (CAS SUs). The sampling plan resulted in the “nested” structure shown below in Figure 17 (shown with Beryllium numbers for this example). Note: The use of “A” and “B” in this figure refer to the two Depths from which the sample was taken at that sample number location.

Figure 17: QA Sampling Scheme

A variance component analysis was performed for each analyte that had no nondetects, which identifies how much variation (estimated variance and percent of total variance) is attributable to variation in the QA CAS SUs and how much to the blind duplicate analyses or **Lab Reps**. These results are presented in Table 7. For reasons described in the Statistical Methods section, the variance component analysis could not be done with sites involving multiple detection limits. Figure 18 illustrates the variance components and deviations graphically.

Task 1 Report
NTS Environmental Restoration
CAU 484 Statistical Analysis

Table 7: Variance Component Analysis

		U234				U235				U238				Be				Li			
		DF	Variance	%	Sigma	DF	Variance	%	Sigma	DF	Variance	%	Sigma	DF	Variance	%	Sigma	DF	Variance	%	Sigma
Variance Components	CAS	3	0.1090	32.6%	0.330	0	0.0000000	0.0%	0.000	3	0.0129	10.1%	0.114	3	0.0807	80.4%	0.284	1	5.4874	8.5%	2.343
	CAS SUs	10	0.1069	32.0%	0.327	1	0.0000744	57.2%	0.009	8	0.0001	0.1%	0.010	10	0.0027	2.7%	0.052	4	58.1937	90.2%	7.628
	Lab Reps	11	0.1182	35.4%	0.344	2	0.0000557	42.8%	0.007	11	0.1149	89.8%	0.339	14	0.0170	16.9%	0.130	6	0.8667	1.3%	0.931
	Total	24	0.3341	100.0%	0.578	3	0.0001301	100.0%	0.011	22	0.1279	100.0%	0.358	27	0.1004	100.0%	0.317	11	64.5478	100.0%	8.034
Ave Lab Measurement Error Sigma					0.357				0.010				0.285								
Ave Lab Measurement Error CV (sigma/ave)					20.0%				16.1%				20.9%								

Note: "Ave Lab Measurement Error Sigma" and "Coefficient of Variation (CV)" are the average of the 2-sigma "U23x Error"/2 terms for the same detect measurements used in the above variance analysis

Notice that these average reported measurement errors are quite close to the sample Lab Reps sigma, which is what we would expect in blind duplicate analyses.

The laboratory variance components ran from 1.3% for Li to 89.8% for U238. The laboratory variation was quite high for the Isotopic Uranium analyses, from 35.4% for U234 to 89.9% for U238 of the total observed variation (variance components analyses do not include the reported 2-sigma error terms, which sigmas are shown in the line below). These measurements all had relatively similar 2-sigma error terms reported with their measurement results. The remaining analytes (U, Hg, and Tl) contained many nondetects in the QA samples, thus the variance components analysis was not appropriate.

The implications of the variance components analyses are insignificant for comparisons to Action Levels, since the variances are very small relative to the magnitude of the AL's. Further, all analyses involving the Isotopic Uranium measurements were done with the 2-sigma measurement error added as a conservative high-end measurement confidence limit, which essentially incorporates a 95% high end limit for each measurement concentration. For the other analytes, Be and Li, the Lab Rep variance was relative small (16.9% and 1.3%, respectively). Thus, for comparisons of Depths A to B, and Verification CAS to Background (PDRO), the measurement error component was either already added in (U234, U235, and U238) or not very large, meaning the results of statistical significance should not be affected much by measurement error.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Figure 18: Illustrative Variance Components Plot (Beryllium)

Figure 18 is a nice plot to illustrate the relative amounts of variation that are quantified overall in the variance components analysis of Table 7. For Beryllium, the analysis shows that of the total variation in the Be QA samples from the four sites, CAS differences accounted for about 80% of the variation, Sampling Unit (SU) differences about 3%, and Lab Rep differences about 17%.

The paired data points in the plot are the two Lab Reps for that blindly split sample, i.e. for DUS SU 10A (Depth A) the two Lab measurements were essentially the same; whereas for the MPDT site, SU 20A had two measurements that were much larger in difference for the same sample. In fact, one can see that the measurement variation for the DUS site, for whatever reason, was very small, but larger for the other sites, which had higher average concentrations.

At the Sampling Unit (SU) level, the variation of the SUs represented by the average lines connecting the two Lab Rep measurements, is illustrated by the differences between the lines. The differences between the CAS Sites is illustrated by comparing the average of all 8 measurements for each site (only 4 in PDRO) to each other (forming a visual average, since there is no “average line” plotted for all 8 measurements for each site). And the total variation can be visualized by simply looking at the variation among all 28 QA points without any association to CAS or SU or Lab Rep.

The 80% component of total variation for CAS can be seen by the large CAS differences for each set of measurements. The 3% component for SUs and 17% component for Lab Reps can be seen from the fact that for all but DUS, the variation of the Lab Reps (difference between the two measurements) is higher than the SU variation (difference between the average lines connecting the two Lab Reps).

Task 1 Report**NTS Environmental Restoration
CAU 484 Statistical Analysis**

One expects large site (CAS) differences due to the different character of each site. One would like to see relative small Lab Rep differences relative to the SU differences, which would indicate that the measurement variation in the Lab is tighter than the field sampling variation that reflects the physical phenomena in the field. However, since both these components of variation are much smaller than the CAS variation, and all values are so far below the Action Levels, the laboratory measurement variation does not have any significant impact on the determination of levels of statistical significance for exceeding Action Levels or comparisons to Background Levels.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Summary of Findings

Surface and Subsurface Concentrations:

For all sites with their respective analytes of interest, there is no statistically significant “Depth differences”, e.g. between Surface (Depth A) and Subsurface (Depth B) concentrations, for:

Uranium (with the exception of one hotspot at the NEDS site), U235, U238, Hg, Nb, and Tl

Differences exist for the other analytes (U234, Be, and Li) on some sites as shown in this copy of *Table 4: Summary of Depth Differences*, summarizing the details of what’s different from what.

Analyte	CAS			
	PDRO	DUS	MPDT	NEDS
U	A = B	A = B	A = B	A = B
U234	A > B	A = B	A = B	A = B
U235	A = B	A = B	A = B	A = B
U238	A = B	A = B	A = B	A = B
Be	A = B	A > B	A > B	A < B
Li	A > B	A = B	None	
Hg	A = B	A = B		
Nb	A = B	A = B		
Tl	A = B	A = B		

Comparison of Verification Sites to Background Site and to Action Levels:

The Background (B) site is PDRO; Verification (V) sites are DUS, MPDT and NEDS. There were no differences between DUS and Background for Hg, Nb and Tl. For all other analytes, there were differences for some sites. These differences are shown in this copy of *Table 6: Summary of Verification v Background Conclusions*.

There was only one situation where the concentration of an analyte exceeded the Action Level: the Uranium hotspot on NEDS (325 mg/kg vs AL = 200 mg/kg).

Analyte	Verification CAS (V) (B = PDRO)		
	DUS	MPDT	NEDS
U	V = B	V = B	V > B
U234	V > B	V > B	V > B
U235	V > B	V > B	V > B
U238	V = B	V > B	V > B
Be	V < B	V > B	V = B
Li	V < B	None	
Hg	V = B		
Nb	V = B		
Tl	V = B		

Probability that Any Locations within each Site will Exceed Action Level

With one exception identified above, the maximum values of concentrations from all Sites for all analyte-site combinations are so far below their respective Action Levels that the probability of any random point at the site having an analyte concentration exceeding its AL is extremely low (e.g. < 0.000001). This also holds for a randomly selected location at the NEDS site, except for the Uranium hotspot. All other values are far below the AL of 200 mg/kg for Uranium.

Specifically, for both U238 and Beryllium, the two critical analytes of interest, there is an extremely low chance (e.g. < 0.000001) that any randomly sampled point from the site will exceed its Action Level (63 pCi/g for U238 and 2,000 mg/kg for Be).

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Appendix: Summary of Key Acronyms

ND	Nondetect: Concentration value less than the analytical detection level. AKA: “Left-censored”, meaning the value is below some number defined as the detection level (< DL).
D	Detect: Concentration value above the DL
DL	Detection Level: Analytical value below which the signal cannot be established as significantly different than a blank.
HDL	Highest Detection Level: Detection levels vary with each measurement; the HDL is the maximum DL for a given analyte at a given site and depth.
AL	Action Level: Maximum concentration for a given analyte above which there must be remediation action taken.
KM	Kaplan Meier: A particular type of statistical estimation, “Maximum Likelihood Estimation” or test, appropriate for left-censored data.
n	Sample size: Number of samples collected from a given site.
WSR	Wilcoxon Signed Rank test: A statistical test used on paired data or a single sample to determine if there is any statistically significant difference of the median from zero.
WRS	Wilcoxon Rank Sum test: A statistical test for comparing the medians of two independent samples.
GWT	Generalized Wilcoxon Test: A statistical test that extends the WRS test to more general situations, including left-censored data
p-value	The measure of statistical significance: “p” is the probability (a number between 0 and 1, or in percent between 0 and 100%) that the differences observed (between two samples or a median and an Action Level, for example) are due to random chance. p is considered statistically significant when $p < 0.05$ (or 5% in percent); meaning the chance of observing differences of the magnitude found or larger by random chance is less than 1 out of 20.
B	Background Site: PDRO Site, assumed to be uncontaminated and to which the active verification sites are compared.
V	Verification Site: These include DUS, MPDT and NEDS, which are to be compared to the Background Site PDRO.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Enlargement of Selected Geo-coordinate Graphs

Note: A single high value will automatically scale all other points to a very small size. Also note that when all values are very small, that is much less than the Action Level, being able to visually discern small detects from even smaller nondetects does not add anything to the spatial understanding of the site.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

Note the effect of excluding all Uranium values less than 10 mg/kg ($U < 10$). In the first two NEDS-Uranium graphs the three large values dominate the scale. In the second two, the maximum value is 3.4 and the nondetects range from 2.1 to 2.4 mg/kg at their detection limits.

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis**MPDT**

Analyte: U-235 (AL = 10.56 pCi/g)

MPDT

Analyte: U-235 (AL = 10.56 pCi/g)

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis**NEDS**

Analyte: U238 (AL = 63 pCi/g)

NEDS

Analyte: U238 (AL = 63 pCi/g)

Task 1 Report

NTS Environmental Restoration
CAU 484 Statistical Analysis

APPENDIX J-2

STATISTICS REPORT

Davis Gun Penetrator
Geophysical Target Statistical Analysis

*Alpine Analytics*TM

PO Box 830
Durango, CO 81302
Tel: 970-884-9490
AlpineAnalytics.com

*Sound ethical decisions based on data!*SM

E-mail: Root@AlpineAnalytics.com

Fax: 970-884-9141

July 27, 2007

**Tonopah Test Range
NSTec Environmental Restoration
*Corrective Action Unit 484***

**Task 2: Davis Gun Penetrator Geophysical Target
Statistical Analysis**

Root Routledge, PhD
Alpine Analytics

Project Subcontract No. 4140-02
Release Order No. 007
Peer Consultants, Inc.
Peer Client: Teledyne Brown Engineering

Alpine Analytics™

PO Box 830
Durango, CO 81302
Tel: 970-884-9490
AlpineAnalytics.com

Sound ethical decisions based on data! SM

E-mail: Root@AlpineAnalytics.com

Fax: 970-884-9141

Project Scope of Work for Statistical Modeling & Analysis

Objective & Background

Complete a statistical evaluation of quantitative and qualitative data collected during the closure of CAU 484 located at the Tonopah Test Range. Data for Task 2 consists of geophysical anomalies and their locations at several different sites, with the results of selected excavation investigations at a few of the locations.

Analytical methods used shall be technically defensible, and data output and analysis shall be presented in both numerical and graphical formats.

Task 2 (this report)

Determine the level of significance for investigating a subset of geophysical anomalies. A percentage of the total number of targets were investigated and the probability/confidence that no additional targets should be investigated needs to be quantified.

Data Provided

Geophysical "Davis Gun Anomaly Data" was provided by NSTec in Excel format. The total number of 1211 targets identified using an EM-61 ID Metal Detection system, covers eight sites of interest to varying degrees. All analysis is based on this data set, with clarifications provided by NSTec Environmental Restoration.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Executive Summary

Eight Davis Gun test locations (Sites) were examined using the EM-61 metal detector for possible Davis Gun Earth Penetrator or Depleted Uranium debris (hereafter EP/DU). This process identified a set of “Targets” for each Site from which sample location Targets were selected and investigated through physical excavation and inspection for “positive” characteristics of EP/DU. No EP/DU was found at any of the sampled Target locations; however, metal debris and unexploded ordnance were found.

The sample Targets selected were not drawn at random, but selected based on “biasing factors,” which Site experts believe were the most likely Targets to be “positive” for EP/DU debris. The argument then is, that if none of these “most likely positive” Targets ended up positive, then a reasonably safe closure decision can be made about all other Targets and unsampled sites under consideration. It is desired to know, however, what confidence statements can be made regarding the probability that other Targets that were not sampled could be EP/DU positive. Also, what sample sizes would it take to be “95% confident”. These results are summarized as a “random sample benchmark scenario” in *Table 1: Site Closure Risks and Potential Contamination Hazards Random Sample Benchmarks* on page 19 of this report, which is discussed thoroughly in the preceding and succeeding pages of the table.

Without duplicating it here, Table 1 summarizes the key parameters of this site end-state decision situation for the Davis Gun Earth Penetrator debris issue. From the benchmark scenario, we find that all closure-risk probabilities for closing sites that may be at least 5% contaminated are very high; ranging from 62.9% for Antelope Lake to 89.6% for Mt Helen, based on the very small sample sizes. As well, the potential level of contamination hazard when closing these sites based on no contaminated Targets in the small samples, ranges from 28.2% for Antelope Lake to 71.9% for Mt Helen, with 95% confidence. These seem to be unacceptable levels for risks and hazards of contamination Targets of concern remaining on the sites.

Biased judgment-based sampling has been employed due to the costs of physically investigating individual Targets in the larger samples that would be required from a random sampling scenario to hold risks and hazards to acceptable levels, following perhaps a “95% convention.” The basis for the judgment sampling is that, having selected the most likely Targets to be positive for the EP/DU contamination of concern, based on expert understanding of external biasing factors, and finding them contamination free, the conditional probabilities of any other Targets containing such contamination are so low as to be of negligible concern for closure decisions. Hence, the random sample benchmark scenario represents a “worst case” if the biasing factors did not end up increasing this likelihood of identifying the highest potential Targets for detailed physical examination.

However, since the biasing efficacy is not well documented empirically, there is no quantitative assessment of how low these conditional probabilities might be; and no way to perform one. The discussion about the judgment sampling by the client and the very small sample sizes employed seem to presume considerable confidence that these conditional probabilities are negligible, meaning that the biasing methodology is thought to be virtually deterministically absolute. Yet,

Task 2 Report**NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis**

even though all of the 16 sampled Targets ended up being “false positives” for contamination, there is no way of knowing whether that reflects the measurement capability of the remote measurement system, or the sampling that was done.

So, it is desired to at least bound the judgment-based sampling results with random sampling theory based on the sample sizes employed. But the bounds end up being so broad with such unacceptably high risk and hazard estimates, that the utility of these random sample bounds seems dubious. This leaves the site-closure manager with the dilemma that, although quantification of risks and confidences for end-state closure decisions are desired, they are either unestimable in the case of judgment-based conditional probabilities; or, they are too broad in a bounded scenario sense to support closure decisions. It may be that the expense of higher sample sizes randomly taken, perhaps along with more rigorous quantification of the biasing methodology, is justifiable in the light of the ambiguity and imprecision of these findings.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Introductory Comments on Analysis Issues

This task involves the evaluation of a dataset of a very small sample of Targets that were inspected and investigated via excavation from a master population of Targets generated by the EM-61 metal detection surveys; as well as the establishment of sampling plan parameters required to meet objectives that are not precisely specified by the client in terms of acceptable risk and contamination levels. The analysis developed below involves potentially confusing terminology and notation, including several kinds of probability statements; unfortunately this cannot be avoided for this kind of data, but this report strives for clarity and consistency to minimize potential confusion. However, even the statistically initiated reader is still burdened with the task of understanding such conceptual differences as they are described and keeping them clearly in mind as they relate to statements about the set of Site Targets.

To help the reader in this regard, for easy quick reference the development is assisted by an appendix of terminology, abbreviations and common notation and values used in the analysis (and used as convention in statistical sampling and analysis literature, in general). Also, clear and consistent notation will be defined when used initially either in the text or tables and graphs, and used consistently throughout the report. Finally, an accompanying “white paper” title, *Statistical Guidance for Understanding Environmental Restoration Closure Risks: End-State Site Decisions and Closure Requirements with Qualitative “Presence/Absence” Contamination Data* (here after *Closure Risk Statistical Guidance*) provides a developed and detailed understanding of the problem, methods and tools related to this class of decision problems.

The industry standard for risk and error rates of “95%” are used where needed and appropriate for establishing benchmarks to which the existing sample sizes can be compared.

Finally, in dealing with uncertainty and without 100% physical inspection/investigation excavation of each Target location, it is not possible to make statements or design sampling plans that give assurance that “no EP/DU Targets” exist in the population, without this 100% sampling. What needs to be specified is some “True Percentage” of EP/DU Targets that, if existing, a sampling plan is designed to find at least one of those with a specified probability. Its complementary probability is the risk of releasing and closing a site that is not fully clean. Throughout, it is assumed that if one or more EP/DU objects are found in the sample, the site will not be declared “clean” and closable; the decision rule being that, if no such objects are found in the sample the site will be releasable; associated with this are the risks that a potentially contaminated site is closed.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Characterization of Sites and Investigated Targets

The eight Sites are divided into two groups: i) Dry Lake (Playa) test sites, and ii) Volcanic Tuff test sites. For each Site, Targets were identified using the EM-61 metal detector and post processing of the raw data based on the associated geophysical prove out study to identify Targets that have the same electromagnetic properties as a Davis Gun penetrator. Targets are identified as those that matched a similar size object to a Davis Gun Earth Penetrator object, holding characteristics as possible Davis Gun Earth Penetrator based on their geophysical response, with some of the Davis Gun penetrators having Depleted Uranium (EP/DU), for potential sampling and further investigation. The primary means of identification has been the EM-61. Figure 1 shows the distribution of a total of 1211 Targets by Site.

Statistically, each Site is considered a separate population of “N” Targets. The basic issue is to sample a number of Targets, say “n”, *at random*¹ from each Site and physically investigate the Target object to determine if it is indeed “positive” in the characteristics for the object of interest, in this case an EP/DU object (but the same holds if instead of EP/DU objects we are interested in UXO objects or any other type of object with characteristics of interest). From the sample inspection information, if all objects in the sample turn out to be “negative” for the characteristic of interest (e.g. EP/DU), that is zero “positive” results ($X = 0$, where X is the number of EP/DU-positive Targets found in the sample of n Targets), then we want to establish the likelihood that other Targets are also negative. That leads the Site manager to a “Site disposition decision” regarding the site as a whole, with a specified risk that the “N” Targets on the Site may still contain an undetected fraction “p” (or in percent $p \times 100 = p\%$) of EP/DU objects.

The client notes that, regarding biased sampling and its known implications, the areas selected were the ones that had the best geophysical signal, had some visible surface features, or some other biasing factor that made it a better target. If these factors are known to increase the likelihood of investigating contaminated Targets, the analysis based on the random sample assumption should represent a “worst case” scenario in terms of deductions for risk-probabilities and potential hazard contamination level remaining — *for the given sample size*.

¹ In order to make any statement of a statistical confidence nature from the data given, it is essential that the Targets selected for investigation and determination as positive or negative for EP/DU are selected at random and are representative of all Targets that make up the population of Targets for that Site. If nonrandom sampling methods are used, the effectiveness of the sampling process is destroyed. The importance of random sampling cannot be over emphasized. If judgment methods are used to select the sample, the statistical basis of the sampling procedure is lost. That said, *if* the judgment method of sampling is known to be efficacious for increasing the likelihood of identifying potentially contaminated Targets, the “random sample” assumption can be used as a benchmark for sample size against which the judgment samples are held, with the judgmental inference that they are likely no worse than the random sample.

Graphical Characterization of the Site Target Data

Number of Targets and Object Found

A preliminary sample of 16 Targets was selected and each Target investigated. The investigation results are shown in Figure 2. No Davis Gun EP/DU objects were found.

Figure 1: Distribution of Targets by Site (921 Playa and 290 Tuff Targets)

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Figure 2: Objects Found from Investigation of 16 Targets

In Figure 2 the sample sizes, “n”, are shown along with the total number of Site Targets, “N”, that were sampled from (the sampled population). For example, at the Pedro Lake Site, n = 5 of N = 151 Targets were sampled. The clustered bar chart identifies the type of object found upon inspection of the n selected Targets. Although no EP/DU objects were found, five bombs and one projectile were found, grouped as UXO. These 16 Targets were *not* selected at random, which is discussed later on.

Target Location by Site

The relative location of the eight sites is shown for reference in Figure 3.³ This diagram is for general reference in comparing the physical location of the different sites and not intended to offer precise location coordinates of individual Targets.

³ The software used here is Statgraphics Centurion XV, a statistical graphics package not a GIS-mapping package, thus the X-Y scale aspect is not 1:1, which allows all graphs to retain the same size and shape, rather than varying with distances. UTM coordinates are in meters relative to the Universal Transverse Mercator global mapping system frame.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Figure 3: Comparison of Site Target Locations

A local X-Y “geo-coordinates” diagram of the location of Targets at each Site, identifying which Targets were selected in the existing samples is shown in Figure 4. Each Site has its own (0,0) point of reference, which in turn, has been documented by NSTec in UTM and Latitude/Longitude geographical mapping coordinates.

Figure 4 merely offers a graphical characterization of the Target locations, how they are physically distributed on the sites, and which ones were sampled and investigated for geophysical characteristics of contamination. The location of the biased sampled Targets relative to the rest gives some indication of area coverage and what parts are represented in the samples.

Figure 4: Target Locations by Site in Local X-Y Geo-coordinates (8 plots)

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Distribution of Target Characteristics by Site

Finally, the following two figures⁴ show the distribution of object characteristics by Site for object *Size* in centimeters (Figure 5) and object *Depth* in feet (Figure 6). The softer Dry Lake

⁴ Box-plot elements include the median (line in the box), mean (“+”), maximum and minimum values (extremes of the whiskers or individual points), and the overall distribution of the data in quartiles (25% of observations)

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Playa Sites have much larger objects and a wider dispersion of sizes than the harder Volcanic Tuff Sites, which were only measured in size classes (0-50 mm, 50-100 mm, and >100 mm).

Figure 5: Object Size Distribution

Figure 6: Object Depth Distribution

portrayed by each whisker and its extreme points; the middle 50% of the data illustrated by the box, separated into lower and upper quartiles by the median line).

Task 2 Report

NTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Analysis of Existing Sampling Plans

Sampling Method Used for Existing Sample of 16 Targets

Description of Method

The existing sample of 16 Targets over three Sites was not a random sample, but determined based on judgment. As noted earlier, this makes it problematic for any probability/confidence statements; however, the analysis will represent a “random sample assumption” benchmark, or “base case” for the given sample sizes, as if they were taken at random. The issue is not the Sites selected, but the sample of Targets from the selected Sites. The sampling scheme was based on an agreement between NNSA and NDEP that allowed the investigation of a limited number of locations selected based on technical criteria that represented the best possible chance of finding Davis Gun debris. The approach was documented and presented to the NDEP for approval and the plan was approved in April 2007.

A strictly random plan was considered but proved to be cost and schedule prohibitive due to the number of targets that would require investigation and the cost for this scale of investigation. The NDEP and NNSA agreed to the investigation approach with the understanding that the two targets selected for investigation at Mt. Helen have the best geophysical signal for a Davis Gun penetrator and have a surface expression that indicates the location of a Davis Gun test. Mt. Helen was selected because it was the oldest of the Davis Gun testing locations and due to the environmental practices of the time; it had the best chance of having residual waste/contamination. The agreement stated that if no Davis Gun penetrator debris was found at the Mt. Helen site, then no additional investigation would be required at any of the playa or tuff Davis Gun test locations. The agreement also stated that an evaluation of the existing Davis Gun target data would be conducted to evaluate the confidence level that any of the geophysical penetrator anomalies contain Davis Gun related debris.

The points for which NNSA and NDEP requested estimation are:

Confidence/Probability that no Davis Gun debris is associated with any of the targets at 1. Playa locations; and, 2. Tuff locations based on the findings that no Davis Gun debris was found at any of the limited locations that were investigated.⁵

What is the existing confidence associated with the total number of targets (at playa and tuff locations) and the limited number of targets investigated.

The anomaly target location selection criteria includes anomalies that yield a geophysical response that matches the geophysical response of Davis Gun penetrator “seed” items used in the geophysical prove out (this included all geophysical anomalies that yielded a response of 10 mV with an anomaly diameter of five meters). In addition, targets were selected for excavation investigation based on a surface disturbance that indicated an area where testing had occurred

⁵ See the attached *Closure Risk Statistical Guidance* document (cited more completely below) for an explanation why this question is not operable for closure decisions. The confidence for this statement will always be “zero confidence.”

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

using aerial photography and multispectral imagery. There are no additional known biasing factors that could be used to select targets for investigation.

The NNSA and NDEP are aware of the impacts that result from collecting data from biased locations based on judgmental assumptions; however the approach was selected so that the sites/locations selected would have the best chance of yielding Davis Gun debris, if any is present. The approach of selecting the target locations with the best chance of containing Davis Gun debris was selected due to cost and schedule constraints (investigating a large number of anomalies is cost prohibitive and access to these areas is limited due to testing activities). The task was also given to analyze the existing data to “estimate” the probability of any of the penetrator anomaly targets containing Davis Gun debris, and “estimating” the confidence level associated with the existing data (total targets vs targets investigated) using the assumption that since no Davis Gun debris was found in the two tuff locations investigated at Mt Helen and 14 sites investigated on Antelope and Pedro Lakes, the remaining uninvestigated anomaly targets do not contain Davis Gun debris. In order to “estimate” these parameters NNSA and NDEP gave direction to make the assumption that the investigated targets were randomly selected, and assuming that the biasing factors used to select the targets for investigation were correct the results would estimate the potential worse case situation for the entire population.

Commentary on Existing Sampling Method

Setting aside for the moment the issue of subjective inferences about other unsampled Sites based on information from sampled Sites, there are two technical concepts that are confounded together with this judgment biased sampling scheme. One is the selection of appropriate Targets for inspection, which includes the proper number of Targets in the sample for the desired probability statement as well as their method of selection, e.g. randomly selected. The second is one of *detectability* of objects of interest, e.g. EP/DU, which is a remote *measurement* issue (not a sampling issue) that incorporates ancillary information.

If one could devise a “detectability function,” say, for all Targets in the EM-61 defined population for the Site based on the “biasing factors” referred to, then that might be used to stratify the targets into “detectability classes” from which probabilities of selection could be rationally influenced by increased likelihood of rich Targets in the give detectability class. However, that was not done since the Targets were simply selected subjectively from the entire set based on judgment, with randomness not entering the process. Further, we have no empirical information that could relate such a function to some scale of likelihood of rich Target classes. To obtain that would require a designed study involving actual EP/DU objects and non-EP/DU objects similar in characteristics to the population of Targets.

Given these difficulties, it would be a distortion of statistical theory and reasoning to claim knowledge on “probabilities that no Davis Gun penetrator debris would be found” based on such biased sampling, yet *assuming* the sample Targets were “randomly selected.” However, without

Task 2 Report

 NSTec Environmental Restoration
 CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

other information to go on, we can only proceed with a *scenario* argument from which we can examine what could be concluded *if these sample Targets were indeed selected at random*, and assuming *equal remote detectability* of all Targets. The only conclusion possible beyond that is a subjective non-quantifiable statement that, in the judgment of site experts, our method of Target selection is biased toward high probability for EP/DU positive targets, and therefore, if none are found, there is *at most* the random sample probability of others existing. Again, this would then represent “worst case” scenario probabilities.

With these rather strong caveats regarding the biasing, and relatively weak counters in terms of defensibility, all the remaining analysis statements will refer to a “random sampling” scenario.

Random Sample Benchmark Analysis

For a fully developed explanation of the analysis methodology, terms and concepts employed here, see the accompanying *Closure Risk Statistical Guidance* (short title) document, fully titled: *Statistical Guidance for Understanding Environmental Restoration Closure Risks: End-State Decisions and Closure Requirements with Qualitative “Presence/Absence” Contamination Data for a Discrete Population of Sampling Units (Targets)*.

Closure Risks and Potential Contamination Hazard Levels

Client Request

The request is to provide benchmark sample size analyses based on random sampling theory. Further, to collapse and aggregate the analysis results from specific site numbers to the two geologic substrate types (Playa and Tuff); and then into an overall set of statements regarding all sites combined. With each level of aggregation, it is requested that benchmark probabilities and confidence statements be produced as if the small set of subjectively selected Targets for investigation were randomly sampled from whatever level of aggregation is being considered.

Concepts and Terminology

Decision Rule: The decision rule and decision criteria for this analysis are defined as follows⁸:

- Close the site as “clean” if the sample of n Targets contains $X = 0$ contaminated Targets
- Else, remediate the site and perform post-remediation verification sampling

Decision Risk: The decision *risk* is the *probability* of closing a site that contains contaminated Targets. That translates to the probability of obtaining a random sample of size n with $X = 0$ *given* some non-zero level of the unknown but true contamination that actually exists on the site.

This probability is a function of this unknown true actual contamination level, p (or $p\%$) of the N Targets, and the sample size, n . It is best portrayed with an “Operating Characteristic” (OC) Curve for a specified sample size n , which plots the “ β -risk” = $P[X = 0 \mid p, n]$ ⁹ vs $p\%$, the true

⁸ Based only on this single “presence/absence” measure of the COPC parameter for site evaluation. Other site variables that enter into the closure decision, such as concentrations of soil contaminants, are not considered here.

⁹ $P[X = 0 \mid p, n]$ is read as “the probability that $X = 0$ *given* (“ $\mid$ ”) specific values for p (or range of values as the X -axis) and n ”; e.g. the β -risk probability is a function of p and n .

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

but unknown percentage of Targets on the site that are actually contaminated (see Figure 7, Figure 8, and Figure 9 OC Curves for the three sites from which samples were investigated). A family of curves can be plotted on the same graph for different sample sizes. (See the *Closure Risk Statistical Guidance* for further detail.)

Management of the Decision Risk: The idea is to select a sample size n that holds the risk to some acceptable level for some specified level of true actual contamination that may exist, in conjunction with the criteria that the sample cannot contain any contaminated Targets ($X = 0$). Alternatively, if budget constraints dictate a specific sample size (as in this case), an OC curve characterizes the risks associated with the sample size.

Potential Decision Hazard: The *hazard* is what *level of contamination exposure* potentially remains in Targets left in the ground if a site that is still contaminated is closed. We can address the hazard question by asking: “How contaminated might the site be, with some level of confidence, if our sample of size n had $X = 0$ contaminated Targets?” The answer to this question involves computing a “95% Upper Confidence Bound” (UCB) on the percentage level of contamination, $p\%$.

Results

β -Risk: “What is the probability of closing a contaminated site, if we close the site based on our sample of size n that has $X = 0$ contaminated Targets?” What needs to be examined is the probability of obtaining a random sample of size n that is contamination free ($X = 0$), *given* some hypothesized value of p (or equivalently, some number, K , of contaminated Targets) that actually exists at the site. This hypothesized value of p is related to the decision risks involved. A “95% convention” would point to both a β -risk of 5% for a contamination level of $p = 5\%$. The existing sample sizes do not come close to achieving this; the results of an analysis of the sample sizes required are shown in *Table 2: Proper Site Sampling Plans to Achieve a 95% Objectives Benchmark*. β -risk is what is plotted on the Y-axis of an “OC Curve”. Table 1 shows the β -risk for the various sampling conditions requested at a contamination level of $p = 5\%$.

Potential Contamination Level Hazard: “How contaminated might the site be, with some level of confidence, if we close the site based on our sample of size n that has $X = 0$ contaminated Targets?” Table 1 contains a 95% UCB on $p\%$, the percentage level of potential contamination, for the various conditions requested, which is a function only of the sample size n , $X = 0$ contaminated Targets in the sample, and for small population sizes N , the total number of Targets in the population. When N is large relative to n (at least $N > 10 \times n$), the Binomial Distribution is a reasonable approximation to the Hypergeometric and can be used to provide the 95% UCB on p when these conditions hold.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Table 1: Site Closure Risks and Potential Contamination Hazards Random Sample Benchmarks

Site	Random Sample Benchmark Analysis for Existing Sample Sizes						Sample Plan (95% Convention)		
	Targets and Samples		Closure Risk Estimation		Potential Site Hazard		Sample Size Required	Closure Risk	Hazard
	N	n	$K = p \times N$ (with $p = 5\%$)	β -risk (%) $P[X=0 p=5\%]$	95% UCB on p	Confidence that $p \leq 5\%$	n (for $\beta = 5\%$ at $p=5\%$, $X = 0$)	β -risk (%) $P[X=0 p=5\%]$	95% UCB on p
	Total number of Targets	Actual sample size: Number of Targets Investigated (all $X = 0$) (e.g. all are negative for EP/DU contamination)	K = potential number of Targets contaminated for closure risk determination (assuming $p = 5\%$ level of contamination)	Risk of closing a site with at least $p = 5\%$ level of contamination (equivalent to K contaminated Targets)	95% Upper Confidence Bound on True p% of EP/DU Targets (want $p < 5\%$)	Confidence Level that the True p% of EP/DU Targets is not greater than 5% ($p \leq 5\%$)	Sample size to achieve 95% objectives: β -risk = 5% for $p = 5\%$ contamination level (with $X = 0$ contaminated Targets in the sample)	Risk of closing a site with at least $p = 5\%$ level of contamination (equivalent to K contaminated Targets)	given $X = 0$, n and N
Dry Lake/Playa									
Browns Lake	15	0	~1	-	-	-	15 (100%)	0.0%	0.0%
N Antelope Lake	755	9	~38	62.9%	28.2%	37.1%	57	4.78%	4.928%
Pedro Lake	151	5	~8	77.1%	44.5%	22.9%	49	4.77%	4.923%
Dry Lake (pooled)	921	14	~46	48.5%	19.1%	51.5%	106	-	-
Volcanic Tuff									
Antelope Tuff 1	75	0	~4	-	-	-	41	4.72%	4.909%
Antelope Tuff 2	98	0	~5	-	-	-	44	4.96%	4.988%
Mt Helen Area 1	8	2	~1	89.6%	71.9%	10.4%	8 (100%)	0.0%	0.0%
Myers Ridge	76	0	~4	-	-	-	41	4.82%	4.942%
Sidewinder Tuff	33	0	~2	-	-	-	28	4.02%	4.685%
Tuff (pooled)	290	2	~15	90.2%	75.5%	9.8%	154	-	-
All Sites (pooled)	1211	16	~61	43.8%	17.0%	56.2%	260	-	-

Cautionary Notes on Applicability of Risk and Hazard Estimates:**No samples were drawn at random**

All samples are **judgment-based samples** using various biasing factors thought to give the highest likelihood of detecting contaminated Targets

The intended non-statistical inference is: If none of these biased samples were contaminated then no other Targets should be contaminated

All derived **Risk and Hazard estimates** in the table are **based on Random Sampling Theory and the Hypergeometric Distribution for finite populations**

These are the **random sample assumptions required** to interpret the sample-size-based results in the table as **Random Sample Benchmark** numbers

Site specific numbers: The n investigated Targets were drawn at random from that specific site total of N Targets

Playa and Tuff "pooled" numbers: All Targets for the geologic substrate (N = 921 and N = 290) had an equal chance to be in the sample as a pooled group

(Sites where n = 0 were purposely not sampled, thus had no chance to be in the "pooled sample" numbers)

The intended non-statistical inference based on the judgment samples from selected Playa and Tuff sites is:

If the site-samples most likely to contain contaminated Targets are clean then other sites not sampled are sure to be clean

All Sites "pooled" numbers: All N = 1211 Targets are assumed to be one pooled population group from which n = 16 were drawn at random

The intended non-statistical inference is: The same for the above pooling and judgment-based samples

Sample Plan (95% Convention)

Site specific sample sizes for 5% risk at 5% site contamination with X = 0 contaminated Targets in sample: Drawn at random from the N Targets at each specific site

Playa and Tuff, and All Sites "pooled" sample sizes: These are the sum of the individual site sample sizes (**not based on pooled populations**)

Due to known differences among the geologic types and the sites themselves there exists a rational heterogeneous stratification factor

Stratified random sampling should allocate the samples according to site population sizes, not randomly across a "pooled" group

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Table 1 presents the key findings of this entire study. The columns are explained below, using the Antelope Lake row for example numbers to refer to in the discussion (to avoid continually repeating this, once it is clear from the development, the reader can assume that all example numbers come from this row, unless otherwise explicitly stated).

The left side of the table is titled, “Random Sample Benchmark Analysis for Existing Sample Sizes,” and it begins with two columns that identify the total number of Targets at each site, N (= 755 for Antelope Lake), and the sample size or the number of Targets that were selected in the judgment samples and investigated for contamination, n (= 9 for this example). All sampled Targets were found to contain no EP/DU, so for statistical analysis $X = 0$ contaminated targets is used to derive probabilities that such samples could be drawn at random from sites that have some level of contamination, say $p\%$ of the total Targets, where p represents an unknown but fixed parameter of the site population of N Targets. For this analysis a “95% convention” is followed, so the contamination level for evaluating risks is set at $p = 5\%$ (not zero, as was requested for presumed perfectly clean sites, since as pointed out earlier such probabilities are not meaningful for site decisions). The next column shows the potential number of contaminated Targets, K , at a $p = 5\%$ level of contamination ($K = 5\%$ of 755 = 38 for Antelope Lake). So far there is nothing statistical involved; these are simply the actual numbers and a possible scenario of a 5% contamination level in order to illustrate risks and hazards associated with it.

The remaining three columns involve statistical inferences based on the random sampling benchmark scenario for these sample sizes. The “ β -risk” shows the risk of closing a site with at least a $p = 5\%$ level of contamination (= 38 contaminated Targets of the 755 Targets for Antelope Lake). This risk is equivalent to the probability of obtaining a sample of size $n = 9$ that contains no contaminated Targets, given that 38 Targets out there are contaminated. Notice that this probability is very high; that is, there is about a 63% chance of obtaining such a sample with no contamination, even though 5% of the site is actually contaminated. This is the site-closure risk.

The next two columns reflect measures of the potential contamination level hazard if such a site is closed; that is, they address the question: “How contaminated might the site be?” The first hazard column is a 95% Upper Confidence Bound on p , the true but unknown percent of Targets that are contaminated. Under the “95% convention,” we would like this number to be less than 5%. However, none of these sites exhibit estimates anywhere close to that with the sample sizes taken. The way to read the two items together, risk and hazard, is this: “With a sample of $n = 9$ Targets, none of which ended up being contaminated, there is still about a 63% risk of closing a site that may have as high as 28% contamination. A sample of size $n = 9$ does not offer much assurance that the site is not contaminated even at the $p = 5\%$ level, let alone at some lower level, say 1%; and in particular, *zero* confidence that *none* of the Targets are contaminated.

Another way to address the hazard question rather than asking, “*What is the contamination level with 95% confidence?*”; yet still following the 95% convention, is to ask: “*What is the confidence that the contamination level does not exceed $p = 5\%$?*” That is shown in the last column of the left side of the table. For Antelope Lake, with a sample of $n = 9$ from the $N = 755$ Targets and $X = 0$ contamination among them, we are only about 37% confident that the contamination level in the entire site does not exceed 5%. That doesn’t mean it *is* that high, it might be zero! What it means is that with a sample of only 9 Targets, it is quite likely to obtain a

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

sample with no contamination (63% chance) even when the site is 5% contaminated; thus we can be only 37% confident that the site doesn't exceed 5% contamination. The burden of proof is on the site owner to demonstrate it is clean with a reasonably high level of confidence, which this is not even close (if 95% confidence of not exceeding 5% contamination represents such a reasonable number for environmental decisions).

Although this report emphasizes throughout the impact of biased sampling on the breakdown of the statistical theory under-girding probability deductions based on random sampling distributions (the basis of the numbers reported in Table 1); what this left side of the table shows is what inferences *could* be made if in fact the small samples that were taken in a biased way, actually represented *random* samples from each site.

The tasking for this report does not include any analysis of the efficacy of the judgment sampling, and no empirical evidence of it appears to be available for such evaluation; therefore, no judgment can be made here about how different these probability and confidence numbers might be for the judgment-based samples. What Table 1 shows, however, is how poorly these small sample sizes perform, regardless of how they were taken. The entire rationale for the judgment-based sampling is that the *conditional probabilities* (whatever they might be as we have no knowledge of them) that contamination exists among other Targets and unsampled sites, given that the biased judgment samples exhibited no contamination, are so small as to negate any concern that there might exist contamination *anywhere* throughout these eight sites. However, even assuming the validity of the biasing for the judgment samples, the efficacy of which is not claimed to be deterministically absolute, if the "random sample benchmark scenario" is to bracket it as a "worst case" possibility, the risk-probabilities and potential contamination level hazards that still might exist are so high that the utility of the this worst case bracket needs to be given serious scrutiny, as well as the tiny sample sizes. Consider the technical argument that must be made, sans any empirical evidence even, that these conditional probabilities are many factors more favorable than those of the random sample benchmarks for the same sample sizes.

The right side of the table shows what would be required for proper random sampling to establish that these risk levels and hazard estimates both conform to a 95% convention, still with no contaminated Targets ending up in any of the samples. They are several times the sample sizes that have been taken. For example, Antelope Lake would require a random sample of $n = 57$ Targets (more than 6 times larger) to ensure that the risk of closing the site (if it indeed was contaminated at least to the level of 5%) was held to no greater than 5% ($\beta = 4.78\%$, which doesn't come out exact due to the discrete sample sizes; e.g. $n = 56$ causes the risk to be greater than 5%). Also with this sample size, we can be 95% confident that when no contaminated Targets ($X = 0$) are among the 57, the potential contamination hazard would not be more than 4.928%; again less than 5%, but not exactly 5% due to the discrete nature of integer sample sizes.

The notes at the bottom of Table 1 are very important for interpretation of these numbers. They emphasize the contrast between the actual conditions under which the judgment samples were drawn and the assumptions required to produce the "random sample scenario benchmark" probabilities. Also, the inferences are even sketchier when pooling the numbers and assuming they can be extrapolated to unsampled sites via judgmental extension that necessarily imply assumptions that these samples were randomly drawn across qualitatively heterogeneous groups. They really don't have much meaning for these kinds of unrealistic scenarios.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis**OC Curves for Existing Sampling (assumes random samples) – Brief Description and Relationship to Industrial Lot-Acceptance Sampling Plans**

For a more fully developed description and interpretation, please refer to the previously mentioned *Closure Risk Statistical Guidance*. The brief description below is intended to help understand the basics of Operating Characteristics (OC) Curves in the context of this report. The probabilities in Table 1 are related to (can be obtained from) these curves, both of which are based on the Hypergeometric Sampling Distribution, the theoretical probability distribution for random sampling from a finite population.

For properly designed random sampling plans, Operating Characteristic (OC) Curves represent the key tool to evaluate the performance of the sampling plan. The OC curve identifies the probability of accepting a Site as “clean” (containing no “positive”, e.g. EP/DU, objects among the N Targets) *relative to* an actual “True Fraction/Percentage, **p**” of positive Targets that *actually might (are presumed to) exist* in the population of N Targets. This class of sampling problems, which is described more formally below, is referred to as “*Lot Acceptance Sampling Plans*,” where a finite “Lot” (Site, in our case) of size “N” (N = total number of units/Targets in the Lot/Site) is to be sampled randomly, with a sample of size “n” units/Targets.

A “Lot sentencing decision” is made as “good” (no remediation required) or “bad” (requires remediation) depending on whether or not the Lot meets some specified minimum quality level. This level is expressed in the industrial language of these Acceptance Sampling Plans as a “Lot Tolerance Percent Defectives” or **LTPD** (aka: actual percent, **p**, of Targets “contaminated” or “nonconforming”, say **p = 5%** “contaminated”) with an associated probability of acceptance that does not exceed some small value.¹⁰ This number is referred to as the “*false negative*” probability, or “beta” (β). Its complement, $(1 - \beta)$ is the probability of rejecting the Lot (finding at least one “positive” EP/DU Target in the sample of size n) given the “True Percent, p” of EP/DU Objects that actually exist. We want $(1 - \beta)$, also known as the “*Power*” of the disposition test, to be at least **1 - β = 95%** for detecting at least one EP/DU object when 5% of them are out there. (Industry standard “95% convention” values are used here.)

The decision criterion is some acceptance number, **c**, such that the Lot is accepted as “clean” or “conforming” at the specified quality level (LTPD) if the number of “nonconforming” units in the sample, say X, does not exceed c (e.g. **accept Lot if $X \leq c$**). In our situation, we are more specifically constrained to the subset of “*Zero Acceptance Number*” ($c = 0$) *sampling plans*. That is, the “Lot” (e.g. Site) must be rejected as contaminated if even *one* Target in the sample turns out to be a positive EP/DU object and therefore the Site must be fully investigated. It is not sufficient just to clean up the EP/DU Target found in the sample and claim nothing else needed.

Each OC Curve figure plots the “closure risk” (probability of accepting the site as clean) versus the potential level of contamination, p%. The risk of closure is relative to the actual contamination level.

¹⁰ In general, another point must also be specified, but that does not apply to our application where we require that no contaminated Targets can exist in the sample ($X = 0$) and have the site still considered clean.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Figure 7: Characteristics of the N. Antelope Lake Sample (if taken at random)

These points are graphically illustrated in Figure 7. Note that even if $p = 5\%$ of the 755 Targets out there at the Site are EP/DU objects (that is, $5\% \times 755 = 38$ EP/DU objects), and none were found in the sample of $n = 9$ Targets, there is still about a $\beta = 63\%$ risk of incorrectly declaring the Site as "clean" (containing no EP/DU objects) and only a $1 - \beta = 37\%$ chance of obtaining a sample of size $n = 9$ containing at least one EP/DU object. Similar OC charts are shown for the other two sampled Sites: Pedro Lake (Figure 8) and Mt Helen Area 1 (Figure 9).

Figure 8: Characteristics for the Pedro Lake Site Sample (if taken at random)

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Figure 9: Characteristics for the Mt Helen Area 1 Site Sample (if taken at random)

None of these sampling plans perform anywhere near the hoped for parameters.

Appropriate Sampling Plans to Achieve Stated Objectives

Specific Site Objectives

The same qualitative statements are translated the same way as above, with “high level” meaning 95%, and the maximum percent EP/DU that we associate the 95% confidence with is $p = 5\%$ of the population of EM-61 generated Targets. It should be clear that the statement “no EP/DU present” ($p = 0\%$) is not a value about which any reasonable probability statement can be made without 100% inspection. This will be made clearer when the sample sizes required for $p = 1\%$ EP/DU are compared to sample sizes required for $p = 5\%$.

Analogy of Lot Acceptance Sampling and Proper Distribution Model

The proper random sampling model for making a “disposition decision” on each Site of N Targets is that of *Lot Acceptance Sampling*. A random sample of n “sampling units” (EM-61 Targets, in our case) is drawn from the fixed and finite total population of N units in the Lot (Site). Based on the desired sampling characteristics, and in our case with $c = 0$ allowable “nonconforming” units (EP/DU positive), a proper sample size is determined that provides the acceptable level of risk for

Task 2 Report

NSTec Environmental Restoration

CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

making the wrong decision; that is, declaring the Lot acceptable (the Site uncontaminated with EP/DU Targets), when in fact it has some percentage p (specifically $p=LTPD$) of EP/DU Targets.

Another physical model analogy is sampling balls (blindly) at random from an urn filled with, say, $N = 800$ balls and $p\%$ of these 800 are red balls, whereas the rest are white. The urn will be rejected as “contaminated” if any red balls end up in the random sample of n balls.

The Hypergeometric probability model is the appropriate model that characterizes this sampling situation. This is what the earlier OC curves for the existing sampling plan were based on. It is also the model used to determine the sample size required so that there is $\geq 95\%$ probability of correctly identifying a Site as “contaminated” with EP/DU if in fact it does contain $p = 5\%$ of the Targets positive for EP/DU. The results of this sampling scheme for the eight sites are shown in Table 2. The table compares these sample sizes, “ **n Required**” and the exact probability ($1-\beta$) of finding at least one EP/DU Target in the sample (which we want $\geq 95\%$), for $p = 5\%$, with the existing investigation sample sizes, n Investigated, and also the plan required for $p = 1\%$.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Formulation of Site Acceptance Plans

Table 2: Proper Site Sampling Plans to Achieve a 95% Objectives Benchmark

Site		Existing Investigation Data Summary						Site Acceptance Sampling Plans to Achieve 95% Objective							
		Current Sampling Intensity						Scenario A: 5% Contaminated				Scenario B: 1% Contaminated			
		n Investigated	EPDU Found	95% UCB on p	p	Expected EP/DU	1 - Beta	p	Expected EP/DU	n Required	1 - Beta	p	Expected EP/DU	n Required	1 - Beta
		Number of Targets Investigated	Number of EP/DU Targets found from locations investigated	95% Upper Confidence Bound on True % of EP/DU Targets (want < 5%)	Assumed True % of EP/DU Targets	Expected number of EP/DU Targets present (p x N)	Current Sampling Probability of finding at least one EP/DU (want >95%)	Assumed True % of Targets with EP/DU	Expected number of EP/DU Targets present (p x N)	Sample size to achieve 95% objectives	Probability of finding at least one EP/DU (want >95%)	Assumed True % of Targets with EP/DU	Expected number of EP/DU Targets present (p x N)	Sample size to achieve 95% objectives	Probability of finding at least one EP/DU (want >95%)
Dry Lake/Playa															
Browns Lake		15	0	-	5%	0.75	-	5%	0.75	14/15	86%/100%	1%	0.15	14/15	30%/100%
N Antelope Lake		755	9	0	28.3%	37.75	37.1%	5%	37.75	57	95.2%	1%	7.55	247	95.1%
Pedro Lake		151	5	0	45.1%	7.55	22.9%	5%	7.55	49	95.2%	1%	1.51	130	95.0%
Total Dry Lake		921	14	0	-	46.05	-		46.05	121	-		9.21	392	-
Volcanic Tuff															
Antelope Tuff 1		75	0	-	5%	3.75	-	5%	3.75	41	95.3%	1%	0.75	74	95.7%
Antelope Tuff 2		98	0	-	5%	4.90	-	5%	4.90	44	95.0%	1%	0.98	94	95.6%
Mt Helen Area 1		8	2	0	77.6%	0.40	10.4%	5%	1.00	7/8	52%/100%	1%	1.00	8	100.0%
Myers Ridge		76	0	-	5%	3.80	-	5%	3.80	41	95.2%	1%	0.76	75	95.9%
Sidewinder Tuff		33	0	-	5%	1.65	-	5%	1.65	28	96.0%	1%	0.33	32/33	65%/100%
Total Tuff		290	2	0	-	14.50	-		15.10	162	-		3.82	284	-
Total (All Sites)		1211	16	0	-	60.55	-		61.15	283	-		13.03	676	-

Note: 95% UCB on p is based on Binomial Distribution, which assumes very large $N > 10 \times n$ (thus the value for Mt Helen Area 1 is not exact due to very small population size of $N = 8$)

Note: The probability 1 - Beta is based on the Hypergeometric Distribution for exact population size N, thus it is exact for all computations

The computations in Table 2 are based on the Hypergeometric sampling distribution for sampling from a finite population, and the Binomial distribution, where indicated. Notice in Scenario A ($p = 5\%$ contaminated) that the sample sizes, **n Required**, are chosen just large enough to produce a $1 - \beta \geq 95\%$, the “high level of assurance” probability to reject such a Site as contaminated (by finding at least one EP/DU in the sample). Compare these sample sizes and $1 - \beta$ values with the existing investigation sample sizes, **n Investigated**, and its $1 - \beta$. The sample sizes required for 95% are much higher. For example with Pedro Lake, $n = 49$ to get 95.2% assurance that $p < 5\%$ contaminated Targets, whereas the existing $n = 5$ sample size gives only a 22.9% level of assurance, meaning that there is a $\beta = 100 - 22.9 = 77.1\%$ chance the Site contains EP/DU even though none were found in the sample of 5 Targets.

Further, if the site restoration manager is uncomfortable with a determination on $p = 5\%$ contamination level, wanting “a high level of confidence that no EP/DU exist” based on the sample, examine the increase in sample sizes for $p = 1\%$ level of contamination. The sample size goes from $n = 49$ to $n = 130$, an increase of 165%. This is the nature of attribute sampling. Unfortunately, for any reasonable level of confidence in a clean site, the sample sizes must be very large.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Bombs and Other Target Objects

All of the previous discussion, sampling plans and analysis apply to Bombs, Projectiles and any other Target Object of interest. The project manager asked: “Since we did find bombs on Pedro Lake and two on Antelope Lake in locations where the geophysics or other criteria indicated Davis Gun debris may be present, what is the confidence/likelihood that the other targets in the area may be bombs?”¹²

All of the discussion regarding “detectability” applies here as well; only in this case for the identification of Bombs. Again, no information is available regarding that. What can be estimated (given all the caveats regarding biased versus random sampling presented earlier) is a 95% UCB on the percentage of Targets that would be “positive” for such Bomb criteria. That is given here in Table 3 for the two sites from which they were found.

Table 3: Bomb Debris Sampling Results

Sites	Sample Size	Number of Bombs	p	95% UCB
	(n Investigated)	Number of Sampled Targets Positive for Bomb Debris	Percentage of Sampled Targets Positive for Bomb Debris	95% Upper Confidence Bound on Percentage of Targets Containing Bombs
N. Antelope Lake	9	1	11.1%	42.9%
Pedro Lake	5	4	80.0%	99.0%

Unsampled Site Inferences

Only three Sites were actually sampled: two Playa sites (N. Antelope Lake and Pedro Lake) and one Tuff site (Mt Helen). There is no statistical inference that can be made about the other sites that were not sampled. Any inferences made to the non-sampled sites would be a judgmental extrapolation of the probability information above based on similarity of characteristics and history of the sites.

This is similar to what is done when medical investigations study the effectiveness on mice (mammals) and want to make extensions of the results to humans (also mammals) who have similar physiological characteristics, but who were not studied. These inferences are then validated in follow up phases by additional studies on human subjects. This may be desirable for the unsampled sites. Again, such judgment factors were not part of this analysis.

¹² Email from NSTec, dated 5/3/07 11:00 am.

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Summary

Without duplicating it here, *Table 1: Site Closure Risks and Potential Contamination Hazards Random Sample Benchmarks* summarizes the key parameters of this site end-state decision situation for the Davis Gun Earth Penetrator debris issue. From the benchmark scenario, we find that all closure-risk probabilities for closing sites that may be at least 5% contaminated are very high; ranging from 62.9% for Antelope Lake to 89.6% for Mt Helen, based on very small sample sizes. As well, the potential level of contamination hazard when closing these sites based on no contaminated Targets in the small samples, ranges from 28.2% for Antelope Lake to 71.9% for Mt Helen, with 95% confidence. These seem to be unacceptable levels for risks and hazards of contamination Targets of concern remaining on the sites.

Biased judgment-based sampling has been employed due to the costs of physically investigating individual Targets in the larger samples that would be required from a random sampling scenario to hold risks and hazards to acceptable levels, following perhaps a “95% convention.” The basis for the judgment sampling is that, having selected the most likely Targets to be positive for the EP/DU contamination of concern, based on expert understanding of external biasing factors, and finding them contamination free, the conditional probabilities of any other Targets containing such contamination are so low as to be of negligible concern for closure decisions. Hence, the random sample benchmark scenario represents a “worst case” if the biasing factors did not increase this likelihood of identifying the highest potential Targets for detailed physical examination.

However, since the biasing efficacy is not well documented empirically, there is no quantitative assessment of how low these conditional probabilities might be; and no way to perform one. The discussion and very small sample sizes seem to presume that they are negligible, meaning that the biasing methodology is virtually deterministically absolute. Yet, even though all of the 16 sampled Targets ended up being “false positives” for contamination, there is no way of knowing whether that reflects the measurement capability or the sampling that was done.

So, it is desired to at least bound the judgment-based sampling results with random sampling theory. But the bounds end up being so broad with such unacceptably high risk and hazard estimates, that the utility of these random sample bounds seems dubious. This leaves the site-closure manager with the dilemma that, although quantification of risks and confidences for end-state closure decisions are desired, they are either unestimable in the case of judgment-based conditional probabilities; or, they are too broad in a bounded scenario sense to support closure decisions. It may be that the expense of higher sample sizes randomly taken, perhaps along with more rigorous quantification of the biasing methodology, is justifiable in the light of the ambiguity and imprecision of these findings.

Task 2 Report**NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis**

Recommendations

The high sample sizes required in scientific random sampling for a reasonable degree of assurance (95%) that a given Site has no more than 5% contaminated EP/DU (or other) Targets suggests that future studies should examine cost tradeoffs with a more sophisticated investigation that would include studying the following parameters:

- Cost of physically excavating and inspecting each Target
- Cost of a designed experiment to develop a “remote detectability” model that would investigate and validate the additional “biasing factors” that could be used in conjunction with the EM-61 metal detector identification of potential targets to provide for a sampling plan based on the estimated probability of detection
- Design of a sampling scheme that incorporates the detectability function in order to focus more effort in a quantifiable way on “richer Targets,” those with higher probability of EP/DU, in order to get better Site information for the sampling/excavation budget dollars
- Possible multistage sampling schemes that would trigger deeper sampling, depending on what is found in initial samples at each Site based on the remote detectability model
- Some kind of sampling scheme for each Site, or a population of Sites, so that quantifiable statistical estimates can be made about all Sites

Task 2 Report

NSTec Environmental Restoration
CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

Appendix: Terminology¹³ and Abbreviations

Site	Any one of the eight test ranges identified in this study: Brownes Lake, N. Antelope Lake, Pedro Lake, Antelope Tuff 1, Antelope Tuff 2, Mt Helen Area 1, Myers Ridge, and Sidewinder Tuff
Target	Specific locations on the ground whose coordinates and possible content are identified by the EM-61 metal detector as having characteristics similar to EP/DU objects
EP/DU	Targets with Davis Gun Earth Penetrator or Depleted Uranium objects and/or debris
Bomb	Targets with Bomb objects and/or debris
N	Population size: Total number of Targets at a Site
n	Sample size: Number of Targets selected for investigation via excavation and inspection of objects and debris
“positive” and “negative”	That status of Targets that if/when inspected test “positive” (contain) or “negative” (don’t contain) attributes defined for the characteristics of interest; e.g. EP/DU or Bombs
p (and p%)	The unknown but “True” fraction or percent (fraction x 100%) of Targets that are positive for the characteristic of interest; e.g. percent of Targets that contain EP/DU
Lot	(= Site) Industrial Lot Acceptance Sampling terminology that refers to the population of sampling units to be sampled from; equivalent to “Site” in this study
LTPD	“Lot Tolerance Percent Defective”: Industrial Lot Acceptance Sampling terminology that refers to a specific value of p for which a specified risk level (β probability) is identified and controlled with sample size n such that the chance of an incorrect “Lot Sentencing Decision” (concluding the Site is clean) will not exceed
Investigated	A sampled Target location that has been physically excavated and inspected for the type of object or debris present
β and $(1 - \beta)$	β is the probability of making an incorrect conclusion that a Site is clean, when in fact it still contains EP/DU positive Targets (Type II error); $1 - \beta$ is the probability of finding at least one EP/DU Target in the sample and correctly declaring the Site contaminated with EP/DU
c (and c = 0)	The maximum number of “positive” Targets in the sample and still

¹³ Primary variable or factor names are capitalized.

Task 2 Report

NSTec Environmental Restoration

CAU 484 Davis Gun Penetrator Geophysical Target Statistical Analysis

	declare the Site clean of EP/DU, which in this study is zero ($c = 0$)
OC Curve	Operating Characteristic Curve: The statistical graphics tool that is used to evaluate the performance of a random sampling plan. It plots the “Probability of Accepting the Site as Clean” against the “True Percent of EP/DU Targets” present (p). A specific value of importance on this curve is the value of β associated with a specific value of p ($=$ LTPD); selection of this pair is what determines the required sample size, n .
95% UCB on p	95% Upper Confidence Bound on p , the True percentage of EP/DU Targets is a one-sided Confidence Interval, interpreted as “95% confident that p is less than or equal to the value of the UCB”

Alpine Analytics™

PO Box 830
Durango, CO 81302
Tel: 970-884-9490
AlpineAnalytics.com

Sound ethical decisions based on data! SM

E-mail: Root@AlpineAnalytics.com

July 27, 2007

Statistical Guidance for Understanding Environmental Restoration Closure Risks

End-State Site Decisions and Closure Requirements with Qualitative “Presence/Absence” Contamination Data for a Discrete Population of Sampling Units (Targets)

Antelope Lake Davis Gun Earth-Penetrator Targets Example

Introduction

The situation involving the risk of contaminated Targets existing among a population of Targets (discrete sampling units) on a site for which a closure decision must be made, based on the investigation and inspection of a small sample of those Targets for contamination (presence/absence), comes up as a generic class of decision problems. How to state and understand this risk is often confusing and hence, regulatory closure requirements can appear ambiguous or improperly specified, if understood at all. This potential for confusion, lack of precise understanding and muddled communications is the motivation behind this brief guidance paper. The paper is developed in generic terms that are generally applicable to this class of decision problems; but it is illustrated with a specific example: The Nevada Tonopah Test Range Corrective Action Unit CAU 484, NSTec Environmental Restoration project for Davis Gun Earth Penetrator Targets on the Antelope Lake Corrective Action Site.

There are several quantities related to the “*likelihood* of something” floating around in this decision problem structure, which doesn’t make it easy to put forth a simple and concise statement about it that calls forth immediate crystal clear clarity. These quantities crop up in statements expressed as “probabilities”, “chances”, “percents”, “confidence levels”, “confidence bounds”, “risks” and so forth, many of which reflect different aspects of the same set of conditions, and hence there is a high potential for the concepts to get muddled. Therefore, the only practical means of bringing clarity to understanding this decision problem is by formally stating and defining the decision problem structure, precisely identifying relevant quantities involved, illustrating the problem with an explicit example, and then discussing the quantities developed for the example and their interpretation. To get the most out of it requires taking the time to carefully read through the analysis to understand the various aspects point-by-point.

Once this is accomplished, the paper concludes with a summary of concise statements regarding the relevant questions about this particular class of decision problems.

Problem Structure

End-State Decision

A Corrective Action Site (e.g. the Antelope Lake CAS, which is used as an explicit decision example) consists of a **“finite population”** of **“N”** (total number of) geophysical **“Targets”**, which are defined as geophysical anomalies identified by the processing of raw data from a remote measurement system (i.e. combination of metal detectors, aerial surveys, etc.) with geo-coordinate locations of each Target noted for possible return and excavation. The *site* (e.g. *Antelope Lake CAS*) is defined as **“contaminated”** if *any* of the **“N”** Targets contain Earth Penetrator or Depleted Uranium debris (EP/DU) or other “Contaminants of Potential Concern” (hereafter all referred to as **“COPC”** or simply “contaminated”); or, **“clean”** if *none* of the **“N”** Targets contain COPC. The end-state decision for the site is to determine if the site is suitable for closure, e.g. “clean,” or if the site requires remediation due to the presence of contamination in any of the Targets.

The decision is based on the closure requirement that the site is **“clean”** at some specified level of assurance (statistically based confidence or probability statement based on data from a properly designed **random sample** of **“n”** Targets). A generic Conceptual Site Model (CSM)¹ is illustrated in Figure 1 (with simulated data, not the actual data).

A seemingly rational question falsely perceived to be the key question of primary interest:
What is the probability or confidence that none of the entire $N = 755$ Targets are contaminated, in other words the site is completely clean, based on the fact that the given sample of $n = 9$, in this example, had no contaminated Targets?

For reasons developed below, this ill formed question is not operable for a site decision.

Sample (of Sampling Units; e.g. Targets)

A **“sample”** of **“n”** Targets is *randomly selected* from the finite population of **“N”** Targets under consideration for the site. In order to make any statement of a statistical confidence nature from information obtained from the sample, it is essential that the Targets selected for investigation and determination as positive or negative for COPC are selected *at random* and are representative of all Targets that make up the population of Targets for that site. If nonrandom sampling methods are used, the effectiveness of the sampling process and statistical theory behind it is destroyed. The importance of random sampling cannot be over emphasized. If judgment methods are used to select the sample, the statistical basis of the sampling procedure and associated risk estimates are lost.

That said; judgment-based samples, which are based on “biasing factors” justified by outside knowledge (geology, historical use, surface characteristics, etc.) and expert opinion, are often employed for economic reasons. However, when this methodology is employed there is no theoretical basis for developing probabilistic confidence statements without a separate quantitative study of the efficacy of these biasing factors. This paper does not address the issue

¹ Although Antelope Lake is an actual site requiring this decision process, from which $N = 755$ actual Targets were identified; the Target locations and Target status (clean or COPC) in this illustrative example, as well as the $n = 9$ sample locations, were simulated with random number generators.

of judgment sampling. It focuses on developing a clear understanding of the scientific basis for risk and confidence statements when scientifically based sampling protocol is employed. This is the benchmark against which all other approaches should be evaluated.

Investigation and Inspection

Through physical excavation and inspection of each Target in the sample, each specific Target is definitively determined either to be “contaminated” with COPC or “clean.”

Notation: We let X = the number of contaminated Targets found in the sample.

Figure 1: An abbreviated CSM from simulated Target locations, status data, and random sample locations

Decision Rule, Decision Risk and Potential Decision Hazard

Decision Rule: The decision rule and decision criteria for this analysis are defined as follows²:

- Close the site as “clean” if the sample of n Targets contains $X = 0$ contaminated Targets
- Else, remediate the site and perform post-remediation verification sampling

Decision Risk: The decision *risk* is the *probability* of closing a site that contains contaminated Targets. That translates to the probability of obtaining a random sample of size n with $X = 0$ given some non-zero level of the unknown but true contamination that actually exists on the site.

This probability is a function of this unknown true actual contamination level, p (or $p\%$) of the N Targets, and the sample size, n . It is best portrayed with an “Operating Characteristic” (OC)

² Based only on this single “presence/absence” measure of the COPC parameter for site evaluation. Other site variables that enter into the closure decision, such as concentrations of soil contaminants, are not considered here.

Curve for a specified sample size n , which plots the “ β -risk” = $P[X = 0 \mid p, n]^3$ vs $p\%$, the true but unknown percentage of Targets on the site that are actually contaminated. A family of curves can be plotted on the same graph for different sample sizes. (See Figure 2 on page 10 discussed in the Problem Analysis section below.)

Management of the Decision Risk: The idea is to select a sample size n that holds the risk to some acceptable level for some specified level of true actual contamination that may exist, in conjunction with the criteria that the sample cannot contain any contaminated Targets ($X = 0$). Alternatively, if budget constraints dictate a specific sample size, an OC curve characterizes the risks associated with the sample size.

Potential Decision Hazard: The *hazard* is what *level of contamination exposure* potentially remains in Targets left in the ground if a site that is still contaminated is closed. We can address the hazard question by asking: “How contaminated might the site be, with some level of confidence, if our sample of size n had $X = 0$ contaminated Targets?” The answer to this question involves computing a “95% Upper Confidence Bound” (UCB) on the percentage level of contamination, $p\%$.

Problem Analysis

Faulty and Misleading Thinking

Seemingly rational question falsely perceived to be the key question of primary interest:

What is the probability that none of the entire $N = 755$ Targets are contaminated (based on the fact that the given sample of $n = 9$, in this example, had no contaminated Targets)? Can we not make some statement of confidence that the site is 100% clean based on a clean sample from the site?

In short, **the answer is zero confidence!** The problem with this question is the way it is formulated, the logic behind it, and the burden of proof. It is asking: “What is the probability or confidence that $p = 0$?” meaning that, in fact, this sample of $n = 9$ came from a population of $N = 755$ where the true percentage of contaminated Targets is zero. If $p = 0$, for sure, you will get 0 contaminated Targets in any sample of $n = 9$, regardless of how many times you take such a sample. But p is not a random variable; it is a parameter of the population that represents the *actual true fixed but unknown* percentage of contaminated Targets on the ground at the site. We don’t know the value of p , in particular we don’t know if $p = 0$. But, there is nothing random about p ; it is whatever it is, even though it is unknown without 100% inspection of all N Targets. Thus, from the sample we need to make statistical inferences about p with associated assurance levels.

Proper Formulation

What needs to be examined is the probability of obtaining a random sample of size n that is contamination free ($X = 0$), *given* some hypothesized value of p (or equivalently, some number, K , of contaminated Targets) that actually exists at the site. This hypothesized value of p is related

³ $P[X = 0 \mid p, n]$ is read as “the probability that $X = 0$ *given* (“ $\mid$ ”) specific values for p (or range of values as the X-axis) and n ”; e.g. the β -risk probability is a function of p and n .

to the decision risks involved. Values for the two quantities together are typically set at some acceptable level. The “95% convention” might suggest that a value of $p = 5\%$ would be appropriate for consideration as a “critical value” for decision purposes; which of course, by definition is not a “clean site” (e.g. 5% of 755 = 38 contaminated Targets out there), but about which we can estimate some reasonable probabilities. We might then hold the decision risk of closing a site with this contamination level or greater to less than a 5% chance; alternatively stated, we would want the sample size n to give us at least a 95% chance of detecting a contamination level of $p = 5\%$, by finding at least one of the contaminated Targets ($X > 0$) in our sample of size n .

Note that these “percents” are *two different parameters*. This is a source of potential confusion. For example, we could have $p = 10\%$, or any other level of contamination, with the associated risk of closing such a site held at 5% (or some other level deemed acceptable). Lacking any other guidance (regulatory, management, risk assessment, or otherwise) a “95%/5% convention” simply sets all of these “risk” parameters at a “5%” level and “confidence” parameters at “95%”.

The answer to this more properly formulated question can be addressed from the theoretical sampling distribution associated with the sampling method and parameters of the site: i.e. Binomial Distribution ($N = \infty$, or approximate for large N) or Hypergeometric Distribution (exact for a given N). At this point we now need to more formally define the quantities, parameters and probabilities involved in this analysis.

Problem Parameters

The following are the variables and parameters that define the site, sampling plan, and decision process (with the Antelope Lake example values in parentheses). All discussion and explanations in this analysis will refer to these quantities.

N (= 755)	Total number of Targets at the site (755 in this example). This is the size of the site “population” of Targets from which a sample is drawn to make a site decision.
K (= 38)	The actual, but <i>unknown</i> , number of Targets that are contaminated . $K = 38$ in this example, represents approximately a 5% contamination level (e.g. 5% of 755 = 37.75). We only “know” this true property of the population in this example problem because it is a simulated contamination level, which is illustrated in the Figure 1 CSM as 38 randomly located red points among the total of 755 Target points. In application, K is a fixed true number, but it is unknown without investigating and inspecting 100% of the Targets.
n (= 9)	The “ sample size ” (number investigated) drawn from the total of N Targets. In the Antelope Lake example, this sample size was selected based on budget considerations — not to control risk level for a specified contamination level. Part of the objectives of this analysis is to characterize the implications of this small sample size.
X (x = 0)	The number of Targets in the sample of n Targets that are “positive” for contamination (COPC). Capital “X” is the random variable; small “x” refers to a specific sample finding, e.g. a specific value of X for a specific sample.

p (or p%)	The unknown but actual true proportion (or equivalent percentage) of N Targets that are contaminated: $p = K/N$ (x100% for p%).
P[X = 0 p*]	Probability that no contaminated Targets are found (implicitly in a random sample of size n, if not indicated directly), <i>given</i> (“ ”) that p = p* , some specified value for the unknown proportion p. Probabilities are numbers between 0 and 1 (without confusion, “chance” expressed in % is often used in an equivalent sense, or interchangeably, as probability expressed in %).
P[X > 0 p*]	Probability that at least one contaminated Target is found in a random sample of size n, <i>given</i> that p = p* . Clearly, no site can be consider “clean” if any contaminated Targets are found in the sample. The issue is about the likelihood (this probability) that there exists contaminated Targets, even though none are found in a random sample of size n. Thus, we can speak of the probability that $X > 0$ even though for a specific sample $x = 0$ (i.e. another sample might have something greater than zero).
Burden of Proof	Given the known history of such weapon sites and their usage, it is presumed (H_0) that <i>the site is contaminated</i> and the burden of proof is on the site owner to demonstrate that the site is clean via a proper sampling plan and inspection, and/or remediation. Without this presumption, the site owner could argue for a low-power sample size of $n = 2$, say, under the assumption that the site is clean, and claim that since no Targets were found, the assumption holds because it was not “disproved” and thus no further investigation is called for. This approach would ignore the risk of closing a contaminated site.
1 - α and Upper Confidence Bound (UCB or UB)	Expressed as a probability or percent, 1 - α is the “ confidence level ” of a statement about p , the unknown but actual true proportion of Targets contaminated. Associated with this confidence level is typically an “ Upper Confidence Bound ” (UCB or simply UB) that is a high-end estimate of the contamination level with the stated level of confidence that it isn’t any higher. Convention in a regulatory framework is to use the industry standard of “95% confidence level.”
α-risk	<p>Owner risk: Site-owner risk (risk is a probability) of declaring a site “contaminated” (unfit for closure without performing further remediation) when in fact the site is clean. Convention in a regulatory framework is to use the industry standard critical significance level of “5%” or “0.05” α-risk level, unless otherwise specified in regulatory law. The site owner wants to see this risk small due to the unnecessary cost of further investigation and remediation of an already clean site. Lowering α-risk, however, without changing sample size, increases β-risk.</p> <p>In industrial lot-acceptance sampling, α-risk is known as the “<i>producer risk</i>” (of having a “good” lot of material rejected by the customer) and, in lot-acceptance sampling designs it is associated with the “<i>Acceptable Quality Level</i>” or <i>AQL</i>, which defines what is meant by “good”. $p = AQL$ is a specific value of p associated with an α-level, i.e. 5%, chance of rejecting the lot, even</p>

though the lot is still defined as “clean” in terms of allowable percent defective items in the lot, which is set by agreement between producer and customer/consumer.

 β -risk

Environment risk: Risk to the environment or public or eventual site user (again, risk is a probability) of declaring a site “clean” (fit for closure of restoration efforts and available for other use) when in fact the site may actually be contaminated. The public and responsible environmental agency regulators would like the sampling to be large enough to hold β -risk at an acceptably low level (β -risk is directly affected by sample size, β decreasing with increasing n). A “95% convention” would point to a β -risk of 5%. β -risk is what is plotted on the Y-axis of an “OC Curve”.

In industrial lot-acceptance sampling β -risk is known as the “*consumer risk*” (of accepting a defective lot of material) and, in lot acceptance sampling designs it is associated with the “*Lot Tolerance Percent Defective*” or *LTPD* ($p = \text{LTPD}$ is a specific value of p associated with a $\beta\%$ chance of acceptance, in terms of the maximum tolerable percent defective; $\text{LTPD} > \text{AQL}$).

 $1 - \beta$

The “**power**” (probability) of detecting a contaminated site from the sample; alternatively, the probability that at least one contaminated Target ($X > 0$) occurs in the sample for a given level of contamination p . **$1 - \beta$** is what is plotted on the Y-axis of a Power Curve (the complement of OC Curves).

p-value

In a statistical test of hypothesis, such as “the site is contaminated” (e.g. the “null” or baseline assumption or hypothesis of $H_0: p \geq 5\%$, say) vs “the site is clean” ($H_a: p < 5\%$), the “**p-value**” is the likelihood (probability) that the sample results were due to the null baseline assumed conditions (e.g. site contaminated at some defined level $p^* = 5\%$, in this example). It is a measure of the plausibility of the null hypothesis (that the site is contaminated) and this baseline assumption should remain operative (with the site owner holding the burden of proof) unless the p-value is sufficiently small. That assumption is rejected and the alternative conclusion (site clean) demonstrated as statistically significant only when the p-value is sufficiently unlikely, typically $p < \alpha$, the decision criteria conventionally set at the critical significance level of 0.05 or 5%.

Crucial Note: The “p” in “p-value” is not the same as the “p” that means proportion of Targets contaminated. They represent completely different things, which should be clear from the context of their use.

Binomial Sampling Distribution

The **Binomial Distribution** is the theoretically appropriate sampling distribution from which to determine probabilities associated with sampling from an *infinite population size* ($N = \infty$); in a practical sense it means N is large enough that probabilities from the Binomial are reasonably close approximations to the exact probabilities (for large N , if not in the hundreds, at least $N > 10 \times n$).

Hypergeometric Sampling

The **Hypergeometric Distribution** is the theoretically appropriate sampling distribution from which to determine probabilities associated with sampling

Distribution	from a <i>finite</i> population size (N being a fixed number); in a practical sense it means exact probabilities, rather than approximate, are obtained for a given population size N.
“c = 0” Lot Acceptance Sampling Plans	<p>A class of lot acceptance sampling plans for which the critical number of allowable “non-conforming” (contaminated or defective) sampling units (Targets) in the sample is <i>zero</i> (e.g. $\mathbf{X} = \mathbf{0}$, the critical “acceptance number” for the sampling plan of $c = 0$). This acceptance number can be forced to $c = 0$ in sampling plan development by setting the AQL = 0%. Acceptance sampling plans exist that allow some non-conforming items to occur in the sample ($c > 0$), which is the only way to adjust both α-risk and β-risk; but these are not appropriate plans for this environmental site end-state decision situation.</p> <p>All discussion in the analysis presumes that <i>no</i> contaminated Targets are acceptable in the sample ($c = 0$); that is, any occurrence of a contaminated Target in the sample is inconsistent with declaring the site “clean,” since it is demonstrated by the sample that at least one Target was contaminated with COPC. This is the basis of the site end-state decision rule used in this analysis. It <i>does not mean</i>, obviously, the reverse; that if no contaminated Targets are found in the sample, then one can conclude that the site is 100% clean.</p>

Statistical Approaches to Address the Risk and Hazard Questions

a) Hazard Question: “How contaminated might the site be, with some level of confidence, if we close the site based on our sample of size n that has $X = 0$ contaminated Targets?”

b) Risk Question: “What is the probability of closing a contaminated site, if we close the site based on our sample of size n that has $X = 0$ contaminated Targets?”

The **hazard** and **risk** issues can be approached and quantified from two different angles:

- a) Hazard: Estimation** of a 95% Upper Confidence Bound (UCB or UB) on p
Interpretation: If p , the true proportion of Targets, was actually as high as this estimated 95% UCB, and repeated random samples of size n ($n = 9$ in our example) were taken from the N Targets ($N = 755$), then 19 out of 20 (95%) of those samples would contain at least one contaminated Target. There would only be 1 out of 20 (a 5% chance) that the sample contained no contaminated Targets.
 Or, equivalently, the probability that $X > 0$, given that $p = \text{“95% UCB”}$ is 0.95:

$$P[X > 0 \mid p = \text{UCB}] = 0.95$$
- b) Risk: Testing** whether or not there is statistically significant evidence from the sample that p , the true but unknown proportion of contaminated Targets, is below some limiting threshold, say p^* , with the accompanying risk-probability that we would close the site based on a sample containing $X = 0$ contaminated Targets, when in fact $p \geq p^*$.
 Or, equivalently, the probability that $X = 0$, given that $p = p^*$:

$$P[X = 0 \mid p = p^*] = \beta\text{-risk of closing a site with } p^*\% \text{ contamination}$$
 (for sample of size n)

Interpretation: The proportion p is assumed to be equal to p^* (that is $H_0: p \geq p^*$, meaning the site is contaminated at some level at least as high as p^* %) and then the probability of obtaining a sample of the given size n ($n = 9$ in our example) with $X = 0$ (no contaminated Targets) is determined. This probability is known as the “*attained level of statistical significance*” and is referred to as the “**p-value**”. Unless the p-value is “*small*,” meaning a low likelihood that $p \geq p^*$, one continues to assume that p is at least as large as p^* and there is no statistically significant evidence from the sample that the site is clean, even though there were no contaminated Targets in the sample. The p-value is thus a probability number that holds the evidence *against* the default assumption or “null hypothesis”. The strength of the evidence “against” H_0 (site contaminated) is indicated by how small the p-value is; e.g. how unlikely it would be to find a random sample with $X = 0$ contaminated Targets if, indeed, the site was actually contaminated at the level specified in H_0 . If it is too unlikely ($p\text{-value} < \alpha$), we conclude that the p-value is small because the site is actually clean (e.g. accepting the alternative $H_a: p < p^*$) in a statistically significant sense.

For the $c = 0$ sampling situation being examined in this paper, when the decision is made (following the decision rule) to close the site based on $X = 0$ contaminated sample Targets, it turns out that this p-value ends up also being the probability of falsely declaring the site “clean” and closing a contaminated site, which is known as the β -risk.

“How ‘*small*’ does the p-value have to be before one can reject the presumed condition of a contaminated site and conclude that the site has been statistically demonstrated as “clean” by the quantified definition of $p < p^*$?” The answer is: less than the “*critical significance level*” referred to as α , or α -risk, conventionally set at $\alpha = 0.05$ or 5%.

β -risk: For this particular $X = 0$ sampling situation it turns out that the p-value is also the same as β , the β -risk level, which is the probability of accepting a site as clean.

Antelope Lake Sample Size ($n = 9$) and Decision Risk

Decision Risk

One OC curve in Figure 2 (the curves are based on the Hypergeometric Sampling Distribution) displays the risk associated with the existing Antelope Lake sample size (**$n = 9$, red curve**) over a potential range of $p = 0$ to 30% contamination level. To understand what the curve represents, it is very important to keep the decision rule in mind:

The decision rule is to close the site as “clean” if our sample of $n = 9$ Targets is contamination free ($X = 0$), regardless of what the actual level of contamination (p) is, since it is unknown.

We interpret the curve in the following way: With a sample of size $n = 9$, the *risk* of closing a site that is as much as $p = 5\%$ contaminated is $\beta = 0.6287$. That is, the probability of drawing a random sample of 9 Targets with no contaminated Targets ($X = 0$) among the 9, from the population of $N = 755$ Targets having 38 contaminated Targets ($p = 5\%$) is 0.6287, or about a 63% chance. This means there is a very high 63% chance that a site with as much as 5% contamination is being declared as “clean” and closed without further investigation or

remediation. Almost 2 out of 3 such samples repeatedly taken at random would have no contaminated targets and hence incorrectly call for the site to be closed.

$$P[X = 0 \mid p=5\%, n=9] = 0.6287 \text{ (about 63\% chance)}$$

Figure 2: Operating Characteristic (OC) Curves for the Antelope Lake CAS with $N = 755$ Targets

The higher the actual level of contamination (p) at the site, the greater likelihood of obtaining at least one contaminated Target in the sample ($X > 0$), and thus the lower the risk of closing the site due to a sample with $X = 0$ Targets. In fact, at the 95% Upper Confidence Bound on p (28.1625%) for a sample of $n = 9$ and $X = 0$, the risk is only 5%. That means 19 out of 20 repeated random samples of size $n = 9$ would contain at least one contaminated Target and we would be 95% confident that we would properly close a site with that level of contamination, base on a sample of $n = 9$ (with still a $\beta = 5\%$ risk of obtaining a sample with $X = 0$ contamination).

Going the other direction, as the curve indicates, the lower the actual site contamination level, the harder it is to detect contaminated Targets with a sample of only $n = 9$, and thus the risk of closing a contaminated site, albeit containing fewer contaminated Targets, goes up and our confidence in correctly closing a site goes down; that is $P[X > 0 \mid p, n = 9]$ decreases with decreasing p . Without keeping the decision rule in mind, a cursory glance at the graph may make it seem “counter-intuitive,” looking like an intuitive contradiction that the cleaner a site is, the greater the risk of closing a contaminated site; when what is going on is that the cleaner a site is, the harder it is to detect contamination at a given sample size.

In fact, we can now see that in the limit, we have zero confidence (maximum risk) of closing a site with some level of contamination as that level p approaches 0 (100% clean site). This can more easily be seen in Table 1 on page 12, which has these Figure 2 OC values computed, along with others, for several values of p . So, under this sample size of $n = 9$, from the eighth column (exact Hypergeometric distribution), the risk of closing a site with only one contaminated Target ($p\% = 1/755 = 0.1325\%$) is 98.8%. Or, stated as its complement: We have only 1.2% confidence level

(ninth column) that the contamination level is as low as one Target somewhere in the site, with a sample size of $n = 9$ and $X = 0$. And, we have 0% confidence that the site is perfectly clean (no contaminated Targets on the site). This is the reason that the earlier “**Seemingly rational question falsely perceived to be the key question of primary interest**” is not an operable decision criteria.

Sampling Design

The sampling design question is: “What sample size would we need to reduce the risk of closing a $p = 5\%$ contaminated site, say, from $\beta = 63\%$ (for $n = 9$) to $\beta = 5\%$?” Statistical software produces this sample size and generates its OC curve, as seen for the **$n = 57$ blue curve** (Figure 2), that goes through that $p = 5\%$ with $\beta = 5\%$ point. If this $p = 5\%$ contamination level/ $\beta = 5\%$ risk level offers a comfortable decision risk structure, we can see from the last column in the Table 1 that from a sample size of $n = 57$ with no contamination ($X = 0$), we would estimate the potential site hazard from closing it to be the 95% UCB on p of 4.9% (it doesn’t come out exactly at 5% due to the discrete nature of the sample size n , which is always rounded up to the higher integer to provide no worse than 5% risk).

If the $p = 5\%$ level of site contamination is, in management judgment, too liberal (allowing for too high of a site contamination level), the sample sizes (and costs) go up drastically to insure lower contamination levels at the same $\beta = 5\%$ risk level: $n = 247$ for $p = 1\%$; $n = 718$ to catch a single contaminated Target (with 5% risk of not catching it); and $n = 755$ (100% sampling) to ensure $p = 0\%$ contamination.

Hazard

The *hazard* of closing the site based on the sample of $n = 9$ with $X = 0$ contaminated Targets, is a 95% chance that the site could have a contamination level as high as 28.16% (Table 1, 7th column, row 3). That is; it could contain as many as 213 contaminated Targets (28.16% of 755). Note that the hazard, as estimated by a 95% Upper Confidence Bound on p , is based only on the sample size and $X = 0$ contaminated Targets in the sample, and (in the Hypergeometric model) $N = 755$, the population size. Hazards for other sample sizes are shown in the last column.

To help understand the effect of sample size on the precision (tightness) of the Hazard estimate, Figure 3 compares the existing **$n = 9$** UCB estimate of 28.16% (which has a β -risk = 62.87% chance of closing a potentially contaminated site), with the sample size **$n = 57$** required to achieve a β -risk of 5% and resulting in an UCB of 4.93% that is just below the H_0 : $p^* = 5\%$ with 95% confidence. It is clear that the sample of $n = 57$ and $X = 0$ demonstrates the site is “clean” ($p < 5\%$) with statistical significance at the 95% confidence level; whereas the sample of $n = 9$ and $X = 0$ does not have the power to demonstrate that.

Figure 3: Illustration of Sample Size on Precision of Hazard Estimate with 95% UCB

Table 1: Characteristic Probabilities, Risks and Confidence Levels for the Antelope Lake Example

		Antelope L. Example Case: Existing Sample Size n = 9, with x = 0 (no contaminated Targets in sample)							Sample Plan (95% Convention)	
		Binomial (p*, n=9)				Hypergeometric (p*, n=9, N=755)			Hypergeometric (p*, n, N = 755)	
		95% UCB on p	P[X=0 p=p*, n=9]		P[X>0 p*]	95% UCB on p	P[X=0 p*]	P[X>0 p*]	n (for β = 5% at p=p*)	95% UCB on
p* %	K = pxN (= px755)	Hazard	p-value	β-risk (%)	Confidence	UCB	p-value & β	Confidence	sample size required	Hazard
contamination criteria for "clean" site decision risk Note		given: x = 0 n = 9 **	Ho: p ≥ p* (contaminated) Ha: p < p* (clean)	Risk of closing a contaminated site (e.g. when p ≥ p*)	(confidence level with UCB = p*)	given: x = 0 n = 9, N = 755 ***	(p-value) (β-risk) (x100% for percent)	(confidence level with UCB = p*)	for p ≤ p* (LTPD) with β = 5% x = 0 (AQL = 0%)	given: x = 0 n, N = 755 ***
30%	1	~227	28.3129%	0.0404	4.04%	95.96%	28.1625%	0.0395	96.05%	
28.3129%	2	~214	28.3129%	0.0500	5.00%	95.00%	28.1625%	0.0491	95.09%	
28.1625%	3	~213	28.3129%	0.0510	5.10%	94.90%	28.1625%	0.0500	95.00%	28.1625%
5%	4	~38	28.3129%	0.6302	63.02%	36.98%	28.1625%	0.6287	37.13%	4.9275%
1%	5	~8	28.3129%	0.9135	91.35%	8.65%	28.1625%	0.9131	8.69%	0.9961%
0.1325%	6	1	28.3129%	0.9881	98.81%	1.19%	28.1625%	0.9881	1.19%	0.1316%
0%	7	0	28.3129%	1.0000	100.00%	0.00%	28.1625%	1.0000	0.00%	0.0000%

Notes: p* % Specific values under consideration to examine relationships to various probabilities

A specific p^* = "LTPD" and an associated β (with AQL = 0% for "X=0 acceptance") must be chosen to produce a sampling plan

The last column gives the sampling plan for p^* and $\beta = 5\%$

(note that $n = 9$ is an adequate sample size only if one is willing to accept a $\beta = 5\%$ chance of closing a site that is $p = 28\%+$ contaminated)

— further, with $n = 9$ one can only be **1.2% confident** that there is a maximum of $K = 1$ contaminated Targets on the site of $N = 755$ Targets

(the $K = 1$ row shows that a sample of $n = 718$ is required in order to have only a $\beta = 5\%$ chance of closing a site that has just **one contaminated Target**)

(the $p^* = 5\%$ row shows that a sample of $n = 57$ is required to have only a $\beta = 5\%$ chance of closing a site that is $p = 5\%$ contaminated)

** Hazard Estimation: 95% Upper Confidence Bound depends only on $n=9$ and $x=0$ for Binomial

*** Hazard Estimation: 95% Upper Confidence Bound depends on n , $x=0$, and $N=755$ for Hypergeometric (95% UCB = LTPD for $\beta = 5\%$)

1. A higher level of contamination than 95% UCB to illustrate the effect on probabilities

2. 95% UCB on p (Binomial large N approximation) (Compare Binomial numbers with Hypergeometric)

3. 95% UCB on p (Hypergeometric exact for given $N = 755$)

4. "95% convention" (CSM is based on this level of possible contamination: $p = 5\%$ or 38 Targets)

5. A tighter criteria for contamination level than conventional 5%

6. Only 1 contaminated Target among the $N = 755$ Targets

7. No contaminated Targets (fully clean site for all $N = 755$ Targets) - "Key and misleading question perceived to be of primary interest"

Finally, both the Binomial Distribution and Hypergeometric Distributions are shown in the table for comparison. With such a large population size ($N = 755$) there is only a slight difference between the two in terms of the probabilities and confidence bounds derived. For small populations, the differences can be quite large, especially when $N < 50$ or $N > 10 \times n$. For these situations it is best to use the correct finite-population sampling distribution, Hypergeometric, to obtain exact estimates.

Table 1 also illustrates that, for this particular sampling situation and decision rule, which requires $X = 0$ for an acceptable closure decision sample, the p-value (plausibility of the site being contaminated, e.g. $p \geq p^*$) and β (the risk of closing a contaminated site) are both equivalent to the probability of obtaining a sample with no contamination ($X = 0$) for the given sample size n and true but unknown level of contamination p : $P[X = 0 | p, n]$. All but the last two columns of the table reflect the existing $n = 9$ sample size, with different β 's under different conditions for p ; whereas the last two columns reflect different sample sizes, n , for a specified $\beta = 5\%$.

Summary and Conclusion

The proper and concise ways to express the relevant aspects of this problem are as follows:

Problem Decision Statement

A site with N total Targets is to be closed if it can be demonstrated with a reasonable degree of confidence that the site Targets are clean of COPC contamination.

The decision rule is:

Close the site if a random sample of n Targets contain no contamination

Remediate the site if the sample contains one or more contaminated Targets

The acceptable level of decision risk for incorrectly closing a contaminated site is specified as:

$\beta = \beta^*$ (e.g. 5% or other specified decision risk level)

at $p = p^*$ (e.g. 5% or other specified contamination level)

Sampling Plan: Based on the site population size, N , and β^* at p^* , with no contamination allowed in the sample ($X = 0$) determine the sample size n for a random sample that most closely meets these decision and site criteria. Use the data from sample to make the site closure decision ($x = 0$: close site; or $x > 0$: remediate site).

For a Given Sample Size (n) and Population Size (N):

What is the *Risk* of closing a contaminated site, when the sample contains no contaminated Targets?

The **Risk** of closing a contaminated site is the probability of obtaining a sample of size n with no contaminated Targets ($X=0$) for a specified level of contamination p :

Risk of closing a contaminated site =

$\beta = P[X = 0 | p, n, N]$ computed from the Hypergeometric Sampling Distribution

A plot of this probability versus contamination level p is known as an OC Curve for a given n .

What is the *Hazard* a site will have with 95% Confidence, in terms of potential level of contamination remaining, if closing a contaminated site when the sample contains no contaminated Targets?

The **Hazard** is the potential level of contamination remaining and is estimated with a 95% Upper Confidence Bound on the contamination level p , based on a sample of size n with no contaminated Targets.

Hazard level p with 95% confidence =
 95% UCB on p computed from the Hypergeometric Sampling Distribution

What is the *Confidence* that the *Hazard* a site will have is no greater than p , if closing a contaminated site when the sample contains no contaminated Targets?

The **Confidence Level** that the **Hazard** contamination level is no greater than p , based on a sample of size n with no contaminated Targets, is estimated from the probability of obtaining at least one contaminated Target in the sample of size n with the UCB set at p :

Confidence for a specified Hazard contamination level of p =
 $P[X > 0 \mid \text{UCB} = p, n, N]$ computed from the Hypergeometric Sampling Distribution

What is the Confidence that no contaminated Targets are present on the site, when the sample contains no contaminated Targets?

Zero confidence

What would it take to have 95% Confidence that no contaminated Targets are present on the site, when the sample contains no contaminated Targets?

100% sampling and investigation of all N Targets

Are the probability statements discussed in this guidance paper valid if a non-random biased sample is taken? Can such probability statements be made if there is no quantifiable data about the nature of the biasing? Is it appropriate to “sort of assume” the biased sample behaves like a random sample in order to use and report these probabilities and other statistical inferences for site closure?

No

No

No (except as a benchmark)

What do we do if our budget doesn't allow the sample sizes required in random sampling, and we have to use biased sampling?

- a) Lower expectations for a clean site (risks and contamination levels)
- b) Do an independent experimentally designed validation study of the measurement technology and biasing factors; use results for more sophisticated stratified random sampling in the future
- c) Take a small *random* sample (to allowable budget level) and make proper statistical inferences
- d) Report the “random sample” statements as a benchmark with technically defensible (not just opinion) justification that the bias would be no worse

APPENDIX K

GEOPHYSICS REPORTS

APPENDIX K-1

Geophysical Target Detection Tonopah Test Range Antelope Lake North, Brownes, NEDS, and Pedro Lakes Tonopah, Nevada

APPENDIX K-2

Geophysical Surveys Tonopah Test Range Tonopah, Nevada

APPENDIX K-1

GEOPHYSICS REPORT

**Geophysical Target Detection
Tonopah Test Range
Antelope Lake North, Brownes, NEDS, and Pedro Lakes
Tonopah, Nevada**

**FINAL REPORT
GEOPHYSICAL TARGET DETECTION
TONOPAH TEST RANGE
ANTELOPE LAKE NORTH, BROWNES, NEDS
AND PEDRO LAKES
TONOPAH, NEVADA**

Project Number 2028

**Prepared For:
NATIONAL SECURITIES TECHNOLOGIES, LLC.**

**Prepared by:
ZAPATAENGINEERING, P.A. Blackhawk Division
301 Commercial Road, Suite B
Golden, CO 80401
Office: (303) 278-8700**

June 2007

**FINAL REPORT
GEOPHYSICAL TARGET DETECTION
TONOPAH TEST RANGE
ANTELOPE LAKE NORTH, BROWNES, NEDS, AND PEDRO LAKES
TONOPAH, NEVADA**

ZAPATAENGINEERING P.A., Blackhawk Division
Project Number: 2028

Prepared For:

NATIONAL SECURITIES TECHNOLOGIES, LLC
Nevada Test Site
NTS 306
Mercury, Nevada 89023
702-295-6711

Prepared By:

ZAPATAENGINEERING P.A., Blackhawk Division
301 Commercial Road, Suite B
Golden, Colorado 80401
303-278-8700 • Fax 303-278-0789

June 2007

TABLE OF CONTENTS

1.0	INTRODUCTION.....	1-1
2.0	SITE DESCRIPTION.....	2-1
2.1	GENERAL	2-1
3.0	DATA ACQUISITION.....	3-1
3.1.1	Grid System	3-1
3.1.2	Data Collection	3-1
3.1.3	Data Gaps.....	3-1
4.0	DATA PROCESSING	4-1
4.1	DATA PROCESSING STEPS	4-1
4.2	ANOMALY SELECTION AND MODELING STEPS	4-1
4.2.1	Size Calculation of Anomalies.....	4-2
4.2.1.1	Size Calculation of Anomalies Application Notes	4-3
4.2.2	Depth Calculation of Anomalies.....	4-4
4.2.2.1	Depth Calculation of Anomalies Application Notes	4-5
5.0	INTERPRETATION AND RESULTS	5-1
5.1	ANTELOPE LAKE NORTH.....	5-1
5.2	BROWNES LAKE.....	5-2
5.3	NEDS LAKE	5-4
5.4	PEDRO LAKE.....	5-6
6.0	SUMMARY AND CONCLUSIONS.....	6-1
7.0	CERTIFICATION AND DISCLAIMER	7-1

LIST OF TABLES

Table 4-1	Size Calculation Steps.....	4-3
Table 4-2	Size Calculation Steps.....	4-4
Table 5-1	Antelope Lake North Depleted Uranium Ring Results	5-1
Table 5-2	Antelope Lake North Penetrator Results	5-1
Table 5-3	Antelope Lake North Potential Disposal Pit Results	5-2
Table 5-4	Antelope Lake North Potential Bomblets Results	5-2
Table 5-5	Brownes Lake Depleted Uranium Ring Results	5-3
Table 5-6	Brownes Lake Penetrator Results	5-3
Table 5-7	Brownes Lake Potential Disposal Pit Results.....	5-3
Table 5-8	Brownes Lake Potential Bomblets Results	5-4
Table 5-9	NEDS Lake Depleted Uranium Ring Results.....	5-4
Table 5-10	NEDS Penetrator Results	5-5
Table 5-11	NEDS Lake Potential Disposal Pit Results	5-5
Table 5-12	NEDS Lake Potential Bomblets Results	5-5
Table 5-13	Pedro Lake Depleted Uranium Ring Results.....	5-6
Table 5-14	Pedro Lake Penetrator Results.....	5-6
Table 5-15	Pedro Lake Potential Disposal Pit Results	5-6
Table 5-16	Pedro Lake Potential Bomblets Results	5-7

ACRONYMS AND ABBREVIATIONS

DoD	United States Department of Defense
EM	Electromagnetic
GPO	Geophysical Prove Out
GPS	Global Positioning System
mV	MilliVolts
MKII	EM61-MKII
Oasis	Geosoft Oasis montaj®
OE	Ordnance and Explosives
RTK	Real Time Kinematic
SOW	Statement of Work
TTR	Tonopah Test Range
WGS 84	World Geodetic System 1984
Zapata	ZAPATAENGINEERING P.A., Blackhawk Division

1.0 INTRODUCTION

The following report details the procedures and results of an electromagnetic (EM) anomaly identification and selection conducted on geophysical data from the Tonopah Test Range (TTR) near Tonopah, Nevada. The areas of interest include the Antelope Lake North, Brownes Lake, NEDS Lake, and Pedro Lake sites. ZAPATAENGINEERING P.A., Blackhawk Division (Zapata) personnel utilized EM61 MKII (MKII) data in grid (*.grd) format provided to Zapata by National Securities Technologies, LLC which was collected over the three lakes in an investigation performed previously by Bechtel. (It should be noted that Antelope Lake North is referred in the report “*Final Report, Geophysical Surveys, Tonopah Test Range, Tonopah, Nevada*” issued June 2007 as Pre-Acquired Antelope Lake Data.)

The objective of the anomaly selection was to detect subsurface metal that may consist of ordnance and explosives (OE) whose size is consistent with bomblets, penetrators, depleted uranium rings, and possible disposal pits identified at the Antelope Lake Site by Zapata in 2006. The data was processed and filtered (in respect to anomaly selection only) using the same techniques employed for anomaly selection of South Antelope Lake to identify anomalies that have similar geophysical signatures to established Geophysical Prove Out (GPO) seeded items. In addition, the selected anomalies were evaluated to estimate their approximate size and depth. The geophysical processing for anomaly selection was in accordance with parameters delineated under Section 2.6.1 of the Statement of Work (SOW), Exhibit B.

To meet this objective, Zapata implemented the following specific tasks:

- Using EM61-MKII data, which had been processed and filtered by Bechtel and delivered to Zapata in a gridded format for top and bottom coils at 660 microseconds, identify geophysical EM anomalies over the four survey areas (North Antelope, Brownes, NEDS, and Pedro Lakes).
- Implement target selections on said data.
- Using subroutines within Geosoft Oasis Montaj® (Oasis) UX-Detect software, calculate sizes and depths of the metal objects suspected to be causing the anomalies, which were selected as anomalies within EM data.

2.0 SITE DESCRIPTION

2.1 GENERAL

The TTR is 200 miles northwest of Las Vegas, Nevada and 40 miles southeast of Tonopah, Nevada. It is operated by the United States Department of Defense (DoD) with management and site access the responsibility of Sandia National Laboratory.

The climate at the TTR is high desert with temperatures ranging from highs in the 100's in the summer to lows down to -20's in the winter. Average rainfall in the valley is only four inches per year with 12 inches per year in the nearby mountains. Dust storms are common in the spring months when winds are high (15 miles per hour). Standing water may be present on the lakebeds until mid-spring.

The site conditions for the four areas covered in this report (North Antelope Lake, Brownes Lake, NEDS Lake, and Pedro Lake) consist of alluvial playas. The playas consist of a thick section of fine-grained unconsolidated sediments. Surface conditions are flat with no vegetation.

3.0 DATA ACQUISITION

This data was collected and processed by Bechtel and supplied to Zapata by National Securities Technologies, LLC in an Oasis gridded format (*.grd) for the top and bottom coils of the EM61 MKII at a 660 microseconds time gate rather than raw data files. These files were georeferenced using UTM Zone 11 north meters WGS84 in order to map seamlessly with data collected by Zapata. No further processing, only target selection, was done in this area. It is assumed that the data collection, processing, and filtering performed by Bechtel were correct.

3.1.1 Grid System

No grid system was used for this area.

3.1.2 Data Collection

Once again, data for this area were provided to Zapata in the form of processed Oasis *.grd files. No further processing was done by Zapata.

3.1.3 Data Gaps

All gaps in the data were due to methods used by Bechtel. Zapata collected within gaps in the southern portion of the North Antelope lake site. The results of this surveying are contained in the report “*Final Report, Geophysical Surveys, Tonopah Test Range, Tonopah, Nevada*”. No data gaps were filled by Zapata for the other three sites.

4.0 DATA PROCESSING

Zapata performed geophysical processing of additional data provided by National Securities Technologies, LLC delineated under Section 2.6.1 of the SOW, Exhibit B. The processing, completed by Zapata, included strictly the identification of EM anomalies that are caused by potential OE, and the estimation of both the depth of burial and size of said anomalies causing the response, and employed the same techniques that were utilized at Antelope Lake. This included identifying targets that have a similar geophysical signature to the GPO's seeded items consisting of depleted uranium rings, baseball-sized sub-munition bomblets, penetrators and potential disposal pits. GPO results are located in "*Final Report, Geophysical Surveys, Tonopah Test Range, Tonopah, Nevada*" issued June 2007. The GX functions within Oasis used to estimate the approximate size and depth of the targets are described below.

Data were processed, interpreted, analyzed, and displayed in this report using Oasis' UX-Detect.

4.1 DATA PROCESSING STEPS

Oasis grid files (*.grd) of the lakes were provided to Zapata by National Securities Technologies, LLC. These files were georeferenced using UTM Zone 11 north meters (WGS 84) in order to map seamlessly with data collected by Zapata. Since Bechtel collected, processed, filtered, and gridded the data, Zapata assumed all data provided has been processed correctly and no further processing was required (i.e. filters, global positioning system [GPS] editing, etc.).

4.2 ANOMALY SELECTION AND MODELING STEPS

The following steps were used for the MKII for anomaly selection. Thresholds (based on the GPO report) were employed.

- Supplied grids were georeferenced onto maps with coordinates, title blocks, north arrows, scales, and colorbars and the grids were set to a threshold of 10 milliVolts (mV) for display purposes.
- EM anomalies were selected on the "Bottom Coil" channel using a peak-picking algorithm (Blakely) in Oasis. The target-picking threshold was determined to be 10 mV based on the mV value required to detect the seeded bomblets at depths less than six inches (0.15 meters) and penetrator at depths less than seven feet (2.2 meters). These parameters were based on the response of UXO seed items in the Zapata GPO performed at the TTR in 2006.

- Targets identified as possible depleted uranium rings were selected by selecting anomalies with thresholds greater than 50 mV and diameters greater than one meter.
- Penetrator rounds were identified within the site by examining the data with a low threshold (10 mV) and selecting anomalies with a diameter of five meters or greater.
- Potential disposal pits were identified within the site. A low threshold (10 mV) was again used and anomalies that had geometric shapes were selected. The geometric shapes indicated that the source of these anomalies were most likely manmade. Additionally, densely anomalous areas of concern were also selected as potential disposal pits.
- Finally, bomblets were identified. A threshold between 10 mV and 50 mV was employed for anomaly selection.
- A visual verification of anomaly picks was conducted in Oasis. An output of the final anomalies (in *.xls) format was generated using WGS 84 UTM Zone 11 north (meters) coordinates, which includes the anomaly location, peak mV value, and a unique ID number.
- The anomaly targets identified within the Antelope Lake North, Brownes Lake, NEDS Lake, and Pedro Lake surveys were then modeled to estimate the depth of burial and overall size of the items causing the anomalies. The modeling routines, each within the Oasis UX-Detect software, were used to estimate these parameters. Both routines, Calculate Target Size and Calculate Target Depth, give qualitative data due to assumptions made in the modeling routines. The depth function estimates the depth of an assumed spherical object and the size function determines the distance from the peak value to the first inflection point and assumes that distance is half the target size.
- Processed data were then outputted as Oasis or *.XYZ formatted files. (For use with the Geosoft Oasis montaj® Viewer)

4.2.1 Size Calculation of Anomalies

To calculate the size of the targets, an Oasis GX called UXPEAKSZ GX was used. This function employs the following steps in Table 4-1.

TABLE 4-1 SIZE CALCULATION STEPS

Step	Description
Grid to define target sizes	Name of the grid to define target sizes. Script Parameter: UXPEAKSZ.GRID
Target list	The Name of the "group" line to save the target data. This value is the same as the most recently specified target list from any of the other GXs that require a Target List. As of v6.3, target data is stored separately from the regular line data, in its own target database. Use the [Targets] button to select a different targets database. Script Parameter: UXDETECT.TARGET _GROUP
Channel to save target sizes	Channel to save target sizes. Script Parameter: UXPEAKSZ.CHAN
[Targets]	Select the current target database, targets group and mask channel.

4.2.1.1 Size Calculation of Anomalies Application Notes

4.2.1.1.1 Estimate target sizes

The GX determines the distance from the peak of an anomaly to its first inflection point. This determination is completed in eight directions. The median value of the eight distances is half of the target size. The estimated target sizes have the same unit as the grid coordinates and are saved in the output channel. The inflection point is found by examining sets of four successive points. From these four points, first and second differences are calculated. An inflection point is found when the second slope is negative, and when the second difference (the change between the second and third slope) is positive. The inflection point is then between the second and third points, and is determined from the calculated intercept of the second derivative values with zero. For this reason, the minimum target size found using this method would be no less than two grid cells.

Note that the sizes calculated may be much smaller than the apparent sizes of target signatures as plotted on a map, because most of the target area is found on the "lower slopes" below the inflection point.

For magnetic data, the size data in this channel is used to determine the window size in the calculation of target information (with the UXYEULER GX).

For EM data, this size data may be used as a grading parameter in UXO characterization

4.2.2 Depth Calculation of Anomalies

Oasis GX UXEMDPTH GX was used to calculate the apparent depths of targets from the original two-coil EM data (top and bottom) grids. This function employs the following steps in Table 4-2.

TABLE 4-2 SIZE CALCULATION STEPS

Step	Description
Target list	The name of the "group" line to save the target data. This value is the same as the most recently specified target list from any of the other GXs that require a Target List. As of v6.3, target data is stored separately from the regular line data, in its own target database. Use the [Targets] button to select a different targets database. Script Parameter: UXDETECT.TARGET_GROUP
EM depth channel	Enter the name of the channel to place the depth values. Select an item from the list, or create a new channel. The default is "EM_Depth". Script Parameter: UXEMDPTH.CHAN
EM bottom channel grid	Specify the bottom grid. Script Parameter: UXEMDPTH.GRD_B
Bottom channel	Enter the name of the channel to place the values from the bottom grid. Select an item from the list, or create a new channel. The default is "Bottom". Script Parameter: UXEMDPTH.BOTTOM
EM top channel grid	Specify the top grid. Script Parameter: UXEMDPTH.GRD_T
Top channel	Enter the name of the channel to place the values from the top grid. Select an item from the list, or create a new channel. The default is "Top". Script Parameter: UXEMDPTH.TOP
Units to use for reporting depth	Select units for reporting depth. Script Parameter: UXDETECT.UNIT

Step	Description
Instrument height (cm)	Specify the instrument height in cm. Script Parameter: UXDETECT.HEIGHT
Instrument Type	Specify the instrument type. Script Parameter: UXDETECT.LOOP: 1: EM61 1m x 1m; 2: EM61 1m x 0.5m, 3: EM61-0.5x0.5m; 4: EM61HH-MK2
[Targets]	Select the current target database, targets group and mask channel.

4.2.2.1 Depth Calculation of Anomalies Application Notes

4.2.2.1.1 Instrument height

It is assumed that the EM instrument is on wheels (i.e. at a height of 45 centimeters above ground). Enter the correct height if the assumption is invalid.

4.2.2.1.2 Negative values

Improper calibration, drift, or other problems may result in negative values from the EM61 instrument. In such cases, the depth formula calculation is invalid. The calculation is skipped if negative or zero values are encountered when sampling the grids. A message is displayed after execution notifying the user of the number of target locations skipped.

4.2.2.1.3 Formulae and Assumptions

The following formulae have been provided by Geonics. They assume a compact, spherical conductor whose radius is small in comparison with the coil radius. The formulae are non-analytic; they are polynomial fits to curves measured for each instrument under laboratory conditions. Real depths, due to real, non-spherical and extended objects may be substantially different than values calculated using these formulae. The formulae assume the instrument is at a height of 45 centimeters.

T = Top coil value
B = Bottom coil value
D = Depth (m)

// EM61 1x1m

R = T/B

D = 0 (R < 0.938)

D = 5 (R > 2.269)

D = 0.01*(((292.118*R - 2158.63)*R + 6458.69)*R - 9635.78)*R + 7288.13)*R - 2229.57)

// EM61 1x0.5m

R = 1.117*T/B

D = 0 (R < 0.811)

D = 5.1 (R > 2.329)

D = (((((12.5886*R-131.581)*R+582.552)*R-1413.19)*R+2026.38)*R-1715.82)*R+795.099)*R-155.95

// EM61-0.5x0.5m

D = 0 (R < 0.588)

D = 4 (R > 2.165)

D = (((((0.841023*R - 4.88195)*R + 11.6106)*R - 13.3465)*R + 8.37497)*R - 2.15721;

// EM61HH-MK2

D = 0 (R < 0.983)

D = 3.85 (R > 2.78)

D = ((((((1.83056*R - 22.7417)*R + 119.597)*R - 344.383)*R + 585.69)*R - 587.627)*R + 322.235)*R - 74.5893

5.0 INTERPRETATION AND RESULTS

5.1 ANTELOPE LAKE NORTH

Antelope Lake North consisted of a surveyed area of ~785 acres with 10,491 anomalies. These anomalies were classified as follows.

Anomalies representing potential depleted uranium rings were identified using a threshold of 50 mV and above and a diameter of one meter or greater. In all, a total of 815 potential depleted uranium rings were identified. Table 5-1 summarizes the results of the survey.

TABLE 5-1 ANTELOPE LAKE NORTH DEPLETED URANIUM RING RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	815	3217555	784.2	1.04
Total	815	3217555	784.2	1.04

Anomalies representing potential penetrator rounds were then identified using a threshold of 10 mV with a diameter of five meters or greater. In all, a total of 673 potential penetrators were identified. Table 5-2 summarizes the results of the survey.

TABLE 5-2 ANTELOPE LAKE NORTH PENETRATOR RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	673	3217555	784.2	.86
Total	673	3217555	784.2	.86

Anomalies representing potential disposal pits were identified using a threshold of 10 mV and by identifying geometric shapes (manmade) with a diameter of five meters or greater. Additionally, densely anomalous areas of concern were also selected as potential disposal pits including one area located at approximately East 528259.0065, North 4172163.1914 as per discussions with on-site personnel. In all, a total of one potential disposal pit was identified. Table 5-3 illustrates the results of the survey.

TABLE 5-3 ANTELOPE LAKE NORTH POTENTIAL DISPOSAL PIT RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	1	3217555	784.2	.001
Total	1	3217555	784.2	.001

Lastly, processors looked for anomalies representing potential bomblets located within the area. This was accomplished by using a threshold of 8 mV to 60 mV. In all, a total of 9,002 potential bomblets were identified. Table 5-4 illustrates the results of the survey.

TABLE 5-4 ANTELOPE LAKE NORTH POTENTIAL BOMBLETS RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	9002	3217555	784.2	11.47
Total	9002	3217555	784.2	11.47

Of these anomalies, 40 targets' estimated depths were unknown, 10,146 targets had estimated depths between 0-3.99 feet, and 305 targets had an estimated depth of greater than four feet.

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response; hence, they were not selected for investigation.

5.2 BROWNES LAKE

Brownes Lake consisted of a surveyed area of ~ 40.8 acres with a total of 596 anomalies. These anomalies were classified as follows.

Anomalies representing potential depleted uranium rings were identified using a threshold of 50 mV and above and a diameter of one meter or greater. In all, a total of 67 potential depleted uranium rings were identified. Table 5-5 summarizes the results of the survey.

TABLE 5-5 BROWNES LAKE DEPLETED URANIUM RING RESULTS

Area	Targets	Area (m ²)	Acre	Targets/ Acre
1	67	165111	40.8	1.64
Total	67	165111	40.8	1.64

Anomalies representing potential penetrator rounds were then identified using a threshold of 10 mV with a diameter of five meters or greater. In all, a total of 15 potential penetrators were identified. Table 5-6 summarizes the results of the survey.

TABLE 5-6 BROWNES LAKE PENETRATOR RESULTS

Area	Targets	Area (m ²)	Acre	Targets/ Acre
1	15	165111	40.8	.37
Total	15	165111	40.8	.37

Anomalies representing potential disposal pits were identified using a threshold of 10 mV and by identifying geometric shapes (manmade) with a diameter of five meters or greater. Additionally, densely anomalous areas of concern were also selected as potential disposal including one area located at approximately East 527882.086, North 4173646.116 as per discussions with on-site personnel. In all, a total of one potential disposal pit was identified. In all, a total of one potential disposal pit was identified. Table 5-7 illustrates the results of the survey.

TABLE 5-7 BROWNES LAKE POTENTIAL DISPOSAL PIT RESULTS

Area	Targets	Area (m ²)	Acre	Targets/ Acre
1	1	165111	40.8	.02
Total	1	165111	40.8	.02

Lastly, processors looked for anomalies representing potential bomblets located within the area. This was accomplished by using a threshold of 10 mV to 50 mV. In all, a total of 513 potential bomblets were identified. Table 5-8 illustrates the results of the survey.

TABLE 5-8 BROWNES LAKE POTENTIAL BOMBLETS RESULTS

Area	Targets	Area (m ²)	Acre	Targets/ Acre
1	513	165111	40.8	12.57
Total	513	165111	40.8	12.57

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response; hence, they were not selected for investigation.

Of these anomalies, 14 targets' estimated depths were unknown, 582 targets had estimated depths between 0-3.99 feet, and zero targets had an estimated depth of greater than four feet.

5.3 NEDS LAKE

NEDS Lake consisted of a surveyed area of ~ 48.6 acres with a total of 715 anomalies. These anomalies were classified as follows.

Anomalies representing potential depleted uranium rings were identified using a threshold of 50 mV and above and a diameter of one meter or greater. In all, a total of 110 potential depleted uranium rings were identified. Table 5-9 summarizes the results of the survey.

TABLE 5-9 NEDS LAKE DEPLETED URANIUM RING RESULTS

Area	Targets	Area (m ²)	Acre	Targets/ Acre
1	110	196677	48.6	2.26
Total	110	196677	48.6	2.26

Anomalies representing potential penetrator rounds were then identified using a threshold of 10 mV with a diameter of five meters or greater. In all, a total of 62 potential penetrators were identified. Table 5-10 summarizes the results of the survey.

TABLE 5-10 NEDS PENETRATOR RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	62	196677	48.6	1.28
Total	62	196677	48.6	1.28

Anomalies representing potential disposal pits were identified using a threshold of 10 mV and by identifying geometric shapes (manmade) with a diameter of five meters or greater. Additionally, densely anomalous areas of concern were also selected as potential disposal pits. In all, a total of 140 potential disposal pits were identified. Table 5-11 summarizes the results of the survey

TABLE 5-11 NEDS LAKE POTENTIAL DISPOSAL PIT RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	140	196677	48.6	2.88
Total	140	196677	48.6	2.88

Lastly, processors looked for anomalies representing potential bomblets located within the area. This was accomplished by using a threshold of 10 mV to 50 mV. In all, a total of 403 potential bomblets were identified. Table 5-12 illustrates the results of the survey.

TABLE 5-12 NEDS LAKE POTENTIAL BOMBLETS RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	403	196677	48.6	8.29
Total	403	196677	48.6	8.29

Of these anomalies, 3 targets' estimated depths were unknown, 685 targets had estimated depths between 0-3.99 feet and 27 targets had an estimated depth of greater than four feet.

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response; hence, they were not selected for investigation.

5.4 PEDRO LAKE

Pedro Lake consisted of a surveyed area of ~ 151.7 acres with a total of 2167 anomalies. These anomalies were classified as follows.

Anomalies representing potential depleted uranium rings were identified using a threshold of 50 mV and above and a diameter of one meter or greater. In all, a total of 472 potential depleted uranium rings were identified. Table 5-13 summarizes the results of the survey.

TABLE 5-13 PEDRO LAKE DEPLETED URANIUM RING RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	472	613908	151.7	3.11
Total	472	613908	151.7	3.11

Anomalies representing potential penetrator rounds were then identified using a threshold of 10 mV with a diameter of five meters or greater. In all, a total of 134 potential penetrators were identified. Table 5-14 summarizes the results of the survey.

TABLE 5-14 PEDRO LAKE PENETRATOR RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	134	613908	151.7	0.88
Total	134	613908	151.7	0.88

Anomalies representing potential disposal pits were identified using a threshold of 10 mV and by identifying geometric shapes (manmade) with a diameter of five meters or greater. Additionally, densely anomalous areas of concern were also selected as potential disposal pits. No potential disposal pits were identified. Table 5-15 illustrates the results of the survey.

TABLE 5-15 PEDRO LAKE POTENTIAL DISPOSAL PIT RESULTS

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	0	613908	151.7	0.00
Total	0	613908	151.7	0.00

Lastly, processors looked for anomalies representing potential bomblets located within the area. This was accomplished by using a threshold of 10 mV to 50 mV. In all, a total of 1,561 potential bomblets were identified. Table 5-16 illustrates the results of the survey.

TABLE 5-16 PEDRO LAKE POTENTIAL BOMBLETS RESULTS

Area	Targets	Area (m²)	Acre	Targets/ Acre
1	1561	613908	151.7	10.29
Total	1561	613908	151.7	10.29

Of these anomalies, 12 targets' estimated depths were unknown, 2,100 targets had estimated depths between 0-3.99 feet and 55 targets had an estimated depth of greater than four feet.

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response; hence, they were not selected for investigation.

6.0 SUMMARY AND CONCLUSIONS

The report details the procedures and results of an EM target detection conducted at the TTR near Tonopah, Nevada, specifically at the Antelope Lake North, Brownes Lake, NEDS Lake, and Pedro Lake sites in February 2007. Zapata personnel utilized EM61 MKII top and bottom coil data at 660 microseconds in a grid (*.grd) format which was provided by National Securities Technologies, LLC, and which was collected over the four lakes in an investigation performed previously by Bechtel.

Zapata performed geophysical processing (target selection) of Antelope Lake North, Brownes Lake, NEDS Lake, and Pedro Lake data supplied by National Securities Technologies, LLC as delineated under section 2.6.1 of the SOW, Exhibit B. This included performing the geophysical data processing (anomaly selection) and reporting using the methods that were utilized for Antelope Lake EM data.

The objective of the anomaly detection was to identify subsurface metal that may consist of OE whose size is consistent with bomblets, penetrators, depleted uranium rings, and possible disposal pits. The anomaly magnitude and shape for the anomalies were determined from a geophysical prove out performed by Zapata at the TTR in 2006.

To meet this objective, Zapata performed the following specific tasks:

- Used geophysical EM surveys to map the distribution and density of buried metal objects to identify potential UXO items.
- Implemented target selections on Antelope Lake North, Brownes, NEDS, and Pedro Lakes.
- Calculated a qualitative estimate of size and depth of selected anomalies.

7.0 CERTIFICATION AND DISCLAIMER

All geophysical data analysis, interpretations, conclusions, and recommendations in this document have been prepared under the supervision of and reviewed by ZAPATAENGINEERING, Blackhawk Division Senior Geophysicists and Engineers.

This geophysical investigation was conducted using sound scientific principles and state-of-the-art technology. A high degree of professionalism was maintained during all aspects of the project from the field investigation and data acquisition, through data processing, interpretation, and reporting. All original field data files, field notes and observations, and other pertinent information are maintained in the project files and are available for the client to review.

A geophysicist's certification of interpreted geophysical conditions comprises a declaration of his/her professional judgment. It does not constitute a warranty or guarantee, expressed or implied, nor does it relieve any other party of its responsibility to abide by contract documents, applicable codes, standards, regulations, or ordinances.

James Hild / Project Manager

Project Manager / Senior Geophysicist
ZAPTATAENGINEERING, P.A.
Blackhawk Division

301 Commercial Road,
Suite B
Golden, Colorado 80401

Phone: (303) 278-8700
Fax: (303) 278-0789
Web: www.blackhawkgeo.com

APPENDIX K-2

GEOPHYSICS REPORT

**Geophysical Surveys
Tonopah Test Range
Tonopah, Nevada**

**FINAL REPORT
GEOPHYSICAL SURVEYS
TONOPAH TEST RANGE
TONOPAH, NEVADA**

Project Number 2028

**Prepared For:
NATIONAL SECURITIES TECHNOLOGIES, LLC.**

**Prepared by:
ZAPATAENGINEERING, P.A., Blackhawk Division
301 Commercial Road, Suite B
Golden, CO 80401
Office: (303) 278-8700**

June 2007

**FINAL REPORT
GEOPHYSICAL SURVEYS
TONOPAH TEST RANGE
TONOPAH, NEVADA**

ZAPATAENGINEERING P.A., Blackhawk Division
Project Number: 2028

Prepared For:

NATIONAL SECURITIES TECHNOLOGIES, LLC.

Nevada Test Site
NTS 306
Mercury, Nevada 89023
702-295-6711

Prepared By:

ZAPATA ENGINEERING, Blackhawk Division

301 Commercial Road, Suite B
Golden, Colorado 80401
303-278-8700 • Fax 303-278-0789

June 2007

TABLE OF CONTENTS

TABLE OF CONTENTS	1-2
LIST OF FIGURES	1-4
LIST OF TABLES	1-4
ACRONYMS AND ABBREVIATIONS	1-5
1.0 INTRODUCTION.....	1-6
2.0 SITE DESCRIPTION.....	2-1
2.1 GENERAL	2-1
2.2 SITE 1 – 408 – BOMBLET TARGET AREA	2-1
2.3 SITE 2 – CLEAN SLATE.....	2-1
2.3.1 Clean Slate I.....	2-2
2.3.2 Clean Slate II.....	2-2
2.3.3 Clean Slate III	2-2
2.4 SITE 3 – ANTELOPE LAKE	2-3
2.5 PRE-ACQUIRED ANTELOPE LAKE DATA	2-3
2.6 SITE 4 – ANTELOPE LAKE FILL-IN	2-3
2.7 SITE 5 – DAVIS GUN SITE.....	2-3
2.8 SITE 6 – MT. HELEN.....	2-4
3.0 GEOPHYSICAL EQUIPMENT	3-1
3.1 EM61-MKII	3-1
3.2 MTADS.....	3-1
3.3 SENSOR POSITIONING.....	3-2
3.4 AUTONOMOUS REMOTE CONTROLLED VEHICLE (ARCV)	3-2
3.5 ARCV SUPPORT	3-3
4.0 INSTRUMENT STANDARDIZATION AND QUALITY ASSURANCE ...	4-1
4.1 EQUIPMENT WARM UP	4-1
4.2 PERSONNEL TEST	4-1
4.3 CABLE SHAKE TESTS	4-1
4.3.1 Cable Shake Tests MKII.....	4-1
4.3.2 Cable Shake Tests MTADS	4-2
4.4 STATIC / STANDARD TESTS	4-3
4.4.1 Static Test.....	4-3
4.4.1.1 Static Tests MKII.....	4-3
4.4.1.2 Static Tests MTADS	4-5
4.4.2 Standard Test	4-6
4.4.2.1 Standard Tests MKII.....	4-6
4.4.2.2 Standard Tests MTADS	4-7
4.5 POSITIONAL TEST.....	4-7
4.5.1 Positional Tests MKII.....	4-8
4.5.2 Positional Tests MTADS	4-8
4.6 SIX LINE TEST.....	4-9
4.6.1 Six Line Test MKII.....	4-10
5.0 DATA ACQUISITION.....	5-1

5.1	408 – BOMBLET TARGET AREA	5-1
5.1.1	Grid System 408 – Bomblet Target Area	5-1
	Data Collection 408 – Bomblet Target Area	5-2
5.1.2	Data Gaps 408 – Bomblet Target Area.....	5-2
5.2	CLEAN SLATE	5-2
5.2.1	Grid System Clean Slate	5-2
5.2.2	Data Collection Clean Slate	5-3
5.2.3	Data Gaps Clean Slate	5-3
5.3	ANTELOPE LAKE.....	5-3
5.3.1	Grid System Antelope Lake.....	5-3
5.3.2	Data Collection Antelope Lake.....	5-4
5.3.3	Data Gaps Antelope Lake	5-4
5.4	PRE-ACQUIRED ANTELOPE LAKE DATA	5-4
5.4.1	Grid System Pre-Acquired Antelope Lake	5-5
5.4.2	Data Collection Pre-Acquired Antelope Lake	5-5
5.4.3	Data Gaps Pre-Acquired Antelope Lake.....	5-5
5.5	ANTELOPE LAKE FILL-IN	5-5
5.5.1	Grid System Antelope Lake Fill-in.....	5-5
5.5.2	Data Collection Antelope Lake Fill-in.....	5-6
5.5.3	Data Gaps Antelope Lake Fill-in	5-6
5.6	DAVIS GUN SITE	5-6
5.6.1	Grid System Davis Gun Site	5-7
5.6.2	Data Collection Davis Gun Site.....	5-7
5.6.3	Data Gaps Davis Gun Site	5-7
5.7	MT. HELEN	5-7
5.7.1	Grid System Mt. Helen	5-8
5.7.2	Data Collection Mt. Helen	5-8
5.7.3	Data Gaps Mt. Helen.....	5-8
6.0	DATA PROCESSING	6-1
6.1	DATA PROCESSING STEPS MKII	6-1
6.2	DATA PROCESSING PRE-ACQUIRED ANTELOPE LAKE.....	6-2
6.3	DATA PROCESSING STEPS MTADS	6-2
6.4	ANOMALY SELECTION AND MODELING STEPS	6-3
6.4.1	408 – Bomblet Target Area.....	6-4
6.4.2	Clean Slate	6-4
6.4.3	Antelope Lake	6-5
6.4.4	Anomaly Selection Pre-Acquired Antelope Lake.....	6-5
6.4.5	Antelope Lake Fill-in.....	6-6
6.4.6	Davis Gun Sites.....	6-6
6.4.7	Mt. Helen Sites.....	6-6
7.0	GEOPHYSICAL PROVE OUT RESULTS	7-1
7.1	DATA QUALITY OBJECTIVES (DQO)	7-1
7.2	GPO DATA INTERPRETATION AND RESULTS.....	7-2
7.2.1	MKII Results.....	7-2

7.2.2	MTADS Results.....	7-4
8.0	INTERPRETATIONS AND RESULTS.....	8-1
8.1	408 – BOMBLET TARGET AREAS.....	8-1
8.2	CLEAN SLATE	8-1
8.3	ANTELOPE LAKE.....	8-2
8.4	PRE-ACQUIRED ANTELOPE LAKE	8-19
8.5	ANTELOPE LAKE FILL-IN	8-20
8.6	DAVIS GUN SITE	8-21
8.7	MT. HELEN	8-22
8.8	GEOGRAPHICAL INFORMATION SYSTEMS (GIS) DATA FORMAT	8-23
9.0	CONCLUSIONS	9-1
10.0	CERTIFICATION AND DISCLAIMER	10-1

LIST OF FIGURES

Figure 4-1	MKII August 28, 2006 Left Coil Cable Shake Profile	4-2
Figure 4-2	MTADS October 12, 2006 Left Coil Cable Shake Profile	4-2
Figure 4-3	MKII August 28, 2006 AM Static Test – Left Coil.....	4-4
Figure 4-4	MKII August 28, 2006 Left Coil Static	4-4
Figure 4-5	MTADS October 12, 2006 AM Static Test – Left Coil.....	4-5
Figure 4-6	MTADS October 12, 2006 Left Coil Static	4-5
Figure 4-7	MKII August 28, 2006 Standard Test Profile Channel 1 – Left Coil	4-6
Figure 4-8	MTADS October 12, 2006 Standard Test Profile Left Bottom Coil	4-7
Figure 4-9	MKII August 28, 2006 Positional Test Profile - Center Coil	4-8
Figure 4-10	MTADS October 12, 2006 Positional Test Profile - Center Coil	4-9

LIST OF TABLES

Table 5-1	408 – Bomblet Target Area Acreage	5-1
Table 5-2	Clean Slate Acreage.....	5-3
Table 7-1	GPO Results for MKII Tests Conducted Between June 1, 2006 and June 6, 2006.....	7-2
Table 7-2	Results of GPO for MKII Channel 1 on June 6, 2006.....	7-3
Table 7-3	Results of GPO for MKII Halfsumdmnl on June 6, 2006	7-4
Table 7-4	GPO Results for MTADS Tests Conducted on June 7, 2006 and August 10, 2006.....	7-5
Table 8-1	408 – Bomblet Target Areas	8-1
Table 8-2	Clean Slate Results	8-2
Table 8-3	Antelope Lake Depleted Uranium Ring Results.....	8-3
Table 8-4	Antelope Lake Penetrator Results.....	8-7
Table 8-5	Antelope Lake Potential Disposal Pit Results	8-11
Table 8-6	Antelope Lake Bomblet Results	8-15
Table 8-7	Pre – Acquired Antelope Lake Depleted Uranium Ring Results	8-19

Table 8-8	Pre – Acquired Antelope Lake Penetrator Results	8-19
Table 8-9	Pre – Acquired Antelope Lake Potential Disposal Pit Results	8-19
Table 8-10	Pre – Acquired Antelope Lake Potential Bomblets Results	8-20
Table 8-11	Antelope Lake Fill-in Depleted Uranium Ring Results	8-20
Table 8-12	Davis Gun Penetrator Results.....	8-21
Table 8-13	Davis Gun Penetrator Results - Sidewinder	8-21
Table 8-14	Mt. Helen Penetrator Results @ 15 mV and 1 Meter Diameter.....	8-22
Table 8-15	Mt. Helen Penetrator Results @ 10 mV and 5 Meter Diameter.....	8-22
Table 9-1	Data Results for Tonopah	9-2

ACRONYMS AND ABBREVIATIONS

ARCV	Autonomous Remote Controlled Vehicle
ATV	All-Terrain Vehicle
DID	Data Item Descriptions
DGM	Digital Geophysical Mapping
DGPS	Digital Global Positioning System
DoD	United States Department of Defense
DoE	United States Department of Energy
DQO	Data Quality Objectives
DU	Depleted Uranium
EM	Electromagnetic
HE	High Explosives
GPO	Geophysical Prove Out
GPS	Global Positioning System
GZ	Ground Zero
INS	Internal Navigation System
kbps	Kilobytes Per Second
M	meter
mV	MilliVolts
MKII	EM61-MKII
MTADS	Multi-Sensor Towed Array Detection System
Oasis	Geosoft Oasis montaj®
OE	Ordnance and Explosives
pCi/g	picoCurie/gram
Pu	Plutonium
RTK	Real Time Kinematic
TDEM	Time Domain Electromagnetic
TTR	Tonopah Test Range
USACE	United States Army Corps of Engineers
WGS 84	World Geodetic System 1984
Zapata	ZAPATAENGINEERING P.A., Blackhawk Division

1.0 INTRODUCTION

The following report details the procedures and results of an electromagnetic (EM) survey conducted at the Tonopah Test Range (TTR) near Tonopah, Nevada between the dates of May 31, 2006 and October 18, 2006. ZAPATAENGINEERING P.A., Blackhawk Division (Zapata) personnel performed the survey using two EM metal detection instruments, the first using an array of three Geonics EM61-MKII (MKII) time domain electromagnetic (TDEM) systems, and the second using the Multi-sensor Towed Array Detection System (MTADS). Both the MKII array and the MTADS were coupled to a Real Time Kinematic (RTK) Global Positioning System (GPS).

The objective of the survey was to detect subsurface metal that is likely to consist of ordnance and explosives (OE), identify potential depleted uranium (DU) rings, and identify potential penetrators. The sensor performance, positioning of equipment, data processing, data transfer, and geophysical quality control procedures are explained in detail within this project.

2.0 SITE DESCRIPTION

2.1 GENERAL

The TTR is 200 miles northwest of Las Vegas, Nevada and 40 miles southeast of Tonopah, Nevada. It is operated by the United States Department of Defense (DoD) with management and site access the responsibility of Sandia National Laboratory.

The climate at the TTR is high desert with temperatures ranging from highs in the 100's in the summer to lows down to -20's in the winter. Average rainfall in the valley is only four inches per year with 12 inches per year in the nearby mountains. Dust storms are common in the spring months when winds are high (15 miles per hour). Standing water may be present on the lakebeds until mid-spring.

The two types of expected site conditions are as follows:

1. Alluvial Playa – Thick section of fine-grained unconsolidated sediments. Surface conditions are flat with no vegetation.
2. Volcanic Tuff - Welded tuff bedrock with thin to absent soil cover. Surface is generally flat with minimal vegetation. Accumulations of rock debris from excavations may be present.

2.2 SITE 1 – 408 – BOMBLET TARGET AREA

The Bomblet target corrective action area currently occupies approximately one square mile at mid-target and approximately two square miles on the south end of Antelope Lake. The area within the 408 site was used for testing anti-personnel and anti-vehicular submunitions during the late 1960's and early 1970's. The primary type of ordnance to be expected with the Bomblet Target Area includes various types of anti-personnel and anti-vehicular submunitions on the ground surface and in the shallow subsurface. One ordnance drop at the extreme end of this area used either live bomblets with high explosives (HE), or mock-live bomblets containing a live fuze, but no HE. No radiological concerns are known to be associated with 408.

2.3 SITE 2 – CLEAN SLATE

Clean Slates I, II and II were all tests in Operation Roller Coaster. Conducted in 1963, they simulated weapons accident scenarios by using conventional explosives to disperse nuclear device mockups that contained plutonium (Pu) and depleted uranium (DU).

2.3.1 Clean Slate I

The Clean Slate 1 Site test was performed on an open concrete slab. The test generated concrete, metal, wooden, and other debris, and soil contaminated with radionuclides from the mock-up devices.

Field restoration consisting of excavation, packaging, and disposal of contaminated soil occurred on the Clean Slate I site in 1977. The remnants of a fence installed shortly after the test are still onsite. Residual radiological impact at the site is limited to soil with a maximum concentration of roughly 400 picoCuries/gram (pCi/g) transuranics. A plume of contaminated soil extends from the original ground zero (GZ) of the test approximately 2.6 miles to the southeast. The plume is roughly 1,000 feet wide.

2.3.2 Clean Slate II

Clean Slate II occurred within a steel-reinforced concrete bunker. The test generated concrete, metal, wooden, and other debris, and soil contaminated with radionuclides from the mock-up devices.

At Clean Slate II, the majority of the original bunker concrete, metal, and wood debris generated from the test were buried in a mound at GZ. An inner fence was constructed around GZ shortly after the test was conducted. An outer fence was installed several years after the test to restrict access to the highest concentrations of radiological contamination at the site. The outer fence encloses an area approximately 2,000 feet wide and 3,300 feet long encompassing the GZ and extending southeastward. An access road traced the perimeter around the outer fence; radiologically contaminated soils with a maximum concentration of 400 pCi/g extend to the southeast beyond the outer fence about 2.9 miles from the original GZ. The plume is roughly 2,000 feet wide.

2.3.3 Clean Slate III

Clean Slate III also occurred within a steel-reinforced concrete bunker. The test generated concrete, metal, wooden, and other debris, and soil contaminated with radionuclides from the mock-up devices.

At Clean Slate III, the majority of the original bunker concrete, metal, and wood debris generated from the test were buried in a mound at GZ similar to Clean Slate II. An inner fence was constructed around GZ shortly after the test was conducted. An outer fence was installed several years after the test to restrict access to the highest concentrations of radiological contamination at the site. The outer fence encloses an area approximately 1,500 feet wide and 2.4 miles long encompassing the GZ and extending southeastward. An access road traces the perimeter around

the outer fence. Radiologically contaminated soil, with a maximum concentration of roughly 400 pCi/g, extends to the southeast beyond the outer fence about 3.4 miles from the regional GZ. The plume is roughly 2,000 feet wide.

2.4 SITE 3 – ANTELOPE LAKE

The Antelope Lake survey area consists of approximately 1,300 acres in the southern portion of a dry lake bed playa. A separate contractor had previously surveyed the northern portion of the playa. The survey site is divided into a northern portion which consists of approximately 510 acres, and a southern portion of the lake consisting of approximately 790 acres. The dry lake bed is generally flat with very few surface obstacles and no appreciable vegetation. Objects of interest in the Antelope Lake survey area include a buried rocket, multi-kilogram rings/plates of depleted uranium debris, baseball sized sub-munitions, and Davis Gun Penetrators. Antelope Lake has been the site of multiple tests since the 1940's and large amounts of metal material from various sources are present within the lake.

2.5 PRE-ACQUIRED ANTELOPE LAKE DATA

Per the request of the client, additional data were added north of the 1,300 acres of Antelope Lake collected by Zapata. These data were collected by a separate contractor who had previously surveyed the northern portion of the playa. Data for this area were provided to Zapata in the form of processed Oasis *.grd files rather than raw data files. These files were georeferenced using UTM zone 11 North meters WGS84 in order to map seamlessly with data collected by Zapata. No further processing, only target selection, was done in this area as Zapata assumed all processing of this data was correct.

See Section 2.4 Antelope Lake

2.6 SITE 4 – ANTELOPE LAKE FILL-IN

The Antelope Lake Fill-in area was an additional area added to the project after the completion of Antelope Lake. This fill-in area encompassed four small areas to the north of Antelope Lake that were excluded from previous surveys done by other contractors.

See Section 2.4 Antelope Lake

2.7 SITE 5 – DAVIS GUN SITE

The Davis Gun was a recoilless rifle used by Sandia National Laboratories to fire artillery projectiles, referred to as penetrators, into soil, rock, and concrete targets. According to

information collected previously, the penetrators used at TTR were usually inert with occasional use of DU as ballasts. According to background documentation, Davis Gun tests are presumed to have taken place in several locations across TTR from the 1960's through the 1990's. The locations where Davis Gun Penetrator tests were conducted and where corresponding geophysical surveys were performed include Antelope Tuff Target 1 (including Antelope Tuff Target 1A), Antelope Tuff Target 2, Meyers Ridge, Sidewinder Tuff Target, Antelope Lake, and Mt. Helen.

Due to size and location the Davis Gun sites are listed in the following manner for this report:

1. Antelope Lake – Located independently from Davis Gun Sites
2. Antelope Lake Fill-In – Located independently from Davis Gun Sites
3. Davis Gun Site

These areas are numbered from sites in the northern part of Davis Gun to the sites located in the south.

- Antelope Tuff Target 2 (Area 1 – Antelope Tuff 2)
- Antelope Tuff Target 1 (Area 2 – Antelope Tuff 1) (Area 3 – Antelope Tuff 1A)
- Sidewinder Tuff Target (Area 4 – Sidewinder)
- Meyers Ridge (Area 5 – Meyers Ridge)

Additionally, Davis Gun contains the area of Main Lake, which was not geophysically surveyed and not detailed in this report.

4. Mt. Helen - Located independently from Davis Gun Sites

2.8 SITE 6 – MT. HELEN

See Section 2.7 Davis Gun Site

3.0 GEOPHYSICAL EQUIPMENT

3.1 EM61-MKII

The MKII system was utilized for most of the digital geophysical mapping (DGM). The MKII is a high-sensitivity TDEM system that is capable of detecting both ferrous (steel) and non-ferrous (aluminum, copper, brass, etc.) metals. The instrument consists of three 0.5 meters by 1.0 meter side-by-side transmitter/receiver coils positioned contiguous to one another with the 1.0 meter edges perpendicular to the direction of travel, resulting in a three-meter sampling swath. The lower transmitter/receiver coils were 45 centimeters above the ground surface while, when used; the upper receiver coils were 28 centimeters above the lower coils. The MKII generates an EM pulse in the bottom transmitter coil causing eddy currents to flow within both the ground and buried metallic objects. When the EM pulse is terminated, the eddy currents decay which produces a changing EM field, also referred to as a secondary EM field. The eddy currents decay more slowly in metallic objects than in the ground and produce measurable signals that can be detected by the EM system. The MKII system records secondary magnetic responses at three or four time intervals along the decay curve after the transmitter is turned off. These intervals are referred to as time gates or channels. In the surveys over the 408 and Clean Slate sites four different time gates were recorded. In the Antelope Lake survey, data three time gates (220 μ s , 360 μ s, and 660 μ s) were recorded from the lower receiver coil and data from one time gate (660 μ s) were recorded from the upper coil. This was done to obtain data which were consistent with the data collected in the previous geophysical survey of the northern portion of Antelope Lake. The response for all four channels are measured for each receiver coil and recorded in milliVolts (mV). For this survey, the first (earliest) time gate of the bottom coil response (Channel 1 at 220 μ s) was used for data interpretation. The MKII system is designed so that a low-level or constant signal is received when no metal is present. When metal is present in the subsurface, an increased secondary EM field response is recorded by the instrument. This EM signal is generally at the maximum level when the receiver coils are located directly over a metallic object. This results in “bulls-eye” type anomalies for isolated buried metallic targets, which allows for simplified anomaly interpretation.

3.2 MTADS

The MTADS system is similar to the EM61 MKII and was also utilized for DGM. Similarly, the MTADS is a high-sensitivity TDEM system that is capable of detecting both ferrous (steel) and non-ferrous (aluminum, copper, brass, etc.) metals. The MTADS consists of three modified Geonics EM61 coils with their planes horizontal. These coils are 1.0 meter square and are arranged in an overlapping configuration. The left and right coils are side by side and the center coil is centered over them, resulting in a two meter

sample swath. The MTADS also generates an EM pulse in the bottom transmitter coil causing eddy currents to flow within both the ground and buried metallic objects in the same manner as the MKII. A low-level or constant signal is received by the MTADS when no metal is present. When metal is present in the subsurface, an increased secondary EM field response is recorded by the instrument. This EM signal is generally at the maximum level when the receiver coils are located directly over a metallic object. This again results in “bulls-eye” type anomalies for isolated buried metallic targets, which allows for simplified anomaly interpretation.

The two main differences in the systems are:

1. The MTADS coil records only one time channel, which is the same as the first channel of the MKII.
2. The MTADS has a higher transmitter moment and overlapping coils which makes it more effective at mapping large metal items buried at depth, i.e. Davis Gun penetrators.

3.3 SENSOR POSITIONING

Positioning of the EM sensors on both geophysical systems was primarily accomplished using a Trimble 5700 RTK Digital Global Positioning System (DGPS). In addition, the MKII positional data were supplemented with an inertial guidance system. The positional data were recorded in World Geodetic System 1984 (WGS 84) Longitude and Latitude. The EM data have a positional error of up to 18 inches due to the fact that a detected item could be anywhere along the width of the one meter coils. The EM and DGPS data were recorded simultaneously on the field computer within the tow vehicle.

3.4 AUTONOMOUS REMOTE CONTROLLED VEHICLE (ARCV)

This geophysical survey was conducted using an Autonomous Remote Controlled Vehicle (ARCV) tailored for operations of large area coverage without exposing personnel to potential hazards from unexploded ordnance. The vehicle is a modified New Holland 2550 Speedrower, which has been retrofitted to allow the machine-actuated functions to be controlled by an onboard computer. Harvesting tasks require the vehicle to cover a field using minimally overlapping rows at slow speeds in a similar manner to geophysical and radiological surveys conducted at the Tonopah Test Site.

Autonomy is realized by establishing a path plan for area coverage using a combined DGPS and inertial guidance system to accurately locate the vehicle at all times and control vehicle operating systems. A path plan is generated by gathering base coordinates for the area to be covered, adding information about the known positions of obstacles or areas that are occluded, and setting the parameters of coverage for the

sensors. The resulting path plan is a series of points that guide the vehicle, allowing complete coverage of the survey area.

Onboard power generation provided the power to operate the geophysical and radiological equipment. Moving equipment inside the Speedrower minimized components exposed to radiological and environmental contamination. Vehicle service was similar to a normal farming vehicle with recommended oil and filter changes every 1000 hours.

The Speedrower was typically guided autonomously, but could be tele-operated or conventionally driven for transport, setup, service, obstacle negotiation, or recovery. The fully-autonomous operation was programmed from the user interface and provided DGPS-based tracking of the platform and payload based on user parameters. The remote control operation was available via the communications link. On-board cameras provided visual feedback for the operator. In addition, the platform was capable of operation from the driver's seat with normal controls. Onboard emergency stop switches and a radio-linked emergency stop assured that remote operators always had a means to stop the vehicle.

3.5 ARCV SUPPORT

The ARCV was operated from an onsite support trailer. The trailer contained communications and console equipment for the technicians to monitor and control autonomous vehicle operation. One site geophysicist or geophysical technician and one robotics technician manned the trailer. Communication links allowed for manual override for remote control operations and real time monitoring. It also allowed for remote collection of data from the vehicle and towed sensor trailers. The vehicle was equipped with high-resolution video, DGPS, long-range high-bandwidth wireless communications capable of transmitting high-resolution video, survey data, and driver commands from the survey vehicle to the field support facility.

The vehicle was equipped with two high-bandwidth wireless connections capable of transmitting and receiving data and operator commands in excess of 500 kilobytes per second (kbps) with a range in excess of three miles. The on-board data logging was capable of recording a minimum of one day's geophysical and location data. The wireless connection was capable of transmitting in excess of seven channels at 19.2 kbps serial rate over a three-mile range. Transmission delay time did not exceed 300 milliseconds over a three-mile range.

The ARCV's DGPS/Inertial Navigation System (INS) provided position estimation to three centimeters with the RTK base station for vehicle position estimation/navigation and towed sensor array position.

High definition, live color video feed was supplied from a high-resolution color camera installed on the front of the vehicle. The color camera was outfitted with a fixed-focus lens and housed in a wash-down capable housing. The video signal is routed back to the base station over the wireless communications.

A stationary video camera, in a wash-down capable housing, was attached facing the rear of the vehicle to provide a view of the sensing trailers. The video signal was routed back to the base station over the wireless communications.

4.0 INSTRUMENT STANDARDIZATION AND QUALITY ASSURANCE

To ensure high-quality geophysical data a Zapata Project Geophysicist evaluated the instrumentation, data collection, and processing steps. Zapata personnel performed several daily operational instrument checks to verify that all instrumentation was operating as designed. These tests comply with US Army Corps of Engineers (USACE) requirements as stated in the “*Ordnance and Explosives Digital Geophysical Mapping Guidance Operational Procedures and Quality Control Manual*” (NAEVA, 2003). These tests are described below. The same tests were performed for both the MKII system and the MTADS. For the MKII, tests were performed on channels one and three of the data. For the MTADS system, tests were performed on channel one data only.

4.1 EQUIPMENT WARM UP

Equipment warm-up time lasted approximately fifteen minutes for both systems prior to data collection.

4.2 PERSONNEL TEST

This test ascertains that the operator is not carrying any metal objects that might interfere with the instrument readings.

4.3 CABLE SHAKE TESTS

On a daily basis, the coils were checked for their response to vibrations in the cables. This was done by recording data in a stationary mode and manually shaking the cables. The response of the coils to this test was similar to the response when traveling over uneven terrain. The test data were visually inspected in the field for spikes within the data. The response of the coils to the cable shake should produce no spikes in the data.

4.3.1 Cable Shake Tests MKII

Figure 4-1 is a profile of a shake test from the MKII system from data recorded on August 28, 2006. The figure shows that the noise created by shaking the cables is less than ± 1.25 millivolt (mV), which is below the target selection threshold. In addition, there are no spikes in the data. The left channel is displayed in that figure.

Figure 4-1 MKII August 28, 2006 Left Coil Cable Shake Profile

A comprehensive overview of the results of the shake tests are as follows. Two of the shake tests collected with the MKII system resulted in bad data files. There was one day when no QC tests were collected and another when no data were collected. One day failed to pass established parameters for the shake test. The data collected on these days were accepted because tests conducted prior and post to these tests were analyzed to ensure they were within established parameters and because supplementary quality assurance testing from the aforementioned days passed established parameters.

4.3.2 Cable Shake Tests MTADS

Figure 4-2 is a profile of a shake test collected with the MTADS system on October 12, 2006. The figure shows that the noise created by shaking the cables is less than ± 1.25 mV, which is below the target selection threshold. In addition, there are no spikes in the data. The left channel is displayed in the following figure.

Figure 4-2 MTADS October 12, 2006 Left Coil Cable Shake Profile

A comprehensive overview of the results of the shake tests are as follows. There was only one shake test collected with the MTADS that did not meet established parameters. This data was accepted because tests conducted prior and post to these tests were analyzed to

ensure they were within established parameters and because supplementary quality assurance testing from the aforementioned days passed established parameters.

4.4 STATIC / STANDARD TESTS

4.4.1 Static Test

Before and after geophysical data collection each day, the background levels and response of the systems to a standard metallic object were measured. The purpose of this test, referred to as static/standard test, is to determine background noise levels, and monitor any changes in the system's response due to a standardized object. Variations in this test are also used to identify problems in the equipment. The tests are conducted in the following manner:

- 1) Data are recorded in a stationary mode for a minimum of three minutes (Static Test 1). In order for the static test to satisfy the quality assurance / quality control (QA/ QC) requirements, 95% of the Channel 3 data (for MKII) cannot vary by more than ± 1.5 mV and Channel 1 data (for MTADS) cannot vary by more than ± 2.5 mV.
- 2) A standardized object, a 2-inch trailer ball in this case, is placed within the array. Data are recorded for one minute to determine the instrument response to the object (Standard Test).
- 3) The standard object is then removed and background levels (Static Test 2) are again recorded for one minute. The differences between the static and standard responses must be within $\pm 20\%$ of the average of all tests conducted throughout the survey to comply with industry standards.

4.4.1.1 Static Tests MKII

Figure 4-3 is the profile from the AM static test recorded with the MKII on August 28, 2006. The data displayed is the third channel.

Figure 4-3 MKII August 28, 2006 AM Static Test – Left Coil

Figure 4-4 shows the response of the left coil of the MKII during first static portion of the AM Static test collected on August 28, 2006. The figure shows that the third channel data falls within the ± 1.5 mV noise envelope.

Figure 4-4 MKII August 28, 2006 Left Coil Static

A comprehensive overview of the results of the static tests are as follows. During the MKII survey there were six files that contained corrupt data. There were also 4 instances where no static tests were performed due to the requirement that the equipment be quickly shut down due to weather safety hazards. Three of the tests had less than 95% of the data contained within the established ± 1.5 mV noise envelopes.

To determine if actual data could be used from days with these discrepancies one or more of the following steps were taken: tests conducted prior and post to these tests were analyzed to ensure they were within established parameters, and supplementary quality assurance testing from the aforementioned days passed established parameters.

The test locations for the instrument standardization and QC tests were moved on multiple occasions because of the large distances between data collection locations. Due to these changes in location, known test points had to be re-established. In addition to the location change, the battery was replaced in the ARCV on the 6th of June 2006 to reduce noise in the right coil; this resulted in stabilization in the noise output in all coils.

4.4.1.2 Static Tests MTADS

The test was run on the MTADS data in the same manner as the MKII data; however, to mitigate noise, it was decided to add a nonlinear filter identical to the filter used on the data files in order to ensure the data peaks outside the established envelope could be normalized. This enabled well over ninety-five percent of the data points to be contained within the established $\pm 2.5\text{mV}$ envelope.

Figure 4-5 is the profile from the AM static test recorded with the MTADS on October 12, 2006. The data displayed is the bottom coil.

Figure 4-5 MTADS October 12, 2006 AM Static Test – Left Coil

Figure 4-6 shows the response of the left coil of the MKII during first static portion of the test collected on October 12, 2006. The figure shows the second channel data falls within the $\pm 2.5\text{ mV}$ noise envelope.

Figure 4-6 MTADS October 12, 2006 Left Coil Static

A comprehensive overview of the results of the static tests are as follows. During the course of the MKII survey there were three occasions when no tests were performed with the MTADS system. Data from these days were used due to all previous data tests meeting requirements. In addition, on October 17, 2006 a wrench was used for the standard instead of a trailer ball. On October 18, 2006 three static standard AM tests were performed using a platform, wrench and trailer ball to compare magnitudes. Only a PM test with a trailer ball was performed.

4.4.2 Standard Test

The standard test consists of 3 values. The static 1 value is the background median reading of the coils prior to placing the metal standard object on the coils (static 1 test). The standard value is the median reading of the coils with the metal standard in place (standard test). The static 2 value is the median reading of the coils after the metal standard has been removed (static 2 test). A 1st magnitude is calculated by taking the difference between the standard test reading and the static 1 value, which represents the actual response of the coils to the standard item. The 2nd magnitude is the same except the static 2 value is used. The daily coil responses as determined from the standard test were then compared to the running averages of all the previous standard tests, and the percent differences calculated. All differences between the daily tests and the project running averages must be within 20% to pass industry standards.

4.4.2.1 Standard Tests MKII

The standard test uses averages of all responses. The average was restarted twice during the project. This was due to the battery being replaced in the ARCV on June 6, 2006 and because the data stream and processing were modified on July 27, 2006.

Figure 4-7 is the profile from the AM standard test recorded with the MKII on August 28, 2006. The data displayed is the first channel.

Figure 4-7 MKII August 28, 2006 Standard Test Profile Channel 1 – Left Coil

A comprehensive overview of the results of the standard tests are as follows. On two occasions no MKII static tests were performed and eight standard files that were corrupted. The percent difference of the first magnitude was greater than the required 20% twice for the left and center coils and once for the right coil. The percent difference of the second magnitude exceeded 20% for each coil twice. Again the data from these days were accepted because tests conducted prior to these days were within standards.

4.4.2.2 Standard Tests MTADS

Since the MTADS system can be recalibrated each day, it was decided to only compare magnitudes between AM and PM tests instead of the average magnitude from day to day.

Figure 4-8 is the profile from the AM standard test recorded with the MTADS on October 12, 2006. The data displayed is the bottom channel.

Figure 4-8 MTADS October 12, 2006 Standard Test Profile Left Bottom Coil

A comprehensive overview of the results of the standard tests are as follows. During the course of the MKII survey there were four occasions no tests were performed. On October 17, 2006 a wrench was used for the standard instead of a trailer ball. On October 18, 2006 three static standard AM tests were performed using a platform, wrench and trailer ball to compare magnitudes. Only a PM test with a trailer ball was performed. The center and right coil met standards for all tests collected while the first percent difference of the left coil failed once as did the second percent difference. The data from this day was accepted due to the magnitude response from the latency test was consistent.

4.5 POSITIONAL TEST

The positional test is performed twice daily. This test has two purposes: to determine a latency value (in milliseconds) and to check the accuracy of the DGPS.

A metallic target (rebar) was placed vertically in the ground at a known location and data were collected over it in two opposing directions. The data were shifted by a calculated latency value for correct positioning. The difference in the location of the spike between the two passes provides the latency value. Once the data were shifted (latency corrected), the location of the anomaly produced by the rebar is documented and compared to the previous day's latency test results. The location of the rebar anomaly interpreted from the positional test data should be within 50 cm of its surveyed location and the mV value should not vary more than 30%.

The test locations for the instrument standardization and QC tests were moved on multiple occasions because of the large distances between data collection locations. Due to the change in location, known test points had to be re-established.

4.5.1 Positional Tests MKII

Figure 4-9 shows the data from the AM positional test from August 28, 2006 collected with the MKII. This positioning is best observed in the center coil. Note that the peak responses off all 3 coils line up in the center of the profile. The smaller peak to the left is due to an item that was not placed in the positional test path by the field crew.

Figure 4-9 MKII August 28, 2006 Positional Test Profile - Center Coil

At times positional data from the ARCV and the Towbot were used due to dropouts in the sensor mounted GPS. When the ARCV GPS was used a separate latency point needed to be established.

A comprehensive overview of the results of the positional tests are as follows. During the MKII survey there were three occasions files contained corrupt data as well as three occasions no positional tests were performed. One test failed due to a difference greater than 50 cm. There were three tests where the median of the amplitude values were greater than 30%. Data from these days were accepted due to prior tests meeting established parameters and due to the other QC tests on those particular days meeting requirements.

4.5.2 Positional Tests MTADS

Figure 4-10 shows the data from the AM positional test collected on October 12, 2006 with the MKII. This positioning is best observed in the center coil. Note that the peaks on all 3 coils line up. The smaller peaks to the right are anomalies that were not placed in the positional test path by the field crew, but were in the test path prior to the test being run.

Figure 4-10 MTADS October 12, 2006 Positional Test Profile - Center Coil

A comprehensive overview of the results of the positional tests are as follows. From all of the MTADS data collected, there were only two occasions when no positional tests were performed. In addition, one test failed due to a difference greater than 50 cm. This was due to a relocation of the latency due to geographical distances in field acquisition locations.

On one occasion the amplitude value median was greater than 30%. Different objects were used for the latency tests giving different amplitudes. For this reason, amplitudes were compared on a daily basis only. The data from these days were still used due to tests conducted prior and post to the aforementioned tests being within established parameters and because the other QC tests collected on those particular days met requirements.

4.6 SIX LINE TEST

The six-line test is performed prior to any survey grid data collection (not on a daily basis). The six-line test consists of six passes over an approximate 100-foot line free from metallic objects detectable by the instrumentation. Two passes are acquired at normal driving speed with no seed item. Two additional passes are conducted at normal speed with an item placed in the approximate center of the test line. A fifth pass is performed while driving at a fast pace with the seeded item in place. The sixth pass is performed while moving at a slow pace with the seeded item in place. Industry standards dictate that the repeatability of the amplitude response must not vary by more than $\pm 20\%$ and that the positional accuracy of the item must not vary by more than ± 50 cm.

4.6.1 Six Line Test MKII

The six-line on June 1, 2006 was collected with the MKII. The positional accuracy in all tests, as well as the amplitude response in the 4th line, is outside of established parameters. Since the detected locations were within approximately 22 cm of each other, it was decided that the known locations provided by the field crews were not valid and that the test would be rerun.

The MKII six-line was collected again on June 14, 2006. It can be observed that the positional accuracy in all tests as well as the amplitude response is within specified parameters.

5.0 DATA ACQUISITION

5.1 408 – BOMBLET TARGET AREA

Geophysical data were collected within the Bomblet sites between the dates of June 6, 2006 and June 28, 2006 using the MKII system described in Section 3.1. All of the MKII data were collected with DGPS and ARCV GPS.

The 408 Bomblet Target Area consisted of three separate areas:

- Mid Target
- South Antelope Lake
- SAC

5.1.1 Grid System 408 – Bomblet Target Area

A traditional grid system was not employed for any of the 408 Bomblet Target Areas. The survey consisted of 10 meter wide transects. Data collection over 10 % of the total area was required within each of the three areas. Total acreage collected in the 408 – Bomblet Target Area is as follows in Table 5-1. It is to be noted that the original size of the South Antelope Lake 408 survey area was reduced during the project from 1543.73 acres to 1183.58 acres.

Table 5-1 408 – Bomblet Target Area Acreage

408 – Bomblet Target Area	Area of Total Polygon (acres)	Collected Area (acres)	Percent Area Covered
Antelope Lake (Original Area)	1543.73	149.84	9.71
Antelope Lake (Modified Area)	1183.58		12.66
Mid-Target	314.71	33.81	10.74
SAC	72.71	33.22	45.69
Total Acreage (Original Area)	1931.16	216.87	11.23
Total Acreage (Modified Area)	1571.00	216.87	13.80

Data Collection 408 – Bomblet Target Area

The sampling width of the MKII array was 3 meters. Array paths were separated by 2.8 meters which resulted in 100 % coverage within surveyed areas. MKII sensor data were recorded at 16 hertz with the array being driven from 2.5 to 5.0 miles per hour depending on terrain conditions. This results in a sensor data point spacing of every 7 to 14 centimeters along the survey line.

5.1.2 Data Gaps 408 – Bomblet Target Area

Obstacles within the survey area caused gaps. Since only selected areas and a set percentage of the total area were being collected, these gaps were not recollected within any of the 408 – Bomblet Target Areas.

5.2 CLEAN SLATE

Geophysical data were collected within the Clean Slate sites between the dates of July 11, 2006 and July 25, 2006 using the MKII system described in Section 3.1. All of the MKII data were collected with DGPS and ARCV GPS.

The Clean Slate Site consisted of three separate areas:

- Area 1 – Clean Slate I Fence and Access Road
- Area 2 – Clean Slate II Fence and Access Road
- Area 3 – Clean Slate III Fence and Access Road

5.2.1 Grid System Clean Slate

A traditional grid system was not employed for any of the Clean Slate Areas. Clean Slate consisted of a sweep of three fence lines and corresponding roads with a width of 10 meters. Staking points were used to calculate 10 meters from the fence line, but were not employed on the roads. Total acreage collected in Clean Slate is as follows in Table 5-2.

Table 5-2 Clean Slate Acreage

Clean Slate Area	Acreage	Total
CS I Road	1.37	21.72
CS I Fence	20.35	
CS II Road	1.73	24.20
CS II Fence	22.48	
CS III Road	1.93	28.27
CS III Fence	26.34	
Total Acreage	74.20	

5.2.2 Data Collection Clean Slate

The sampling width of the MKII array was 3 meters. Array paths were separated by 2.8 meters which resulted in 100 % coverage within surveyed areas. EM61 MKII sensor data were recorded at 16 hertz with the array being driven from 2.5 to 5.0 miles per hour depending on terrain conditions. This results in a sensor data point spacing of every 7 to 14 centimeters along the survey line.

5.2.3 Data Gaps Clean Slate

Due to obstacles within the survey area gaps were identified in the data. The locations of collectable gaps were determined and the field technicians returned to these areas to recollect EM data via hand sweeping to ensure maximum coverage. However, several data gaps are present on the final map because the final map only depicts areas which were collected with the towed array and do not include the hand swept area.

5.3 ANTELOPE LAKE

Geophysical data were collected within Antelope Lake between the dates of July 27, 2006 and October 1, 2006 using the MKII system described in Section 3.1. All of the MK2 data were collected with DGPS and ARCV GPS.

5.3.1 Grid System Antelope Lake

The grid areas in Antelope Lake were 200 m by 200 m with a total of 165 grids making up the area with a total collected area of 1384 acres. Table 5-3 details these results.

Table 5-3 Antelope Lake Acreage

Area	Area of Total Polygon (acres)	Collected Area (acres)	Percent Area Covered
1	1384.90	1384.30	99.96
Total	1384.90	1384.30	99.96

5.3.2 Data Collection Antelope Lake

The sampling width of the MKII array was 3 meters. Array paths were separated by 2.8 meters which resulted in 100 % coverage within surveyed areas. EM61 MKII sensor data were recorded at 16 hertz with the array being driven from 2.5 to 5.0 miles per hour depending on terrain conditions. This results in a sensor data point spacing of every 7 to 14 centimeters along the survey line.

5.3.3 Data Gaps Antelope Lake

Due to obstacles within the survey area, gaps were identified in the data. The locations of collectable gaps were determined and the field technicians returned to these areas to recollect EM data to ensure maximum coverage. However, several data gaps are present on the final map because these areas were inaccessible to the towed array.

5.4 PRE-ACQUIRED ANTELOPE LAKE DATA

Per the request of the client, 785 acres of additional data were added north of the 1,300 acres of Antelope Lake data collected by Zapata. These data were collected by a separate contractor who had previously surveyed the northern portion of the playa. Data for this area were provided to Zapata in the form of processed Oasis *.grd files. These files were georeferenced using UTM zone 11 north meters (WGS84) in order to map seamlessly with data collected by Zapata. No further processing, only target selection, was done in this area as Zapata assumed all processing of this data was correct. Table 5-4 details these results.

Table 5-4 Pre – Acquired Antelope Lake Acreage

Area	Area of Total Polygon (acres)	Collected Area (acres)	Percent Area Covered
1	795.08	784.23	98.64
Total	795.08	784.23	98.64

5.4.1 Grid System Pre-Acquired Antelope Lake

No grid system was used for this area.

5.4.2 Data Collection Pre-Acquired Antelope Lake

Once again, data for this area were provided to Zapata in the form of processed Oasis *.grd files. No further processing was done by Zapata.

5.4.3 Data Gaps Pre-Acquired Antelope Lake

All gaps in the data were due to methods used by a previous contractor; no data gaps were filled by Zapata.

5.5 ANTELOPE LAKE FILL-IN

Geophysical data were collected within Antelope Lake Fill-in between the dates of October 2, 2006 to October 9, 2006 using the MKII system described in Section 3.1. All of the MK2 data were collected with DGPS and ARCV GPS.

Data collected in the Antelope Lake Fill-in Site consisted of four separate areas:

- Area 1
- Area 2
- Area 3
- Area 4

5.5.1 Grid System Antelope Lake Fill-in

A traditional grid system was not employed for any of the Antelope Lake Fill-in Sites. The areas in the Antelope Lake Fill-in Sites were additional areas where previous geophysical

investigations by a separate contractor had areas of missing data. Total acreage collected in the Antelope Lake Fill-in is as follows in Table 5-5.

Table 5-5 Antelope Lake Fill-in Acreage

Antelope Lake Fill-in Site Area	Acreage
Area 1	2.58
Area 2	6.19
Area 3	41.34
Area 4	4.64
Total Acreage	54.75

5.5.2 Data Collection Antelope Lake Fill-in

The sampling width of the MKII array was 3 meters. Array paths were separated by 2.8 meters which resulted in 100 % coverage within surveyed areas. EM61 MKII sensor data were recorded at 16 hertz with the array being driven from 2.5 to 5.0 miles per hour depending on terrain conditions. This results in a sensor data point spacing of every 7 to 14 centimeters along the survey line.

5.5.3 Data Gaps Antelope Lake Fill-in

Obstacles within the survey area gaps were identified in the data. No gaps were recollected within any of the Antelope Lake Fill-in Sites.

5.6 DAVIS GUN SITE

Geophysical data were collected within the Davis Gun Site between the dates of August 10, 2006 and October 16, 2006 using the MTADS system described in Section 3.2. All of the MTADS data were collected with DGPS.

The Davis Gun Site consisted of five separate areas:

- Area 1 – Antelope Tuff 2
- Area 2 – Antelope Tuff 1
- Area 3 – Antelope Tuff 1A
- Area 4 – Sidewinder
- Area 5 – Meyers Ridge

5.6.1 Grid System Davis Gun Site

A traditional grid system was not employed for any of the Davis Gun Sites. Known boundaries were given for the Antelope Tuff 2, Antelope Tuff 1, and Antelope Tuff 1A; however, only areas of interest were geophysically surveyed within these areas. Total acreage collected in the Davis Gun Sites area is as follows in Table 5-6

Table 5-6 Davis Gun Acreage

Davis Gun Site Area	Area of Total Polygon (acres)	Collected Area (acres)	Percent Area Covered
Area 1 - Antelope Tuff 2	3.67	2.70	73.57
Area 2 - Antelope Tuff 1	1.32	1.27	96.21
Area 3 - Antelope Tuff 1A	0.01	0.01	100
Area 4 – Sidewinder	16.08	6.89	42.41
Area 5 – Meyers Ridge	2.89	2.64	91.35
Total Acreage	23.96	13.52	56.43

5.6.2 Data Collection Davis Gun Site

The sampling width of the MTADS was 2 meters. Array paths were separated by 1.8 meters which resulted in 100 % coverage within surveyed areas. EM61 MTADS sensor data were recorded at 16 hertz with the array being driven from 1.5 to 4.0 miles per hour depending on terrain conditions. This results in a sensor data point spacing of every 4 to 11 centimeters along the survey line.

5.6.3 Data Gaps Davis Gun Site

Gaps were identified in the data. However, no gaps were recollected within any of the Davis Gun Sites due to obstacles within the survey area, and only selected areas being collected.

5.7 MT. HELEN

Geophysical data were collected within the Mt. Helen area between the dates of August 10, 2006 and October 16, 2006 using the MTADS system described in Section 3.2. All of the MTADS data were collected with DGPS.

The Mt Helen area consisted of three separate areas:

- Area 1 – Mt. Helen 1
- Area 2 – Mt. Helen 2
- Area 3 – Mt. Helen 3

5.7.1 Grid System Mt. Helen

A traditional grid system was not employed for any of the Mt. Helen Sites. The boundaries of the three sub areas were supplied to Zapata in WGS-84 coordinates. Geophysical data were collected within the areas given. Total acreage collected in Mt. Helen is as follows in Table 5-7.

Table 5-7 Mt. Helen Acreage

Mt. Helen Site Area	Area of Total Polygon (acres)	Collected Area (acres)	Percent Area Covered
Area 1 – Mt. Helen 1	2.82	2.79	99.27
Area 2 – Mt. Helen 2	0.027	0.024	88.87
Area 3 – Mt. Helen 3	0.022	0.019	88.54
Total Acreage	2.86	2.84	99.10

5.7.2 Data Collection Mt. Helen

The sampling width of the MTADS was 2 meters. Array paths were separated by 1.8 meters which resulted in 100 % coverage within surveyed areas. EM61 MTADS sensor data were recorded at 16 hertz with the array being driven from 1.5 to 4.0 miles per hour depending on terrain conditions. This results in a sensor data point spacing of every 4 to 11 centimeters along the survey line.

5.7.3 Data Gaps Mt. Helen

Gaps identified in the data were due to obstacles within the survey area. No gaps were recollected within any of the Mt. Helen Sites.

6.0 DATA PROCESSING

Geophysical data were processed, interpreted, analyzed, and displayed using an assortment of software packages including Pythonwin, MagMap2000, and Geosoft Oasis montaj® (Oasis).

6.1 DATA PROCESSING STEPS MKII

Data processing from May 25, 2006 to July 26, 2006 was accomplished using these basic processing steps.

- Raw geophysical data were downloaded from the field computer in two ways.
 - i. Production data were imported using Pythonwin to convert data from the ARCV or Towbot to a format that could be imported into MagMap2000.
 - ii. Test Files were imported into the MagMap2000 program without the use of Pythonwin.
- Data files were exported from MagMap2000 in *.xyz format.
- Data files were imported into the Oasis program, an industry standard UXO data processing software package.
- The shake, static/standard, latency, and six line tests were evaluated for QC compliance.
- Field notes were reviewed for observations such as cultural features and equipment / GPS malfunctions that could affect data quality and interpretation.
- The latency correction was calculated using the positional test.
- A demedian filter of 50-point for static tests, and 200-point (for data from May 25, 2006 – June 5, 2006) and 300-point (data after June 5, 2006) was applied to the geophysical data to remove sensor drift. The motive to modify the demedian filter was a due to the expectation of locating spatially larger anomalies (i.e. penetrators and bomblets.)
- A two-point non-linear filter with a filter tolerance of one was applied to the data to remove spikes.
- The sensor data were gridded using a 0.2-meter cell size and 0.6-meter blanking distance and displayed on the screen in gridded format.

In late July, data processing procedures were slightly modified for the geophysical data collected over the Antelope Lake Site. Data processing from July 27, 2006 to October 9, 2006 was accomplished using these basic processing steps.

- Raw geophysical data were downloaded from the field computer in two ways.
 - iii. Production data were imported using Pythonwin to convert data from the ARCV or Towbot to a format that could be imported into MagMap2000.
 - iv. Test Files were imported into the MagMap2000 program without the use of Pythonwin.

- Data files were exported from MagMap2000 in *.xyz format.
- Data files were imported into the Oasis program, an industry standard UXO processing software package.
- The shake, static/standard, latency, and six line tests were evaluated for QC compliance.
- Field notes were reviewed for observations such as cultural features and equipment / GPS malfunctions that could affect data quality and interpretation.
- Four channels were analyzed, Channel 1, Channel 2, Channel 3, and Top.
- The latency correction was calculated using the positional test.
- A demedian filter of 50-point for static tests, and 300-point for data was applied to the geophysical data to remove sensor drift.
- A two-point non-linear filter with a filter tolerance of one was applied to the data to remove spikes.
- A sum of the demedian of Channels 1, 2, and 3 was calculated into channel Sumdm3.
- The result of the Sumdm3 channel was divided by two into an output channel called Halfsumdmnl. All final data were generated from this channel.
- The sensor data were gridded using a 0.2-meter cell size and 0.6-meter blanking distance and displayed on the screen in gridded format.
- The target-picking threshold was determined based on the mV value needed to detect the seeded targets. It was then compared to the mV response of anomalies within each survey area and targets were then picked on the mV magnitude of the anomaly and its aerial extent.
- Processed data were then outputted as Oasis or *.XYZ formatted files. (For use with the Geosoft Oasis montaj® Viewer)

6.2 DATA PROCESSING PRE-ACQUIRED ANTELOPE LAKE

Per the request of the client, 785 acres of additional data were added north of the 1,300 acres of Antelope Lake data collected by Zapata. These data were collected by a separate contractor who had previously surveyed the northern portion of the playa. Data for this area were provided to Zapata in the form of processed Oasis *.grd files. These files were georeferenced using UTM zone 11 north meters (WGS 84) in order to map seamlessly with data collected by Zapata. No further processing, only target selection, was done in this area as Zapata assumed all processing of this data was correct.

6.3 DATA PROCESSING STEPS MTADS

Data processing from June 6, 2006 to June 7, 2006 and August 10, 2006 to October 18, 2006 was accomplished using these basic processing steps.

- Raw geophysical data were downloaded from the field computer and imported into the MagMap2000 program without the use of Pythonwin.

- Data files were exported from MagMap2000 in *.xyz format.
- Data files were imported into the Oasis program, an industry standard UXO processing software package.
- The shake, static/standard, latency, and six line tests were evaluated for QC compliance.
- Field notes were reviewed for observations such as cultural features and equipment / GPS malfunctions that could affect data quality and interpretation.
- Geophysical sensor data were evaluated in profile format for spikes, gaps, and sensor failure.
- One coil was analyzed Channel 1 data only.
- The latency correction was calculated using the positional test.
- A demedian filter of 50-point for static tests, and 200 (for data from May 25, 2006 – June 5, 2006) and 300 (data after June 5, 2006) was applied to the geophysical data to remove sensor drift. The motive to modify the demedian filter was a result of the large amount of data located within the data files.
- A two-point non-linear filter with a filter tolerance of one was applied to the data to remove spikes.
- The sensor data were gridded using a 0.2 meter cell size and 0.6 meter blanking distance and displayed on the screen in gridded format. The target-picking threshold was determined based on the mV value needed to detect the seeded targets. It was then compared to the mV response of anomalies within each survey area and targets were then picked on the mV magnitude of the anomaly and its aerial extent.
- Processed data were then outputted as Oasis or *.XYZ formatted files. (For use with the Geosoft Oasis montaj® Viewer)

6.4 ANOMALY SELECTION AND MODELING STEPS

Due to the varying types of large anomalies being searched for, multiple techniques were employed to determine if an anomaly was to be selected as a possible candidate for remediation.

The following steps were used for both the MKII and the MTADS data for anomaly selection. Thresholds (based on the GPO report) were customized for each site to interpret specific anomalies being detected (as discussed below.) The anomalies were separated into different types of targets (Bomblets, Penetrators, DU Rings, and Debris Disposal Pits). The following basic parameters were used for each of the sites.

- EM anomalies were selected from the filtered and gridded CH1dmnl data (for MKII data prior to June 6, 2006) Halfsumdmnl data (for MKII data post June 6, 2006) and CH2dmnl data (for MTADS data) using a peak-picking algorithm (Blakely) in Oasis.
- A visual verification of anomaly picks was conducted in Oasis using the gridded data. An output of the final anomalies in *.xls format was generated using WGS 84 UTM Zone 11 N (meters) coordinates, which includes the anomaly location, peak mV value, and a unique ID number.

- The anomaly targets identified within the Antelope Lake Surveys were modeled to estimate the apparent depth of burial and the apparent size of the item causing the anomalies. The modeling routines within the Oasis Geosoft UXO Detect software were used to estimate these parameters. Both routines, Calculate Target Size and Calculate Target Depth, give qualitative data due to the number of assumptions made in the modeling routines. The depth function estimates the apparent depth of an assumed spherical object using a ratio of the top and bottom coil grid data and the instrument coil dimensions. The size function determines the distance from the peak value to the first inflection point in eight directions. The median value of the eight distances is assumed to be half of the target size.
- The anomaly targets identified within the Davis Gun Site using the MTADS data were modeled using TD3D. TD3D is a time-dependent triaxial dipole modeling algorithm developed by Zapata under a SERDP contract. For the MTADS array, the three-sensor, lower coil data were used as input for a single-axis (sphere) model with no time dependence. These modeling results are also to be considered qualitative.

Zapata dug only a limited number of targets, most of which were large bombs. A comparison of target signatures could not be made for the bomblets. It should also be noted that additional anomalies displayed on the maps, but not selected as targets did not meet the established criteria (explained in detail in Section 8.0) for diameter size and/or milliVolt response, hence they were not selected for investigation.

6.4.1 408 – Bomblet Target Area

Targets were selected using 3 mV as the threshold (as per the GPO), but due to the large number of targets selected at this value, the mV value was raised to 5mV for data on June 22, 2006 and the data were reprioritized to show the distribution of targets on June 27, 2006 and June 28, 2006 (less than 5 mV and greater than 5 mV).

6.4.2 Clean Slate

Targets were initially selected using 3 mV, but again due to the large number of targets selected at this value, the threshold was raised as the Clean Slate portion of the project progressed. The target threshold was initially raised to 5 mV and finally to 10 mV (as per the GPO and input from the field managers). The 10 mV range gave the best results for the items of interest.

6.4.3 Antelope Lake

Targets were selected in multiple steps for the Antelope Lake Site.

Targets identified as possible DU rings were selected first. This was done by selecting anomalies with thresholds greater than 50mV and diameters greater than one meter. This method was employed throughout the entire site.

In addition, possible penetrator rounds were identified within the first 63 grids (northern portion of the survey area ~550 acres) of the site. This was done by examining the data with a low threshold (10mV) and selecting anomalies with a diameter of five meters or greater (as per the GPO).

Potential disposal pits were identified within the first 63 grids (~550 acres) of the site. A low threshold (10mV) was again used and anomalies that had geometric shapes were selected. The geometric shapes indicated that the source of these anomalies were most likely man made. In addition, a possible disposal pit was added in grid 156 in the northwest portion of the lake. In this area the land was previously scraped potentially disseminating debris over a wide area.

Finally, bomblets were identified within grids 64 -165 (~ 835 acres) of the site. A threshold between 8 mV and 60 mV was employed for anomaly selection (as per the GPO).

The penetrator and the potential disposal pit sites were then overlain on an aerial map of the area. From this map, possible candidates for remediation were determined.

6.4.4 Anomaly Selection Pre-Acquired Antelope Lake

Targets were selected in multiple steps for the Antelope Lake Site.

Targets identified as possible DU rings were selected first. This was done by selecting anomalies with thresholds greater than 50mV and diameters greater than one meter. This method was employed throughout the entire site.

In addition, possible penetrator rounds were identified within the site. This was done by examining the data with a low threshold (10mV) and selecting anomalies with a diameter of five meters or greater (as per the GPO).

Potential disposal pits were identified within the site. A low threshold (10mV) was again used and anomalies that had geometric shapes were selected. The geometric shapes indicated that the source of these anomalies were most likely man made. Additionally, a disposal site was added near East 528259.0065, North 4172163.1914 due to a cluster of items located at this site.

Finally, bomblets were identified. A threshold between 10 mV and 50 mV was employed for anomaly selection.

The penetrator and the potential disposal pit sites were then overlain on an aerial map of the area. From this map, possible candidates for remediation were determined.

6.4.5 Antelope Lake Fill-in

Possible depleted uranium rings were the objective in areas one through four within Antelope Lake Fill-in. Anomalies with magnitudes of 50 mV or greater and a diameter of 1 meter or greater were selected.

6.4.6 Davis Gun Sites

For Davis Gun Sites, penetrator rounds were the target of interest. For this site a threshold of 15mV was used. Again only targets greater than this threshold with a diameter of a meter or greater were selected. These targets were handpicked.

For Area Four - Sidewinder, an additional map was made at the request of the field managers. The map contained a colorbar with a minimum non-gray value of 15 mV. An anomaly threshold of 15 mV with a diameter of five meters or greater (as per the GPO) was handpicked as a sufficient threshold to detect the penetrators. From this map, field managers determined possible candidates for remediation.

6.4.7 Mt. Helen Sites

Penetrator rounds were the object of interest for the Mt. Helen Sites. Similar to the Davis Gun Sites, anomalies wider than one meter in diameter with responses greater than 15mV were selected. In addition anomalies with diameters greater than 5 m and responses higher than 10 mV were also selected.

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the aforementioned established criteria for diameter size, hence they were not selected for investigation.

7.0 GEOPHYSICAL PROVE OUT RESULTS

ZAPATA conducted a Geophysical Prove Out (GPO) to establish confidence levels prior to calibration activities and to determine survey parameters. This was done in accordance with USACE Data Item Descriptions (DIDs) for conducting the GPO and digital geophysical mapping. The GPO assured the working quality of the personnel, equipment, and methodology used to support the geophysical effort. Additionally, it documented the site-specific capabilities of proposed survey platforms, sensors, navigation equipment, data analysis, data management, QC procedures and associated equipment and personnel to operate as an integrated system capable of meeting data quality objective (DQO) performance goals. The GPO refined DQO's as related to specific ordnance items.

ZAPATA demonstrated geophysical data collection using the autonomous vehicle MKII towed platform. Additionally, ZAPATA demonstrated geophysical data collection using the MTADS System vehicle-towed cart-mounted sensor system, as this system was used for data collection in areas of the volcanic tuff, such as the Davis Gun Sites.

7.1 DATA QUALITY OBJECTIVES (DQO)

The primary data quality objectives (DQO) were to map both ferrous (standard steel ordnance) and non-ferrous (depleted uranium) metal objects within two geologic conditions.

The two types of expected site conditions were:

1. Alluvial Playa – Thick section of fine-grained unconsolidated sediments. Surface conditions are flat with no vegetation.
2. Volcanic Tuff - Welded tuff bedrock with thin to absent soil cover. Surface is generally flat with minimal vegetation. Accumulations of rock debris from excavations may be present.

A GPO grid was established in areas representative of each of the site conditions.

To meet this objective, the geophysical data acquisition was divided into the following four components to demonstrate the objectives of the DQO.

1. Geophysical detection system performance, including sensor platform, positioning system, and operating personnel.
 - Determination of the maximum detection depth for metal targets.
 - Demonstration of the accuracy of the target locations (within a one-meter radius).
 - Demonstration of the ability to avoid a “false negative”.
 - Determination of the required depth of investigation for OE known to exist at the site.
2. Geophysical data management, including data transfer, processing, and storage.
 - The ability to transfer, process, interpret and store data.

3. Anomaly identification and target selection.
 - Determination of the appropriate interpretation threshold value to detect OE items at the required depths.

7.2 GPO DATA INTERPRETATION AND RESULTS

The DQO for geophysical data management required that data be transferred, processed, interpreted, and stored in an appropriate fashion. This DQO was achieved by utilizing one network drive containing appropriately named file folders for each of the data management steps.

7.2.1 MKII Results

GPO's for the MKII were run numerous times on three dates using varying methods. The data processing steps using the GPO data are the same as described in section 6.0 Data Processing. Table 7-1 is a summary of all GPO data collected.

Table 7-1 GPO Results for MKII Tests Conducted Between June 1, 2006 and June 6, 2006

Date	Description	Total Targets Found	Seeded Not Found	Seeded Item Not Used	Seeded at or Below 5mV	Seeded Greater Than 1 Meter	Additional Targets	Additional Targets at or Below 5mV	Seeded at or Below 10mV
6/1/2006	June 1st at 4 MPH	203	4	1	4	6	174	56	n/a
6/1/2006	June 1st at 3.75 MPH	125	4	1	4	5	96	32	n/a
6/1/2006	June 1st at 3 MPH	95	5	1	2	3	66	27	n/a
6/1/2006	June 1st Combined	58	2	1	6	4	29	25	n/a
6/5/2006	Two Coils	132	7	1	5	0	99	68	n/a
6/6/2006	Three Coils (Ch1)	30	6	n/a	2	0	1	1	n/a
6/6/2006	Three Coils (halfsumdmnl)	44	5	n/a	4	0	20	19	n/a

From the results, it was determined that the parameters used on June 6, 2006, both the Channel 1 for (408 and Clean Slate) and the (halfsumdmnl for Antelope Lake and Antelope Lake Holes) would be used as the standard for the MKII portions of the project. These data were determined to be superior in the following manner:

1. Locating accurately a diverse array of targets located at multiple depths
2. Discrimination of target locations within a one-meter radius
3. Ability to avoid “false negatives” within the required depth of investigation for OC known to exist at the site.

Using the Channel 1 data, Zapata detected 23 of the 29 seeded targets within one meter radius from their known locations. Of the items not located, one was at a depth of nine feet, one at eight feet, three at 30 inches, and one at 14 inches. This information is summarized in Table 7-2.

Table 7-2 Results of GPO for MKII Channel 1 on June 6, 2006

Total Number of Seeded Items	29
Number of Located Items	23
Number of Items not Located	6
Number of Located Items from 0.5 to 1.5 Meters of Seeded Item	1
Number of Located Items from 0.2 to 0.5 Meters of Seeded Item	10
Number of Located Items Within .2 Meters of Seeded Item	12

The data from the June 6, 2006 GPO was recalculated using weighting coefficient timegates (halfsumdmnl as the output channel). With this method, Zapata detected 24 of the 29 detectable targets within one meter from their known locations. Of the items not located, one was at a depth of nine feet, three at 30 inches, and one at 42 inches. This information is summarized in Table 7-3.

Table 7-3 Results of GPO for MKII Halfsumdmnl on June 6, 2006

Total Number of Seeded Items	29
Number of Located Items	24
Number of Items not Located	5
Number of Located Items from 0.5 to 1.5 Meters of Seeded Item	2
Number of Located Items from 0.2 to 0.5 Meters of Seeded Item	12
Number of Located Items Within.2 Meters of Seeded Item	10

The DQO does not specify the threshold for data. The target selection of 3 mV was initially chosen as it yielded the best results for anomaly reacquisition with the least amount of false negatives.

7.2.2 MTADS Results

Tests for the MTADS system were initially run on June 7, 2006; however, the GPO for the MTADS system was repeated on August 10, 2006 at a new location. The items within the August 10, 2006 GPO were projectiles located at two depths, 6.5 feet and 8 feet, within volcanic tuff.

The data processing steps using the GPO data are the same as described in Section 6.0 Data Processing. The results for the GPOs for the MTADS system are listed below in Table 7-4.

Table 7-4 GPO Results for MTADS Tests Conducted on June 7, 2006 and August 10, 2006

Date	Description	Total Targets Found	Seeded Not Found	Seeded Item Not Used	Seeded at or Below 5mV	Seeded Greater Than 1 Meter	Additional Targets	Additional Targets at or Below 5mV	Seeded at or Below MTADS Threshold of 5mV	Additional Targets at or Below MTADS Threshold of 5mV
6/7/2006	MTADS @ 3mV	128	6	n/a	2	0	99	68	n/a	n/a
6/7/2006	MTADS @ 5mV	72	6	n/a	n/a	0	43	n/a	3	42
8/10/2006	MTADS Deep Projectile 8 ft In Tuff (1 Pass)	5	0	n/a	n/a	0	4	0	n/a	n/a
8/10/2006	MTADS Deep Projectile 8 ft In Tuff (Multiple Passes)	6	0	n/a	n/a	0	5	0	n/a	n/a
8/10/2006	MTADS Shallow Projectile 6.5 ft In Granite (1 Pass)	4	0	n/a	n/a	0	3	0	n/a	n/a
8/10/2006	MTADS Shallow Projectile 6.5 ft In Tuff (3 Passes)	17	0	n/a	n/a	0	16	0	n/a	n/a
8/10/2006	MTADS Shallow Projectile 6.5 ft In Tuff (4 Passes)	22	0	n/a	n/a	0	21	0	n/a	n/a

From these results, it was determined that due to the depth of the projectiles of concern, a minimum target diameter of one meter, in addition to the target's mV value, would be used to determine the location of possible projectiles for the MTADS portion of the project (i.e. Davis Gun Range, Mt. Helen). It was determined that this approach would be superior in the following manner:

1. Locating accurately a selected type of targets located at shallow depths.
2. Discrimination of target locations within a minimum of one-meter diameter.
3. Ability to avoid "false negatives" within the required depth of investigation for OE known to exist at the site.

8.0 INTERPRETATIONS AND RESULTS

8.1 408 – BOMBLET TARGET AREAS

The 408 – Bomblet Target Areas consisted of three areas totaling a surveyed area of 216.87 acres. The results for each area are listed below.

Each area within 408 – Bomblet Target Areas consisted of one large area in which 10-meter wide swaths were collected covering a minimum of 10 % of the total area. The following data in Table 8-1 were extrapolated. It should also be noted that the original size of the Antelope Lake survey area was reduced during the project from 1543.73 acres to 1183.58 acres

Table 8-1 408 – Bomblet Target Areas

Area	Targets	Threshold	Area of Total Polygon (acres)	Collected Area (acres)	Targets / Acre
Antelope Lake (Original Area)	11022	3 & 5	1543.73	149.84	73.56
Antelope Lake (Modified Area)			1183.58		
Mid-Target	7849	3	314.71	33.81	232.18
SAC	268	3	72.71	33.22	0.09

8.2 CLEAN SLATE

Clean Slate consisted of three areas totaling a surveyed area of 74.20 acres. The results for each area are listed below. Gaps are located within the surveyed areas and were hand-swept. These hand-swept gaps are listed as part of the acreage below.

Each area within Clean Slate consisted of one road and one fence area, with which the following data in Table 8-2 were compiled.

Table 8-2 Clean Slate Results

Clean Slate 1 Data				
Area	Targets	Threshold	Acreage	Total
CS I - Road	188	5	1.37	21.72
CS I- Fence	3073	5	20.35	

Clean Slate 2 Data				
Area	Targets	Threshold	Acreage	Total
CS II- Road	108	3	1.73	24.20
CS II- Fence	606	5 & 10	22.48	

Clean Slate 3 Data				
Area	Targets	Threshold	Acreage	Total
CS III - Road	45	10	1.93	28.27
CS III - Fence	543	10	26.34	

Clean Slate I was the second area completed. All targets within the area were picked at 5 mV. Of the targets selected, 188 were located on the road and 3073 were located along the fence. A total of 21.72 acres were surveyed in this investigation, with 1.37 acres on the road and 20.35 acres along the fence.

Clean Slate II was the first area completed. Targets within the area were picked initially at 5 mV, then at 10 mV for the final 70 targets along the fence. Of the targets selected, 108 were located on the road and 606 were located along the fence. A total of 24.20 acres were surveyed in this investigation, with 1.73 acres on the road and 22.48 acres along the fence.

Clean Slate III was the final area completed. Targets within the area were picked at 10 mV, but only targets above 15 mV were given to the field crews for relocation. Of the targets selected, 45 were located on the road and 543 were located along the fence. A total of 28.27 acres were surveyed in this investigation, with 1.93 acres on the road and 26.34 acres along the fence.

8.3 ANTELOPE LAKE

Targets were selected in multiple steps for the Antelope Lake Site.

Processors initially looked for possible depleted uranium rings located within Antelope Lake at a threshold of 50 mV with a diameter of one meter or greater. This method was employed throughout the entire site. In all, a total of 2503 potential targets were identified within a 1,384.18 acre area. Table 8-3 summarizes the results of the survey.

Table 8-3 Antelope Lake Depleted Uranium Ring Results

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
1	2	906	0.22	9.09
2	17	31872	7.88	2.16
3	19	34749	8.59	2.21
4	10	34927	8.63	1.16
5	29	35093	8.67	3.34
6	48	35296	8.72	5.50
7	68	35331	8.73	7.79
8	23	35641	8.81	2.61
9	22	35883	8.87	2.48
010	14	35863	8.86	1.58
011	6	35982	8.89	0.67
012	4	36242	8.96	0.45
013	5	36429	9.00	0.56
014	6	36581	9.04	0.66
015	11	33818	8.36	1.32
016	1	7317	1.81	0.55
017	6	20393	5.04	1.19
018	11	40000	9.88	1.11
019	8	40000	9.88	0.81
020	18	40000	9.88	1.82
021	42	40000	9.88	4.25
022	23	40000	9.88	2.33
023	24	40000	9.88	2.43
024	21	40000	9.88	2.12
025	6	40000	9.88	0.61
026	19	40000	9.88	1.92
027	7	40000	9.88	0.71
028	1	40000	9.88	0.10
029	7	40000	9.88	0.71
030	16	40000	9.88	1.62
031	3	37547.8	9.28	0.32
032	4	1774.6	0.439	9.11
033	0	2984	0.74	0.00
034	7	37520	9.27	0.76
035	9	40000	9.88	0.91
036	20	40000	9.88	2.02
037	29	40000	9.88	2.93
038	11	40000	9.88	1.11
039	10	40000	9.88	1.01
040	18	40000	9.88	1.82
041	9	40000	9.88	0.91

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
042	22	40000	9.88	2.23
043	9	40000	9.88	0.91
044	12	40000	9.88	1.21
045	8	40000	9.88	0.81
046	17	40000	9.88	1.72
047	7	40000	9.88	0.71
048	0	2993	0.74	0.00
049	5	17196	4.25	1.18
050	9	40000	9.88	0.91
051	12	40000	9.88	1.21
052	8	40000	9.88	0.81
053	34	40000	9.88	3.44
054	11	40000	9.88	1.11
055	10	40000	9.88	1.01
056	30	40000	9.88	3.04
057	8	40000	9.88	0.81
058	72	40000	9.88	7.28
059	15	40000	9.88	1.52
060	20	40000	9.88	2.02
061	16	40000	9.88	1.62
062	2	40000	9.88	0.20
063	3	40000	9.88	0.30
064	0	1122	0.28	0.00
065	11	37882	9.36	1.18
066	9	40000	9.88	0.91
067	8	40000	9.88	0.81
068	8	40000	9.88	0.81
069	3	40000	9.88	0.30
070	11	40000	9.88	1.11
071	17	40000	9.88	1.72
072	8	40000	9.88	0.81
073	11	40000	9.88	1.11
074	32	40000	9.88	3.24
075	25	40000	9.88	2.53
076	9	40000	9.88	0.91
077	12	40000	9.88	1.21
078	2	38474	9.51	0.21
079	1	4920	1.22	0.82
081	9	19349	4.78	1.88
082	10	40000	9.88	1.01
083	15	40000	9.88	1.52
084	5	40000	9.88	0.51
085	9	40000	9.88	0.91
086	21	40000	9.88	2.13

Grid	Targets	Area (m²)	Acre	Targets/ Acre
087	29	40000	9.88	3.64
088	3	40000	9.88	0.30
089	13	40000	9.88	1.32
090	40	40000	9.88	4.05
091	20	40000	9.88	2.02
092	7	40000	9.88	0.71
093	8	40000	9.88	0.81
094	2	40000	9.88	0.20
095	1	7959	1.97	0.51
096	6	2921	0.72	8.33
097	7	36122	8.93	0.78
098	12	40000	9.88	1.21
099	11	40000	9.88	1.11
100	9	40000	9.88	0.91
101	13	40000	9.88	1.32
102	52	40000	9.88	5.26
103	18	40000	9.88	1.82
104	19	40000	9.88	1.92
105	32	40000	9.88	3.24
106	15	40000	9.88	1.52
107	10	40000	9.88	1.01
108	11	40000	9.88	1.11
109	1	30559	7.55	0.13
110	0	654	0.16	0.00
111	1	9845	2.43	0.41
112	3	38118	9.42	0.32
113	4	40000	9.88	0.40
114	40	40000	9.88	4.05
115	17	40000	9.88	1.72
116	27	40000	9.88	2.73
117	27	40000	9.88	2.73
118	57	40000	9.88	5.77
119	16	40000	9.88	1.62
120	5	40000	9.88	0.51
121	6	40000	9.88	0.61
122	3	39829	9.84	0.30
123	0	12837	3.17	0.00
124	7	25430	6.28	1.11
125	16	40000	9.88	1.62
126	24	40000	9.88	2.43
127	56	40000	9.88	5.67
128	33	40000	9.88	3.34
129	88	40000	9.88	8.90
130	29	40000	9.88	2.93

Grid	Targets	Area (m²)	Acre	Targets/ Acre
131	15	40000	9.88	1.52
132	18	40000	9.88	1.82
133	6	40000	9.88	0.61
134	4	28788	7.11	0.56
135	2	5327	1.32	1.52
136	3	39790	9.83	0.31
137	19	40000	9.88	1.92
138	31	40000	9.88	3.14
139	11	40000	9.88	1.11
140	12	40000	9.88	1.21
141	34	40000	9.88	3.44
142	15	40000	9.88	1.52
143	6	40000	9.88	0.61
144	2	38780	9.58	0.21
145	0	6543	1.62	0.00
146	2	14328	3.54	0.56
147	12	40000	9.88	1.21
148	9	40000	9.88	0.91
149	14	40000	9.88	1.42
150	14	40000	9.88	1.42
151	3	40000	9.88	0.30
152	10	40000	9.88	1.01
153	6	37756	9.33	0.64
154	6	12892	3.19	1.88
155	2	3689	0.91	2.19
156	198	23497	5.81	34.08
157	46	29102	7.19	6.40
158	5	38461	9.50	0.53
159	8	40000	9.88	0.81
160	5	35703	8.82	0.57
161	2	17446	4.31	0.46
162	2	3783	0.93	2.14
163	0	3087	0.76	0.00
164	1	11552	2.85	0.35
165	2	2654	0.66	3.05
Total	2503	5601541	1384.18	

Possible penetrator rounds were then identified throughout the entire site using a threshold of 10 mV with a diameter of five meters. In all, a total of 253 potential targets were identified within a 1,384.18 acre area. Table 8-4 summarizes the results of the survey.

Table 8-4 Antelope Lake Penetrator Results

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
1	0	906	0.22	0.00
2	0	31872	7.88	0.00
3	1	34749	8.59	0.12
4	0	34927	8.63	0.00
5	1	35093	8.67	0.12
6	3	35296	8.72	0.34
7	10	35331	8.73	1.15
8	2	35641	8.81	0.23
9	1	35883	8.87	0.11
010	0	35863	8.86	0.00
011	0	35982	8.89	0.00
012	0	36242	8.96	0.00
013	0	36429	9.00	0.00
014	0	36581	9.04	0.00
015	0	33818	8.36	0.00
016	0	7317	1.81	0.00
017	0	20393	5.04	0.00
018	0	40000	9.88	0.00
019	1	40000	9.88	0.10
020	2	40000	9.88	0.20
021	5	40000	9.88	0.51
022	4	40000	9.88	0.40
023	2	40000	9.88	0.20
024	0	40000	9.88	0.00
025	0	40000	9.88	0.00
026	4	40000	9.88	0.40
027	0	40000	9.88	0.00
028	0	40000	9.88	0.00
029	0	40000	9.88	0.00
030	2	40000	9.88	0.20
031	0	37547.8	9.28	0.00
032	1	1774.6	0.439	2.28
033	0	2984	0.74	0.00
034	0	37520	9.27	0.00
035	0	40000	9.88	0.00
036	2	40000	9.88	0.20
037	4	40000	9.88	0.40
038	1	40000	9.88	0.10
039	1	40000	9.88	0.10
040	0	40000	9.88	0.00

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
041	0	40000	9.88	0.00
042	0	40000	9.88	0.00
043	0	40000	9.88	0.00
044	0	40000	9.88	0.00
045	0	40000	9.88	0.00
046	0	40000	9.88	0.00
047	1	40000	9.88	0.10
048	0	2993	0.74	0.00
049	1	17196	4.25	0.24
050	0	40000	9.88	0.00
051	1	40000	9.88	0.10
052	0	40000	9.88	0.00
053	12	40000	9.88	1.21
054	1	40000	9.88	0.10
055	1	40000	9.88	0.10
056	3	40000	9.88	0.30
057	2	40000	9.88	0.20
058	2	40000	9.88	0.20
059	0	40000	9.88	0.00
060	3	40000	9.88	0.30
061	0	40000	9.88	0.00
062	0	40000	9.88	0.00
063	0	40000	9.88	0.00
064	0	1122	0.28	0.00
065	11	37882	9.36	1.18
066	2	40000	9.88	0.20
067	4	40000	9.88	0.40
068	0	40000	9.88	0.00
069	7	40000	9.88	0.71
070	0	40000	9.88	0.00
071	6	40000	9.88	0.61
072	0	40000	9.88	0.00
073	0	40000	9.88	0.00
074	0	40000	9.88	0.00
075	0	40000	9.88	0.00
076	3	40000	9.88	0.30
077	0	40000	9.88	0.00
078	0	38474	9.51	0.00
079	0	4920	1.22	0.00
081	1	19349	4.78	0.21
082	0	40000	9.88	0.00
083	12	40000	9.88	1.21
084	0	40000	9.88	0.00
085	0	40000	9.88	0.00

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
086	5	40000	9.88	0.51
087	7	40000	9.88	0.71
088	0	40000	9.88	0.00
089	0	40000	9.88	0.00
090	18	40000	9.88	1.82
091	0	40000	9.88	0.00
092	0	40000	9.88	0.00
093	0	40000	9.88	0.00
094	0	40000	9.88	0.00
095	0	7959	1.97	0.00
096	0	2921	0.72	0.00
097	0	36122	8.93	0.00
098	0	40000	9.88	0.00
099	17	40000	9.88	1.72
100	3	40000	9.88	0.30
101	2	40000	9.88	0.20
102	8	40000	9.88	0.81
103	4	40000	9.88	0.40
104	8	40000	9.88	0.81
105	8	40000	9.88	0.81
106	7	40000	9.88	0.71
107	0	40000	9.88	0.00
108	1	40000	9.88	0.10
109	0	30559	7.55	0.00
110	0	654	0.16	0.00
111	0	9845	2.43	0.00
112	0	38118	9.42	0.00
113	0	40000	9.88	0.00
114	5	40000	9.88	0.51
115	0	40000	9.88	0.00
116	18	40000	9.88	1.82
117	6	40000	9.88	0.61
118	0	40000	9.88	0.00
119	0	40000	9.88	0.00
120	0	40000	9.88	0.00
121	0	40000	9.88	0.00
122	0	39829	9.84	0.00
123	0	12837	3.17	0.00
124	0	25430	6.28	0.00
125	0	40000	9.88	0.00
126	1	40000	9.88	0.10
127	3	40000	9.88	0.30
128	0	40000	9.88	0.00
129	0	40000	9.88	0.00

Grid	Targets	Area (m ²)	Acre	Targets/ Acre
130	0	40000	9.88	0.00
131	0	40000	9.88	0.00
132	0	40000	9.88	0.00
133	0	40000	9.88	0.00
134	0	28788	7.11	0.00
135	0	5327	1.32	0.00
136	0	39790	9.83	0.00
137	2	40000	9.88	0.20
138	3	40000	9.88	0.30
139	0	40000	9.88	0.00
140	0	40000	9.88	0.00
141	3	40000	9.88	0.30
142	0	40000	9.88	0.00
143	0	40000	9.88	0.00
144	0	38780	9.58	0.00
145	0	6543	1.62	0.00
146	0	14328	3.54	0.00
147	0	40000	9.88	0.00
148	1	40000	9.88	0.10
149	0	40000	9.88	0.00
150	0	40000	9.88	0.00
151	0	40000	9.88	0.00
152	0	40000	9.88	0.00
153	0	37756	9.33	0.00
154	0	12892	3.19	0.00
155	0	3689	0.91	0.00
156	2	23497	5.81	0.34
157	0	29102	7.19	0.00
158	0	38461	9.50	0.00
159	0	40000	9.88	0.00
160	0	35703	8.82	0.00
161	0	17446	4.31	0.00
162	0	3783	0.93	0.00
163	0	3087	0.76	0.00
164	0	11552	2.85	0.00
165	0	2654	0.66	0.00
Total	253	5601541	1384.18	

Potential disposal pits were identified throughout the entire site using a threshold of 10 mV and by looking for geometric shapes (man-made) with a diameter of five meters or greater. In all, a total of 24 potential disposal pit targets were identified within a 1,384.18 acre area. Table 8-5 summarizes the results of the survey.

Table 8-5 Antelope Lake Potential Disposal Pit Results

Grid	Targets	Area (m²)	Acre	Targets/ Acre
1	0	906	0.22	0.00
2	0	31872	7.88	0.00
3	0	34749	8.59	0.00
4	0	34927	8.63	0.00
5	0	35093	8.67	0.00
6	1	35296	8.72	0.11
7	0	35331	8.73	0.00
8	0	35641	8.81	0.00
9	0	35883	8.87	0.00
010	0	35863	8.86	0.00
011	0	35982	8.89	0.00
012	0	36242	8.96	0.00
013	0	36429	9.00	0.00
014	0	36581	9.04	0.00
015	0	33818	8.36	0.00
016	0	7317	1.81	0.00
017	0	20393	5.04	0.00
018	0	40000	9.88	0.00
019	0	40000	9.88	0.00
020	0	40000	9.88	0.00
021	0	40000	9.88	0.00
022	0	40000	9.88	0.00
023	0	40000	9.88	0.00
024	0	40000	9.88	0.00
025	0	40000	9.88	0.00
026	0	40000	9.88	0.00
027	0	40000	9.88	0.00
028	0	40000	9.88	0.00
029	0	40000	9.88	0.00
030	0	40000	9.88	0.00
031	0	37547.824	9.28	0.00
032	0	1774.5762	0.439	0.00
033	0	2984	0.74	0.00
034	0	37520	9.27	0.00
035	0	40000	9.88	0.00
036	0	40000	9.88	0.00
037	0	40000	9.88	0.00
038	0	40000	9.88	0.00
039	0	40000	9.88	0.00
040	0	40000	9.88	0.00
041	0	40000	9.88	0.00

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
042	0	40000	9.88	0.00
043	1	40000	9.88	0.10
044	0	40000	9.88	0.00
045	0	40000	9.88	0.00
046	0	40000	9.88	0.00
047	0	40000	9.88	0.00
048	0	2993	0.74	0.00
049	0	17196	4.25	0.00
050	0	40000	9.88	0.00
051	0	40000	9.88	0.00
052	0	40000	9.88	0.00
053	1	40000	9.88	0.10
054	0	40000	9.88	0.00
055	0	40000	9.88	0.00
056	0	40000	9.88	0.00
057	0	40000	9.88	0.00
058	1	40000	9.88	0.10
059	1	40000	9.88	0.10
060	0	40000	9.88	0.00
061	0	40000	9.88	0.00
062	0	40000	9.88	0.00
063	0	40000	9.88	0.00
064	0	1122	0.28	0.00
065	0	37882	9.36	0.00
066	0	40000	9.88	0.00
067	0	40000	9.88	0.00
068	0	40000	9.88	0.00
069	0	40000	9.88	0.00
070	0	40000	9.88	0.00
071	0	40000	9.88	0.00
072	0	40000	9.88	0.00
073	0	40000	9.88	0.00
074	1	40000	9.88	0.10
075	2	40000	9.88	0.20
076	0	40000	9.88	0.00
077	0	40000	9.88	0.00
078	0	38474	9.51	0.00
079	0	4920	1.22	0.00
081	0	19349	4.78	0.00
082	0	40000	9.88	0.00
083	1	40000	9.88	0.10
084	0	40000	9.88	0.00
085	0	40000	9.88	0.00
086	0	40000	9.88	0.00

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
087	0	40000	9.88	0.00
088	0	40000	9.88	0.00
089	0	40000	9.88	0.00
090	2	40000	9.88	0.20
091	0	40000	9.88	0.00
092	0	40000	9.88	0.00
093	0	40000	9.88	0.00
094	0	40000	9.88	0.00
095	0	7959	1.97	0.00
096	0	2921	0.72	0.00
097	0	36122	8.93	0.00
098	0	40000	9.88	0.00
099	1	40000	9.88	0.10
100	0	40000	9.88	0.00
101	1	40000	9.88	0.10
102	1	40000	9.88	0.10
103	0	40000	9.88	0.00
104	1	40000	9.88	0.10
105	0	40000	9.88	0.00
106	1	40000	9.88	0.10
107	0	40000	9.88	0.00
108	0	40000	9.88	0.00
109	0	30559	7.55	0.00
110	0	654	0.16	0.00
111	0	9845	2.43	0.00
112	0	38118	9.42	0.00
113	1	40000	9.88	0.10
114	1	40000	9.88	0.10
115	0	40000	9.88	0.00
116	1	40000	9.88	0.10
117	1	40000	9.88	0.10
118	2	40000	9.88	0.20
119	0	40000	9.88	0.00
120	0	40000	9.88	0.00
121	0	40000	9.88	0.00
122	0	39829	9.84	0.00
123	0	12837	3.17	0.00
124	0	25430	6.28	0.00
125	0	40000	9.88	0.00
126	0	40000	9.88	0.00
127	0	40000	9.88	0.00
128	0	40000	9.88	0.00
129	0	40000	9.88	0.00
130	0	40000	9.88	0.00

Grid	Targets	Area (m²)	Acre	Targets/ Acre
131	0	40000	9.88	0.00
132	0	40000	9.88	0.00
133	0	40000	9.88	0.00
134	0	28788	7.11	0.00
135	0	5327	1.32	0.00
136	0	39790	9.83	0.00
137	0	40000	9.88	0.00
138	0	40000	9.88	0.00
139	0	40000	9.88	0.00
140	0	40000	9.88	0.00
141	0	40000	9.88	0.30
142	0	40000	9.88	0.00
143	0	40000	9.88	0.00
144	0	38780	9.58	0.00
145	0	6543	1.62	0.00
146	0	14328	3.54	0.00
147	0	40000	9.88	0.00
148	0	40000	9.88	0.00
149	0	40000	9.88	0.00
150	0	40000	9.88	0.00
151	0	40000	9.88	0.00
152	0	40000	9.88	0.00
153	0	37756	9.33	0.00
154	0	12892	3.19	0.00
155	0	3689	0.91	0.00
156	1	23497	5.81	0.17
157	1	29102	7.19	0.14
158	0	38461	9.50	0.00
159	0	40000	9.88	0.00
160	0	35703	8.82	0.00
161	0	17446	4.31	0.00
162	0	3783	0.93	0.00
163	0	3087	0.76	0.00
164	0	11552	2.85	0.00
165	0	2654	0.66	0.00
Total	24	5601541	1384.18	

The potential penetrators and the potential disposal pit sites were then overlain on an aerial map of the area.

Lastly, processors looked for bomblets located throughout the entire site. This was accomplished by using a threshold of 8 mV to 60 mV. In all, a total of 11,118 potential targets were identified within a 1,384.18 acre area. Table 8-6 summarizes the results of the survey.

Table 8-6 Antelope Lake Bomblet Results

Grid	Targets	Area (m ²)	Acre	Targets/ Acre
1	2	906	0.22	9.09
2	104	31872	7.88	13.20
3	82	34749	8.59	9.55
4	36	34927	8.63	4.17
5	124	35093	8.67	14.30
6	333	35296	8.72	38.19
7	204	35331	8.73	23.37
8	183	35641	8.81	20.77
9	129	35883	8.87	14.54
010	66	35863	8.86	7.45
011	83	35982	8.89	9.34
012	29	36242	8.96	3.24
013	16	36429	9.00	1.78
014	17	36581	9.04	1.88
015	23	33818	8.36	2.75
016	3	7317	1.81	1.66
017	93	20393	5.04	18.45
018	95	40000	9.88	9.62
019	114	40000	9.88	11.54
020	106	40000	9.88	10.73
021	220	40000	9.88	22.27
022	215	40000	9.88	21.76
023	259	40000	9.88	26.21
024	108	40000	9.88	10.93
025	37	40000	9.88	3.74
026	34	40000	9.88	3.44
027	30	40000	9.88	3.04
028	21	40000	9.88	2.13
029	22	40000	9.88	2.23
030	33	40000	9.88	3.34
031	24	37547.824	9.28	2.59
032	7	1774.5762	0.439	15.95
033	7	2984	0.74	9.46
034	61	37520	9.27	6.58
035	58	40000	9.88	5.87
036	83	40000	9.88	8.40
037	113	40000	9.88	11.44
038	112	40000	9.88	11.34
039	102	40000	9.88	10.32
040	82	40000	9.88	8.30
041	65	40000	9.88	6.58

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
042	140	40000	9.88	14.17
043	138	40000	9.88	13.97
044	30	40000	9.88	3.04
045	46	40000	9.88	4.66
046	71	40000	9.88	7.19
047	38	40000	9.88	3.85
048	7	2993	0.74	9.46
049	20	17196	4.25	4.71
050	34	40000	9.88	3.44
051	73	40000	9.88	7.39
052	43	40000	9.88	4.35
053	162	40000	9.88	16.40
054	42	40000	9.88	4.25
055	98	40000	9.88	9.92
056	108	40000	9.88	10.93
057	65	40000	9.88	6.58
058	183	40000	9.88	18.52
059	55	40000	9.88	5.57
060	79	40000	9.88	8.00
061	77	40000	9.88	7.79
062	17	40000	9.88	1.72
063	5	40000	9.88	0.51
064	3	1122	0.28	10.82
065	39	37882	9.36	4.17
066	47	40000	9.88	4.76
067	60	40000	9.88	6.07
068	51	40000	9.88	5.16
069	42	40000	9.88	4.25
070	68	40000	9.88	6.88
071	139	40000	9.88	14.07
072	53	40000	9.88	5.36
073	48	40000	9.88	4.86
074	130	40000	9.88	13.16
075	182	40000	9.88	18.42
076	93	40000	9.88	9.41
077	29	40000	9.88	2.93
078	16	38474	9.51	1.68
079	2	4920	1.22	1.64
081	28	19349	4.78	5.86
082	40	40000	9.88	4.05
083	80	40000	9.88	8.10
084	21	40000	9.88	2.12
085	26	40000	9.88	2.63
086	84	40000	9.88	8.50

Grid	Targets	Area (m^2)	Acre	Targets/ Acre
087	91	40000	9.88	9.21
088	58	40000	9.88	5.87
089	104	40000	9.88	10.52
090	237	40000	9.88	24.00
091	209	40000	9.88	21.14
092	46	40000	9.88	4.65
093	21	40000	9.88	2.12
094	12	40000	9.88	1.21
095	2	7959	1.97	1.02
096	0	2921	0.72	0.00
097	57	36122	8.93	6.39
098	30	40000	9.88	3.04
099	68	40000	9.88	6.88
100	78	40000	9.88	7.89
101	105	40000	9.88	10.63
102	184	40000	9.88	18.62
103	97	40000	9.88	9.81
104	66	40000	9.88	6.68
105	180	40000	9.88	18.22
106	82	40000	9.88	8.30
107	67	40000	9.88	6.78
108	30	40000	9.88	3.04
109	22	30559	7.55	2.91
110	1	654	0.16	6.19
111	3	9845	2.43	1.23
112	14	38118	9.42	1.49
113	109	40000	9.88	11.03
114	154	40000	9.88	15.59
115	72	40000	9.88	7.28
116	168	40000	9.88	17.00
117	115	40000	9.88	11.64
118	120	40000	9.88	12.15
119	58	40000	9.88	5.87
120	33	40000	9.88	3.34
121	21	40000	9.88	2.12
122	21	39829	9.84	2.13
123	3	12837	3.17	0.95
124	20	25430	6.28	3.18
125	56	40000	9.88	5.67
126	100	40000	9.88	10.12
127	103	40000	9.88	10.42
128	94	40000	9.88	9.51
129	163	40000	9.88	16.49
130	49	40000	9.88	4.96

Grid	Targets	Area (m ²)	Acre	Targets/ Acre
131	30	40000	9.88	3.04
132	36	40000	9.88	3.64
133	22	40000	9.88	2.23
134	14	28788	7.11	1.97
135	9	5327	1.32	6.84
136	69	39790	9.83	7.02
137	78	40000	9.88	7.89
138	93	40000	9.88	9.41
139	86	40000	9.88	8.70
140	32	40000	9.88	3.24
141	73	40000	9.88	7.39
142	30	40000	9.88	3.04
143	20	40000	9.88	2.02
144	16	38780	9.58	1.67
145	3	6543	1.62	1.86
146	16	14328	3.54	4.52
147	59	40000	9.88	5.97
148	64	40000	9.88	6.47
149	56	40000	9.88	5.67
150	32	40000	9.88	3.24
151	15	40000	9.88	1.52
152	20	40000	9.88	2.02
153	7	37756	9.33	0.75
154	11	12892	3.19	3.45
155	4	3689	0.91	4.39
156	357	23497	5.81	61.49
157	85	29102	7.19	11.82
158	35	38461	9.50	3.68
159	33	40000	9.88	3.34
160	25	35703	8.82	2.83
161	5	17446	4.31	1.16
162	0	3783	0.93	0.00
163	2	3087	0.76	2.62
164	3	11552	2.85	1.05
165	8	2654	0.66	12.20
Total	11118	3379203	835.03	

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response, hence they were not selected for investigation.

8.4 PRE-ACQUIRED ANTELOPE LAKE

Anomalies representing potential depleted uranium rings were identified using a threshold of 50 mV and a diameter of one meter or greater. This method was employed throughout the entire site. In all, a total of 815 potential targets were identified within a ~785 acre area. Table 8-7 summarizes the results of the survey.

Table 8-7 Pre – Acquired Antelope Lake Depleted Uranium Ring Results

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	815	3217555	784.23	1.04
Total	815	3217555	784.23	

Anomalies representing potential penetrator rounds were then identified using a threshold of 10 mV with a diameter of five meters. In all, a total of 673 potential targets were identified within a ~785 acre area. Table 8-8 summarizes the results of the survey.

Table 8-8 Pre – Acquired Antelope Lake Penetrator Results

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	673	3217555	784.23	.86
Total	673	3217555	784.23	

Anomalies representing potential disposal pits were identified using a threshold of 10 mV and by identifying geometric shapes (man-made) with a diameter of five meters or greater. In addition, one area located at approximately East 528259.0065, North 4172163.1914 was also labeled as a potential disposal pit as per discussions with on-site personnel. In all, a total of one potential target was identified within a ~785 acre area. Table 8-9 illustrates the results of the survey.

Table 8-9 Pre – Acquired Antelope Lake Potential Disposal Pit Results

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	1	3217555	784.23	.001
Total	1	3217555	784.23	

Lastly, processors looked for anomalies representing potential bomblets located within the area. This was accomplished by using a threshold of 8 mV to 60 mV. In all, a total of 9,002 potential targets were identified within a ~785 acre area. Table 8-10 illustrates the results of the survey.

Table 8-10 Pre – Acquired Antelope Lake Potential Bomblets Results

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	9002	3217555	784.23	11.47
Total	9002	3217555	784.23	

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response, hence they were not selected for investigation.

8.5 ANTELOPE LAKE FILL-IN

Anomalies representing potential depleted uranium rings were identified within Antelope Lake Fill-in using a threshold of 50 mV and a diameter of one meter or greater. This method was employed throughout the entire site. In all, a total of 143 potential targets were identified within a 54.75 acre area. Table 8-11 summarizes the results of the survey.

Table 8-11 Antelope Lake Fill-in Depleted Uranium Ring Results

Area	Targets	Area (m ²)	Acre	Targets/Acre
1	55	10424	2.58	21.32
2	13	25030.95	6.19	2.10
3	52	167306.1	41.34	8.41
4	23	18761	4.64	0.56
Total	143	18761	54.75	

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response, hence they were not selected for investigation.

8.6 DAVIS GUN SITE

For Davis Gun Sites, anomalies representing potential penetrator rounds were identified using a threshold of 15 mV and a diameter of one meter or greater. In all, a total of 420 potential targets were identified within a 13.52 acre area. Table 8-12 summarizes the results of the survey.

Table 8-12 Davis Gun Penetrator Results

Antelope Tuff 2				
Area	Targets	Area (m ²)	Acre	Targets/Acre
1	98	10925	2.70	36.30
Antelope Tuff 1				
Area	Targets	Area (m ²)	Acre	Targets/Acre
2	74	5154	1.27	58.10
Antelope Tuff 1A				
Area	Targets	Area (m ²)	Acre	Targets/Acre
3	1	28	0.01	144.53
Sidewinder				
Area	Targets	Area (m ²)	Acre	Targets/Acre
4	171	27896	6.89	24.81
Meyers Ridge				
Area	Targets	Area (m ²)	Acre	Targets/Acre
5	76	10700	2.64	28.74
Total	420	54703	13.52	

For Area Four - Sidewinder, the targets were reduced by using a threshold of 10 mV and a diameter of five meters or greater. This reduced the initial target count of 171 potential targets to 33 potential targets for the area. Table 8-13 summarizes the results of the survey.

Table 8-13 Davis Gun Penetrator Results - Sidewinder

Sidewinder				
Area	Targets	Area (m ²)	Acre	Targets/Acre
4 Pen	33	27896	6.89	4.79

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response, hence they were not selected for investigation.

8.7 MT. HELEN

Anomalies with a threshold of 15 mV with a diameter of one meter or greater was used to identify possible penetrator rounds within the Mt. Helen site. This method was employed at each of the three sites. In all, a total of 85 potential targets were identified within a 2.87 acre area. Table 8-14 illustrates the results of the survey.

Table 8-14 Mt. Helen Penetrator Results @ 15 mV and 1 Meter Diameter

Grid	Targets	Area (m ²)	Acre	Targets/Acre
1	79	11394	2.82	28.06
2	3	109	0.03	111.53
3	3	92	0.02	131.46
Total	85	11595	2.87	

Anomalies representing potential penetrator rounds were then examined within the site at a threshold of 10 mV with a diameter of five meters. In all, a total of eight potential targets were identified within a 2.87 acre area. Table 8-15 illustrates the results of the survey.

Table 8-15 Mt. Helen Penetrator Results @ 10 mV and 5 Meter Diameter

Grid	Targets	Area (m ²)	Acre	Targets/Acre
1 Pen	8	11394	2.82	2.84
2 Pen	0	109	0.03	0.00
3 Pen	0	92	0.02	0.00
Total	8	11595	2.87	

It should be noted that additional anomalies displayed on the maps, but not selected as targets, did not meet the established criteria for diameter size and/or milliVolt response, hence they were not selected for investigation.

8.8 GEOGRAPHICAL INFORMATION SYSTEMS (GIS) DATA FORMAT

All data for the aforementioned survey sites within the TTR have been provided to Ms. Tuyet Nguyen of the DOE in GIS formats as per the request of the client via Zapata's FTP site. This data includes the following GIS layers:

1. Arc Info *.tiff - georeferenced
2. Penetrator target picks
3. Bomblet target picks
4. DU ring target picks
5. Disposal pit target picks
6. Survey path coverage

As mentioned in previous sections, the anomaly picks for data collected by Zapata and previous contractors have been processed in the same fashion and that the data are presented in a seamless and consistent manner so that direct comparisons between areas can be made. However, the actual data sets collected, processed and gridded previously by a separate contractor in the northern portion of the playa were assumed correct and no further processing was done by Zapata.

9.0 CONCLUSIONS

This report details the procedures and results of the electromagnetic (EM) survey conducted at the Tonopah Test Range (TTR) near Tonopah, Nevada. ZAPATAENGINEERING P.A., Blackhawk Division (Zapata) personnel performed the survey using two methods. This was done using both an array of three Geonics EM61-MKII (MKII) time domain electromagnetic (TDEM) systems and the Multi-sensor Towed Array Detection System (MTADS). Both the MKII array and the MTADS were coupled to a Real Time Kinematic (RTK) Global Positioning System (GPS). All geophysical data were collected between the dates of May 31, 2006 and October 18, 2006.

The objective of the survey was to utilize the aforementioned EM methods for the detection and acquisition of potential ordnance and explosives (OE), particularly depleted uranium rings, penetrator rounds, and potential disposal pits. The sensor performance, positioning of equipment, data processing, data transfer, and geophysical quality control procedures are explained in detail within this project.

To meet this objective, Zapata performed the following specific tasks:

- Perform GPO's to determine the appropriate parameters for EM surveys.
- Geophysical EM survey to map the distribution and density of buried metal objects (potential UXO items).

Geophysical Prove Out data were collected preceding mass production data collection in order to demonstrate and document the performance of the data acquisition methodology. Through the GPO survey, it was determined that:

- A threshold of 3.0 mV would be initially established to identify possible candidates for remediation.
- This was modified for each area (as discussed in Section 6) to maximize the efficiency of locating: depleted uranium rings, penetrators, and potential disposal pits.
- Both methods of selecting possible candidates for remediation by mV value and diameter of the anomaly were based on the GPOs conducted on June 6, 2006 and August 10, 2006.
- The maximum allowable data gap should equal one grid cell perpendicular to the direction of travel.
- Adequate data management is achieved by utilizing one network drive for all data management steps.
- The potential for additional anomalies outside the surveyed area depends primarily on the density of targets approaching the edges of the data collected.

The digital mapping occurred over the following areas with the following results located in Table 9-1.

Table 9-1 Data Results for Tonopah

Area	Target Type	Targets	mV Range	Minimum Anomaly Size (m)	Acres Processed
408 – Bomblet Target - Antelope Lake	Misc UXO	11022	3 & 5	1	149.84
408 – Bomblet Target – Mid Range	Misc UXO	7849	3	1	33.81
408- Bomblet Target – Sac	Misc UXO	268	3	1	33.22
Clean Slate 1 - Road	Misc UXO	188	5	1	1.37
Clean Slate 1 - Fence	Misc UXO	3073	5	1	20.35
Clean Slate 2 - Road	Misc UXO	108	3	1	1.73
Clean Slate 2 - Fence	Misc UXO	606	5 & 10	1	22.48
Clean Slate 3 - Road	Misc UXO	45	10	1	1.93
Clean Slate 3 - Fence	Misc UXO	543	10	1	26.34
Antelope Lake	Depleted Uranium Rings	2503	50	1	1384.18
Antelope Lake	Possible Disposal Pits	24	10	5	549.16
Antelope Lake	Penetrator	253	10	5	
Antelope Lake	Bomblets	11118	8 - 60	1	835.03
Pre-Acquired Antelope Lake	Depleted Uranium Rings	815	50	1	784.23
Pre-Acquired Antelope Lake	Possible Disposal Pits	1	10	5	
Pre-Acquired Antelope Lake	Penetrator	673	10	5	
Pre-Acquired Antelope Lake	Bomblets	9002	8-60	1	
Antelope Lake Fill-in Area 1	Penetrator	55	50	1	2.58
Antelope Lake Fill-in Area 2	Penetrator	13	50	1	6.19
Antelope Lake Fill-in Area 3	Penetrator	52	50	1	41.34
Antelope Lake Fill-in Area 4	Penetrator	23	50	1	4.64
Davis Gun Area 1 Antelope Tuff 2	Penetrator	98	15	1	2.7
Davis Gun Area 2 Antelope Tuff 1	Penetrator	74	15	1	1.27
Davis Gun Area 3 Antelope Tuff 1A	Penetrator	1	15	1	0.01
Davis Gun Area 4 Sidewinder	Penetrator	171	15	1	6.89
Davis Gun Area 4 Sidewinder Penetrator	Penetrator	33	10	5	
Davis Gun Area 5 Meyers Ridge	Penetrator	76	15	1	2.64
Mt. Helen Area 1	Penetrator	79	15	1	2.82
Mt. Helen Area 1 - Penetrator	Penetrator	8	10	5	
Mt. Helen Area 2	Penetrator	3	15	1	0.03
Mt. Helen Area 2- Penetrator	Penetrator	0	10	5	
Mt. Helen Area 3	Penetrator	3	15	1	0.02
Mt. Helen Area 3 - Penetrator	Penetrator	0	10	5	

Overall, Zapata has performed the preceding to aid in the remediation of the site for future use. In this survey, Zapata used the best available technologies for detection of UXO/OE items, including an autonomous Towbot to mitigate exposure of a tow vehicle operator to potentially hazardous OE. Zapata dug only a limited number of targets, most of which were large bombs. A comparison of target signatures could not be made for the bomblets.

Lastly, networking software can be used in the future in conjunction with the results of the dig results to refine the classification of targets using the dig results.

10.0 CERTIFICATION AND DISCLAIMER

All geophysical data analysis, interpretations, conclusions, and recommendations in this document have been prepared under the supervision of and reviewed by ZAPATAENGINEERING, Blackhawk Division Senior Geophysicists and Engineers.

This geophysical investigation was conducted using sound scientific principles and state-of-the-art technology. A high degree of professionalism was maintained during all aspects of the project from the field investigation and data acquisition, through data processing, interpretation, and reporting. All original field data files, field notes and observations, and other pertinent information are maintained in the project files and are available for the client to review.

A geophysicist's certification of interpreted geophysical conditions comprises a declaration of his/her professional judgment. It does not constitute a warranty or guarantee, expressed or implied, nor does it relieve any other party of its responsibility to abide by contract documents, applicable codes, standards, regulations, or ordinances.

James Hild / Project Manager

Project Manager / Senior Geophysicist
ZAPTATAENGINEERING, P.A.
Blackhawk Division

301 Commercial Road,
Suite B
Golden, Colorado 80401

Phone: (303) 278-8700
Fax: (303) 278-0789
Web: www.blackhawkgeo.com

APPENDIX L

DAVIS GUN TARGETS TABLE

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Pedro Lake	171.8	PL_006	No	EM-61	1.7	0.2	37.43.00.06	-116.41.25.53	527284.1	4174426.2
Pedro Lake	161.2	PL_010	No	EM-61	2.43	0.2	37.43.05.03	-116.41.25.28	527289.7	4174579.5
Pedro Lake	210.3	PL_030	No	EM-61	2.18	0.2	37.42.55.17	-116.41.24.72	527304.4	4174275.7
Pedro Lake	739.8	PL_033	No	EM-61	2.31	0	37.42.58.62	-116.41.24.68	527305.1	4174382.1
Pedro Lake	190.9	PL_050	No	EM-61	2.41	0	37.42.47.36	-116.41.24.30	527315.6	4174034.9
Pedro Lake	423.6	PL_080	No	EM-61	2.37	0.2	37.42.43.02	-116.41.23.89	527326.1	4173901.2
Pedro Lake	18.2	PL_092	No	EM-61	2.29	>4	37.42.42.40	-116.41.23.80	527328.2	4173882.3
Pedro Lake	269.7	PL_127	No	EM-61	2.37	0.2	37.42.55.96	-116.41.23.23	527340.8	4174300.2
Pedro Lake	14	PL_141	No	EM-61	2.19	0.2	37.43.07.32	-116.41.23.07	527343.6	4174650.2
Pedro Lake	15.4	PL_177	No	EM-61	4.29	0.2	37.42.43.90	-116.41.22.37	527363.2	4173928.5
Pedro Lake	33.8	PL_200	No	EM-61	2.99	0	37.43.06.29	-116.41.21.93	527371.6	4174618.7
Pedro Lake	12.3	PL_254	No	EM-61	2.13	0	37.43.08.04	-116.41.21.04	527393.3	4174672.6
Pedro Lake	119.7	PL_290	No	EM-61	2.47	0	37.42.43.40	-116.41.20.77	527402.4	4173913.1
Pedro Lake	11.1	PL_292	No	EM-61	2.15	0.5	37.42.44.71	-116.41.20.73	527403.1	4173953.7
Pedro Lake	20	PL_298	No	EM-61	4.81	0	37.42.58.79	-116.41.20.62	527404.5	4174387.7
Pedro Lake	14.3	PL_303	No	EM-61	3.74	0.2	37.42.57.16	-116.41.20.60	527405.2	4174337.3
Pedro Lake	41.8	PL_314	No	EM-61	2.92	0.3	37.43.03.18	-116.41.20.49	527407.3	4174522.8
Pedro Lake	14.9	PL_333	No	EM-61	3.74	0	37.43.06.06	-116.41.20.30	527411.5	4174611.7
Pedro Lake	119.6	PL_337	No	EM-61	3.17	1.4	37.43.01.11	-116.41.20.29	527412.2	4174459.1
Pedro Lake	17.9	PL_346	No	EM-61	3.76	0.2	37.43.09.36	-116.41.20.20	527413.6	4174713.2
Pedro Lake	2844.2	PL_353	No	EM-61	3.51	0	37.42.41.67	-116.41.20.29	527414.3	4173859.9
Pedro Lake	17	PL_365	No	EM-61	3.65	0.2	37.43.09.85	-116.41.20.06	527417.1	4174728.6
Pedro Lake	66.4	PL_374	No	EM-61	4.18	Unknown	37.42.41.69	-116.41.20.06	527419.9	4173860.6
Pedro Lake	65.6	PL_382	No	EM-61	3.4	1.9	37.43.01.11	-116.41.19.87	527422.7	4174459.1
Pedro Lake	157.9	PL_388	No	EM-61	1.57	0	37.43.06.88	-116.41.19.78	527424.1	4174636.9
Pedro Lake	103.2	PL_390	No	EM-61	3.94	0.2	37.43.10.10	-116.41.19.74	527424.8	4174736.3
Pedro Lake	16.4	PL_394	No	EM-61	2.1	0.3	37.43.10.21	-116.41.19.73	527425.1	4174739.7
Pedro Lake	32.7	PL_395	No	EM-61	4.4	0.2	37.42.42.48	-116.41.19.83	527425.5	4173885.1
Pedro Lake	37	PL_397	No	EM-61	1.4	1.2	37.43.01.43	-116.41.19.75	527425.5	4174468.9
Pedro Lake	24.9	PL_409	No	EM-61	4.09	0	37.43.02.34	-116.41.19.69	527426.9	4174496.9
Pedro Lake	11.2	PL_437	No	EM-61	2.32	0.2	37.43.04.38	-116.41.19.37	527434.6	4174559.9
Pedro Lake	13	PL_438	No	EM-61	2.81	0.2	37.43.03.56	-116.41.19.34	527435.3	4174534.7
Pedro Lake	23	PL_441	No	EM-61	4.49	0.2	37.43.04.15	-116.41.19.31	527436.0	4174552.9
Pedro Lake	25.1	PL_452	No	EM-61	4.71	2.4	37.42.54.97	-116.41.19.18	527440.2	4174270.1
Pedro Lake	270.4	PL_534	No	EM-61	2.41	0.2	37.42.49.64	-116.41.18.54	527456.3	4174105.6
Pedro Lake	20.2	PL_568	No	EM-61	2.17	0.7	37.42.59.49	-116.41.18.16	527464.7	4174409.4
Pedro Lake	13.3	PL_573	No	EM-61	4.28	0.4	37.42.56.18	-116.41.18.14	527465.4	4174307.2
Pedro Lake	13.1	PL_588	No	EM-61	4.22	0.4	37.43.05.72	-116.41.17.99	527468.2	4174601.2
Pedro Lake	228.2	PL_602	No	EM-61	2.51	0.1	37.43.04.83	-116.41.17.82	527472.4	4174573.9
Pedro Lake	12.2	PL_603	No	EM-61	3.6	0	37.43.08.18	-116.41.17.80	527472.6	4174677.1

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Pedro Lake	15.2	PL_625	No	EM-61	3.56	0.2	37.42.47.63	-116.41.17.69	527477.3	4174044.0
Pedro Lake	11	PL_627	No	EM-61	2.27	0.2	37.42.59.24	-116.41.17.64	527477.3	4174401.7
Pedro Lake	21.8	PL_634	No	EM-61	1.87	0	37.43.07.30	-116.41.17.55	527478.7	4174650.2
Pedro Lake	46	PL_672	No	EM-61	2.01	0	37.43.05.35	-116.41.17.07	527490.6	4174590.0
Pedro Lake	11.8	PL_673	No	EM-61	2.74	0.1	37.43.06.53	-116.41.17.07	527490.6	4174626.4
Pedro Lake	15.4	PL_681	No	EM-61	2.2	0.2	37.42.57.99	-116.41.17.05	527492.0	4174363.2
Pedro Lake	545.6	PL_697	No	EM-61	4.27	0.2	37.42.55.76	-116.41.16.86	527496.9	4174294.6
Pedro Lake	10.6	PL_726	No	EM-61	3.33	Unknown	37.42.41.18	-116.41.16.60	527504.6	4173845.2
Pedro Lake	19.3	PL_737	No	EM-61	2.36	0.1	37.42.46.81	-116.41.16.44	527508.1	4174018.8
Pedro Lake	165.9	PL_742	No	EM-61	4.21	0	37.43.02.74	-116.41.16.31	527509.5	4174509.5
Pedro Lake	89.6	PL_773	No	EM-61	3.93	0.2	37.42.46.15	-116.41.16.10	527516.5	4173998.5
Pedro Lake	10.6	PL_795	No	EM-61	4.24	>4	37.42.49.42	-116.41.15.91	527520.7	4174099.3
Pedro Lake	50.9	PL_822	No	EM-61	4.87	0.2	37.42.55.22	-116.41.15.72	527524.8	4174277.9
Pedro Lake	106.4	PL_833	No	EM-61	2.31	0	37.43.05.28	-116.41.15.62	527526.3	4174587.9
Pedro Lake	122.8	PL_870	No	EM-61	3.93	0.2	37.43.08.50	-116.41.15.40	527531.2	4174687.3
Pedro Lake	63.7	PL_873	No	EM-61	2.97	0.2	37.42.57.05	-116.41.15.42	527531.9	4174334.5
Pedro Lake	20.8	PL_878	No	EM-61	4.18	0.4	37.43.05.87	-116.41.15.36	527532.6	4174606.1
Pedro Lake	15.9	PL_901	No	EM-61	3.76	0.2	37.42.51.65	-116.41.15.19	527538.2	4174167.9
Pedro Lake	11.8	PL_910	No	EM-61	3.26	0.2	37.42.38.41	-116.41.15.10	527541.7	4173759.8
Pedro Lake	48.2	PL_912	No	EM-61	4.28	0	37.42.55.49	-116.41.15.03	527541.7	4174286.2
Pedro Lake	105.2	PL_933	No	EM-61	2.3	0.2	37.42.42.31	-116.41.14.80	527548.7	4173880.2
Pedro Lake	20.1	PL_991	No	EM-61	3.32	1	37.42.58.23	-116.41.14.24	527560.6	4174370.9
Pedro Lake	11.2	PL_1012	No	EM-61	2.84	0.1	37.43.10.07	-116.41.14.05	527564.1	4174735.6
Pedro Lake	14.1	PL_1101	No	EM-61	3.85	0.2	37.43.05.70	-116.41.13.24	527584.4	4174601.2
Pedro Lake	39.1	PL_1138	No	EM-61	2.68	0.2	37.43.02.23	-116.41.12.97	527591.4	4174494.1
Pedro Lake	11	PL_1147	No	EM-61	3.89	0.2	37.43.06.13	-116.41.12.90	527592.8	4174614.5
Pedro Lake	48.5	PL_1159	No	EM-61	1.4	0.1	37.43.04.75	-116.41.12.82	527594.9	4174571.8
Pedro Lake	10.3	PL_1195	No	EM-61	3.73	0.2	37.43.08.29	-116.41.12.52	527601.9	4174681.0
Pedro Lake	94	PL_1215	No	EM-61	2.6	0.2	37.42.45.78	-116.41.12.41	527606.8	4173987.3
Pedro Lake	264.1	PL_1229	No	EM-61	5.29	0.9	37.43.08.27	-116.41.12.18	527610.2	4174680.3
Pedro Lake	66.5	PL_1232	No	EM-61	1.93	0.2	37.42.58.11	-116.41.12.21	527610.3	4174367.4
Pedro Lake	2596	PL_1240	No	EM-61	2.15	1.4	37.43.08.24	-116.41.12.12	527611.7	4174679.6
Pedro Lake	104.3	PL_1241	No	EM-61	4.04	0.7	37.43.08.04	-116.41.12.10	527612.1	4174673.3
Pedro Lake	2074.7	PL_1263	No	EM-61	3.03	0.7	37.43.07.93	-116.41.11.97	527615.2	4174669.8
Pedro Lake	41.4	PL_1276	No	EM-61	2.15	0.3	37.42.51.73	-116.41.11.96	527617.3	4174170.7
Pedro Lake	15.6	PL_1300	No	EM-61	2.74	0.2	37.43.03.79	-116.41.11.76	527620.8	4174542.4
Pedro Lake	11	PL_1314	No	EM-61	2.82	>4	37.42.39.92	-116.41.11.78	527622.9	4173806.7
Pedro Lake	44.5	PL_1315	No	EM-61	4.11	0.2	37.42.59.61	-116.41.11.69	527622.9	4174413.6
Pedro Lake	35.8	PL_1319	No	EM-61	3.69	0.5	37.42.59.59	-116.41.11.67	527623.6	4174412.8
Pedro Lake	10.5	PL_1326	No	EM-61	3.54	3.7	37.42.39.85	-116.41.11.69	527625.0	4173804.6

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Pedro Lake	22.6	PL_1327	No	EM-61	5.21	0.1	37.43.09.29	-116.41.11.54	527625.7	4174711.8
Pedro Lake	15.9	PL_1332	No	EM-61	2.35	0.2	37.42.46.41	-116.41.11.58	527627.1	4174006.9
Pedro Lake	23.7	PL_1340	No	EM-61	2.07	0.2	37.42.51.89	-116.41.11.50	527628.5	4174175.6
Pedro Lake	31.3	PL_1344	No	EM-61	2.2	0.2	37.43.08.85	-116.41.11.37	527629.9	4174698.5
Pedro Lake	13.7	PL_1351	No	EM-61	3.77	0.2	37.43.04.95	-116.41.11.33	527631.3	4174578.1
Pedro Lake	34.5	PL_1365	No	EM-61	3.04	0.2	37.43.08.42	-116.41.11.17	527634.8	4174685.2
Pedro Lake	21.5	PL_1369	No	EM-61	3.97	0.2	37.43.04.61	-116.41.11.13	527636.2	4174567.6
Pedro Lake	14.6	PL_1373	No	EM-61	2.25	>4	37.42.58.29	-116.41.11.13	527636.9	4174373.0
Pedro Lake	26.2	PL_1374	No	EM-61	4.24	0	37.43.08.38	-116.41.11.09	527636.9	4174683.8
Pedro Lake	28.3	PL_1379	No	EM-61	2.59	0.8	37.43.05.61	-116.41.11.07	527637.6	4174598.4
Pedro Lake	13.3	PL_1380	No	EM-61	4.72	1	37.43.04.58	-116.41.11.04	527638.3	4174566.9
Pedro Lake	34.9	PL_1411	No	EM-61	4.26	0.2	37.42.44.75	-116.41.10.90	527643.9	4173955.8
Pedro Lake	13.2	PL_1420	No	EM-61	2.35	0.2	37.42.54.32	-116.41.10.74	527646.7	4174250.5
Pedro Lake	25	PL_1442	No	EM-61	3.43	0.2	37.43.07.65	-116.41.10.40	527653.7	4174661.4
Pedro Lake	230.7	PL_1444	No	EM-61	3.56	0.2	37.42.44.78	-116.41.10.47	527654.4	4173956.5
Pedro Lake	15	PL_1447	No	EM-61	4.83	0.6	37.42.51.82	-116.41.10.44	527654.4	4174173.5
Pedro Lake	15.9	PL_1478	No	EM-61	3.3	0.3	37.42.44.59	-116.41.10.21	527660.7	4173950.9
Pedro Lake	13	PL_1494	No	EM-61	2.32	0.2	37.43.09.10	-116.41.09.97	527664.2	4174706.2
Pedro Lake	57.6	PL_1495	No	EM-61	4.28	0	37.42.43.43	-116.41.10.02	527665.6	4173915.2
Pedro Lake	150.3	PL_1500	No	EM-61	4.6	0.2	37.42.46.86	-116.41.09.92	527667.7	4174020.9
Pedro Lake	203.4	PL_1520	No	EM-61	2.14	0.7	37.42.59.99	-116.41.09.66	527672.6	4174425.5
Pedro Lake	17.1	PL_1521	No	EM-61	3.69	0.6	37.42.48.91	-116.41.09.68	527673.3	4174083.9
Pedro Lake	37.9	PL_1529	No	EM-61	3.06	0.7	37.42.54.38	-116.41.09.63	527674.0	4174252.6
Pedro Lake	39.2	PL_1532	No	EM-61	3.09	0.3	37.42.56.83	-116.41.09.58	527674.9	4174328.2
Pedro Lake	17.4	PL_1568	No	EM-61	3.59	0.3	37.42.49.63	-116.41.09.11	527687.3	4174106.3
Pedro Lake	31.3	PL_1576	No	EM-61	3.56	0.2	37.42.50.25	-116.41.08.99	527690.1	4174125.2
Pedro Lake	11.9	PL_1622	No	EM-61	4.24	0.2	37.42.48.18	-116.41.08.40	527704.8	4174061.5
Pedro Lake	18.3	PL_1670	No	EM-61	4.47	0.2	37.42.47.15	-116.41.07.77	527720.2	4174030.0
Pedro Lake	17.3	PL_1676	No	EM-61	3.54	0.5	37.42.50.47	-116.41.07.64	527723.0	4174132.2
Pedro Lake	16.9	PL_1679	No	EM-61	2.42	0.2	37.43.04.57	-116.41.07.58	527723.0	4174566.9
Pedro Lake	100.1	PL_1694	No	EM-61	3.03	0.2	37.42.47.61	-116.41.07.43	527728.6	4174044.0
Pedro Lake	582.4	PL_1702	No	EM-61	2.83	0	37.42.47.56	-116.41.07.34	527730.7	4174042.6
Pedro Lake	36.2	PL_1703	No	EM-61	4.03	0	37.43.08.03	-116.41.07.23	527731.4	4174673.3
Pedro Lake	74.2	PL_1761	No	EM-61	4.32	0	37.43.00.57	-116.41.06.34	527753.8	4174443.7
Pedro Lake	43.9	PL_1788	No	EM-61	2.12	0.2	37.42.47.24	-116.41.05.88	527766.4	4174032.8
Pedro Lake	12.5	PL_1825	No	EM-61	4.26	0.2	37.43.03.64	-116.41.04.99	527786.7	4174538.2
Pedro Lake	12.7	PL_1860	No	EM-61	3.82	0.3	37.43.00.23	-116.41.04.29	527804.2	4174433.2
Pedro Lake	52.3	PL_1862	No	EM-61	2.09	0.2	37.42.45.58	-116.41.04.35	527804.2	4173981.7
Pedro Lake	62	PL_1865	No	EM-61	1.57	0	37.43.07.34	-116.41.04.17	527806.3	4174652.3
Pedro Lake	28	PL_1874	No	EM-61	2.38	0	37.43.07.31	-116.41.03.94	527811.9	4174651.6

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Pedro Lake	56.1	PL_1878	No	EM-61	1.4	0.2	37.42.47.87	-116.41.03.82	527816.8	4174052.4
Pedro Lake	18.9	PL_1899	No	EM-61	1.91	0.5	37.42.50.82	-116.41.03.33	527828.7	4174143.4
Pedro Lake	48	PL_1901	No	EM-61	3.41	0	37.42.59.77	-116.41.03.26	527829.4	4174419.2
Pedro Lake	13.6	PL_1919	No	EM-61	2.52	>4	37.43.09.63	-116.41.02.87	527837.8	4174723.0
Pedro Lake	178.9	PL_2002	No	EM-61	1.65	0	37.42.57.22	-116.41.01.04	527884.0	4174340.8
Pedro Lake	17.2	PL_2007	No	EM-61	3.69	0	37.42.47.48	-116.41.01.02	527885.4	4174040.5
Pedro Lake	109	PL_2019	No	EM-61	3.75	0	37.42.52.52	-116.41.00.72	527892.4	4174195.9
Pedro Lake	30	PL_2063	No	EM-61	1.74	0.2	37.42.52.51	-116.40.58.80	527939.3	4174195.9
Pedro Lake	32.5	PL_2090	No	EM-61	3.01	0.6	37.42.47.38	-116.40.57.42	527973.6	4174037.7
Pedro Lake	17.4	PL_2091	No	EM-61	2.42	0.2	37.42.46.58	-116.40.57.37	527975.0	4174013.2
Pedro Lake	10.8	PL_2111	No	EM-61	2.06	0.7	37.42.46.40	-116.40.56.54	527995.3	4174007.6
Pedro Lake	77.2	PL_2144	No	EM-61	3.72	0.2	37.42.48.88	-116.40.52.61	528091.2	4174084.6
Pedro Lake	139	PL_2153	No	EM-61	2.74	0	37.42.50.52	-116.40.52.00	528106.0	4174134.9
Pedro Lake	545.5	PL_2157	No	EM-61	4.17	1	37.42.50.43	-116.40.51.87	528109.3	4174132.4
Pedro Lake	n/a	PD2	M-117 Bomb	EM-61 and Photo	n/a	n/a			527526.0	4174107.0
Pedro Lake	n/a	PD3	Mk-82 Bomb	EM-61 and Photo	n/a	n/a			527519.0	4174097.0
Pedro Lake	n/a	IM13	M-117 Bomb	EM-61 and Photo	n/a	n/a			527477.0	4174159.0
Pedro Lake	n/a	IM7	Mk-82 Bomb	EM-61 and Photo	n/a	n/a			527987.0	4174054.0
Pedro Lake	n/a	DG area	Scrap Metal	EM-61	n/a	n/a			527393.0	4174566.0
Pedro Lake	n/a	IM1	No	Photo	n/a	n/a			527473.2	4174586.0
Pedro Lake	n/a	IM2	No	Photo	n/a	n/a			527442.5	4174656.0
Pedro Lake	n/a	IM3	No	Photo	n/a	n/a			527534.6	4174683.0
Pedro Lake	n/a	IM4	No	Photo	n/a	n/a			527574.5	4174221.0
Pedro Lake	n/a	IM5	No	Photo	n/a	n/a			527398.9	4174323.0
Pedro Lake	n/a	IM6	No	Photo	n/a	n/a			527357.2	4174352.0
Pedro Lake	n/a	IM8	No	Photo	n/a	n/a			527582.2	4173745.0
Pedro Lake	n/a	IM9	No	Photo	n/a	n/a			527769.8	4174034.0
Pedro Lake	n/a	IM10	No	Photo	n/a	n/a			527724.0	4174046.0
Pedro Lake	n/a	IM11	No	Photo	n/a	n/a			527620.6	4174166.0
Pedro Lake	n/a	IM12	No	Photo	n/a	n/a			527513.2	4174150.0
Pedro Lake	n/a	EM 1711	No	EM-61	n/a	n/a			527289.7	4174587.0
Brownes Lake	527.4	BL_013	No	EM-61	0.79	0.2	37.42.30.57	-116.41.12.82	527598.3	4173518.4
Brownes Lake	25.1	BL_067	No	EM-61	1.62	0	37.42.29.60	-116.41.09.24	527686.0	4173489.0
Brownes Lake	737.6	BL_206	No	EM-61	0.63	0.2	37.42.31.45	-116.41.02.66	527846.9	4173546.5
Brownes Lake	253.7	BL_249	No	EM-61	1.44	0.2	37.42.35.35	-116.41.01.45	527876.3	4173666.6
Brownes Lake	282.7	BL_250	No	EM-61	1.22	0.2	37.42.35.31	-116.41.01.44	527876.5	4173665.6
Brownes Lake	217.9	BL_253	No	EM-61	1.54	0.2	37.42.35.35	-116.41.01.38	527878.0	4173666.6
Brownes Lake	75	BL_257	No	EM-61	1.74	0.2	37.42.35.31	-116.41.01.34	527879.0	4173665.5
Brownes Lake	121.9	BL_264	No	EM-61	1.11	0.2	37.42.36.72	-116.41.01.20	527882.1	4173708.9
Brownes Lake	51.7	BL_267	No	EM-61	2.06	0.2	37.42.36.68	-116.41.01.19	527882.5	4173707.6

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Brownes Lake	1371.9	BL_298	No	EM-61	2.54	0.2	37.42.31.72	-116.41.00.33	527904.1	4173555.1
Brownes Lake	74.4	BL_337	No	EM-61	2.35	0.2	37.42.40.47	-116.40.59.06	527934.3	4173824.8
Brownes Lake	1286.5	BL_338	No	EM-61	1.65	0.2	37.42.40.39	-116.40.59.02	527935.3	4173822.2
Brownes Lake	903.7	BL_339	No	EM-61	1.42	0.2	37.42.40.39	-116.40.58.97	527936.3	4173822.2
Brownes Lake	70.4	BL_340	No	EM-61	2.51	0.2	37.42.40.47	-116.40.58.92	527937.7	4173824.8
Brownes Lake	459.3	BL_501	No	EM-61	1.27	0.2	37.42.35.65	-116.40.51.35	528123.5	4173676.8
North Antelope Lake	28	8493	No	EM-61	2.31	>4	37.41.58.07	-116.41.17.76	527480.8	4172516.6
North Antelope Lake	45.2	8396	No	EM-61	2.18	0	37.41.57.62	-116.41.17.53	527486.4	4172502.6
North Antelope Lake	37.7	7918	No	EM-61	2.11	1.7	37.41.55.35	-116.41.17.25	527493.4	4172432.6
North Antelope Lake	118.4	10056	No	EM-61	2.17	0	37.42.05.93	-116.41.17.15	527494.8	4172758.8
North Antelope Lake	189.7	8129	No	EM-61	4.4	0.2	37.41.56.28	-116.41.17.16	527495.5	4172461.3
North Antelope Lake	465.6	8113	No	EM-61	3.78	0.2	37.41.56.21	-116.41.17.11	527496.9	4172459.2
North Antelope Lake	92.2	8130	No	EM-61	4.68	0.2	37.41.56.28	-116.41.17.11	527496.9	4172461.3
North Antelope Lake	50.6	10335	No	EM-61	2.12	0.2	37.42.08.79	-116.41.17.00	527498.3	4172847.0
North Antelope Lake	51.7	9187	No	EM-61	2.33	0.2	37.42.01.57	-116.41.16.28	527516.5	4172624.4
North Antelope Lake	57.1	10177	No	EM-61	2.15	0.2	37.42.06.79	-116.41.16.23	527517.2	4172785.4
North Antelope Lake	3294.9	9265	No	EM-61	2.76	0	37.42.02.04	-116.41.16.00	527523.5	4172639.1
North Antelope Lake	207.5	8433	No	EM-61	4.18	0.2	37.41.57.80	-116.41.15.98	527524.2	4172508.2
North Antelope Lake	314.5	8446	No	EM-61	3.83	0	37.41.57.86	-116.41.15.98	527524.2	4172510.3
North Antelope Lake	19.3	6595	No	EM-61	1.91	3.7	37.41.50.57	-116.41.15.99	527524.9	4172285.6
North Antelope Lake	26.2	6596	No	EM-61	2.46	2.2	37.41.50.57	-116.41.15.79	527529.8	4172285.6
North Antelope Lake	388.5	8625	No	EM-61	3.41	0	37.41.58.73	-116.41.15.72	527530.5	4172536.9
North Antelope Lake	362.1	8612	No	EM-61	4.39	0	37.41.58.66	-116.41.15.70	527531.2	4172534.8
North Antelope Lake	43.6	6113	No	EM-61	2.19	0.2	37.41.48.51	-116.41.15.54	527536.1	4172221.9
North Antelope Lake	62	6153	No	EM-61	3.25	0.2	37.41.48.69	-116.41.15.39	527539.6	4172227.5
North Antelope Lake	305.7	5368	No	EM-61	2.55	0.2	37.41.45.14	-116.41.14.92	527551.5	4172118.3
North Antelope Lake	103.2	8214	No	EM-61	4.13	0.2	37.41.56.73	-116.41.14.73	527555.0	4172475.3
North Antelope Lake	23.6	5917	No	EM-61	2.45	>4	37.41.47.44	-116.41.14.71	527556.4	4172189.0
North Antelope Lake	119.7	8613	No	EM-61	3.41	0	37.41.58.66	-116.41.14.49	527560.6	4172534.8
North Antelope Lake	62.1	4504	No	EM-61	2.48	0.2	37.41.41.21	-116.41.13.80	527579.5	4171997.2
North Antelope Lake	35.8	3821	No	EM-61	3.27	0	37.41.37.85	-116.41.13.78	527580.2	4171893.6
North Antelope Lake	23.2	7379	No	EM-61	1.47	3.3	37.41.53.34	-116.41.13.60	527583.0	4172371.0
North Antelope Lake	334	9956	No	EM-61	1.65	0	37.42.05.33	-116.41.13.55	527583.0	4172740.6
North Antelope Lake	166.9	9967	No	EM-61	4.81	0	37.42.05.40	-116.41.13.55	527583.0	4172742.7
North Antelope Lake	122	4550	No	EM-61	1.78	0.2	37.41.41.44	-116.41.13.51	527586.5	4172004.2
North Antelope Lake	356.6	9699	No	EM-61	2.68	0.3	37.42.04.01	-116.41.13.39	527587.2	4172700.0
North Antelope Lake	194.9	9706	No	EM-61	4.51	0.4	37.42.04.04	-116.41.13.33	527588.6	4172700.7
North Antelope Lake	103.9	6303	No	EM-61	1.68	0.2	37.41.49.41	-116.41.13.05	527597.0	4172249.9
North Antelope Lake	26.4	9136	No	EM-61	2.98	>4	37.42.01.33	-116.41.12.88	527599.8	4172617.4
North Antelope Lake	245	8951	No	EM-61	5.14	0.2	37.42.00.47	-116.41.12.83	527601.2	4172590.8

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	279.6	8970	No	EM-61	4.36	0.2	37.42.00.54	-116.41.12.83	527601.2	4172592.9
North Antelope Lake	27.2	9137	No	EM-61	3.41	>4	37.42.01.33	-116.41.12.83	527601.2	4172617.4
North Antelope Lake	25.9	6362	No	EM-61	3.18	3.7	37.41.49.61	-116.41.12.65	527606.8	4172256.2
North Antelope Lake	50.7	7365	No	EM-61	2.25	0.2	37.41.53.31	-116.41.12.54	527608.9	4172370.3
North Antelope Lake	120	5986	No	EM-61	2.55	0	37.41.47.75	-116.41.12.48	527611.0	4172198.8
North Antelope Lake	33.1	9981	No	EM-61	2.72	3.2	37.42.05.44	-116.41.12.35	527612.4	4172744.1
North Antelope Lake	359.7	8998	No	EM-61	3.57	0	37.42.00.67	-116.41.12.34	527613.1	4172597.1
North Antelope Lake	301.5	9014	No	EM-61	4.07	0.2	37.42.00.74	-116.41.12.34	527613.1	4172599.2
North Antelope Lake	22.3	9982	No	EM-61	2.97	>4	37.42.05.44	-116.41.12.21	527615.9	4172744.1
North Antelope Lake	69.6	7059	No	EM-61	2.54	0.2	37.41.52.38	-116.41.12.18	527618.0	4172341.6
North Antelope Lake	29.4	9439	No	EM-61	3.23	>4	37.42.02.87	-116.41.12.10	527618.7	4172665.0
North Antelope Lake	24.4	7369	No	EM-61	2.29	>4	37.41.53.31	-116.41.11.86	527625.7	4172370.3
North Antelope Lake	56.5	7483	No	EM-61	2.6	0.2	37.41.53.51	-116.41.11.69	527629.9	4172376.6
North Antelope Lake	70.1	6647	No	EM-61	1.89	0.2	37.41.50.77	-116.41.11.67	527630.6	4172291.9
North Antelope Lake	43.9	7167	No	EM-61	2.17	0.2	37.41.52.67	-116.41.11.66	527630.6	4172350.7
North Antelope Lake	42.4	7370	No	EM-61	1.4	0.2	37.41.53.31	-116.41.11.66	527630.6	4172370.3
North Antelope Lake	86.8	7630	No	EM-61	3.83	0.2	37.41.54.11	-116.41.11.66	527630.6	4172394.8
North Antelope Lake	50.5	3069	No	EM-61	2.43	0.2	37.41.33.46	-116.41.11.66	527632.7	4171758.5
North Antelope Lake	130.2	7484	No	EM-61	1.99	0.2	37.41.53.51	-116.41.11.54	527633.4	4172376.6
North Antelope Lake	70.3	5273	No	EM-61	3.06	0.2	37.41.44.72	-116.41.11.29	527640.4	4172105.7
North Antelope Lake	59.5	6904	No	EM-61	3.11	0.2	37.41.51.81	-116.41.11.24	527641.1	4172324.1
North Antelope Lake	28.7	5253	No	EM-61	2.1	0.2	37.41.44.66	-116.41.11.24	527641.8	4172103.6
North Antelope Lake	18.6	9301	No	EM-61	2.24	0.2	37.42.02.24	-116.41.10.96	527646.7	4172645.4
North Antelope Lake	90.8	2643	No	EM-61	2.7	0.2	37.41.31.82	-116.41.11.06	527647.4	4171708.1
North Antelope Lake	73.5	6069	No	EM-61	2.33	0	37.41.48.20	-116.41.10.99	527647.4	4172212.8
North Antelope Lake	78.2	3908	No	EM-61	2	0.2	37.41.38.36	-116.41.10.86	527651.6	4171909.7
North Antelope Lake	88.6	10201	No	EM-61	3.26	>4	37.42.06.96	-116.41.10.57	527655.8	4172791.0
North Antelope Lake	42.6	4613	No	EM-61	2.78	>4	37.41.41.75	-116.41.10.56	527658.6	4172014.0
North Antelope Lake	150.4	5611	No	EM-61	2.67	0.4	37.41.46.13	-116.41.10.43	527661.4	4172149.1
North Antelope Lake	15.2	4855	No	EM-61	3.78	0.2	37.41.42.90	-116.41.10.39	527662.8	4172049.7
North Antelope Lake	13.8	6539	No	EM-61	3.62	0.2	37.41.50.35	-116.41.10.33	527663.5	4172279.3
North Antelope Lake	13.8	4858	No	EM-61	3.33	0.2	37.41.42.93	-116.41.10.16	527668.4	4172050.4
North Antelope Lake	116.8	5595	No	EM-61	2.58	0.2	37.41.46.06	-116.41.09.57	527682.4	4172147.0
North Antelope Lake	246.1	3715	No	EM-61	4.51	0	37.41.37.04	-116.41.09.55	527683.8	4171869.1
North Antelope Lake	61.2	9204	No	EM-61	2.59	0.2	37.42.01.66	-116.41.09.17	527690.8	4172627.9
North Antelope Lake	133.8	3696	No	EM-61	2.49	0.2	37.41.36.92	-116.41.08.27	527715.3	4171865.6
North Antelope Lake	814.5	7754	No	EM-61	2.18	0.2	37.41.54.64	-116.41.08.17	527716.0	4172411.6
North Antelope Lake	56.8	9007	No	EM-61	2.54	0.2	37.42.00.71	-116.41.08.00	527719.5	4172598.5
North Antelope Lake	353.4	3954	No	EM-61	2.97	0.3	37.41.38.65	-116.41.07.78	527727.2	4171918.8
North Antelope Lake	157.8	10443	No	EM-61	4.63	>4	37.42.11.17	-116.41.07.30	527735.6	4172921.2

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	69.2	6447	No	EM-61	2.3	0.2	37.41.49.89	-116.41.07.30	527737.7	4172265.3
North Antelope Lake	55.3	6442	No	EM-61	2.86	0.2	37.41.49.87	-116.41.07.21	527739.8	4172264.6
North Antelope Lake	57.4	9209	No	EM-61	2.4	0.2	37.42.01.68	-116.41.06.99	527744.0	4172628.6
North Antelope Lake	60	9210	No	EM-61	3	0.2	37.42.01.68	-116.41.06.76	527749.6	4172628.6
North Antelope Lake	52.3	6683	No	EM-61	3.73	0.2	37.41.50.91	-116.41.06.72	527751.7	4172296.8
North Antelope Lake	47.2	4000	No	EM-61	1.6	>4	37.41.38.96	-116.41.06.40	527760.8	4171928.6
North Antelope Lake	35.1	8231	No	EM-61	4.17	0.2	37.41.56.77	-116.41.06.13	527765.7	4172477.4
North Antelope Lake	30.2	6475	No	EM-61	3.91	0.2	37.41.50.07	-116.41.06.10	527767.1	4172270.9
North Antelope Lake	52.8	6377	No	EM-61	2.05	0.2	37.41.49.64	-116.41.06.04	527768.5	4172257.6
North Antelope Lake	12.8	1126	No	EM-61	3.51	>4	37.41.24.45	-116.41.06.06	527770.6	4171481.3
North Antelope Lake	45.4	6214	No	EM-61	2.2	0.2	37.41.48.98	-116.41.05.90	527772.0	4172237.3
North Antelope Lake	108.6	9339	No	EM-61	2.48	0	37.42.02.49	-116.41.05.76	527774.1	4172653.8
North Antelope Lake	65.6	6328	No	EM-61	1.49	0.2	37.41.49.43	-116.41.05.62	527779.0	4172251.3
North Antelope Lake	148.8	7673	No	EM-61	2.78	0.2	37.41.54.27	-116.41.05.51	527781.1	4172400.4
North Antelope Lake	54.1	8404	No	EM-61	2.89	0.2	37.41.57.61	-116.41.05.47	527781.8	4172503.3
North Antelope Lake	66.9	6371	No	EM-61	5.11	0.2	37.41.49.61	-116.41.05.36	527785.3	4172256.9
North Antelope Lake	59.6	7079	No	EM-61	1.67	0.2	37.41.52.45	-116.41.05.17	527789.5	4172344.4
North Antelope Lake	61.7	4056	No	EM-61	2.19	0.2	37.41.39.28	-116.41.05.11	527792.3	4171938.4
North Antelope Lake	35.9	5221	No	EM-61	2.6	0.2	37.41.44.48	-116.41.05.09	527792.3	4172098.7
North Antelope Lake	136.6	8180	No	EM-61	3.38	0.2	37.41.56.52	-116.41.05.01	527793.0	4172469.7
North Antelope Lake	83.7	10451	No	EM-61	2.83	0.7	37.42.11.42	-116.41.04.95	527793.0	4172928.9
North Antelope Lake	269.8	8108	No	EM-61	2.18	0.2	37.41.56.13	-116.41.04.90	527795.8	4172457.8
North Antelope Lake	16.2	7381	No	EM-61	2.22	0.2	37.41.53.31	-116.41.04.83	527797.9	4172371.0
North Antelope Lake	18.9	7416	No	EM-61	4.66	0.2	37.41.53.36	-116.41.04.83	527797.9	4172372.4
North Antelope Lake	86.9	5872	No	EM-61	1.76	0.2	37.41.47.16	-116.41.04.51	527806.3	4172181.3
North Antelope Lake	85.9	5404	No	EM-61	2.42	0.2	37.41.45.27	-116.41.04.46	527807.7	4172123.2
North Antelope Lake	68.1	8577	No	EM-61	4.29	0.2	37.41.58.47	-116.41.04.38	527808.4	4172529.9
North Antelope Lake	69.2	2472	No	EM-61	1.96	0	37.41.31.21	-116.41.04.35	527811.9	4171689.9
North Antelope Lake	156.3	2432	No	EM-61	3.13	0.2	37.41.31.01	-116.41.04.18	527816.1	4171683.6
North Antelope Lake	87.7	9000	No	EM-61	5.14	0.2	37.42.00.65	-116.41.03.91	527819.6	4172597.1
North Antelope Lake	69.9	8339	No	EM-61	2.78	0.2	37.41.57.29	-116.41.03.90	527820.3	4172493.5
North Antelope Lake	29.9	5405	No	EM-61	2.14	0.2	37.41.45.27	-116.41.03.63	527828.0	4172123.2
North Antelope Lake	21.3	7138	No	EM-61	2.72	0	37.41.52.58	-116.41.03.57	527828.7	4172348.6
North Antelope Lake	74.5	6978	No	EM-61	2.24	0.2	37.41.52.08	-116.41.03.32	527835.0	4172333.2
North Antelope Lake	25.7	8763	No	EM-61	1.95	0.2	37.41.59.35	-116.41.03.14	527838.5	4172557.2
North Antelope Lake	74.9	6341	No	EM-61	2.56	0.2	37.41.49.52	-116.41.03.10	527840.6	4172254.1
North Antelope Lake	84.8	8809	No	EM-61	2.99	0.2	37.41.59.58	-116.41.02.83	527846.2	4172564.2
North Antelope Lake	117	6088	No	EM-61	2.55	0.2	37.41.48.31	-116.41.02.76	527849.0	4172217.0
North Antelope Lake	48.5	5781	No	EM-61	1.55	0.2	37.41.46.72	-116.41.02.65	527851.8	4172168.0
North Antelope Lake	45.1	4124	No	EM-61	2.41	0.2	37.41.39.59	-116.41.02.57	527854.6	4171948.2

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	36.5	9607	No	EM-61	2.32	0.2	37.42.03.62	-116.41.02.47	527854.6	4172688.8
North Antelope Lake	128	7285	No	EM-61	2.49	0.2	37.41.53.10	-116.41.02.46	527856.0	4172364.7
North Antelope Lake	207.6	678	No	EM-61	4.06	0.2	37.41.21.62	-116.41.02.50	527858.1	4171394.5
North Antelope Lake	58.8	6668	No	EM-61	2.35	0.2	37.41.50.83	-116.41.02.32	527859.5	4172294.7
North Antelope Lake	43.3	8769	No	EM-61	2.61	0.2	37.41.59.35	-116.41.02.29	527859.5	4172557.2
North Antelope Lake	15.7	8770	No	EM-61	3.09	0.2	37.41.59.35	-116.41.02.09	527864.4	4172557.2
North Antelope Lake	91.6	6083	No	EM-61	4.22	0.2	37.41.48.29	-116.41.01.96	527868.6	4172216.3
North Antelope Lake	47	9793	No	EM-61	2.51	0.2	37.42.04.46	-116.41.01.84	527870.0	4172714.7
North Antelope Lake	72.1	10150	No	EM-61	4.05	0.7	37.42.06.55	-116.41.01.77	527871.4	4172779.1
North Antelope Lake	20.3	8775	No	EM-61	3.21	0.2	37.41.59.37	-116.41.01.77	527872.1	4172557.9
North Antelope Lake	134.9	5818	No	EM-61	2.15	0.2	37.41.46.86	-116.41.01.77	527873.5	4172172.2
North Antelope Lake	65.7	6159	No	EM-61	3.09	0.2	37.41.48.72	-116.41.01.73	527874.2	4172229.6
North Antelope Lake	112.4	5774	No	EM-61	2.2	0.2	37.41.46.70	-116.41.01.37	527883.3	4172167.3
North Antelope Lake	40.1	5197	No	EM-61	2.2	0.2	37.41.44.40	-116.41.01.12	527889.6	4172096.6
North Antelope Lake	88.5	7631	No	EM-61	2.9	0.2	37.41.54.08	-116.41.01.08	527889.6	4172394.8
North Antelope Lake	94.1	1049	No	EM-61	3.4	0.2	37.41.23.80	-116.41.01.01	527894.5	4171461.7
North Antelope Lake	127.4	5129	No	EM-61	2.45	0.2	37.41.44.10	-116.41.00.72	527899.4	4172087.5
North Antelope Lake	99.6	10474	No	EM-61	2.36	0.2	37.42.12.59	-116.41.00.54	527900.8	4172965.3
North Antelope Lake	20.1	10490	No	EM-61	2.08	0.2	37.42.13.70	-116.41.00.48	527902.2	4172999.6
North Antelope Lake	96.4	9602	No	EM-61	3.62	0	37.42.03.59	-116.41.00.50	527902.9	4172688.1
North Antelope Lake	89.6	10307	No	EM-61	2.09	0	37.42.08.02	-116.41.00.42	527904.3	4172824.6
North Antelope Lake	39.5	9658	No	EM-61	2.94	0.2	37.42.03.80	-116.41.00.38	527905.7	4172694.4
North Antelope Lake	90.7	9670	No	EM-61	3.45	0	37.42.03.84	-116.41.00.29	527907.8	4172695.8
North Antelope Lake	324.4	9235	No	EM-61	2.46	0	37.42.01.84	-116.41.00.25	527909.2	4172634.2
North Antelope Lake	90.3	10406	No	EM-61	3.01	0.2	37.42.10.02	-116.41.00.07	527912.7	4172886.2
North Antelope Lake	135.2	5283	No	EM-61	2.47	0.2	37.41.44.74	-116.41.00.12	527914.1	4172107.1
North Antelope Lake	114	5423	No	EM-61	2.04	0.2	37.41.45.31	-116.41.00.12	527914.1	4172124.6
North Antelope Lake	87.1	10478	No	EM-61	3.8	0.2	37.42.12.86	-116.40.59.97	527914.8	4172973.7
North Antelope Lake	141.1	5679	No	EM-61	3.69	0.2	37.41.46.35	-116.41.00.00	527916.9	4172156.8
North Antelope Lake	51.1	9521	No	EM-61	2.36	0	37.42.03.18	-116.40.59.78	527920.4	4172675.5
North Antelope Lake	80.5	642	No	EM-61	2.24	0.2	37.41.21.14	-116.40.59.88	527922.5	4171379.8
North Antelope Lake	60.1	6204	No	EM-61	3.74	0.2	37.41.48.92	-116.40.59.67	527924.6	4172235.9
North Antelope Lake	64.6	31	No	EM-61	3.11	0.2	37.41.14.69	-116.40.59.67	527928.1	4171181.0
North Antelope Lake	72.8	5145	No	EM-61	2.45	0.2	37.41.44.15	-116.40.59.46	527930.2	4172088.9
North Antelope Lake	107.4	5101	No	EM-61	2.95	0.2	37.41.43.92	-116.40.59.35	527933.0	4172081.9
North Antelope Lake	260.2	10334	No	EM-61	2.51	0.2	37.42.08.72	-116.40.59.22	527933.7	4172846.3
North Antelope Lake	155.6	93	No	EM-61	2.64	0.2	37.41.15.19	-116.40.59.41	527934.4	4171196.4
North Antelope Lake	140.2	5105	No	EM-61	1.84	0.2	37.41.43.94	-116.40.59.26	527935.1	4172082.6
North Antelope Lake	67.9	6116	No	EM-61	2.43	0.2	37.41.48.46	-116.40.59.10	527938.6	4172221.9
North Antelope Lake	125.2	10337	No	EM-61	2.16	0.2	37.42.08.74	-116.40.58.93	527940.7	4172847.0

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	121.9	10369	No	EM-61	1.93	0.2	37.42.09.33	-116.40.58.76	527944.9	4172865.2
North Antelope Lake	181.6	7812	No	EM-61	1.69	0.2	37.41.54.91	-116.40.58.65	527949.1	4172420.7
North Antelope Lake	151.8	10063	No	EM-61	3.33	0.2	37.42.05.93	-116.40.58.40	527954.0	4172760.2
North Antelope Lake	104	10182	No	EM-61	1.98	0.2	37.42.06.74	-116.40.58.31	527956.1	4172785.4
North Antelope Lake	50	9337	No	EM-61	2.1	0.2	37.42.02.45	-116.40.58.24	527958.2	4172653.1
North Antelope Lake	92.2	9803	No	EM-61	2.94	0.2	37.42.04.50	-116.40.58.23	527958.2	4172716.1
North Antelope Lake	144.4	8060	No	EM-61	4.02	0.2	37.41.55.95	-116.40.58.21	527959.6	4172452.9
North Antelope Lake	200	10045	No	EM-61	2.12	0.2	37.42.05.79	-116.40.58.17	527959.6	4172756.0
North Antelope Lake	94.2	5959	No	EM-61	3.12	0.2	37.41.47.55	-116.40.58.22	527960.3	4172193.9
North Antelope Lake	122	8061	No	EM-61	3.59	0.2	37.41.55.95	-116.40.58.13	527961.7	4172452.9
North Antelope Lake	75.7	3799	No	EM-61	2.92	0.2	37.41.37.60	-116.40.58.15	527963.1	4171887.3
North Antelope Lake	126.3	3805	No	EM-61	1.95	0.2	37.41.37.62	-116.40.58.06	527965.2	4171888.0
North Antelope Lake	45.1	5935	No	EM-61	3.11	0.2	37.41.47.44	-116.40.57.91	527968.0	4172190.4
North Antelope Lake	25.7	9661	No	EM-61	2.96	0.2	37.42.03.79	-116.40.57.81	527968.7	4172694.4
North Antelope Lake	53.2	10042	No	EM-61	2.47	0.2	37.42.05.74	-116.40.57.80	527968.7	4172754.6
North Antelope Lake	107.4	673	No	EM-61	3.74	0	37.41.21.57	-116.40.57.84	527972.2	4171393.1
North Antelope Lake	45.1	5023	No	EM-61	2.78	0.2	37.41.43.62	-116.40.57.69	527973.6	4172072.8
North Antelope Lake	143.5	5509	No	EM-61	2.46	0.2	37.41.45.66	-116.40.57.66	527974.3	4172135.8
North Antelope Lake	82.4	66	No	EM-61	4.01	0.2	37.41.14.93	-116.40.57.67	527977.1	4171188.7
North Antelope Lake	46.1	9775	No	EM-61	2.11	0.2	37.42.04.33	-116.40.57.46	527977.1	4172711.2
North Antelope Lake	38.7	4694	No	EM-61	3.29	0.2	37.41.42.12	-116.40.57.44	527979.9	4172026.6
North Antelope Lake	53.9	7615	No	EM-61	2.45	0.2	37.41.54.00	-116.40.57.22	527984.1	4172392.7
North Antelope Lake	258.1	9159	No	EM-61	3.27	0.2	37.42.01.38	-116.40.57.19	527984.1	4172620.2
North Antelope Lake	123.2	1393	No	EM-61	1.64	0	37.41.25.90	-116.40.57.31	527984.8	4171526.8
North Antelope Lake	66.4	9097	No	EM-61	3.99	0.2	37.42.01.13	-116.40.57.16	527984.8	4172612.5
North Antelope Lake	44.4	5334	No	EM-61	2.34	0.2	37.41.44.96	-116.40.57.20	527985.5	4172114.1
North Antelope Lake	52.5	9089	No	EM-61	3.41	0	37.42.01.08	-116.40.57.10	527986.2	4172611.1
North Antelope Lake	114.8	4618	No	EM-61	2.65	0.2	37.41.41.73	-116.40.56.93	527992.5	4172014.7
North Antelope Lake	12.1	7843	No	EM-61	3.01	0	37.41.55.00	-116.40.56.84	527993.2	4172423.5
North Antelope Lake	66.9	5262	No	EM-61	2.45	0.2	37.41.44.64	-116.40.56.83	527994.6	4172104.3
North Antelope Lake	233	1561	No	EM-61	1.74	0.2	37.41.26.79	-116.40.56.74	527998.8	4171554.1
North Antelope Lake	45.8	7857	No	EM-61	2.16	0.2	37.41.55.04	-116.40.56.62	527998.8	4172424.9
North Antelope Lake	276.5	2286	No	EM-61	2.25	0.2	37.41.30.44	-116.40.56.69	527999.5	4171666.8
North Antelope Lake	119.6	3847	No	EM-61	1.97	0.2	37.41.37.98	-116.40.56.63	528000.2	4171899.2
North Antelope Lake	38.2	7844	No	EM-61	2.63	0.2	37.41.55.00	-116.40.56.53	528000.9	4172423.5
North Antelope Lake	33.5	4406	No	EM-61	3.13	0.2	37.41.40.66	-116.40.56.51	528003.0	4171981.8
North Antelope Lake	29	4064	No	EM-61	2.85	0.2	37.41.39.32	-116.40.56.48	528003.7	4171940.5
North Antelope Lake	177.8	9287	No	EM-61	1.86	0.2	37.42.02.10	-116.40.55.96	528014.2	4172642.6
North Antelope Lake	117.8	10303	No	EM-61	3.82	0.2	37.42.07.96	-116.40.55.82	528017.0	4172823.2
North Antelope Lake	84	3814	No	EM-61	1.75	0.2	37.41.37.71	-116.40.55.89	528018.4	4171890.8

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	99.3	3723	No	EM-61	2.58	0.2	37.41.37.03	-116.40.55.83	528019.8	4171869.8
North Antelope Lake	256.1	2599	No	EM-61	2.97	0.2	37.41.31.62	-116.40.55.77	528021.9	4171703.2
North Antelope Lake	90.2	8889	No	EM-61	3.75	0.2	37.42.00.06	-116.40.55.45	528026.8	4172579.6
North Antelope Lake	92.9	4756	No	EM-61	4.39	0.2	37.41.42.46	-116.40.55.33	528031.7	4172037.1
North Antelope Lake	179.8	10380	No	EM-61	3.03	0	37.42.09.48	-116.40.55.18	528032.4	4172870.1
North Antelope Lake	123.4	8111	No	EM-61	1.82	0.2	37.41.56.13	-116.40.55.21	528033.1	4172458.5
North Antelope Lake	174	4310	No	EM-61	3.59	0.2	37.41.40.32	-116.40.55.16	528035.9	4171971.3
North Antelope Lake	97.1	4428	No	EM-61	3.93	0.2	37.41.40.77	-116.40.55.16	528035.9	4171985.3
North Antelope Lake	199.6	5581	No	EM-61	1.78	0.2	37.41.45.95	-116.40.55.02	528038.7	4172144.9
North Antelope Lake	63.5	309	No	EM-61	2.46	0.2	37.41.16.58	-116.40.55.12	528039.4	4171239.8
North Antelope Lake	105.5	4710	No	EM-61	3.92	0.2	37.41.42.20	-116.40.54.90	528042.2	4172029.4
North Antelope Lake	67.3	9211	No	EM-61	2.43	0	37.42.01.65	-116.40.54.81	528042.2	4172628.6
North Antelope Lake	117.3	8006	No	EM-61	3.82	0.2	37.41.55.72	-116.40.54.81	528042.9	4172445.9
North Antelope Lake	131.5	4136	No	EM-61	2.69	0.2	37.41.39.66	-116.40.54.82	528044.3	4171951.0
North Antelope Lake	59.1	9470	No	EM-61	2.6	0.2	37.42.02.96	-116.40.54.61	528047.1	4172669.2
North Antelope Lake	56.1	6685	No	EM-61	2.36	0.2	37.41.50.88	-116.40.54.55	528049.9	4172296.8
North Antelope Lake	47.5	10446	No	EM-61	2.62	>4	37.42.11.19	-116.40.54.40	528051.3	4172922.6
North Antelope Lake	83.7	385	No	EM-61	2.38	0.2	37.41.17.13	-116.40.54.55	528053.4	4171256.6
North Antelope Lake	67.1	5099	No	EM-61	2.79	0.2	37.41.43.88	-116.40.54.38	528054.8	4172081.2
North Antelope Lake	67.2	5109	No	EM-61	1.4	0.2	37.41.43.95	-116.40.54.29	528056.9	4172083.3
North Antelope Lake	64.9	4009	No	EM-61	3.27	0.2	37.41.38.95	-116.40.54.23	528059.0	4171929.3
North Antelope Lake	98.8	2009	No	EM-61	2.48	0	37.41.29.05	-116.40.54.10	528063.2	4171624.1
North Antelope Lake	78.5	4768	No	EM-61	2.3	0.2	37.41.42.52	-116.40.53.84	528068.1	4172039.2
North Antelope Lake	25.9	7155	No	EM-61	2.84	0.2	37.41.52.58	-116.40.53.74	528069.5	4172349.3
North Antelope Lake	120.4	10119	No	EM-61	1.68	0.2	37.42.06.34	-116.40.53.51	528073.7	4172773.5
North Antelope Lake	329.6	3947	No	EM-61	3.47	0.7	37.41.38.54	-116.40.53.51	528076.5	4171916.7
North Antelope Lake	81.1	5417	No	EM-61	3.09	0.2	37.41.45.27	-116.40.53.48	528076.5	4172123.9
North Antelope Lake	53.2	9376	No	EM-61	2.5	0	37.42.02.60	-116.40.53.41	528076.5	4172658.0
North Antelope Lake	65	4338	No	EM-61	2.87	0.2	37.41.40.43	-116.40.53.48	528077.2	4171974.8
North Antelope Lake	65.1	4281	No	EM-61	2.87	0.2	37.41.40.18	-116.40.53.45	528077.9	4171967.1
North Antelope Lake	104.6	3054	No	EM-61	2.75	0.2	37.41.33.36	-116.40.53.28	528082.8	4171757.1
North Antelope Lake	75.8	4085	No	EM-61	2.4	0.2	37.41.39.38	-116.40.53.19	528084.2	4171942.6
North Antelope Lake	72.2	7247	No	EM-61	4.28	0.2	37.41.52.92	-116.40.53.11	528084.9	4172359.8
North Antelope Lake	46.5	2475	No	EM-61	3.16	0	37.41.31.18	-116.40.53.14	528086.3	4171689.9
North Antelope Lake	57.6	9331	No	EM-61	3.82	0.2	37.42.02.39	-116.40.53.01	528086.3	4172651.7
North Antelope Lake	56.6	9437	No	EM-61	3.36	0.2	37.42.02.80	-116.40.52.92	528088.4	4172664.3
North Antelope Lake	108.4	2293	No	EM-61	2.79	0.2	37.41.30.46	-116.40.53.03	528089.1	4171667.5
North Antelope Lake	58.2	4179	No	EM-61	2.77	0.1	37.41.39.81	-116.40.52.94	528090.5	4171955.9
North Antelope Lake	97.9	9332	No	EM-61	3.12	0	37.42.02.39	-116.40.52.84	528090.5	4172651.7
North Antelope Lake	276.8	3728	No	EM-61	1.73	0.2	37.41.37.04	-116.40.52.92	528091.2	4171870.5

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	156.7	8687	No	EM-61	1.82	0.2	37.41.59.01	-116.40.52.80	528091.9	4172547.4
North Antelope Lake	77	683	No	EM-61	2.58	0.2	37.41.21.64	-116.40.52.90	528093.3	4171395.9
North Antelope Lake	70	5727	No	EM-61	2.62	0.2	37.41.46.51	-116.40.52.74	528094.7	4172162.4
North Antelope Lake	100.4	2519	No	EM-61	2.23	0.2	37.41.31.30	-116.40.52.77	528095.4	4171693.4
North Antelope Lake	117.4	4649	No	EM-61	2.57	0.2	37.41.41.86	-116.40.52.64	528097.5	4172018.9
North Antelope Lake	893.1	170	No	EM-61	2.52	0	37.41.15.71	-116.40.52.58	528101.7	4171213.2
North Antelope Lake	192.4	7864	No	EM-61	3.25	0.2	37.41.55.05	-116.40.52.30	528104.5	4172425.6
North Antelope Lake	276.4	8153	No	EM-61	3.53	0.2	37.41.56.30	-116.40.52.29	528104.5	4172464.1
North Antelope Lake	98.6	4016	No	EM-61	2.7	>4	37.41.38.97	-116.40.52.28	528106.6	4171930.0
North Antelope Lake	267.2	10458	No	EM-61	1.7	0.5	37.42.11.50	-116.40.52.14	528106.6	4172932.4
North Antelope Lake	54.6	9351	No	EM-61	2.62	0.2	37.42.02.50	-116.40.52.12	528108.0	4172655.2
North Antelope Lake	78.3	319	No	EM-61	1.87	0.2	37.41.16.64	-116.40.51.72	528122.7	4171241.9
North Antelope Lake	94.7	4453	No	EM-61	4.23	0.2	37.41.40.90	-116.40.51.59	528123.4	4171989.5
North Antelope Lake	94.5	8796	No	EM-61	4.14	0.2	37.41.59.41	-116.40.51.51	528123.4	4172560.0
North Antelope Lake	35.5	3960	No	EM-61	2.51	1.6	37.41.38.63	-116.40.51.37	528129.0	4171919.5
North Antelope Lake	148.5	2101	No	EM-61	3.06	0.2	37.41.29.52	-116.40.51.26	528132.5	4171638.8
North Antelope Lake	111.5	9106	No	EM-61	1.92	0	37.42.01.16	-116.40.51.10	528133.2	4172613.9
North Antelope Lake	174.8	3699	No	EM-61	2.83	0.2	37.41.36.88	-116.40.50.98	528138.8	4171865.6
North Antelope Lake	109.8	4187	No	EM-61	2.4	0.2	37.41.39.83	-116.40.50.82	528142.3	4171956.6
North Antelope Lake	36.2	7127	No	EM-61	2.77	0.2	37.41.52.50	-116.40.50.68	528144.4	4172347.2
North Antelope Lake	54	4219	No	EM-61	2	0.2	37.41.39.94	-116.40.50.71	528145.1	4171960.1
North Antelope Lake	47.3	4271	No	EM-61	3.92	0.2	37.41.40.13	-116.40.50.70	528145.1	4171965.7
North Antelope Lake	80.8	4396	No	EM-61	3.94	0.2	37.41.40.60	-116.40.50.65	528146.5	4171980.4
North Antelope Lake	20.9	7128	No	EM-61	3.96	0.2	37.41.52.50	-116.40.50.59	528146.5	4172347.2
North Antelope Lake	85.2	4272	No	EM-61	3.18	0.2	37.41.40.13	-116.40.50.62	528147.2	4171965.7
North Antelope Lake	38.6	4233	No	EM-61	4.28	0.2	37.41.39.97	-116.40.50.59	528147.9	4171960.8
North Antelope Lake	42.4	6487	No	EM-61	3.61	0.2	37.41.50.07	-116.40.50.52	528148.6	4172272.3
North Antelope Lake	75.9	3045	No	EM-61	1.78	1.4	37.41.33.31	-116.40.50.56	528149.3	4171755.7
North Antelope Lake	31.8	10243	No	EM-61	2.17	>4	37.42.07.36	-116.40.50.42	528149.3	4172805.0
North Antelope Lake	44.4	7165	No	EM-61	3.5	>4	37.41.52.59	-116.40.50.42	528150.7	4172350.0
North Antelope Lake	109.3	3329	No	EM-61	1.62	0.2	37.41.34.51	-116.40.50.47	528151.4	4171792.8
North Antelope Lake	148.4	10147	No	EM-61	4.08	0	37.42.06.50	-116.40.50.33	528151.4	4172778.4
North Antelope Lake	151.6	918	No	EM-61	3.79	0.2	37.41.22.93	-116.40.50.46	528152.8	4171435.8
North Antelope Lake	110.8	8172	No	EM-61	2.86	0.2	37.41.56.41	-116.40.50.32	528152.8	4172467.6
North Antelope Lake	40.8	9019	No	EM-61	2.14	0	37.42.00.68	-116.40.50.25	528154.2	4172599.2
North Antelope Lake	115.9	745	No	EM-61	1.81	0.2	37.41.21.98	-116.40.50.30	528157.0	4171406.4
North Antelope Lake	2513.1	2255	No	EM-61	4.32	0.3	37.41.30.27	-116.40.50.09	528161.2	4171661.9
North Antelope Lake	56.6	9579	No	EM-61	3.2	0.2	37.42.03.45	-116.40.49.89	528162.6	4172684.6
North Antelope Lake	16.4	6816	No	EM-61	3.48	>4	37.41.51.39	-116.40.49.91	528163.3	4172312.9
North Antelope Lake	213.6	1640	No	EM-61	2.44	0	37.41.27.18	-116.40.49.99	528164.0	4171566.7

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	364.1	4762	No	EM-61	3.8	0	37.41.42.49	-116.40.49.75	528168.2	4172038.5
North Antelope Lake	93.3	9382	No	EM-61	4.05	0.2	37.42.02.61	-116.40.49.61	528169.6	4172658.7
North Antelope Lake	196	8816	No	EM-61	1.82	0.2	37.41.59.57	-116.40.49.48	528173.1	4172564.9
North Antelope Lake	113.7	9093	No	EM-61	2.69	0.2	37.42.01.06	-116.40.49.27	528178.0	4172611.1
North Antelope Lake	181.8	3205	No	EM-61	3.64	0.3	37.41.33.94	-116.40.49.27	528180.8	4171775.3
North Antelope Lake	209.5	9946	No	EM-61	2.11	0.2	37.42.05.17	-116.40.49.14	528180.8	4172737.8
North Antelope Lake	112.6	1398	No	EM-61	1.95	0	37.41.25.90	-116.40.49.22	528182.9	4171527.5
North Antelope Lake	100.4	3033	No	EM-61	3.6	0.5	37.41.33.24	-116.40.49.16	528183.6	4171753.6
North Antelope Lake	160.7	2960	No	EM-61	2.74	0.5	37.41.32.92	-116.40.49.02	528187.1	4171743.8
North Antelope Lake	98.6	3237	No	EM-61	3.65	0.2	37.41.34.08	-116.40.49.02	528187.1	4171779.5
North Antelope Lake	174	8009	No	EM-61	2.45	0.2	37.41.55.73	-116.40.48.92	528187.1	4172446.6
North Antelope Lake	97.6	8800	No	EM-61	3.93	0.2	37.41.59.45	-116.40.48.85	528188.5	4172561.4
North Antelope Lake	115	8801	No	EM-61	3.76	0	37.41.59.45	-116.40.48.76	528190.6	4172561.4
North Antelope Lake	25.7	10384	No	EM-61	2.9	0.2	37.42.09.67	-116.40.48.29	528201.1	4172876.4
North Antelope Lake	537.4	2811	No	EM-61	3.13	0	37.41.32.42	-116.40.48.42	528201.8	4171728.4
North Antelope Lake	84.9	2792	No	EM-61	2.8	0.4	37.41.32.31	-116.40.48.39	528202.5	4171724.9
North Antelope Lake	59.7	3465	No	EM-61	2.69	0.4	37.41.35.19	-116.40.48.18	528207.4	4171813.8
North Antelope Lake	202.4	1711	No	EM-61	4.52	3.4	37.41.27.51	-116.40.48.16	528208.8	4171577.2
North Antelope Lake	104.8	8581	No	EM-61	2.29	0.2	37.41.58.45	-116.40.48.02	528208.8	4172530.6
North Antelope Lake	153.1	8379	No	EM-61	2.9	0.2	37.41.57.40	-116.40.48.00	528209.5	4172498.4
North Antelope Lake	69.7	8359	No	EM-61	2.24	0.8	37.41.57.31	-116.40.47.97	528210.2	4172495.6
North Antelope Lake	42521.5	1701	No	EM-61	4.65	0.4	37.41.27.47	-116.40.47.87	528215.8	4171575.8
North Antelope Lake	71.9	8450	No	EM-61	2.61	0.2	37.41.57.79	-116.40.47.68	528217.2	4172510.3
North Antelope Lake	50453.5	1691	No	EM-61	2.88	0.3	37.41.27.40	-116.40.47.79	528217.9	4171573.7
North Antelope Lake	217.3	2541	No	EM-61	3.31	0.5	37.41.31.35	-116.40.47.77	528217.9	4171695.5
North Antelope Lake	1292.8	1673	No	EM-61	6.43	3.8	37.41.27.31	-116.40.47.76	528218.6	4171570.9
North Antelope Lake	63.1	2572	No	EM-61	6.6	0.4	37.41.31.49	-116.40.47.71	528219.3	4171699.7
North Antelope Lake	123.1	7315	No	EM-61	2.94	0.2	37.41.53.11	-116.40.47.62	528219.3	4172366.1
North Antelope Lake	199.2	2554	No	EM-61	2.04	0.5	37.41.31.40	-116.40.47.68	528220.0	4171696.9
North Antelope Lake	186.3	2566	No	EM-61	2.47	0.8	37.41.31.44	-116.40.47.66	528220.7	4171698.3
North Antelope Lake	160.7	5323	No	EM-61	2.84	0.2	37.41.44.89	-116.40.47.60	528220.7	4172112.7
North Antelope Lake	105.2	2435	No	EM-61	1.4	0	37.41.30.96	-116.40.47.63	528221.4	4171683.6
North Antelope Lake	115.8	2588	No	EM-61	1.66	0.3	37.41.31.55	-116.40.47.63	528221.4	4171701.8
North Antelope Lake	52.9	1726	No	EM-61	1.4	3	37.41.27.60	-116.40.47.61	528222.1	4171580.0
North Antelope Lake	39	2490	No	EM-61	2.3	0.2	37.41.31.21	-116.40.47.60	528222.1	4171691.3
North Antelope Lake	289.6	3694	No	EM-61	4.87	0.4	37.41.36.85	-116.40.47.52	528223.5	4171864.9
North Antelope Lake	120.5	3357	No	EM-61	1.4	0	37.41.34.67	-116.40.47.50	528224.2	4171797.7
North Antelope Lake	315.8	1474	No	EM-61	3.11	0.2	37.41.26.24	-116.40.47.51	528224.9	4171538.0
North Antelope Lake	564.7	2423	No	EM-61	2.35	1.2	37.41.30.92	-116.40.47.46	528225.6	4171682.2
North Antelope Lake	363.3	390	No	EM-61	3.19	0	37.41.17.13	-116.40.47.49	528226.3	4171257.3

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	49.4	1692	No	EM-61	4.25	0.2	37.41.27.40	-116.40.47.44	528226.3	4171573.7
North Antelope Lake	51.5	331	No	EM-61	2.26	1.8	37.41.16.72	-116.40.47.40	528228.4	4171244.7
North Antelope Lake	908.7	2409	No	EM-61	2.62	3.1	37.41.30.85	-116.40.47.29	528229.8	4171680.1
North Antelope Lake	137	5427	No	EM-61	1.46	0.8	37.41.45.27	-116.40.47.22	528229.8	4172124.6
North Antelope Lake	81	3174	No	EM-61	1.89	0.2	37.41.33.76	-116.40.47.24	528230.5	4171769.7
North Antelope Lake	29.2	10174	No	EM-61	2.81	0.2	37.42.06.67	-116.40.46.93	528234.7	4172784.0
North Antelope Lake	77.3	1137	No	EM-61	1.95	0.2	37.41.24.51	-116.40.47.03	528236.8	4171484.8
North Antelope Lake	35	2215	No	EM-61	5.6	0	37.41.30.08	-116.40.47.00	528236.8	4171656.3
North Antelope Lake	51.9	88	No	EM-61	3.81	2.2	37.41.15.09	-116.40.47.04	528237.5	4171194.3
North Antelope Lake	23.1	2193	No	EM-61	3.28	1.7	37.41.29.96	-116.40.46.92	528238.9	4171652.8
North Antelope Lake	119.1	2542	No	EM-61	2.3	0.2	37.41.31.35	-116.40.46.88	528239.6	4171695.5
North Antelope Lake	230.6	5521	No	EM-61	4.17	0.8	37.41.45.66	-116.40.46.82	528239.6	4172136.5
North Antelope Lake	48.1	8326	No	EM-61	2.24	0.2	37.41.57.15	-116.40.46.77	528239.6	4172490.7
North Antelope Lake	46.5	2189	No	EM-61	4.09	3	37.41.29.94	-116.40.46.83	528241.0	4171652.1
North Antelope Lake	19721.7	2242	No	EM-61	3.59	2.4	37.41.30.19	-116.40.46.83	528241.0	4171659.8
North Antelope Lake	107.8	4128	No	EM-61	1.83	0	37.41.39.57	-116.40.46.79	528241.0	4171948.9
North Antelope Lake	94.9	4515	No	EM-61	1.67	0.2	37.41.41.18	-116.40.46.78	528241.0	4171998.6
North Antelope Lake	7503.6	2216	No	EM-61	2.64	1.4	37.41.30.08	-116.40.46.72	528243.8	4171656.3
North Antelope Lake	20595.8	2246	No	EM-61	3.91	2.1	37.41.30.21	-116.40.46.72	528243.8	4171660.5
North Antelope Lake	117.8	3985	No	EM-61	2.08	0	37.41.38.77	-116.40.46.68	528243.8	4171924.4
North Antelope Lake	53.5	9383	No	EM-61	2.83	0	37.42.02.60	-116.40.46.58	528243.8	4172658.7
North Antelope Lake	163.9	2271	No	EM-61	3.56	>4	37.41.30.35	-116.40.46.69	528244.5	4171664.7
North Antelope Lake	128.1	8264	No	EM-61	1.81	0.2	37.41.56.90	-116.40.46.49	528246.6	4172483.0
North Antelope Lake	75	5673	No	EM-61	2.23	0.9	37.41.46.29	-116.40.46.42	528249.4	4172156.1
North Antelope Lake	124	1641	No	EM-61	1.93	0.4	37.41.27.17	-116.40.46.47	528250.1	4171566.7
North Antelope Lake	221.8	2767	No	EM-61	2.14	0.2	37.41.32.21	-116.40.46.42	528250.8	4171722.1
North Antelope Lake	115.2	4418	No	EM-61	1.4	0.2	37.41.40.70	-116.40.46.39	528250.8	4171983.9
North Antelope Lake	51.7	2793	No	EM-61	2.7	0.2	37.41.32.30	-116.40.46.39	528251.5	4171724.9
North Antelope Lake	123.9	9538	No	EM-61	2.47	0.2	37.42.03.21	-116.40.46.26	528251.5	4172677.6
North Antelope Lake	31.9	5771	No	EM-61	2.04	0	37.41.46.63	-116.40.46.27	528252.9	4172166.6
North Antelope Lake	79.6	5804	No	EM-61	1.71	1.3	37.41.46.75	-116.40.46.25	528253.6	4172170.1
North Antelope Lake	48.9	2463	No	EM-61	3.3	1.3	37.41.31.12	-116.40.46.28	528254.3	4171688.5
North Antelope Lake	33.8	2782	No	EM-61	2.59	0.2	37.41.32.25	-116.40.46.28	528254.3	4171723.5
North Antelope Lake	67.5	5674	No	EM-61	4.3	0.3	37.41.46.29	-116.40.46.22	528254.3	4172156.1
North Antelope Lake	150.9	6307	No	EM-61	2.94	0.2	37.41.49.34	-116.40.46.21	528254.3	4172249.9
North Antelope Lake	1182.3	2429	No	EM-61	3.44	3.8	37.41.30.94	-116.40.46.26	528255.0	4171682.9
North Antelope Lake	93.8	5640	No	EM-61	2.24	0.2	37.41.46.18	-116.40.46.16	528255.7	4172152.6
North Antelope Lake	46.9	5786	No	EM-61	2.94	0.2	37.41.46.70	-116.40.46.13	528256.4	4172168.7
North Antelope Lake	490.7	5710	No	EM-61	3.77	1.6	37.41.46.45	-116.40.46.08	528257.8	4172161.0
North Antelope Lake	415.7	5735	No	EM-61	2.94	0.9	37.41.46.52	-116.40.46.05	528258.5	4172163.1

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	132.6	1399	No	EM-61	3.23	0.2	37.41.25.89	-116.40.46.11	528259.2	4171527.5
North Antelope Lake	86.4	4243	No	EM-61	2.91	0.2	37.41.40.00	-116.40.45.93	528262.0	4171962.2
North Antelope Lake	84.3	5663	No	EM-61	2.15	0.3	37.41.46.25	-116.40.45.90	528262.0	4172154.7
North Antelope Lake	150.6	8278	No	EM-61	2.4	0.2	37.41.56.97	-116.40.45.72	528265.5	4172485.1
North Antelope Lake	74.1	7751	No	EM-61	2.33	0.2	37.41.54.56	-116.40.45.58	528269.0	4172410.9
North Antelope Lake	74.6	275	No	EM-61	3	1.7	37.41.16.26	-116.40.45.69	528270.4	4171230.7
North Antelope Lake	149.6	5900	No	EM-61	2.6	1.4	37.41.47.24	-116.40.45.36	528275.3	4172185.5
North Antelope Lake	115.2	8553	No	EM-61	2.19	0.2	37.41.58.28	-116.40.45.31	528275.3	4172525.7
North Antelope Lake	35.7	5736	No	EM-61	1.71	0.2	37.41.46.52	-116.40.45.30	528276.7	4172163.1
North Antelope Lake	75.4	10402	No	EM-61	3.39	0.2	37.42.09.93	-116.40.45.17	528277.4	4172884.8
North Antelope Lake	1006.4	2445	No	EM-61	4.01	>4	37.41.31.03	-116.40.45.31	528278.1	4171685.7
North Antelope Lake	95.5	4284	No	EM-61	3.88	0.2	37.41.40.16	-116.40.45.16	528280.9	4171967.1
North Antelope Lake	75.5	5308	No	EM-61	3.55	0.2	37.41.44.81	-116.40.45.14	528280.9	4172110.6
North Antelope Lake	303.8	8146	No	EM-61	1.9	0.2	37.41.56.26	-116.40.45.00	528283.0	4172463.4
North Antelope Lake	64.7	4398	No	EM-61	2.62	0	37.41.40.59	-116.40.44.99	528285.1	4171980.4
North Antelope Lake	333.2	5979	No	EM-61	3.97	0.9	37.41.47.63	-116.40.44.96	528285.1	4172197.4
North Antelope Lake	117.5	10065	No	EM-61	1.88	0.2	37.42.05.89	-116.40.44.88	528285.1	4172760.2
North Antelope Lake	65.6	4032	No	EM-61	3.15	0.2	37.41.39.04	-116.40.44.96	528285.8	4171932.8
North Antelope Lake	396.8	2247	No	EM-61	2.97	>4	37.41.30.21	-116.40.44.95	528287.2	4171660.5
North Antelope Lake	86.3	8122	No	EM-61	2.9	0.2	37.41.56.15	-116.40.44.83	528287.2	4172459.9
North Antelope Lake	148.3	4026	No	EM-61	3.89	0.2	37.41.39.02	-116.40.44.85	528288.6	4171932.1
North Antelope Lake	153.8	2491	No	EM-61	4.25	0.2	37.41.31.21	-116.40.44.83	528290.0	4171691.3
North Antelope Lake	59.7	7994	No	EM-61	2.49	0.2	37.41.55.60	-116.40.44.64	528292.1	4172443.1
North Antelope Lake	193.6	6064	No	EM-61	3.15	0.6	37.41.48.06	-116.40.44.61	528293.5	4172210.7
North Antelope Lake	82.4	2345	No	EM-61	2.48	0.6	37.41.30.61	-116.40.44.57	528296.3	4171673.1
North Antelope Lake	127.8	5496	No	EM-61	3.22	0.5	37.41.45.54	-116.40.44.48	528297.0	4172133.0
North Antelope Lake	59.1	890	No	EM-61	3.59	0	37.41.22.71	-116.40.44.43	528300.5	4171429.5
North Antelope Lake	138.6	8036	No	EM-61	1.92	0.2	37.41.55.80	-116.40.44.09	528305.4	4172449.4
North Antelope Lake	247.2	3501	No	EM-61	3.89	0.2	37.41.35.41	-116.40.44.15	528306.1	4171820.8
North Antelope Lake	156.1	5420	No	EM-61	2.31	0	37.41.45.24	-116.40.44.11	528306.1	4172123.9
North Antelope Lake	175.8	8020	No	EM-61	2.5	0.2	37.41.55.73	-116.40.43.86	528311.0	4172447.3
North Antelope Lake	64.6	1484	No	EM-61	2.69	0	37.41.26.30	-116.40.43.96	528311.7	4171540.1
North Antelope Lake	72.1	6472	No	EM-61	2.24	0.2	37.41.49.99	-116.40.43.66	528316.6	4172270.2
North Antelope Lake	171.2	7978	No	EM-61	1.84	0.2	37.41.55.53	-116.40.43.64	528316.6	4172441.0
North Antelope Lake	95.2	7961	No	EM-61	3.45	0.2	37.41.55.39	-116.40.43.41	528322.2	4172436.8
North Antelope Lake	76.4	9358	No	EM-61	3.24	0.2	37.42.02.50	-116.40.43.26	528325.0	4172655.9
North Antelope Lake	143.7	7891	No	EM-61	2.49	0.2	37.41.55.12	-116.40.42.81	528336.9	4172428.4
North Antelope Lake	258.7	2567	No	EM-61	4.04	0.2	37.41.31.45	-116.40.42.77	528340.4	4171699.0
North Antelope Lake	159	8893	No	EM-61	2.07	0.2	37.42.00.02	-116.40.42.53	528343.2	4172579.6
North Antelope Lake	53.3	968	No	EM-61	2.03	0.2	37.41.23.16	-116.40.42.55	528346.7	4171443.5

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	115.2	6901	No	EM-61	1.82	0.2	37.41.51.71	-116.40.42.39	528347.4	4172323.4
North Antelope Lake	267	6560	No	EM-61	2.16	0	37.41.50.37	-116.40.42.34	528348.8	4172282.1
North Antelope Lake	56	5863	No	EM-61	2.56	0.2	37.41.47.05	-116.40.42.21	528352.3	4172179.9
North Antelope Lake	55.3	693	No	EM-61	2.52	0.7	37.41.21.68	-116.40.42.27	528353.7	4171398.0
North Antelope Lake	237.6	5847	No	EM-61	1.72	0	37.41.46.94	-116.40.41.99	528357.9	4172176.4
North Antelope Lake	56.1	7979	No	EM-61	2.43	0.2	37.41.55.52	-116.40.41.78	528362.1	4172441.0
North Antelope Lake	108.2	9278	No	EM-61	1.95	0.2	37.42.02.00	-116.40.41.69	528363.5	4172640.5
North Antelope Lake	131.9	7951	No	EM-61	2.29	0.2	37.41.55.34	-116.40.41.69	528364.2	4172435.4
North Antelope Lake	264.8	5949	No	EM-61	2.96	0.2	37.41.47.46	-116.40.41.70	528364.9	4172192.5
North Antelope Lake	46.7	9645	No	EM-61	1.79	0.2	37.42.03.70	-116.40.41.63	528364.9	4172693.0
North Antelope Lake	91.1	7662	No	EM-61	2.49	0.2	37.41.54.12	-116.40.41.50	528369.1	4172397.6
North Antelope Lake	418.1	10240	No	EM-61	2.19	0.2	37.42.07.29	-116.40.41.35	528371.2	4172803.6
North Antelope Lake	51.7	1475	No	EM-61	4.2	0.2	37.41.26.22	-116.40.41.50	528371.9	4171538.0
North Antelope Lake	83.9	278	No	EM-61	2.39	0.2	37.41.16.27	-116.40.41.35	528376.8	4171231.4
North Antelope Lake	93.4	171	No	EM-61	2.44	0.2	37.41.15.68	-116.40.41.29	528378.2	4171213.2
North Antelope Lake	110.9	302	No	EM-61	1.96	0	37.41.16.50	-116.40.41.23	528379.6	4171238.4
North Antelope Lake	73.5	5002	No	EM-61	2.32	0.2	37.41.43.48	-116.40.41.11	528379.6	4172070.0
North Antelope Lake	95	172	No	EM-61	2.27	0.2	37.41.15.68	-116.40.41.06	528383.8	4171213.2
North Antelope Lake	61.4	7635	No	EM-61	3.83	0	37.41.54.02	-116.40.40.61	528390.8	4172394.8
North Antelope Lake	73.1	7647	No	EM-61	1.98	0	37.41.54.07	-116.40.40.58	528391.5	4172396.2
North Antelope Lake	49.4	1457	No	EM-61	2.84	0.2	37.41.26.13	-116.40.40.68	528392.2	4171535.2
North Antelope Lake	284.1	9467	No	EM-61	2.75	0.2	37.42.02.90	-116.40.40.17	528400.6	4172668.5
North Antelope Lake	94.5	8166	No	EM-61	2.46	0.2	37.41.56.36	-116.40.40.09	528403.4	4172466.9
North Antelope Lake	109.6	6451	No	EM-61	3	0	37.41.49.82	-116.40.39.77	528411.8	4172265.3
North Antelope Lake	76.1	8336	No	EM-61	1.9	0.2	37.41.57.20	-116.40.39.68	528413.2	4172492.8
North Antelope Lake	81.1	6922	No	EM-61	2.11	0	37.41.51.77	-116.40.38.85	528434.2	4172325.5
North Antelope Lake	302.7	7720	No	EM-61	1.79	0.2	37.41.54.36	-116.40.38.61	528439.8	4172405.3
North Antelope Lake	64	9371	No	EM-61	2.64	0	37.42.02.53	-116.40.38.57	528439.8	4172657.3
North Antelope Lake	76.9	8593	No	EM-61	4.66	0.2	37.41.58.47	-116.40.38.48	528442.6	4172532.0
North Antelope Lake	164.6	7735	No	EM-61	4.24	0.2	37.41.54.45	-116.40.38.29	528447.5	4172408.1
North Antelope Lake	97.9	7894	No	EM-61	2.08	0.2	37.41.55.11	-116.40.38.23	528448.9	4172428.4
North Antelope Lake	156.3	5011	No	EM-61	5.18	0	37.41.43.50	-116.40.38.26	528449.6	4172070.7
North Antelope Lake	98.3	7071	No	EM-61	3.23	0.2	37.41.52.33	-116.40.38.22	528449.6	4172343.0
North Antelope Lake	27.6	7423	No	EM-61	2.33	3.8	37.41.53.29	-116.40.37.90	528457.3	4172372.4
North Antelope Lake	61.7	7605	No	EM-61	2.06	0.2	37.41.53.88	-116.40.37.73	528461.5	4172390.6
North Antelope Lake	126.3	6794	No	EM-61	2.11	0.2	37.41.51.29	-116.40.37.59	528465.0	4172310.8
North Antelope Lake	39.2	406	No	EM-61	2.48	0	37.41.17.24	-116.40.37.54	528469.9	4171261.5
North Antelope Lake	53.2	6818	No	EM-61	2.53	0.2	37.41.51.36	-116.40.37.22	528474.1	4172312.9
North Antelope Lake	96.9	3314	No	EM-61	4.55	0.2	37.41.34.37	-116.40.37.27	528474.8	4171789.3
North Antelope Lake	56.3	4146	No	EM-61	2.45	0.2	37.41.39.66	-116.40.37.24	528474.8	4171952.4

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	144.2	9573	No	EM-61	1.4	0.2	37.42.03.39	-116.40.37.08	528476.2	4172683.9
North Antelope Lake	30.5	9548	No	EM-61	3.08	0.2	37.42.03.26	-116.40.37.06	528476.9	4172679.7
North Antelope Lake	56.2	7702	No	EM-61	2.66	0.2	37.41.54.31	-116.40.36.44	528493.0	4172403.9
North Antelope Lake	161	6802	No	EM-61	2.42	0.2	37.41.51.31	-116.40.36.22	528498.6	4172311.5
North Antelope Lake	125.7	5924	No	EM-61	2.09	0	37.41.47.33	-116.40.36.01	528504.2	4172189.0
North Antelope Lake	71.9	8563	No	EM-61	2.17	0.2	37.41.58.30	-116.40.35.88	528506.3	4172527.1
North Antelope Lake	59.8	1314	No	EM-61	2.73	0.2	37.41.25.50	-116.40.35.93	528508.4	4171516.3
North Antelope Lake	343.4	2747	No	EM-61	3.29	0.6	37.41.32.11	-116.40.35.90	528508.4	4171720.0
North Antelope Lake	61.8	3638	No	EM-61	2.5	0.2	37.41.36.36	-116.40.35.74	528511.9	4171850.9
North Antelope Lake	437	3745	No	EM-61	2.44	0	37.41.37.06	-116.40.35.45	528518.9	4171872.6
North Antelope Lake	362	5806	No	EM-61	4.05	0.2	37.41.46.72	-116.40.35.30	528521.7	4172170.1
North Antelope Lake	150.4	1401	No	EM-61	3.01	0.2	37.41.25.87	-116.40.35.33	528523.1	4171527.5
North Antelope Lake	62	2583	No	EM-61	2.13	0.2	37.41.31.48	-116.40.35.28	528523.8	4171700.4
North Antelope Lake	74.7	8645	No	EM-61	3.38	0.2	37.41.58.78	-116.40.35.02	528527.3	4172541.8
North Antelope Lake	137.9	6454	No	EM-61	2.25	0.2	37.41.49.83	-116.40.34.83	528532.9	4172266.0
North Antelope Lake	70.5	6703	No	EM-61	2.1	0.2	37.41.50.87	-116.40.34.79	528533.6	4172298.2
North Antelope Lake	42.2	2059	No	EM-61	3.16	0	37.41.29.29	-116.40.34.49	528543.4	4171633.2
North Antelope Lake	110.6	8912	No	EM-61	2.64	0.2	37.42.00.09	-116.40.34.15	528548.3	4172582.4
North Antelope Lake	133.3	3163	No	EM-61	3.97	0.2	37.41.33.68	-116.40.34.18	528550.4	4171768.3
North Antelope Lake	397.1	1879	No	EM-61	2.54	1.1	37.41.28.41	-116.40.34.03	528554.6	4171605.9
North Antelope Lake	61.9	5614	No	EM-61	2.43	0.2	37.41.46.03	-116.40.33.79	528558.8	4172149.1
North Antelope Lake	43.8	2802	No	EM-61	3.09	0.2	37.41.32.33	-116.40.33.70	528562.3	4171727.0
North Antelope Lake	64.9	7598	No	EM-61	2.7	0.2	37.41.53.84	-116.40.33.61	528562.3	4172389.9
North Antelope Lake	53.7	7756	No	EM-61	2.81	0.2	37.41.54.55	-116.40.33.58	528563.0	4172411.6
North Antelope Lake	52.2	8732	No	EM-61	2.82	0.2	37.41.59.18	-116.40.33.44	528565.8	4172554.4
North Antelope Lake	82.8	3271	No	EM-61	3.58	0.2	37.41.34.15	-116.40.33.52	528566.5	4171783.0
North Antelope Lake	302	1430	No	EM-61	3.86	0.2	37.41.26.00	-116.40.33.50	528567.9	4171531.7
North Antelope Lake	252.8	8719	No	EM-61	2.07	0.2	37.41.59.11	-116.40.33.30	528569.3	4172552.3
North Antelope Lake	145.8	1283	No	EM-61	3.76	0.2	37.41.25.31	-116.40.33.39	528570.7	4171510.7
North Antelope Lake	136.1	6873	No	EM-61	1.92	0	37.41.51.50	-116.40.33.16	528573.5	4172317.8
North Antelope Lake	62.6	4862	No	EM-61	2.35	0.2	37.41.42.83	-116.40.33.09	528576.3	4172050.4
North Antelope Lake	143	6537	No	EM-61	5.25	0.2	37.41.50.23	-116.40.33.02	528577.0	4172278.6
North Antelope Lake	117.8	8361	No	EM-61	2.3	0.2	37.41.57.27	-116.40.32.99	528577.0	4172495.6
North Antelope Lake	91.3	8154	No	EM-61	2.94	0.2	37.41.56.25	-116.40.32.97	528577.7	4172464.1
North Antelope Lake	155.1	20	No	EM-61	1.67	0.2	37.41.14.55	-116.40.33.12	528578.4	4171178.9
North Antelope Lake	259	4384	No	EM-61	2.67	0.2	37.41.40.51	-116.40.32.90	528581.2	4171979.0
North Antelope Lake	222.8	1597	No	EM-61	1.86	1.1	37.41.26.93	-116.40.32.78	528585.4	4171560.4
North Antelope Lake	256.6	1632	No	EM-61	1.88	0.9	37.41.27.11	-116.40.32.78	528585.4	4171566.0
North Antelope Lake	103	1668	No	EM-61	4.4	0.7	37.41.27.24	-116.40.32.70	528587.5	4171570.2
North Antelope Lake	61.3	1698	No	EM-61	2.6	0.3	37.41.27.40	-116.40.32.70	528587.5	4171575.1

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	101.4	5807	No	EM-61	2.06	0	37.41.46.71	-116.40.32.61	528587.5	4172170.1
North Antelope Lake	279.9	1657	No	EM-61	2.38	0.3	37.41.27.18	-116.40.32.67	528588.2	4171568.1
North Antelope Lake	109.6	2975	No	EM-61	1.4	0.2	37.41.32.94	-116.40.32.61	528588.9	4171745.9
North Antelope Lake	31.1	1706	No	EM-61	3.45	0.2	37.41.27.45	-116.40.32.58	528590.3	4171576.5
North Antelope Lake	146.9	8192	No	EM-61	2.12	0.2	37.41.56.45	-116.40.32.45	528590.3	4172470.4
North Antelope Lake	51.2	586	No	EM-61	2.34	0.1	37.41.20.75	-116.40.32.38	528595.9	4171370.0
North Antelope Lake	39.1	424	No	EM-61	2.34	2.8	37.41.17.32	-116.40.32.34	528597.3	4171264.3
North Antelope Lake	44.9	3367	No	EM-61	1.92	0.2	37.41.34.67	-116.40.32.23	528598.0	4171799.1
North Antelope Lake	75.4	1487	No	EM-61	2.09	1.6	37.41.26.26	-116.40.31.96	528605.7	4171540.1
North Antelope Lake	95.2	5554	No	EM-61	2.37	0.2	37.41.45.75	-116.40.31.84	528606.4	4172140.7
North Antelope Lake	21.7	7443	No	EM-61	3.02	>4	37.41.53.29	-116.40.31.81	528606.4	4172373.1
North Antelope Lake	22.7	7444	No	EM-61	3.94	2.1	37.41.53.29	-116.40.31.75	528607.8	4172373.1
North Antelope Lake	33.3	2640	No	EM-61	3.18	0.2	37.41.31.69	-116.40.31.82	528608.5	4171707.4
North Antelope Lake	92.9	1431	No	EM-61	2.51	0	37.41.25.99	-116.40.31.30	528621.8	4171531.7
North Antelope Lake	134.9	8239	No	EM-61	2.81	0	37.41.56.68	-116.40.31.11	528623.2	4172477.4
North Antelope Lake	400	3136	No	EM-61	3.9	0.2	37.41.33.58	-116.40.30.98	528628.8	4171765.5
North Antelope Lake	47.4	2676	No	EM-61	2.43	0	37.41.31.83	-116.40.30.90	528630.9	4171711.6
North Antelope Lake	100.5	2694	No	EM-61	2.85	0	37.41.31.92	-116.40.30.90	528630.9	4171714.4
North Antelope Lake	89.6	372	No	EM-61	2.98	0	37.41.16.97	-116.40.30.83	528634.4	4171253.8
North Antelope Lake	67.1	72	No	EM-61	2.07	0.2	37.41.14.90	-116.40.30.81	528635.1	4171190.1
North Antelope Lake	69.7	5967	No	EM-61	1.4	0.9	37.41.47.54	-116.40.30.66	528635.1	4172196.0
North Antelope Lake	560.5	3968	No	EM-61	4.14	0.2	37.41.38.59	-116.40.30.62	528637.2	4171920.2
North Antelope Lake	247.2	3986	No	EM-61	2.36	1.4	37.41.38.73	-116.40.30.62	528637.2	4171924.4
North Antelope Lake	926.9	3998	No	EM-61	1.4	0.6	37.41.38.84	-116.40.30.53	528639.3	4171927.9
North Antelope Lake	376.8	6695	No	EM-61	1.52	0.2	37.41.50.84	-116.40.30.48	528639.3	4172297.5
North Antelope Lake	162.8	3948	No	EM-61	1.85	0	37.41.38.48	-116.40.30.50	528640.0	4171916.7
North Antelope Lake	552	3957	No	EM-61	4.75	0	37.41.38.55	-116.40.30.50	528640.0	4171918.8
North Antelope Lake	807.9	3894	No	EM-61	4.56	0	37.41.38.16	-116.40.30.48	528640.7	4171906.9
North Antelope Lake	60.5	3918	No	EM-61	3.54	0.3	37.41.38.32	-116.40.30.48	528640.7	4171911.8
North Antelope Lake	440.4	3901	No	EM-61	1.98	0	37.41.38.19	-116.40.30.39	528642.8	4171907.6
North Antelope Lake	153.1	2695	No	EM-61	2.77	0.2	37.41.31.92	-116.40.30.39	528643.5	4171714.4
North Antelope Lake	90.5	2601	No	EM-61	2.38	0.2	37.41.31.55	-116.40.30.13	528649.8	4171703.2
North Antelope Lake	51.5	7278	No	EM-61	2.11	0	37.41.52.99	-116.40.29.81	528655.4	4172364.0
North Antelope Lake	138.5	3842	No	EM-61	3.3	0.2	37.41.37.87	-116.40.29.82	528656.8	4171897.8
North Antelope Lake	287	707	No	EM-61	3.92	0.2	37.41.21.72	-116.40.29.52	528665.9	4171400.1
North Antelope Lake	86.9	2602	No	EM-61	2.03	0.2	37.41.31.55	-116.40.29.42	528667.3	4171703.2
North Antelope Lake	200.8	3147	No	EM-61	3.93	0.2	37.41.33.62	-116.40.29.12	528674.3	4171766.9
North Antelope Lake	102.2	2902	No	EM-61	3.43	0.2	37.41.32.68	-116.40.29.07	528675.7	4171738.2
North Antelope Lake	141.8	253	No	EM-61	4.79	0	37.41.16.08	-116.40.28.77	528684.8	4171226.5
North Antelope Lake	98.8	1147	No	EM-61	2.25	0.2	37.41.24.51	-116.40.28.68	528686.2	4171486.2

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	120.6	5075	No	EM-61	3.45	0.2	37.41.43.68	-116.40.28.51	528688.3	4172077.0
North Antelope Lake	136.4	259	No	EM-61	3.06	0	37.41.16.12	-116.40.28.49	528691.8	4171227.9
North Antelope Lake	183.2	5263	No	EM-61	1.67	0.2	37.41.44.56	-116.40.28.36	528691.8	4172104.3
North Antelope Lake	97.8	5968	No	EM-61	2.05	0.2	37.41.47.54	-116.40.28.32	528692.5	4172196.0
North Antelope Lake	93.1	5955	No	EM-61	4.69	0.2	37.41.47.45	-116.40.28.21	528695.3	4172193.2
North Antelope Lake	133.4	553	No	EM-61	3.31	0	37.41.18.30	-116.40.28.30	528696.0	4171295.1
North Antelope Lake	76.8	266	No	EM-61	2.01	0.7	37.41.16.17	-116.40.28.29	528696.7	4171229.3
North Antelope Lake	54.1	5964	No	EM-61	2.89	0	37.41.47.49	-116.40.28.15	528696.7	4172194.6
North Antelope Lake	85.4	5950	No	EM-61	2.27	0.2	37.41.47.42	-116.40.28.06	528698.8	4172192.5
North Antelope Lake	191.6	7670	No	EM-61	2.51	0.2	37.41.54.15	-116.40.27.86	528703.0	4172399.7
North Antelope Lake	154.2	276	No	EM-61	2.23	0.6	37.41.16.21	-116.40.28.00	528703.7	4171230.7
North Antelope Lake	88.7	3277	No	EM-61	2.06	0	37.41.34.16	-116.40.27.63	528710.7	4171783.7
North Antelope Lake	132	6515	No	EM-61	2.53	0.2	37.41.50.10	-116.40.27.57	528710.7	4172275.1
North Antelope Lake	73.1	6020	No	EM-61	2.06	0	37.41.47.72	-116.40.27.55	528711.4	4172201.6
North Antelope Lake	202.1	3370	No	EM-61	2.57	0	37.41.34.66	-116.40.27.46	528714.9	4171799.1
North Antelope Lake	87.9	3281	No	EM-61	3.6	0.1	37.41.34.18	-116.40.27.43	528715.6	4171784.4
North Antelope Lake	76.4	2969	No	EM-61	4.25	0.2	37.41.32.91	-116.40.27.41	528716.3	4171745.2
North Antelope Lake	68.9	7225	No	EM-61	1.95	0.2	37.41.52.74	-116.40.27.30	528717.0	4172356.3
North Antelope Lake	349.5	343	No	EM-61	4.13	0.2	37.41.16.71	-116.40.27.34	528719.8	4171246.1
North Antelope Lake	159.7	4334	No	EM-61	1.99	2.2	37.41.40.33	-116.40.27.04	528724.7	4171974.1
North Antelope Lake	2375.8	4335	No	EM-61	3.69	0.2	37.41.40.33	-116.40.26.72	528732.4	4171974.1
North Antelope Lake	51.6	513	No	EM-61	3.14	1.2	37.41.17.96	-116.40.26.62	528737.3	4171284.6
North Antelope Lake	499.5	2377	No	EM-61	2.42	0	37.41.30.66	-116.40.26.54	528738.0	4171675.9
North Antelope Lake	227	4747	No	EM-61	1.9	1.4	37.41.42.33	-116.40.26.48	528738.0	4172035.7
North Antelope Lake	80.7	7744	No	EM-61	1.94	0.2	37.41.54.44	-116.40.26.12	528745.7	4172408.8
North Antelope Lake	368.3	3201	No	EM-61	1.5	0.2	37.41.33.83	-116.40.25.89	528753.4	4171773.9
North Antelope Lake	82.2	3138	No	EM-61	3.73	0.2	37.41.33.56	-116.40.25.78	528756.2	4171765.5
North Antelope Lake	42.6	1476	No	EM-61	2.38	2.1	37.41.26.18	-116.40.25.44	528765.3	4171538.0
North Antelope Lake	180.2	5366	No	EM-61	2.39	0	37.41.44.98	-116.40.25.22	528768.8	4172117.6
North Antelope Lake	192.5	2994	No	EM-61	3	1.5	37.41.32.99	-116.40.25.07	528773.7	4171748.0
North Antelope Lake	65.5	2728	No	EM-61	4.07	0.2	37.41.32.01	-116.40.24.93	528777.2	4171717.9
North Antelope Lake	199	6811	No	EM-61	2.47	0	37.41.51.30	-116.40.24.73	528780.0	4172312.2
North Antelope Lake	107.7	3190	No	EM-61	2.35	0.1	37.41.33.76	-116.40.24.78	528780.7	4171771.8
North Antelope Lake	83.8	1943	No	EM-61	1.72	0.2	37.41.28.65	-116.40.24.77	528781.4	4171614.3
North Antelope Lake	319	654	No	EM-61	1.86	0.8	37.41.21.13	-116.40.24.72	528783.5	4171382.6
North Antelope Lake	410.2	733	No	EM-61	2.24	1.5	37.41.21.82	-116.40.24.60	528786.3	4171403.6
North Antelope Lake	916.3	3376	No	EM-61	2.34	0	37.41.34.69	-116.40.24.40	528789.8	4171800.5
North Antelope Lake	251	635	No	EM-61	1.4	0.7	37.41.21.02	-116.40.24.41	528791.2	4171379.1
North Antelope Lake	96.5	7163	No	EM-61	1.65	0.2	37.41.52.50	-116.40.23.87	528801.0	4172349.3
North Antelope Lake	1277.7	825	No	EM-61	1.9	1.2	37.41.22.31	-116.40.23.97	528801.7	4171419.0

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	150.6	10491	No	EM-61	4.58	2	37.41.22.26	-116.40.23.84	528804.8	4171417.5
North Antelope Lake	49.6	1195	No	EM-61	2.63	1.8	37.41.24.83	-116.40.23.73	528807.3	4171496.7
North Antelope Lake	34.6	7181	No	EM-61	3.13	0	37.41.52.56	-116.40.22.84	528826.2	4172351.4
North Antelope Lake	103.8	5194	No	EM-61	4.18	0.2	37.41.44.27	-116.40.22.70	528830.4	4172095.9
North Antelope Lake	59.9	7120	No	EM-61	3.28	0	37.41.52.41	-116.40.22.67	528830.4	4172346.5
North Antelope Lake	100	1165	No	EM-61	2.53	2.9	37.41.24.60	-116.40.22.76	528831.1	4171489.7
North Antelope Lake	262.4	1206	No	EM-61	2.17	2.4	37.41.24.90	-116.40.22.73	528831.8	4171498.8
North Antelope Lake	143.4	6009	No	EM-61	2.32	0.2	37.41.47.66	-116.40.22.49	528835.3	4172200.2
North Antelope Lake	154.4	643	No	EM-61	2.17	1.1	37.41.21.04	-116.40.22.49	528838.1	4171379.8
North Antelope Lake	65	3754	No	EM-61	2.66	0.2	37.41.37.10	-116.40.22.33	528840.2	4171874.7
North Antelope Lake	59.3	632	No	EM-61	2.34	3.2	37.41.20.97	-116.40.22.20	528845.1	4171377.7
North Antelope Lake	59.6	1823	No	EM-61	2.42	0	37.41.28.05	-116.40.22.15	528845.8	4171596.1
North Antelope Lake	432.8	1846	No	EM-61	3.62	0	37.41.28.17	-116.40.22.14	528845.8	4171599.6
North Antelope Lake	35.6	2201	No	EM-61	2.94	0.2	37.41.29.96	-116.40.22.14	528845.8	4171654.9
North Antelope Lake	151	657	No	EM-61	1.77	0.9	37.41.21.15	-116.40.22.09	528847.9	4171383.3
North Antelope Lake	116.2	2394	No	EM-61	2.18	0.2	37.41.30.71	-116.40.22.05	528847.9	4171678.0
North Antelope Lake	131.1	661	No	EM-61	3.53	0.8	37.41.21.19	-116.40.22.06	528848.6	4171384.7
North Antelope Lake	169.9	2504	No	EM-61	1.84	0.2	37.41.31.17	-116.40.21.90	528851.4	4171692.0
North Antelope Lake	85.6	3024	No	EM-61	2.04	0.2	37.41.33.12	-116.40.21.89	528851.4	4171752.2
North Antelope Lake	84.7	2678	No	EM-61	2.63	0.2	37.41.31.80	-116.40.21.81	528853.5	4171711.6
North Antelope Lake	613.1	1840	No	EM-61	4.16	0.2	37.41.28.10	-116.40.21.69	528857.0	4171597.5
North Antelope Lake	161	3580	No	EM-61	1.95	0.2	37.41.35.80	-116.40.21.51	528860.5	4171834.8
North Antelope Lake	86.2	997	No	EM-61	4.13	0.2	37.41.23.33	-116.40.21.37	528865.4	4171450.5
North Antelope Lake	121.9	4532	No	EM-61	2.84	0.2	37.41.41.23	-116.40.21.23	528866.8	4172002.1
North Antelope Lake	285.8	2597	No	EM-61	3.27	0.8	37.41.31.50	-116.40.21.24	528867.5	4171702.5
North Antelope Lake	98.2	2008	No	EM-61	2.16	0	37.41.28.94	-116.40.21.17	528869.6	4171623.4
North Antelope Lake	657.1	2378	No	EM-61	4.14	0	37.41.30.64	-116.40.21.10	528871.0	4171675.9
North Antelope Lake	57.5	1988	No	EM-61	2.71	2.4	37.41.28.82	-116.40.21.03	528873.1	4171619.9
North Antelope Lake	4811	2051	No	EM-61	2.53	0.2	37.41.29.16	-116.40.21.03	528873.1	4171630.4
North Antelope Lake	1393.6	2065	No	EM-61	2.67	0	37.41.29.28	-116.40.21.00	528873.8	4171633.9
North Antelope Lake	104	1974	No	EM-61	4.05	0.3	37.41.28.76	-116.40.20.94	528875.2	4171617.8
North Antelope Lake	42.1	2006	No	EM-61	2.52	2.4	37.41.28.91	-116.40.20.94	528875.2	4171622.7
North Antelope Lake	193.7	2137	No	EM-61	2.31	0	37.41.29.55	-116.40.20.88	528876.6	4171642.3
North Antelope Lake	230.9	2714	No	EM-61	3.45	0.2	37.41.31.96	-116.40.20.76	528879.4	4171716.5
North Antelope Lake	60.1	6929	No	EM-61	4.08	0	37.41.51.74	-116.40.20.67	528879.4	4172326.2
North Antelope Lake	57.4	2598	No	EM-61	4.04	0.2	37.41.31.50	-116.40.20.56	528884.3	4171702.5
North Antelope Lake	2338.6	1848	No	EM-61	2.06	1.1	37.41.28.16	-116.40.20.29	528891.3	4171599.6
North Antelope Lake	169.9	5379	No	EM-61	1.4	0.2	37.41.45.04	-116.40.20.18	528892.0	4172119.7
North Antelope Lake	121.2	2289	No	EM-61	3.35	0.2	37.41.30.34	-116.40.20.13	528894.8	4171666.8
North Antelope Lake	136.3	2609	No	EM-61	1.67	0.2	37.41.31.55	-116.40.20.13	528894.8	4171703.9

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	15.9	6733	No	EM-61	3.57	>4	37.41.50.94	-116.40.19.90	528898.3	4172301.7
North Antelope Lake	16.2	6736	No	EM-61	3.21	>4	37.41.50.97	-116.40.19.81	528900.4	4172302.4
North Antelope Lake	57.3	2228	No	EM-61	3.65	0.2	37.41.30.05	-116.40.19.85	528901.8	4171657.7
North Antelope Lake	79	10	No	EM-61	1.96	0	37.41.14.35	-116.40.19.80	528904.6	4171174.0
North Antelope Lake	91.9	4351	No	EM-61	3.99	0.2	37.41.40.38	-116.40.19.58	528907.4	4171976.2
North Antelope Lake	195.9	2314	No	EM-61	3.84	0.2	37.41.30.41	-116.40.19.59	528908.1	4171668.9
North Antelope Lake	49.9	23	No	EM-61	2.98	0	37.41.14.53	-116.40.19.23	528918.6	4171179.6
North Antelope Lake	83.3	528	No	EM-61	2.55	3	37.41.18.01	-116.40.19.22	528918.6	4171286.7
North Antelope Lake	151.1	2252	No	EM-61	2.73	0.2	37.41.30.16	-116.40.19.13	528919.3	4171661.2
North Antelope Lake	82.7	1007	No	EM-61	2.83	0.2	37.41.23.39	-116.40.18.42	528937.5	4171452.6
North Antelope Lake	152.7	2300	No	EM-61	2.67	0.2	37.41.30.36	-116.40.18.25	528941.0	4171667.5
North Antelope Lake	275.9	616	No	EM-61	3.32	0.2	37.41.20.84	-116.40.17.89	528950.8	4171374.2
North Antelope Lake	641.3	2130	No	EM-61	1.6	0	37.41.29.52	-116.40.17.85	528950.8	4171641.6
North Antelope Lake	329.2	5134	No	EM-61	3.05	0	37.41.43.99	-116.40.17.10	528967.6	4172087.5
North Antelope Lake	137.6	2513	No	EM-61	2.74	0	37.41.31.17	-116.40.17.02	528971.1	4171692.7
North Antelope Lake	53.8	235	No	EM-61	1.96	>4	37.41.15.93	-116.40.16.91	528975.3	4171223.0
North Antelope Lake	185	6230	No	EM-61	4.85	0.2	37.41.48.94	-116.40.16.71	528976.7	4172240.1
North Antelope Lake	136.3	2827	No	EM-61	3.94	0.2	37.41.32.38	-116.40.16.58	528981.6	4171729.8
North Antelope Lake	490.9	1176	No	EM-61	4.29	0.2	37.41.24.68	-116.40.16.53	528983.7	4171492.5
North Antelope Lake	93.7	2870	No	EM-61	2.34	0.2	37.41.32.54	-116.40.16.38	528986.5	4171734.7
North Antelope Lake	115.8	3191	No	EM-61	4.48	0.2	37.41.33.74	-116.40.16.35	528987.2	4171771.8
North Antelope Lake	58.4	969	No	EM-61	4.39	0.7	37.41.23.09	-116.40.16.28	528990.0	4171443.5
North Antelope Lake	44.4	95	No	EM-61	3.66	0.2	37.41.15.07	-116.40.16.29	528990.7	4171196.4
North Antelope Lake	25.1	242	No	EM-61	4.21	>4	37.41.15.98	-116.40.16.28	528990.7	4171224.4
North Antelope Lake	24.3	248	No	EM-61	2.72	>4	37.41.16.02	-116.40.16.25	528991.4	4171225.8
North Antelope Lake	35.6	956	No	EM-61	3.53	0.9	37.41.23.04	-116.40.16.22	528991.4	4171442.1
North Antelope Lake	99.2	2093	No	EM-61	2.07	0.8	37.41.29.38	-116.40.15.97	528997.0	4171637.4
North Antelope Lake	101.6	120	No	EM-61	2.33	0.2	37.41.15.27	-116.40.15.94	528999.1	4171202.7
North Antelope Lake	207.9	2265	No	EM-61	2.27	1.1	37.41.30.19	-116.40.15.65	529004.7	4171662.6
North Antelope Lake	115	2780	No	EM-61	4.49	0.2	37.41.32.15	-116.40.15.44	529009.6	4171722.8
North Antelope Lake	120.4	1758	No	EM-61	1.92	0.2	37.41.27.65	-116.40.14.83	529025.0	4171584.2
North Antelope Lake	68.8	2930	No	EM-61	3.27	0.1	37.41.32.71	-116.40.13.49	529057.2	4171740.3
North Antelope Lake	77.3	2922	No	EM-61	2.23	0	37.41.32.69	-116.40.13.35	529060.7	4171739.6
North Antelope Lake	89.4	3100	No	EM-61	2.28	0.2	37.41.33.41	-116.40.13.32	529061.4	4171762.0
North Antelope Lake	510.4	844	No	EM-61	2.89	0.2	37.41.22.40	-116.40.13.28	529063.5	4171422.5
North Antelope Lake	89	5432	No	EM-61	2.21	0	37.41.45.18	-116.40.12.52	529079.6	4172124.6
North Antelope Lake	68	1506	No	EM-61	2.81	0.8	37.41.26.28	-116.40.12.35	529085.9	4171542.2
North Antelope Lake	252.3	515	No	EM-61	2.63	0.2	37.41.17.92	-116.40.11.81	529099.9	4171284.6
North Antelope Lake	123.2	3426	No	EM-61	2.22	0	37.41.34.90	-116.40.10.37	529133.5	4171808.2
North Antelope Lake	151.9	289	No	EM-61	2.49	0.2	37.41.16.30	-116.40.10.28	529137.7	4171234.9

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	45.5	5877	No	EM-61	3.58	0.2	37.41.47.01	-116.40.09.68	529148.9	4172181.3
North Antelope Lake	277.1	304	No	EM-61	3.21	0.2	37.41.16.41	-116.40.08.59	529179.0	4171238.4
North Antelope Lake	38.8	185	No	EM-61	2.86	0.2	37.41.15.64	-116.40.08.17	529189.5	4171214.6
North Antelope Lake	179.8	1531	No	EM-61	1.65	0.2	37.41.26.45	-116.40.07.92	529194.4	4171547.8
North Antelope Lake	481.7	3656	No	EM-61	2.79	0.2	37.41.36.42	-116.40.07.67	529199.3	4171855.1
North Antelope Lake	123.2	1897	No	EM-61	3.02	0.2	37.41.28.40	-116.40.06.77	529222.4	4171608.0
North Antelope Lake	225.9	3996	No	EM-61	2.62	2.8	37.41.38.75	-116.40.05.49	529252.5	4171927.2
North Antelope Lake	877.7	4018	No	EM-61	2.93	2.7	37.41.38.84	-116.40.05.40	529254.6	4171930.0
North Antelope Lake	229.6	5042	No	EM-61	2.43	0.2	37.41.43.52	-116.40.05.01	529263.7	4172074.2
North Antelope Lake	168.7	3939	No	EM-61	3.42	0.3	37.41.38.36	-116.40.02.81	529318.3	4171915.3
North Antelope Lake	82.7	1255	No	EM-61	2.71	0.2	37.41.25.09	-116.40.02.84	529319.0	4171506.5
North Antelope Lake	63.8	158	No	EM-61	3.34	0.2	37.41.15.41	-116.40.01.48	529353.3	4171208.3
North Antelope Lake	73.6	2751	No	EM-61	1.98	0.2	37.41.32.02	-116.40.00.89	529365.9	4171720.0
North Antelope Lake	282.1	1170	No	EM-61	4.46	0	37.41.24.61	-116.39.59.69	529396.0	4171491.8
North Antelope Lake	68.7	135	No	EM-61	1.43	0.2	37.41.15.29	-116.39.59.56	529400.2	4171204.8
North Antelope Lake	86.8	272	No	EM-61	2.44	0	37.41.16.11	-116.39.59.19	529409.3	4171230.0
North Antelope Lake	1029.1	322	No	EM-61	1.6	0.5	37.41.16.50	-116.39.58.96	529414.9	4171241.9
North Antelope Lake	227.3	2420	No	EM-61	1.4	1.1	37.41.30.76	-116.39.57.98	529437.3	4171681.5
North Antelope Lake	246.8	2431	No	EM-61	1.81	0.9	37.41.30.80	-116.39.57.92	529438.7	4171682.9
North Antelope Lake	332	2125	No	EM-61	4.08	0.2	37.41.29.43	-116.39.54.90	529512.9	4171640.9
North Antelope Lake	14263.1	1966	No	EM-61	2.45	0.2	37.41.28.63	-116.39.54.19	529530.4	4171616.4
North Antelope Lake	100.7	125	No	EM-61	3.07	0.2	37.41.15.23	-116.39.51.36	529601.1	4171203.4
North Antelope Lake	101.2	48	No	EM-61	1.98	0	37.41.14.61	-116.39.51.02	529609.5	4171184.5
North Antelope Lake	196.2	165	No	EM-61	1.4	0.2	37.41.15.47	-116.39.50.53	529621.4	4171211.1
North Antelope Lake	196.3	2954	No	EM-61	1.88	0.2	37.41.32.71	-116.39.50.28	529625.6	4171742.4
North Antelope Lake	93.8	2068	No	EM-61	2.1	0.2	37.41.29.21	-116.39.49.47	529645.9	4171634.6
North Antelope Lake	81.4	2818	No	EM-61	1.72	0.2	37.41.32.25	-116.39.46.60	529715.9	4171728.4
North Antelope Lake	179.2	757	No	EM-61	2.01	0.2	37.41.21.84	-116.39.45.99	529732.0	4171407.8
North Antelope Lake	124.6	1882	No	EM-61	4.62	0.2	37.41.28.27	-116.39.44.84	529759.3	4171605.9
North Antelope Lake	515.5	3184	No	EM-61	2.55	0.9	37.41.33.60	-116.39.43.79	529784.5	4171770.4
North Antelope Lake	38.5	4399	No	EM-61	3.76	1.1	37.41.40.41	-116.39.43.07	529801.3	4171980.4
North Antelope Lake	314	1093	No	EM-61	4.81	0.2	37.41.23.98	-116.39.39.66	529886.7	4171474.3
North Antelope Lake	142.1	512	No	EM-61	1.83	0.7	37.41.17.80	-116.39.38.95	529904.9	4171283.9
North Antelope Lake	49.7	617	No	EM-61	3.64	0.2	37.41.20.73	-116.39.37.25	529946.2	4171374.2
North Antelope Lake	733.3	748	No	EM-61	4.02	0	37.41.21.77	-116.39.35.78	529981.9	4171406.4
North Antelope Lake	363.4	842	No	EM-61	6.63	0	37.41.22.27	-116.39.34.98	530001.5	4171421.8
North Antelope Lake	61.7	2111	No	EM-61	2.68	0	37.41.29.33	-116.39.33.78	530030.2	4171639.5
North Antelope Lake	33.6	2133	No	EM-61	2.12	0.2	37.41.29.39	-116.39.32.40	530063.8	4171641.6
North Antelope Lake	27.7	1180	No	EM-61	3.48	0.2	37.41.24.57	-116.39.29.63	530132.4	4171493.2
North Antelope Lake	n/a	ID 2614	Scrap Metal	EM-61 and Photo	n/a	n/a			528229.0	4171680.0

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	n/a	ID 2657	Concrete/Rebar	EM-61 and Photo	n/a	n/a			528278.0	4171685.0
North Antelope Lake	n/a	ID 2457	Concrete/Rebar	EM-61 and Photo	n/a	n/a			528287.0	4171660.0
North Antelope Lake	n/a	ID 2636	Concrete/Rebar	EM-61 and Photo	n/a	n/a			528255.0	4171682.0
North Antelope Lake	n/a	ID 1088	Scrap Metal	EM-61 and Photo	n/a	n/a			528325.0	4171442.0
North Antelope Lake	n/a	JT 4724	Scrap Metal	EM-61	n/a	n/a			528855.0	4171981.0
North Antelope Lake	n/a	ID 11476	Scrap Metal	EM-61 and Photo	n/a	n/a			529252.0	4171927.0
North Antelope Lake	n/a	P007_001	155 Projectile	EM-61	n/a	n/a			537636.0	4171204.0
North Antelope Lake	n/a	P006_001	Mk-82 Bomb	EM-61	n/a	n/a			528699.0	4171153.0
North Antelope Lake	n/a	EM 1	No	EM-61	n/a	n/a			528259.6	4172162.0
North Antelope Lake	n/a	ID 2456	No	EM-61	n/a	n/a			528243.1	4171660.5
North Antelope Lake	n/a	ID 2615	No	EM-61	n/a	n/a			528379.7	4171680.1
North Antelope Lake	n/a	ID 279	No	EM-61	n/a	n/a			529020.8	4171227.9
North Antelope Lake	n/a	IM 1	No	Photo	n/a	n/a			528159.0	4171671.6
North Antelope Lake	n/a	IM 2	No	EM-61 and Photo	n/a	n/a			528261.8	4171671.6
North Antelope Lake	n/a	IM 3	No	Photo	n/a	n/a			528070.2	4171671.4
North Antelope Lake	n/a	IM 4	No	Photo	n/a	n/a			528121.0	4171672.0
North Antelope Lake	n/a	IM 5	No	Photo	n/a	n/a			528232.0	4171672.3
North Antelope Lake	n/a	IM 6	No	Photo	n/a	n/a			528518.7	4171679.0
North Antelope Lake	n/a	IM 7	No	Photo	n/a	n/a			528577.8	4171567.0
North Antelope Lake	n/a	IM 8	No	Photo	n/a	n/a			528580.0	4171261.0
North Antelope Lake	n/a	IM 9	No	Photo	n/a	n/a			528806.2	4171674.2
North Antelope Lake	n/a	IM 10	No	Photo	n/a	n/a			528871.3	4171674.0
North Antelope Lake	629.9078204	P003_001	No	EM-61	1	0.2	37.41.12.95	-116.40.50.75	528146.9	4171128.3
North Antelope Lake	169.3765442	P005_001	No	EM-61	1.5	2.1	37.41.12.77	-116.40.32.70	528589.1	4171124.2
North Antelope Lake	94.21380025	P006_001	No	EM-61	1.61	>4	37.41.13.67	-116.40.28.22	528698.6	4171152.4
North Antelope Lake	61.88247228	P006_002	No	EM-61	1.58	1.5	37.41.12.74	-116.40.27.47	528717.1	4171123.8
North Antelope Lake	267.5299548	P006_003	No	EM-61	1.27	3.5	37.41.11.50	-116.40.26.69	528736.2	4171085.4
North Antelope Lake	71.26310443	P007_001	No	EM-61	0.96	2.1	37.41.14.18	-116.40.23.31	528818.8	4171168.3
North Antelope Lake	70.08785988	P007_002	No	EM-61	1.05	2.2	37.41.14.07	-116.40.19.04	528923.4	4171165.3
North Antelope Lake	82.87924442	P007_003	No	EM-61	1.5	>4	37.41.11.05	-116.40.22.53	528838.2	4171072.0
North Antelope Lake	56.96318166	P007_004	No	EM-61	1.97	>4	37.41.09.33	-116.40.19.49	528912.9	4171019.2
North Antelope Lake	49.52033439	P007_005	No	EM-61	1.48	>4	37.41.10.25	-116.40.21.70	528858.7	4171047.3
North Antelope Lake	1116.085121	P007_006	No	EM-61	2.05	>4	37.41.09.03	-116.40.21.72	528858.2	4171010.0
North Antelope Lake	110.0284865	P007_007	No	EM-61	1.47	4.1	37.41.08.88	-116.40.21.91	528853.5	4171005.1
North Antelope Lake	139.5553149	P007_008	No	EM-61	1.33	>4	37.41.09.59	-116.40.22.78	528832.1	4171026.9
North Antelope Lake	324.3564022	P007_009	No	EM-61	1.53	>4	37.41.08.76	-116.40.22.71	528834.1	4171001.3
North Antelope Lake	166.0031635	P007_010	No	EM-61	1.74	2.2	37.41.10.53	-116.40.22.66	528835.2	4171055.9
North Antelope Lake	269.0308004	P008_001	No	EM-61	1.19	>4	37.41.09.38	-116.40.11.50	529108.5	4171021.6
North Antelope Lake	71.51160896	P008_002	No	EM-61	0.98	>4	37.41.09.08	-116.40.14.66	529031.3	4171011.9
North Antelope Lake	45.40967746	P009_01	No	EM-61	1.13	>4	37.41.08.78	-116.40.07.65	529203.0	4171003.4

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	246.7976646	P017_01	No	EM-61	1.44	>4	37.41.06.18	-116.41.00.68	527904.2	4170918.8
North Antelope Lake	73.41980365	P019_01	No	EM-61	1.06	1.5	37.41.04.54	-116.40.48.33	528206.9	4170869.3
North Antelope Lake	50.97398218	P020.01	No	EM-61	0.9	>4	37.41.05.68	-116.40.33.18	528578.0	4170905.7
North Antelope Lake	293.2156692	P020.02	No	EM-61	1.37	2.6	37.41.07.81	-116.40.33.07	528580.4	4170971.2
North Antelope Lake	1322.004152	P021_01	No	EM-61	1.21	3.4	37.41.03.05	-116.40.26.88	528732.5	4170825.2
North Antelope Lake	82.77844772	P021_02	No	EM-61	1.84	2	37.41.05.81	-116.40.26.10	528751.3	4170910.4
North Antelope Lake	208.2314879	P021_03	No	EM-61	1.26	1.1	37.41.05.94	-116.40.31.91	528609.0	4170913.7
North Antelope Lake	170.3312483	P021_04	No	EM-61	0.91	2.3	37.41.06.19	-116.40.26.25	528747.7	4170921.9
North Antelope Lake	89.25682407	P021_05	No	EM-61	1.2	3.2	37.41.08.43	-116.40.25.04	528776.9	4170991.0
North Antelope Lake	76.06479526	P022_01	No	EM-61	1.9	2.8	37.41.04.19	-116.40.17.35	528965.8	4170861.1
North Antelope Lake	103.4925926	P022_02	No	EM-61	1.09	3.3	37.41.07.51	-116.40.23.45	528816.1	4170962.7
North Antelope Lake	104.8333929	P022_03	No	EM-61	1.07	>4	37.41.08.59	-116.40.22.70	528834.3	4170996.3
North Antelope Lake	64.45781793	P022_04	No	EM-61	0.87	4	37.41.08.66	-116.40.23.76	528808.3	4170998.3
North Antelope Lake	53.47320382	P023_01	No	EM-61	1.17	0.8	37.41.05.57	-116.40.08.49	529182.6	4170904.3
North Antelope Lake	198.4167585	P023_02	No	EM-61	1.25	>4	37.41.08.20	-116.40.08.63	529178.9	4170985.4
North Antelope Lake	167.0815715	P026_001	No	EM-61	1.09	>4	37.41.08.41	-116.39.51.01	529610.5	4170993.4
North Antelope Lake	289.1890202	P026_002	No	EM-61	1.97	>4	37.41.05.01	-116.39.47.60	529694.3	4170888.9
North Antelope Lake	242.2432754	P026_003	No	EM-61	1.48	2.4	37.41.04.80	-116.39.47.59	529694.5	4170882.3
North Antelope Lake	356.4435571	P026_004	No	EM-61	1.12	>4	37.41.03.94	-116.39.47.46	529697.9	4170855.9
North Antelope Lake	96.75576693	P030_001	No	EM-61	1.48	3.9	37.41.06.04	-116.39.15.10	530490.2	4170923.6
North Antelope Lake	236.8722103	P030_002	No	EM-61	0.89	>4	37.41.05.60	-116.39.15.63	530477.2	4170910.1
North Antelope Lake	2210.60857	P032_001	No	EM-61	0.95	>4	37.41.04.35	-116.39.02.16	530807.4	4170872.7
North Antelope Lake	38.83385684	P036_01	No	EM-61	0.87	2.9	37.40.57.85	-116.40.38.06	528459.2	4170663.8
North Antelope Lake	565.619521	P036_02	No	EM-61	0.95	0.3	37.41.00.55	-116.40.34.11	528555.7	4170747.5
North Antelope Lake	18.61917925	P037_01	No	EM-61	0.83	>4	37.40.57.40	-116.40.27.29	528723.0	4170651.0
North Antelope Lake	2614.191003	P037_02	No	EM-61	0.96	>4	37.41.00.15	-116.40.26.72	528736.8	4170735.6
North Antelope Lake	104.1564895	P037_03	No	EM-61	1.73	0.1	37.41.00.88	-116.40.28.01	528705.2	4170758.3
North Antelope Lake	262.3479345	P037_04	No	EM-61	1.63	1.6	37.41.02.00	-116.40.27.42	528719.4	4170792.7
North Antelope Lake	20.24446664	P038_01	No	EM-61	1.25	>4	37.40.59.23	-116.40.22.04	528851.4	4170707.6
North Antelope Lake	396.0398605	P039_01	No	EM-61	1.02	2.2	37.40.57.30	-116.40.11.16	529118.1	4170649.1
North Antelope Lake	500.618502	P047_01	No	EM-61	0.72	0	37.40.58.61	-116.39.07.80	530669.8	4170695.3
North Antelope Lake	1002.786471	P049_01	No	EM-61	1.5	0.7	37.40.54.65	-116.40.53.21	528088.5	4170563.9
North Antelope Lake	189.4533155	P051_01	No	EM-61	1.52	1.4	37.40.51.05	-116.40.36.22	528505.1	4170454.6
North Antelope Lake	117.9988485	P053_12	No	EM-61	1.56	2.8	37.40.55.68	-116.40.21.03	528876.6	4170598.3
North Antelope Lake	1023.394197	P054_01	No	EM-61	0.9	2.2	37.40.55.23	-116.40.08.98	529171.7	4170585.6
North Antelope Lake	282.5217072	P055_01	No	EM-61	1.04	0.3	37.40.51.50	-116.40.02.44	529332.4	4170471.2
North Antelope Lake	1594.802706	P056_03	No	EM-61	0.93	1.8	37.40.51.59	-116.39.56.36	529481.3	4170474.6
North Antelope Lake	1319.553394	P057_01	No	EM-61	1.01	>4	37.40.55.02	-116.39.47.81	529690.2	4170581.1
North Antelope Lake	343.3	P057-002	No	EM-61	1.27	unknown	37.40.54.74	-116.39.51.48	529600.5	4170572.0
North Antelope Lake	1008.399536	P058_01	No	EM-61	1.29	>4	37.40.53.38	-116.39.36.44	529969.1	4170531.3

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
North Antelope Lake	1416.601462	P058_02	No	EM-61	1.29	>4	37.40.54.88	-116.39.38.09	529928.5	4170577.4
Antelope Tuff 1	121.0967712	A02_001	No	EM-61	> 100	1.07	37.38.35.72	-116.34.28.51	537530.4	4166319.8
Antelope Tuff 1	126.9375	A02_002	No	EM-61	> 100	1.41	37.38.35.75	-116.34.28.19	537538.4	4166320.6
Antelope Tuff 1	355.2828674	A02_003	No	EM-61	> 100	0.52	37.38.35.79	-116.34.28.65	537527.0	4166321.8
Antelope Tuff 1	186.0317123	A02_004	No	EM-61	0-50	0	37.38.35.82	-116.34.28.66	537526.9	4166322.8
Antelope Tuff 1	108.6561661	A02_005	No	EM-61	0-50	0.06	37.38.36.00	-116.34.27.52	537554.6	4166328.4
Antelope Tuff 1	80.99757385	A02_006	No	EM-61	0-50	0.18	37.38.36.02	-116.34.27.55	537554.0	4166329.2
Antelope Tuff 1	137.3817749	A02_007	No	EM-61	> 100	1.57	37.38.36.08	-116.34.28.73	537525.0	4166330.8
Antelope Tuff 1	217.0278855	A02_008	No	EM-61	> 100	0.46	37.38.36.08	-116.34.27.21	537562.4	4166331.1
Antelope Tuff 1	1553.414551	A02_009	No	EM-61	> 100	0	37.38.36.36	-116.34.29.42	537508.2	4166339.4
Antelope Tuff 1	78.01734924	A02_010	No	EM-61	0-50	0.14	37.38.36.42	-116.34.29.32	537510.6	4166341.2
Antelope Tuff 1	1244.063232	A02_011	No	EM-61	> 100	0.28	37.38.36.49	-116.34.28.48	537531.2	4166343.4
Antelope Tuff 1	1112.423584	A02_012	No	EM-61	> 100	0.47	37.38.36.52	-116.34.28.40	537533.2	4166344.4
Antelope Tuff 1	1065.097656	A02_013	No	EM-61	> 100	0	37.38.36.64	-116.34.28.59	537528.4	4166348.0
Antelope Tuff 1	591.8530884	A02_014	No	EM-61	0-50	0.12	37.38.36.66	-116.34.28.61	537527.8	4166348.8
Antelope Tuff 1	657.4464818	A02_015	No	EM-61	0-50	0	37.38.36.67	-116.34.28.39	537533.4	4166349.1
Antelope Tuff 1	1105.756348	A02_016	No	EM-61	> 100	2.04	37.38.36.71	-116.34.28.37	537533.8	4166350.2
Antelope Tuff 1	206.9748533	A02_017	No	EM-61	> 100	2.17	37.38.36.73	-116.34.28.35	537534.4	4166351.0
Antelope Tuff 1	1134.8927	A02_018	No	EM-61	> 100	0.26	37.38.36.75	-116.34.28.80	537523.2	4166351.6
Antelope Tuff 1	1478.41809	A02_019	No	EM-61	> 100	0.32	37.38.36.80	-116.34.28.73	537525.0	4166353.0
Antelope Tuff 1	148.2327881	A02_020	No	EM-61	0-50	0	37.38.36.85	-116.34.28.98	537518.8	4166354.4
Antelope Tuff 1	1826.892334	A02_021	No	EM-61	> 100	0.02	37.38.36.86	-116.34.28.18	537538.4	4166355.0
Antelope Tuff 1	5096.319824	A02_022	No	EM-61	> 100	0.3	37.38.36.88	-116.34.28.30	537535.4	4166355.4
Antelope Tuff 1	183.5243916	A02_023	No	EM-61	50-100	0.07	37.38.36.87	-116.34.29.00	537518.2	4166355.1
Antelope Tuff 1	701.6811523	A02_024	No	EM-61	> 100	0.96	37.38.36.89	-116.34.28.97	537519.0	4166355.8
Antelope Tuff 1	953.6956134	A02_025	No	EM-61	0-50	0	37.38.36.91	-116.34.28.32	537535.1	4166356.4
Antelope Tuff 1	1477.138672	A02_026	No	EM-61	> 100	0.1	37.38.36.99	-116.34.28.10	537540.4	4166359.0
Antelope Tuff 1	1588.249146	A02_027	No	EM-61	> 100	0.06	37.38.37.00	-116.34.28.78	537523.8	4166359.2
Antelope Tuff 1	512.3568115	A02_028	No	EM-61	> 100	0.4	37.38.37.00	-116.34.28.74	537524.8	4166359.2
Antelope Tuff 1	144.6507416	A02_029	No	EM-61	> 100	1.37	37.38.37.02	-116.34.28.57	537528.8	4166359.8
Antelope Tuff 1	1584.486572	A02_030	No	EM-61	> 100	0.06	37.38.37.04	-116.34.28.29	537535.8	4166360.4
Antelope Tuff 1	249.3630066	A02_031	No	EM-61	> 100	0.39	37.38.37.04	-116.34.27.95	537544.0	4166360.4
Antelope Tuff 1	246.7623071	A02_032	No	EM-61	50-100	0.05	37.38.37.16	-116.34.28.67	537526.4	4166364.1
Antelope Tuff 1	687.705322	A02_033	No	EM-61	> 100	1.07	37.38.37.16	-116.34.28.60	537528.2	4166364.0
Antelope Tuff 1	2647.756836	A02_034	No	EM-61	> 100	0.18	37.38.37.18	-116.34.28.95	537519.4	4166364.8
Antelope Tuff 1	106.5794601	A02_035	No	EM-61	> 100	0.83	37.38.37.18	-116.34.28.05	537541.6	4166364.8
Antelope Tuff 1	125.8350677	A02_036	No	EM-61	> 100	0.97	37.38.37.33	-116.34.28.61	537527.8	4166369.4
Antelope Tuff 1	615.9520263	A02_037	No	EM-61	> 100	0.05	37.38.37.34	-116.34.28.79	537523.4	4166369.6
Antelope Tuff 1	100.499115	A02_038	No	EM-61	> 100	0.61	37.38.37.35	-116.34.28.66	537526.6	4166370.0
Antelope Tuff 1	1808.767944	A02_039	No	EM-61	> 100	0.95	37.38.37.35	-116.34.27.90	537545.2	4166370.2

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Antelope Tuff 1	252.465454	A02_040	No	EM-61	> 100	1.25	37.38.37.37	-116.34.28.83	537522.4	4166370.6
Antelope Tuff 1	145.8226928	A02_041	No	EM-61	> 100	0.44	37.38.37.47	-116.34.28.51	537530.2	4166373.6
Antelope Tuff 1	77.48783874	A02_042	No	EM-61	> 100	0.68	37.38.37.49	-116.34.29.09	537516.0	4166374.2
Antelope Tuff 1	433.927551	A02_043	No	EM-61	0-50	0	37.38.37.52	-116.34.29.73	537500.4	4166375.0
Antelope Tuff 1	242.3859558	A02_044	No	EM-61	> 100	0.3	37.38.37.52	-116.34.28.49	537530.8	4166375.2
Antelope Tuff 1	102.1544513	A02_045	No	EM-61	0-50	0	37.38.37.51	-116.34.28.44	537532.0	4166375.0
Antelope Tuff 1	487.8575468	A02_046	No	EM-61	50-100	0.01	37.38.37.56	-116.34.28.51	537530.3	4166376.3
Antelope Tuff 1	75.41605222	A02_047	No	EM-61	> 100	1.83	37.38.37.64	-116.34.28.58	537528.5	4166379.0
Antelope Tuff 1	1877.151245	A02_048	No	EM-61	> 100	0.56	37.38.37.54	-116.34.28.27	537536.2	4166375.8
Antelope Tuff 1	116.7446823	A02_049	No	EM-61	0-50	0	37.38.37.54	-116.34.28.42	537532.4	4166376.0
Antelope Tuff 1	1066.666137	A02_050	No	EM-61	> 100	0.86	37.38.37.56	-116.34.28.38	537533.4	4166376.6
Antelope Tuff 1	1059.361303	A02_051	No	EM-61	> 100	0.25	37.38.37.56	-116.34.28.46	537531.5	4166376.5
Antelope Tuff 1	145.178543	A02_052	No	EM-61	50-100	0.23	37.38.37.58	-116.34.28.58	537528.6	4166377.0
Antelope Tuff 1	2312.421875	A02_053	No	EM-61	> 100	0.52	37.38.37.59	-116.34.28.50	537530.6	4166377.4
Antelope Tuff 1	881.5501098	A02_054	No	EM-61	> 100	1.24	37.38.37.60	-116.34.28.43	537532.2	4166377.6
Antelope Tuff 1	2637.863525	A02_055	No	EM-61	> 100	0	37.38.37.62	-116.34.28.48	537531.0	4166378.4
Antelope Tuff 1	2144.729248	A02_056	No	EM-61	> 100	0.17	37.38.37.64	-116.34.28.53	537529.8	4166378.8
Antelope Tuff 1	2224.5271	A02_057	No	EM-61	> 100	0.52	37.38.37.70	-116.34.29.62	537503.0	4166380.8
Antelope Tuff 1	904.1717529	A02_058	No	EM-61	0-50	0	37.38.37.74	-116.34.29.60	537503.4	4166381.8
Antelope Tuff 1	85.81639218	A02_059	No	EM-61	> 100	0.34	37.38.37.74	-116.34.28.55	537529.2	4166382.0
Antelope Tuff 1	123.3190841	A02_060	No	EM-61	> 100	0.48	37.38.37.82	-116.34.27.92	537544.6	4166384.6
Antelope Tuff 1	84.14748383	A02_061	No	EM-61	50-100	0.51	37.38.37.83	-116.34.29.00	537518.2	4166384.8
Antelope Tuff 1	59.48457413	A02_062	No	EM-61	50-100	0.4	37.38.37.86	-116.34.27.44	537556.4	4166385.7
Antelope Tuff 1	85.31106204	A02_063	No	EM-61	0-50	0.17	37.38.37.93	-116.34.29.32	537510.3	4166387.9
Antelope Tuff 1	99.18401443	A02_064	No	EM-61	0-50	0.06	37.38.37.96	-116.34.29.39	537508.7	4166388.7
Antelope Tuff 1	94.70148468	A02_065	No	EM-61	> 100	0.91	37.38.37.94	-116.34.29.36	537509.4	4166388.2
Antelope Tuff 1	185.149765	A02_066	No	EM-61	> 100	1.08	37.38.37.94	-116.34.27.46	537556.0	4166388.2
Antelope Tuff 1	55.42341531	A02_067	No	EM-61	0-50	0	37.38.37.97	-116.34.29.32	537510.2	4166389.0
Antelope Tuff 1	78.86222075	A02_068	No	EM-61	> 100	0.56	37.38.37.97	-116.34.28.71	537525.2	4166389.0
Antelope Tuff 1	2410.422119	A02_069	No	EM-61	> 100	0	37.38.38.12	-116.34.29.20	537513.2	4166393.8
Antelope Tuff 1	1503.977294	A02_070	No	EM-61	> 100	0.13	37.38.38.26	-116.34.29.04	537517.2	4166398.0
Antelope Tuff 1	294.6197203	A02_071	No	EM-61	0-50	0.17	37.38.38.31	-116.34.29.12	537515.2	4166399.6
Antelope Tuff 1	66.21424383	A02_072	No	EM-61	> 100	0.57	37.38.37.96	-116.34.28.67	537526.2	4166388.9
Antelope Tuff 1	55.98818165	A02_073	No	EM-61	50-100	0.28	37.38.36.63	-116.34.27.79	537548.1	4166348.0
Antelope Tuff 1	61.609982	A02_074	No	EM-61	50-100	0.47	37.38.36.87	-116.34.29.19	537513.7	4166355.1
Antelope Tuff 1A	53.15109062	A03_001	No	EM-61	50-100	0.46	37.38.33.88	-116.34.30.06	537492.7	4166263.0
Antelope Tuff 2	89.30002594	A01_001	No	EM-61	> 100	0.66	37.39.03.83	-116.35.08.62	536543.8	4167181.6
Antelope Tuff 2	1371.173828	A01_002	No	EM-61	> 100	0.35	37.39.04.08	-116.35.09.82	536514.4	4167189.2
Antelope Tuff 2	276.7088928	A01_003	No	EM-61	> 100	0.22	37.39.04.14	-116.35.09.06	536533.0	4167191.2
Antelope Tuff 2	86.80807859	A01_004	No	EM-61	> 100	1.31	37.39.04.14	-116.35.09.72	536516.7	4167191.3

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Antelope Tuff 2	185.7362671	A01_005	No	EM-61	> 100	0	37.39.04.18	-116.35.09.82	536514.2	4167192.2
Antelope Tuff 2	1038.161621	A01_006	No	EM-61	> 100	0.63	37.39.04.18	-116.35.09.77	536515.6	4167192.2
Antelope Tuff 2	175.4237976	A01_007	No	EM-61	> 100	0.99	37.39.04.17	-116.35.09.70	536517.2	4167192.2
Antelope Tuff 2	113.2630997	A01_008	No	EM-61	> 100	0.85	37.39.04.23	-116.35.09.84	536513.8	4167194.0
Antelope Tuff 2	581.4048462	A01_009	No	EM-61	0-50	0.06	37.39.04.45	-116.35.09.63	536519.0	4167200.6
Antelope Tuff 2	146.8759737	A01_010	No	EM-61	> 100	0.72	37.39.04.46	-116.35.09.58	536520.0	4167201.0
Antelope Tuff 2	373.8952942	A01_011	No	EM-61	> 100	1.68	37.39.04.47	-116.35.09.54	536521.0	4167201.2
Antelope Tuff 2	172.5840756	A01_012	No	EM-61	0-50	0.33	37.39.04.51	-116.35.09.56	536520.6	4167202.4
Antelope Tuff 2	109.6725311	A01_013	No	EM-61	0-50	0.12	37.39.04.55	-116.35.09.90	536512.2	4167203.8
Antelope Tuff 2	102.1651687	A01_014	No	EM-61	> 100	1.04	37.39.04.55	-116.35.09.86	536513.2	4167203.8
Antelope Tuff 2	115.1486663	A01_015	No	EM-61	> 100	0.67	37.39.04.57	-116.35.09.89	536512.4	4167204.4
Antelope Tuff 2	162.6413727	A01_016	No	EM-61	50-100	0.17	37.39.04.63	-116.35.11.06	536483.8	4167206.2
Antelope Tuff 2	97.65257261	A01_017	No	EM-61	50-100	0.37	37.39.04.97	-116.35.09.85	536513.4	4167216.6
Antelope Tuff 2	1997.842163	A01_018	No	EM-61	> 100	0.07	37.39.04.98	-116.35.09.81	536514.4	4167217.0
Antelope Tuff 2	129.081085	A01_019	No	EM-61	> 100	1.74	37.39.05.03	-116.35.09.74	536516.2	4167218.4
Antelope Tuff 2	1293.911254	A01_020	No	EM-61	> 100	0.54	37.39.05.07	-116.35.08.96	536535.2	4167219.8
Antelope Tuff 2	844.321581	A01_021	No	EM-61	> 100	0.57	37.39.05.08	-116.35.09.73	536516.4	4167220.0
Antelope Tuff 2	2238.562011	A01_022	No	EM-61	> 100	0.1	37.39.05.11	-116.35.09.74	536516.0	4167221.0
Antelope Tuff 2	3196.788543	A01_023	No	EM-61	> 100	0.44	37.39.05.14	-116.35.09.72	536516.7	4167221.8
Antelope Tuff 2	104.1390686	A01_024	No	EM-61	0-50	0	37.39.05.15	-116.35.08.79	536539.4	4167222.4
Antelope Tuff 2	442.9122512	A01_025	No	EM-61	> 100	0.69	37.39.05.16	-116.35.08.76	536540.2	4167222.5
Antelope Tuff 2	185.9874725	A01_026	No	EM-61	0-50	0	37.39.05.17	-116.35.08.68	536542.2	4167223.0
Antelope Tuff 2	1694.225231	A01_027	No	EM-61	> 100	0.8	37.39.05.19	-116.35.09.72	536516.6	4167223.4
Antelope Tuff 2	3334.343994	A01_028	No	EM-61	> 100	0.43	37.39.05.21	-116.35.09.69	536517.4	4167224.0
Antelope Tuff 2	119.5713282	A01_029	No	EM-61	> 100	0.9	37.39.05.21	-116.35.09.64	536518.5	4167224.0
Antelope Tuff 2	1667.583374	A01_030	No	EM-61	0-50	0.09	37.39.05.24	-116.35.09.66	536518.0	4167225.0
Antelope Tuff 2	207.57489	A01_031	No	EM-61	> 100	0.5	37.39.05.30	-116.35.09.57	536520.2	4167226.8
Antelope Tuff 2	819.3988647	A01_032	No	EM-61	> 100	0.03	37.39.05.30	-116.35.09.25	536528.0	4167227.0
Antelope Tuff 2	442.5690002	A01_033	No	EM-61	0-50	0	37.39.05.30	-116.35.09.16	536530.2	4167227.0
Antelope Tuff 2	442.2000523	A01_034	No	EM-61	> 100	0.03	37.39.05.31	-116.35.09.21	536529.2	4167227.2
Antelope Tuff 2	104.4393845	A01_035	No	EM-61	> 100	0.47	37.39.05.34	-116.35.08.63	536543.4	4167228.2
Antelope Tuff 2	314.9288557	A01_036	No	EM-61	> 100	1.15	37.39.05.36	-116.35.09.61	536519.4	4167228.6
Antelope Tuff 2	211.7576716	A01_037	No	EM-61	> 100	1.19	37.39.05.32	-116.35.09.60	536519.5	4167227.6
Antelope Tuff 2	392.3757413	A01_038	No	EM-61	> 100	0.83	37.39.05.34	-116.35.09.57	536520.3	4167228.1
Antelope Tuff 2	184.3907318	A01_039	No	EM-61	50-100	0.32	37.39.05.35	-116.35.08.90	536536.6	4167228.6
Antelope Tuff 2	102.0831024	A01_040	No	EM-61	> 100	0.28	37.39.05.36	-116.35.09.53	536521.1	4167228.7
Antelope Tuff 2	133.7206266	A01_041	No	EM-61	> 100	1.92	37.39.05.38	-116.35.09.57	536520.2	4167229.4
Antelope Tuff 2	117.7671432	A01_042	No	EM-61	> 100	0.93	37.39.05.43	-116.35.09.50	536522.0	4167231.0
Antelope Tuff 2	107.3552087	A01_043	No	EM-61	> 100	1.47	37.39.05.55	-116.35.09.91	536512.0	4167234.5
Antelope Tuff 2	123.8595734	A01_044	No	EM-61	> 100	1.4	37.39.05.58	-116.35.09.91	536511.8	4167235.6

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Antelope Tuff 2	87.08030701	A01_045	No	EM-61	50-100	0.67	37.39.05.69	-116.35.08.75	536540.2	4167239.0
Antelope Tuff 2	92.45804596	A01_046	No	EM-61	> 100	0.74	37.39.05.70	-116.35.09.15	536530.4	4167239.2
Antelope Tuff 2	81.89744568	A01_047	No	EM-61	> 100	0.76	37.39.05.81	-116.35.08.91	536536.4	4167242.6
Antelope Tuff 2	106.211138	A01_048	No	EM-61	0-50	0	37.39.05.96	-116.35.09.66	536518.0	4167247.2
Antelope Tuff 2	116.297905	A01_049	No	EM-61	> 100	1.32	37.39.06.00	-116.35.09.48	536522.4	4167248.6
Antelope Tuff 2	165.9365692	A01_050	No	EM-61	> 100	0.29	37.39.06.19	-116.35.09.23	536528.4	4167254.2
Antelope Tuff 2	1023.413513	A01_051	No	EM-61	> 100	0	37.39.06.19	-116.35.09.48	536522.4	4167254.4
Antelope Tuff 2	86.09307336	A01_052	No	EM-61	> 100	1.34	37.39.06.21	-116.35.09.28	536527.2	4167254.9
Antelope Tuff 2	93.12323761	A01_053	No	EM-61	0-50	0	37.39.06.22	-116.35.09.24	536528.2	4167255.2
Antelope Tuff 2	190.0585022	A01_054	No	EM-61	0-50	0	37.39.06.25	-116.35.10.18	536505.2	4167256.2
Antelope Tuff 2	88.41239929	A01_055	No	EM-61	> 100	0.96	37.39.06.28	-116.35.10.20	536504.6	4167257.0
Antelope Tuff 2	164.6018219	A01_056	No	EM-61	> 100	0.43	37.39.06.28	-116.35.10.15	536506.0	4167257.0
Antelope Tuff 2	84.91069794	A01_057	No	EM-61	50-100	0.31	37.39.06.33	-116.35.09.00	536534.2	4167258.6
Antelope Tuff 2	114.1850815	A01_058	No	EM-61	> 100	1.38	37.39.06.39	-116.35.09.24	536528.2	4167260.6
Antelope Tuff 2	57.37884545	A01_059	No	EM-61	> 100	0.88	37.39.06.41	-116.35.09.19	536529.3	4167261.0
Antelope Tuff 2	85.0625	A01_060	No	EM-61	50-100	0.27	37.39.06.41	-116.35.09.28	536527.2	4167261.0
Antelope Tuff 2	47.7545085	A01_061	No	EM-61	> 100	0.94	37.39.06.43	-116.35.09.25	536528.0	4167261.6
Antelope Tuff 2	80.93502044	A01_062	No	EM-61	> 100	1.23	37.39.06.63	-116.35.10.23	536504.0	4167267.8
Antelope Tuff 2	273.1737976	A01_063	No	EM-61	0-50	0	37.39.06.64	-116.35.10.75	536491.2	4167268.0
Antelope Tuff 2	495.9472961	A01_064	No	EM-61	> 100	1.06	37.39.06.71	-116.35.10.79	536490.2	4167270.2
Antelope Tuff 2	91.58968353	A01_065	No	EM-61	> 100	0.34	37.39.06.73	-116.35.09.74	536516.0	4167271.0
Antelope Tuff 2	102.0078125	A01_066	No	EM-61	> 100	0.98	37.39.06.76	-116.35.09.74	536516.0	4167272.0
Antelope Tuff 2	81.29265574	A01_067	No	EM-61	0-50	0.13	37.39.06.82	-116.35.09.25	536527.8	4167273.8
Antelope Tuff 2	85.7978897	A01_068	No	EM-61	0-50	0.21	37.39.06.96	-116.35.09.66	536517.8	4167278.0
Antelope Tuff 2	79.22315213	A01_069	No	EM-61	> 100	1.83	37.39.06.98	-116.35.10.87	536488.2	4167278.4
Antelope Tuff 2	85.11030578	A01_070	No	EM-61	0-50	0.37	37.39.07.03	-116.35.09.80	536514.4	4167280.2
Antelope Tuff 2	939.8493646	A01_071	No	EM-61	> 100	2.2	37.39.07.10	-116.35.08.88	536537.0	4167282.4
Antelope Tuff 2	333.9421692	A01_072	No	EM-61	> 100	0.31	37.39.07.12	-116.35.08.77	536539.6	4167283.0
Antelope Tuff 2	178.7877045	A01_073	No	EM-61	> 100	0.95	37.39.07.14	-116.35.10.30	536502.2	4167283.4
Antelope Tuff 2	112.858139	A01_074	No	EM-61	> 100	0.85	37.39.07.23	-116.35.09.22	536528.6	4167286.4
Antelope Tuff 2	75.0037384	A01_075	No	EM-61	> 100	0.93	37.39.07.24	-116.35.09.48	536522.2	4167286.6
Antelope Tuff 2	82.04140465	A01_076	No	EM-61	50-100	0.64	37.39.07.25	-116.35.11.48	536473.2	4167286.8
Antelope Tuff 2	111.9729767	A01_077	No	EM-61	50-100	0.19	37.39.07.30	-116.35.09.46	536522.8	4167288.6
Antelope Tuff 2	766.8761597	A01_078	No	EM-61	> 100	0.71	37.39.07.32	-116.35.11.18	536480.6	4167289.0
Antelope Tuff 2	60.83224686	A01_079	No	EM-61	> 100	1.17	37.39.07.33	-116.35.09.48	536522.3	4167289.5
Antelope Tuff 2	443.7626953	A01_080	No	EM-61	> 100	0.26	37.39.07.35	-116.35.11.10	536482.6	4167289.8
Antelope Tuff 2	62.50689977	A01_081	No	EM-61	> 100	0.57	37.39.07.41	-116.35.09.21	536528.7	4167292.1
Antelope Tuff 2	104.2229993	A01_082	No	EM-61	> 100	0.32	37.39.07.45	-116.35.09.61	536519.0	4167293.2
Antelope Tuff 2	68.85398088	A01_083	No	EM-61	50-100	0.51	37.39.07.48	-116.35.09.63	536518.5	4167294.1
Antelope Tuff 2	97.22296142	A01_084	No	EM-61	0-50	0	37.39.07.92	-116.35.09.22	536528.4	4167307.6

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Antelope Tuff 2	134.4427947	A01_085	No	EM-61	50-100	0.24	37.39.08.92	-116.35.11.06	536483.2	4167338.4
Antelope Tuff 2	310.9881896	A01_086	No	EM-61	> 100	0.93	37.39.09.13	-116.35.09.32	536525.8	4167344.8
Antelope Tuff 2	190.700592	A01_087	No	EM-61	> 100	1.33	37.39.09.65	-116.35.09.66	536517.4	4167361.0
Antelope Tuff 2	106.4268875	A01_088	No	EM-61	0-50	0.01	37.39.09.68	-116.35.09.45	536522.6	4167362.0
Antelope Tuff 2	181.1043549	A01_089	No	EM-61	> 100	1.58	37.39.09.96	-116.35.09.86	536512.4	4167370.6
Antelope Tuff 2	105.4228592	A01_090	No	EM-61	50-100	0.14	37.39.10.38	-116.35.10.44	536498.2	4167383.4
Antelope Tuff 2	162.4817356	A01_091	No	EM-61	> 100	2.31	37.39.04.41	-116.35.09.59	536519.9	4167199.4
Antelope Tuff 2	60.13414439	A01_092	No	EM-61	0-50	0.15	37.39.05.39	-116.35.08.88	536537.2	4167229.7
Antelope Tuff 2	60.85325736	A01_093	No	EM-61	> 100	0.62	37.39.05.74	-116.35.09.08	536532.1	4167240.4
Antelope Tuff 2	72.2886757	A01_094	No	EM-61	> 100	0.83	37.39.05.72	-116.35.09.27	536527.4	4167240.0
Antelope Tuff 2	69.68934806	A01_095	No	EM-61	> 100	0.54	37.39.06.51	-116.35.09.85	536513.2	4167264.2
Antelope Tuff 2	60.7995608	A01_096	No	EM-61	> 100	0.88	37.39.07.19	-116.35.09.38	536524.6	4167285.1
Antelope Tuff 2	65.523328	A01_097	No	EM-61	0-50	0.04	37.39.10.61	-116.35.09.29	536526.4	4167390.4
Antelope Tuff 2	60.2765177	A01_098	No	EM-61	50-100	0.26	37.39.03.98	-116.35.09.31	536526.8	4167186.3
Sidewinder Tuff	2142.009661	PA01_001	No	EM-61	> 100	0.48	37.37.40.92	-116.35.41.18	535757.0	4164622.9
Sidewinder Tuff	482.4086376	PA01_002	No	EM-61	> 100	0.13	37.37.41.29	-116.35.44.21	535682.6	4164634.0
Sidewinder Tuff	167.8417674	PA01_003	No	EM-61	> 100	1.12	37.37.41.32	-116.35.40.35	535777.3	4164635.5
Sidewinder Tuff	295.3965253	PA01_004	No	EM-61	> 100	0.52	37.37.41.40	-116.35.41.78	535742.2	4164637.7
Sidewinder Tuff	1737.231366	PA01_005	No	EM-61	> 100	0.36	37.37.41.44	-116.35.42.93	535714.0	4164639.0
Sidewinder Tuff	177.3364929	PA01_006	No	EM-61	> 100	1.14	37.37.41.92	-116.35.43.47	535700.6	4164653.6
Sidewinder Tuff	49.05409447	PA01_007	No	EM-61	> 100	1.55	37.37.42.01	-116.35.43.26	535705.7	4164656.4
Sidewinder Tuff	278.2658863	PA01_008	No	EM-61	> 100	1.27	37.37.42.61	-116.35.42.96	535713.2	4164674.9
Sidewinder Tuff	63.91493976	PA01_009	No	EM-61	> 100	0.86	37.37.42.61	-116.35.43.35	535703.6	4164675.0
Sidewinder Tuff	326.8290311	PA01_010	No	EM-61	> 100	0.94	37.37.42.61	-116.35.43.14	535708.7	4164675.0
Sidewinder Tuff	62.45587961	PA01_011	No	EM-61	> 100	1.39	37.37.42.80	-116.35.42.75	535718.2	4164680.8
Sidewinder Tuff	303.2011075	PA01_012	No	EM-61	> 100	0.52	37.37.42.97	-116.35.43.51	535699.7	4164686.0
Sidewinder Tuff	263.1334897	PA01_013	No	EM-61	> 100	0.92	37.37.43.75	-116.35.42.26	535730.1	4164710.1
Sidewinder Tuff	83.32051176	PA01_014	No	EM-61	> 100	1.67	37.37.43.80	-116.35.43.99	535687.8	4164711.6
Sidewinder Tuff	23.18588631	PA01_015	No	EM-61	> 100	1.75	37.37.44.03	-116.35.44.14	535683.9	4164718.7
Sidewinder Tuff	152.4360554	PA01_016	No	EM-61	> 100	1.12	37.37.44.35	-116.35.44.10	535684.9	4164728.6
Sidewinder Tuff	223.4615211	PA01_017	No	EM-61	> 100	1.08	37.37.44.62	-116.35.44.38	535678.0	4164736.9
Sidewinder Tuff	218.7593061	PA01_018	No	EM-61	50-100	0.04	37.37.44.85	-116.35.47.03	535613.1	4164743.5
Sidewinder Tuff	56.55918271	PA01_019	No	EM-61	> 100	1.19	37.37.45.20	-116.35.43.65	535695.7	4164754.6
Sidewinder Tuff	74.77349048	PA01_020	No	EM-61	> 100	0.94	37.37.45.75	-116.35.40.73	535767.4	4164772.0
Sidewinder Tuff	331.012653	PA01_021	No	EM-61	> 100	0.79	37.37.47.08	-116.35.42.89	535714.1	4164812.6
Sidewinder Tuff	2061.711531	PA01_022	No	EM-61	> 100	0.43	37.37.48.31	-116.35.43.21	535706.3	4164850.5
Sidewinder Tuff	15.75574565	PA01_023	No	EM-61	> 100	2	37.37.49.34	-116.35.42.04	535734.7	4164882.4
Sidewinder Tuff	80.1528689	PA01_024	No	EM-61	> 100	1.33	37.37.49.82	-116.35.41.71	535742.8	4164897.4
Sidewinder Tuff	153.5677531	PA01_025	No	EM-61	> 100	1.09	37.37.49.97	-116.35.41.75	535741.8	4164902.0
Sidewinder Tuff	100.1458433	PA01_026	No	EM-61	> 100	1.23	37.37.50.09	-116.35.44.54	535673.5	4164905.4

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Sidewinder Tuff	22.04937809	PA01_027	No	EM-61	> 100	1.82	37.37.50.17	-116.35.42.18	535731.3	4164908.0
Sidewinder Tuff	160.4654268	PA01_028	No	EM-61	> 100	1.09	37.37.50.19	-116.35.41.81	535740.2	4164908.6
Sidewinder Tuff	1459.970766	PA01_029	No	EM-61	> 100	0.53	37.37.50.37	-116.35.44.29	535679.5	4164913.9
Sidewinder Tuff	409.557854	PA01_030	No	EM-61	> 100	0.88	37.37.50.50	-116.35.43.56	535697.3	4164918.0
Sidewinder Tuff	108.2351078	PA01_031	No	EM-61	> 100	1.27	37.37.50.91	-116.35.41.92	535737.6	4164930.9
Sidewinder Tuff	51.57902887	PA01_032	No	EM-61	> 100	0.58	37.37.51.57	-116.35.43.73	535693.1	4164950.9
Sidewinder Tuff	82.61358149	PA01_033	No	EM-61	> 100	1.35	37.37.51.68	-116.35.42.01	535735.1	4164954.6
Myers Ridge	226.3008881	A05_001	No	EM-61	> 100	1.09	37.37.37.94	-116.35.34.66	535917.2	4164532.0
Myers Ridge	78.98525237	A05_002	No	EM-61	> 100	1.6	37.37.38.79	-116.35.26.93	536106.6	4164558.8
Myers Ridge	328.6183775	A05_003	No	EM-61	50-100	0.01	37.37.38.90	-116.35.26.84	536108.8	4164562.2
Myers Ridge	108.4505694	A05_004	No	EM-61	0-50	0	37.37.38.92	-116.35.26.79	536109.9	4164563.1
Myers Ridge	198.8853301	A05_005	No	EM-61	> 100	0.32	37.37.38.93	-116.35.26.84	536108.6	4164563.4
Myers Ridge	104.6245269	A05_006	No	EM-61	50-100	0.19	37.37.39.13	-116.35.35.97	535885.0	4164568.4
Myers Ridge	115.6922759	A05_007	No	EM-61	0-50	0.16	37.37.39.18	-116.35.25.89	536132.0	4164571.2
Myers Ridge	780.3331298	A05_008	No	EM-61	0-50	0.31	37.37.40.05	-116.35.27.32	536096.8	4164597.6
Myers Ridge	425.8085022	A05_009	No	EM-61	> 100	0.25	37.37.40.08	-116.35.27.30	536097.2	4164598.6
Myers Ridge	355.7914155	A05_010	No	EM-61	> 100	2.02	37.37.40.23	-116.35.28.42	536069.8	4164603.1
Myers Ridge	628.6760857	A05_011	No	EM-61	50-100	0.35	37.37.40.26	-116.35.28.42	536069.8	4164604.2
Myers Ridge	2484.757077	A05_012	No	EM-61	> 100	0	37.37.40.35	-116.35.28.00	536080.0	4164606.8
Myers Ridge	520.4999995	A05_013	No	EM-61	> 100	0.09	37.37.40.65	-116.35.28.29	536073.0	4164616.2
Myers Ridge	81.58089995	A05_014	No	EM-61	> 100	1.5	37.37.40.68	-116.35.28.20	536075.0	4164616.9
Myers Ridge	65.31063818	A05_015	No	EM-61	50-100	0.46	37.37.40.85	-116.35.27.44	536093.7	4164622.5
Myers Ridge	148.1898193	A05_016	No	EM-61	> 100	0.53	37.37.40.94	-116.35.27.28	536097.6	4164625.0
Myers Ridge	668.0728759	A05_017	No	EM-61	> 100	0.1	37.37.41.26	-116.35.28.16	536076.0	4164634.8
Myers Ridge	141.5563201	A05_018	No	EM-61	50-100	0.15	37.37.41.27	-116.35.27.44	536093.6	4164635.4
Myers Ridge	620.1985474	A05_019	No	EM-61	> 100	0.58	37.37.41.28	-116.35.28.17	536075.8	4164635.6
Myers Ridge	110.620346	A05_020	No	EM-61	> 100	1.22	37.37.41.28	-116.35.26.53	536116.0	4164635.8
Myers Ridge	97.01586089	A05_021	No	EM-61	> 100	0.95	37.37.41.32	-116.35.26.54	536115.8	4164636.8
Myers Ridge	479.3511352	A05_022	No	EM-61	> 100	0.65	37.37.41.40	-116.35.27.07	536102.8	4164639.2
Myers Ridge	306.7777403	A05_023	No	EM-61	50-100	0.01	37.37.41.40	-116.35.27.32	536096.6	4164639.2
Myers Ridge	98.75270073	A05_024	No	EM-61	> 100	0.31	37.37.41.43	-116.35.26.68	536112.2	4164640.4
Myers Ridge	75.98223866	A05_025	No	EM-61	0-50	0.03	37.37.41.47	-116.35.26.66	536112.8	4164641.4
Myers Ridge	87.23274224	A05_026	No	EM-61	50-100	0.47	37.37.41.63	-116.35.27.93	536081.6	4164646.4
Myers Ridge	179.3125	A05_027	No	EM-61	> 100	0.19	37.37.41.65	-116.35.26.57	536115.0	4164647.0
Myers Ridge	83.02833557	A05_028	No	EM-61	> 100	1.13	37.37.41.67	-116.35.27.87	536083.0	4164647.6
Myers Ridge	143.1387786	A05_029	No	EM-61	50-100	0.6	37.37.41.70	-116.35.27.82	536084.4	4164648.4
Myers Ridge	1782.151855	A05_030	No	EM-61	> 100	0.06	37.37.41.71	-116.35.28.15	536076.2	4164648.8
Myers Ridge	1678.088135	A05_031	No	EM-61	50-100	0.01	37.37.41.72	-116.35.28.13	536076.6	4164649.0
Myers Ridge	85.6550064	A05_032	No	EM-61	> 100	1.81	37.37.41.73	-116.35.27.26	536098.0	4164649.6
Myers Ridge	2325.41748	A05_033	No	EM-61	> 100	0.28	37.37.41.74	-116.35.28.17	536075.8	4164649.6

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Myers Ridge	365.12323	A05_034	No	EM-61	> 100	0.19	37.37.41.74	-116.35.26.98	536105.0	4164649.8
Myers Ridge	62.48053689	A05_035	No	EM-61	0-50	0.14	37.37.41.74	-116.35.27.22	536099.1	4164649.9
Myers Ridge	249.8890381	A05_036	No	EM-61	> 100	1.03	37.37.41.75	-116.35.28.48	536068.0	4164650.0
Myers Ridge	190.1287535	A05_037	No	EM-61	> 100	0.24	37.37.41.76	-116.35.27.02	536103.8	4164650.4
Myers Ridge	96.74719238	A05_038	No	EM-61	> 100	1.63	37.37.41.77	-116.35.27.19	536099.8	4164650.6
Myers Ridge	498.9313753	A05_039	No	EM-61	> 100	0.87	37.37.41.79	-116.35.26.82	536108.7	4164651.5
Myers Ridge	52.37002699	A05_040	No	EM-61	> 100	1.6	37.37.41.80	-116.35.26.67	536112.6	4164651.6
Myers Ridge	9239.061523	A05_041	No	EM-61	> 100	0.2	37.37.41.80	-116.35.26.87	536107.6	4164651.6
Myers Ridge	98.21019744	A05_042	No	EM-61	> 100	1.71	37.37.41.80	-116.35.26.94	536105.8	4164651.8
Myers Ridge	491.4782101	A05_043	No	EM-61	> 100	1.15	37.37.41.80	-116.35.27.19	536099.8	4164651.8
Myers Ridge	136.5344848	A05_044	No	EM-61	> 100	1.3	37.37.41.84	-116.35.27.50	536092.2	4164652.8
Myers Ridge	1545.651489	A05_045	No	EM-61	> 100	0.59	37.37.41.84	-116.35.27.44	536093.6	4164652.8
Myers Ridge	695.2117531	A05_046	No	EM-61	> 100	0.81	37.37.41.85	-116.35.27.39	536094.7	4164653.2
Myers Ridge	82.91851043	A05_047	No	EM-61	> 100	0.87	37.37.41.86	-116.35.26.85	536108.0	4164653.4
Myers Ridge	113.3329238	A05_048	No	EM-61	> 100	1.27	37.37.41.87	-116.35.26.89	536107.0	4164653.8
Myers Ridge	66.77781088	A05_049	No	EM-61	> 100	0.29	37.37.41.90	-116.35.26.64	536113.2	4164654.8
Myers Ridge	134.4795989	A05_050	No	EM-61	> 100	1.41	37.37.41.92	-116.35.27.39	536094.8	4164655.4
Myers Ridge	101.7871856	A05_051	No	EM-61	> 100	0.24	37.37.41.95	-116.35.27.37	536095.4	4164656.4
Myers Ridge	298.8825377	A05_052	No	EM-61	0-50	0	37.37.41.99	-116.35.28.02	536079.4	4164657.4
Myers Ridge	166.6021118	A05_053	No	EM-61	> 100	1.19	37.37.42.06	-116.35.27.17	536100.2	4164659.6
Myers Ridge	121.4144745	A05_054	No	EM-61	0-50	0	37.37.42.07	-116.35.27.38	536095.0	4164660.0
Myers Ridge	406.5817869	A05_055	No	EM-61	> 100	0.06	37.37.42.12	-116.35.28.11	536077.2	4164661.4
Myers Ridge	173.2503662	A05_056	No	EM-61	> 100	0.36	37.37.42.14	-116.35.28.14	536076.4	4164662.0
Myers Ridge	248.4951629	A05_057	No	EM-61	> 100	0.35	37.37.42.18	-116.35.26.78	536109.8	4164663.4
Myers Ridge	119.1429672	A05_058	No	EM-61	50-100	0.47	37.37.42.27	-116.35.27.16	536100.4	4164666.2
Myers Ridge	91.34688261	A05_059	No	EM-61	> 100	1.15	37.37.42.31	-116.35.27.08	536102.3	4164667.3
Myers Ridge	102.902008	A05_060	No	EM-61	> 100	1.32	37.37.42.33	-116.35.26.86	536107.8	4164668.0
Myers Ridge	442.4726562	A05_061	No	EM-61	> 100	0.29	37.37.42.35	-116.35.26.89	536107.0	4164668.6
Myers Ridge	179.2449797	A05_062	No	EM-61	> 100	2.02	37.37.42.42	-116.35.27.74	536086.2	4164670.8
Myers Ridge	272.6409302	A05_063	No	EM-61	> 100	1.22	37.37.42.45	-116.35.27.75	536086.0	4164671.6
Myers Ridge	799.4726562	A05_064	No	EM-61	> 100	0.45	37.37.42.53	-116.35.27.89	536082.4	4164674.2
Myers Ridge	67.44606476	A05_065	No	EM-61	> 100	1.61	37.37.42.60	-116.35.28.32	536072.0	4164676.1
Myers Ridge	142.6687317	A05_066	No	EM-61	> 100	0.51	37.37.42.69	-116.35.27.53	536091.4	4164679.0
Myers Ridge	102.9672622	A05_067	No	EM-61	> 100	0.4	37.37.42.70	-116.35.27.92	536081.6	4164679.2
Myers Ridge	210.4488067	A05_068	No	EM-61	> 100	0.79	37.37.42.83	-116.35.27.59	536089.8	4164683.4
Myers Ridge	340.517046	A05_069	No	EM-61	> 100	0.54	37.37.42.85	-116.35.27.63	536088.9	4164683.8
Myers Ridge	101.0521479	A05_070	No	EM-61	0-50	0.2	37.37.42.99	-116.35.27.65	536088.4	4164688.1
Myers Ridge	99.87306969	A05_071	No	EM-61	50-100	0.47	37.37.43.02	-116.35.27.66	536088.0	4164689.2
Myers Ridge	94.07456199	A05_072	No	EM-61	50-100	0.18	37.37.43.19	-116.35.27.56	536090.4	4164694.4
Myers Ridge	2144.721191	A05_073	No	EM-61	> 100	0.47	37.37.43.19	-116.35.27.63	536088.8	4164694.4

APPENDIX L. DAVIS GUN PENETRATOR ANOMALIES FROM GEOPHYSICAL RESULTS

Location	Grid Value	Target ID	Investigated	ID Method	Size playa (ft) Tuff (mm)	Depth (ft)	Lat	Long	X_utm (m)	Y_utm (m)
Myers Ridge	117.1304702	A05_074	No	EM-61	0-50	0.08	37.37.43.22	-116.35.27.57	536090.2	4164695.4
Myers Ridge	78.12903124	A05_075	No	EM-61	> 100	1.86	37.37.43.22	-116.35.27.61	536089.2	4164695.5
Myers Ridge	121.179012	A05_076	No	EM-61	0-50	0	37.37.43.36	-116.35.28.16	536075.8	4164699.6
Mt Helen	2042.377066	PH01_001	Conduit	EM-61	> 100	0.45	37.32.44.84	-116.42.53.02	525199.9	4155459.6
Mt Helen	1050.4943	PH01_002	Wire/debris	EM-61	> 100	0.41	37.32.43.74	-116.42.53.34	525192.1	4155425.6
Mt Helen	144.4894178	PH01_003	No	EM-61	> 100	1.37	37.32.43.13	-116.42.52.83	525204.7	4155406.7
Mt Helen	100.4507415	PH01_004	No	EM-61	> 100	1.21	37.32.43.24	-116.42.53.02	525200.1	4155410.2
Mt Helen	466.3815465	PH01_005	No	EM-61	0-50	0	37.32.43.22	-116.42.47.53	525334.7	4155410.1
Mt Helen	132.2183242	PH01_006	No	EM-61	> 100	0.2	37.32.41.69	-116.42.45.33	525388.9	4155363.1
Mt Helen	854.311415	PH01_007	No	EM-61	> 100	0.8	37.32.41.57	-116.42.45.18	525392.5	4155359.3
Mt Helen	1527.44875	PH01_008	No	EM-61	> 100	0.63	37.32.41.59	-116.42.50.91	525252.0	4155359.7

APPENDIX M

RADIOLOGICAL SURVEY REPORTS

APPENDIX M-1

Depleted Uranium Distribution Surveys at the Tonopah Test Range Corrective Action Unit 484

APPENDIX M-2

AMS Kiwi Final Results Tonopah Test Range – CAU 484

APPENDIX M-1

RADIOLOGICAL SURVEY REPORT

**Depleted Uranium Distribution Surveys
at the Tonopah Test Range
Corrective Action Unit 484**

Report

Depleted Uranium Distribution Surveys at the Tonopah Test Range Corrective Action Unit 484

**Craig Lyons
Thane Hendricks
Remote Sensing Laboratory-Nellis
Las Vegas, Nevada**

**Revision 4
August 2007**

DEPLETED URANIUM DISTRIBUTION SURVEYS AT THE TONOPAH TEST RANGE CORRECTIVE ACTION UNIT 484

ACRONYMS, ABBREVIATIONS, AND SYMBOLS

ADC	analog-to-digital converter
agl	above ground level
Am	americium
CAS	Corrective Action Site
CAU	Corrective Action Unit
cm	centimeter(s)
cm ³	cubic centimeter(s)
cps	counts per second
DU	depleted uranium
ER	Environmental Restoration
FWHM	full width at half maximum
ft	foot (feet)
GC	gross count
GPS	Global Positioning System
keV	kiloelectronvolt
m	meter(s)
MDA	minimum detectable activity
mph	mile(s) per hour
NaI	sodium iodide
pCi/g	picocurie(s) per gram
RCT	Radiological Control Technician

RDGPS	Real-Time Differential Global Positioning System
REDAR	Radiation and Environmental Data Acquisition and Recorder
REDAR V	Radiation and Environmental Data Acquisition and Recorder, Version V
RSL-N	Remote Sensing Laboratory-Nellis
SAP	self-attenuation parameter
SCA	Soil Contamination Area
TTR	Tonopah Test Range
U	Uranium
UXO	unexploded ordnance
μCi	microcurie(s)
μCi/m ²	microcurie(s) per square meter

INTRODUCTION

Radiological surveys were conducted on Antelope Lake, Brownes Lake, Pedro Lake, and NEDS Lake to map the surface and shallow subsurface distribution of radioactive debris to support the establishment of Data Quality Objectives for the characterization and cleanup of Corrective Action Unit (CAU) 484 and CAU 496. CAU 484 consists of surface debris, waste sites and a burn area and is comprised of 6 Corrective Action Sites (CASs). CAU 496 is comprised of one CAS for buried ordnance and is located on Antelope Lake. The purpose of these initial radiological surveys was to obtain preliminary information from which the scope and scale of the characterization program was established.

The objective of the radiological survey program was to map areas with elevated gamma activity due to depleted uranium (DU) or other radionuclides in conjunction with geophysical surveys to determine the areal extent of metallic debris. Targets located from these surveys were examined in further detail under a follow-up characterization program. The final goal of the program was to locate, characterize, and remediate known and unknown waste sites as identified in the CAUs. The Kiwi survey work scope was limited to non-intrusive, non-contact surveys.

After completion of characterization surveys, Remote Sensing Laboratory – Nellis (RSL-N) was requested to provide additional assistance in marking the suspected DU point sources for the Radiological Control Technicians (RCTs) and clean-up personnel. As the remediation work progressed, the Kiwi was used periodically to confirm the success of the clean-up and became the final verification asset for the project.

OPERATIONS HISTORY

Numerous tests were conducted at the Tonopah Test Range (TTR) in the 1980's related to weapon ballistics and penetration capabilities. A number of these tests involved the use of DU as part of the surrogate projectile configuration. After a test, TTR personnel attempted to retrieve all of the metal debris associated with a specific test. The success of these clean-up operations and the instruments used for the work are not known. However, a number of the dry lake bed areas have historical "Soil Contamination" area postings at the access roads or around bermed areas on the lake to inform TTR personnel of possible residual DU material left after testing.

The TTR lakes identified under CAU 484 include Antelope Lake, Pedro Lake, Brownes Lake, and NEDS Lake.

The scope of work for the CAU 484 characterization included:

- An unexploded ordnance (UXO) and radiological screening of debris that was performed ahead of the Kiwi vehicle on each lake bed.
- A Kiwi radiological survey of each lake bed with a planned line separation of approximately 10 feet and vehicle speed less than 10 miles per hour (mph). The line spacing was expected to provide greater than 95% coverage of the study areas.
- An EM-61 MK2 geophysical survey consisting of an array of three cart-mounted metal detectors towed behind the Kiwi vehicle. The array had an operator in the kiwi vehicle in addition to the two RSL-N personnel supporting the Kiwi surveys.
- RCTs supported the surveys by providing radiological surveys of the equipment and vehicles as they exited from any lake bed. In addition, breathing zone air sampling was conducted on both the interior and exterior of the Kiwi vehicle during surveys.

ENVIRONMENTAL SETTING

Antelope Lake, Pedro Lake, Brownes Lake, and Mt. Mellan are located in the south-central portion of TTR, approximately 14 miles directly south-southeast of Main Gate. Main Lake is located in the northern portion of TTR, approximately 3 miles southeast of Main Gate.

Most of TTR, including the CAU locations, is located in Cactus Flat. Cactus Flat is an intermontane basin, typical of the Basin and Range Physiographic Province, surrounded by the Cactus Range to the southwest, the northern portion of the Kawich Range to the east, and the Monitor Range to the north. Antelope Lake appears to be smooth; however, its clay surface is broken in places by desiccation cracks (mud cracks) caused by drying. The alluvium can be divided into local landslide and talus, fan alluvium, valley-fill alluvium, and lake and shoreline deposits; each division differs in grain size, locality, and/or degree of compaction and cementation. The depth of the alluvium is unknown, but exploratory drilling discovered the thickness to exceed 1,000 feet (ft).

The alluvium layer is underlain by related tuffs and lavas of the Thirsty Canyon Tuff unit, which can be as deep as 500 ft below ground surface. Beneath the Thirsty Canyon Tuff unit lies the rhyolitic tuffs of the timber Mountain Tuff unit and the rhyolitic ash-fall and lavas of the Paintbrush Tuff unit. The Paintbrush Tuff unit is underlain by various layers of Miocene-aged volcanic lavas and tuffs and various-aged limestone and dolomite layers.

SURVEY OBJECTIVES

The radiological survey consisted of ground-based measurements using the RSL-N specially modified Ford F-350 pickup truck (Kiwi), which is equipped with the Radiation and Environmental Data Acquisition and Recorder system, Version V (REDAR V). It will collect the radiation data within a speed range of 5 to 10 mph (nominal 10 feet/sec), at 28 inches above ground level (agl), and with an approximate line spacing of 10 feet. A metal detector survey was conducted at the same time as the radiometric survey to minimize positioning errors and to maintain a complimentary data set. The metal detector system consisted of three Geonics EM-61 MK2 high-power time-domain metal detectors. The detector coils were operated as a time-synchronized array and will record four time gates of data per coil. The array was towed behind the KIWI system with a coverage width of approximately 3 meters (m). Global Positioning System (GPS) data were collected and integrated with both the radiometric and metal detector systems to produce a contour map of distributions of radionuclides and metallic debris.

Position information is provided by a Real-Time Differential Global Positioning System (RDGPS). Latitude and longitude coordinates are recorded second-by-second for post-flight analysis. Ideally, the vehicle operator is guided along the desired survey paths in real time by meter/lightbar indicators, which provide visual indications of vehicle deviation from the desired survey path. The RDGPS nominal accuracy is better than 1 m for both recorded and steering information. Under some circumstances, where straight-line navigation is impossible (washes, rocks, bushes, and other obstacles), the vehicle operator may need to visually follow the vehicle path utilizing previous tire tracks to guarantee full areal coverage of the area of interest. The actual recorded path, not the planned path, is used for final data analysis.

Some of the survey sites were posted radioactive soil contamination areas that require a radiological work permit for entry.

The UXO initial assessments were performed by Sandia EOD technicians to screen for potential UXO on the lakebeds designated for radiological and geophysical surveys. The survey area consists of approximately 1,440 acres of flat open playa and adjacent areas with sparse vegetation. The project provided additional UXO and RCT personnel to screen debris ahead of the survey vehicle and a geophysical cart for each lake.

SYSTEM DESCRIPTION

The Kiwi system uses detectors and a data collection system developed for RSL-N's helicopter mission, mounted on a Ford F-250 crew-cab pickup truck (Figure 1). Eight 4 x 4 x 16-inch sodium iodide (NaI) detector logs are housed in four pods mounted on an angle-iron frame attached to the rear of the vehicle. The detector frame is adjustable, allowing the bottom of the detector pods to be placed from 8 to 20 inches above the ground. Signals from the detectors feed into a REDAR V data-recording system mounted inside the rear of the truck cab. In addition to the REDAR V system, a second electronic rack cabinet houses power supplies and other support electronic equipment.

Figure 1. Kiwi Detection System

In addition to seating two people, the front half of the cab houses the GPS steering indicator, which is used by the vehicle driver to maintain proper survey line spacing, and the keyboard and display system, which is used by the electronic technician to operate and monitor the REDAR system. The Trimble AgGPS™ positioning/steering system was recently installed in the Kiwi. This system allows the driver and technician to create survey areas in real time. This was invaluable for the verification surveys.

For the Kiwi system, the eight detectors are routed to four analog-to-digital converters (ADCs). The signals from two detectors are routed to each ADC.

Starting on the driver's side looking forward:

- Detectors 1 and 2, in the left pod, are routed to ADC0.

- Detectors 3 and 4 are routed to ADC1.
- Detectors 5 and 6 are routed to ADC2.
- Detectors 7 and 8, in the right pod, are routed to ADC3.

Based on earlier data and discussions, it was expected that the majority of the DU contamination would consist of discrete point sources. The arrangement of two detectors per ADC would allow identification of the point source under a specific detector pod, real-time or during post-survey data analysis.

The Kiwi detectors produce voltage pulses which are proportional to the energy of the incident gamma rays. These voltage pulses are processed by the REDAR V. Four complete gamma-ray energy spectra are recorded during each second of operation. The spectral energy range spans from 0 to 4,000 kiloelectronvolts (keV). Each full gamma spectrum permits the identification of other gamma-emitting radioisotopes present in the environment, in addition to the target contaminants. This allows a more accurate determination of the amounts of anthropogenic radioisotopes that are present in comparison with background levels, even if background levels change spatially over the survey area.

The Kiwi vehicle was expected to map dispersed DU contamination by measuring the 1,000-keV gamma ray emitted by the Protactinium-234m daughter. To produce a well-defined footprint, a cadmium sheet shields the Kiwi detectors on the back, top, and sides, while the end-mounted photomultiplier tubes and the vehicle chassis provide shielding to the front of the detectors. This shielding is more than adequate for attenuating low-energy gamma rays, but does not significantly affect the higher-energy radiation from the natural radioisotopes. Cadmium is used instead of lead because, when lead is stimulated by high-energy gamma rays, it emits x-rays in the 70-95 keV energy range. These x-rays would interfere with the low-energy gamma-ray photopeaks in post-survey data analysis.

With the chosen detector height 28 inches agl for TTR and the cadmium shielding, the DU footprint of the stationary Kiwi system is about 2.1 m wide and 0.8 m long. With the Kiwi traveling at 1.8 meters per second (4 mph), the footprint for each 1-second measurement is about 2.1 m wide by 2.0 m long. The speed of the Kiwi over the lake beds was generally constant, except for turns and obstacles.

Unlike the helicopter system, the Kiwi travels along the surface of the ground and must make allowances for obstacles in its path. On level, hard-packed ground the Kiwi could travel at speeds up to 10 mph.

PRE-DEPLOYMENT SPATIAL, SENSITIVITY, AND DETECTABILITY TESTS

Pull-By Test Procedures

Source pull-by measurements were conducted in the RSL-N hangar for the purpose of characterizing the spatial, sensitivity, and detectability properties of the detectors at various heights agl. Unobstructed pull-by ranges of about 30 ft (15 ft left, right, forward, and aft of the detector rack centerline) were set up in the hangar area. A clock-motor/pull-string device was used to pull the sled carrying two 9.5-microcurie (μCi) Americium (Am)-241 sources directly underneath the detector rack. Pull-by speed was set to be approximately 2 ft per minute (i.e., 15 minutes for each 30-ft pull). Reference marks were placed on the along- and cross-track paths at 0; ± 5 ft; ± 10 ft; and ± 15 ft, to allow conversion of measurement time to distance from the detector rack centerline.

Using the two Am sources placed closely together on the pull-by sled, pull-bys were done for along-track and cross-track centerlines for the lowest detector rack placement (8 inches agl), near-mid-rack placement (14 inches agl), and highest rack placement (20 inches agl). Based on the results of these pull-bys, the 14-inch detector height was chosen for the survey.

Gross Count Parameters for the Chosen Survey Configuration

Data acquired in the pull-by were analyzed to produce Figures 2 and 3, which show the gross count (GC) spatial patterns associated with the chosen 14-inch agl detector height. GC activity is defined as the sum of the count rate data within the spectral window extending from 38 keV to 3,026 keV. From these pull-by data, the nominal point source GC sensitivity of the system (measured with the source at the center of the detector array) was determined to be:

$$\text{GC sensitivity} = 484 \text{ counts per second (cps) per } \mu\text{Ci of Am-241}.$$

The minimum detectable activity (MDA) is defined as three times the standard deviation of the background activity. For the parameters measured in the hangar pull-by, the nominal point source MDA (for hangar background) was determined to be:

$$\text{GC MDA} = 0.78 \mu\text{Ci of Am-241}.$$

Figure 2. Cross-Track Source Pull-By at 14 Inches AGL, Gross Count

Figure 3. Along-Track Source Pull-By at 14 Inches AGL, Gross Count

Algorithm Parameters for the Chosen Survey Configuration

In any real survey situation, the variability of the background is far greater than the counting statistics exhibited by the constant background in the hangar. For this reason, a 3-window algorithm, which targets the specific isotope photopeak and tracks background in a second-by-second manner, was used. Three windows were chosen to optimize the Am data extraction:

1. A central window, which brackets the photopeak of interest
(A = 50 to 70 keV for the 60-keV Am photopeak)
2. Background windows on each side of the photopeak window
(B1 = 38 to 50 keV)
(B2 = 70 to 82 keV)

The ratio, K, of the photopeak window counts to the sum of the counts from the two background windows, is very nearly constant in natural background areas.

$$K = A / (B1 + B2) \text{ determined from background areas}$$

Using the background K (evaluated for each flight), the second-by-second net Am count for a flight is:

$$\text{Am net} = A - K (B1 + B2)$$

Figures 4 and 5 show the Am net results for the pull-by tests. From these pull-by data, the nominal Am point source sensitivity was determined to be:

$$\text{Am net sensitivity} = 316 \text{ cps}/\mu\text{Ci}$$

And the nominal MDA (for hangar background) was determined to be:

$$\text{Am MDA} = 0.214 \mu\text{Ci}$$

Sensitivity is relatively fixed for a given system configuration. However, the MDA is a function of the background properties of the survey area and was therefore evaluated under actual field conditions. This will be discussed in further detail when field measurements are discussed in the Data Analysis section.

Figure 4. Cross-Track Source Pull-By at 14 Inches AGL, 3-Window Net

Figure 5. Along-Track Source Pull-By at 14 Inches AGL, Americium 3-Window Net

Spatial Parameters from the Pull-By Data

The nominal cross-track full width at half maximum (FWHM) was measured to be:

$$\text{CROSS-TRACK FWHM} = 7.0 \text{ ft (2.1 m)}$$

The along-track FWHM (no forward speed) was:

$$\text{ALONG-TRACK FWHM} = 2.7 \text{ ft (0.8 m)}$$

The actual along-track FWHM is a function of speed, and is the quadrature sum of the stationary FWHM and the speed $[(\text{FWHM})^2 = (\text{FWHM})^2 + v^2]$, where v is the target speed or velocity, at the target speed of 6 ft per second:

$$\text{ALONG-TRACK FWHM} = 6.6 \text{ ft (2.0 m)}$$

Characteristics of Uranium-238 Decay Chain

As summarized in the following table, the Kiwi radiological surveys conducted at CAU 484 are actually detecting the gamma rays emitted from the daughter products of the parent DU decay. The two daughter radionuclides are Thorium-234 and Protactinium-234m. Both have very short half-lives compared to Uranium (U)-238, but they are in secular equilibrium (equivalent disintegrations per minute) with the parent. The two daughter products quickly achieve equilibrium with the U-238 parent after the manufacturing process has been completed. The fourth radionuclide in the decay chain, U-234, has a very long half-life and no significant gammas are produced. Due to the long half-life of U-234, no other daughters from the decay of the originally deposited DU will contribute to the gamma spectrum at the TTR for another 10,000 years.

Table 1. Depleted Uranium Gamma-Ray Energies of Interest

Radionuclide	Gamma Energy (keV)	Yield (%)
U-238	No Gamma Emitted	
Thorium-234	63.3	3.8
	92.6	5.4
Protactinium-234m	1,001	0.6
	767	0.3
U-234	No Gamma Emitted	

As discussed previously, the man-made count algorithm used on board the Kiwi for reacquiring DU targets and for evaluation of clean-up efforts included a broad region of interest from 30 keV to 1,400 keV. This allowed for the inclusion of the four gamma ray energies included in Table 1. This algorithm was effective due to the relatively stable background GCs on each lake bed. The characterization survey data did not indicate the presence of any other man-made radionuclides during the extensive post-flight analysis that was conducted. Therefore, any increase of count rates displaying this man-made algorithm can be attributed to the deposited DU, rather than background concentrations.

DATA COLLECTION

Collection Method

RSL-N and National Security Technologies Environmental Restoration (ER) personnel conducted a site walk-down upon arrival at each lake bed and established a suitable deployment location for entry and exit. The walk-down included driving the primary access roads to the lake bed as well as driving along the lake bed periphery. On the larger lake bed areas, additional walk-down drives were conducted periodically as the surveys advanced. ER personnel established a support zone location for each survey day, where personnel could exit vehicles for water and lunch breaks. RCTs would conduct radiological surveys as needed.

The basic survey strategy included section-by-section Kiwi surveys of the lake bed. The data from each section were processed and overlaid on the lake bed image. Any potential DU target locations were also identified after post-processing of each Kiwi drive path (aka, “flight”). RSL-N personnel also responded to ER special requests to re-survey suspect areas. RSL-N personnel also conducted static measurements using the Kiwi to assist RCT and ER personnel in locating previously identified low-activity targets.

The Kiwi surveys continued within the lake beds with the emphasis on conducting large area surveys to cover as much area as possible per drive path. The surveys were designed to maximize the amount of time driven for each survey line. Most of the survey lines were oriented in a west-east direction to optimize distance, but still provide reasonable visual coverage from the support area on the periphery of the lake bed.

A summary of the drive lines for each lake bed survey are available as GIS images. The images for the CAU 484 report include Brownes Lake, NEDS Lake, Pedro Lake, north Antelope Lake, and the Soil Contamination Area (SCA) within north Antelope Lake. The drive lines represent the cumulative one-second data points collected along the drive path. Each image can be used to document the total coverage of the Kiwi over the land surface. Locations of obstacles or hazards that were avoided during the surveys can be determined from the images and the GPS data from the Kiwi, if necessary. Due to the large size of the images (normally 22 x 34 inches) necessary to evaluate the data and underlying geographical features, none of the drive line image maps are included within this report. They are available with the imagery DVD provided with the CAU 484 report.

DATA ANALYSIS

Preflight

Prior to each “flight” (set of field measurements), the system calibration was checked at a fixed location near the field operations trailer. A standardized preflight procedure was executed and data were recorded. A preflight analysis sequence, tailored for the CAU 484 surveys, was executed to validate performance of every component of the system. This preflight sequence provides detailed checks and pass/fail information for GPS, gamma spectral, and other critical parameters.

Post-flight

At the conclusion of each “flight,” a tailored post-flight analysis sequence was executed. Several functions are performed by the post-flight. As with the preflight sequence, system performance parameters are validated. Mission performance is also evaluated, and desired data extractions (GC, DU net count, MDA, etc.) are performed in preparation for data-mapping operations.

The post-flight initially computes the DU net with the 3-window algorithm described in the pull-by test section. However, it also conditions the data based on the instantaneous MDA. As noted, the field MDA is not the same as in the laboratory and, in fact, varies a great deal because of the variability of the background at the site. If an MDA appropriate for low-background areas is used, a large number of false positives will occur in high-background areas. Conversely, if an MDA appropriate for high-background areas is used, true positives would be ignored in low-background areas.

In the post-flight computation, the DU net is deemed true positive only when it exceeds the instantaneously calculated MDA. If the DU net does not exceed the MDA, its value is set to zero. Figure 6 shows the unconditioned DU net along with the second-by-second MDA values.

Figure 6. Three-Window Spectrum Net, Typical Field Data

Figure 7. Three-Window Net, Typical Field Data, MDA Acceptance

MAPPING CRITERIA

The Kiwi system was originally designed to produce contour maps of distributed radioactivity. Depending on the source term and site conditions, the contours could consist of gross gamma data or of the man-made constituents. The gross gamma and man-made mapping results are different. Gross gamma includes all contributors, natural as well as man-made. The spectral energies displayed range from 30 keV to 3,000 keV. The overall activity and variability of the natural contributors masks low-level contributions from the man-made material-of-interest. In contrast, the man-made process achieves improved detectability by selectively extracting only the unique spectrum of the material-of-interest, while suppressing the natural background spectrum.

For CAU 484, the man-made extraction was markedly superior to gross gamma extraction for the survey-of-interest. The man-made region of interest is adjustable, depending on the nuclide of interest. For CAU 484, the most effective man-made count display included the energy region from 30 keV to 1,400 keV. This produced a count rate display for each ADC at approximately 5,000 cps during surveys. Additional counts produced by the DU daughters were discernable on the display inside the Kiwi at about 5,500 cps, or an additional 10% of the base count rate. Also, the data produced a number of discreet DU targets consisting of one or two seconds of data. The initial data set did not produce any areas of distributed DU activity that allowed for contour mapping. For this reason, gross gamma contours have not been produced for the surveyed area.

SURVEY RESULTS

To provide for a simpler data presentation regarding the DU material discovered on the lake beds, a letter ranking system was developed for presenting the characterization survey results on maps. The DU target ranking was based on the spectral quality of each net spectrum analyzed at an elevated GC or man-made count location. The presence of the primary DU and daughter peaks is considered.

- Ranking A: All three photo peaks at 93 keV, 767 keV, and 1,001 keV are present. This ranking represents the most significant DU target in activity.
- Ranking B: Only the two photo peaks at 93 keV and 1,001 keV are present.
- Ranking C: There are elevated net spectral counts from 40 keV to 1,100 keV, but the key DU photo peaks are not well defined.
- Ranking D: The total man-made count level is greater than 3 sigmas. There is no spectral consideration.

Brownes Lake was surveyed from December 3 to 4, 2003. Post-survey analysis showed four possible DU locations falling within the D ranking (Table 2).

Table 2. Brownes Lake Possible DU Locations and Rankings

ID	Ranking	Latitude	Longitude
BRO_001	D	37.709956	-116.684681
BRO_002	D	37.710123	-116.682592
BRO_003	D	37.709874	-116.680565
BRO_004	D	37.708964	-116.682284

The north half of Antelope Lake, excluding the SCA, was initially surveyed April 27 through June 2, 2004. Table 3 presents the survey results with possible DU locations (targets) and their associated rankings.

**Table 3. North Antelope Lake (Excluding SCA)
Possible DU Locations and Rankings**

Location	Ranking	Latitude	Longitude
NA_001	B2	37.7008771	-116.677017
NA_002	A2	37.6983515	-116.6755531
NA_003	A3	37.6973936	-116.6791458
NA_004	C3	37.6939282	-116.6858395
NA_005	D3	37.6925855	-116.6813119
NA_006	C1	37.6922562	-116.6852371
NA_007	D1	37.6922786	-116.6795676
NA_008	D4	37.6911284	-116.684972
NA_009	D6	37.6911015	-116.6847009
NA_010	D8	37.6911022	-116.679037
NA_011	D7	37.6910769	-116.6836755
NA_012	D2	37.6910184	-116.6771268
NA_013	C2	37.6883612	-116.6749809
NA_013a	A1	37.6883293	-116.6750572
NA_013b	B1	37.6883006	-116.6749628
NA_014	D5	37.6873936	-116.6831286

The SCA on Antelope Lake was surveyed from December 5 through 11, 2003. Table 4 presents a list of the survey result targets and associated rankings.

Table 4. Antelope Lake SCA Possible DU Locations and Rankings

ID	Ranking	Latitude	Longitude
SCA_001	D	37.703078	-116.681096
SCA_002	D	37.702776	-116.684737
SCA_003	D	37.702557	-116.682561
SCA_004	D	37.702202	-116.682783
SCA_005	D	37.70223	-116.682653
SCA_006	D	37.70223	-116.681788
SCA_007	D	37.701897	-116.681072
SCA_008	D	37.701735	-116.683416
SCA_009	D	37.70162	-116.681601
SCA_010	D	37.700776	-116.68368
SCA_011	D	37.700691	-116.682647
SCA_012	D	37.700662	-116.685753
SCA_013	D	37.700585	-116.684496
SCA_014	D	37.700637	-116.682969
SCA_015	D	37.700332	-116.684556
SCA_016	D	37.700279	-116.685848
SCA_017	D	37.70025	-116.683972
SCA_018	D	37.700324	-116.680753
SCA_019	D	37.700113	-116.681376
SCA_020	D	37.699505	-116.682163
SCA_021	D	37.699391	-116.683545
SCA_022	D	37.699037	-116.682731
SCA_023	D	37.699005	-116.681694
SCA_024	D	37.698354	-116.685639
SCA_025	D	37.698299	-116.68468
SCA_026	D	37.697635	-116.685401
SCA_027	D	37.697526	-116.684792
SCA_028	D	37.697527	-116.684193
SCA_029	D	37.697339	-116.6833
SCA_030	D	37.696401	-116.685277
SCA_031	D	37.696293	-116.684501
SCA_032	D	37.695624	-116.68099
SCA_033	A	37.695471	-116.683495
SCA_034	D	37.694843	-116.682965
SCA_035	D	37.694479	-116.683473

Pedro Lake was surveyed from June 21 through 25, 2004. The initial results showed no rankable target locations.

NEDS Lake was surveyed on June 28 through 29, 2004. Table 5 presents a list of the survey result targets and associated rankings.

Table 5. NEDS Lake Possible DU Locations and Rankings

ID	Ranking	Latitude	Longitude
NEDS_001	A1	37.758638	-116.695795
NEDS_002	A2	37.758367	-116.695048
NEDS_003	A3	37.756034	-116.69324
NEDS_004	A4	37.759317	-116.692048
NEDS_005	A5	37.756965	-116.694482
NEDS_006	A6	37.75666	-116.693297
NEDS_007	A7	37.756189	-116.693022
NEDS_008	B1	37.75663	-116.69336
NEDS_009	B2	37.757536	-116.694725
NEDS_010	B3	37.756635	-116.693042
NEDS_011	B4	37.75773	-116.694183
NEDS_012	C1	37.756965	-116.692169
NEDS_013	C2	37.756661	-116.69322
NEDS_014	C3	37.755771	-116.693128
NEDS_015	C4	37.755813	-116.694439
NEDS_016	D1	37.758668	-116.69498
NEDS_017	D2	37.757869	-116.694107
NEDS_018	D3	37.757838	-116.694882
NEDS_019	D4	37.757071	-116.693893
NEDS_020	D5	37.756765	-116.694903

A number of images were produced by RSL-N to document the radiological survey results for each lake bed. Each map legend includes the appropriate ranking information, provided in the above tables, for each lake bed. The images were produced to evaluate the distribution of the discrete DU targets to discern any possible pattern based on the historical test information collected earlier in the project. The DU target locations were also compared with the geophysical data indicators for subsurface anomalies, which are primarily indications of disposal pits, trenches, or large metallic objects. Locations with both radiological and geophysical anomalies were given priority for subsequent investigations.

Due to the large size of the images (normally 22 x 34 inches) necessary to evaluate the data and underlying geographical features, none of the DU target locations or geophysical target anomaly image maps are included within this report. They are available on the DVD provided with the CAU 484 report.

EXAMPLES OF SPECTRAL RANKINGS

Figure 8. Net Spectrum at Location NEDS-3, Ranking A

Figure 9. Net Spectrum at Location NEDS-8, Ranking B

Figure 10. Net Spectrum at Location NEDS-12, Ranking C

Figure 11. Net Spectrum at Location NEDS-19, Ranking D

Figure 12. Typical Background Spectrum at NEDS Lake

CLOSURE STANDARDS AND TECHNIQUES

The initial standard for clean closure of DU at CAU 484 sites was considered to be met if the concentrations were less than the minimum detectable concentration using field survey instruments. Alternatively, soil samples could be collected, in which case concentrations would need to be less than recommended screening limits for construction, commercial, and industrial land use scaled to 25 millirem per year dose. Using these criteria, the U-238 clean-up concentration was 63 picocuries per gram (pCi/g).

Remediation and clean closure activities were initially conducted without RSL-N support, as planned; however, soil samples taken after hand-held instrument readings had been used to determine clean-up success were consistently showing U-238 concentrations exceeding the 63 pCi/g criteria. It was determined that the hand-held instruments had a much lower sensitivity to gamma emissions from the surface and subsurface DU than did the Kiwi NaI log detectors.

ER project personnel requested sensitivity calculations for the Kiwi against the pCi/g standard. Initial calculations confirmed sufficient sensitivity using the Kiwi as the field survey instrument for final confirmation that remaining concentrations met the clean-up standard. The Kiwi was used to reacquire previous DU source target areas so that the remediation crews could remove DU soil and debris. The Kiwi was then repositioned periodically over the excavated area or removed soil to measure residual DU activity. This process was repeated as necessary to confirm that the DU had been successfully removed.

In support of this task, RSL-N personnel lowered the detector pods on the Kiwi from 28 inches to 14 inches agl. In addition, the verification measurements were conducted in a static location above each excavation when possible. The REDAR operator, in the Kiwi, also modified the data display to optimize spectral regions of interest to provide a more sensitive real-time analysis of the remediation status for the clean-up crews.

Due to the large size of the images (normally 22 x 34 inches) necessary to evaluate the data and underlying geographical features, none of the interim verification survey and static measurement image maps are included within this report. They are available on the DVD provided with the CAU 484 report.

“Rule of Thumb” Area and Volume Calculations from RSL-N Calibration Data.

Using the calibration data, one obtains the following:

Point source sensitivity = 8,459 cps per detector pod/ 30 apparent source strength = 282 cps per point source

Point source MDA = 195 3-sigma uncertainty/ 282 cps per $\mu\text{Ci}/\text{m}^2$ = 0.69 point source μCi

Area activity = $8,459 / 30 = 282$ cps per microcurie/square meter ($\mu\text{Ci}/\text{m}^2$)

Area MDA = $195 \text{ 3-sigma uncertainty} / 282 \text{ cps per } \mu\text{Ci}/\text{m}^2 = 0.69 \mu\text{Ci}/\text{m}^2$

Volumetric activity = $282 * 22.2 \text{ pCi/g per } \mu\text{Ci} = 6,260 \text{ cps per pCi/g}$

Volumetric MDA = $0.69 * 22.2 \text{ pCi/g per } \mu\text{Ci} = 15.3 \text{ pCi/g}$

Depleted Uranium Measurements at TTR

Area conversions

The nominal footprint of a Kiwi single pod (two $4 \times 4 \times 16$ -inch detectors) is 1 m^2 . To convert point source activity to first order equivalent area activity is a simple unit change.

Area activity ($\mu\text{Ci}/\text{m}^2$) = Point source activity (μCi)

Volumetric conversions

The volume of 1 m^2 area, 2 centimeters (cm) in depth (assuming uniform depth distribution) is 20,000 cubic centimeters (cm^3).

Assuming a nominal soil density of 2.25 grams per cm^3 , one may convert point source activity to first order equivalent volumetric activity by the relation:

Volumetric activity (pCi/g) = Point source activity (μCi) * 22.2

Calibration data taken at RSL-N

Single pod point source measurements were taken at RSL-N prior to the last deployment of the Kiwi to the TTR in August, 2007. The net observed average count rate (two different sources, four different pods) under a single pod, for a DU penetrator point source of approximately 117 total μCi , was 8,459 cps. The 3-sigma uncertainty (generally used for MDA) for the net count rate at the RSL-N location was 195 cps. Because the DU penetrator is self shielding, correction must be made to obtain the apparent source strength seen by the detector pod.

Calculation of Apparent Source Strength of DU Penetrator

One may approximate the penetrator as a rectangular slab of thickness 1.65 cm (the diameter of the penetrator). For computation purposes, the average energy for DU is assumed to be 500 keV. At 500 keV, the half-attenuation thickness for DU is 0.3 cm. The calculated self-attenuation parameter (SAP) is then

$$\text{SAP} = 0.3 / 1.65 = 0.182$$

The relationship for apparent source strength is

$$AS = (TS / 0.693) * SAP * (1 - \exp(-0.693 / SAP))$$

Where AS = apparent source, TS = total source, SAP = slab attenuation parameter

For the penetrator with TS = 117 μ Ci and a SAP of 0.182:

Apparent strength = 30 μ Ci

RECORD AND DATA ARCHIVING

Kiwi data for the extensive surveys of the various lake beds require the use of multiple computer servers at RSL-N. The raw data encompass second-by-second GPS readings, detector counts for each pod, vehicle speed, etc. It also contains one-second spectral information generated concurrently with the raw data. Post-processing products have been produced that include GC maps, man-made count maps, DU target maps, and spectral analysis. The RSL-N will maintain all the original data and map products and can produce specific target, lake bed analysis, or map products upon request.

CONCLUSION

Kiwi data revealed that a large part of the DU contamination existed in spatial distributions smaller than the Kiwi footprint, bounded by much larger background areas. This was evident in Kiwi data when activity occurred totally within a 1-second data frame (i.e., less than 2 m forward travel) and/or was detected only in some of the detectors (e.g., 0.7-m footprint per 2-detector sub-array, see Figure 2). A number of such areas were confirmed by portable instrument measurements. It was not unusual for the Electra probe to completely cover a contaminated area, with no other measurable activity present for many feet outside of the detected area.

Subsequent clean-up and verification operations and supporting Kiwi surveys have continued through July 2007. The project has had success in removing many of the discrete DU targets with minimal effort (i.e. shoveling into waste bags). The RCTs and the Kiwi have confirmed the successful removal of DU to levels below the respective MDAs with the exception of four target locations on Antelope Lake. At these locations, the initial surface target excavations failed to reduce instrument readings or, in some instances, caused an increase in subsequent readings. The excavations vary in depth from six inches to approximately six ft bgs. Recent negotiations with the state of Nevada have allowed for a modification of the clean-up standard to be limited to the MDA of the Kiwi and the RCTs' instruments for surface measurements only. The survey plan for the final measurements is being developed for implementation during the August-September 2007 final clean-up efforts.

APPENDIX M-2

RADIOLOGICAL SURVEY REPORT

AMS Kiwi Final Results
Tonopah Test Range – CAU 484

AERIAL MEASURING SYSTEM KIWI FINAL RESULTS TONOPAH TEST RANGE – CAU 484 August 31, 2007

Introduction

Radiological surveys were initially conducted on Antelope Lake, Brownes Lake, Pedro Lake, and NEDS Lake to map the surface and shallow subsurface distribution of radioactive debris to support the establishment of Data Quality Objects for the characterization and cleanup of Corrective Action Unit (CAU) 484. CAU 484 consists of surface debris, waste sites, and a burn area, and is comprised of six Corrective Action Sites (CASs). The purpose of these initial radiological surveys was to obtain preliminary information from which the scope and scale of the characterization program was established.

The objective of the radiological survey program was to map areas with elevated gamma activity due to depleted uranium (DU) or other radionuclides in conjunction with geophysical surveys to determine the area of extent of metallic debris. Targets located from these surveys were examined in further detail under a follow-up characterization program. The final goal of the program was to locate, characterize, and remediate known and unknown waste sites as identified in the CAUs. The Kiwi survey work scope was limited to non-intrusive, non-contact surveys.

After completion of characterization surveys, the Remote Sensing Laboratory (RSL) was requested to provide additional assistance in marking the suspected DU point sources for the radiological control technicians (RCTs) and clean-up personnel. As the remediation work progressed, the Kiwi was used periodically to confirm the success of the clean-up and became the final verification asset for the project.

Subsequent clean-up and verification operations and supporting Kiwi surveys continued through July 2007. The project had success in removing many of the discrete DU targets with minimal effort (i.e., shovel and waste bags). The RCTs and Kiwi have confirmed the successful removal below their respective minimum detectable activities (MDAs). The project did encounter four locations on Antelope Lake where the initial surface target excavations failed to reduce instrument readings or in some instances caused an increase in subsequent readings. The excavations varied in depth from six inches to approximately six feet. Recent negotiations with the state of Nevada have allowed for a modification of the clean-up standard to be limited to the MDA of the Kiwi and the RCTs' instruments for surface measurements only.

The Kiwi verification survey plan for the final measurements was implemented during the week of August 20, 2007, to support the final clean-up efforts. The project identified five sites for final surveys: Contamination Area 1 (CA-1), Contamination Area 2 (CA-2), SA-5-9, SA-12-15, and SA-004. The primary clean-fill area that was used was located at the intersection of Main Road and Brownes Lake Road. The Kiwi personnel were deployed on August 19, 2007, to direct additional excavation work around the periphery of

the excavations as needed. Once the excavation work was completed, clean fill material was transported to the Antelope Lake excavated areas. The Kiwi performed the final surveys as planned for each site. The final surveys were completed on August 22, 2007.

Post-acquisition analysis was performed from August 23 through August 30, 2007. The analysis included plotting the man-made count data for each of the three passes at each site. A final map was compiled to display the three pass results for each site, including any statistical anomalies. Post-acquisition spectral analysis showed no gamma peaks for DU. Single pass maps and spectral results are available upon request.

Survey Objectives

The specific closure standard for DU was to be the minimum detectable concentration using field survey instruments. The primary measurement systems to be used were the RSL Kiwi vehicle and the Thermo Electron Corporation Electra Rate Meter portable instrument.

The Kiwi system was modified in configuration to perform the final verification surveys. The detector pods were lowered to 14 inches above ground level (agl) to improve gamma sensitivity under each detector box. The data display was modified to show the gamma man-made algorithm counts for each detector box inside the cab of the vehicle. This allowed the RSL personnel to observe any changes to the man-made counts due to the deposited DU. The man-made algorithm included the four primary gamma rays emitted by the Thorium-234 and Protactinium-234m daughters. If gamma from DU was detected by the Kiwi, an Electra was to be used for additional surveys as the Kiwi had no sensitivity to the alpha or beta particles emitted by the radionuclides of interest.

The Kiwi system data objectives were to conduct scanning surveys over each excavation that had been completely refilled back to the lake-bed surface using imported soil from a nearby gravel pit. The Kiwi performed slow (1 to 5 miles per hour [mph]) surveys over each former excavated area to document final radioactivity levels. Where the Kiwi personnel observed elevated readings on the man-made algorithm display during any survey, they returned to each elevated radioactivity location and assisted the RCTs in conducting surface radioactivity surveys under the Kiwi detector pods.

Characteristics of Uranium-238 Decay Chain

As summarized in Table 1, the Kiwi radiological surveys conducted at CAU 484 actually detected the gamma rays emitted from the daughter products of the parent DU decay. The two daughter radionuclides are Thorium-234 and Protactinium-234m. Both have very short half-lives compared to Uranium-238, but they are in secular equilibrium (i.e., equivalent disintegrations per minute) with the parent. The two daughter products quickly achieve equilibrium with the U-238 parent after the manufacturing process has been completed. The fourth radionuclide in the decay chain, Uranium-234, has a very long half-life and no significant gammas are produced. Due to the long half-life of

Uranium-234, no other daughters from the decay of the originally deposited DU will contribute to the gamma spectrum at the TTR for another 10,000 years.

Table 1
Simplified Depleted Uranium Gamma Ray Energies of Interest

Radionuclide	Gamma Energy (keV)	Yield (%)
Uranium-238	No Gamma Emitted	
Thorium-234	63.3	3.8
	92.6	5.4
Protactinium-234m	1,001	0.6
	767	0.3
Uranium-234	No Gamma Emitted	

As discussed previously, the man-made count algorithm used on board the Kiwi for reacquiring DU targets and for evaluation of clean-up efforts included a broad region of interest from 30 keV to 1,400 keV. This allowed for the inclusion of the four gamma-ray energies included in Table 1. This algorithm was effective due to the relatively stable background gross counts on each lake bed. The characterization survey data did not indicate the presence of any other man-made radionuclides during the extensive post-analysis that was conducted. Therefore, any increase of count rates displaying this man-made algorithm can be attributed to the deposited DU.

Survey Procedures

1. Pre-acquisition spectral Calibration - The RSL personnel confirmed the spectral calibration of the Kiwi detectors using the natural spectral energy peaks for Bismuth-214 (609 keV), Potassium-40 (1460 keV), and Thallium-208 (2614 keV). These natural radionuclides were present in sufficient activity to confirm the performance of the Kiwi system before daily deployment. The pre-acquisition spectral comparison also provided a daily background spectrum for data analysis and comparison between data sets.
2. Kiwi Survey of Excavation Boundaries - Using the previous data from surveys of each Antelope Lake excavation, the RSL personnel conducted a series of scanning and static surveys around the boundaries of each excavation. They directed the Environmental Restoration personnel to spray paint the areas around each excavation that required additional excavation to remove potential surface DU contamination still detectable by the Kiwi system. The National Security Technologies^{LLC} (NSTec) equipment operators then cut from the painted boundaries into the excavated area as required. The recommended final depth for any excavated area was at least 6 inches (15 centimeters). Assuming a soil density of 1.5 grams per cubic centimeter (g/cm³) and 6 inches of “clean” fill over the

excavated areas, the Kiwi sensitivity to any subsurface residual DU was to be reduced by a factor of two or more of the surface MDA.

3. Kiwi survey of Gravel Pit - The soil to be removed and used as fill for the Antelope Lake excavations had the potential to contain a slightly different mixture of natural radionuclides than the soil found on Antelope Lake. RSL personnel performed a scanning survey of the gravel pit area. The Kiwi survey used the same parameters as those planned for the Antelope Lake final surveys. The vehicle speed did not exceed 5 mph and the detector pod height was 14 inches agl. The survey provided man-made algorithm count-rate data and spectral data to compare to previously acquired Antelope Lake bed data. These data were necessary if the fill material provided an observable change in the man-made count rates observed from the Kiwi detectors while conducting the final surveys.
4. Kiwi Surveys of the Excavations - After each excavation was filled and compacted to the original lake bed level, RSL performed a Kiwi survey over the area. The survey parameters included a vehicle speed of less than 5 mph and a detector height of 14 inches. The entire area was surveyed using a parallel pattern with no stopping. The survey was repeated two additional times, for a total of three passes. The survey lines were driven in the same direction for each survey. The multiple passes provided sufficient data to evaluate any elevated point source indications during post-analysis. Any elevated location that did not repeat for all three passes was treated as a statistical anomaly and ignored as an indication of DU. Previously, these elevated areas were reported as range D targets based on single Kiwi passes during the initial characterization surveys. Based on the lack of success for confirming such targets as deposited DU, the multiple pass survey technique and subsequent data analysis provided sufficient information to assess the target's validity.
5. Kiwi Support to RCT Surveys - After the Kiwi completed the three scanning surveys at each excavation area, RSL personnel conducted static surveys over any elevated activity areas observed previously. If the RSL personnel confirmed an elevated area, then the RCTs conducted surface scan and static surveys under the Kiwi pods displaying elevated counts. The effective field of view under any detector pod at 14 inches was less than 1square meter (m^2). The RCTs provided documentation of the survey results to the NSTec Environmental Remediation (ER) project. The NE Electra portable instrument used for these surface surveys would detect the Protactinium-234m beta particle. The beta particle had a maximum energy of 2.3 million electron volts and a yield of 98.6%.
6. Post-Survey Data Analysis - The RSL data analyst reviewed the Kiwi scanning survey data. This review focused on any elevated point source locations and their repeatability, as described previously. If a location met the criteria, the information was provided to the NSTec ER project and RCTs for further investigation. Any static measurements performed at each excavation location were combined with the RCT data results for a final determination of surface or subsurface DU activity.

Post-Deployment Data Analysis and Map Products

1. Vehicle Path Mapping - RSL produced a vehicle path map for each excavation area as the final survey verification result. The three repeated paths were color plotted to document any elevated areas.
2. Man-Made Activity Plots - The vehicle path data was plotted using the man-made algorithm count rates used previously.
3. Spectral Data - Baseline and target spectra data were produced as necessary to document the source of count-rate changes plotted using the man-made count-rate data.
4. Surface and Subsurface Determinations - RSL analyzed the various data sources available, man-made count rate data, spectral data, and NE Electra data to validate that the CAU 484 closure objectives were achieved for any location exhibiting elevated Kiwi counts.

Final Survey Results

1. CA-2 - A minor volume of soil was removed from the existing excavation and transported to CA-1. The site was then contoured to allow for the Kiwi to drive over the entire site. The site was driven three times, as planned. Based on real-time observation of the data and post survey analysis, the site was determined to contain no detectable DU activity.
2. Junction of Main Road and Brownes Lake Road - The Kiwi was driven around an existing mound of soil to be used for the clean fill at the Antelope Lake excavations. The initial survey consisted of one series of passes around the mound. The potential survey area was confined due to existing fences, vegetation, and operating equipment.
3. CA-1 - The Kiwi was driven around the periphery of the existing excavation to determine elevated DU activity present at the lake-bed surface. The areas were spray-painted and the NSTec operator excavated all elevated activity into the middle of the excavation. The new lake-bed surface excavations were at least six inches in depth, as recommended. After excavations were completed, clean fill soil was deposited over all excavated surfaces. The fill material was mounded to approximately two feet above the lake-bed surface when contouring was completed. The Kiwi was then driven over the entire site three times, as planned. No elevated man-made anomaly areas were observed during the surveys, and the RCTs were not required to perform additional surface surveys. No repeatable DU activity locations were identified during the post-survey analysis. Net spectra of single location anomalies were inconclusive.
4. SA-5-9 - The Kiwi was driven around the periphery of the existing excavation to determine elevated DU activity present at the lake-bed surface. One small area was spray-painted and the NSTec operator excavated all elevated activity into the middle of the excavation. The new lake-bed surface excavations were at least six

inches in depth, as recommended. After excavations were completed, clean fill soil was deposited over all excavated surfaces. The fill material was mounded to approximately two feet above the lake-bed surface when contouring was completed. The Kiwi was then driven over the entire site three times, as planned. No elevated man-made anomaly areas were observed during the surveys and the RCTs were not required to perform additional surface surveys. No repeatable DU activity locations were identified during the post-survey analysis. Net spectra of single-location anomalies were inconclusive.

5. SA-004 - The Kiwi was driven around the periphery of the existing excavation to determine elevated DU activity present at the lake bed surface. No additional surface areas were identified. After excavations were completed, clean fill soil was deposited over all excavated surfaces. The fill material was mounded to approximately two feet above the lake-bed surface when contouring was completed. The Kiwi was then driven over the entire site three times, as planned. No elevated man-made anomaly areas were observed during the surveys and the RCTs were not required to perform additional surface surveys. No repeatable DU activity locations were identified during the post-survey analysis. Net spectra of single-location anomalies were inconclusive.
6. SA-12-15 - The Kiwi was driven around the periphery of the existing excavation to determine elevated DU activity present at the lake-bed surface. The areas were spray-painted and the NSTec operator excavated all elevated activity into the middle of the excavation. The new lake-bed surface excavations were at least six inches in depth as recommended. After excavations were completed, clean fill soil was deposited over all excavated surfaces. The fill material was mounded to approximately two feet above the lake-bed surface when contouring was completed. The Kiwi was then driven over the entire site three times, as planned. No elevated man-made anomaly areas were observed during the surveys and the RCTs were not required to perform additional surface surveys. No elevated locations were identified during the post-survey analysis.

Conclusions

The Excavations at CA-1, SA-5-9, SA-004, and SA-12-15 have no detectable surface DU activity. Based on previous survey data over the open excavations, the sites do have underground radioactive material present under the newly contoured clean soil. The CA-2 site had no residual detectable DU activity.

Attachments

1. CA-1 Clean-up Verification Map (Three Passes) – Hardcopy
2. CA-2 Clean-up Verification Map (Three Passes before fill) - Hardcopy
3. SA-5-9 Clean-up Verification Map (Three Passes) – Hardcopy
4. SA-12-15 Clean-up Verification Map (Three Passes) – Hardcopy
5. SA-004 Clean-up Verification Map (Three Passes) – Hardcopy

**ANTELOPE LAKE
CA1 after backfill
All Three Passes
August 21, 2007**

**CLEAN-UP VERIFICATION
Man-made Counts**

— Excavated Boundary

SYMBOLS

- from First Pass
- from Second Pass
- from Third Pass
- from All 3 Passes

0 10 20 30 40 50Feet

**CA2 before backfill
All Three Passes
August 20, 2007**

CLEAN-UP VERIFICATION

Man-made Counts

< 1500 cps
1500 - 2000
2000 - 2500
2500 - 3000
3000 - 3500
3500 - 4000
4000 - 6000
6000 - 10500

SYMBOLS

from First Pass
from Second Pass
from Third Pass
from All 3 Passes

0 10 20 30 40Feet

SA 5-9 after backfill
All Three Passes
August 21, 2007

SA 12-15 after backfill
All Three Passes
August 22, 2007

CLEAN-UP VERIFICATION
Man-made Counts

— Excavated Boundary

SYMBOLS

- ◇ from First Pass
- ⊕ from Second Pass
- ☆ from Third Pass
- from All 3 Passes

0 10 20 30 40 Feet

**SA_004 after backfill
All Three Passes
August 21, 2007**

APPENDIX N

IMAGERY

(Includes Geophysics, Radiological, and Multispectral)*

* The enclosed disk contains copies of the referenced imagery.

THIS PAGE INTENTIONALLY LEFT BLANK

APPENDIX O

USE RESTRICTION DOCUMENTATION

THIS PAGE INTENTIONALLY LEFT BLANK

Department of Energy
National Nuclear Security Administration
Nevada Site Office
P.O. Box 98518
Las Vegas, NV 89193-8518

SEP 5 2007

E. V. Hopper
Chief, Environmental Flight
4349 Duffer Dr., Ste 1601
Nellis AFB, NV 89191-7007

**SUBMITTAL OF THE USE RESTRICTION INFORMATION FOR CAU 484, SURFACE
DEBRIS, WASTE SITES AND BURN AREA (TTR)**

Enclosed are three copies of the Use Restriction Information form for CAU 484 to file in your GIS system. The site is located on the Tonopah Test Range. The use restriction is for subsurface only. The use restriction coordinates are in the UTM Zone 11, NAD27 (meters). Please reply when the use restriction is filed.

<u>CAU No.</u>	<u>Description</u>
484	Surface Debris, Waste Sites, And Burn Area (TTR)

Please direct comments and questions to Kevin J. Cabble, of my staff, at (702) 295-5000.

ERP:3420.SC

John B. Jones
Acting Federal Project Director
Environmental Restoration Project

Enclosures:
As stated

cc w/o encl via e-mail:

D. R. Elle, NDEP, Las Vegas, NV

D. C. Loewer, DTRA/CXT1, M/S 645, Mercury, NV

T. A. Lantow, DTRA/CXT1, M/S 645, Mercury, NV

W. R. Griffin, SNJV/DTRA, M/S 645, Mercury, NV

T. A. Thiele, NSTec, Las Vegas, NV

NSTec Technical Information Officer, Las Vegas, NV

R. F. Boehlecke, SNJV, Las Vegas, NV

E. F. Di Sanza, WMP, NNSA/NSO, Las Vegas, NV

S. T. Curtis, ERP, NNSA/NSO, Las Vegas, NV

K. J. Cabbie, ERP, NNSA/NSO, Las Vegas, NV

FFACO Group, PSG, NNSA/NSO, Las Vegas, NV

CAU Use Restriction Information

CAU Number/Description: CAU 484: Surface Debris, Waste Sites, and Burn Area (TTR)

Applicable CAS Numbers/Descriptions: CAS RG-52-007-TAML
Davis Gun Penetrator Test

Contact (organization/project): NNSA/NSO Federal Sub-Project Director

Surveyed Area (UTM, Zone 11, NAD 27, meters):

CA-1

UR POINTS	NORTHING	EASTING
North Corner	4,171,047.729	529,068.684
East Corner	4,171,032.005	529,076.922
South Corner	4,171,019.661	529,061.209
West Corner	4,171,039.415	529,048.832

SA-4

UR POINTS	NORTHING	EASTING
North Corner	4,170,774.405	529,389.497
East Corner	4,170,763.657	529,394.887
South Corner	4,170,754.726	529,386.560
West Corner	4,170,765.922	529,377.659

SA-5-9

UR POINTS	NORTHING	EASTING
North Corner	4,170,482.056	529,845.995
East Corner	4,170,466.774	529,852.813
South Corner	4,170,457.134	529,839.947
West Corner	4,170,471.915	529,829.948

SA-12-15

UR POINTS	NORTHING	EASTING
North Corner	4,169,010.526	529,418.788
East Corner	4,168,997.283	529,422.866
South Corner	4,168,987.970	529,412.863
West Corner	4,169,001.692	529,405.847

Survey Date: 08/23/2007 **Survey Method (GPS, etc):** GPS

Site Monitoring Requirements: Visual Inspections

Required Frequency (quarterly, annually?): 1st year, semi-annually
Annually thereafter

If Monitoring Has Started, Indicate last Completion Date: N/A

If Monitoring Has Started, Indicate last Completion Date: N/A

Use Restrictions

The future use of any land related to this Corrective Action Unit (CAU), as described by the above surveyed location, is restricted from any DOE or Air Force activity that may alter or modify the containment control as approved by the state and identified in the CAU Closure Report or other CAU documentation unless appropriate concurrence is obtained in advance.

Comments: See the Closure Report for additional information on the condition of the site(s) and any monitoring and/or inspection requirements. This use restriction applies to four locations on Antelope Lake. The use restriction applies to subsurface depleted uranium contamination that is at least 0.5 feet below the ground surface. A minimum of 0.5 feet of clean fill is on top of the contamination.

Submitted By: _____ Date: 9/5/07

cc with copy of survey map (paper and digital (dgn) formats):
CAU Files (2 copies)

THIS PAGE INTENTIONALLY LEFT BLANK

LIBRARY DISTRIBUTION LIST

THIS PAGE INTENTIONALLY LEFT BLANK

LIBRARY DISTRIBUTION LIST

U.S. Department of Energy
National Nuclear Security Administration
Nevada Site Office
Technical Library
P.O. Box 98518, M/S 505
Las Vegas, NV 89193-8518

1 (Uncontrolled, electronic copy)

U.S. Department of Energy
Office of Scientific and Technical Information
P.O. Box 62
Oak Ridge, TN 37831-0062

1 (Uncontrolled, electronic copy)

Southern Nevada Public Reading Facility
c/o Nuclear Testing Archive
P.O. Box 98521, M/S 400
Las Vegas, NV 89193-8521

2 (Uncontrolled, electronic copies)

Manager, Northern Nevada FFAO
Public Reading Facility
c/o Nevada State Library & Archives
Carson City, NV 89701-4285

1 (Uncontrolled, electronic copy)

THIS PAGE INTENTIONALLY LEFT BLANK

ANTELOPE LAKE

Data collected December 2003 - September 2006

Geophysics Data

**EM-61
Geophysics Data**

○ DU Ring (3461)

ANTELOPE LAKE

Data collected December 2003 - September 2006

Geophysics Data

**EM-61
Geophysics Data**

◆ Disposal Pit (25)

Created
July 20, 2007

ANTELOPE LAKE

Data collected December 2003 - September 2006

Geophysics Data

EM-61
Geophysics Data

□ Bomblet (20,762)